



# Logs Reference

## Logs Reference

### Introduction

This guide describes the logs that may be raised during operation and configuration of the Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series.

A description of the log and an appropriate remedial action is provided along with the severity and source of the log. Each log is listed alphabetically corresponding to the first letter of the log name. You can navigate the alphabetical listings by selecting:

- [All logs](#)
- [Log source](#)
- [Log severity](#)

Use the 'find-in-page' function of the browser to search for a command based on the page you are viewing. Most browsers launch 'find' using CTRL+F.

### Legal Notice

Extreme Networks, Inc. reserves the right to make changes in specifications and other information contained in this document and its website without prior notice. The reader should in all cases consult representatives of Extreme Networks to determine whether any such changes have been made.

The hardware, firmware, software or any specifications described or referred to in this document are subject to change without notice.

### Trademarks

Extreme Networks and the Extreme Networks logo are trademarks or registered trademarks of Extreme Networks, Inc. in the United States and/or other countries.

All other names (including any product names) mentioned in this document are the property of their respective owners and may be trademarks or registered trademarks of their respective companies/owners.

For additional information on Extreme Networks trademarks, please see:

<http://www.extremenetworks.com/company/legal/trademarks>.

### Software Licensing

Some software files have been licensed under certain open source or third-party licenses. End-user license agreements and open source declarations can be found at: <https://www.extremenetworks.com/support/policies/software-licensing>.

### Support

For product support, phone the Global Technical Assistance Center (GTAC) at 1-800-998-2408 (toll-free in U.S. and Canada) or +1-408-579-2826. For the support phone number in other countries, visit: <https://www.extremenetworks.com/support/contact>.

For product documentation online, visit: <https://www.extremenetworks.com/documentation>.



# Alphabetized list of logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Alphabetized list of logs

All logs are organized alphabetically by their name. Select the letter to navigate to the list of all logs starting with that letter.

<a href="#">A</a> 197 logs	<a href="#">B</a> 58 logs	<a href="#">C</a> 247 logs	<a href="#">D</a> 212 logs
<a href="#">E</a> 283 logs	<a href="#">F</a> 325 logs	<a href="#">G</a> 12 logs	<a href="#">H</a> 21 logs
<a href="#">I</a> 660 logs	<a href="#">J</a> 2 logs	<a href="#">K</a> 1 logs	<a href="#">L</a> 122 logs
<a href="#">M</a> 124 logs	<a href="#">N</a> 81 logs	<a href="#">O</a> 68 logs	<a href="#">P</a> 130 logs
<a href="#">Q</a> 41 logs	<a href="#">R</a> 95 logs	<a href="#">S</a> 485 logs	<a href="#">T</a> 354 logs
<a href="#">U</a> 272 logs	<a href="#">V</a> 57 logs	<a href="#">W</a> 50 logs	<a href="#">X</a> 1 logs
Y		<a href="#">Z</a> 11 logs	

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Log source listing

Select name of the source to see all logs that are generated by that source. Each source page lists all the applicable logs alphabetically.

### Sources sorted by log quantity

[QoS](#) --988 logs  
[Fabric Attach](#) --210 logs  
[SNMP](#) --208 logs  
[EAP](#) --189 logs  
[ISIS](#) --158 logs  
[SMGR](#) --100 logs  
[AUR](#) --98 logs  
[VLAN](#) --78 logs  
[L3Mgr](#) --70 logs  
[IGMP](#) --69 logs  
[MLT](#) --67 logs  
[SSH](#) --64 logs  
[HMOD](#) --58 logs  
[LAC](#) --57 logs  
[Telnet](#) --55 logs  
[DHCP Snoop](#) --51 logs  
[port driver](#) --51 logs  
[OSPF](#) --49 logs  
[STP](#) --47 logs  
[IMC](#) --45 logs  
[CDT](#) --44 logs  
[IKE](#) --43 logs  
[Stack Manager](#) --38 logs  
[Radius](#) --35 logs  
[WEB](#) --33 logs  
[TACACS](#) --32 logs  
[Bay secure](#) --31 logs  
[ipsg](#) --30 logs  
[Telnet server](#) --27 logs  
[Boot Ascii](#) --26 logs  
[Console](#) --26 logs  
[Flash Driver](#) --26 logs  
[GBIC](#) --25 logs

### Sources sorted alphabetically

[\\_](#) -- 1 log  
[802.1AB](#) -- 5 logs  
[AAA](#) -- 17 logs  
[ACG](#) -- 7 logs  
[ADAC](#) -- 19 logs  
[APPTTEL](#) -- 7 logs  
[ASCFG](#) -- 1 log  
[Audit](#) -- 2 logs  
[AUR](#) -- 98 logs  
[Bay secure](#) -- 31 logs  
[BAYSECURE, DCE](#) -- 2 logs  
[Boot Ascii](#) -- 26 logs  
[CAMPOLICY](#) -- 4 logs  
[CDT](#) -- 44 logs  
[CFC](#) -- 1 log  
[CFG](#) -- 10 logs  
[CFGSO](#) -- 17 logs  
[CFM](#) -- 1 log  
[CLI](#) -- 4 logs  
[CLI Audit](#) -- 11 logs  
[CLOCK](#) -- 1 log  
[config](#) -- 14 logs  
[CONFIG DATA](#) -- 1 log  
[Console](#) -- 26 logs  
[DAI](#) -- 2 logs  
[DCE](#) -- 2 logs  
[DHCPR](#) -- 6 logs  
[DHCP Snoop](#) -- 51 logs  
[DIGICERT](#) -- 4 logs  
[DOWNLOAD](#) -- 1 log  
[Download Task](#) -- 4 logs  
[DRIVER](#) -- 2 logs  
[EAP](#) -- 189 logs

[Quick Install](#) --25 logs  
[IPFIX](#) --22 logs  
[PIM](#) --22 logs  
[SC](#) --21 logs  
[IPv6](#) --20 logs  
[ADAC](#) --19 logs  
[MCFG](#) --19 logs  
[SLAMon](#) --19 logs  
[Source Based Routing](#) --19 logs  
[SPB](#) --19 logs  
[Stack Monitor](#) --19 logs  
[IPT](#) --18 logs  
[SMLT](#) --18 logs  
[VLACP](#) --18 logs  
[AAA](#) --17 logs  
[CFGSO](#) --17 logs  
[PMT](#) --17 logs  
[VRRP](#) --17 logs  
[NES](#) --16 logs  
[Run scripts: IP Office, LLDP, ADAC](#) --16 logs  
[IPIGMP](#) --15 logs  
[config](#) --14 logs  
[FCoE Redirect](#) --13 logs  
[LACP](#) --13 logs  
[ospf\(drpmgr\)](#) --13 logs  
[Link State Tracking](#) --12 logs  
[SSHC \(SFTP and SSH Client\)](#) --12 logs  
[SSH Client](#) --12 logs  
[CLI Audit](#) --11 logs  
[CFG](#) --10 logs  
[ENGMENU](#) --10 logs  
[Hello Module](#) --10 logs  
  
[PoE](#) --9 logs  
  
[SSL](#) --9 logs  
[Energy Server](#) --8 logs  
[ACG](#) --7 logs  
[APPTel](#) --7 logs  
[PDT](#) --7 logs  
[SPBM](#) --7 logs  
[ZTP](#) --7 logs  
[DHCPR](#) --6 logs  
[IPv6 First Hop Security](#) --6 logs  
[MLD](#) --6 logs  
[POL](#) --6 logs  
[Run scripts: LLDP, ADAC](#) --6 logs  
[SBR](#) --6 logs

[EAP-Filter Manager](#) -- 5 logs  
[EAP-VLAN \(QDT\)](#) -- 2 logs  
[Energy Server](#) -- 8 logs  
[ENGMENU](#) -- 10 logs  
[ENTMIB](#) -- 1 log  
[Exception](#) -- 1 log  
[FAA](#) -- 2 logs  
[Fabric Attach](#) -- 210 logs  
[FCoE Redirect](#) -- 13 logs  
[Flash](#) -- 2 logs  
[Flash Driver](#) -- 26 logs  
[FNC](#) -- 4 logs  
[GBIC](#) -- 25 logs  
[Hello Module](#) -- 10 logs  
[HMOD](#) -- 58 logs  
[IDT](#) -- 2 logs  
[IFMGR, SNMP](#) -- 2 logs  
[IGMP](#) -- 69 logs  
[IKE](#) -- 43 logs  
[IMC](#) -- 45 logs  
[Inband IP address](#) -- 1 log  
[IPFIX](#) -- 22 logs  
[IPIGMP](#) -- 15 logs  
[ipmc \(igmp\)](#) -- 3 logs  
[IPMGR](#) -- 1 log  
[IPSEC](#) -- 1 log  
[ipsq](#) -- 30 logs  
[IPT](#) -- 18 logs  
[IPv4 Routing](#) -- 1 log  
[IPv6](#) -- 20 logs  
[IPv6 Data Tunneling](#) -- 1 log  
[IPv6 First Hop Security](#) -- 6 logs  
[IPv6 management over SPB \(routing mode\)](#) -  
- 2 logs  
[IPv6 Source Guard](#) -- 2 logs  
[ISIS](#) -- 158 logs  
[L3, MLT](#) -- 2 logs  
[L3Mgr](#) -- 70 logs  
[LAC](#) -- 57 logs  
[LACP](#) -- 13 logs  
[Link State Tracking](#) -- 12 logs  
[LST](#) -- 2 logs  
[MCFG](#) -- 19 logs  
[MCFG \(Second INFO BLOCK\)](#) -- 1 log  
[MCM](#) -- 1 log  
[MCMGR, DRPMGR](#) -- 1 log  
[MCMGR/IGMP](#) -- 3 logs



<a href="#"><u>802.1AB</u></a> --5 logs	<a href="#"><u>MDA</u></a> -- 5 logs
<a href="#"><u>EAP-Filter Manager</u></a> --5 logs	<a href="#"><u>Memory Tool</u></a> -- 1 log
<a href="#"><u>MDA</u></a> --5 logs	<a href="#"><u>MLD</u></a> -- 6 logs
<a href="#"><u>NNCLI</u></a> --5 logs	<a href="#"><u>MLT</u></a> -- 67 logs
<a href="#"><u>NNRST</u></a> --5 logs	<a href="#"><u>Multi Config</u></a> -- 2 logs
<a href="#"><u>Run scripts: ADAC</u></a> --5 logs	<a href="#"><u>NES</u></a> -- 16 logs
<a href="#"><u>CAMPOLICY</u></a> --4 logs	<a href="#"><u>NNCLI</u></a> -- 5 logs
<a href="#"><u>CLI</u></a> --4 logs	<a href="#"><u>NNRST</u></a> -- 5 logs
<a href="#"><u>DIGICERT</u></a> --4 logs	<a href="#"><u>NTP</u></a> -- 1 log
<a href="#"><u>Download Task</u></a> --4 logs	<a href="#"><u>NUQC</u></a> -- 4 logs
<a href="#"><u>FNC</u></a> --4 logs	<a href="#"><u>OSPF</u></a> -- 49 logs
<a href="#"><u>NUQC</u></a> --4 logs	<a href="#"><u>ospf(drpmgr)</u></a> -- 13 logs
<a href="#"><u>PLATFORM</u></a> --4 logs	<a href="#"><u>Password Security</u></a> -- 2 logs
<a href="#"><u>QPAV2</u></a> --4 logs	<a href="#"><u>PDT</u></a> -- 7 logs
<a href="#"><u>Run scripts: IP Office</u></a> --4 logs	<a href="#"><u>PIM</u></a> -- 22 logs
<a href="#"><u>SFTP Client</u></a> --4 logs	<a href="#"><u>PLATFORM</u></a> -- 4 logs
<a href="#"><u>USB</u></a> --4 logs	<a href="#"><u>PM</u></a> -- 1 log
<a href="#"><u>ipmc (igmp)</u></a> --3 logs	<a href="#"><u>PMT</u></a> -- 17 logs
<a href="#"><u>MCMGR/IGMP</u></a> --3 logs	<a href="#"><u>PoE</u></a> -- 9 logs
<a href="#"><u>QoS Agent</u></a> --3 logs	<a href="#"><u>POL</u></a> -- 6 logs
<a href="#"><u>SLOG</u></a> --3 logs	<a href="#"><u>port driver</u></a> -- 51 logs
<a href="#"><u>SLPP Guard</u></a> --3 logs	<a href="#"><u>Port Mirroring</u></a> -- 1 log
<a href="#"><u>SNTP</u></a> --3 logs	<a href="#"><u>QoS</u></a> -- 988 logs
<a href="#"><u>System Logging</u></a> --3 logs	<a href="#"><u>QoS Agent</u></a> -- 3 logs
<a href="#"><u>Audit</u></a> --2 logs	<a href="#"><u>QPAV2</u></a> -- 4 logs
<a href="#"><u>BAYSECURE, DCE</u></a> --2 logs	<a href="#"><u>Quick Install</u></a> -- 25 logs
<a href="#"><u>DAI</u></a> --2 logs	<a href="#"><u>Radius</u></a> -- 35 logs
<a href="#"><u>DCE</u></a> --2 logs	<a href="#"><u>Rear-Port</u></a> -- 2 logs
<a href="#"><u>DRIVER</u></a> --2 logs	<a href="#"><u>RMON</u></a> -- 2 logs
<a href="#"><u>EAP-VLAN (QDT)</u></a> --2 logs	<a href="#"><u>Run scripts: ADAC</u></a> -- 5 logs
<a href="#"><u>FAA</u></a> --2 logs	<a href="#"><u>Run scripts: IP Office</u></a> -- 4 logs
<a href="#"><u>Flash</u></a> --2 logs	<a href="#"><u>Run scripts: IP Office, LLDP</u></a> -- 2 logs
<a href="#"><u>IDT</u></a> --2 logs	<a href="#"><u>Run scripts: IP Office, LLDP, ADAC</u></a> -- 16 logs
<a href="#"><u>IFMGR, SNMP</u></a> --2 logs	<a href="#"><u>Run scripts: LLDP, ADAC</u></a> -- 6 logs
<a href="#"><u>IPv6 management over SPB (routing mode)</u></a> --2 logs	<a href="#"><u>SBR</u></a> -- 6 logs
<a href="#"><u>IPv6 Source Guard</u></a> --2 logs	<a href="#"><u>SC</u></a> -- 21 logs
<a href="#"><u>L3, MLT</u></a> --2 logs	<a href="#"><u>SFTP</u></a> -- 2 logs
<a href="#"><u>LST</u></a> --2 logs	<a href="#"><u>SFTP Client</u></a> -- 4 logs
<a href="#"><u>Multi Config</u></a> --2 logs	<a href="#"><u>SLAMon</u></a> -- 19 logs
<a href="#"><u>Password Security</u></a> --2 logs	<a href="#"><u>SLOG</u></a> -- 3 logs
<a href="#"><u>Rear-Port</u></a> --2 logs	<a href="#"><u>SLPP</u></a> -- 2 logs
<a href="#"><u>RMON</u></a> --2 logs	<a href="#"><u>SLPP Guard</u></a> -- 3 logs
<a href="#"><u>Run scripts: IP Office, LLDP</u></a> --2 logs	<a href="#"><u>SMGR</u></a> -- 100 logs
<a href="#"><u>SFTP</u></a> --2 logs	<a href="#"><u>SMLT</u></a> -- 18 logs
<a href="#"><u>SLPP</u></a> --2 logs	<a href="#"><u>SNMP</u></a> -- 208 logs
<a href="#"><u>SOFTLIC</u></a> --2 logs	<a href="#"><u>SNTP</u></a> -- 3 logs

<a href="#"><u>SPAD</u></a> --2 logs	<a href="#"><u>SOFTLIC</u></a> -- 2 logs
<a href="#"><u>VRRPv3</u></a> --2 logs	<a href="#"><u>source</u></a> -- 1 log
<a href="#"><u>_</u></a> -- 1 log	<a href="#"><u>Source Based Routing</u></a> -- 19 logs
<a href="#"><u>ASCFG</u></a> -- 1 log	<a href="#"><u>SPAD</u></a> -- 2 logs
<a href="#"><u>CFC</u></a> -- 1 log	<a href="#"><u>SPB</u></a> -- 19 logs
<a href="#"><u>CFM</u></a> -- 1 log	<a href="#"><u>SPBM</u></a> -- 7 logs
<a href="#"><u>CLOCK</u></a> -- 1 log	<a href="#"><u>SSH</u></a> -- 64 logs
<a href="#"><u>CONFIG DATA</u></a> -- 1 log	<a href="#"><u>SSHC (SFTP and SSH Client)</u></a> -- 12 logs
<a href="#"><u>DOWNLOAD</u></a> -- 1 log	<a href="#"><u>SSH Client</u></a> -- 12 logs
<a href="#"><u>ENTMIB</u></a> -- 1 log	<a href="#"><u>SSL</u></a> -- 9 logs
<a href="#"><u>Exception</u></a> -- 1 log	<a href="#"><u>Stack Manager</u></a> -- 38 logs
<a href="#"><u>Inband IP address</u></a> -- 1 log	<a href="#"><u>Stack Monitor</u></a> -- 19 logs
<a href="#"><u>IPMGR</u></a> -- 1 log	<a href="#"><u>STP</u></a> -- 47 logs
<a href="#"><u>IPSEC</u></a> -- 1 log	<a href="#"><u>SWEXCEPTION</u></a> -- 1 log
<a href="#"><u>IPv4 Routing</u></a> -- 1 log	<a href="#"><u>System Logging</u></a> -- 3 logs
<a href="#"><u>IPv6 Data Tunneling</u></a> -- 1 log	<a href="#"><u>TACACS</u></a> -- 32 logs
<a href="#"><u>MCFG (Second INFO BLOCK)</u></a> -- 1 log	<a href="#"><u>Telnet</u></a> -- 55 logs
<a href="#"><u>MCM</u></a> -- 1 log	<a href="#"><u>Telnet server</u></a> -- 27 logs
<a href="#"><u>MCMGR, DRPMGR</u></a> -- 1 log	<a href="#"><u>TOTAL SYS UPTIME (TSU)</u></a> -- 1 log
<a href="#"><u>Memory Tool</u></a> -- 1 log	<a href="#"><u>USB</u></a> -- 4 logs
<a href="#"><u>NTP</u></a> -- 1 log	<a href="#"><u>VLACP</u></a> -- 18 logs
<a href="#"><u>PM</u></a> -- 1 log	<a href="#"><u>VLAN</u></a> -- 78 logs
<a href="#"><u>Port Mirroring</u></a> -- 1 log	<a href="#"><u>VRRP</u></a> -- 17 logs
<a href="#"><u>source</u></a> -- 1 log	<a href="#"><u>VRRPv3</u></a> -- 2 logs
<a href="#"><u>SWEXCEPTION</u></a> -- 1 log	<a href="#"><u>WEB</u></a> -- 33 logs
<a href="#"><u>TOTAL SYS UPTIME (TSU)</u></a> -- 1 log	<a href="#"><u>ZTP</u></a> -- 7 logs



# Listing of log severities

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Log severity listing

Select name of the source to see all logs that are generated by that source. Each severity page lists all the applicable logs alphabetically.

### Severities sorted by log quantity

[Information](#) --1077 logs

[Serious](#) --525 logs

[Critical](#) --184 logs

[Warning](#) --25 logs

[Minor](#) --16 logs

[Error](#) --10 logs

[Inform](#) --7 logs

[Major](#) --3 logs

[Warning/Information](#) --2 logs

[Console](#) -- 1 log

[Serious/Critical](#) -- 1 log

[severity](#) -- 1 log

### Severities sorted alphabetically

[Console](#) -- 1 log

[Critical](#) -- 184 logs

[Error](#) -- 10 logs

[Inform](#) -- 7 logs

[Information](#) -- 1077 logs

[Major](#) -- 3 logs

[Minor](#) -- 16 logs

[Serious](#) -- 525 logs

[Serious/Critical](#) -- 1 log

[severity](#) -- 1 log

[Warning](#) -- 25 logs

[Warning/Information](#) -- 2 logs

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Logs starting with A

This page lists all logs that have a starting letter of A. Select the log you wish to view or navigate to a different starting letter.

Using your browser's 'find' function on this page may help you locate a specific log name faster.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

- [AAUR - Info: AAUR default](#)
- [AAUR-Info AAUR default](#)
- [AAUR - Info: AAUR disable](#)
- [AAUR-Info AAUR disable](#)
- [AAUR - Info: AAUR enable](#)
- [AAUR-Info AAUR enable](#)
- [AAUR - Info: Agent transfer finished](#)
- [AAUR-Info Agent transfer finished](#)
- [AAUR - Info: Receive request for agent image, start transfer](#)
- [AAUR-Info Receive request for agent image start transfer](#)
- [AAUR - Info: Receive request for agent image, Unable to start transfer](#)
- [AAUR-Info Receive request for agent image, Unable to start transfer](#)
- [AAUR-Info Send request for new agent image](#)
- [AAUR - Info: Slave refuse transfer](#)
- [AAUR-Info Slave refuse transfer](#)
- [AAUR - Info: Start receive image](#)
- [AAUR-Info The hardware is not compatible with the image version number version](#)
- [AAUR - The hardware is not compatible with the %s version](#)
- [AAUR - Warning Agent image check sum ERROR](#)
- [AAUR - Warning: Agent image check sum ERROR](#)
- [AAUR - Warning: Agent image hash ERROR](#)
- [AAUR - Warning: Cannot get FLASH resource](#)
- [AAUR-Warning Cannot get FLASH resource](#)
- [AAUR - Warning Slave agent image check sum ERROR](#)
- [AAUR - Warning: Slave agent image check sum ERROR](#)
- [AAUR - Warning: Slave agent image hash ERROR](#)
- [Access assignment distribution across stack failed](#)
- [Access assignment modifications not supported](#)
- [Access assignment modification support limited](#)
- [Access assignment name contains unacceptable characters](#)
- [Access assignment name length outside of acceptable limits](#)
- [Access assignment name not acceptable - reserved](#)
- [Access assignment template still in use \(siblings active\)](#)
- [Access element block label contains unacceptable characters](#)
- [Access element block label length outside of acceptable limits](#)
- [Access element cluster count \( cluster count \) exceeds limit \( cluster limit \)](#)
- [Access element cluster count \(%d\) exceeds limit \(%d\)](#)
- [Access element cluster is referenced \(addition prohibited\)](#)
- [Access element cluster is referenced \(deletion prohibited\)](#)
- [Access element distribution across stack failed](#)
- [Access element modifications not supported](#)
- [Access element name contains unacceptable characters](#)
- [Access element name length outside of acceptable limits](#)
- [Access element name not acceptable - reserved](#)
- [Accessing information that has not been initialized.](#)

[Access not granted. Contact \[www.extremenetworks.com\]\(http://www.extremenetworks.com\) to update Software license.](#)

- [Action not supported](#)
- [ADAC: ADAC of IP Phones not functional](#)
- [ADAC: ADAC of Nortel IP Phones not functional](#)
- [ADAC: Error applying main %s configuration](#)
- [ADAC Error applying main VLAN QoS configuration](#)
- [ADAC: Error applying %s configuration for unit/port: %d/%d](#)
- [ADAC Error applying VLAN QoS configuration for unit port unit# port#](#)
- [ADAC Error forcing administrative state to disable enable](#)
- [ADAC: Error forcing administrative state to %s](#)
- [ADAC: Error registering CDT handlers](#)
- [ADAC: Error removing main %s configuration](#)
- [ADAC Error removing main VLAN QoS configuration](#)
- [ADAC: Error removing %s configuration for unit/port: %d/%d](#)
- [ADAC Error removing VLAN QoS configuration for unit port unit# port#](#)
- [ADAC Forced administrative state to disable enable](#)
- [ADAC: Forced administrative state to %s](#)
- [ADAC System operationally disable enable](#)
- [ADAC: System operationally %s](#)
- [Additional metering data needed for specified metering mode](#)
- [address add was aborted. \(an event callback instructed the driver to remove the address\)](#)
- [address add was aborted. \(the address was being inserted into an inactive FID. code=%d\)](#)
- [After agent change message became invalid:](#)
- [After agent change message became invalid:](#)
- [Agent configuration distribution across stack failed](#)
- [!Alert! file=%s line=%d msg=%s](#)
- [Allowed connection attempt from user :](#)
- [Another BU tried to join the stack. Unit ignored](#)
- [An SPBM instance must be configured before the requested operation can proceed](#)
- [application-name failed DB-exchange stack failed to form](#)
- [application\\_name failed DB-exchange stack formation delayed](#)
- [application-name failed DB-exchange stack formation delayed](#)
- [App-Telemetry: Configuration file missing or cannot be read. No config file will be used](#)
- [App-Telemetry: Default configuration file is missing](#)
- [App-Telemetry: Default configuration file loaded](#)
- [App-Telemetry: Maximum number of entries has been reached](#)
- [App-Telemetry: Parse error detected in policy file at line](#)
- [App-Telemetry: Policy file is empty](#)
- [App-Telemetry: User configuration file loaded](#)
- [ASCFG - Error: Failed to get file from TFTP](#)
- [ASCFG - Error: Failed to get file from USB](#)
- [ASCFG - Error: Failed to get script buffer](#)
- [ASCFG - Error: Failed to get the flash resource](#)
- [ASCFG - Error: Failed to give sem semBAutoSaveAscDone](#)
- [ASCFG - Error: Failed to init ascii file system](#)
- [ASCFG - Error: Failed to malloc memory for ram drive](#)
- [ASCFG - Error: Failed to open ascii file system](#)
- [ASCFG - Error: Failed to open record file](#)
- [ASCFG - Error: Failed to open script file](#)
- [ASCFG - Error: Failed to read record file](#)
- [ASCFG - Error: Failed to read script file](#)
- [ASCFG - Error: Failed to release the flash resource](#)
- [ASCFG - Error: Failed to run script file](#)
- [ASCFG - Error: Failed to save ascii file system](#)
- [ASCFG - Error: Failed to send msg to ascfg queue](#)
- [ASCFG - Error: Failed to send notice to NBU](#)
- [ASCFG - Error: Failed to take sem semBAutoSaveAscDone](#)
- [ASCFG - Error: Failed to update the status](#)
- [ASCFG - Error: Failed to write record file](#)
- [ASCFG - Error: Failed to write script file](#)
- [ASCFG - Error: File larger max file size](#)
- [ASCFG - Error: Invalid file system. Init](#)
- [ASCFG - Error: Invalid file system. Init](#)
- [ASCFG - Error: Invalid script entry 0](#)
- [ASCFG - Error: Invalid script entry 1](#)

- [ASCFG - Info: Run Boot Script Successfully](#)
- [ASCII failed](#)
- [ASCII finished successfully](#)
- [ASCII finished successfully at load on boot](#)
- [ASCII transfer failed](#)
- [ASCII transfer failed at load on boot](#)
- [ASCII transfer OK](#)
- [ASCII transfer OK at load on boot](#)
- [Assertion Failure in bcm\\_l3\\_hit\\_check- l3sw ip=%#x.l3hw ip=%#x](#)
- [ASTP debug: %d - %d - %x](#)
- [ASTP error: %d - %d - %d](#)
- [ASTP state: %d - %d - %d](#)
- [Attempt to create an element that already exists \(prohibited\)](#)
- [Attempt to delete modify non-existing element \(prohibited\)](#)
- [Attempt to delete/modify non-existing element \(prohibited\)](#)
- [Attempt to delete referenced NSNA filter set \(prohibited\)](#)
- [Attempt to delete referenced UBP filter set \(prohibited\)](#)
- [Attempt to manipulate system-owned interface \(prohibited\)](#)
- [Attempt to manipulate user policy data rejected \(disabled\)](#)
- [Audit commit failed \(cannot erase flash sector\(s\)\)](#)
- [Audit commit failed \(cannot take audit semaphore\)](#)
- [Audit commit failed \(cannot take flash semaphore\)](#)
- [Audit commit failed \(cannot write flash sector\(s\)\)](#)
- [Audit data initialized \(bad checksum\)](#)
- [Audit data initialized \(bad magic number\)](#)
- [Audit log disabled](#)
- [Audit log enabled](#)
- [Audit message add failed \(audit header too long\)](#)
- [Audit message send failed \(cannot resend data to remote syslog server\)](#)
- [Audit message send failed \(cannot send data to remote syslog server\)](#)
- [AUR - Error: Checksum Error. Could not restore the old config. Using the default cfg](#)
- [AUR - Error: Failed process MAC](#)
- [AUR - Error: Failed to cancel delay watchdog timer](#)
- [AUR - Error: Failed to cancel process watchdog timer](#)
- [AUR - Error: Failed to cancel watchdog timer](#)
- [AUR - Error: Failed to create a new MAC record](#)
- [AUR - Error: Failed to create message queue](#)
- [AUR - Error: Failed to create watchdog timer](#)
- [AUR - Error: Failed to disable AUR](#)
- [AUR - Error: Failed to enable AUR](#)
- [AUR - Error: Failed to get an imc buffer](#)
- [AUR - Error: Failed to save data to NBU](#)
- [AUR - Error: Failed to send msg to IMC](#)
- [AUR - Error: Failed to spawn cfgso task](#)
- [AUR - Error: Failed to start delay watchdog timer](#)
- [AUR - Error: Failed to start process watchdog timer](#)
- [AUR - Error: Failed to start watchdog timer](#)
- [AUR - Error: file not close](#)
- [AUR - Error: File not open](#)
- [AUR - Error: File not read](#)
- [AUR - Error: File not write](#)
- [AUR - Error: Invalid value](#)
- [AUR - Error: Next BU ID is 0](#)
- [AUR-Info AUR disable](#)
- [AUR-Info AUR enable](#)
- [AUR - Info: AUR Restored to default](#)
- [AUR-Info AUR Restored to default](#)
- [AUR - Info: Base Unit refused configuration transfer](#)
- [AUR - Info: Busy - Wait for the next sync](#)
- [AUR - Info: Configuration transfer finished](#)
- [AUR - Info: Configuration transfer from Unit %d finished](#)
- [AUR - Info: Configuration transfer to Base Unit finished](#)
- [AUR - Info: Configuration transfer to Unit %d finished](#)
- [AUR - Info: Do MIRROR](#)
- [AUR - Info: Do Restore](#)

- [AUR - Info: New unit has different HW config. Using cfg from the new unit](#)
- [AUR-Info New unit has different HW config Using cfg from the new unit](#)
- [AUR - Info: No VALID INACTIVE - do MIRROR](#)
- [AUR - Info: process flash sync](#)
- [AUR - Info: Receive request for configuration transfer. Start transfer](#)
- [AUR - Info: Receive request for configuration transfer. Unable to start transfer](#)
- [AUR - Info: same MAC - do MIRROR](#)
- [AUR - Info: Send configuration request to restore Base Unit](#)
- [AUR - Info: Send configuration to restore Unit %d](#)
- [AUR - Info: sending MAC to slave](#)
- [AUR - Info: Slave Unit %d refused configuration transfer](#)
- [AUR - Warning: Cannot get FLASH resource](#)
- [AUR - Warning: Configuration check sum ERROR](#)
- [AUR - Warning: Delay Watchdog timer expire](#)
- [AUR - Warning: Invalid Msg.Id](#)
- [AUR - Warning: No matched MAC](#)
- [AUR - Warning: Process Watchdog timer expire](#)
- [AUR - Warning: Watchdog timer expire](#)
- [Authentication Failure Trap](#)
- [AutoQoS mode enable failure - inadequate resources](#)
- [Auto-renew for CA %s failed with message: %s](#)
- [Auto-renew for CA %s was successful](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Logs starting with B

This page lists all logs that have a starting letter of B. Select the log you wish to view or navigate to a different starting letter.

Using your browser's 'find' function on this page may help you locate a specific log name faster.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

- [Backup configuration block %d in use](#)
- [Backup Configuration files are corrupted. Restored to default](#)
- [Backup configuration restored from primary configuration block %d](#)
- [Backup configuration updated for next active configuration block %d](#)
- [Backup Configuration Version is updated](#)
- [Bad Param %d](#)
- [Base action distribution across stack failed](#)
- [Base action entry referenced by clfr block \(deletion prohibited\)](#)
- [Base action entry referenced by meter \(deletion prohibited\)](#)
- [Base action entry referenced by policy \(deletion prohibited\)](#)
- [Base action extension identifier invalid](#)
- [Base action modification prohibited due to action usage](#)
- [Base action modifications not supported](#)
- [Base requesting re-discovery, this unit becoming base](#)
- [Base unit has loopback port mode %s and the current unit %s. Unit reconfigured and rebooted](#)
- [BaySec cdtInit 0x%0x 0x%0x 0x%0x](#)
- [BaySec cdtIntruder 0x%0x 0x%0x 0x%0x](#)
- [BaySec cdtMigrate 0x%0x 0x%0x 0x%0x](#)
- [BaySec cdtNewMac 0x%0x 0x%0x 0x%0x](#)
- [BaySec Exceeded number MAC addresses on unit# port#](#)
- [BaySec IMC cmd error %0x](#)
- [BaySec msgQ error: 0x%x](#)
- [BaySec Not enough resource on port port# . Check OOS cfg](#)
- [Bay Secure:](#)
- [Bay Secure: add](#)
- [Bay Secure: current=%d localPortMacNumber=%d](#)
- [Bay Secure: del](#)
- [Bay Secure: del \(entry\)](#)
- [Bay Secure: del\(LINK-DOWN\)](#)
- [Bay Secure: error](#)
- [Bay Secure error line line# # of octets read from NVRAM](#)
- [Bay Secure: Exceeded %d per-port MAC addresses](#)
- [Bay Secure: Exceeded %d per-trunk MAC addresses on trunk %d](#)
- [Bay Secure Exceeded number per-port MAC addresses on port unit# port#](#)
- [Bay Secure intruder](#)
- [Bay Secure intruder MAC](#)
- [Bay Secure MAC DA filtering not enough resources](#)
- [Bay Secure: MAC DA filtering not enough resources](#)
- [Bay Secure per-port address deleted:](#)
- [Bay Secure per-port addresses deleted](#)
- [Bay Secure Policy Error error type line line# 0](#)
- [Bay Secure Policy Error %s line %u 0x%X](#)
- [Bay Secure Resource Error error# line line# resource ID](#)
- [Bay Secure Resource Error %s line %u 0x%X](#)
- [Bay Secure %s line %u 0x%X](#)



[BECOME\\_TEMP\\_BU event sent unit mask value appl mask value](#)

- [Boot: system boot status 0x%x](#)
- [BPDU received on port with BPDU-Filtering enabled.](#)
- [BPDU received on port with BPDU-Filtering enabled. Port %d has been disabled](#)
- [Broadcast block unit/port %d/%d level %u watermark %u](#)
- [Broadcast over high watermark unit/port %d/%d level %u watermark %u](#)
- [Broadcast still blocked unit/port %d/%d level %u watermark %u](#)
- [Broadcast still over low watermark unit/port %d/%d level %u watermark %u](#)
- [Broadcast unblock unit/port %d/%d level %u watermark %u](#)
- [Broadcast under low watermark unit/port %d/%d level %u watermark %u](#)
- [Buffer configuration inconsistency detected \(local buffer conf stack buffer conf \)](#)
- [Buffer configuration inconsistency detected \(local %d, stack %d\)](#)
- [BU was unable to send IMC for NBUs VLAN/Port configuration](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Logs starting with C

This page lists all logs that have a starting letter of C. Select the log you wish to view or navigate to a different starting letter.

Using your browser's 'find' function on this page may help you locate a specific log name faster.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

- [call to cdt api function failed due to lock timeout \(code=%d, total failures=%d, task=%s\)](#)
- [call to IDT\\_LearnAddress has failed \(code=%d, total failures=%d, errno=%x\)](#)
- [cam block lookup first 8 chars of mac=%08x, fid=0x%04x, num returned=%d](#)
- [cam database manager reached processing capacity: delaying some actions](#)
- [CAM driver control initialization failed \(code=%d,argument=%d\)](#)
- [cam driver initialization failed \(code=%d,argument=%d\)](#)
- [cam driver initialization failed \(code= error type argument= line# \)](#)
- [cam driver initialized](#)
- [cam imc allocation error \(code=%d, total failures=%d\)](#)
- [cam imc failed to receive to message queue](#)
- [cam imc failed to send to message queue \(code=%d, total failures=%d, errno=%x\)](#)
- [cam lookup error first 8 chars of mac=%08x, fid=0x%04x \(code=%d\)](#)
- [cam policies executing code that has not been completed \(code=%d\)](#)
- [cam policies initialized](#)
- [cam policy initialization failed \(code=%d,argument=%d\)](#)
- [cam policy initialization failed \(code=%d,argument=%d\)](#)
- [cam processing aborted \(code=%d,argument=0\)](#)
- [cam processing aborted \(code= error type argument= line# \)](#)
- [cam processing error \(code=%d,argument=%d\)](#)
- [cam synchronization disabled: cam will operate as standalone driver](#)
- [cam synchronization enabled](#)
- [cam synchronization temporarily disabled](#)
- [Cannot access instance data for Port # %u](#)
- [Cannot access port data for unit](#)
- [Cannot add C-VLAN to ETRF](#)
- [Cannot add C-VLAN to ISID. IGMP Snooping is enabled on C-VLAN from I-SID](#)
- [Cannot add C-VLAN with IGMP Snooping to ISID with multiple VLANs configured](#)
- [Cannot add ETRF to ISID with multiple VLANs configured](#)
- [Cannot add SWITCHED UNI to ISID. IGMP Snooping is enabled on C-VLAN from I-SID](#)
- [Cannot change metric type from wide to narrow](#)
- [Cannot change system ID with nodal MEP MIP association](#)
- [Cannot config i-sid for spbm vlan](#)
- [Cannot configure ethertype without SPBM globally enabled](#)
- [Cannot configure SPBM in non SPBM mode](#)
- [Cannot configure without loopback port available](#)
- [Cannot configure without SPBM globally enabled](#)
- [Cannot create an SPBM VLAN from a regular VLAN that has static MAC addresses](#)
- [Cannot create circuit interface on eap port](#)
- [Cannot create circuit interface on port %i. Maximum circ number exceded](#)
- [Cannot create circuit interface on unit %i port %i. Maximum circ number exceded](#)
- [Cannot create CVLAN if the indicated VLAN contains NNI](#)
- [Cannot create CVLAN on L3 VLAN](#)
- [Cannot create CVLAN on vlan: IGMP Snooping enabled and SPBM Mcast disabled](#)
- [Cannot create CVLAN on VLAN that is part of SMLT](#)
- [Cannot create dead timer for port %u](#)

- [Cannot create IS-IS interface on IST interface](#)
- [Cannot create IS-IS interface on MLT which has port member with IS-IS interface](#)
- [Cannot create IS-IS interface on port which is member of MLT with IS-IS interface](#)
- [Cannot create IS-IS interface on port with IPFIX enabled](#)
- [Cannot create IS-IS interface on private vlan isolated/promiscuous port](#)
- [Cannot create IS-IS interface on SMLT interface](#)
- [Cannot create switched UNI on NNI interface](#)
- [Cannot create transparent UNI as port belongs to at least one VLAN](#)
- [Cannot create UNI on VLAN with IGMP SNOOP enabled](#)
- [Cannot create UNI on VLAN with IPV6 VRRPV3 configured](#)
- [Cannot create UNI on VLAN with MLD SNOOP configured](#)
- [Can not create user](#)
- [Cannot delete dead timer for port %u](#)
- [Cannot delete ISID used by EAP Fail Open VLAN](#)
- [Cannot delete ISID used by EAP Guest VLAN](#)
- [Cannot delete ISID used by EAP VoIP VLAN](#)
- [Cannot delete SPBM instance, IS-IS interface is configured](#)
- [Cannot delete SPBM instance, system ID is configured](#)
- [Can not delete user, user does not exist](#)
- [Cannot disable IP Shortcut without first disabling IP routing](#)
- [Cannot disable IP Source Guard on Unit %d Port %d](#)
- [Cannot disable IP Source Guard on Unit unit# Port port#](#)
- [Cannot disable SPBM globally while i-sid and UNI configuration exists](#)
- [Cannot disable SPBM multicast - IGMP Snooping is enabled on C-VLANs](#)
- [Can not disable user, user does not exist](#)
- [Cannot enable IP Source Guard on Unit %d Port %d](#)
- [Cannot enable IS-IS interface on port with mac-security settings](#)
- [Cannot enable IS-IS interface without SPBM instance](#)
- [Cannot enable SPBM: EAP Guest, FailOpen or Voice VLANs are not default](#)
- [Cannot enable SPBM globally if next STP operation mode is RSTP](#)
- [Cannot enable SPBM globally on RSTP mode](#)
- [Cannot enable SPBM globally on stack mode](#)
- [Cannot enable SPBM globally while L3 is enabled](#)
- [Cannot enable SPBM multicast: feature unsupported](#)
- [Cannot enable SPBM multicast while unknown-mcast-no-flood is enabled](#)
- [Cannot enable SPBM while MVR is enabled](#)
- [Cannot enable SPBM while PIM is enabled](#)
- [Cannot enable the SPBM instance on a IS-IS interface configured 'UntagAll'](#)
- [Can not enable user, user does not exist](#)
- [Cannot get dead timer ID for port %u](#)
- [Cannot set dead timer to %u for port %u](#)
- [Cannot set IP source address to zero when IP Shortcut is enabled](#)
- [Cannot set SPBM instance on adac call server port](#)
- [Cannot set SPBM instance on adac phone port](#)
- [Cannot set SPBM instance on adac uplink port](#)
- [Cannot set SPBM instance on a monitor port with allow traffic disabled](#)
- [Cannot set SPBM instance on MLT which is in a CVLAN](#)
- [Cannot set SPBM instance on port of CVLAN](#)
- [Cannot set SPBM instance on transparent UNI port](#)
- [Cannot update settings with the same data](#)
- [Cannot use multicast address](#)
- [Capabilities determined by agent \(not-writable\)](#)
- [Capabilities value invalid](#)
- [CDT AgeTime set failed \(line = %d\)](#)
- [CDT MAC address mac address was removed because LAG trunk trunked has disaggregated.](#)
- [CDT MAC address mac address was removed because port port no has aggregated in LAG](#)
- [CDT The static FDB entry MAC mac address VLAN vlan Id trunk trunkId was deleted because LAG has disaggregated](#)
- [CDT The static FDB entry MAC mac address VLAN vlan id was deleted because Unit Port unit port has aggregated](#)
- [CFG - Backup Configuration files are corrupted. Restore backup from primary config.](#)
- [CFG - Backup Configuration files are corrupted. Restored to default.](#)
- [CFG - Configuration files are corrupted. Restored from backup.](#)
- [CFG - Could not acquire FLASH sem](#)
- [CFG - Could not acquire FLASH sem.](#)
- [CFG - Could not create ram copy buffer.](#)
- [CFG has No Error %d, %d, %d](#)

- [CFG layer - invalid error %d, %d, %d](#)
- [CFG - NVRAM file system check: errors detected. Please reboot the system!](#)
- [CFG - NVRAM file system check: errors detected. Restored to default.](#)
- [CFGSO - Error: Failed to cancel watchdog timer](#)
- [CFGSO - Error: Failed to create message queue](#)
- [CFGSO - Error: Failed to create watchdog timer](#)
- [CFGSO - Error: Failed to get an imc buffer](#)
- [CFGSO - Error: Failed to save data to NBU](#)
- [CFGSO - Error: Failed to send message to queue](#)
- [CFGSO - Error: Failed to spawn cfgso task](#)
- [CFGSO - Error: Failed to start watchdog timer](#)
- [CFGSO - Error: file not close](#)
- [CFGSO - Error: File not open](#)
- [CFGSO - Error: File not read](#)
- [CFGSO - Error: File not write](#)
- [CFGSO - Error: Invalid value](#)
- [CFGSO - Warning Invalid Msg Id](#)
- [CFGSO - Warning: Invalid Msg Id](#)
- [CFGSO - Warning Watchdog timer expire](#)
- [CFGSO - Warning: Watchdog timer expire](#)
- [CFM: ERROR adding port filters for VLAN %d - no resources](#)
- [CFM SPBM failed to install pdu capture filter\(s\) on port %d for vlan %d](#)
- [Change of active config block and or reset failed block-number](#)
- [Change of active config block failed %d](#)
- [Change rear-port mode before setting SPBM globally](#)
- [Classifier block component set ID out-of-range \( clfr comp set ID \)](#)
- [Classifier block component set ID out-of-range \(%d\)](#)
- [Classifier block distribution across stack failed](#)
- [Classifier block modifications not supported](#)
- [Classifier block number out-of-range \( block# \)](#)
- [Classifier block number out-of-range \(%d\)](#)
- [Classifier block precedence value not supported](#)
- [Classifier component distribution across stack failed](#)
- [Classifier component modifications not supported](#)
- [Classifier component set ID out-of-range \( clfr comp set ID \)](#)
- [Classifier component set ID out-of-range \(%d\)](#)
- [Classifier conflict \(duplicate clfr data in block\) detected](#)
- [Classifier content incompatible with target interface\(s\)](#)
- [Classifier inconsistency detected \(conflicting allocation modes\)](#)
- [Classifier set block reference out-of-range \( clfr setblock# \)](#)
- [Classifier set/block reference out-of-range \(%d\)](#)
- [Classifier type unknown](#)
- [Clearing MC unicast IMC entries, unit %d, end\\_type %s, stk\\_type %s](#)
- [Clearing VLAN entries, end\\_type %s, stk\\_type %s](#)
- [Clfr content \(system\) incompatible with target interface\(s\)](#)
- [Cli add vlan vlan id members port mask](#)
- [Cli create vlan vlan id type port](#)
- [Cli delete vlan vlan id members port mask](#)
- [Cli delete vlan vlan id type port](#)
- [CLI pswd: A unified authentication method is now used. The local switch credentials are no longer supported](#)
- [CLI pswd: Stack authentication parameter is obsolete: unified changes have been applied to both stack and switch](#)
- [CLI pswd: Stack authentication parameter is obsolete: unified changes have been applied to both stack and switch](#)
- [CLI pswd: Stack auth type RADIUS/TACACS+ won't apply partially \(stack IP addr not set\). Local user/pass used](#)
- [CLI pswd: Stack auth type RADIUS/TACACS+ won't apply partially \(switch IP addr not set\). Local user/pass used](#)
- [CLI pswd: Switch authentication parameter is obsolete: changes have not been applied](#)
- [Cli set autopvid disable](#)
- [Cli set autopvid enable](#)
- [Cli set management vlan vlan id](#)
- [Cli set ports port mask tagging disable](#)
- [Cli set ports port mask tagging enable](#)
- [Cli set pvid vlan id ports port mask](#)
- [Cli set vlan vlan id members port mask](#)
- [code execution took unexpected, but safe, execution path \(code=%d,argument=0\)](#)
- [Cold Start Trap](#)
- [Composite filter set addition failure comp filter set unknown](#)

- [Composite filter set addition failure: comp filter set unknown](#)
- [Composite filter set addition failure data consistency issue](#)
- [Composite filter set addition failure: data consistency issue](#)
- [Composite filter set addition failure data invalid](#)
- [Composite filter set addition failure: data invalid](#)
- [Composite filter set addition failure replication failure](#)
- [Composite filter set addition failure: replication failure](#)
- [Composite filter set addition failure resources unavailable](#)
- [Composite filter set addition failure: resources unavailable](#)
- [Composite filter set addition failure seed filter set unknown](#)
- [Composite filter set addition failure: seed filter set unknown](#)
- [Composite filter set creation failure data invalid](#)
- [Composite filter set creation failure: data invalid](#)
- [Composite filter set creation failure MAC data not allowed](#)
- [Composite filter set creation failure: MAC data not allowed](#)
- [Composite filter set creation failure replication failure](#)
- [Composite filter set creation failure: replication failure](#)
- [Composite filter set creation failure seed filter set unknown](#)
- [Composite filter set creation failure: seed filter set unknown](#)
- [Composite filter set creation failure: set already exists](#)
- [Composite filter set deletion failure base set target invalid](#)
- [Composite filter set deletion failure: base set target invalid](#)
- [Composite filter set deletion failure comp filter set unknown](#)
- [Composite filter set deletion failure: comp filter set unknown](#)
- [Composite filter set deletion failure data invalid](#)
- [Composite filter set deletion failure: data invalid](#)
- [Composite filter set deletion failure seed filter set unknown](#)
- [Composite filter set deletion failure: seed filter set unknown](#)
- [Composite filter set destruction failure data invalid](#)
- [Composite filter set destruction failure: data invalid](#)
- [Composite filter set membership limits exceeded](#)
- [Config areas already remapped on unit %d](#)
- [Configuration block %d is now in use](#)
- [Configuration does not exist](#)
- [Configuration saved to nv block # block\\_number](#)
- [Configuration saved to nv block %d](#)
- [Configured base unit detected, drop its discovery msg - %s line %d](#)
- [Conflicting action sources detected](#)
- [Conflicting egress interface and egress trunk data specified](#)
- [Conflicting master block member information detected](#)
- [Conflicting policy role policy interface index data detected](#)
- [Conflicting policy role/policy interface index data detected](#)
- [Connection closed \(failed login\) IP address:](#)
- [Connection closed \(inactivity logout\) IP address:](#)
- [Connection closed \(login timeout\) IP address:](#)
- [Connection closed \(lost connection\) IP address:](#)
- [Connection closed \(lost connection\), IP address:](#)
- [Connection closed. Maximum number of sessions reached. IP address:](#)
- [Connection closed. Maximum number of sessions reached. IP address:](#)
- [Connection closed \(user logout\), IP address:](#)
- [Cons activate vlan vlan id](#)
- [Cons add vlan vlan id port unit port](#)
- [Cons create vlan vlan id type port](#)
- [Cons delete vlan vlan id port unit port](#)
- [Cons delete vlan vlan id type port](#)
- [Cons set autopvid disable](#)
- [Cons set autopvid enable](#)
- [Cons set management vlan vlan id](#)
- [Cons set port unit port pvid vlan id](#)
- [Cons set port unit port tagging disable](#)
- [Cons set port unit port tagging enable](#)
- [Control VLAN does not exist](#)
- [COS mapping distribution across stack failed](#)
- [CoS shaping distribution across stack failed](#)
- [CoS shaping modifications not supported](#)

- [CoS shaping not supported with specified interface](#)
- [Count action distribution across stack failed](#)
- [Count action entry referenced by meter \(deletion prohibited\)](#)
- [Count action entry referenced by policy \(deletion prohibited\)](#)
- [Count action modifications not supported](#)
- [CVLAN already exists](#)
- [C-VLAN UNI already configured with same I-SID](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# All logs starting with D

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Logs starting with D

This page lists all logs that have a starting letter of D. Select the log you wish to view or navigate to a different starting letter.

Using your browser's 'find' function on this page may help you locate a specific log name faster.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

- [DAI: ARP packet with invalid IP/MAC binding dropped on untrusted port %d/%d. ARP packet has MAC source %02x-%02x-%02x-%02x-%02x-%02x](#)
- [DAI: ARP packet with invalid IP/MAC binding dropped on untrusted port %d/%d. ARP packet has MAC source %02x-%02x-%02x-%02x-%02x-%02x](#)
- [DAI ARP packet with invalid IP MAC binding dropped on untrusted port unit# port#](#)
- [DAPP-detected DoS attack blocked: unit %d \(many ports\)](#)
- [DAPP-detected DoS attack blocked: unit %d port %d](#)
- [DAPP-detected DoS attack blocked unit unit# \(many ports\)](#)
- [DAPP-detected DoS attack blocked unit unit# port port#](#)
- [DAPP resources not available \(unit %d\)](#)
- [DAPP resources not available \(unit unit# \)](#)
- [DAPP support disable failure](#)
- [DAPP support enable failure](#)
- [DAPP with statistics tracking in use \(QoS disable prohibited\)](#)
- [Data distribution class class# across stack failed](#)
- [Data distribution \(class %d\) across stack failed](#)
- [Data model version attribute value not supported](#)
- [DAUR - Info Diag transfer finished](#)
- [DAUR - Info: Diag transfer finished](#)
- [DAUR - Info Receive request for diag image start transfer](#)
- [DAUR - Info: Receive request for diag image. start transfer](#)
- [DAUR - Info: Receive request for diag image. Unable to start transfer](#)
- [DAUR - Info Receive request for diag image. Unable to transfer](#)
- [DAUR - Info Send request for new diag image](#)
- [DAUR - Info: Send request for new diag image](#)
- [DAUR - Info Slave refuse transfer](#)
- [DAUR - Info: Slave refuse transfer](#)
- [DAUR - Info Start receive image](#)
- [DAUR - Info: Start receive image](#)
- [DAUR - The hardware is not compatible with the image version number version](#)
- [DAUR - The hardware is not compatible with the %s version](#)
- [DAUR - Warning: Cannot get FLASH resource](#)
- [DAUR - Warning Diag image check sum ERROR](#)
- [DAUR - Warning: Diag image check sum ERROR](#)
- [DAUR - Warning Slave diag image check sum ERROR](#)
- [DAUR - Warning: Slave diag image check sum ERROR](#)
- [DB Ack from %s for unit #%d. mask 0x%X](#)
- [Default ifc assignment failure \[%d port\(s\)\]: ifc OoS-disabled](#)
- [Default ifc assignment failure port# port\(s\) ifc OoS-disabled](#)
- [Default VRF Name can not be changed.](#)
- [Delayed filter set installation completed \(time %d\)](#)
- [Delayed filter set installation started \(time %d\)](#)
- [Delete all interfaces before set SPBM globally](#)
- [Delete manual area before set SPBM globally](#)
- [Delete SPBM instance before set SPBM globally](#)



[Delete SPBM VLAN before set SPBM globally](#)

- [Delete summary address before set SPBM globally](#)
- [Destination MAC address and mask values out-of-sync](#)
- [Destination unit not found](#)
- [%d event sent, unit mask 0x%02X, appl mask 0x%08X](#)
- [DHCP Option 82 information could not be added to the DHCP packet because the resulting packet would be too long](#)
- [DHCP packet with mismatch MAC address dropped on un-trusted port %d/%d mac\(0x%08x\)](#)
- [DHCP packet with mismatch MAC address dropped on un-trusted port unit# port# mac\(MAC ADDRESS\)](#)
- [DHCP relay is now disabled](#)
- [DHCP reply packet received without request on port %d/%d mac\(0x%08x\)](#)
- [DHCP Snoop: DHCP ACK dropped on untrusted port %d/%d \(not allowed on untrusted port\)](#)
- [DHCP Snoop DHCP ACK dropped on untrusted port unit# port# \(not allowed on untrusted port\)](#)
- [DHCP Snoop DHCP binding table is full additional DHCP clients will not be added to the binding table](#)
- [DHCP Snoop: DHCP binding table is full, additional DHCP clients will not be added to the binding table](#)
- [DHCP Snoop: DHCP binding table is full on unit %d, additional DHCP clients will not be added on this unit](#)
- [DHCP Snoop: DHCP DISCOVER dropped on port %d/%d \(source MAC not matching client MAC\)](#)
- [DHCP Snoop: DHCP DISCOVER dropped on port %d/%d \(source MAC %02x-%02x-%02x-%02x-%02x-%02x not matching client MAC %02x-%02x-%02x-%02x-%02x-%02x\)](#)
- [DHCP Snoop: DHCP INFORM dropped on port %d/%d \(source MAC %02x-%02x-%02x-%02x-%02x-%02x not matching client MAC %02x-%02x-%02x-%02x-%02x-%02x\)](#)
- [DHCP Snoop: DHCP LEASEACTIVE dropped on untrusted port %d/%d \(not allowed on untrusted port\)](#)
- [DHCP Snoop: DHCP LEASEQUERY dropped on untrusted port %d/%d \(not allowed on untrusted port\)](#)
- [DHCP Snoop: DHCP LEASEUNASSIGNED dropped on untrusted port %d/%d \(not allowed on untrusted port\)](#)
- [DHCP Snoop: DHCP LEASEUNKNOWN dropped on untrusted port %d/%d \(not allowed on untrusted port\)](#)
- [DHCP Snoop: DHCP NAK dropped on untrusted port %d/%d \(not allowed on untrusted port\)](#)
- [DHCP Snoop DHCP NAK dropped on untrusted port unit# port# \(not allowed on untrusted port\)](#)
- [DHCP Snoop: DHCP OFFER dropped on untrusted port %d/%d \(not allowed on untrusted port\)](#)
- [DHCP Snoop DHCP OFFER dropped on untrusted port unit# port# \(not allowed on untrusted port\)](#)
- [DHCP Snoop: DHCP packet dropped on port %d/%d - static entry with the same MAC %02x-%02x-%02x-%02x-%02x-%02x in binding table](#)
- [DHCP Snoop: DHCP packet dropped on port %d/%d - static entry with the same MAC %02x-%02x-%02x-%02x-%02x-%02x in binding table](#)
- [DHCP Snoop: DHCP RELEASE/DECLINE dropped on port %d/%d \(MAC %02x-%02x-%02x-%02x-%02x-%02x does not exist in binding table\)](#)
- [DHCP Snoop: DHCP RELEASE/DECLINE dropped on port %d/%d \(MAC %02x-%02x-%02x-%02x-%02x-%02x is associated to port %d/%d\)](#)
- [DHCP Snoop: DHCP RELEASE/DECLINE dropped on untrusted port %d/%d because MAC Addr\(0x%08x\) is associated to port %d/%d](#)
- [DHCP Snoop: DHCP RELEASE/DECLINE dropped on untrusted port %d/%d \(MAC Addr\(0x%08x\) does not exist in binding table\)](#)
- [DHCP Snoop DHCP RELEASE DECLINE dropped on untrusted port unit# port# because MAC Addr\( MACaddress \) is associated to port unit# port#](#)
- [DHCP Snoop DHCP RELEASE DECLINE dropped on untrusted port unit# port# \(MAC Addr\(MACaddress \) does not exist in binding table\)](#)
- [DHCP Snoop: DHCP REPLY with MAC %02x-%02x-%02x-%02x-%02x-%02x and IP Lease %d.%d.%d.%d dropped \(no DHCP REQUEST was received\)](#)
- [DHCP Snoop: DHCP REQUEST dropped on port %d/%d \(source MAC %02x-%02x-%02x-%02x-%02x-%02x not matching client MAC %02x-%02x-%02x-%02x-%02x-%02x\)](#)
- [DHCP Snoop: DHCP REQUEST dropped on untrusted port %d/%d due to Source MAC Address \(0x%08x\) not matching DHCP client MAC Address \(0x%08x\)](#)
- [DHCP Snoop DHCP REQUEST dropped on un-trusted port unit# port# due to source MAC address\(MAC ADDRESS\) not matching DHCP client](#)
- [DHCP Snoop DHCP snooping binding table restored successfully from TFTP address](#)
- [DHCP Snoop: DHCP snooping binding table restored successfully from TFTP address](#)
- [DHCP Snoop: DHCP snooping binding table restored successfully from USB unit %d](#)
- [DHCP Snoop DHCP snooping binding table restored successfully from USB unit unit#](#)
- [DHCP Snoop: DHCP snooping binding table restore from SFTP address](#)
- [DHCP Snoop: DHCP snooping binding table restore from SFTP address](#)
- [DHCP Snoop: DHCP snooping binding table restore from TFTP address](#)
- [DHCP Snoop DHCP snooping binding table restore from TFTP address A.B.C.D IPv6 address failed](#)
- [DHCP Snoop: DHCP snooping binding table restore from USB unit %d, failed](#)
- [DHCP Snoop DHCP snooping binding table restore from USB unit unit# failed](#)
- [DHCP Snoop: DHCP snooping binding table saved successfully to SFTP address](#)
- [DHCP Snoop: DHCP snooping binding table saved successfully to SFTP address](#)
- [DHCP Snoop DHCP snooping binding table saved successfully to TFTP address](#)
- [DHCP Snoop: DHCP snooping binding table saved successfully to TFTP address](#)



- [DHCP Snoop: DHCP snooping binding table saved successfully to USB unit %d](#)
- [DHCP Snoop DHCP snooping binding table saved successfully to USB unit unit#](#)
- [DHCP Snoop: DHCP snooping binding table save to SFTP address](#)
- [DHCP Snoop: DHCP snooping binding table save to SFTP address](#)
- [DHCP Snoop: DHCP snooping binding table save to TFTP address](#)
- [DHCP Snoop DHCP snooping binding table save to TFTP address A.B.C.D IPv6 address failed](#)
- [DHCP Snoop: DHCP snooping binding table save to TFTP address, failed](#)
- [DHCP Snoop: DHCP snooping binding table save to USB unit %d, failed](#)
- [DHCP Snoop DHCP snooping binding table save to USB unit unit# failed](#)
- [DHCP Snoop: DHCP snooping binding table succesfully restored from SFTP address](#)
- [DHCP Snoop: DHCP snooping binding table succesfully restored from SFTP address](#)
- [DHCP Snoop DHCP snooping entry entry number not restored due to expired lease](#)
- [DHCP Snoop DHCP snooping entry entry number not restored due to MAC conflict](#)
- [DHCP Snoop DHCP snooping entry entry number not restored due to parsing failure](#)
- [DHCP Snoop DHCP snooping entry with MAC MacAddress not restored on invalid interface unit# port#](#)
- [DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored \(expired lease\)](#)
- [DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored \(invalid interface %d/%d\)](#)
- [DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored \(invalid Vlan %d\)](#)
- [DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored \(MAC conflict\)](#)
- [DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored on trusted interface %d/%d](#)
- [DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored \(parsing failure\)](#)
- [DHCP Snoop: DHCP snooping entry 0x%08x not restored due to expired lease](#)
- [DHCP Snoop: DHCP snooping entry 0x%08x not restored due to MAC conflict](#)
- [DHCP Snoop: DHCP snooping entry 0x%08x not restored due to parsing failure](#)
- [DHCP Snoop: DHCP snooping entry 0x%08x not restored on invalid interface %d/%d](#)
- [DHCP Snoop: DHCP snooping entry 0x%08x not restored on trusted interface %d/%d](#)
- [DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored \(invalid Vlan %d\)](#)
- [DHCP Snoop: NTP is not synchronized: external save of DHCP snooping entries not possible](#)
- [DHCP Snoop NTP is not synchronized: external save restore of DHCP snooping entries not possible](#)
- [DHCP Snoop: NTP is not synchronized: external save/restore of DHCP snooping entries not possible](#)
- [Different classifier component masks keys in block detected](#)
- [Different classifier component masks/keys in block detected](#)
- [Different enhanced secure mode settings than BU. Unit reconfigured and rebooted.](#)
- [Different spanning-tree mode configured than BU. Unit re-configured and rebooted](#)
- [Different spanning-tree mode configured than BU. Unit reconfigured and rebooted.](#)
- [Different SPBM operating mode than BU. Unit reconfigured and rebooted %s](#)
- [Disable IS-IS before set SPBM globally](#)
- [Disabling trunk ports for loop prevention:](#)
- [Disallowed connection Access Reject for user :](#)
- [Disallowed connection attempt from IP address:](#)
- [Disallowed connection attempt - too many telnet sessions](#)
- [Disallowed connection Invalid SvcType for user :](#)
- [Discovery delayed due to NSNA configuration in progress](#)
- [Discovery ignored due to agent image download in progress](#)
- [Discovery message not received](#)
- [Discovery Msg dropped, expiry time exceeded %d ticks, actual %d](#)
- [DISTRIBUTE DB event sent unit mask value appl mask value](#)
- [DMLT:%d disabled due stack failure keep unit:%d port:%d enabled](#)
- [Do not configure more than two VLANs per SPBM instance](#)
- [DosFs - Error File not closed](#)
- [Download - DL CKSUM ACK ERROR](#)
- [Download - DL HASH ACK ERROR](#)
- [Download - DL PROGRAM STATUS ACK ERROR](#)
- [Download - DL START PROGRAM FLASH ACK ERROR](#)
- [Download - Error: Failed to get FLASH sem](#)
- [Download - Error: Failed to get the dl resource.](#)
- [Download - Error: Failed to get the Reset sem](#)
- [Download - Error: Failed to send message to dlQueue](#)
- [Download - Error: Image is invalid](#)
- [Download - Error: Watchdog expire: No Ack from NBUs, download MSG # %d](#)
- [Download - Failed to get buffer](#)
- [Download - Failed to malloc for buffer](#)
- [Download - Failed to start a watchdog](#)
- [Download - Image Checksum Error](#)
- [Download - Image Hash Error](#)

- [Download - Largest mem blk < DL\\_SYSMEM\\_RESERVED](#)
- [Download – NBU: Block Checksum Error](#)
- [Download – NBU: DL\\_PROGRAM\\_STATUS: ERROR](#)
- [Download - %s image %sprogrammed successfully](#)
- [Download - TFTP timeout OR image file not found](#)
- [Download - tftpXfer failed](#)
- [Downstream direction is logically down](#)
- [Downstream direction is logically up](#)
- [Downstream Port # %u is unexpectedly logically up](#)
- [Downstream stack direction is down cable removed or neighbor powered off](#)
- [Downstream stack direction is down, cable removed or neighbor powered off](#)
- [Downstream stack direction is misconfigured](#)
- [Downstream stack direction is mis-configured](#)
- [Downstream stack direction is up cable inserted or neighbor powered on](#)
- [Downstream stack direction is up, cable inserted or neighbor powered on](#)
- [Downstream stack ports down, wait for stack ports before processing](#)
- [Downstream Stack Port # %u is logically down](#)
- [Downstream Stack Port # %u is logically up](#)
- [Downstream stack port %u is misconfigured](#)
- [DSCP mapping distribution across stack failed](#)
- [DSCP mapping modifications not supported](#)
- [DSCP remarking not supported for IPv6 \(green action\)](#)
- [DSCP remarking not supported for IPv6 \(in-profile action\)](#)
- [DSCP remarking not supported for IPv6 \(match action\)](#)
- [DSCP remarking not supported for IPv6 \(non-match action\)](#)
- [DSCP remarking not supported for IPv6 \(out-of-profile action\)](#)
- [DSCP remarking not supported for IPv6 \(red action\)](#)
- [DSCP remarking not supported for IPv6 \(yellow action\)](#)
- [DSCP value modification prohibited](#)
- [DS/L2 entry mismatch detected \(NSNA filter set data\)](#)
- [DS/L2 entry mismatch detected \(UBP filter set data\)](#)
- [Dst IP addr matching not supported with IP addr type data](#)
- [Dst Layer 4 port min max values invalid \(max must be = to min\)](#)
- [Dst Layer 4 port min/max values invalid \(max must be >= to min\)](#)
- [Dst MAC addr matching not supported with address type data](#)
- [Duplicate access asgn name type index detected \(prohibited\)](#)
- [Duplicate access asgn name/type/index detected \(prohibited\)](#)
- [Duplicate address deletion failed ipv6 address](#)
- [Duplicate address detection failed:](#)
- [Duplicate address detection succeeded:](#)
- [Duplicate address detection succeeded ipv6 address](#)
- [Duplicate classifier class values in set detected](#)
- [Duplicate DB Ack for %s\(%d\) detected](#)
- [Duplicate entry detected \(prohibited\)](#)
- [Duplicate FCoE redirection entry detected](#)
- [Duplicate FCoE redirection entry detected \(prohibited\)](#)
- [Duplicate set values in block detected](#)
- [Duplicate users \(different port, same user name\) prohibited](#)
- [Dynamic ARP could not be learned, maximum dynamic ARP limit is reached.](#)
- [Dynamic interface assignment failure \(%d/%d\)](#)
- [Dynamic role combination cannot be used in explicit assignment](#)
- [Dynamic route could not be learned, maximum dynamic route is reached.](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Logs starting with E

This page lists all logs that have a starting letter of E. Select the log you wish to view or navigate to a different starting letter.

Using your browser's 'find' function on this page may help you locate a specific log name faster.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

- [EAP: AdminfMgr Install Set Failed on port:](#)
- [EAP: AdminfMgr Install Test Failed on port:](#)
- [EAP Bad pkt id](#)
- [EAP Bad pkt len](#)
- [EAP: Bad pkt len](#)
- [EAP: cannot add Isolated %s to multiple VLANs. Port already assigned to one Private VLAN.](#)
- [EAP: cannot add Isolated %s to non-Private VLAN %d.](#)
- [EAP: cannot add non-Isolated %s to private VLAN %d.](#)
- [EAP: cannot apply contradictory Egress Vid %d on port %d.](#)
- [EAP: cannot apply contradictory Egress Vid %d on port %d.](#)
- [EAP: cannot apply Egress Vids on ADAC port %d.](#)
- [EAP: cannot apply Egress Vids on ADAC port %d.](#)
- [EAP: cannot apply inexistent Egress Vid %d on port %d.](#)
- [EAP: cannot apply inexistent Egress Vid %d on port %d.](#)
- [EAP: cannot apply inexistent Egress VLAN Name on port %d.](#)
- [EAP: cannot apply inexistent Egress VLAN Name on port %d.](#)
- [EAP: Cannot assign PVID %d. on port %d it is in another STP group](#)
- [EAP: cannot autocreate a Non-Private VLAN for Isolated %s.](#)
- [EAP: Cannot auto-create VLAN %d. it is mapped to another STP group](#)
- [EAP: Cannot enable IP source guard on port %s: DHCP snooping is not enabled globally](#)
- [EAP: Cannot enable IP source guard on port %s: the port is not a member of a DHCP Snooping enabled VLAN](#)
- [EAP: Cannot enable IP source guard on port %s: the port is not a member of an ARP Inspection enabled VLAN](#)
- [EAP: Cannot enable IP source guard on port %s: unable to apply the new setting](#)
- [EAP: Cannot set DHCP Snooping on non-autocreated VLAN %d](#)
- [EAP: Cannot set DHCP Snooping option82 on non-autocreated VLAN %d](#)
- [EAP: Cannot set Dynamic ARP Inspection on non-autocreated VLAN %d](#)
- [EAP: Cannot set IGMP Snooping on non-autocreated VLAN %d](#)
- [EAP: Cannot set IGMP Snooping on Switched UNI VLAN %d](#)
- [EAP: Cannot set option 82 subscriber ID longer than %d characters on port %d](#)
- [EAP: cannot set PVID %d to %s. VLAN is Private and port is not Isolated.](#)
- [EAP: Cannot set speed/duplex on port %s: cannot retrieve current configuration](#)
- [EAP: Cannot set speed/duplex on port %s: memory allocation error](#)
- [EAP: Cannot set speed/duplex on port %s: speed or duplex value missing](#)
- [EAP: Cannot set speed/duplex on port %s: unable to apply the new port configuration](#)
- [EAP: Cannot set speed/duplex on port %s: unsupported values](#)
- [EAP CDT Error](#)
- [EAP: CDT Error](#)
- [EAP Client blocked \(Block Subsequent MAC Authentication\): Different VID than expected](#)
- [EAP Client blocked \(Block Subsequent MAC Authentication\): Invalid VID](#)
- [EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. All bindings have been rejected](#)
- [EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. All RAVs or Bindings from RADIUS are invalid](#)
- [EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Cannot use FA bindings in Legacy networks](#)
- [EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. EAP FA context unknown network](#)
- [EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Maximum number of VLANs reached](#)
- [EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Only MHSA mode supports multiple RAVs](#)

- [EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Receiving unconfigured VLAN from Radius without Autocreate](#)
- [EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid bindings exceeded the maximum threshold of 16](#)
- [EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid bindings exceeded the maximum threshold of 94](#)
- [EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid not supported in MHMA and SHSA](#)
- [EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with different Isid from the configured one is invalid](#)
- [EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with Isid equal to 0 not supported in FA SPB networks](#)
- [EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with Isid <> 0 not supported in Standalone Proxy or Autoproxy](#)
- [EAP Client %02x:%02x:%02x:%02x:%02x:%02x: Vlan %d not created. Maximum number of VLANs reached](#)
- [EAP Could not process pkt](#)
- [EAP: Could not process pkt](#)
- [EAP: Done Read From NVRAM - readVer %d in %s: cfgVer %d](#)
- [EAP Error - Default](#)
- [EAP Error - Failed to free mac info memory](#)
- [EAP: Error initializing dynamic settings semaphore](#)
- [EAP: Error initializing semaphore](#)
- [EAP Error Radius - ifIndex not found](#)
- [EAP: Error Radius - ifIndex not found](#)
- [EAP Error: Reached maximum number of messages in the queue](#)
- [EAP Error while sending Access Violation Trap](#)
- [EAP: Error while sending Access Violation Trap](#)
- [EAP Error while sending RAV Error Trap](#)
- [EAP: Error while sending RAV Error Trap](#)
- [EAP: FA bind conflict between](#)
- [EAP Failed initialize global arrays](#)
- [EAP: Failed initialize global arrays](#)
- [EAP: Failed installing FOV UBP.](#)
- [EAP: Failed qpa-RoleAssociation on port: %s. MAC %02x:%02x:%02x:%02x:%02x:%02x](#)
- [EAP Failed qpa-RoleAssociation unitPort ifIndex macHi xx-xx macLo xx-xx-xx-xx](#)
- [EAP Failed qpa-RoleAssociation unitPort 0x%x mac %08x%04x](#)
- [EAP Failed to add host. max number of clients reached](#)
- [EAP: Failed to add host. max number of clients reached](#)
- [EAP Failed to add host. memory allocation error](#)
- [EAP: Failed to add host. memory allocation error](#)
- [EAP Failed to create dyna global arrays](#)
- [EAP: Failed to create dyna global arrays](#)
- [EAP: GVlan Deleted](#)
- [EAP: GVlan Disabled for](#)
- [EAP GVlan Disabled for unitPort ifIndex - GVlan\( vid \) in different stg\( id \)](#)
- [EAP IMC Failed to send message](#)
- [EAP: IMC Failed to send message](#)
- [EAP IMC Memory allocation error](#)
- [EAP: IMC Memory allocation error](#)
- [EAP: Invalid NRAV ID](#)
- [EAP: Invalid RAV ID](#)
- [EAP: Invalid RAV ID](#)
- [EAP: Invalid Vlan ID %d configured for port %d](#)
- [EAP Invalid Vlan ID vid configured for port num](#)
- [EAP: Mac Authenticated - port %d mac %08x%04x](#)
- [EAP: Mac AuthFail -](#)
- [EAP Mac AuthFail - unitPort <unit-portnum> macHi <xx-xx> macLo <xx-xx-xx-xx>](#)
- [EAP: Mac Deleted - Aborted - port %d mac %08x%04x](#)
- [EAP: Mac Deleted - Bkend Timeout - port %d mac %08x%04x](#)
- [EAP: Mac Deleted - Disconnected - port %d mac %08x%04x](#)
- [EAP: Mac Intruder -](#)
- [EAP: Maximum number of FA Table entries reached](#)
- [EAP Memory allocation error](#)
- [EAP: Memory allocation error](#)
- [EAP Message queue error](#)
- [EAP: Message queue error](#)
- [EAP: NEAP port %s not member of any VLAN. Added to VLAN %d for NEAP authentication](#)
- [EAP Neap port was not member of any vlan](#)
- [EAP NULL pkt to send on Success](#)

- [EAP: NULL pkt to send on Success](#)
- [EAP NVRAM open error](#)
- [EAP: NVRAM open error](#)
- [EAP NVRAM read port admin state error](#)
- [EAP: NVRAM read port admin state error](#)
- [EAP NVRAM read system admin state error](#)
- [EAP: NVRAM read system admin state error](#)
- [EAP NVRAM read system ubp state error](#)
- [EAP: NVRAM read system ubp state error](#)
- [EAP NVRAM write error](#)
- [EAP: NVRAM write error](#)
- [EAP: Pvid attribute from RADIUS ignored.](#)
- [EAP: Pvid attribute from RADIUS ignored.](#)
- [EAP: RAV not configured on switch for MHSA and Isolated %s.](#)
- [EAP Reached Mac Intruder Count](#)
- [EAP: Reached MAC intruder count on %s](#)
- [EAP: Reached maximum number of VLAN ranges for ARP inspection](#)
- [EAP: Reached maximum number of VLAN ranges for DHCP snooping](#)
- [EAP: Reached maximum number of VLAN ranges for DHCP snooping option 82](#)
- [EAP: Reached maximum number of VLAN ranges for IGMP snooping](#)
- [EAP: Receiving unsupported Auto-Create-VLAN VSA in SHSA or MHMA](#)
- [EAP Task spawn error](#)
- [EAP: Task spawn error](#)
- [EAP: Timer error](#)
- [EAP: Unable to Reserve EapAdmin Filter Resources](#)
- [EAP Unable to Reserve EapAdmin Filter Resources rc retCode unitPort ifIndex](#)
- [EAP Unable to Reserve Filter Resources rc retCode unitPort ifIndex Force- Unauthorised](#)
- [EAP: Unable to UnReserve EapAdmin Filter Resources](#)
- [EAP Unable to UnReserve EapAdmin Filter Resources rc retCode unitPort ifIndex](#)
- [EAP Unable to UnReserve Filter Resources rc retCode unitPort unit-portnum](#)
- [EAP Vlan Change Aborted](#)
- [EAP: Vlan Change Aborted. it is in another STP Group](#)
- [EAP: Vlan Change Aborted on brouter.](#)
- [EAP: Warning. trying to set DHCP Snooping on VLAN %d not from client's attributes](#)
- [EAP: Warning. trying to set DHCP Snooping option82 on VLAN %d not from client's attributes](#)
- [EAP: Warning. trying to set Dynamic ARP Inspection on VLAN %d not from client's attributes](#)
- [EAP: Warning. trying to set IGMP Snooping on VLAN %d not from client's attributes](#)
- [ECMP features disabled due to inadequate license](#)
- [ECMP features disabled due to inadequate license.](#)
- [Egp Neighbor Loss Trap](#)
- [Egp Neighbor Loss Trap](#)
- [Egress interface and egress mask are mutually exclusive](#)
- [Egress interface or trunk data is required - data missing](#)
- [Element deletion prohibited \(permanent read-only system entry\)](#)
- [Element deletion prohibited \(permanent/read-only/system entry\)](#)
- [Element enable prohibited. Please delete and re-enter data](#)
- [Element label contains unacceptable characters](#)
- [Element label length outside of acceptable limits \(max 16 chars\)](#)
- [Element label not acceptable - reserved](#)
- [Element may only be modified not created or deleted](#)
- [Element modification prohibited \(read-only or system entry\)](#)
- [Enabling trunk ports:](#)
- [Energy Saver: activated by schedule](#)
- [Energy Saver: activated by schedule](#)
- [Energy Saver: deactivated by schedule](#)
- [Energy Saver: deactivated by schedule](#)
- [Energy Saver: globally disabled](#)
- [Energy Saver: globally disabled](#)
- [Energy Saver: globally enabled](#)
- [Energy Saver: globally enabled](#)
- [Energy Saver: manually activated](#)
- [Energy Saver: manually activated](#)
- [Energy Saver: manually deactivated](#)
- [Energy Saver: manually deactivated](#)
- [Energy Saver: not applying schedule because NTP/SNTP not synchronized](#)

- [Energy Saver: not applying schedule because NTP/SNTP not synchronized](#)
- [Energy Saver: time is synchronized, applying schedule](#)
- [Energy Saver: time is synchronized, applying schedule](#)
- [Energy Server activated by schedule](#)
- [Energy Server deactivated by schedule](#)
- [Energy Server globally disabled](#)
- [Energy Server globally enabled](#)
- [Energy Server manually activated](#)
- [Energy Server manually deactivated](#)
- [Energy Server not applying schedule because SNTP not synchronized](#)
- [Energy Server time is synchronized applying schedule](#)
- [Eng Menu Generation Test - Customer Message %d](#)
- [Eng Menu Test Msg #1 : Hi there! This is 1st test message.](#)
- [Eng Menu Test Msg #2 : Hi there! This is 2st test message.](#)
- [Eng Menu Test Msg #3 : Hi there! This is 3st test message.](#)
- [Eng Menu Test Msg #4 : Hi there! This is 4st test message.](#)
- [Eng Menu Test Msg #0 : No Error](#)
- [Enterprise Specific Trap](#)
- [Enterprise Specific Trap](#)
- [Entry already exists](#)
- [Entry does not exist](#)
- [Entry is not active](#)
- [Error](#)
- [Error accessing Image File](#)
- [Error Bad Image Checksum](#)
- [Error clearing the configuration counters from flash history on unit %d](#)
- [Error: CML gw bcmx chip to modid unit %d chip %d rv %d](#)
- [Error: CML lppm\\_get unit chip %d port %d p->port 0x%x](#)
- [Error: CML received MAC with unit %d on unit %d](#)
- [Error configuring 802.1AB](#)
- [Error configuring LLDP MED policies](#)
- [Error configuring Management IP Address](#)
- [Error configuring port names](#)
- [Error copying the configuration to new flash areas on unit %d](#)
- [Error creating Data VLAN](#)
- [Error creating MLT](#)
- [Error creating Voice VLAN](#)
- [Error deleting previously created cost 1 default route](#)
- [Error deleting previously created Voice and Data VLANs](#)
- [Error disabling global DHCP relay %d](#)
- [Error disabling global DHCP relay errCode](#)
- [Error enabling ADAC](#)
- [Error enabling ADAC on ports](#)
- [Error enabling global DHCP relay %d](#)
- [Error enabling global DHCP relay errCode](#)
- [Error enabling IP Routing](#)
- [Error enabling mstp learning on all ports](#)
- [Error enabling rstp learning on all ports](#)
- [Error executing script](#)
- [Error getting VLAN info for Port's pvid](#)
- [Error in DMA transfer](#)
- [Error in q\\_smgr.c - line %d, p1 = %d, p2 = %d](#)
- [Error in XGS3 memory DMA transfer](#)
- [Error loading backup configuration block %d](#)
- [Error loading configuration block %d](#)
- [Error loading primary configuration block # block\\_number](#)
- [Error loading primary configuration block %d](#)
- [Error reading Image File](#)
- [Error reading nvq\\_ObjDescr from VLAN file](#)
- [Error reading prec from VLAN file](#)
- [Error reading vmrec from VLAN file](#)
- [Error reading vrec from VLAN file](#)
- [Error restoring from VLAN file](#)
- [Error restoring from VLAN file. Wrong nvq.Descr.devVer](#)
- [Error restoring from VLAN file. Wrong nvq.Descr.notBlank](#)



- [Error restoring management vlan to 1 or disabling ip routing](#)
- [Error restoring nvq.Descr from VLAN file](#)
- [Error restoring object from VLAN file - bad file pointer or mode](#)
- [Error restoring object from VLAN file - bad file pointer or mode.](#)
- [Error restoring object from VLAN NVRAM file](#)
- [Error restoring Port from VLAN NVRAM file](#)
- [Error restoring Ports from VLAN file](#)
- [Error restoring VLANs from VLAN file](#)
- [Error restoring VMACs from VLAN file](#)
- [Error saving configuration](#)
- [Error saving configuration to block # block\\_number](#)
- [Error saving configuration to block %d](#)
- [Error seeking object in VLAN file](#)
- [Error seeking Ports in VLAN file](#)
- [Error seeking VLANs in VLAN file](#)
- [Error seeking VMACs in VLAN file](#)
- [Error setting ADAC operating mode](#)
- [Error setting call server ports](#)
- [Error setting Data VLAN Gateway IP address and network mask](#)
- [Error setting default IP Route](#)
- [Error setting IP Office Call-Server IP address](#)
- [Error setting IP Office File-Server IP address](#)
- [Error setting Management VLAN](#)
- [Error setting poe-priority high on ports](#)
- [Error setting QoS](#)
- [Error setting spanning-tree learning to fast on all ports](#)
- [Error setting the remap flag in flash on unit %d](#)
- [Error setting uplink ports](#)
- [Error setting VLAN attributes](#)
- [Error setting VLAN Gateway IP address and network mask](#)
- [Error setting Voice VLAN Gateway IP address and network mask](#)
- [Error updating Private VLAN configuration when transitioning from](#)
- [Error updating Private VLAN configuration when trying to](#)
- [Error/Warning - Eap File Read: readVer %d in %s:cfgVer %d](#)
- [Error/Warning - Eap File signals a software downgrade:%d \(%s:%d\), default all eap settings](#)
- [Error/Warning - Eap File Version Mismatch:%d \(%s:%d\)](#)
- [Error/Warning - Eap File Write:%d \(%s:%d\)](#)
- [Error/Warning - Param:%d \(%s:%d\)](#)
- [Evaluation precedence conflict detected \(NSNA filter set data\)](#)
- [Evaluation precedence conflict detected \(UBP filter set data\)](#)
- [Evaluation precedence conflict \(Traffic Prof filter set data\)](#)
- [Evaluation precedence value required but not specified](#)
- [Event logging disabled](#)
- [Event logging enabled](#)
- [Event %s\(%d\) causes state transition to %s](#)
- [Exception tid=%p vec=%#x esf=%#x](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Logs starting with F

This page lists all logs that have a starting letter of F. Select the log you wish to view or navigate to a different starting letter.

Using your browser's 'find' function on this page may help you locate a specific log name faster.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

- [Fabric Attach: agent settings reset incomplete](#)
- [Fabric Attach: application discovery notification \(event %d\)](#)
- [Fabric Attach: application state notification \(event %d\)](#)
- [Fabric Attach: asgn activation failure \(port tagging\)](#)
- [Fabric Attach: asgn activation failure \(PVID update\)](#)
- [Fabric Attach: asgn activation failure \(switched UNI creation\)](#)
- [Fabric Attach: asgn activation failure \(VLAN creation\)](#)
- [Fabric Attach: asgn activation failure \(VLAN membership\)](#)
- [Fabric Attach: asgn rejection failure \(port PVID update\)](#)
- [Fabric Attach: asgn rejection failure \(switched UNI deletion\)](#)
- [Fabric Attach: asgn rejection failure \(VLAN deletion\)](#)
- [Fabric Attach: asgn rejection failure \(VLAN membership\)](#)
- [Fabric Attach: asgn reset issues \(%d asgns\)](#)
- [Fabric Attach: Auto Attach capabilities disabled](#)
- [Fabric Attach: Auto Attach capabilities enabled](#)
- [Fabric Attach: auto attach operations not completed \(VLAN <VID>\)](#)
- [Fabric Attach: auto provision setting not supported by platform](#)
- [Fabric Attach: binding acceptance failure \(ifc %d %d/%d\)](#)
- [Fabric Attach: binding acceptance failure \(port %d %d/%d\)](#)
- [Fabric Attach: binding acceptance failure \(port %d/%d %d/%d\)](#)
- [Fabric Attach: binding accepted \(ifc %d %d/%d\)](#)
- [Fabric Attach: binding accepted \(port %d %d/%d\)](#)
- [Fabric Attach: binding accepted \(port %d/%d %d/%d\)](#)
- [Fabric Attach: binding activation failure \(%d/%d\)](#)
- [Fabric Attach: binding activation success \(ifc %d %d/%d\)](#)
- [Fabric Attach: binding activation success \(port %d %d/%d\)](#)
- [Fabric Attach: binding activation success \(port %d/%d %d/%d\)](#)
- [Fabric Attach: binding activation success \(trunk %d %d/%d\)](#)
- [Fabric Attach: binding deactivation failure \(ifc %d %d/%d\)](#)
- [Fabric Attach: binding deactivation failure \(port %d %d/%d\)](#)
- [Fabric Attach: binding deactivation failure \(port %d/%d %d/%d\)](#)
- [Fabric Attach: binding deactivation failure \(trunk %d %d/%d\)](#)
- [Fabric Attach: binding deactivation success \(ifc %d %d/%d\)](#)
- [Fabric Attach: binding deactivation success \(port %d %d/%d\)](#)
- [Fabric Attach: binding deactivation success \(port %d/%d %d/%d\)](#)
- [Fabric Attach: binding deactivation success \(trunk %d %d/%d\)](#)
- [Fabric Attach: binding deleted \(ifc %d %d/%d\)](#)
- [Fabric Attach: binding expiration \(ifc %d %d/%d\)](#)
- [Fabric Attach: binding expiration \(port %d %d/%d\)](#)
- [Fabric Attach: binding expiration \(port %d/%d %d/%d\)](#)
- [Fabric Attach: binding updated \(ifc %d %d/%d\)](#)
- [Fabric Attach: can't transition to server from standalone mode](#)
- [Fabric Attach: can't update standalone mode setting in server mode](#)
- [Fabric Attach: client attach delete failure - Type %d \(VLAN deletion\)](#)
- [Fabric Attach: client attach delete failure - Type %d \(VLAN membership\)](#)



- [Fabric Attach: client attach install failure - Type %d \(I-SID/VLAN binding install\)](#)
- [Fabric Attach: client attach install failure - Type %d \(priority update\)](#)
- [Fabric Attach: client attach install failure - Type %d \(PVID update\)](#)
- [Fabric Attach: client attach install failure - Type %d \(tagging mode update\)](#)
- [Fabric Attach: client attach install failure - Type %d \(VLAN creation\)](#)
- [Fabric Attach: client attach install failure - Type %d \(VLAN membership\)](#)
- [Fabric Attach: client binding accepted \(%d/%d/%d\)](#)
- [Fabric Attach: client binding conflict detected \(%d/%d/%d\)](#)
- [Fabric Attach: client binding deleted \(%d/%d/%d\)](#)
- [Fabric Attach: client detection settings update failed \(type %d\)](#)
- [Fabric Attach: client settings update failed \(type %d\)](#)
- [Fabric Attach: client update requires global zero touch option be enabled](#)
- [Fabric Attach: conflicting uplink data detected](#)
- [Fabric Attach: device deleted \(port %d\)](#)
- [Fabric Attach: device deleted \(port %d/%d\)](#)
- [Fabric Attach: device deleted \(stack operations\)](#)
- [Fabric Attach: device deleted \(trunk %d port %d\)](#)
- [Fabric Attach: device deleted \(trunk %d port %d/%d\)](#)
- [Fabric Attach: device discovered \(Auth Fail - element %d port %d\)](#)
- [Fabric Attach: device discovered \(Auth Fail - element %d port %d/%d\)](#)
- [Fabric Attach: device discovered \(Auth Fail - element %d trunk %d port %d\)](#)
- [Fabric Attach: device discovered \(Auth Fail - element %d trunk %d port %d/%d\)](#)
- [Fabric Attach: device discovered \(Auth Pass - element %d port %d\)](#)
- [Fabric Attach: device discovered \(Auth Pass - element %d port %d/%d\)](#)
- [Fabric Attach: device discovered \(Auth Pass - element %d trunk %d port %d\)](#)
- [Fabric Attach: device discovered \(Auth Pass - element %d trunk %d port %d/%d\)](#)
- [Fabric Attach: device discovered \(Not Auth - element %d port %d\)](#)
- [Fabric Attach: device discovered \(Not Auth - element %d port %d/%d\)](#)
- [Fabric Attach: device discovered \(Not Auth - element %d trunk %d port %d\)](#)
- [Fabric Attach: device discovered \(Not Auth - element %d trunk %d port %d/%d\)](#)
- [Fabric Attach: device expired \(port %d\)](#)
- [Fabric Attach: device expired \(port %d/%d\)](#)
- [Fabric Attach: device expired \(trunk %d port %d\)](#)
- [Fabric Attach: device expired \(trunk %d port %d/%d\)](#)
- [Fabric Attach: EAP notification - discovery \(ifc %d type %d\)](#)
- [Fabric Attach: EAP notification - expiration \(ifc %d type %d\)](#)
- [Fabric Attach: element type updated](#)
- [Fabric Attach: expiration cleanup issue detected \(%d secs\)](#)
- [Fabric Attach: incompatible device advertisement \(port %d\)](#)
- [Fabric Attach: incompatible device advertisement \(port %d/%d\)](#)
- [Fabric Attach: incompatible \(non-EAP\) zero touch options cleared during restore](#)
- [Fabric Attach: interface-specific I-SID/VLAN assignments not allowed](#)
- [Fabric Attach: internal client \(%d/%d/%d\) creation failure](#)
- [Fabric Attach: internal client \(%d/%d/%d\) creation success](#)
- [Fabric Attach: internal client \(%d/%d/%d\) deletion failure](#)
- [Fabric Attach: internal client \(%d/%d/%d\) deletion success](#)
- [Fabric Attach: invalid client detection data \(type %d\)](#)
- [Fabric Attach: invalid client detection element type \(type %d\)](#)
- [Fabric Attach: invalid MAC address range data \(type %d\)](#)
- [Fabric Attach: invalid VLAN data \(unknown or incompatible type\)](#)
- [Fabric Attach: invalid zero touch client custom ID \(type %d\)](#)
- [Fabric Attach: invalid zero touch client description \(type %d\)](#)
- [Fabric Attach: invalid zero touch client name \(type %d\)](#)
- [Fabric Attach: invalid zero touch client options \(type %d\)](#)
- [Fabric Attach: I-SID/VLAN assignment creation failure \(unexpected\)](#)
- [Fabric Attach: I-SID/VLAN assignment deletion failure \(unexpected\)](#)
- [Fabric Attach: LLDP sync issue - add \(%d/%d/%d\)](#)
- [Fabric Attach: LLDP sync issue - delete \(%d/%d/%d\)](#)
- [Fabric Attach: LLDP sync issue - update \(%d/%d/%d\)](#)
- [Fabric Attach: local asgn - created \(%d/%d\)](#)
- [Fabric Attach: local asgn - deleted \(%d/%d\)](#)
- [Fabric Attach: management VLAN updated \(was %d, now %d\) by zero touch auto-attach](#)
- [Fabric Attach: management VLAN updated \(was <VID>, now <VID>\) by Auto Attach](#)
- [Fabric Attach: message authentication support not available](#)
- [Fabric Attach: message processing \(msgid %d\)](#)

- [Fabric Attach: multiple FA Servers detected](#)
- [Fabric Attach: non-deterministic client detection data \(type %d\)](#)
- [Fabric Attach: non-MLT trunk uplink requires MLT ID/LACP key binding \(missing\)](#)
- [Fabric Attach: NVRAM port data restore failure detected](#)
- [Fabric Attach: NVRAM port data save failure detected](#)
- [Fabric Attach: NVRAM restore failure detected](#)
- [Fabric Attach: NVRAM save failure detected](#)
- [Fabric Attach: NVRAM save success \(%d local %d remote\)](#)
- [Fabric Attach: NVRAM save success \(port-specific data\)](#)
- [Fabric Attach: operation failure detected](#)
- [Fabric Attach: operation not supported \(server-only operation\)](#)
- [Fabric Attach: operation not supported \(switch-only operation\)](#)
- [Fabric Attach: operation rejected - client-owned entry](#)
- [Fabric Attach: operation rejected - CVLAN already exists](#)
- [Fabric Attach: operation rejected - entry does not exist](#)
- [Fabric Attach: operation rejected - not supported by element type](#)
- [Fabric Attach: operation rejected - service not enabled](#)
- [Fabric Attach: operation rejected - table entry limits reached](#)
- [Fabric Attach: option incompatible with other options \(type %d\)](#)
- [Fabric Attach: port authentication update - data flushed \(MLT %d\)](#)
- [Fabric Attach: port authentication update - data flushed \(port %d\)](#)
- [Fabric Attach: port authentication update - data flushed \(port %d/%d\)](#)
- [Fabric Attach: potential incomplete binding cleanup](#)
- [Fabric Attach: primary FA Server lost](#)
- [Fabric Attach: primary FA server selected \(port %d\)](#)
- [Fabric Attach: primary FA server selected \(port %d/%d\)](#)
- [Fabric Attach: primary FA server selected \(trunk %d\)](#)
- [Fabric Attach: proxy not supported by element type](#)
- [Fabric Attach: proxy sync issue - update \(%d/%d - %d\)](#)
- [Fabric Attach: rcvd invalid I-SID/VLAN asgn state \(%d - %d/%d\)](#)
- [Fabric Attach: remote asgn - switch removal \(%d/%d/%d\)](#)
- [Fabric Attach: remote smlt peer asgn - acceptance failure \(%d/%d/%d\)](#)
- [Fabric Attach: remote smlt peer asgn - accepted \(%d/%d/%d\)](#)
- [Fabric Attach: remote smlt peer asgn - deleted \(%d/%d/%d\)](#)
- [Fabric Attach: remote smlt peer asgn - updated \(%d/%d/%d\)](#)
- [Fabric Attach: remote smlt peer removal \(%d/%d/%d\)](#)
- [Fabric Attach: remote smlt peer removal issue detected](#)
- [Fabric Attach: server asgn \(%d/%d\) rejection](#)
- [Fabric Attach: server asgn \(%d/%d\) rejection - application interactions](#)
- [Fabric Attach: server asgn \(%d/%d\) rejection - invalid binding with SPBM provisioning](#)
- [Fabric Attach: server asgn \(%d/%d\) rejection - invalid VLAN](#)
- [Fabric Attach: server asgn \(%d/%d\) rejection - no FA resources](#)
- [Fabric Attach: server asgn \(%d/%d\) rejection - no VLAN resources](#)
- [Fabric Attach: server asgn \(%d/%d\) rejection - peer acceptance](#)
- [Fabric Attach: server asgn \(<ISID>/<VID>\) rejection](#)
- [Fabric Attach: server asgn \(<ISID>/<VID>\) rejection - application interactions](#)
- [Fabric Attach: server asgn \(<ISID>/<VID>\) rejection - invalid VLAN](#)
- [Fabric Attach: server asgn \(<ISID>/<VID>\) rejection - no FA resources](#)
- [Fabric Attach: server asgn \(<ISID>/<VID>\) rejection - no VLAN resources](#)
- [Fabric Attach: server connection type change](#)
- [Fabric Attach: server connection type change \(different ports\)](#)
- [Fabric Attach: server connection type change \(different trunks\)](#)
- [Fabric Attach: server connection type change \(non-trunk to trunk\)](#)
- [Fabric Attach: server connection type change \(trunk to non-trunk\)](#)
- [Fabric Attach: service disabled](#)
- [Fabric Attach: service enabled](#)
- [Fabric Attach: specified element type not supported](#)
- [Fabric Attach: specified uplink currently a trunk member](#)
- [Fabric Attach: specified uplink currently invalid](#)
- [Fabric Attach: standalone/non-standalone proxy transition \(service reset\)](#)
- [Fabric Attach: standalone proxy unavailable when SPBM is enabled](#)
- [Fabric Attach: static uplink addition failure](#)
- [Fabric Attach: static uplink deletion failure](#)
- [Fabric Attach: switch removal issue detected \(switch %d/%d\)](#)
- [Fabric Attach: temporary I-SID/VLAN binding deletion failure](#)

- [Fabric Attach: timer-related services unavailable](#)
- [Fabric Attach: trunk link automatically enabled \(MLT %d port %d/%d\)](#)
- [Fabric Attach: trusted client bindings \(%d\) exceed limit \(%d\)](#)
- [Fabric Attach: Trusted interface update - clear \(ifc %d\)](#)
- [Fabric Attach: Trusted interface update failure - clear \(ifc %d\)](#)
- [Fabric Attach: Trusted interface update failure - set \(ifc %d\)](#)
- [Fabric Attach: Trusted interface update - set \(ifc %d\)](#)
- [Fabric Attach: unknown I-SID/VLAN asgn \(update %d/%d\)](#)
- [Fabric Attach: unknown message rcvd \(msgId %d\)](#)
- [Fabric Attach: uplink operation only supported by FA Proxy](#)
- [Fabric Attach: zero touch auto-attach capabilities disabled](#)
- [Fabric Attach: zero touch auto-attach capabilities enabled](#)
- [Fabric Attach: zero touch auto-attach failure \(DHCP initiation\)](#)
- [Fabric Attach: zero touch auto-attach failure \(mgmt VLAN update\)](#)
- [Fabric Attach: zero touch auto-attach failure \(port tagging\)](#)
- [Fabric Attach: zero touch auto-attach failure \(PVID update\)](#)
- [Fabric Attach: zero touch auto-attach failure \(VLAN creation\)](#)
- [Fabric Attach: zero touch auto-attach failure \(VLAN membership\)](#)
- [Fabric Attach: zero touch auto-attach operations not completed \(mgmt VLAN %d\)](#)
- [Fabric Attach: zero touch client already exists \(type %d\)](#)
- [Fabric Attach: zero touch client attach creation \(Type %d\) failure](#)
- [Fabric Attach: zero touch client attach creation \(Type %d\) success](#)
- [Fabric Attach: zero touch client attach deletion \(Type %d\) failure](#)
- [Fabric Attach: zero touch client attach deletion \(Type %d\) success](#)
- [Fabric Attach: zero touch client attach failure - operation not supported](#)
- [Fabric Attach: zero touch client attach failure - Type %d Port %d](#)
- [Fabric Attach: zero touch client attach failure - Type %d Port %d/%d](#)
- [Fabric Attach: zero touch client attach success - Type %d Port %d](#)
- [Fabric Attach: zero touch client attach success - Type %d Port %d/%d](#)
- [Fabric Attach: zero touch client unknown \(type %d\)](#)
- [Fabric Attach: zero touch custom client deletion rejected \(type %d referenced\)](#)
- [Fabric Attach: zero touch failure \(trusted connection\)](#)
- [Fabric Attach: zero touch mgmt VLAN distribution disabled](#)
- [Fabric Attach: zero touch mgmt VLAN distribution enabled](#)
- [Fabric Attach: zero touch option failure \(PVID update ifc %d\)](#)
- [Fabric Attach: zero touch option processing failure detected](#)
- [Fabric Attach: zero touch setting read-only for FA element type](#)
- [Failed ARP add ip addr 0xFFFFFFFF to HW hw error code](#)
- [Failed ARP add %#x/%#x to HW \(%d\).](#)
- [Failed login from IP address](#)
- [Failed login from IP address:](#)
- [Failed login from serial connection](#)
- [Failed login \(local auth\) from IP address:](#)
- [Failed login \(local auth\) from IP address:](#)
- [Failed login \(local auth\) from serial connection](#)
- [Failed login\(radius auth\) from IP add](#)
- [Failed login\(RADIUS auth\) from IP add:](#)
- [Failed login\(radius auth\) from serial conn](#)
- [Failed login\(RADIUS auth\) from serial connection](#)
- [Failed login\(TACACS+ auth\) from IP add:](#)
- [Failed login\(TACACS+ auth\) from serial connection](#)
- [Failed MVLAN\(%d\) L3 %d.%d.%d.%d](#)
- [Failed MVLAN\( vid \) L3 ip addr ip mask](#)
- [Failed route add <ip addr/ip mask> to HW <hw error code>](#)
- [Failed route add %#x/%#x nh %#x, vlan %d, port %#x to HW \(%d\).](#)
- [failed to add address to preinsertion table, table is probably full \(code=%d\)](#)
- [Failed to Create a Watchdog](#)
- [Failed to create IP intf %d:%#x in HW \(%d\).](#)
- [Failed to create IP intf vid ip addr in HW hw error code](#)
- [Failed to create paltform info task.](#)
- [Failed to create platform info message queue.](#)
- [Failed to Read Image from Memory](#)
- [Failed to restore dynamic role combination post QoS reset](#)
- [Failed to set platform info. FLASH sem not acquired.](#)
- [Fatal in %s at line %d](#)

- [FCoE controller ifIndex not set - FCoE redirection enable prohibited](#)
- [FCoE controller MAC not set - FCoE redirection enable prohibited](#)
- [FCoE controller VLAN not set - FCoE redirection enable prohibited](#)
- [FCoE FNC access disabled](#)
- [FCoE FNC access enabled](#)
- [FCoE ingress interface list content issue - ifIndex %d invalid](#)
- [FCoE redirection controller filter deletion failure detected](#)
- [FCoE redirection controller filter installation failure detected](#)
- [FCoE redirection default frame filter deletion failure detected](#)
- [FCoE redirection default frame filter installation failure detected](#)
- [FCoE redirection disable issue - incomplete FCoE entry deletion](#)
- [FCoE redirection - egress interface issue detected \(ifIndex %d\)](#)
- [FCoE redirection - egress trunk issue detected \(trunk ID %d\)](#)
- [FCoE redirection element manipulation blocked \(operation mode is disabled\)](#)
- [FCoE redirection element name contains unacceptable characters](#)
- [FCoE redirection element name length outside of acceptable limits](#)
- [FCoE redirection element name not acceptable - reserved](#)
- [FCoE redirection enable issue - incomplete FCoE entry installation](#)
- [FCoE redirection entry modification not supported](#)
- [FCoE redirection traffic filter deletion failure detected](#)
- [FCoE redirection traffic filter installation failure detected](#)
- [FCoE traffic redirection disabled](#)
- [FCoE traffic redirection enabled](#)
- [File=%s line=%d val=0x%X](#)
- [Filter control block resources exhausted](#)
- [Filter creation issue detected - in-profile action component](#)
- [Filter creation issue detected - match action component](#)
- [Filter creation issue detected - metering component](#)
- [Filter creation issue detected - non-match action component](#)
- [Filter creation issue detected - out-of-profile action component](#)
- [Filter limiting mode not supported on 5510-XX unit cannot join stack](#)
- [Filter limiting mode not supported on 5510-XX, unit cannot join stack](#)
- [Filter manager internal error encountered](#)
- [Filter manager memory resources exhausted](#)
- [Filter manager metering or policy rule space exhausted](#)
- [Filter manager metering resources exhausted](#)
- [Filter manager policy rule space potentially exhausted](#)
- [Filter manager request parameter invalid](#)
- [Filter manager statistics tracking resources exhausted](#)
- [Filter set data inconsistent \(conflicting IP/non-IP data\)](#)
- [Filter set installation timeout detected \(ID %d\)](#)
- [Filter set \(NSNA\) was not restored/installed](#)
- [Filter set requirements incompatible with target interface](#)
- [Filter set \(Traffic Profile\) was not restored/installed](#)
- [Filter set \(User Based Policy\) was not restored/installed](#)
- [First TrTCM Meter Index must be in range 1-5000](#)
- [Flash Erase Failed Sector %d Address 0x%x](#)
- [Flash Erase Warning Sector %d Address 0x%x Erase time %d ms](#)
- [Flash Erase Warning Sector %d Address 0x%x Erase time %d ms](#)
- [Flow ID filtering not supported for IPv4](#)
- [Flow ID out-of-range \(%d\)](#)
- [Flow ID out-of-range \( Flow ID \)](#)
- [FMGR: CoSQ Init - CoS Mapping: unit\(%d\)](#)
- [FMGR: CoSQ Init - CoS Queues: unit\(%d\)](#)
- [FMGR: CoSQ Init - CoS Schedule: unit\(%d\) port\(%d\)](#)
- [FMGR: CoSQ Init - end](#)
- [FMGR: CoSQ Init - HOL Cell Limit: unit\(%d\) port\(%d\)](#)
- [FMGR: CoSQ Init - HOL Packet Limit: unit\(%d\) port\(%d\)](#)
- [FMGR: CoSQ Init - IBP Cell Limit: unit\(%d\) port\(%d\)](#)
- [FMGR: CoSQ Init - IBP Discard Limit: unit\(%d\) port\(%d\)](#)
- [FMGR: CoSQ Init - IBP Packet Limit: unit\(%d\) port\(%d\)](#)
- [FMGR: CoSQ Init - Packet Maximum: unit\(%d\) port\(%d\)](#)
- [FMGR: CoSQ Init - start](#)
- [forwarding database message queue failure \(code=%d,total failures=%d,errno=%x\)](#)
- [Found MAC in NAP entry %d of %d stKCfg is "%s"](#)

- [Front-panel UI requested stack reset](#)
- [Front-panel UI selected Base unit](#)
- [Front-panel UI selected non-Base unit](#)
- [Front-panel UI selected use rear-panel base non-base switch](#)
- [Front-panel UI selected use rear-panel base/non-base switch](#)
- [FSH – Error: Calling taskLock\(\) returns Error](#)
- [FSH - Error: Failed to erase flash address %x located in the %s](#)
- [FSH – Error: Failed to erase flash sector](#)
- [FSH – Error: Failed to get flash sem. tName %x. tName %x owns sem](#)
- [FSH – Error: Failed to lock flash sector](#)
- [FSH – Error: Failed to program flash](#)
- [FSH – Error: Failed to release the flash resource](#)
- [FSH – Error: Failed to unlock flash sector](#)
- [FSH – Error: Failed to write to flash address](#)
- [FSH - Error: Failed to write to %s, at address:%x](#)
- [FSH - File not closed .:](#)
- [FSH - NULL version for next reboot \(could not get semaphore\)](#)
- [FSH - Some files are not closed. MsgType # %d](#)
- [FSH - Time to Download the Image: %d seconds](#)
- [FSH - Time to Program the Image to flash: %d seconds](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)



# All logs starting with G

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Logs starting with G

This page lists all logs that have a starting letter of G. Select the log you wish to view or navigate to a different starting letter.

Using your browser's 'find' function on this page may help you locate a specific log name faster.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

- [Gateway IP changed](#)
- [Gateway=%#x cost=%d line=%d](#)
- [General Error](#)
- [GLB – Error: Failed to get glb data sem tName: %x](#)
- [Got dynamic UBP but it's not enabled for EAP clients, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x](#)
- [Got dynamic UBP but it's not enabled for Non-EAP clients, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x](#)
- [Got UserPolicy from Radius but QosOperMode disabled - unitPort %08x%04x](#)
- [Got UserPolicy from Radius but UBP disabled - unitPort 0x%x mac %08x%04x](#)
- [Got UserPolicy from Radius but UBP disabled - unitPort 0x%x mac %08x%04x](#)
- [GWL3 failed at %d, IP %#x, vid %d unit %d \(%d\).](#)
- [GWL3 failed at %d, MAC %08x%04x, vid %d unit %d \(%d\).](#)
- [GWL3 failed at %d, NET %#x/%#x, vid %d unit %d \(%d\).](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# All logs starting with H

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Logs starting with H

This page lists all logs that have a starting letter of H. Select the log you wish to view or navigate to a different starting letter.

Using your browser's 'find' function on this page may help you locate a specific log name faster.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

- [Hello module detected %s stack direction %s](#)
- [Hello Module unable to communicate with neighbor\(s\) unit reset](#)
- [Hello Module unable to communicate with neighbor\(s\) unit reset](#)
- [Hello Module unable to communicate with neighbor\(s\). unit reset](#)
- [Hello Module unable to read from configuration file](#)
- [Hello Module unable to write to configuration file](#)
- [HMOD: error: %s line %d %d](#)
- [HMOD: error: %s line %d 0x%X](#)
- [HMOD: event received msg\\_src=0x%X num= 0x%X](#)
- [HMOD: IMC ack msg failed: status %d](#)
- [HMOD: info: %s line %d %d](#)
- [HMOD: initialized arg1= %d arg2 = %d arg3 = %d](#)
- [HMOD: queue creation failed %s line %d](#)
- [HMOD: queue rec error qid= 0x%X errno=0x%X](#)
- [HMOD: queue send error qid= 0x%X errno=0x%X](#)
- [HMOD: %s](#)
- [HMOD: semaphore creation failed %s line %d](#)
- [HMOD: %s msg send failed](#)
- [HMOD: startup event failed type: 0x%08X option: %d](#)
- [HMOD: STEG\\_GO event missed](#)
- [HMOD: 0x%X 0x%X 0x%X](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)



[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Logs starting with I

This page lists all logs that have a starting letter of I. Select the log you wish to view or navigate to a different starting letter.

Using your browser's 'find' function on this page may help you locate a specific log name faster.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

- [IDT: End](#)
- [IDT: Start](#)
- [Ifc app modification issue \(inconsistent default gateway data\)](#)
- [Ifc app modification issue \(inconsistent DHCP server data\)](#)
- [Ifc app modification issue \(inconsistent ifType data\)](#)
- [Ifc app support not currently available on interface \(%d\)](#)
- [Ifc app support not currently available on interface \( ifc# \)](#)
- [Ifc assignment issue - prec conflict \(policy %d disabled\)](#)
- [Ifc assignment issue - prec conflict \(policy policy# disabled\)](#)
- [IGAP : Acct started - Group = 0x%x, UsrIP = 0x%x, port = %d](#)
- [IGAP : Acct stopped - Group = 0x%x, UsrIP = 0x%x, port = %d](#)
- [IGAP : Enabled\(1\)/Disabled\(0\) - %d](#)
- [IGAP : Join Failed. Same m/c MAC-vlan=%d.OldGrp=0x%x.NewGrp=0x%x](#)
- [IGAP : Set Router Port - vlan = %d, port = %d](#)
- [IGAP : Stacking is not supported but detected stack!](#)
- [IGAP : User Join - Group = 0x%x, UsrIP = 0x%x, port = %d](#)
- [IGAP : User Leave - Group = 0x%x, UsrIP = 0x%x, port = %d](#)
- [IGAP : User Timeout - Group = 0x%x, UsrIP = 0x%x, port = %d](#)
- [IGMP Added reserved multicast address](#)
- [IGMP: Added reserved multicast address](#)
- [IGMP: Config. database exchanged between all units of the stack](#)
- [IGMP: Config. database received on unit %d from %d](#)
- [IGMP: Config. database sent by unit %d](#)
- [IGMP: Config. failed. Loaded to factory default](#)
- [IGMP: Config. loaded successfully](#)
- [IGMP: Dynamic router port %d added](#)
- [IGMP: Dynamic router port %d removed](#)
- [IGMP: Error sending database from unit %d](#)
- [IGMP Error sending database from unit unit#](#)
- [IGMP: Error sending group database from unit %d](#)
- [IGMP Error sending group database from unit unit#](#)
- [IGMP: Exceeded reserved multicast address range: #Addr %d \\* #VLANs %d > %d](#)
- [IGMP Exceeded reserved multicast address range #Addr numResAddrEntries+1 \\* #VLANs numActiveVLANs maxReservedRange](#)
- [IGMP: Group database received from all non-base units](#)
- [IGMP: Group database received on unit %d from %d](#)
- [IGMP: Group database sent by unit %d](#)
- [IGMP: Initialization failed: Error code %d](#)
- [IGMP Initialization failed Error code errCode](#)
- [IGMP: Initialization success](#)
- [IGMP: Join stack completed. Database synchronized](#)
- [IGMP: Last member query interval changed](#)
- [IGMP: LEAVE received for Group 0x%x on VLAN %d and port %d](#)
- [IGMP Maximum number of igmp enabled interfaces reached](#)
- [IGMP: Maximum number of igmp enabled interfaces reached](#)



- [IGMP: Mirror port %d set](#)
- [IGMP: Multicast table full, dropping streams](#)
- [IGMP: new Querier IP learned on port %d](#)
- [IGMP No hardware resource available](#)
- [IGMP: No hardware resource available](#)
- [IGMP: Not able to join stack: Error code %d](#)
- [IGMP: Policy initialization failed](#)
- [IGMP: Policy initialization success](#)
- [IGMP: Port %d added to VLAN %d](#)
- [IGMP: Port %d removed from VLAN %d](#)
- [IGMP: Proxy disabled](#)
- [IGMP: Proxy disabled on VLAN %d](#)
- [IGMP Proxy disabled on VLAN vlan#](#)
- [IGMP: Proxy enabled](#)
- [IGMP: Proxy enabled on VLAN %d](#)
- [IGMP Proxy enabled on VLAN vlan#](#)
- [IGMP: Query max response changed](#)
- [IGMP: QUERY received for Group 0x%x on VLAN %d and port %d](#)
- [IGMP: Query Time changed](#)
- [IGMP: Query Time set to %d on VLAN %d](#)
- [IGMP Query Time set to num on VLAN vlan#](#)
- [IGMP Removed reserved multicast address](#)
- [IGMP: Removed reserved multicast address](#)
- [IGMP: REPORT received for Group 0x%x on VLAN %d and port %d](#)
- [IGMP: Robust Value changed](#)
- [IGMP: Robust Value set to %d on VLAN %d](#)
- [IGMP Robust Value set to num on VLAN vlan#](#)
- [IGMP: Router Alert changed](#)
- [IGMP: Snooping disabled](#)
- [IGMP: Snooping disabled on VLAN %d](#)
- [IGMP Snooping disabled on VLAN vlan#](#)
- [IGMP: Snooping enabled](#)
- [IGMP: Snooping enabled on VLAN %d](#)
- [IGMP Snooping enabled on VLAN vlan#](#)
- [IGMP SSM Range changed](#)
- [IGMP SSM Range changed](#)
- [IGMP: SSM Range changed](#)
- [IGMP: Static Router ports](#)
- [IGMP: Trunk %d created. IGMP groups added on all trunk ports](#)
- [IGMP: Trunk %d removed. IGMP groups removed on all trunk ports](#)
- [IGMP Unable to add reserved multicast address](#)
- [IGMP: Unable to add reserved multicast address](#)
- [IGMP Unknown Multicast Filter disabled](#)
- [IGMP: Unknown Multicast Filter disabled](#)
- [IGMP Unknown Multicast Filter enabled](#)
- [IGMP: Unknown Multicast Filter enabled](#)
- [IGMP: Unknown Query received on SPBM Multicast C-VLAN](#)
- [IGMP: Version changed](#)
- [IGMP: V2 report drop on reserved GA](#)
- [IGMP: V3 report group skip on invalid GA](#)
- [IGMP: V3 report group skip on reserved GA](#)
- [IGMP V1 router ports mask](#)
- [IGMP V2 router ports mask](#)
- [IGMP: V1 router ports mask](#)
- [IGMP: V2 router ports mask](#)
- [Ignored event %s for state %s, arg: %d](#)
- [IKE CRL validate of peer %d.%d.%d.%d certificate status OK](#)
- [IKE CRL validate of peer %d.%d.%d.%d certificate status revoked](#)
- [IKE CRL validate of peer %s certificate status OK](#)
- [IKE CRL validate of peer %s certificate status revoked](#)
- [IKE CRL validation of peer %d.%d.%d.%d failed to get certificate status](#)
- [IKE CRL validation of peer %s failed to get certificate status](#)
- [IKE init done with auth-method only as PSK](#)
- [IKE OCSP validate of peer %d.%d.%d.%d certificate status OK](#)
- [IKE OCSP validate of peer %d.%d.%d.%d certificate status revoked](#)

- [IKE OCSF validate of peer %s certificate status OK](#)
- [IKE OCSF validate of peer %s certificate status revoked](#)
- [IKE OCSF validation of peer %d.%d.%d.%d failed to get certificate status](#)
- [IKE OCSF validation of peer %s failed to get certificate status](#)
- [IKE P2 SA failed status:%s](#)
- [IKE P2 SA lifetime expired. P2 SA rekey initiated. I/R: %s IAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d](#)
- [IKE P2 SA rekey due to DPD. I/R: %s IAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d](#)
- [IKE server listening for data](#)
- [IKE trust anchor created successfully](#)
- [KEv%d P1 DPD - Dead Peer Detected I/R: %s IAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d](#)
- [KEv%d P1 IPv6 SA Created. IAddr:%s status:%s](#)
- [KEv%d P2 IPv6 SA Created. IAddr:%s status:%s](#)
- [KEv%d P1 IPv6 SA Deleted. IAddr:%s status:%s](#)
- [KEv%d P2 IPv6 SA Deleted. IAddr:%s status:%s](#)
- [KEv%d P1 IPv6 SA Failed. IAddr:%s status:%s](#)
- [KEv%d P2 IPv6 SA Failed. IAddr:%s status:%s](#)
- [KEv%d P1 IPv6 SA lifetime expired. IAddr:%s status:%s](#)
- [KEv%d P1 SA Created. I/R: %s IAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d](#)
- [KEv%d P2 SA Created. I/R: %s IAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d Src Port:%d Dest Port:%d Protocol:%d status:%s](#)
- [KEv%d P2 SA Deleted. I/R: %s IAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d](#)
- [KEv%d P1 SA Deleted. I/R: %s IAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d status:%s](#)
- [KEv%d P2 SA Failed. I/R: %s IAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d Src Port: %d Dest Port: %d Protocol: %d](#)
- [KEv%d P1 SA Failed. I/R: %s IAddr:%d.%d.%d.%d rAddr: %d.%d.%d.%d status:%s](#)
- [KEv%d P1 SA lifetime expired. I/R: %s IAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d](#)
- [IMC ack pool alloc failed %s line %d](#)
- [IMC ack timeout msgType= %d imcSeq= %d ackExpected= 0x%02X](#)
- [IMC app rcv routine error, type= %s\(%d\)](#)
- [IMC buffers of size buffer size have been exhausted buffer pool size pool size](#)
- [IMC buffers of size size have been exhausted buffer pool size size](#)
- [IMC buffers of size %u have been exhausted, buffer pool size %u](#)
- [imc cam processing aborted \(code=%d,argument=0\)](#)
- [IMC destination error rcvMsgDest= %d myUnitId= %d type= %s](#)
- [IMC Error \(mem or send\)](#)
- [IMC error: %s line %d %s](#)
- [IMC IMC ackedXmt\(\) failed status= %d dest= 0x%02X](#)
- [IMC imc\\_ackReceive\(\) ackRcvd= %d rcvSrcModule= %d](#)
- [IMC imc\\_idtPacketDispatch\(\) incorrect rcvMsgType = %s\(%d\)](#)
- [IMC imc\\_idtPacketDispatch\(\) NULL routine rcvMsgType= %s\(%d\)](#)
- [IMC IMC\\_idtPktRecv\(\) high queue imcType= %s\(%d\) length = %d](#)
- [IMC IMC\\_idtPktRecv\(\) low queue imcType= %s\(%d\) length = %d](#)
- [IMC IMC\\_idtPktRecv\(\) %s line %d length = %d](#)
- [IMC incorrect message type file = %s line = %d MsgType = %s](#)
- [IMC initialized arg1= %d arg2 = %d arg3 = %d](#)
- [IMC jumbo pool alloc failed %s line %d](#)
- [IMC memory allocation error packetLength = %d file %s line %d](#)
- [IMC msg pool creation failed %s line %d](#)
- [IMC normal pool alloc failed %s line %d](#)
- [IMC normal-small pool alloc failed %s line %d](#)
- [IMC packet alloc failed %s line %d](#)
- [IMC packet length too large file = %s line = %d size = %d](#)
- [IMC pkt dump offset= %d 0x%08X 0x%08X](#)
- [IMC priority pool alloc failed %s line %d](#)
- [IMC queue creation failed %s line %d](#)
- [IMC quick buffers maximum number of tasks %d to be traced reachhead for IMC buffer of size %u](#)
- [IMC rcv checksum error rcvMsgChksum= 0x%08X calcMsgChksum= 0x%08X type= %s](#)
- [IMC rcv msg sequence error rcvMsgSeq= %d rcvMsgType= %s\(%d\)](#)
- [IMC rcv status error rcvStatus= %d rcvMsgType= %s\(%d\)](#)
- [IMC retries exceeded msgType= %d imcSeq= %d ackExpected= 0x%02X](#)
- [IMC semaphore creation failed %s line %d](#)
- [IMC sending ACK pkt\(s\) %d %s line %d](#)
- [IMC sending pkt: bad dest. 0x%02X %s line %d](#)
- [IMC sending pkt imcSeq= %d imcMsgType= %d dest= 0x%02X](#)
- [IMC send pkt error imcSeq= %d imcMsgType= %d dest= 0x%02X](#)
- [IMC send pkt fmt error imcSeq= %d imcMsgType= %d status= 0x%02X](#)

- [IMC small pool alloc failed %s line %d](#)
- [IMC source error rcvMsgSrc= %d type= %s\(%d\)](#)
- [IMC timer creation failed %s line %d](#)
- [IMC type error rcvMsgType= %s\(%d\) rcvMsgSrc= %d](#)
- [IMC version error rcvMsgVersion= %d type= %s src= %d](#)
- [Inadequate resources available for application policy criteria](#)
- [Inappropriate status transition specified](#)
- [Incompatible base action extension specified](#)
- [Incompatible classifier reference \(agent-defined clfr\)](#)
- [Incompatible data model version values \(referenced clfr data\)](#)
- [Incompatible data model version values \(referenced meter data\)](#)
- [Incompatible in-profile action \(trusted ifc\)](#)
- [Incompatible in-profile action \(unrestricted ifc\)](#)
- [Incompatible in-profile action \(untrusted ifc\)](#)
- [Incompatible in-profile action \(untrustedv4v6 ifc\)](#)
- [Incompatible match action \(trusted ifc\)](#)
- [Incompatible match action \(unrestricted ifc\)](#)
- [Incompatible match action \(untrusted ifc\)](#)
- [Incompatible match action \(untrustedv4v6 ifc\)](#)
- [Incompatible non-match action \(trusted ifc\)](#)
- [Incompatible non-match action \(unrestricted ifc\)](#)
- [Incompatible non-match action \(untrusted ifc\)](#)
- [Incompatible non-match action \(untrustedv4v6 ifc\)](#)
- [Incompatible out-of-profile action \(trusted ifc\)](#)
- [Incompatible out-of-profile action \(unrestricted ifc\)](#)
- [Incompatible out-of-profile action \(untrusted ifc\)](#)
- [Incompatible out-of-profile action \(untrustedv4v6 ifc\)](#)
- [Incompatible range requirements detected](#)
- [Incompatible StorageType specified \(re classifier\)](#)
- [Incompatible StorageType specified \(re: classifier\)](#)
- [Inconsistency detected between SPBM instance VLAN data and primary SPBM BVLAN](#)
- [Inconsistent action criteria detected across block members](#)
- [Inconsistent classifier component \( clfr comp# \) state detected](#)
- [Inconsistent classifier component \(%d\) state detected](#)
- [Inconsistent labels detected for members of same block](#)
- [Inconsistent labels detected for members of same set](#)
- [Inconsistent MAC data detected across filter set members](#)
- [Inconsistent metering criteria detected across block members](#)
- [Inconsistent value](#)
- [Index value out-of-range](#)
- [Index value out-of-range or permanent/read-only/system entry](#)
- [Info: Transceiver inserted on %s](#)
- [Info: Transceiver inserted on %s](#)
- [Info: Transceiver removed from %s](#)
- [Info: Transceiver removed from %s](#)
- [Inner VLAN ID filtering requires double tag](#)
- [Inner VLAN ID min/max values invalid \(%d !< %d\)](#)
- [Inner VLAN ID min max values invalid \( min VLAN ID ! max VLAN ID \)](#)
- [In-profile action contains conflicting data](#)
- [Insufficient dynamic UBP attributes in CoA, need ACL, UROL and SET](#)
- [Insufficient dynamic UBP attributes, need ACL, UROL and SET, port %s, MAC %02x:%02x:%02x:%02x:%02x](#)
- [Insufficient HW resources to support port role association](#)
- [Insufficient HW resources to support port/role association](#)
- [Insufficient policy space available to support access assignment](#)
- [Insufficient resources available to support policy installation](#)
- [Interface action distribution across stack failed](#)
- [Interface action entry referenced by base action](#)
- [Interface action extension identifier invalid](#)
- [Interface action modifications not supported](#)
- [Interface Application data in use \(QoS disable prohibited\)](#)
- [Interface application distribution across stack failed](#)
- [Interface application modifications not supported](#)
- [Interface application Undo failure \(app app# \)](#)
- [Interface application Undo failure \(app %d\)](#)
- [Interface assignment distribution across stack failed](#)

- [Interface assignment failure - precedence conflict detected](#)
- [Interface assignment modifications not supported](#)
- [Interface capabilities incompatible with policy data](#)
- [Interface data out-of-sync in Policy and User Policy entries](#)
- [Interface queue modifications not supported](#)
- [Interface resources inadequate to support application enable](#)
- [Interface shaping and CoS shaping conflict \(same ifc specified\)](#)
- [Interface shaping and queue shaping conflict \(same ifc specified\)](#)
- [Interface shaping distribution across stack failed](#)
- [Interface shaping modifications not supported](#)
- [Interface shaping not supported with specified interface](#)
- [Interfaces QoS-disabled \(%d on unit %d\) - restoration issue](#)
- [Interfaces QoS-disabled \( port# on unit# \) - restoration issue](#)
- [Internal Error](#)
- [Invalid access assignment type option specified](#)
- [Invalid access element type option specified](#)
- [Invalid authentication type](#)
- [Invalid classifier ID specified](#)
- [Invalid classifier reference](#)
- [Invalid classifier reference \(unknown class\)](#)
- [Invalid classifier reference \(unknown incompatible set\)](#)
- [Invalid classifier reference \(unknown/incompatible set\)](#)
- [Invalid classifier reference \(unknown instance\)](#)
- [Invalid clear QoS statistics value specified](#)
- [Invalid Configuration Block Number %d](#)
- [Invalid Configuration Magic Number](#)
- [Invalid Configuration Version Number](#)
- [Invalid CSNP interval](#)
- [Invalid DAPP state transition detected \(prohibited\)](#)
- [Invalid datapath identifier specified](#)
- [Invalid default DSCP value specified](#)
- [Invalid default packet format value specified](#)
- [Invalid destination MAC address length specified](#)
- [Invalid destination MAC address mask length specified](#)
- [Invalid drop action option specified](#)
- [Invalid drop action option specifiedInvalid drop action option specified](#)
- [Invalid drop precedence value specified \(%d\)](#)
- [Invalid drop precedence value specified \( precedence \)](#)
- [Invalid DSCP value specified \(%d\)](#)
- [Invalid DSCP value specified \( DSCP value \)](#)
- [Invalid egress interface specified \(%d\)](#)
- [Invalid egress interface specified \( ifc# \)](#)
- [Invalid egress interface tag option specified](#)
- [Invalid egress interface type specified \(%d\)](#)
- [Invalid egress interface type specified \(<ifc type>\)](#)
- [Invalid egress mask value specified](#)
- [Invalid entry creation attempted \(index %d\)](#)
- [Invalid entry creation attempted \(index index# \)](#)
- [Invalid Ethertype](#)
- [Invalid EtherType value specified \( Ether Type 0xXXXX \)](#)
- [Invalid EtherType value specified \(%04x\)](#)
- [Invalid expired session data specified](#)
- [Invalid/expired session data specified](#)
- [Invalid FCoE controller ingress interface specified](#)
- [Invalid FCoE controller MAC address specified](#)
- [Invalid FCoE controller VLAN specified](#)
- [Invalid FCoE D ID data specified](#)
- [Invalid FCoE redirection destination MAC address specified](#)
- [Invalid FCoE redirection source MAC address specified](#)
- [Invalid FCoE S ID data specified](#)
- [Invalid filter set priority value detected](#)
- [Invalid/incompatible queue reference detected](#)
- [Invalid interface found in egress mask \(%d\)](#)
- [Invalid interface found in egress mask \( egress mask bit# \)](#)
- [Invalid interface index](#)

- [Invalid interface index data specified \(%d\)](#)
- [Invalid interface index data specified \( ifc index \)](#)
- [Invalid interface index data \(system-owned\) specified](#)
- [Invalid IP address](#)
- [Invalid IP address type](#)
- [Invalid IP destination address prefix detected](#)
- [Invalid IP source address](#)
- [Invalid IP source address prefix detected](#)
- [Invalid IS-IS circuit ID](#)
- [Invalid IS-IS circuit type](#)
- [Invalid key ID](#)
- [Invalid manual area address length](#)
- [Invalid master block member value specified](#)
- [Invalid maximum inner VLAN ID value specified \(%d\)](#)
- [Invalid maximum inner VLAN ID value specified \( VLAN ID \)](#)
- [Invalid maximum VLAN ID value specified \(%d\)](#)
- [Invalid maximum VLAN ID value specified \( VLAN ID \)](#)
- [Invalid metering data \(bucket size\) specified for interface\(s\)](#)
- [Invalid metering data \(granularity\) specified for interface\(s\)](#)
- [Invalid metering data \(rate\) specified for interface\(s\)](#)
- [Invalid metering data \(srTCM trTCM\) specified for interface\(s\)](#)
- [Invalid metering data \(srTCM/trTCM\) specified for interface\(s\)](#)
- [Invalid minimum inner VLAN ID value specified \(%d\)](#)
- [Invalid minimum inner VLAN ID value specified \( VLAN ID \)](#)
- [Invalid minimum VLAN ID value specified \(%d\)](#)
- [Invalid minimum VLAN ID value specified \( VLAN ID \)](#)
- [Invalid mix of classifiers \(IPv4&IPv6\) in block detected](#)
- [Invalid mix of IP address data \(Dst IP type\) in set detected](#)
- [Invalid mix of IP address data \(Dst IP/type\) in set detected](#)
- [Invalid mix of IP and non-IP data in set detected](#)
- [Invalid mix of IP data \(IPv4 IPv6\) in set detected](#)
- [Invalid mix of IP data \(IPv4/IPv6\) in set detected](#)
- [Invalid mix of IP type data \(options/non-IP\) in set detected](#)
- [Invalid NRAV id %d, on port %d, cannot be B-VLAN](#)
- [Invalid NRAV id %d, on port %d, it isn't a SPBM VLAN](#)
- [Invalid option specified for BcastFrames attribute](#)
- [Invalid option specified for KnownIpMcast attribute](#)
- [Invalid option specified for KnownMcastFrames attribute](#)
- [Invalid option specified for KnownNonIpMcast attribute](#)
- [Invalid option specified for KnownUcastFrames attribute](#)
- [Invalid option specified for NonIpPkt attribute](#)
- [Invalid option specified for PatternIpVersion attribute](#)
- [Invalid option specified for PatternL2Format attribute](#)
- [Invalid option specified for UnknownIpMcast attribute](#)
- [Invalid option specified for UnknownMcastFrames attribute](#)
- [Invalid option specified for UnknownNonIpMcast attribute](#)
- [Invalid option specified for UnknownUcastFrames attribute](#)
- [Invalid or inconsistent value](#)
- [Invalid parameters on egress stage \(not currently supported\)](#)
- [Invalid password](#)
- [Invalid pattern data length \(untagged format\) specified](#)
- [Invalid pattern data string length specified](#)
- [Invalid pattern format data specified](#)
- [Invalid pattern position string length specified](#)
- [Invalid port](#)
- [Invalid port detected in specified port mask](#)
- [Invalid 802.1p user priority value specified \(%d\)](#)
- [Invalid 802.1p user priority value specified \( priority value \)](#)
- [Invalid RAV id %d, on port %d, cannot be B-VLAN](#)
- [Invalid RAV id %d, on port %d, it isn't a SPBM VLAN](#)
- [Invalid resetToDefaults value specified](#)
- [Invalid RXMT LSP interval](#)
- [Invalid set drop precedence value specified](#)
- [Invalid shaping data \(bucket size\) specified for interface\(s\)](#)
- [Invalid shaping data \(granularity\) specified for interface\(s\)](#)

- [Invalid shaping data \(minimum rate granularity\) specified](#)
- [Invalid shaping data \(minimum rate > maximum rate\) specified](#)
- [Invalid shaping data \(minimum rate maximum rate\) specified](#)
- [Invalid shaping data \(minimum rate\) specified](#)
- [Invalid shaping data \(rate\) specified for interface\(s\)](#)
- [Invalid source interface id](#)
- [Invalid source interface type](#)
- [Invalid source MAC address length specified](#)
- [Invalid source MAC address mask length specified](#)
- [Invalid SPF delay, should be multiple of hundred](#)
- [Invalid statistics counter identification specified](#)
- [Invalid statistics tracking value](#)
- [Invalid statistics type value](#)
- [Invalid track statistics value specified](#)
- [Invalid/unknown access assignment entry state encountered \(%d\)](#)
- [Invalid unknown access assignment entry state encountered \( entry state \)](#)
- [Invalid/unknown access element entry state encountered \(%d\)](#)
- [Invalid unknown access element entry state encountered \( entry state \)](#)
- [Invalid/unknown action entry state encountered \(%d\)](#)
- [Invalid unknown action entry state encountered \( entry state \)](#)
- [Invalid unknown bandwidth type specified](#)
- [Invalid/unknown bandwidth type specified](#)
- [Invalid/unknown classifier block entry state encountered \(%d\)](#)
- [Invalid unknown classifier block entry state encountered \( entry state \)](#)
- [Invalid/unknown CoS shaping entry state encountered \(%d\)](#)
- [Invalid unknown CoS shaping entry state encountered \( entry state \)](#)
- [Invalid/unknown count action entry state encountered \(%d\)](#)
- [Invalid/unknown DSCP mapping entry state encountered \(%d\)](#)
- [Invalid unknown DSCP mapping entry state encountered \( entry state \)](#)
- [Invalid unknown entry state \(class class# \) encountered \( entry state \)](#)
- [Invalid/unknown entry state \(class %d\) encountered \(%d\)](#)
- [Invalid/unknown FCoE redirection egress trunk ID specified](#)
- [Invalid/unknown FCoE redirection entry state encountered \(%d\)](#)
- [Invalid/unknown interface action entry state encountered \(%d\)](#)
- [Invalid unknown interface action entry state encountered \( entry state \)](#)
- [Invalid/unknown interface app entry state encountered \(%d\)](#)
- [Invalid/unknown interface app entry state encountered \(<entry state>\)](#)
- [Invalid/unknown interface assignment entry state encountered \(%d\)](#)
- [Invalid unknown interface assignment entry state encountered \( entry state \)](#)
- [Invalid/unknown interface queue entry state encountered \(%d\)](#)
- [Invalid unknown interface queue entry state encountered \( entry state \)](#)
- [Invalid/unknown interface shaping entry state encountered \(%d\)](#)
- [Invalid unknown interface shaping entry state encountered \( entry# \)](#)
- [Invalid/unknown IP filter entry state encountered \(%d\)](#)
- [Invalid unknown IP filter entry state encountered \( entry state \)](#)
- [Invalid/unknown Layer 2 filter entry state encountered \(%d\)](#)
- [Invalid unknown Layer 2 filter entry state encountered \( entry state \)](#)
- [Invalid/unknown meter entry state encountered \(%d\)](#)
- [Invalid unknown meter entry state encountered \( entry state \)](#)
- [Invalid/unknown policy entry state encountered \(%d\)](#)
- [Invalid unknown policy entry state encountered \( entry state \)](#)
- [Invalid/unknown 802.1p user priority mapping entry state \(%d\)](#)
- [Invalid unknown 802.1p user priority mapping entry state \( entry state \)](#)
- [Invalid/unknown queue set assignment entry state encountered \(%d\)](#)
- [Invalid unknown queue set assignment entry state encountered \( entry state \)](#)
- [Invalid/unknown queue shaping entry state encountered \(%d\)](#)
- [Invalid unknown queue shaping entry state encountered \( entry state \)](#)
- [Invalid/unknown queuing discipline enum specified \(%d\)](#)
- [Invalid unknown queuing discipline enum specified \( queuing discipline \)](#)
- [Invalid/unknown role combination entry state encountered \(%d\)](#)
- [Invalid unknown role combination entry state encountered \( entry state \)](#)
- [Invalid/unknown System filter entry state encountered \(%d\)](#)
- [Invalid unknown System filter entry state encountered \( entry state \)](#)
- [Invalid/unknown token bucket entry state encountered \(%d\)](#)
- [Invalid unknown token bucket entry state encountered \( entry state \)](#)



- [Invalid/unknown user policy entry state encountered \(%d\)](#)
- [Invalid unknown user policy entry state encountered \( entry state \)](#)
- [Invalid/unsupported AutoQoS mode value specified](#)
- [Invalid unsupported buffering capabilities value specified](#)
- [Invalid unsupported buffering capabilities value specified](#)
- [Invalid/unsupported classifier allocation mode specified](#)
- [Invalid/unsupported classifier meter type specified](#)
- [Invalid unsupported copy-to-cpu option specified](#)
- [Invalid/unsupported copy-to-cpu option specified](#)
- [Invalid unsupported DAPP enable value specified](#)
- [Invalid/unsupported DAPP enable value specified](#)
- [Invalid unsupported DAPP maximum IPv4 ICMP length specified](#)
- [Invalid unsupported DAPP maximum IPv6 ICMP length specified](#)
- [Invalid/unsupported DAPP maximum IPv4 ICMP length specified](#)
- [Invalid/unsupported DAPP maximum IPv6 ICMP length specified](#)
- [Invalid unsupported DAPP minimum TCP header length specified](#)
- [Invalid/unsupported DAPP minimum TCP header length specified](#)
- [Invalid unsupported default gateway address length specified](#)
- [Invalid/unsupported default gateway address length specified](#)
- [Invalid unsupported default gateway address specified](#)
- [Invalid/unsupported default gateway address specified](#)
- [Invalid unsupported destination IP address length specified](#)
- [Invalid/unsupported destination IP address length specified](#)
- [Invalid unsupported DHCP server address length specified](#)
- [Invalid/unsupported DHCP server address length specified](#)
- [Invalid unsupported DHCP server address specified](#)
- [Invalid/unsupported DHCP server address specified](#)
- [Invalid/unsupported FCoE accessibility mode value specified](#)
- [Invalid/unsupported FCoE ingress interface list specified](#)
- [Invalid/unsupported FCoE redirection egress interface specified](#)
- [Invalid/unsupported FCoE redirection etherType detected](#)
- [Invalid/unsupported FCoE redirection mode value specified](#)
- [Invalid unsupported interface type specified](#)
- [Invalid/unsupported interface type specified](#)
- [Invalid/unsupported IP address/mask length specified](#)
- [Invalid/unsupported metering mode value specified](#)
- [Invalid unsupported mirror frame option specified](#)
- [Invalid/unsupported mirror frame option specified](#)
- [Invalid unsupported NT application mode value specified](#)
- [Invalid unsupported packet type value specified](#)
- [Invalid/unsupported packet type value specified](#)
- [Invalid unsupported QoS system operational mode value specified](#)
- [Invalid/unsupported QoS system operational mode value specified](#)
- [Invalid unsupported queue configuration value specified](#)
- [Invalid/unsupported queue configuration value specified](#)
- [Invalid unsupported role assoc compatibility specified](#)
- [Invalid/unsupported role assoc compatibility specified](#)
- [Invalid unsupported source IP address length specified](#)
- [Invalid/unsupported source IP address length specified](#)
- [Invalid/unsupported stage specified](#)
- [Invalid unsupported Trusted processing mode value specified](#)
- [Invalid/unsupported Trusted processing mode value specified](#)
- [Invalid unsupported UBP support level value specified](#)
- [Invalid/unsupported UBP support level value specified](#)
- [Invalid/unsupported VLAN tag value specified \(%d\)](#)
- [Invalid unsupported VLAN tag value specified \( VLAN tag \)](#)
- [Invalid update DSCP value specified \(%d\)](#)
- [Invalid update DSCP value specified \( DSCP value \)](#)
- [Invalid update DSCP value specified \(not currently supported\)](#)
- [Invalid update priority value specified](#)
- [Invalid update VLAN Id specified \(%d\)](#)
- [Invalid update VLAN Id specified \( VLAN Id \)](#)
- [Invalid user priority match selection specified \(%d\)](#)
- [Invalid user priority match selection specified \( priority value \)](#)
- [Invalid VLAN ID](#)



- [IP blocking now %d \(1=ON,2=OFF\).](#)
- [IP blocking now 1 2 \(1=ON 2=OFF\)](#)
- [IP classifier distribution across stack failed](#)
- [IP classifier entry still referenced \(deletion prohibited\)](#)
- [IP classifier modifications not supported](#)
- [IP destination address and mask values out-of-sync](#)
- [IP destination Layer 4 port maximum value out-of-range \(%d\)](#)
- [IP destination Layer 4 port maximum value out-of-range \( dest port#](#)
- [IP destination Layer 4 port minimum value out-of-range \(%d\)](#)
- [IP destination Layer 4 port minimum value out-of-range \( dest port# \)](#)
- [IPFIX: disable failure](#)
- [IPFIX: enable fail since NSNA enabled](#)
- [IPFIX enable failure](#)
- [IPFIX: enable failure](#)
- [IPFIX: enable failure due to invalid license](#)
- [IPFIX: error setting observation port](#)
- [IPFIX: init info failure](#)
- [IPFIX: malloc failure](#)
- [IPFIX: msgQSend failure](#)
- [IPFIX: port %d/%d is NNI. IPFIX is disabled on NNI ports](#)
- [IPFIX: port %d is NNI. IPFIX is disabled on NNI ports](#)
- [IPFIX: queue create failure](#)
- [IPFIX: read from nvram failed](#)
- [IPFIX: semaphore create failure](#)
- [IPFIX: semTake failure](#)
- [IPFIX: socket failure error=%d](#)
- [IPFIX: task spawn failure](#)
- [IPFIX: timer cancel failure](#)
- [IPFIX: timer create failure](#)
- [IPFIX: timer set failure](#)
- [IPFIX: too many entries requested](#)
- [IPFIX: write to nvram failed](#)
- [IpFwdNhop Err Filter Install mod\\_inst=0x%08x vid=%d rv=%d](#)
- [IpFwdNhop Err Filter Modify mod\\_inst=0x%08x vid=%d rv=%d](#)
- [IpFwdNhop Err Filter UnInstall mod\\_inst=0x%08x vid=%d rv=%d](#)
- [IpFwdNhop Err Get NxtHopId mod\\_inst=0x%08x vid=%d nhop=0x%08x](#)
- [IpFwdNhop Err Save DB to NVRAM General File myMod=%d isBU=%d rw=%d](#)
- [IpFwdNhop Err Save DB to NVRAM Instance File myMod=%d isBU=%d rw=%d](#)
- [IpFwdNhop Err Save DB to NVRAM Policy File myMod=%d isBU=%d rw=%d](#)
- [IpFwdNhop Err Unknown](#)
- [IpFwdNhop: Feature enable temporarily blocked - resources unavailable](#)
- [IpFwdNhop: Filter installation issue - resources unavailable](#)
- [IpFwdNhop: Invalid/inconsistent VLAN admin status specified](#)
- [IpFwdNhop: Issue detected during data restore \(interface entry %d\)](#)
- [IpFwdNhop: Issue detected during enable retry \(interface entry %d\)](#)
- [IpFwdNhop: Issue detected during feature enable \(interface entry %d\)](#)
- [IpFwdNhop: Issue detected during interface creation \(interface entry %d\)](#)
- [IpFwdNhop: Issue detected during VLAN admin status enable \(VID %d\)](#)
- [IpFwdNhop: Issue detected during VLAN %d routing status update](#)
- [IpFwdNhop: Issue detected during VLAN membership addition \(VID %d\)](#)
- [IpFwdNhop: Issue detected during VLAN membership deletion \(VID %d\)](#)
- [IpFwdNhop: Issue detected during VLAN policy association \(entry %d\)](#)
- [IpFwdNhop: Requested precedence and/or filter resources unavailable](#)
- [IpFwdNhop: Requested range checking resources unavailable](#)
- [IpFwdNhop: VLAN %d admin status enable failure - resources unavailable](#)
- [IpFwdNhop: VLAN membership update \(VID %d\) issue - resources unavailable](#)
- [IP protocol value out-of-range \(%d\)](#)
- [IP protocol value out-of-range \( IP protocol# \)](#)
- [IP protocol value TCP or UDP needed with Layer 4 port filtering](#)
- [IPSEC - Packet dropped: lAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d Src Port:%d Dest Port:%d Protocol:%d](#)
- [IPSEC - Packet dropped: lAddr:%04x:%04x:%04x:%04x:%04x:%04x:%04x rAddr:%04x:%04x:%04x:%04x:%04x:%04x:%04x Src Port:%d Dest Port:%d Protocol:%d](#)
- [IPSG: Admin Cmd Event Error %x %x %x](#)
- [IPSG: Db exchange %d %d 0x%x](#)
- [IPSG: Debug %d %d 0x%x](#)

- [IPSG: DHCP Event Error %x %x %x](#)
- [IPSG: Fatal Error %d %d %d](#)
- [IPSG: IMC Error %d %d 0x%x](#)
- [IPSG: Insufficient resources available to enable IPSG on port %d/%d](#)
- [IPSG: Insufficient resources available to enable IPSG on port unit# port#](#)
- [IPSG: Invalid Stack Event %d %d %d](#)
- [IPSG: Join Stack %d %d 0x%x](#)
- [IPSG: Leave Stack %d %d 0x%x](#)
- [IPSG: Log End](#)
- [IPSG: Log Start](#)
- [IPSG: Maximum IP entries on port %d/%d has been reached](#)
- [IPSG: Maximum IP entries on port unit# port# has been reached](#)
- [IPSG: Message Queue Rcv Error %d %d %d](#)
- [IPSG: Message Queue Send Error %d %d %d](#)
- [IPSG: nvRam file error: %d %d %d](#)
- [IPSG: nvRam file error param1 param2 param3](#)
- [IPSG: Reached Max. IP entries supported on this port %d](#)
- [IPSG: Reached Max. IP entries supported on this port port#](#)
- [IPSG: Reached Max. IP entries supported on this port unit# port#](#)
- [IPSG: Reached Max. IP entries supported on this port %x/%d](#)
- [IPSG: Resource allocated for Ports unit# port#](#)
- [IPSG: Resource allocated for Ports %x %x](#)
- [IPSG: Unit %d leave stack %d 0x%x](#)
- [IP source address and mask values out-of-sync](#)
- [IP source address must be configured before enable IP SC](#)
- [IP Source Guard disabled on Unit %d Port %d](#)
- [IP Source Guard disabled on Unit unit# Port port#](#)
- [IP Source Guard enabled on Unit %d Port %d](#)
- [IP Source Guard enabled on Unit unit# Port port#](#)
- [IP source Layer 4 port maximum value out-of-range \(%d\)](#)
- [IP source Layer 4 port minimum value out-of-range \(%d\)](#)
- [IP source Layer 4 port minimum value out-of-range \( src port# \)](#)
- [IPT: BootP Disabled \(response not received from server\)](#)
- [IPT: BootP Disabled \(response not received from server\)](#)
- [IPT: error: %s line %d %d](#)
- [IPT: info: %s arg1 %d arg2 %d](#)
- [IPT: IP Address changed by BOOTP Server](#)
- [IPT: IP Address changed by BOOTP Server](#)
- [IPT: IP Address changed by DHCP Server](#)
- [IPT: IP Address not in use \(duplicate detected\)](#)
- [IPT: Join Mac Add: inStack %d, isBase %d, port id %d](#)
- [IPT: Leave Mac Add: inStack %d, isBase %d, port id %d](#)
- [IPT: MVLAN Mac Add: inStack %d, isBase %d, port id %d](#)
- [IPT: Startup Mac Add: inStack %d, isBase %d, port id %d](#)
- [IPT: Temp BU Mac Add: inStack %d, isBase %d, port id %d](#)
- [IPT: Upd NBU\(Temp BU\) Mac Add: inStack %d, isBase %d, port id %d](#)
- [IPT: Using the last BOOTP/DHCP assigned IP address \(BOOTP server not reachable\)](#)
- [IPv6 DST MAC filters could NOT be installed.](#)
- [IPv6 DST MAC filters successfully installed.](#)
- [IPv6 enabled with hardware support and FMGR filters](#)
- [IPv6 enabled with hardware support and FMGR filters.](#)
- [IPv6 enabled with hardware support only](#)
- [IPv6 enabled with hardware support only.](#)
- [IPv6 FHS filters could NOT be installed](#)
- [IPv6 FHS filters could NOT be installed](#)
- [IPv6 FHS filters successfully installed](#)
- [IPv6 FHS filters successfully installed](#)
- [IPv6 FHS nvram failure.](#)
- [IPv6 Forwarding disabled due to inadequate license](#)
- [IPv6 Forwarding disabled due to inadequate license.](#)
- [IPv6 in IPv4 tunnel SIP mismatch](#)
- [IPv6 in IPv4 tunnel SIP mismatch](#)
- [IPv6 malloc failure](#)
- [IPv6 malloc failure.](#)
- [IPv4-only filter criteria mixed with IPv6 criteria](#)

- [IPv6 over SPBM filters could NOT be installed.](#)
- [IPv6 over SPBM filters successfully installed.](#)
- [IPv6 SG filters could NOT be installed](#)
- [IPv6 SG filters could NOT be installed](#)
- [IPv6 SG filters successfully installed](#)
- [IPv6 SG filters successfully installed](#)
- [IS-IS cannot be enabled when SPBM is globally disabled](#)
- [IS-IS circuit already exists](#)
- [IS-IS circuit does not exist](#)
- [IS-IS circuit level hello timer should be in seconds](#)
- [IS-IS interface is enabled](#)
- [IS-IS interface type cannot be changed: point-to-point interface type only](#)
- [IS-IS is enabled on this interface](#)
- [IS-IS is enabled, runtime change not allowed](#)
- [IS-IS Level-2 circuits defined \(Level-1 only operation request rejected\)](#)
- [IS-IS Level-1 only operation supported](#)
- [IS-IS Level-1 operation is required for SPBM](#)
- [IS-IS manual area must be configured before the requested operation can proceed](#)
- [IS-IS max LSP generation interval must be >= to the min LSP interval](#)
- [IS-IS system ID cannot be a multicast address](#)
- [IS-IS system ID must be configured before the requested operation can proceed](#)
- [Issue detected during OoS stack synchronization](#)
- [Issue detected enabling/disabling DSCP Mapping Table usage \(port %d\)](#)
- [Issue detected enabling/disabling DSCP table usage \(port#\)](#)
- [Issue detected restoring OPA data from NV \(class class#\)](#)
- [Issue detected restoring OPA data from NV \(class %d\)](#)
- [Issue detected setting native DSCP Mapping Table values](#)
- [Issue detected setting native DSCP table values](#)
- [Issues detected with OoS operational mode disable \(%d ifcs\)](#)
- [Issues detected with OoS operational mode disable \( ifcs# ifcs\)](#)
- [Issues detected with OoS operational mode enable \(%d ifcs\)](#)
- [Issues detected with OoS operational mode enable \( ifcs# ifcs\)](#)
- [Issue with classifier component mask detected](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# All logs starting with J

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Logs starting with J

This page lists all logs that have a starting letter of J. Select the log you wish to view or navigate to a different starting letter.

Using your browser's 'find' function on this page may help you locate a specific log name faster.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

- [JOIN event sent unit mask value appl mask value](#)
- [Join event sent, unit mask 0x%02X, appl mask 0x%08X 0x%08X](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# All logs starting with K

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Logs starting with K

This page lists all logs that have a starting letter of K. Select the log you wish to view or navigate to a different starting letter.

Using your browser's 'find' function on this page may help you locate a specific log name faster.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

- [keep alive expired](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Logs starting with L

This page lists all logs that have a starting letter of L. Select the log you wish to view or navigate to a different starting letter.

Using your browser's 'find' function on this page may help you locate a specific log name faster.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

- [LAC: Allocated trunk with id %d for aggregator %d](#)
- [LAC: API error: %d-%d-%d.](#)
- [LAC: Deallocated trunk with id %d for aggregator %d](#)
- [LAC: Failed to release trunk group: %d - %d - %d](#)
- [LAC: get buffer fail: %d-%d-%d](#)
- [LAC: input parameter error: %d-%d-%d](#)
- [LAC: lac\\_log\\_add\\_link: %d - %d - %d](#)
- [LAC: lac\\_log\\_link\\_change: %d - %d - %d](#)
- [LAC: lac\\_log\\_rem\\_link: %d - %d - %d](#)
- [LAC: MLT %d error on far end.](#)
- [LAC: MLT %d error, partner aggregation bit not set.](#)
- [LAC: MLT %d error, partner expired bit set.](#)
- [LAC: MLT %d error, partner synchronization bit not set.](#)
- [LAC MLT error on far end. 0 - 0 - 0](#)
- [LAC: MLT error, partner aggregation bit not set](#)
- [LAC: MLT error, partner expired bit set.](#)
- [LAC: MLT error, partner synchronization bit not set.](#)
- [LAC: MLT remove port: unit %d, port %d, trunk group %d](#)
- [LAC: MLT set port: unit %d, port %d, trunk group %d](#)
- [LAC: msgQ error: %d-%d-%d](#)
- [LAC: Msg Type Err: %s : %d, msgid = %d](#)
- [LAC: Mux event: %d - %d - %d](#)
- [LAC No more trunk group available for LAC. 0 - 0 - 0](#)
- [LAC: No more trunk group available for LAC.](#)
- [LAC: nvRam file error %d %d](#)
- [LAC: RX event: %d - %d - %d](#)
- [LAC: Stack event: %d - %d - 0x%x](#)
- [LAC: Start](#)
- [LAC: TMR event: %d - %d - %d](#)
- [LAC: Trunk %d is disabled](#)
- [LAC: Trunk %d is enabled](#)
- [LAC: TX event: %d - %d - %d](#)
- [LAC with admin key %d failed configuration verification. Bad ARP INSPECTION configuration.](#)
- [LAC with admin key %d failed configuration verification. Bad DHCP-SNOOPING configuration.](#)
- [LAC with admin key %d failed configuration verification. Bad EGRESS settings.](#)
- [LAC with admin key %d failed configuration verification. Bad IGMP configuration.](#)
- [LAC with admin key %d failed configuration verification. Bad MAC Security configuration.](#)
- [LAC with admin key %d failed configuration verification. Bad MAC Security configuration.](#)
- [LAC with admin key %d failed configuration verification. Bad qos status.](#)
- [LAC with admin key %d failed configuration verification. Bad rate-limiting configuration.](#)
- [LAC with admin key %d failed configuration verification. Bad VLAN configuration.](#)
- [LAC with admin key %d failed configuration verification. Cannot set admin key to the value used by ADAC Uplink.](#)
- [LAC with admin key %d failed configuration verification. Error #: %d-%d](#)
- [LAC with admin key %d failed configuration verification. Ports have different FA configuration.](#)
- [LAC with admin key %d failed configuration verification. Ports have different IPSG configurations.](#)

- [LAC with admin key %d failed configuration verification.Ports have different MAC learning status.](#)
- [LAC with admin key %d failed configuration verification.Ports have different mac security learning status.](#)
- [LAC with admin key %d failed configuration verification.Ports have different mac security settings.](#)
- [LAC with admin key %d failed configuration verification.Ports have different mac security status.](#)
- [LAC with admin key %d failed configuration verification. Ports have different private-vlan port type.](#)
- [LAC with admin key %d failed configuration verification. Ports have different qos config.](#)
- [LAC with admin key %d failed configuration verification.Ports have different SLPP-guard configurations.](#)
- [LAC with admin key %d failed configuration verification.Ports have different SPBM configurations.](#)
- [LAC with admin key %d failed configuration verification.Ports have different VLACP admin enable state.](#)
- [LAC with admin key %d failed configuration verification.Ports have different VLACP ethertype.](#)
- [LAC with admin key %d failed configuration verification.Ports have different VLACP fast periodic time value.](#)
- [LAC with admin key %d failed configuration verification.Ports have different VLACP mac address.](#)
- [LAC with admin key %d failed configuration verification.Ports have different VLACP slow periodic time value.](#)
- [LAC with admin key %d failed configuration verification.Ports have different VLACP timeout scale.](#)
- [LAC with admin key %d failed configuration verification.Ports have different VLACP timeout type.](#)
- [LAC with admin key %d failed configuration verification. Ports have different vlan filter tag frames settings.](#)
- [LAC with admin key %d failed configuration verification. Ports have different vlan filter unreg frames settings.](#)
- [LAC with admin key %d failed configuration verification. Ports have different vlan filter untag frames settings.](#)
- [LAC with admin key %d failed configuration verification. Ports have different vlan priorities.](#)
- [LAC with admin key %d failed configuration verification. Ports have different vlan PVIDs.](#)
- [LAC with admin key %d failed configuration verification. Ports have different vlan tagging.](#)
- [LAC with admin key %d failed configuration verification. Same key is used by ports belonging to different VLAN.](#)
- [Last MLT trunk was allocated by LAC. No more free trunk groups.](#)
- [Last MLT trunk was allocated by MLT. No more free trunk groups.](#)
- [Layer 2 classifier modifications not supported](#)
- [Layer 2 classifier still referenced \(deletion prohibited\)](#)
- [Layer 2 filter distribution across stack failed](#)
- [Layer 4 port filtering with IPv6 requires UDP TCP Next Header](#)
- [Layer 4 port filtering with IPv6 requires UDP/TCP Next Header](#)
- [Layer 4 port range could not be reduced sufficiently](#)
- [LEAVE event sent unit mask value appl mask value](#)
- [Leave event sent. unit mask 0x%02X. appl mask 0x%08X 0x%08X](#)
- [Level router does not support](#)
- [Limit reached for static routes.](#)
- [Link Down Trap](#)
- [Link Down Trap](#)
- [LinkStateTracking: First interface %d/d went up in link state group %d. enabling downstream ports](#)
- [LinkStateTracking: First interface mlt %d went up in link state group %d. enabling downstream interfaces](#)
- [LinkStateTracking: First interface %s went up in link state group %d. enabling downstream interfaces](#)
- [LinkStateTracking: Interface %d/d went down in link state group %d](#)
- [LinkStateTracking: Interface %d/d went up in link state group %d](#)
- [LinkStateTracking: Interface mlt %d went down in link state group %d](#)
- [LinkStateTracking: Interface mlt %d went up in link state group %d](#)
- [LinkStateTracking: Interface %s went down in link state group %d](#)
- [LinkStateTracking: Interface %s went up in link state group %d](#)
- [LinkStateTracking: Last interface %d/d went down in link state group %d. disabling downstream interfaces](#)
- [LinkStateTracking: Last interface mlt %d went down in link state group %d. disabling downstream interfaces](#)
- [LinkStateTracking: Last interface %s went down in link state group %d. disabling downstream interfaces](#)
- [Link Up Trap](#)
- [Link Up Trap](#)
- [L3MGR is %s %s %x](#)
- [l3m smgr exp db %s 0x%X](#)
- [l3m smgr rep db cat=%d cnt=%d](#)
- [l3m smgr rx db cat=%d cnt=%d rxdb=0x%X](#)
- [l3m smgr stkev %d %x %s](#)
- [Loading configuration block # block\\_number](#)
- [Loading configuration block %d](#)
- [Local authentication disabled on serial](#)
- [Local authentication disabled on stack serial](#)
- [Local authentication disabled on stack TELNET/WEB/SSH](#)
- [Local authentication disabled on switch serial](#)
- [Local authentication disabled on switch TELNET/WEB/SSH](#)
- [Local authentication disabled on telnet](#)
- [Local authentication disabled on TELNET/WEB/SSH](#)
- [Local authentication enabled on serial](#)



- [Local authentication enabled on stack serial](#)
- [Local authentication enabled on stack TELNET/WEB/SSH](#)
- [Local authentication enabled on switch serial](#)
- [Local authentication enabled on switch TELNET/WEB/SSH](#)
- [Local authentication enabled on telnet](#)
- [Local authentication enabled on TELNET/WEB/SSH](#)
- [Login timeout serial connection](#)
- [Login timeout. serial connection](#)
- [Lossless and Lossless-PFC modes are only supported in queue set 2](#)
- [L3S event=%s state=%s new=%s](#)
- [L3S unexpected event=%s state=%s enabled=%d](#)
- [L3 %s %#x %#x](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Logs starting with M

This page lists all logs that have a starting letter of M. Select the log you wish to view or navigate to a different starting letter.

Using your browser's 'find' function on this page may help you locate a specific log name faster.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

- [mac address appears twice in cam \(this has happened a total of %d times\)](#)
- [MAC security table full](#)
- [MAC %02x:%02x:%02x:%02x:%02x:%02x not authenticated: only one client is allowed in MHSA mode](#)
- [Management IP: excess traffic received on Management port%s](#)
- [Management IP: OOB port%s](#)
- [Management IP: OOB port%s](#)
- [Manual area entry exists](#)
- [Manual area error](#)
- [Martian packet detected with destination address mask %s on port %d/%d](#)
- [Martian packet detected with source address mask %s and destination address mask %s on port %d](#)
- [Martian packet detected with source address mask %s on port %d/%d](#)
- [Martian packet logging does not support metering](#)
- [Martian packet logging requires individual tracking statistics](#)
- [Maximum number of dynamic routes reached](#)
- [Maximum number of dynamic routes reached.](#)
- [Maximum users-per-interface limit \(%d\) reached](#)
- [Max-local is smaller than local configured interfaces number.](#)
- [Max number of dynamic routes increased.](#)
- [Max-static is smaller than local configured static routes number.](#)
- [MCM group node corrupted:](#)
- [Memory Allocation Error](#)
- [Memory on unit %d is under %d MBytes.](#)
- [Meter distribution across stack failed](#)
- [Meter entry referenced by clfr block \(deletion prohibited\)](#)
- [Meter entry referenced by meter \(deletion prohibited\)](#)
- [Meter entry referenced by policy \(deletion prohibited\)](#)
- [Meter \(from clfr block\) usage in multiple policies prohibited](#)
- [Meter \(from policy\) usage in multiple policies prohibited](#)
- [Meter identifier out-of-range \(%d\)](#)
- [Meter identifier out-of-range \( meter id \)](#)
- [Metering not supported with DS L2 access control lists](#)
- [Metering not supported with DS/L2 access control lists](#)
- [Meter modifications not supported](#)
- [Metric value is invalid for narrow type](#)
- [MHSA Auto-Configuration completed on port %s.](#)
- [MHSA Auto-Configuration failed on port %s - eap status is unauthorized.](#)
- [MHSA Auto-Configuration failed on port %s - port is RSPAN destination.](#)
- [MHSA Auto-Configuration failed on port %s - port mirroring is enabled.](#)
- [Min LSP interval should not be >= max LSP](#)
- [Mirroring \(requested via action\) not configured correctly](#)
- [MLD: Filters could NOT be installed.](#)
- [MLD: Filters successfully installed.](#)
- [MLD: HW ipmc entries exceeded](#)
- [MLD: Maximum number of mld enabled interfaces reached](#)
- [MLD: The maximum number of available hardware MLD entries has been reached](#)

MLD: The maximum number of available hardware MLD entries has been reached

- MLT %d disabled due to: %s
- MLT debug: %d, %d, %x
- MLT %d failed configuration verification.
- MLT %d failed configuration verification. Bad ARP INSPECTION configuration.
- MLT %d failed configuration verification. Bad DHCP-SNOOPING configuration.
- MLT %d failed configuration verification. Bad IGMP configuration.
- MLT %d failed configuration verification. Bad IPSG CLASS configuration.
- MLT %d failed configuration verification. Bad ISPG CLASS configuration.
- MLT %d failed configuration verification. Bad MAC learning configuration.
- MLT %d failed configuration verification. Bad rate-limiting configuration.
- MLT %d failed configuration verification. Bad SLPP-guard configuration.
- MLT %d failed configuration verification. Bad SPBM configuration.
- MLT %d failed configuration verification. Bad STORM CONTROL configuration.
- MLT %d failed configuration verification. Bad VLACP configuration.
- MLT %d failed configuration verification. Bad VLAN configuration.
- MLT %d failed configuration verification. Error #: %d-%d
- MLT %d failed configuration verification. Ports are in different static VLANs.
- MLT %d failed configuration verification. Ports are in different VLANs.
- MLT %d failed configuration verification. Ports have different private-vlan port type.
- MLT %d failed configuration verification. Ports have different static vlan PVIDs.
- MLT %d failed configuration verification. Ports have different static vlan tagging.
- MLT %d failed configuration verification. Ports have different VLACP admin enable state.
- MLT %d failed configuration verification. Ports have different VLACP ethertype.
- MLT %d failed configuration verification. Ports have different VLACP fast periodic time value.
- MLT %d failed configuration verification. Ports have different VLACP mac address.
- MLT %d failed configuration verification. Ports have different VLACP slow periodic time value.
- MLT %d failed configuration verification. Ports have different VLACP timeout scale.
- MLT %d failed configuration verification. Ports have different VLACP timeout type.
- MLT %d failed configuration verification. Ports have different vlan priorities.
- MLT %d failed configuration verification. Ports have different vlan PVIDs.
- MLT %d failed configuration verification. Ports have different vlan tag frames filter settings.
- MLT %d failed configuration verification. Ports have different vlan tagging.
- MLT %d failed configuration verification. Ports have different vlan unreg frames filter settings.
- MLT %d failed configuration verification. Ports have different vlan untag frames filter settings.
- MLT Distribute DB fail
- MLT failed to get STP sync semaphore.
- MLT get buffer failed
- MLT get module info fail
- MLT get msgQ RX fail
- MLT get msgQ unknown cmd
- MLT get stack event invalid
- MLT ID# failed configuration verification. Error # error num
- MLT IMC acknowledge error
- MLT IMC get buffer fail
- MLT IMC invalid cmd
- MLT IMC set link fail
- MLT IMC set name fail
- MLT IMC set state fail
- MLT IMC set STP fail
- MLT IMC set trunk with bad parameters
- MLT IMC subType invalid
- MLT IMC tx error
- MLT Join module DB fail
- mlt look up database has been attached to CDT (fn addr=0x%08x)
- MLT misconfiguration may be on Trunk #1.
- MLT misconfiguration may be on Trunk #2.
- MLT misconfiguration may be on Trunk #3.
- MLT misconfiguration may be on Trunk #4.
- MLT misconfiguration may be on Trunk #5.
- MLT misconfiguration may be on Trunk #6.
- MLT NV File error
- MLT NV File reset
- Modification of action (non-match usage) prohibited
- Modify the pattern data or use the correct data format

- [MODULE\\_INACTIVE event sent unit mask value appl mask value](#)
- [More than %d units discovered](#)
- [More than value units discovered](#)
- [Msg not sent, "numUnits" to big - %s line %d](#)
- [Multicast block unit/port %d/%d level %u watermark %u](#)
- [Multicast over high watermark unit/port %d/%d level %u watermark %u](#)
- [Multicast still blocked unit/port %d/%d level %u watermark %u](#)
- [Multicast still over low watermark unit/port %d/%d level %u watermark %u](#)
- [Multicast unblock unit/port %d/%d level %u watermark %u](#)
- [Multicast under low watermark unit/port %d/%d level %u watermark %u](#)
- [Multiple base units detected](#)
- [Multiple Waverunner units detected when base is a Flagship](#)
- [Must change node nickname after updating the system ID](#)
- [MVLAN vid=%d ip=%#x msk=%#x](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Logs starting with N

This page lists all logs that have a starting letter of N. Select the log you wish to view or navigate to a different starting letter.

Using your browser's 'find' function on this page may help you locate a specific log name faster.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

- [name](#)
- [Narrow metric is not supported in SPBM mode](#)
- [NEAP Accounting - Memory allocation failure](#)
- [NEAP Accounting: Memory allocation failure](#)
- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. All bindings have been rejected](#)
- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. All NRAVs or Bindings from RADIUS are invalid](#)
- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Already authenticated by other method.](#)
- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Cannot use FA bindings in Legacy networks](#)
- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. EAP FA context unknown network](#)
- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Maximum number of VLANs reached](#)
- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Only MHSA mode supports multiple NRAVs](#)
- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Receiving unconfigured VLAN from Radius without Autocreate](#)
- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid bindings exceeded the maximum threshold of 16](#)
- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid bindings exceeded the maximum threshold of 94](#)
- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid not supported in MHMA and SHSA](#)
- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with different Isid from the configured one is invalid](#)
- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with Isid equal to 0 not supported in FA SPB networks](#)
- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with Isid <> 0 not supported in Standalone Proxy or Autoproxy](#)
- [NEAP Client %02x:%02x:%02x:%02x:%02x:%02x. Vlan %d not created. Maximum number of VLANs reached](#)
- [NEAP: MAC - %02x:%02x:%02x:%02x:%02x:%02x. Binding already set for client. pushed trusted bindings will be ingored.](#)
- [NEAP: MAC - %02x:%02x:%02x:%02x:%02x:%02x. Invalid Fabric-Attach-Client-Trust value](#)
- [NEAP: MAC - %02x:%02x:%02x:%02x:%02x:%02x. Multiple trusted bindings supported only in MHSA](#)
- [NEAP: MAC - %02x:%02x:%02x:%02x:%02x:%02x. Number of ranges exceeded the maximum threshold of 10](#)
- [NEAP: MAC - %02x:%02x:%02x:%02x:%02x:%02x. Ranges are ignored](#)
- [NEAP Phone %02x:%02x:%02x:%02x:%02x:%02x migrated from port %d/%d.](#)
- [NEAP: Pvid attribute from RADIUS ignored.](#)
- [NEAP: Receiving unsupported Auto-Create-VLAN VSA in SHSA or MHMA](#)
- [Network access settings for FCoE Redirect must be modified locally](#)
- [Network access to FCoE Redirect functionality is currently disabled](#)
- [New IP Route Partitioning becomes effective on next L3/L2 mode change.](#)
- [New time:%s, old:%s, src:%s.](#)
- [Nickname range 3.33.xx is reserved: coresponding mac used by IPv6 multicast](#)
- [NNI is not suported over SMLT ports](#)
- [Non-EAP Client blocked \(Block Subsequent MAC Authentication\): Different VID than expected](#)
- [Non-EAP Client blocked \(Block Subsequent MAC Authentication\): EAP Use Rav Not enabled](#)
- [Non-match action contains conflicting data](#)
- [Non-match action not available for use with filter sets](#)
- [Non-match action support not available on certain interfaces](#)
- [Non-QoS interfaces may not be assigned to a role combination](#)
- [Non-supported action option \(green action\) specified](#)
- [Non-supported action option \(in-profile action\) specified](#)

- [Non-supported action option \(match action\) specified](#)
- [Non-supported action option \(out-of-profile action\) specified](#)
- [Non-supported action option \(policy non-match action\) specified](#)
- [Non-supported action option \(red action\) specified](#)
- [Non-supported action option \(yellow action\) specified](#)
- [Non-unique element label detected \(prohibited\)](#)
- [Non-unique FCoE redirection entry name detected \(prohibited\)](#)
- [Non-unique precedence order value detected \(prohibited\)](#)
- [Non-volatile QoS data discarded during restoration](#)
- [Non-volatile storage commit delay too large](#)
- [Non-zero pattern data detected in masked position](#)
- [No resources available for classifier port range checking](#)
- [No resources available for classifier range checking](#)
- [No Response from RADIUS Server](#)
- [no room in cam, cannot add address](#)
- [No stack ports available](#)
- [Not Enough Memory](#)
- [Notice: DAC Cable on %s is below HW rev "H" and may cause link issues with a small number of PHYs](#)
- [NSNA filter set assignment failed](#)
- [NSNA filter set count \(%d\) exceeds limit \(%d\)](#)
- [NSNA filter set data in use \(QoS disable prohibited\)](#)
- [NSNA filter set data in use \(QoS reset prohibited\)](#)
- [NSNA filter set delete operation failed](#)
- [NSNA filter set element count exceeds available resources](#)
- [NSNA filter set install operation failed](#)
- [NSNA filter set template does not exist](#)
- [NSNA filter set update operation failed](#)
- [NSNA system port transition failed](#)
- [NSX Retrieve Events ... cur=0x%08X error=%d errno=0x%X.](#)
- [NSX Retrieve Events ERR event\\_group:%p req=0x%08X op=%d...](#)
- [NT application mode enable failure - inadequate resources](#)
- [NTP synchronized](#)
- [numberAssignment ack received from unit # %d](#)
- [Number assignment message not received](#)
- [Number of VLANs does not match BU number of VLANs. VLAN config defaulted](#)
- [Number of VLANs does not match BU number of VLANs. VLAN config defaulted](#)
- [NUOC - Disabled](#)
- [NUOC - Enabled](#)
- [NUOC - Execution of the cli template failed](#)
- [NUOC - Execution of the cli template succeeded](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Logs starting with O

This page lists all logs that have a starting letter of O. Select the log you wish to view or navigate to a different starting letter.

Using your browser's 'find' function on this page may help you locate a specific log name faster.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

- [OCP server running.](#)
- [Ok](#)
- [Only one frame type supported per classifier](#)
- [Only one SPBM instance allowed](#)
- [Ospf Area Mismatch:](#)
- [Ospf Area Mismatch RxArea ra.rb.rc.rd IntfArea ia.ib.ic.id](#)
- [Ospf Auth Failed:](#)
- [Ospf Auth Failed IpAddr ia.ib.ic.id](#)
- [Ospf Auth Type Mismatch in Hello](#)
- [Ospf Auth Type Mismatch in Hello:](#)
- [Ospf Auto Virt Link Failed:](#)
- [Ospf Auto Virt Link Failed area a1.a2.a3.a4 rtid r1.r2.r3.r4](#)
- [Ospf Bad Version](#)
- [Ospf Bad Version:](#)
- [OSPF Callback function of timer is NULL](#)
- [OSPF Callback function of timer is NULL:](#)
- [Ospf Cost Exceeds Limit:](#)
- [Ospf Cost Exceeds Limit Skip route Lsid l1.l2.l3.l4 Adv-rtr a1.a2.a3.a4](#)
- [OspfDbg Done Filter Init](#)
- [OspfDbg Done Global Init](#)
- [OspfDbg Done Global Init](#)
- [OspfDbg Done NV-Restore](#)
- [OspfDbg Done NV-Restore](#)
- [OspfDbg Done ReDist Init](#)
- [OspfDbg Done ReDist Init](#)
- [OspfDbg Init Instance vrfId=%d nodeP=0x%0x](#)
- [OspfDbg Init Instance vrfId=%d nodeP=0x%0x](#)
- [OspfDbg PostInit Done vrfId=%d nodeP=0x%0x](#)
- [OspfDbg PostInit Done vrfId=%d nodeP=0x%0x](#)
- [OspfDbg PostInit EnableOspf vrfId=%d nodeP=0x%0x](#)
- [OspfDbg PostInit EnableOspf vrfId=%d nodeP=0x%0x](#)
- [OspfDbg Started ospfTxHelloTimerTask](#)
- [OspfDbg Started ospfTxHelloTimerTask](#)
- [Ospf Dead Int Mismatch in Hello](#)
- [Ospf Dead Int Mismatch in Hello:](#)
- [Ospf Enable Failed as Resource Unavailable](#)
- [Ospf Hello Int Mismatch in Hello](#)
- [Ospf Hello Int Mismatch in Hello:](#)
- [Ospf Hello: RId Same as Neighbor:](#)
- [Ospf Hello: RId Same as Neighbor: rtid <r1.r2.r3.r4>, IpAddr <i1.i2.i3.i4>](#)
- [Ospf HW Mode Change:](#)
- [Ospf Invalid packet received:](#)
- [Ospf Invalid packet received: Pkt type <ospfPacketType>](#)
- [Ospf License Is Missing. Disable OSPF](#)
- [Ospf Nbr State Change:](#)



[Ospf Nbr State Change: rtid <ra.rb.rc.rd> ipa <ia.ib.ic.id> state <neighborState>](#)

- [Ospf Netmask Mismatch in Hello:](#)
- [Ospf Netmask Mismatch in Hello IpAddr ia.ib.ic.id](#)
- [Ospf Option Mismatch in Hello:](#)
- [Ospf Option Mismatch in Hello IpAddr ia.ib.ic.id RxOption optionVal IntfOption optionVal](#)
- [OSPF Timer Link Error](#)
- [OSPF Timer Link Error:](#)
- [OSPF Timer List is corrupted](#)
- [OSPF Timer List is corrupted:](#)
- [OSPF Timer Unlink Error](#)
- [OSPF Timer Unlink Error:](#)
- [Ospf Virt Nbr State Change:](#)
- [Ospf Virt Nbr State Change: rtid <r1.r2.r3.r4>, virtAreaId <v1.v2.v3.v4>, state <neighborState>](#)
- [Out-of-profile action contains conflicting data](#)
- [Out-of-range CoS index value \( COS index value \)](#)
- [Out-of-range CoS index value \(%d\)](#)
- [Out-of-range queue index value \(%d\) for in-use queue set](#)
- [Out-of-range queue index value \(%d\) for pending queue set](#)
- [Out-of-range queue index value \(%d\) specified](#)
- [Out-of-range queue index value \( queue index \) for in-use queue set](#)
- [Out-of-range queue index value \( queue index \) for pending queue set](#)
- [Overload cannot be disabled](#)
- [Overload on startup is out of range](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series

9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Logs starting with P

This page lists all logs that have a starting letter of P. Select the log you wish to view or navigate to a different starting letter.

Using your browser's 'find' function on this page may help you locate a specific log name faster.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

- [Packet redirection support limited by target interfaces](#)
- [Packet reordering detected \(re: new mappings\)](#)
- [Password exists](#)
- [Password policy has changed](#)
- [Pattern matching data in excess of bytes# bytes specified](#)
- [Pattern matching data in excess of %d bytes specified](#)
- [Pattern matching \(Dst IP\) not supported with IP addr type data](#)
- [Pattern matching \(Dst MAC\) not supported with address type data](#)
- [Pattern matching \(IP\) not supported with non-IP addr type data](#)
- [Pattern matching not supported with other classification data](#)
- [Pattern modifier data specified without actual pattern data](#)
- [Pattern position and data strings must be same length](#)
- [Peer certificate validation against same CA, expiry and chain order is success](#)
- [Peer certificate validation failed with status:%s](#)
- [Pending filter control block already defined](#)
- [Pim Active RP change:](#)
- [Pim Assert change:](#)
- [Pim E-BSR change](#)
- [Pim E-BSR change:](#)
- [Pim Invalid packet received](#)
- [Pim Invalid packet received:](#)
- [Pim License Is Missing Disable PIM](#)
- [Pim License Is Missing, Disable PIM](#)
- [Pim Mode Change](#)
- [Pim Mode Change:](#)
- [Pim Nbr State Change:](#)
- [Pim Nbr State Change Up](#)
- [PIM: Neighbor status change](#)
- [PIM Neighbor status change Down](#)
- [PIM Neighbor status change Up](#)
- [Pim not enabled due to HW resources on port](#)
- [Pim RP type change:](#)
- [Pim RP type state](#)
- [Pim Unicast route change](#)
- [Pim Unicast route change:](#)
- [Pim Virt Nbr State Change:](#)
- [Pim Virt Nbr State Change Down](#)
- [Pim Virt Nbr State Change Up](#)
- [P1 IPv6 Dead Peer Detected. I/R: %s rAddr:%s status:%s](#)
- [P1 IPv6 SA Created. I/R: %s rAddr:%s status:%s](#)
- [P2 IPv6 SA Created. I/R: %s rAddr:%s status:%s](#)
- [P1 IPv6 SA Deleted. I/R: %s rAddr:%s status:%s](#)
- [P2 IPv6 SA Deleted. I/R: %s rAddr:%s status:%s](#)
- [P1 IPv6 SA Failed. I/R: %s rAddr:%s status:%s](#)
- [P2 IPv6 SA Failed. I/R: %s rAddr:%s status:%s](#)

P1 IPv6 SA lifetime expired. I/R: %s rAddr:%s status:%s

- PM in port mirroring the old data were modified - feature Allow Traffic in mirror port was added.
- PM in port mirroring the old data were modified - feature Many to Many was added.
- PM in port mirroring the old data were modified - feature Many to One was added.
- PM in port mirroring the old data were modified - feature Many to One with 128bits was added.
- PM: in port mirroring the old data were modified - feature RSPAN was added
- PM in port mirroring the old data were modified - mode type was out of range.
- PM in port mirroring the old data were modified - monitored portA was out of range.
- PM in port mirroring the old data were modified - monitored portB was out of range.
- PM in port mirroring the old data were modified - NVRAM file structure was changed.
- PM in port mirroring the old data were modified - probe port was out of range.
- PM: mirroring data modified - all data were changed to default.
- PM: mirroring data modified - mode type was out of range.
- PM: mirroring data modified - monitored portA was out of range.
- PM: mirroring data modified - monitored portB was out of range.
- PM: mirroring data modified - probe port was out of range.
- PM: mirroring data modified - RSPAN was corrupted
- PM some port mirroring messages were stored to be displayd with delay.
- PM: unable to create mirror for instance %d due to lack of available filter resources
- PM unable to create mirror for instance instance number due to lack of available filter resources
- PoE Main Power Usage Off
- PoE Main Power Usage On
- PoE Module Reset
- PoE Port Detection Status:
- PoE Port Detection Status port# Status powerStatus
- PoE The PoE power limit for port unit port has been changed to x Watts based on IP phone discovery settings
- PoE The PoE power limit for port unit port has been restored to previous value x Watts
- PoE The PoE priority for port unit port has been changed to x based on IP phone discovery settings
- PoE The PoE priority for port unit port has been restored to previous value x
- Policies with session data must be port-based
- Policy action out-of-range ( action# )
- Policy action out-of-range (%d)
- Policy content incompatible with precedence allocation mode
- Policy content incompatible with target interface(s)
- Policy distribution across stack failed
- Policy mask availability issue (space exhausted)
- Policy mask issue (space exhausted/precedence conflict)
- Policy modifications not supported
- Policy modification support limited
- Policy non-match action out-of-range (%d)
- Policy non-match action out-of-range ( non-match action# )
- Policy precedence conflict detected with non-QoS application
- Policy precedence value out-of-range for target interface(s)
- Policy requirements exceed available resources (slot %d)
- Policy requirements exceed available resources (slot slot# )
- Policy statistics index out-of-range (%d)
- Policy statistics index out-of-range ( stats index )
- Policy with this filtering values is already installed on this precedence
- Pol nvRam file error
- Port %d blocked by VLACP due to end-partner down state
- Port %d blocked by VLACP until end-partner connection reestablished
- Port %d/%d blocked by VLACP due to end-partner down state
- Port %d/%d blocked by VLACP until end-partner connection reestablished
- Port %d/%d of MLT %d is disabled because it has wrong configuration
- Port %d/%d reenabled by VLACP
- Port %d reenabled by VLACP
- Port is not member of VLAN
- Port %s of LAC with key %d is disabled because it has wrong configuration
- Port unit# port# blocked by VLACP until end-partner connection reestablished
- Port unit# port# reenabled by VLACP
- Post-join ACL installation issue detected (ifc %d)
- Post-join ACL installation issue detected (ifc ifc# )
- Post-join filter set installation issue detected (ifc %d)
- Post-join filter set installation issue detected (ifc ifc# )
- Post-join policy installation issue detected (ifc %d)

- [Post-join traffic-profile installation issue detected \(ifc %d\)](#)
- [Post-join traffic-profile installation issue detected \(ifc ifc# \)](#)
- [Potential inconsistent access asgn state \(Undo fail\) detected](#)
- [Potential inconsistent access asgn state \(Undo fail - unit %d\)](#)
- [Potential inconsistent access elem state \(Undo fail\) detected](#)
- [Potential inconsistent access elem state \(Undo fail - unit %d\)](#)
- [Potential inconsistent block state \(Undo fail\) detected](#)
- [Potential inconsistent ifc assignment state \(Undo fail\) detected](#)
- [Potential inconsistent ifc assignment state \(Undo fail - unit %d\)](#)
- [Potential inconsistent policy state \(Undo fail\) detected](#)
- [Potential inconsistent policy state \(Undo fail - unit %d\)](#)
- [Precedence value out-of-range](#)
- [Primary Configuration files are corrupted. Restored to default](#)
- [Primary Configuration Version is updated](#)
- [Primary VLAN does not match for the specified SPBM instance](#)
- [Primary VLAN is not added for the specified SPBM instance](#)
- [Priority is only for broadcast type](#)
- [Provided metering information incomplete](#)
- [802.1p user priority mapping modifications not supported](#)
- [802.1p user priority value modification prohibited](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series

9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Logs starting with Q

This page lists all logs that have a starting letter of Q. Select the log you wish to view or navigate to a different starting letter.

Using your browser's 'find' function on this page may help you locate a specific log name faster.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

- [QOS filter-limiting mode modified and unit reset](#)
- [QoS inter-module communication failure: class %d phase %d](#)
- [QoS inter-module communication issue detected](#)
- [QoS policies may not be applied to uplink or daisy chain ports \(%d\)](#)
- [QoS policies may not be applied to uplink or daisy chain ports \( port# \)](#)
- [Queue configuration inconsistency detected \(local %d, stack %d\)](#)
- [Queue configuration inconsistency detected \(local queue conf stack queue conf \)](#)
- [Queue data distribution across stack failed](#)
- [Queue set assignment distribution across stack failed](#)
- [Queue set assignment modifications not supported](#)
- [Queue set unacceptable - pending range excludes in-use queues](#)
- [Queue set value modification prohibited](#)
- [Queue set value modification prohibited](#)
- [Queue shaping distribution across stack failed](#)
- [Queue shaping modifications not supported](#)
- [Queue shaping not supported with specified interface](#)
- [QuickInstall console configuration error.](#)
- [QuickInstall: console configuration error.](#)
- [QuickInstall: console configuration success.](#)
- [QuickInstall:console configuration success.](#)
- [QuickInstall: console SNMP duplicate community error.](#)
- [QuickInstall: Error! Unable to locate agent software file](#)
- [QuickInstall: Error! Unable to locate agent software file.](#)
- [QuickInstall: Error! Unable to locate ASCII configuration file](#)
- [QuickInstall: Error! Unable to locate ASCII configuration file.](#)
- [QuickInstall: Error! Unable to locate diagnostics software file.](#)
- [QuickInstall: Processing of USB config file has commenced.](#)
- [QuickInstall: Processing of USB config file is complete](#)
- [QuickInstall: Processing of USB config file is complete.](#)
- [QuickInstall: USB config file not entirely executed](#)
- [QuickInstall USB config file not found.](#)
- [QuickInstall: USB config file not found.](#)
- [QuickInstall: USB file config error at line: %d.](#)
- [QuickInstall USB file config error at line line#](#)
- [QuickInstall: USB file config error: %d.](#)
- [QuickInstall USB file config error - file exceed 4096 bytes](#)
- [QuickInstall USB file config error - file exceed 200 lines.](#)
- [QuickInstall: USB file config error - file exceeds 4096 bytes](#)
- [QuickInstall: USB file config error - file exceeds 200 lines.](#)
- [QuickInstall: USB file config success.](#)
- [QuickInstall:USB file config success.](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Logs starting with R

This page lists all logs that have a starting letter of R. Select the log you wish to view or navigate to a different starting letter.

Using your browser's 'find' function on this page may help you locate a specific log name faster.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

- [RADIUS authentication on serial port disabled](#)
- [RADIUS authentication on serial port enabled](#)
- [RADIUS authentication on stack serial disabled](#)
- [RADIUS authentication on stack serial enabled](#)
- [RADIUS authentication on stack telnet disabled](#)
- [RADIUS authentication on stack telnet enabled](#)
- [RADIUS authentication on stack TELNET/WEB/SSH disabled](#)
- [RADIUS authentication on stack TELNET/WEB/SSH enabled](#)
- [RADIUS authentication on switch serial disabled](#)
- [RADIUS authentication on switch serial enabled](#)
- [RADIUS authentication on switch telnet disabled](#)
- [RADIUS authentication on switch telnet enabled](#)
- [RADIUS authentication on switch TELNET/WEB/SSH disabled](#)
- [RADIUS authentication on switch TELNET/WEB/SSH enabled](#)
- [RADIUS authentication on TELNET/WEB/SSH disabled](#)
- [RADIUS authentication on TELNET/WEB/SSH enabled](#)
- [RADIUS: ERROR - Couldn't create RADIUS Acct semaphore. errno %d](#)
- [RADIUS: ERROR - Couldn't create RADIUS semaphore. errno %d](#)
- [RADIUS: ERROR - Couldn't start RADIUS AcctClient\(\) task. errno %d](#)
- [RADIUS: ERROR - Couldn't start RADIUS client\(\) task. errno %d](#)
- [RADIUS: ERROR - Couldn't start radius\\_recv\(\) task. errno %d](#)
- [RADIUS: ERROR - Couldn't start RADIUS ServerCheck\(\) task. errno %d](#)
- [RADIUS MS-CHAPv2: Failed to change password](#)
- [RADIUS MS-CHAPv2: No response from RADIUS server](#)
- [RADIUS MS-CHAPv2: Password changed successfully](#)
- [RADIUS MS-CHAPv2: RADIUS server not properly configured](#)
- [RADIUS MS-CHAPv2: Server does not speak RADIUS](#)
- [RADIUS MS-CHAPv2: Unable to change password at RADIUS server](#)
- [Radius: Server with index %d is down](#)
- [Radius: Server with index %d is up](#)
- [Radius use-mgmt-ip must be disabled first](#)
- [Rate granularity limited to increments of 1 Mbps or 64 Kbps](#)
- [Rate \(min\) granularity limited \(increments of 1 Mbps or 64 Kbps\)](#)
- [RC SNMP CANNOT CONFIG PLSB ISIS INTE ON IST PORT](#)
- [RC SNMP CANNOT CONFIG PLSB ISIS INTE ON SMLT](#)
- [RC SNMP ISIS BCAST NOT SUPPORT OVER MLT](#)
- [Receive sync packet for L2 entry: MAC:%02x-%02x-%02x-%02x-%02x-%02x trunk %d modid %d from Remote modid %d](#)
- [Referenced block \(by policy\) deletion prohibited](#)
- [Referenced set \(by block\) modifications prohibited](#)
- [Referenced set \(by policy\) modifications prohibited](#)
- [Referenced token bucket data invalid \(burst size\)](#)
- [Remote access on this device has been](#)
- [Remote QoS-disable request failure \(%d on unit %d\)](#)
- [Remote QoS-disable request failure \( port# on unit unit# \)](#)
- [Remove Data Ack from unit # %d. mask 0x%X](#)



- [REMOVE DATA event sent unit mask value appl mask value](#)
- [Remove event sent, unit mask 0x%02X, appl mask 0x%08X 0x%08X](#)
- [Replaced "Wrong QoS Agent buffer setting, expected %u, actual %u, unit cannot join stack" with "Wrong QoS Agent buffer setting, expected %s, actual %s, unit cannot join stack"](#)
- [Requested attribute usage is currently not supported](#)
- [Requested filter manager support unavailable](#)
- [Requested operation succeeded](#)
- [Requested precedence mask reservation not available](#)
- [Requested reserve data invalid](#)
- [Request invalid - QoS interface apps enabled on interface\(s\)](#)
- [Request invalid - specified interface currently QoS-disabled](#)
- [Request temporarily denied - QoS support is currently disabled](#)
- [Required application data not provided](#)
- [Required bandwidth information not specified](#)
- [Required FCoE filter resources unavailable - enable request denied](#)
- [Required FCoE resources currently unavailable \(unit %d\)](#)
- [Required range check resources are not currently available](#)
- [Reset - Error Failed to get the Reset sem](#)
- [Reset initiated by console](#)
- [Reset initiated through http by IP address](#)
- [Reset initiated through snmp](#)
- [Reset initiated through SSH by IP address](#)
- [Reset initiated through SSH by IP address:](#)
- [Reset initiated through telnet by IP address](#)
- [Reset initiated through telnet by IP address:](#)
- [Reset initiated through http by IP address](#)
- [Reset to default initiated by console](#)
- [Reset to default initiated through SSH by IP address:](#)
- [Reset to default initiated through telnet by IP address](#)
- [Reset to default initiated through telnet by IP address:](#)
- [Reset to default initiated through http by IP address](#)
- [Resource alloc event timeout \(tgt all apps except QoS Agent rcv event.\)](#)
- [Resource alloc event timeout \(tgt %08x rcv %08x\)](#)
- [Resource not available](#)
- [Resources exhausted \(maximum class entries reached\)](#)
- [Resources exhausted \(maximum dynamic class entries reached\)](#)
- [Resources exhausted \(out-of-memory\)](#)
- [Resource unavailable DHCP relay %d err %d](#)
- [Restart discovery msg rcvd from unit # %d, "%s"](#)
- [Restarting discovery due to local stack port](#)
- [Restore Backup Configuration to Manufacture Default](#)
- [Restore Primary Configuration to Manufacture Default](#)
- [Role combination associated with interface \(deletion prohibited\)](#)
- [Role combination contains unacceptable characters](#)
- [Role combination distribution across stack failed](#)
- [Role combination length outside of acceptable limits](#)
- [Role combination modifications not supported](#)
- [Role combination referenced by policy \(deletion prohibited\)](#)
- [Role \(interface\) capabilities incompatible with policy data](#)
- [RPC app rcv routine error, type= %s\(%d\)](#)
- [RPC Error \(mem or send\)](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Logs starting with S

This page lists all logs that have a starting letter of S. Select the log you wish to view or navigate to a different starting letter.

Using your browser's 'find' function on this page may help you locate a specific log name faster.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

- [%s Appl. unexpectedly set bit in DB exch. rcv mask. bit 0x%08X](#)
- [Save/restore line=%d msg=%s val=0x%X](#)
- [%s card inserted \(in unit %s\)](#)
- [%s card removed \(from unit %s\)](#)
- [SC Install SET fail unit/port %d/%d status=%d](#)
- [SC Install TEST fail unit/port %d/%d status=%d](#)
- [Scratchpad failed to copy sector \(%x, %d\)](#)
- [Scratchpad failed to erase sector \(%x, %x, %d\)](#)
- [Script was successfully executed](#)
- [SC UnInst SET failed for port %u status=%d](#)
- [%s DB exchange succeeded for this unit. bit 0x%08X](#)
- [Sending restart discovery msg to base unit](#)
- [Session closed \(inactivity logout\) IP address](#)
- [Session closed \(inactivity logout\), IP address:](#)
- [Session closed \(inactivity logout\), serial connection](#)
- [Session closed \(lost connection\) IP address](#)
- [Session closed \(lost connection\), IP address:](#)
- [Session closed \(serial console disconnected\)](#)
- [Session closed \(user logout\) IP address](#)
- [Session closed \(user logout\), IP address:](#)
- [Session closed \(user logout\) serial connection](#)
- [Session closed \(user logout\), serial connection](#)
- [Session negotiation failure from IP address:](#)
- [Session opened from IP address](#)
- [Session opened from IP address:](#)
- [Session opened from serial connection](#)
- [Session opened \(local auth\) from IP address:](#)
- [Session opened \(local auth\) from IP address:](#)
- [Session opened \(local auth\) from serial connection](#)
- [Session opened\(radius auth\) from IP add](#)
- [Session opened\(RADIUS auth\) from IP add:](#)
- [Session opened\(radius auth\) from serial conn](#)
- [Session opened\(RADIUS auth\) from serial connection](#)
- [Session opened\(RADIUS fallback auth\) from IP add:](#)
- [Session opened\(RADIUS fallback auth\) from serial connection](#)
- [Session opened\(TACACS+ auth\) from IP add:](#)
- [Session opened\(TACACS+ auth\) from serial connection](#)
- [Session opened\(TACACS+ fallback auth\) from IP add:](#)
- [Session opened\(TACACS+ fallback auth\) from serial connection](#)
- [Set drop precedence value and update DSCP value out-of-sync](#)
- [Set port to default](#)
- [Setting MC broadcast IMC entry. ports %X, end type %s, stk type %s](#)
- [Setting MC non-IMC entries. end type %s, stk type %s](#)
- [Setting MC unicast IMC entries. unit %d, end type %s, stk type %s](#)
- [Setting VLAN entries. end type %s, stk type %s](#)

%s event NOT sent to %s

- %s event sent to %s, unit mask 0x%02X
- %s event sent, unit mask 0x%02X, appl mask 0x%08X
- %s failed DB-exchange, stack failed to form
- %s failed DB-exchange, stack formation delayed
- %s failed to set its stack startup event: 0x%08X
- SFP internal supply voltage is at high alarm level on %s
- SFP internal supply voltage is at high alarm level on s
- SFP internal supply voltage is at high warning level on %s
- SFP internal supply voltage is at low alarm level on %s
- SFP internal supply voltage is at low warning level on %s
- SFP internal supply voltage is no longer at the high alarm level
- SFP internal supply voltage is no longer at the high alarm level on %s
- SFP internal supply voltage is no longer at the high warning level
- SFP internal supply voltage is no longer at the high warning level on %s
- SFP internal supply voltage is no longer at the low alarm level
- SFP internal supply voltage is no longer at the low alarm level on %s
- SFP internal supply voltage is no longer at the low warning level
- SFP internal supply voltage is no longer at the low warning level on %s
- SFP internal temperature is at high alarm level on %s
- SFP internal temperature is at high warning level on %s
- SFP internal temperature is at low alarm level on %s
- SFP internal temperature is at low warning level on %s
- SFP internal temperature is no longer at the high alarm level
- SFP internal temperature is no longer at the high alarm level on %s
- SFP internal temperature is no longer at the high warning level
- SFP internal temperature is no longer at the high warning level on %s
- SFP internal temperature is no longer at the low alarm level
- SFP internal temperature is no longer at the low alarm level on %s
- SFP internal temperature is no longer at the low warning level
- SFP internal temperature is no longer at the low warning level on %s
- SFP Received power is at high alarm level on %s
- SFP Received power is at high warning level on %s
- SFP Received power is at low alarm level on %s
- SFP Received power is at low warning level on %s
- SFP Received power is no longer at the high alarm level
- SFP Received power is no longer at the high alarm level on %s
- SFP Received power is no longer at the high warning level
- SFP Received power is no longer at the high warning level on %s
- SFP Received power is no longer at the low alarm level
- SFP Received power is no longer at the low alarm level on %s
- SFP Received power is no longer at the low warning level
- SFP Received power is no longer at the low warning level on %s
- SFP TX Bias current is at high alarm level on %s
- SFP TX Bias current is at high warning level on %s
- SFP TX Bias current is at low alarm level on %s
- SFP TX Bias current is at low warning level on %s
- SFP TX Bias current is no longer at the high warning level on %s
- SFP TX Bias current is no longer at the low warning level on %s
- SFP TX Bias is no longer at the high alarm level
- SFP TX Bias is no longer at the high alarm level on %s
- SFP TX Bias is no longer at the high warning level
- SFP TX Bias is no longer at the low alarm level
- SFP TX Bias is no longer at the low alarm level on %s
- SFP TX Bias is no longer at the low warning level
- SFP TX output power is at high alarm level on %s
- SFP TX output power is at high warning level on %s
- SFP TX output power is at low alarm level on %s
- SFP TX output power is at low warning level on %s
- SFP TX output power is no longer at the high alarm level
- SFP TX output power is no longer at the high alarm level on %s
- SFP TX output power is no longer at the high warning level
- SFP TX output power is no longer at the high warning level on %s
- SFP TX output power is no longer at the low alarm level
- SFP TX output power is no longer at the low alarm level on %s

- [SFP TX output power is no longer at the low warning level](#)
- [SFP TX output power is no longer at the low warning level on %s](#)
- [Simultaneous operations involving access asgn ifcs prohibited](#)
- [Simultaneous operations involving access asgn/ifcs prohibited](#)
- [Simultaneous operations involving policies and blocks prohibited](#)
- [Simultaneous operations involving policies and ifcs prohibited](#)
- [Simultaneous operations involving policy blocks ifcs prohibited](#)
- [Simultaneous operations involving policy blocks/ifcs prohibited](#)
- [SLAMon Agent: agent IP address reset to default value](#)
- [SLAMon Agent: CLI support not available](#)
- [SLAMon Agent: CLI timeout value out-of-range](#)
- [SLAMon Agent: disabled](#)
- [SLAMon Agent: enabled](#)
- [SLAMon Agent: inconsistent IP address data specified](#)
- [SLAMon Agent: inconsistent UDP port data specified](#)
- [SLAMon Agent: info: %d %d %d](#)
- [SLAMon Agent: invalid agent-to-agent port \(must be even value\)](#)
- [SLAMon Agent: message channel creation failure](#)
- [SLAMon Agent: operation is restricted \(CLI-only\)](#)
- [SLAMon Agent: platform CLI command interface initialization issue](#)
- [SLAMon Agent: platform timer initialization issue](#)
- [SLAMon Agent: terminated](#)
- [SLAMon Agent: terminated - command/frame processing issue detected](#)
- [SLAMon Agent: terminated - NTR test exception detected](#)
- [SLAMon Agent: terminated - resources unavailable](#)
- [SLAMon Agent: terminated - RTP test exception detected](#)
- [%s line %d: Dropping msg that originated from this unit \(#%d\)](#)
- [%s line %d: Logical unit #%d out of range](#)
- [%s line %d: Physical unit #%d out of range](#)
- [%s line %d: Stack links already down unit #%d](#)
- [%s line %d: Unexpected stack link down msg from unit #%d](#)
- [SLPP: \(Continued\) - PDU was sent on Vlan %d.](#)
- [SLPP-guard: hold-down timer has expired on port with SLPP-guard enabled. Port %s has been re-enabled](#)
- [SLPP-guard: SLPP-guard has not been enabled on port %s as no filters or filter precedences are available to setup an Ethertype filter](#)
- [SLPP-guard: SLPP packet received on port with SLPP-guard enabled. Port %s has been disabled](#)
- [SLPP: Warning - PDU was received on Unit %d, Port %d, Vlan %d.](#)
- [SLPP Warning - PDU was received on Vlan VlanId Unit UnitNo Port PortNo.](#)
- [SMLT IMC invalid cmd 1- StkCmd](#)
- [SMLT IMC tx error](#)
- [SMLT input parameter error mlt port vlan](#)
- [SMLT Stack db ex event num -0 -0\\*22221111](#)
- [SMLT stackEventNotify Invalid Msg Cmd - 0 - 0](#)
- [SMLT Stack inactive event 0-0- modMask](#)
- [SMLT Stack joined event num - 0 - 0\\*33331111](#)
- [SMLT Stack leaved event 0 - 0 - modMask](#)
- [SMLT STP enabled on IST trunk trkNo stp group grp](#)
- [SMLT Warning - LAC SMLT with more than 8 links - key - count](#)
- [SMLT Warning - smltEnable Software License Error- 0 - 0](#)
- [SMLT Warning - SMLT mismatched Lac Sys ID error shutdown all SMLT lac po](#)
- [%s neighbor is mis-configured, see neighboring unit for details](#)
- [SNMP-access is disabled](#)
- [SNMP-access is disabled](#)
- [SNMP-access is enabled](#)
- [SNMP-access is enabled](#)
- [SNTP Could not sync to NTP servers.](#)
- [SNTP: Could not sync to SNTP servers.](#)
- [SNTP: First synchronization successful.](#)
- [Source MAC address and mask values out-of-sync](#)
- [SPBM adjacency with neighbor](#)
- [SPBM adjacency with neighbor](#)
- [SPBM BVLAN is required but has not been configured](#)
- [SPB-MC Dynamic i-sid range conflicts with existing i-sid](#)
- [SPBM: Configuration on unit %d does not match BU configuration - SPBM local config discarded](#)
- [SPBM detect adj](#)

- [SPBM detect adj](#)
- [SPBM: ERROR adding C-VLAN UNI for i-sid %d, vlan %d - no resources](#)
- [SPBM: ERROR adding i-sid %x to i-sid table - table full](#)
- [SPBM: ERROR adding NNI on port %d vlan %d - no resources](#)
- [SPBM: ERROR adding peer %04x.%04x.%04x - no resources](#)
- [SPBM: ERROR adding switched UNI for i-sid %d, port %d, vlan %d - no resources](#)
- [SPBM: ERROR adding Transparent UNI for i-sid %d, port %d - no resources](#)
- [SPBM: ERROR enabling SPBM due to Software License error](#)
- [SPBM: ERROR same value for System ID and SMLT VIRTUAL BMAC - ISIS disabled](#)
- [SPBM: ERROR Trying to delete a non existing entry](#)
- [SPBM: ERROR updating UNI for port %d/%d - no resources](#)
- [SPBM: ERROR updating UNIs for trunk %d - no resources](#)
- [SPBM instance already exists](#)
- [SPBM instance does not exist](#)
- [SPBM instance is not enabled on this IS-IS interface](#)
- [SPBM: IPFIX over port %d/%d is disabled. IPFIX cannot be enabled over NNI](#)
- [SPBM: IPFIX over port %d is disabled. IPFIX cannot be enabled over NNI](#)
- [SPBM ISIS](#)
- [SPBM ISIS](#)
- [SPBM ISIS detect duplicate nick-name](#)
- [SPBM ISIS detect duplicate nick-name](#)
- [SPBM ISIS node](#)
- [SPBM ISIS node](#)
- [SPBM: Node already present on unit %d – will not add again](#)
- [SPBM system ID cannot be same as IST peer system ID](#)
- [SPBM system ID cannot be same as IST virtual bmac](#)
- [SPBM system nickname is required but has not been configured](#)
- [SPBM transparent UNI already configured on port](#)
- [Specified Destination Layer 4 min max range not supported](#)
- [Specified Destination Layer 4 min/max range not supported](#)
- [Specified filter criteria contains conflicting data](#)
- [Specified filter criteria is invalid inconsistent](#)
- [Specified filter criteria is invalid/inconsistent](#)
- [Specified filter criteria too complex](#)
- [Specified filter information not found](#)
- [Specified filter manager resource invalid](#)
- [Specified filter manager resource uninitialized](#)
- [Specified inner VLAN ID min max range not supported](#)
- [Specified inner VLAN ID min/max range not supported](#)
- [Specified IS-IS BVLAN does not currently exist](#)
- [Specified IS-IS BVLAN is not an SPBM VLAN](#)
- [Specified IS-IS system ID is invalid](#)
- [Specified metering operation not supported](#)
- [Specified metering statistics entry already in-use \(by policy\)](#)
- [Specified policy components \(classifiers\) conflicting](#)
- [Specified policy criteria too complex](#)
- [Specified policy identifier \(cookie\) invalid](#)
- [Specified policy statistics entry already in-use \(by meter\)](#)
- [Specified precedence mask reservation not found](#)
- [Specified precedence mask reservation parameter invalid](#)
- [Specified queue set information invalid](#)
- [Specified rule/precedence mask reservation not found](#)
- [Specified shaping bucket size out of supported range](#)
- [Specified shaping rate out of supported range](#)
- [Specified Source Layer 4 min max range not supported](#)
- [Specified Source Layer 4 min/max range not supported](#)
- [Specified statistics tracking operation not supported](#)
- [Specified token bucket criteria out of range](#)
- [Specified token bucket refresh interval not supported](#)
- [Specified token bucket size \(burst size\) not supported](#)
- [Specified user policy interface currently QoS-disabled](#)
- [Specified VLAN ID min max range not supported](#)
- [Specified VLAN ID min/max range not supported](#)
- [Src Layer 4 port min max values invalid \(max must be = to min\)](#)
- [Src Layer 4 port min/max values invalid \(max must be >= to min\)](#)

- [srTCM meter issue - CIR must be the same in both meters](#)
- [srTCM meter issue - EBS must be greater than CBS](#)
- [srTCM trTCM meter issue - diff algorithms in associated meters](#)
- [srTCM/trTCM meter issue - diff algorithms in associated meters](#)
- [srTCM trTCM meter issue - referenced meter incompatible unknown](#)
- [srTCM/trTCM meter issue - referenced meter incompatible/unknown](#)
- [srTCM trTCM meter issue - too many cascaded meters](#)
- [srTCM/trTCM meter issue - too many cascaded meters](#)
- [SSHC ASCII CFG download SFTP failure](#)
- [SSHC: ASCII CFG download SFTP failure](#)
- [SSHC ASCII CFG upload SFTP failure](#)
- [SSHC: ASCII CFG upload SFTP failure](#)
- [SSHC CFG download SFTP failure](#)
- [SSHC: CFG download SFTP failure](#)
- [SSHC CFG upload SFTP failure](#)
- [SSHC: CFG upload SFTP failure](#)
- [SSHC DSA Authentication failure](#)
- [SSHC: DSA Authentication failure](#)
- [SSHC: DSA key deleted](#)
- [SSHC: DSA key generation completed](#)
- [SSHC DSA key generation failure](#)
- [SSHC: DSA key generation failure](#)
- [SSHC DSA key save failure](#)
- [SSHC: DSA key save failure](#)
- [SSHC DSA key upload TFTP failure](#)
- [SSHC: DSA key upload TFTP failure](#)
- [SSHC DSA key upload USB failure](#)
- [SSHC: DSA key upload USB failure](#)
- [SSH CLIENT Key couldn't be saved for host ip address](#)
- [SSH CLIENT: Key couldn't be saved for host %s](#)
- [SSH CLIENT SSH Connection to IP ip address was closed because parent console session console session ID was closed](#)
- [SSH CLIENT: SSH Connection to %s was closed because parent console session # %d was closed.](#)
- [SSH CLIENT SSH Connection to %s was disconnected](#)
- [SSH CLIENT: SSH Connection to %s was disconnected by host. Connection time: %s](#)
- [SSH CLIENT: SSH Connection to %s was disconnected by host. Connection time: %s.](#)
- [SSH CLIENT: SSH Connection to %s was disconnected by user. Connection time: %s.](#)
- [SSH CLIENT Successful SSH Connection to %s using %s authentication](#)
- [SSH CLIENT: Successful SSH Connection to %s. using %s authentication](#)
- [SSH: Client tried to authenticate with invalid certificate from address %s](#)
- [SSH: Client tried to authenticate without principal name in certificate from address %s](#)
- [SSH: Client tried to authenticate with revoked certificate from address %s](#)
- [SSH: could not perform OCSP for the server certificate from address %s](#)
- [SSH: Couldn't create SSH Data Semaphore](#)
- [SSHC Password Authentication failure](#)
- [SSHC: Password Authentication failure](#)
- [SSHC RSA Authentication failure](#)
- [SSHC: RSA Authentication failure](#)
- [SSHC: RSA key deleted](#)
- [SSHC: RSA key generation completed](#)
- [SSHC RSA key generation failure](#)
- [SSHC RSA key save failure](#)
- [SSHC RSA key upload TFTP failure](#)
- [SSHC: RSA key upload TFTP failure](#)
- [SSHC RSA key upload USB failure](#)
- [SSHC: RSA key upload USB failure](#)
- [SSHC server connection failure](#)
- [SSHC: server connection failure](#)
- [SSHC: SSH Client session rekey failure](#)
- [SSHC: SSH Client session rekey success](#)
- [SSH disabled](#)
- [SSH: DSA Authentication failure](#)
- [SSH: DSA auth key deleted](#)
- [SSH DSA key deleted](#)
- [SSH DSA KEY generation completed](#)
- [SSH: DSA KEY generation completed](#)



- [SSH enabled in non-secure mode](#)
- [SSH enabled in secure mode](#)
- [SSH Maximum number of ssh sessions has been reached](#)
- [SSH: Maximum number of ssh sessions has been reached](#)
- [SSH: No response to OCSP query for client certificate from address %s](#)
- [SSH: OCSP query verification passed for server certificate from address %s](#)
- [SSH: OCSP test failed for client certificate from address %s](#)
- [SSH: OCSP test failed for server certificate from address %s](#)
- [SSH: Password Authentication failure](#)
- [SSH: RADIUS server unreachable - client at address %s authenticated with local credentials](#)
- [SSH: RSA Authentication failure](#)
- [SSH: RSA auth key deleted](#)
- [SSH RSA key deleted](#)
- [SSH RSA KEY generation completed](#)
- [SSH: RSA KEY generation completed](#)
- [SSH RSA key overwritten](#)
- [SSH: Server tried to authenticate with revoked certificate from address %s](#)
- [SSH session closed by ip address remote host. Connection time h hours m minutes](#)
- [SSH session login using port](#)
- [SSH session login using port:](#)
- [SSH: SSH session rekey failure](#)
- [SSH: SSH session rekey success](#)
- [SSH: Succesfull response to OCSP query for client certificate from address %s](#)
- [SSH System is generating DSA KEY wait ...](#)
- [SSH: System is generating DSA KEY. wait ...](#)
- [SSH: System is generating RSA KEY. wait ...](#)
- [SSH TFTP DSA key download complete](#)
- [SSH TFTP RSA key download complete](#)
- [SSH: The DSA key overwritten](#)
- [SSH: The RSA key overwritten](#)
- [SSH: Unknown response to OCSP query for client certificate from address %s](#)
- [SSH: Unknown response to OCSP query for server certificate from address %s](#)
- [SSH USB DSA key download complete](#)
- [SSH: USB DSA key download complete](#)
- [SSH USB RSA key download complete](#)
- [SSH: USB RSA key download complete](#)
- [%s %s in %s%s has expired](#)
- [%s %s in %s%s will expire in %d days](#)
- [SSL certificate creation completed](#)
- [SSL certificate creation failed](#)
- [SSL certificate deleted](#)
- [SSL connection was closed from](#)
- [SSL disabled](#)
- [SSL enabled](#)
- [SSL negotiation failure from](#)
- [SSL server reset](#)
- [SSL successful connection from](#)
- [Stack cable "Down 1" is misconfigured](#)
- [Stack cable "Down 2" is misconfigured](#)
- [Stack cable Down 1 is misconfigured](#)
- [Stack cable Down 2 is misconfigured](#)
- [Stack cable "Up 1" is misconfigured](#)
- [Stack cable "Up 2" is misconfigured](#)
- [Stack cable Up 1 is misconfigured](#)
- [Stack cable Up 2 is misconfigured](#)
- [Stack IP changed](#)
- [Stack link down. neighboring unit is not in stack](#)
- [Stack Manager config file ver. %d upgraded to ver. %d](#)
- [Stack Manager unable to read from to configuration file](#)
- [Stack Manager unable to write to configuration file](#)
- [Stack Mgr: error: %s line %d %d](#)
- [Stack Mgr: error: %s line %d 0x%X](#)
- [Stack Mgr: event received msg\\_src=0x%X num= 0x%X](#)
- [Stack Mgr: ignored event %s for state %s. arg: %d](#)
- [Stack Mgr: IMC ack msg failed: status %d](#)



- [Stack Mgr: info: %s line %d %d](#)
- [Stack Mgr: initialized arg1= %d arg2 = %d arg3 = %d](#)
- [Stack Mgr: internal 5670 ports INACTIVE 0x%X](#)
- [Stack Mgr: NAP error: MAC not found. stack size %d](#)
- [Stack Mgr: queue creation failed %s line %d](#)
- [Stack Mgr: queue rec error qid= 0x%X errno=0x%X](#)
- [Stack Mgr: queue send error qid= 0x%X errno=0x%X](#)
- [Stack Mgr: semaphore creation failed %s line %d](#)
- [Stack Mgr: %s msg send failed](#)
- [Stack Mgr: startup event failed type: 0x%08X option: %d](#)
- [Stack Mgr: STEG GO event missed](#)
- [Stack Mgr: 0x%X 0x%X 0x%X](#)
- [Stack must have a configured base unit!](#)
- [Stack operation mode modified to Hybrid and unit reset](#)
- [Stack operation mode modified to Pure and unit reset](#)
- [Stack operation mode modified to %s and unit reset](#)
- [Stack Port %d: event %s causes state transition to %s](#)
- [Stack Port %d: ignored event %s for state %s](#)
- [Stack RO password changed from IP add](#)
- [Stack RO password changed from IP add:](#)
- [Stack RO password changed from IP address](#)
- [Stack RO password changed from serial conn](#)
- [Stack RO password changed from serial connection](#)
- [Stack RW password changed from IP add](#)
- [Stack RW password changed from IP add:](#)
- [Stack RW password changed from IP address](#)
- [Stack RW password changed from serial conn](#)
- [Stack RW password changed from serial connection](#)
- [Stack sync failed Exp: 0x%08X Act: 0x%08X Missing: 0x%08X](#)
- [Stack sync failed stack failed to form](#)
- [Stack sync failed. stack failed to form](#)
- [Stack sync failed. unit not in stack](#)
- [Stack synchronization failed Exp value Act value Missing value](#)
- [Stack synchronization failed stack formation delayed](#)
- [startDiscoveryMsg from unit # %d \(%s\) will be processed now](#)
- [Static role association not found for ifc. default was used \(%d/%d\)](#)
- [Stk config is "%s", %d units](#)
- [STKMON: Could not get available buffer](#)
- [STKMON: End](#)
- [STKMON: Failed to open config file](#)
- [STKMON: Failed to write to config file](#)
- [STKMON: Failed to xmit packet in stack](#)
- [STKMON: msgOReceive failed](#)
- [STKMON: Received unknown message into STKMON msg queue](#)
- [STKMON: Start](#)
- [stk startup event failed Exp: 0x%08X Act: 0x%08X Missing: 0x%08X](#)
- [Stk startup event failed type: 0x%08X option: %d](#)
- [STP add Mlt link: %d - %d - %d](#)
- [STP CDT interface error](#)
- [STP Config Chk: %d - %d - %d](#)
- [STP dbrcv error: %d - %d - %d](#)
- [STP db record done: %d - %d - %d](#)
- [STP db remove: %d - %d - %d](#)
- [STP db remove done: %d - %d - %d](#)
- [STP dbxc error: %d - %d - %d](#)
- [STP db xchg: %d - %d - %d](#)
- [STP db xchg done: %d - %d - %d](#)
- [STP db xchg mask empty: %d - %d - %d](#)
- [STP db xchg rcv last pkt: %d - %d - %d](#)
- [STP different op mode remote-local-Module: %d - %d - %d](#)
- [STP Fatal Error: taskSuspend\(0\) called %s line %d: %d](#)
- [STP get buffer fail: %d - %d - %d](#)
- [STP group %d disabled. empty vlans or no vlans %d - %d](#)
- [STP IMC error: %d - %d - %d](#)
- [STP join: %d - %d - %d](#)

- [STP join done: %d - %d - %d](#)
- [STP join timeout : %d - %d - %d](#)
- [STP leave: %d - %d - %d](#)
- [STP leave done: %d - %d - %d](#)
- [STP Mlt create: %d - %d - %d](#)
- [STP Mlt remove: %d - %d - %d](#)
- [STP mod inactive: %d - %d - %d](#)
- [STP mod ina done: %d - %d - %d](#)
- [STP msgQ error: %d - %d - %d](#)
- [STP NV port clr: %d - %d - %d](#)
- [STP nvRam file error: %d - %d - %d](#)
- [STP parameter error: %d - %d - %d](#)
- [STP PDT interface error: %d - %d - %d](#)
- [STP port disable: %d - %d - %d](#)
- [STP STKM mask error: %d - %d - %d](#)
- [STP stpMlt create: %d - %d - %d](#)
- [STP Task Error: %d - %d - %d](#)
- [STP Timer 1st: %d - %d - %d](#)
- [STP Tx BPDU Alloc Fail: %d - %d - %d](#)
- [STP Tx BPDU IMC Fail: %d - %d - %d](#)
- [STP update cnfg: %d - %d - %d](#)
- [STP vlan clr cnfg: %d - %d - %d](#)
- [STP VLAN error: %d - %d - %d](#)
- [Successful connection from IP address:](#)
- [Successfully loaded backup configuration files](#)
- [Successfully loaded configuration files from block %d](#)
- [Successfully remapped config areas on unit %d](#)
- [Successful SSH connection to ip address](#)
- [Superfluous request from unit #%d to restart discovery](#)
- [Sw Exception](#)
- [Sw Exception:](#)
- [Switched UNI already configured with same I-SID](#)
- [Switch IP changed](#)
- [Switch RO password changed from IP add:](#)
- [Switch RO password changed from IP address](#)
- [Switch RO password changed from serial connection](#)
- [Switch RO password changed from serial connection](#)
- [Switch RW password changed from IP add](#)
- [Switch RW password changed from IP add:](#)
- [Switch RW password changed from IP address](#)
- [Switch RW password changed from serial conn](#)
- [Switch RW password changed from serial connection](#)
- [Syslog Stress Test customer message .](#)
- [Syslog Stress Test engineering message .](#)
- [System classifier modifications not supported](#)
- [System classifier still referenced \(deletion prohibited\)](#)
- [System filter distribution across stack failed](#)
- [System memory on unit %d is under %d MBytes.](#)
- [System: Rear-Port Mode has been set to disable \(reboot required to take effect\)](#)
- [System: Rear-Port Mode has been set to disable \(reboot required to take effect\).](#)
- [System: Rear-Port Mode has been set to enable \(reboot required to take effect\).](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Logs starting with T

This page lists all logs that have a starting letter of T. Select the log you wish to view or navigate to a different starting letter.

Using your browser's 'find' function on this page may help you locate a specific log name faster.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

- [Table is full](#)
- [TACACS+ accounting disabled](#)
- [TACACS+ accounting enabled](#)
- [TACACS+ authenticated serial connection closed](#)
- [TACACS+ authenticated ssh session closed](#)
- [TACACS+ authenticated telnet session closed](#)
- [TACACS+ authenticated telnet session max retries exceeded](#)
- [TACACS+ authentication on serial port disabled](#)
- [TACACS+ authentication on serial port enabled](#)
- [TACACS+ authentication on stack serial disabled](#)
- [TACACS+ authentication on stack serial enabled](#)
- [TACACS+ authentication on stack TELNET/WEB/SSH disabled](#)
- [TACACS+ authentication on stack TELNET/WEB/SSH enabled](#)
- [TACACS+ authentication on switch serial disabled](#)
- [TACACS+ authentication on switch serial enabled](#)
- [TACACS+ authentication on switch serial port disabled](#)
- [TACACS+ authentication on switch serial port enabled](#)
- [TACACS+ authentication on switch telnet disabled](#)
- [TACACS+ authentication on switch telnet enabled](#)
- [TACACS+ authentication on switch telnet enabled](#)
- [TACACS+ authentication on switch TELNET/WEB/SSH disabled](#)
- [TACACS+ authentication on switch TELNET/WEB/SSH enabled](#)
- [TACACS+ authentication on TELNET/WEB/SSH disabled](#)
- [TACACS+ authentication on TELNET/WEB/SSH enabled](#)
- [TACACS+ authorization disabled](#)
- [TACACS+ authorization enabled](#)
- [TACACS+ successful authentication](#)
- [TACACS+ unsuccessful authentication](#)
- [TACACS authenticated SSH session closed](#)
- [TACACS authentication on stack serial disabled](#)
- [TACACS authentication on stack serial enabled](#)
- [TACACS authentication on stack telnet disabled](#)
- [TACACS authentication on stack telnet enabled](#)
- [Task priority changed for %s to %d](#)
- [Task %s is suspended](#)
- [Task task\\_name is suspended](#)
- [Task task-name is suspended](#)
- [Task whose index is %d,%d is suspended](#)
- [TCP Control Flag filter criteria requires TCP protocol](#)
- [Telnet-access is disabled](#)
- [Telnet-access is enabled](#)
- [Temporary access assignment sync issue detected \(ifc %d\)](#)
- [Temporary base unit detected, becoming a non-base unit- %s line %d](#)
- [Temporary interface assignment sync issue detected \(ifc %d\)](#)
- [Temporary QoS inter-module communication issue encountered](#)

## TFTP Failed

- The account for user <%s> expires in %d days due to inactivity
- The base (unit #%d) has left the stack. Unit #%d is now the base
- The base (unit# number ) has left the stack. Unit# number is now the base
- The BU switch is enabled. Cannot join existing stack
- The IP phone PoE limit has been changed to x Watts due to the stack modules configuration
- The number of stack units is %d instead of expected %d
- The number of stack units is number instead of expected number
- The password for user <%s> expires in %d days due to password aging
- The password for user <%s> has expired.
- The password for user <%s> was changed
- The password for user <%s> was not changed
- The role for user <%s> changed to %s
- The static FDB entry MAC %02x-%02x-%02x-%02x-%02x-%02x VLAN %d trunk %d was deleted because LAG has disaggregated
- The static FDB entry MAC %02x-%02x-%02x-%02x-%02x-%02x VLAN %d was deleted because Port: %d has aggregated
- The static FDB entry MAC %02x-%02x-%02x-%02x-%02x-%02x VLAN %d was deleted because Unit/Port: %d/%d has aggregated
- The user <%s> was disabled
- The user <%s> was enabled
- The user <%s> was locked
- The user <%s> was locked.
- The user <%s> was unlocked
- The user <%s> with %s role has been created
- The user <%s> with %s role has been deleted
- This attribute is currently not configurable
- This log msg contains 3 encoded variables %x, %x, %x
- This unit has already been discovered
- This unit has an incompatible stack operational mode setting
- This unit has wrong F/W version, expected %s, actual %s
- This unit has wrong F W version expected version actual version
- This unit has wrong S/W version, expected %s, actual %s
- This unit has wrong S W version expected version actual version
- This unit is operating as the Base unit
- Toggle the Agent Primary Image
- Token bucket algorithm identifier invalid
- Token bucket algorithm identifier unknown unsupported
- Token bucket algorithm identifier unknown/unsupported
- Token bucket data distribution across stack failed
- Token bucket entry referenced by meter (deletion prohibited)
- Token bucket entry referenced by shaper (deletion prohibited)
- Token bucket minimum rate outside limits (64 - 10230000 Kbps)
- Token bucket modifications not supported
- Token bucket rate outside limits (64 - 10230000 Kbps)
- Token bucket size not compatible with committed fill rate
- Too many manual area addresses
- Traffic Prof filter set delete operation failed
- Traffic Prof filter set elem count exceeds available resources
- Traffic Prof filter set install operation failed
- Traffic Prof filter set policy count (%d) exceeds limit (%d)
- Traffic Prof filter set policy count ( policy count ) exceeds limit ( policy limit )
- Traffic Prof filter set rule count (%d) exceeds limit (%d)
- Traffic Prof filter set rule count ( rule count ) exceeds limit ( rule limit )
- Traffic Prof filter set update operation failed
- Traffic Prof installation conflict seen (ID %d Ifc %d)
- Transparent UNI already configured with same I-SID
- Trap: avFabricAttachDiscoveredElement - ifIndex %d element %d
- Trap: avFabricAttachExpiredElement - ifIndex %d element %d
- Trap bsAdacPortConfigNotification
- Trap: bsAdacPortConfigNotification
- Trap bsAdacPortOperDisabledNotification
- Trap: bsAdacPortOperDisabledNotification
- Trap: bsDhcpSnoopingExtSaveSFTPRestoreFailure
- Trap: bsDhcpSnoopingExtSaveSFTPRestoreFailure
- Trap: bsDhcpSnoopingExtSaveSFTPRestoreSuccess

- [Trap: bsDhcpSnoopingExtSaveSFTPRestoreSuccess](#)
- [Trap: bsDhcpSnoopingExtSaveSFTPSyncFailure](#)
- [Trap: bsDhcpSnoopingExtSaveSFTPSyncFailure](#)
- [Trap: bsDhcpSnoopingExtSaveSFTPSyncSuccess](#)
- [Trap: bsDhcpSnoopingExtSaveSFTPSyncSuccess](#)
- [Trap: bsDhcpSnoopingExtSaveSFTPSyncSuccess](#)
- [Trap: bsifnInstallationFailure](#)
- [Trap: bsIpv6DHCPGNotif%\\$ MAC:%02x:%02x:%02x:%02x:%02x:%02x Addr:%s Port:%hhu/%hhu](#)
- [Trap: bsIpv6NDNotificationSBTTableFull - MAC:%02x:%02x:%02x:%02x:%02x:%02x Addr:%s Port:%hhu/%hhu](#)
- [Trap: bsIpv6NDNotificationsUntrustedPort - MAC:%02x:%02x:%02x:%02x:%02x:%02x Addr:%s Port:%hhu/%hhu](#)
- [Trap: bsIpv6NDNotificationUntrustedPort - MAC:%02x:%02x:%02x:%02x:%02x:%02x Addr:%s Port:%hhu/%hhu](#)
- [Trap: bsIpv6NDSBTTableFull - MAC:%02x:%02x:%02x:%02x:%02x:%02x Addr:%s Port:%hhu/%hhu](#)
- [Trap: bsIpv6RAGNotif%\\$ MAC:%02x:%02x:%02x:%02x:%02x:%02x Addr:%s Port:%hhu/%hhu](#)
- [Trap: bsLstGroupOperStateChanged](#)
- [Trap: bsLstGroupOperStateChanged](#)
- [Trap: bsLstInterfaceStatusChanged](#)
- [Trap: bsLstInterfaceStatusChanged](#)
- [Trap: bsnAaaAlreadyConnected](#)
- [Trap: bsnAaaAlreadyConnected](#)
- [Trap: bsnAaaIncorrectLogOnThresholdExceeded](#)
- [Trap: bsnAaaIncorrectLogOnThresholdExceeded](#)
- [Trap: bsnAaaMaxNoOfSessionsExceeded](#)
- [Trap: bsnAaaMaxNoOfSessionsExceeded](#)
- [Trap: bsnAaaUserAccountInactivityTrap](#)
- [Trap: bsnAaaUserAccountNotUsed](#)
- [Trap: bsnAaaUserAccountNotUsed](#)
- [Trap: bsnAaaUserPasswordAgingTrap](#)
- [Trap: bsnAaaUserPasswordExpired](#)
- [Trap: bsnAuditRecordEventsFailure](#)
- [Trap: bsnAuditShutDownTrap](#)
- [Trap: bsnAuditStartUpTrap](#)
- [Trap: bsnAuditStorageAlarm](#)
- [Trap: bsnAuditUnsentMessages](#)
- [Trap: bsnConfigurationSavedToNvram](#)
- [Trap: bsnConfigurationSavedToNvram](#)
- [Trap: bsnEapAccessViolation](#)
- [Trap: bsnEapAccessViolation](#)
- [Trap: bsnEapAccessViolationExt](#)
- [Trap: bsnEapRAVErrors](#)
- [Trap: bsnEapRAVErrorsExt](#)
- [Trap: bsnEapUbpFailure](#)
- [Trap: bsnEapUbpFailure](#)
- [Trap: bsnesActivated](#)
- [Trap: bsnesDeactivated](#)
- [Trap: bsnesGloballyDisabled](#)
- [Trap: bsnesGloballyEnabled](#)
- [Trap: bsnesManuallyActivated](#)
- [Trap: bsnesManuallyDeactivated](#)
- [Trap: bsnesScheduleApplied](#)
- [Trap: bsnesScheduleNotApplied](#)
- [Trap: bsnLacPortDisabledDueToLossOfVLACPDU](#)
- [Trap: bsnLacPortDisabledDueToLossOfVLACPDU](#)
- [Trap: bsnLacPortEnabledDueToReceiptOfVLACPDU](#)
- [Trap: bsnLacPortEnabledDueToReceiptOfVLACPDU](#)
- [Trap: bsnLacTrunkUnavailable](#)
- [Trap: bsnLoginFailure](#)
- [Trap: bsnPortSpeedDuplexMismatch](#)
- [Trap: bsnROPasswordExpired: Read-only password expired](#)
- [Trap: bsnROPasswordExpired: Read-only password expired](#)
- [Trap: bsnRWPasswordExpired: Read-write password expired](#)
- [Trap: bsnRWPasswordExpired: Read-write password expired](#)
- [Trap: bsnSFPInsertion on port](#)
- [Trap: bsnSFPInsertion on port](#)
- [Trap: bsnSFPRemoval on port](#)
- [Trap: bsnSFPRemoval on port](#)

- [Trap: bsnSnmpMaxPktSizeChanged - Maximum SNMP packet size changed to %d](#)
- [Trap bsnStackConfigurationError](#)
- [Trap: bsnStackConfigurationError](#)
- [Trap bsnStackManagerReconfiguration](#)
- [Trap: bsnStackManagerReconfiguration](#)
- [Trap: bsnStackProtection](#)
- [Trap: bsnSystemUp365Days sent from unit %d](#)
- [Trap: bsnSystemUp365Days sent from unit %d](#)
- [Trap: bsnTrialLicenseExpiration: Trial license %d has expired. Disable licensed features to avoid network interruption](#)
- [Trap: bsnTrialLicenseExpiration: Trial license %d will expire in %d day\(s\)](#)
- [Trap bsnTrialLicenseExpiration Trial license license# has expired. Disable licensed features to avoid network interruption](#)
- [Trap bsnTrialLicenseExpiration Trial license license# will expire in # days day\(s\)](#)
- [Trap: bsnTrunkPortDisabledToPreventBroadcastStorm](#)
- [Trap: bsnTrunkPortEnabledToPreventBroadcastStorm](#)
- [Trap: bsnUSBInsertion on unit](#)
- [Trap: bsnUSBInsertion on unit](#)
- [Trap: bsnUSBRemoval on unit](#)
- [Trap: bsnUSBRemoval on unit](#)
- [Trap: bspelPhonePowerLimitNotification](#)
- [Trap: bspelPhonePowerPriorityNotification](#)
- [Trap bspePethPsePortCurrentStatusNotification](#)
- [Trap: bspePethPsePortCurrentStatusNotification](#)
- [Trap: bsStormControlAboveHighWatermark](#)
- [Trap: bsStormControlBelowLowWatermark](#)
- [Trap bsUnicastStormControlAboveHighWatermark](#)
- [Trap: bsUnicastStormControlAboveHighWatermark](#)
- [Trap bsUnicastStormControlBelowLowWatermark](#)
- [Trap: bsUnicastStormControlBelowLowWatermark](#)
- [Trap bsveVrrpTrapStateTransition](#)
- [Trap: bsveVrrpTrapStateTransition](#)
- [Trap DAPP - DoS Attack Detected](#)
- [Trap: DAPP - DoS Attack Detected](#)
- [Trap Device has entered Forced Stack Mode \( MAC Address \)](#)
- [Trap: Device has entered Forced Stack Mode \(MAC:%02x:%02x:%02x:%02x:%02x IP:%s\)](#)
- [Trap entConfigChange](#)
- [Trap: entConfigChange](#)
- [Trap fallingAlarm](#)
- [Trap: fallingAlarm](#)
- [Trap: FCoE - Egress Issue Detected](#)
- [Trap: FCoE - Egress Issue Detected](#)
- [Trap IldpRemTableChange Ageouts = count](#)
- [Trap: IldpRemTableChange Ageouts = %d](#)
- [Trap IldpRemTableChange Deletes = count](#)
- [Trap: IldpRemTableChange Deletes = %d](#)
- [Trap IldpRemTableChange Drops = count](#)
- [Trap: IldpRemTableChange Drops = %d](#)
- [Trap IldpRemTableChange Inserts = count](#)
- [Trap: IldpRemTableChange Inserts = %d](#)
- [Trap: IldpXMedTopologyChangeDetected, Subtype = %d Class = %d](#)
- [Trap IldpXMedTopologyChangeDetected Subtype = subtype Class = class](#)
- [Trap: MSTP Error Event](#)
- [Trap: MSTP General Event:](#)
- [Trap: MSTP General Event:](#)
- [Trap: MSTP New Root](#)
- [Trap: MSTP Protocol Migration](#)
- [Trap: MSTP Region Config Change](#)
- [Trap: MSTP Topology Change](#)
- [Trap newRoot](#)
- [Trap: newRoot](#)
- [Trap ntnQosPolicyEvolLocalUbpSessionFailure](#)
- [Trap: ntnQosPolicyEvolLocalUbpSessionFailure](#)
- [Trap ospfIfAuthFailure](#)
- [Trap: ospfIfAuthFailure](#)
- [Trap ospfIfConfigError](#)
- [Trap: ospfIfConfigError](#)

- [Trap ospfIfStateChange](#)
- [Trap: ospfIfStateChange](#)
- [Trap ospfNbrStateChange](#)
- [Trap: ospfNbrStateChange](#)
- [Trap ospfVirtIfAuthFailure](#)
- [Trap: ospfVirtIfAuthFailure](#)
- [Trap ospfVirtIfConfigError](#)
- [Trap: ospfVirtIfConfigError](#)
- [Trap ospfVirtIfStateChange](#)
- [Trap: ospfVirtIfStateChange](#)
- [Trap ospfVirtNbrStateChange](#)
- [Trap: ospfVirtNbrStateChange](#)
- [Trap pethMainPowerUsageOffNotification](#)
- [Trap: pethMainPowerUsageOffNotification](#)
- [Trap pethMainPowerUsageOnNotification](#)
- [Trap: pethMainPowerUsageOnNotification](#)
- [Trap pethPsePortOnOffNotification](#)
- [Trap: pethPsePortOnOffNotification](#)
- [Trap: rclpBgpTmpAfBackwardTransitionNotification](#)
- [Trap: rclpBgpTmpAfEstablishedNotification](#)
- [Trap: rclsisPlsbBvidMismatchTrap](#)
- [Trap: rclsisPlsbBvidMismatchTrap](#)
- [Trap: rclsisPlsbLsdbUpdateTrap](#)
- [Trap: rclsisPlsbLsdbUpdateTrap](#)
- [Trap: rclsisPlsbSmltPeerBmacMismatchTrap](#)
- [Trap: rclsisPlsbSmltPeerBmacMismatchTrap](#)
- [Trap: rclsisPlsbSmltSplitBebMismatchTrap](#)
- [Trap: rclsisPlsbSmltSplitBebMismatchTrap](#)
- [Trap: rclsisPlsbSmltVirtBmacMismatchTrap](#)
- [Trap: rclsisPlsbSmltVirtBmacMismatchTrap](#)
- [Trap: rcVrrpExtTrapStateTransitionTrap - master ipv6 address %s, ifindex %i, vrid %i](#)
- [Trap: rcVrrpTmpTrapNewMasterTrap - master ipv6 address %s, ifindex %d, vrid %d](#)
- [Trap risingAlarm](#)
- [Trap: risingAlarm](#)
- [Trap RSTP Error Event](#)
- [Trap: RSTP Error Event](#)
- [Trap RSTP General Event](#)
- [Trap: RSTP General Event:](#)
- [Trap: RSTP General Event:](#)
- [Trap RSTP New Root](#)
- [Trap: RSTP New Root](#)
- [Trap RSTP Protocol Migration](#)
- [Trap: RSTP Protocol Migration](#)
- [Trap RSTP Topology Change](#)
- [Trap: RSTP Topology Change](#)
- [Trap: Run %s %s](#)
- [Trap: Run %s %s](#)
- [Trap: s5CtrFanDirectionError](#)
- [Trap: s5CtrFanDirectionError](#)
- [Trap: s5CtrHighTemperatureError](#)
- [Trap: s5CtrHighTemperatureError](#)
- [Trap s5CtrHotSwap](#)
- [Trap: s5CtrNewHotSwap](#)
- [Trap: s5CtrNewProblem](#)
- [Trap: s5CtrNewUnitDown](#)
- [Trap: s5CtrNewUnitUp](#)
- [Trap s5CtrUnitDown](#)
- [Trap: s5CtrUnitDown](#)
- [Trap: s5EtrMacAddressTablesThresholdReached](#)
- [Trap: s5EtrMacAddressTablesThresholdReached](#)
- [Trap: s5EtrNewSbsMacAccessViolation](#)
- [Trap s5EtrSbsMacAccessViolation](#)
- [Trap: s5EtrSbsMacAccessViolation](#)
- [Trap s5EtrSbsMacRemoved](#)
- [Trap: s5EtrSbsMacRemoved](#)



- [Trap s5EtrSbsMacTableCleared](#)
- [Trap: s5EtrSbsMacTableCleared](#)
- [Trap s5EtrSbsMacTableClearedForPort](#)
- [Trap: s5EtrSbsMacTableClearedForPort](#)
- [Trap: s5EtrSbsMacTableFull](#)
- [Trap: SFP Transceiver's Bias has reached an alarm level](#)
- [Trap: SFP Transceiver's Bias has reached a warning level](#)
- [Trap: SFP Transceiver's Bias is no longer at warning/alarm level](#)
- [Trap: SFP Transceiver's Bias is no longer at warning/alarm level](#)
- [Trap:\\$#160:SFP Transceiver's Bias is no longer at warning/alarm level](#)
- [Trap: SFP Transceiver's Rx Power has reached an alarm level](#)
- [Trap: SFP Transceiver's Rx Power has reached a warning level](#)
- [Trap: SFP Transceiver's Rx Power is no longer at warning/alarm level](#)
- [Trap: SFP Transceiver's Temperature has reached an alarm level](#)
- [Trap: SFP Transceiver's Temperature has reached a warning level](#)
- [Trap: SFP Transceiver's Temperature is no longer at warning/alarm level](#)
- [Trap: SFP Transceiver's Temperature is no longer at warning/alarm level](#)
- [Trap:\\$#160:SFP Transceiver's Temperature is no longer at warning/alarm level](#)
- [Trap: SFP Transceiver's Tx Power has reached an alarm level](#)
- [Trap: SFP Transceiver's Tx Power has reached a warning level](#)
- [Trap: SFP Transceiver's Tx Power is no longer at warning/alarm level](#)
- [Trap: SFP Transceiver's Tx Power is no longer at warning/alarm level](#)
- [Trap:\\$#160:SFP Transceiver's Tx Power is no longer at warning/alarm level](#)
- [Trap: SFP Transceiver's Voltage has reached an alarm level](#)
- [Trap: SFP Transceiver's Voltage has reached a warning level](#)
- [Trap: SFP Transceiver's Voltage is no longer at warning/alarm level](#)
- [Trap: slaMonitorAgentExceptionDetected](#)
- [Trap: SLPP Guard Hold Down Expired. %s. Port has been re-enabled](#)
- [Trap: SLPP Guard Packet Received. %s. Port has been disabled](#)
- [Trap SLPP Port Down Event](#)
- [Trap: SLPP Port Down Event](#)
- [Trap Smlt Ist Link Down](#)
- [Trap: Smlt Ist Link Down](#)
- [Trap Smlt Ist Link Up](#)
- [Trap: Smlt Ist Link Up](#)
- [Trap Smlt Link Down](#)
- [Trap: Smlt Link Down](#)
- [Trap Smlt Link Up](#)
- [Trap: Smlt Link Up](#)
- [Trap topologyChange](#)
- [Trap: topologyChange](#)
- [Trap ubpEAPSessionEnd](#)
- [Trap: ubpEAPSessionEnd](#)
- [Trap ubpEAPSessionStart](#)
- [Trap: ubpEAPSessionStart](#)
- [Trap vrrpTrapNewMaster](#)
- [Trap: vrrpTrapNewMaster](#)
- [trTCM meter issue - PBS must be greater than CBS](#)
- [trTCM meter issue - PIR must be greater than CIR](#)
- [Trusted processing mode change rejected - inadequate resources](#)
- [tx db cat=%d cnt=%d](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Logs starting with U

This page lists all logs that have a starting letter of U. Select the log you wish to view or navigate to a different starting letter.

Using your browser's 'find' function on this page may help you locate a specific log name faster.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

- [UBP CoA cannot proceed, dynamic UBP not enabled either for EAP or Non-EAP clients](#)
- [Unable to add block member \( block elem# component set id \) to existing policy](#)
- [Unable to add block member \(%d/%d\) to existing policy](#)
- [Unable to apply existing policy data to interface \(%d/%d\)](#)
- [Unable to apply existing policy data to interface \( unit# port# \)](#)
- [Unable to apply existing user-based policy data to new user](#)
- [Unable to apply filter set to ports \(unsupported capabilities\)](#)
- [Unable to apply newly-defined UBP filter set to existing user](#)
- [Unable to apply pre-defined UBP filter set to new user](#)
- [Unable to apply pre-defined UBP filter set to new user \(port %d/%d\)](#)
- [Unable to complete requested access asgn system operation \(%d\)](#)
- [Unable to complete requested access asgn system operation \( oper type \)](#)
- [Unable to complete requested policy system operation \(%d\)](#)
- [Unable to complete requested policy system operation \( operation type \)](#)
- [Unable to compress classification criteria in set adequately](#)
- [Unable to compress specified policy criteria](#)
- [Unable to create action for access element](#)
- [Unable to create classifier block entry for access element](#)
- [Unable to create classifier component entry for access element](#)
- [Unable to create count action \(meter\) for access assignment](#)
- [Unable to create count action \(policy\) for access assignment](#)
- [Unable to create count action \(secondary meter\) for access asgn](#)
- [Unable to create DS MF classifier for access element](#)
- [Unable to create L2 MF classifier for access element](#)
- [Unable to create metering data for access assignment](#)
- [Unable to create non-match components for ACL](#)
- [Unable to create out-of-profile action for access assignment](#)
- [Unable to create policy data for access assignment](#)
- [Unable to create secondary metering data for access assignment](#)
- [Unable to create secondary token bucket data for access asgn](#)
- [Unable to create token bucket data for access assignment](#)
- [Unable to create yellow action for access assignment](#)
- [Unable to deactivate policy associated with interface](#)
- [Unable to delete block member \( block element# component set id \) from existing policy](#)
- [Unable to delete block member \(%d/%d\) from existing policy](#)
- [Unable to delete UBP filter set on interface %d](#)
- [Unable to delete UBP filter set on interface ifc#](#)
- [Unable to derive suitable filter set element eval precedence](#)
- [Unable to determine clfr interface\(s\) compatibility](#)
- [Unable to determine clfr/interface\(s\) compatibility](#)
- [Unable to determine meter/interface\(s\) compatibility](#)
- [Unable to disable ARP Spoofing support on interface \(%d\)](#)
- [Unable to disable ARP Spoofing support on interface \( ifc# \)](#)
- [Unable to disable BPDUBIkr support on interface \(%d\)](#)
- [Unable to disable BPDUBIkr support on interface \( ifc# \)](#)

- [Unable to disable DHCP Snooping support on interface \(%d\)](#)
- [Unable to disable DHCP Snooping support on interface \( ifc# \)](#)
- [Unable to disable DHCP Spoofing support on interface \(%d\)](#)
- [Unable to disable DHCP Spoofing support on interface \( ifc# \)](#)
- [Unable to disable DNSPort support on interface \(%d\)](#)
- [Unable to disable DNSPort support on interface \( ifc# \)](#)
- [Unable to disable existing policy data on interface \(%d/%d\)](#)
- [Unable to disable existing policy data on interface \( unit# port# \)](#)
- [Unable to disable FTPPort support on interface \(%d\)](#)
- [Unable to disable FTPPort support on interface \( ifc# \)](#)
- [Unable to disable Nachia support on interface \(%d\)](#)
- [Unable to disable Nachia support on interface \( ifc# \)](#)
- [Unable to disable policy data for access assignment](#)
- [Unable to disable SQLSlam support on interface \(%d\)](#)
- [Unable to disable SQLSlam support on interface \( ifc# \)](#)
- [Unable to disable SynFinScan support on interface \(%d\)](#)
- [Unable to disable SynFinScan support on interface \( ifc# \)](#)
- [Unable to disable Xmas support on interface \(%d\)](#)
- [Unable to disable Xmas support on interface \( ifc# \)](#)
- [Unable to enable ARP Spoofing support on interface \(%d\)](#)
- [Unable to enable ARP Spoofing support on interface \( ifc# \)](#)
- [Unable to enable BPDUBIkr support on interface \(%d\)](#)
- [Unable to enable BPDUBIkr support on interface \( ifc# \)](#)
- [Unable to enable BPDUBIkr support on multiple interfaces](#)
- [Unable to enable DHCP Snooping support on interface \(%d\)](#)
- [Unable to enable DHCP Snooping support on interface \( ifc# \)](#)
- [Unable to enable DHCP Spoofing support on interface \(%d\)](#)
- [Unable to enable DHCP Spoofing support on interface \( ifc# \)](#)
- [Unable to enable DNSPort support on interface \(%d\)](#)
- [Unable to enable DNSPort support on interface \( ifc# \)](#)
- [Unable to enable FTPPort support on interface \(%d\)](#)
- [Unable to enable FTPPort support on interface \( ifc# \)](#)
- [Unable to enable Nachia support on interface \(%d\)](#)
- [Unable to enable Nachia support on interface \( ifc# \)](#)
- [Unable to enable policy data for access assignment](#)
- [Unable to enable SQLSlam support on interface \(%d\)](#)
- [Unable to enable SQLSlam support on interface \( ifc# \)](#)
- [Unable to enable SynFinScan support on interface \(%d\)](#)
- [Unable to enable SynFinScan support on interface \( ifc# \)](#)
- [Unable to enable Xmas support on interface \(%d\)](#)
- [Unable to inform SPB of ifc assignment change \(%d/%d\)](#)
- [Unable to inform SPB of ifc assignment change \(%d/%d\)](#)
- [Unable to install access assignment - component creation issue](#)
- [Unable to install access element - component creation issue](#)
- [Unable to locate corresponding DS L2 access elements](#)
- [Unable to locate corresponding DS/L2 access elements](#)
- [Unable to manipulate DAPP support \(no applicable interfaces\)](#)
- [Unable to modify access assignment - component modify issue](#)
- [Unable to relinquish FCoE resource reservations](#)
- [Unable to restore dynamic ifc to default role association \(%d/%d\)](#)
- [Unable to restore dynamic ifc to static role association \(%d/%d\)](#)
- [Unable to update config in NVRAM - %s line %d](#)
- [Unable to validate metering data - request denied](#)
- [Unable to verify required filter criteria](#)
- [Unauthorized connection attempt from IP address:](#)
- [Unexpected DB Ack, got %s from unit # %d, expected %s](#)
- [UNI already exists on the specified port and VLAN](#)
- [Unicast block unit/port %d/%d level %u watermark %u](#)
- [Unicast block unit port unit port level level watermark watermark](#)
- [Unicast \(%d\) and Non-Unicast \(%d\) interfaces in conflict](#)
- [Unicast \( Interface# \) and Non-Unicast \( interface# \) interfaces in conflict](#)
- [Unicast over high watermark unit/port %d/%d level %u watermark %u](#)
- [Unicast still blocked unit/port %d/%d level %u watermark %u](#)
- [Unicast still over low watermark unit/port %d/%d level %u watermark %u](#)
- [Unicast unblock unit/port %d/%d level %u watermark %u](#)

- [Unicast unblock unit port unit port level level watermark watermark](#)
- [Unicast under low watermark unit/port %d/%d level %u watermark %u](#)
- [Unit #%d already deleted from this unit's database](#)
- [Unit #%d link down on %s](#)
- [Unit #%d link up on %s](#)
- [Unknown access assignment entry specified \(%d\)](#)
- [Unknown access element entry specified \(%d\)](#)
- [Unknown access element entry specified \( entry# \)](#)
- [Unknown action entry specified \(%d\)](#)
- [Unknown action entry specified \( entry# \)](#)
- [Unknown classifier block entry specified \(%d\)](#)
- [Unknown classifier block entry specified \( entry# \)](#)
- [Unknown classifier component entry specified \(%d\)](#)
- [Unknown classifier component entry specified \( entry# \)](#)
- [Unknown CoS shaping entry specified \(%d/%d\)](#)
- [Unknown CoS shaping entry specified \( entry# CoS \)](#)
- [Unknown count action entry specified \(%d\)](#)
- [Unknown count action entry specified \( entry# \)](#)
- [Unknown DSCP mapping entry specified \(%d\)](#)
- [Unknown DSCP mapping entry specified \( entry# \)](#)
- [Unknown entry \(class class# \) specified \( entry# \)](#)
- [Unknown entry \(class %d\) specified \(%d\)](#)
- [Unknown FCoE redirection entry specified \(%d\)](#)
- [Unknown incompatible access element specified](#)
- [Unknown/incompatible access element specified](#)
- [Unknown incompatible action component specified](#)
- [Unknown/incompatible action component specified](#)
- [Unknown incompatible classifier block specified](#)
- [Unknown/incompatible classifier block specified](#)
- [Unknown incompatible classifier set specified](#)
- [Unknown/incompatible classifier set specified](#)
- [Unknown incompatible in-profile action specified](#)
- [Unknown/incompatible in-profile action specified](#)
- [Unknown incompatible in-profile \(green\) action specified](#)
- [Unknown/incompatible in-profile \(green\) action specified](#)
- [Unknown incompatible match action specified](#)
- [Unknown/incompatible match action specified](#)
- [Unknown incompatible metering component specified](#)
- [Unknown/incompatible metering component specified](#)
- [Unknown incompatible metering statistics entry specified](#)
- [Unknown/incompatible metering statistics entry specified](#)
- [Unknown incompatible out-of-profile action specified](#)
- [Unknown/incompatible out-of-profile action specified](#)
- [Unknown incompatible out-of-profile \(red\) action specified](#)
- [Unknown/incompatible out-of-profile \(red\) action specified](#)
- [Unknown incompatible out-of-profile \(yellow\) action specified](#)
- [Unknown/incompatible out-of-profile \(yellow\) action specified](#)
- [Unknown incompatible policy non-match action specified](#)
- [Unknown/incompatible policy non-match action specified](#)
- [Unknown incompatible policy statistics entry specified](#)
- [Unknown/incompatible policy statistics entry specified](#)
- [Unknown incompatible queue set specified](#)
- [Unknown/incompatible queue set specified](#)
- [Unknown incompatible role combination specified](#)
- [Unknown/incompatible role combination specified](#)
- [Unknown incompatible token bucket reference specified](#)
- [Unknown incompatible token bucket reference specified](#)
- [Unknown/incompatible token bucket reference specified](#)
- [Unknown interface application entry specified \(%d\)](#)
- [Unknown interface application entry specified \( entry# \)](#)
- [Unknown interface assignment entry specified \(%d\)](#)
- [Unknown interface assignment entry specified \( entry# \)](#)
- [Unknown interface queue entry specified \(%d\)](#)
- [Unknown interface queue entry specified \( ifc queue id \)](#)
- [Unknown interface shaping entry specified \(%d\)](#)

- [Unknown interface shaping entry specified \( entry# \)](#)
- [Unknown IP classifier entry specified \(%d\)](#)
- [Unknown Layer 2 classifier entry specified \(%d\)](#)
- [Unknown Layer 2 classifier entry specified \( entry# \)](#)
- [Unknown meter entry specified \(%d\)](#)
- [Unknown/out-of-range interface index value \(%d\)](#)
- [Unknown out-of-range interface index value \( ifc# \)](#)
- [Unknown out-of-range interface index value \( ifc index \)](#)
- [Unknown policy entry specified \(%d\)](#)
- [Unknown policy entry specified \( entry# \)](#)
- [Unknown 802.1p user priority mapping entry specified \(%d\)](#)
- [Unknown 802.1p user priority mapping entry specified \( entry# \)](#)
- [Unknown queue set assignment entry specified \(%d\)](#)
- [Unknown queue set assignment entry specified \( entry# \)](#)
- [Unknown queue set queue reference detected](#)
- [Unknown queue set/queue reference detected](#)
- [Unknown queue shaping entry specified \(%d/%d\)](#)
- [Unknown queue shaping entry specified \( entry# queue \)](#)
- [Unknown role combination entry specified \(%d\)](#)
- [Unknown role combination entry specified \( role comb id \)](#)
- [Unknown System classifier entry specified \(%d\)](#)
- [Unknown System classifier entry specified \( entry# \)](#)
- [Unknown token bucket entry specified \(%d\)](#)
- [Unknown token bucket entry specified \( entry# \)](#)
- [Unknown unsupported attribute specified \( attribute \)](#)
- [Unknown/unsupported attribute specified \(%d\)](#)
- [Unknown unsupported interface application type specified](#)
- [Unknown/unsupported interface application type specified](#)
- [Unknown/unsupported interface class specified \(%d\)](#)
- [Unknown unsupported interface class specified \( ifc class \)](#)
- [Unknown unsupported IP Flag specified](#)
- [Unknown/unsupported IP Flag specified](#)
- [Unknown unsupported RowStatus specified](#)
- [Unknown/unsupported RowStatus specified](#)
- [Unknown unsupported StorageType specified](#)
- [Unknown/unsupported StorageType specified](#)
- [Unknown unsupported TCP Control Flag specified](#)
- [Unknown/unsupported TCP Control Flag specified](#)
- [Unknown user policy entry specified \(%d\)](#)
- [Unknown user policy entry specified \( entry# \)](#)
- [Unsupported field for ACL in dynamic CoA UBP](#)
- [Unsupported field for ACL in dynamic UBP, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x](#)
- [Unsupported field for SET in dynamic CoA UBP](#)
- [Unsupported field for SET in dynamic UBP, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x](#)
- [Unsupported IP address type specified](#)
- [Unsupported IPv4 Options value specified](#)
- [Unsupported pattern offset data specified](#)
- [Unsupported unknown QoS agent configuration attribute \( attribute# \)](#)
- [Unsupported/unknown QoS agent configuration attribute \(%d\)](#)
- [Unsupported value for ACL field in dynamic CoA UBP](#)
- [Unsupported value for ACL field in dynamic UBP, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x](#)
- [Unsupported value for SET field in dynamic CoA UBP](#)
- [Unsupported value for SET field in dynamic UBP, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x](#)
- [Update priority value and update DSCP value out-of-sync](#)
- [Update priority value per ingress DSCP currently not supported](#)
- [Upstream direction is logically down](#)
- [Upstream direction is logically up](#)
- [Upstream Port #%u is unexpectedly logically up](#)
- [Upstream stack direction is down cable removed or neighbor powered off](#)
- [Upstream stack direction is down, cable removed or neighbor powered off](#)
- [Upstream stack direction is misconfigured](#)
- [Upstream stack direction is mis-configured](#)
- [Upstream stack direction is up, cable inserted or neighbor powered on](#)
- [Upstream stack ports down, wait for stack ports before processing](#)
- [Upstream Stack Port #%u is logically down](#)

- [Upstream Stack Port # %u is logically up](#)
- [Upstream stack port %u is misconfigured](#)
- [USB device inserted](#)
- [USB device removed](#)
- [USB nvRam file error](#)
- [USB unsupported file system](#)
- [USC Install SET fail unit port unit port status = status](#)
- [USC Install TEST fail unit port unit port status = status](#)
- [USC UnInst SET failed for port port status = status](#)
- [Used stack size of task %s is \(%d%%\).](#)
- [User allowed \(fallback authentication\) to log in from Web from Src IP](#)
- [User allowed \(radius authentication pass\) to log in from Web from Src IP](#)
- [User allowed \(radius authentication pass\) to log in from Web from Src IP](#)
- [User disallowed \(radius authentication fail\) to log in from Web from Src IP](#)
- [User Policy data referencing interface \(operation prohibited\)](#)
- [User policy distribution across stack failed](#)
- [User policy filter set count \(%d\) exceeds limit \(%d\)](#)
- [User policy filter set count \(<set count>\) exceeds limit \(<set limit>\)](#)
- [User policy filter set delete operation failed](#)
- [User policy filter set element count exceeds available resources](#)
- [User policy filter set install operation failed](#)
- [User policy filter set update operation failed](#)
- [User policy group contains invalid unacceptable characters](#)
- [User policy group contains invalid/unacceptable characters](#)
- [User policy group length outside of acceptable limits](#)
- [User policy modifications not supported](#)
- [User policy name contains invalid unacceptable characters](#)
- [User policy name contains invalid/unacceptable characters](#)
- [User policy name length outside of acceptable limits](#)
- [User Policy \(UBP\) filter set in use \(QoS disable prohibited\)](#)
- [User Policy \(UBP\) filter set in use \(QoS reset prohibited\)](#)
- [User priority specified with untagged frames \(invalid\)](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Logs starting with V

This page lists all logs that have a starting letter of V. Select the log you wish to view or navigate to a different starting letter.

Using your browser's 'find' function on this page may help you locate a specific log name faster.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

- [VLACP: API error: %d-%d-%d.](#)
- [VLACP: input parameter error: %d-%d-%d](#)
- [VLACP: msgQ error: %d-%d-%d](#)
- [VLACP: nvRam file error](#)
- [VLACP: RX event: %d - %d - %d](#)
- [VLACP: Stack event: %d - %d - 0x%x](#)
- [VLACP: Start](#)
- [VLACP: TMR event: %d - %d - %d](#)
- [VLACP: TX event: %d - %d - %d](#)
- [VLACP: vlacp\\_log\\_link\\_change: %d - %d - %d](#)
- [VLAN cannot re-assign](#)
- [VLAN configuration does not match BU VLAN configuration.DIFF\\_MASK=](#)
- [VLAN configuration does not match BU VLAN configuration. VLAN config defaulted](#)
- [VLAN configuration does not match BU VLAN configuration. VLAN config defaulted](#)
- [VLAN does not exist](#)
- [VLAN ID min/max values invalid \(%d !< %d\)](#)
- [VLAN ID min max values invalid \( min VLAN ID ! max VLAN ID \)](#)
- [VLAN IMC callback failed](#)
- [VLAN IMC was not sent](#)
- [Vlan is already a RSPAN vlan](#)
- [VLAN is configured as C-VLAN](#)
- [VLAN is configured as switched UNI](#)
- [VLAN is not switched UNI](#)
- [VLAN NVRAM read error](#)
- [VLAN NVRAM read error](#)
- [VLAN queue messages discarded](#)
- [VLAN queue messages discarded](#)
- [VLAN range could not be reduced sufficiently](#)
- [VLAN range support with FCoE redirection not available](#)
- [VLAN set error from IMC](#)
- [VLAN set error from RPC](#)
- [VLAN to VRF Mapping Message Sent Failure.](#)
- [Voice VLAN ID and Data VLAN ID cannot have the same value](#)
- [VRF Already Exist.](#)
- [VRF Constructor failed to create.](#)
- [VRF feature disabled due to inadequate license.](#)
- [VRF IP Forwarding is Enable while changing the Maxroutes.](#)
- [VRF Not Exist.](#)
- [VRF NvRAM Open Error.](#)
- [VRF NvRAM Read Error.](#)
- [VRRP Feature globally disabled due to missing license](#)
- [VRRP: Feature globally disabled due to missing license](#)
- [VRRP: IP address is changed to \(0x%08X\), different than Phy IP Address. Decreasing automatically priority from 255 to 254.](#)
- [VRRPv3 filters have NOT been installed.](#)
- [VRRPv3 filters successfully installed.](#)



- [VRRP: VR %d/%d: Received mismatching advertisement interval \(%d\)](#)
- [VRRP: VR %d/%d: Received mismatching advertisement type \(%d\)](#)
- [VRRP: VR %d/%d: Received mismatching fast advertisement interval \(%d\)](#)
- [VRRP: VR %d/%d: Received mismatching virtual IP address \(0x%08X\)](#)
- [VRRP: VR %d/%d: Received unknown VRRP packet type \(%d\)](#)
- [VRRP: vrrpAdvQueue is FULL. RX advertisement dropped in vlan %d!](#)
- [VRRP: vrrpQueue is FULL. Message dropped.](#)
- [VRRP VR VR Id VLAN Id Received mismatching advertisement interval \( advertisement interval\)](#)
- [VRRP VR VR Id VLAN Id Received mismatching advertisement type \( advertisement type \)](#)
- [VRRP VR VR Id VLAN Id Received mismatching fast advertisement interval \( fast advertisement interval\)](#)
- [VRRP VR VR Id VLAN Id Received mismatching virtual IP address \( received virtual ip address \)](#)
- [VRRP VR VR Id VLAN Id Received unknown VRRP packet type \( vrrp packet type \)](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Logs starting with W

This page lists all logs that have a starting letter of W. Select the log you wish to view or navigate to a different starting letter.

Using your browser's 'find' function on this page may help you locate a specific log name faster.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

- [Warm Start Trap](#)
- [Warning](#)
- [Warning failed to connect to %s card \(in unit %s\)](#)
- [Warning: non-supported qsfp inserted on %s. Port will be disabled.](#)
- [Warning: non-supported qsfp inserted on %s. Port will not link up.](#)
- [Warning: non-supported stack cable inserted on %s. Stacking port will be admin disabled.](#)
- [Warning:non-supported transceiver on %s has been detected.](#)
- [Warning %s card unsafely removed \(from unit %s\)](#)
- [WEB-access is disabled](#)
- [WEB-access is disabled](#)
- [WEB-access is enabled](#)
- [WEB-access is enabled](#)
- [Web authentication fail from IP address](#)
- [Web authentication fail from IP address](#)
- [Web authentication from IP address](#)
- [Web authentication from IP address](#)
- [Web authentication \(RADIUS auth\) from IP address](#)
- [Web connection from IP address](#)
- [Web connection from IP address](#)
- [WebControl server running.](#)
- [Web disconnect from IP address](#)
- [Web disconnect from IP address](#)
- [Web server attempting to open socket for port %d.](#)
- [Web server attempting to open socket for port HTTP port](#)
- [Web server starts service on port %d.](#)
- [Web server starts service on port HTTP port](#)
- [Web server starts service on ports: %d for HTTP and %d for HTTPS.](#)
- [Web timeout from IP address](#)
- [Web timeout from IP address](#)
- [When enable IST must configure SMLT peer BMAC](#)
- [When setting Virtual BMAC to zero. Peer BMAC must be zero](#)
- [Wrong OoS Agent buffer setting. expected %s, actual %s, unit cannot join stack](#)
- [Wrong OoS Agent buffer setting. expected %s, actual %s, unit reconfigured and reboot](#)
- [Wrong OoS Agent buffer setting. expected %s, actual %s, unit re-configured and reboot](#)
- [Wrong OoS Agent buffer setting. expected %s, actual %s, unit re-configured and reboot](#)
- [Wrong OoS Agent buffer setting expected value actual value unit cannot join stack.](#)
- [Wrong OoS Agent queue setting. expected %u, actual %u, unit cannot join stack](#)
- [Wrong OoS Agent queue setting. expected %u, actual %u, unit cannot join stack](#)
- [Wrong OoS Agent queue setting. expected %u, actual %u, unit reconfigured and reboot](#)
- [Wrong OoS Agent queue setting. expected %u, actual %u, unit re-configured and reboot](#)
- [Wrong OoS Agent queue setting. expected %u, actual %u, unit reconfigured and reboot](#)
- [Wrong OoS Agent queue setting. expected %u, actual %u, unit re-configured and reboot](#)
- [Wrong value](#)
- [Wrong value](#)
- [Wrong VLANs nvq\\_RecDescr actRecs](#)

- [Wrong VLANs nvq RecDescr actRecs](#)
- [Wrong VMACs nvq RecDescr actRecs](#)
- [Wrong VMACs nvq RecDescr actRecs](#)
- [Wrong vrec field](#)
- [Wrong vrec field](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# All logs starting with X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Logs starting with X

This page lists all logs that have a starting letter of X. Select the log you wish to view or navigate to a different starting letter.

Using your browser's 'find' function on this page may help you locate a specific log name faster.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

- [0x%X 0x%X 0x%X](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# All logs starting with Z

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Logs starting with Z

This page lists all logs that have a starting letter of Z. Select the log you wish to view or navigate to a different starting letter.

Using your browser's 'find' function on this page may help you locate a specific log name faster.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

- [Zero SMLT peer BMAC must have primary split BEB](#)
- [Zero SMLT peer BMAC must have primary split BEB](#)
- [Zero SMLT peer BMAC must have zero virtual BMAC](#)
- [Zero SMLT peer BMAC must have zero virtual BMAC](#)
- [ZTP+: failed to connect to the XMC server](#)
- [ZTP+: failed to start the auto-provisioning process](#)
- [ZTP+: failed to upgrade the firmware](#)
- [ZTP+: successfully connected to the XMC server](#)
- [ZTP+: successfully upgraded the firmware](#)
- [ZTP+: the auto-provisioning process has started](#)
- [ZTP+: the firmware upgrade has started](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [K](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [X](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QoS logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QoS logs

There are 988 logs for this source. To simplify navigation, all logs are organized alphabetically by their name. Select the letter to navigate to the list of all logs starting with that letter for this source.

<a href="#">A</a> 28 logs	<a href="#">B</a> 9 logs	<a href="#">C</a> 64 logs	<a href="#">D</a> 45 logs
<a href="#">E</a> 14 logs	<a href="#">F</a> 41 logs	<a href="#">G</a> 1 logs	H
<a href="#">I</a> 315 logs	J	K	<a href="#">L</a> 7 logs
<a href="#">M</a> 20 logs	<a href="#">N</a> 31 logs	<a href="#">O</a> 9 logs	<a href="#">P</a> 50 logs
<a href="#">Q</a> 15 logs	<a href="#">R</a> 32 logs	<a href="#">S</a> 54 logs	<a href="#">T</a> 26 logs
<a href="#">U</a> 223 logs	<a href="#">V</a> 4 logs	W	X
Y	Z		

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## logs

The following logs are generated for this source:

- [DosFs - Error File not closed](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Fabric Attach logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach logs

There are 210 logs for this source. To simplify navigation, all logs are organized alphabetically by their name. Select the letter to navigate to the list of all logs starting with that letter for this source.

A	B	C	D
E	<b>E</b> 210 logs	G	H
I	J	K	L
M	N	O	P
Q	R	S	T
U	V	W	X
Y		Z	

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# 802.1AB logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## 802.1AB logs

The following logs are generated for this source:

- [Trap IldpRemTableChange Ageouts = count](#)
- [Trap IldpRemTableChange Deletes = count](#)
- [Trap IldpRemTableChange Drops = count](#)
- [Trap IldpRemTableChange Inserts = count](#)
- [Trap IldpXMedTopologyChangeDetected Subtype = subtype Class = class](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SNMP logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SNMP logs

There are 208 logs for this source. To simplify navigation, all logs are organized alphabetically by their name. Select the letter to navigate to the list of all logs starting with that letter for this source.

<a href="#">A</a> 1 logs	B	<a href="#">C</a> 1 logs	<a href="#">D</a> 30 logs
<a href="#">E</a> 4 logs	F	G	H
<a href="#">I</a> 2 logs	J	K	<a href="#">L</a> 2 logs
M	N	O	<a href="#">P</a> 1 logs
Q	<a href="#">R</a> 1 logs	<a href="#">S</a> 9 logs	<a href="#">T</a> 156 logs
U	V	<a href="#">W</a> 1 logs	X
Y		Z	

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AAA logs

The following logs are generated for this source:

- [Can not create user](#)
- [Can not delete user, user does not exist](#)
- [Can not disable user, user does not exist](#)
- [Can not enable user, user does not exist](#)
- [Password policy has changed](#)
- [The account for user <%s> expires in %d days due to inactivity](#)
- [The password for user <%s> expires in %d days due to password aging](#)
- [The password for user <%s> has expired.](#)
- [The password for user <%s> was changed](#)
- [The password for user <%s> was not changed](#)
- [The role for user <%s> changed to %s](#)
- [The user <%s> was disabled](#)
- [The user <%s> was enabled](#)
- [The user <%s> was locked](#)
- [The user <%s> was unlocked](#)
- [The user <%s> with %s role has been created](#)
- [The user <%s> with %s role has been deleted](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# EAP logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP logs

There are 189 logs for this source. To simplify navigation, all logs are organized alphabetically by their name. Select the letter to navigate to the list of all logs starting with that letter for this source.

<a href="#">A</a>	<a href="#">B</a>	<a href="#">C</a>	<a href="#">D</a>
<a href="#">E</a> 136 logs	<a href="#">F</a>	<a href="#">G</a> 4 logs	<a href="#">H</a>
<a href="#">I</a> 6 logs	<a href="#">J</a>	<a href="#">K</a>	<a href="#">L</a>
<a href="#">M</a> 5 logs	<a href="#">N</a> 27 logs	<a href="#">O</a>	<a href="#">P</a>
<a href="#">Q</a>	<a href="#">R</a>	<a href="#">S</a>	<a href="#">T</a> 2 logs
<a href="#">U</a> 9 logs	<a href="#">V</a>	<a href="#">W</a>	<a href="#">X</a>
<a href="#">Y</a>		<a href="#">Z</a>	

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ACG logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ACG logs

The following logs are generated for this source:

- [ASCII failed](#)
- [ASCII finished successfully](#)
- [ASCII finished successfully at load on boot](#)
- [ASCII transfer failed](#)
- [ASCII transfer failed at load on boot](#)
- [ASCII transfer OK](#)
- [ASCII transfer OK at load on boot](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ISIS logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ISIS logs

There are 158 logs for this source. To simplify navigation, all logs are organized alphabetically by their name. Select the letter to navigate to the list of all logs starting with that letter for this source.

<a href="#">A</a> 2 logs	B	<a href="#">C</a> 60 logs	<a href="#">D</a> 7 logs
E	F	G	H
<a href="#">I</a> 34 logs	J	K	<a href="#">L</a> 1 logs
<a href="#">M</a> 5 logs	<a href="#">N</a> 2 logs	<a href="#">O</a> 3 logs	<a href="#">P</a> 5 logs
Q	<a href="#">R</a> 4 logs	<a href="#">S</a> 18 logs	<a href="#">T</a> 5 logs
<a href="#">U</a> 1 logs	<a href="#">V</a> 5 logs	<a href="#">W</a> 2 logs	X
Y	<a href="#">Z</a> 4 logs		

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# ADAC logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ADAC logs

The following logs are generated for this source:

- [ADAC: ADAC of IP Phones not functional](#)
- [ADAC: ADAC of Nortel IP Phones not functional](#)
- [ADAC: Error applying main %s configuration](#)
- [ADAC Error applying main VLAN QoS configuration](#)
- [ADAC: Error applying %s configuration for unit/port: %d/%d](#)
- [ADAC Error applying VLAN QoS configuration for unit port unit# port#](#)
- [ADAC Error forcing administrative state to disable enable](#)
- [ADAC: Error forcing administrative state to %s](#)
- [ADAC: Error registering CDT handlers](#)
- [ADAC: Error removing main %s configuration](#)
- [ADAC Error removing main VLAN QoS configuration](#)
- [ADAC: Error removing %s configuration for unit/port: %d/%d](#)
- [ADAC Error removing VLAN QoS configuration for unit port unit# port#](#)
- [ADAC Forced administrative state to disable enable](#)
- [ADAC: Forced administrative state to %s](#)
- [ADAC System operationally disable enable](#)
- [ADAC: System operationally %s](#)
- [Trap bsAdacPortConfigNotification](#)
- [Trap bsAdacPortOperDisabledNotification](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SMGR logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SMGR logs

There are 100 logs for this source. To simplify navigation, all logs are organized alphabetically by their name. Select the letter to navigate to the list of all logs starting with that letter for this source.

A	<a href="#">B</a> 1 logs	<a href="#">C</a> 4 logs	<a href="#">D</a> 9 logs
<a href="#">E</a> 1 logs	<a href="#">F</a> 6 logs	G	<a href="#">H</a> 1 logs
I	<a href="#">J</a> 1 logs	K	<a href="#">L</a> 1 logs
<a href="#">M</a> 2 logs	<a href="#">N</a> 2 logs	O	P
Q	<a href="#">R</a> 4 logs	<a href="#">S</a> 49 logs	<a href="#">T</a> 9 logs
<a href="#">U</a> 6 logs	V	<a href="#">W</a> 4 logs	X
Y		Z	

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# APPTTEL logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## APPTTEL logs

The following logs are generated for this source:

- [App-Telemetry: Configuration file missing or cannot be read. No config file will be used](#)
- [App-Telemetry: Default configuration file is missing](#)
- [App-Telemetry: Default configuration file loaded](#)
- [App-Telemetry: Maximum number of entries has been reached](#)
- [App-Telemetry: Parse error detected in policy file at line](#)
- [App-Telemetry: Policy file is empty](#)
- [App-Telemetry: User configuration file loaded](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR logs

There are 98 logs for this source. To simplify navigation, all logs are organized alphabetically by their name. Select the letter to navigate to the list of all logs starting with that letter for this source.

<a href="#">A</a>	B	C	<a href="#">D</a>
79 logs			19 logs
E	F	G	H
I	J	K	L
M	N	O	P
Q	R	S	T
U	V	W	X
Y		Z	



# ASCFG logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCFG logs

The following logs are generated for this source:

- [ASCFG - Error: Invalid file system. Init](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLAN logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN logs

There are 78 logs for this source. To simplify navigation, all logs are organized alphabetically by their name. Select the letter to navigate to the list of all logs starting with that letter for this source.

A	<a href="#">B</a> 1 logs	<a href="#">C</a> 22 logs	D
<a href="#">E</a> 23 logs	<a href="#">F</a> 12 logs	G	H
I	J	K	L
M	<a href="#">N</a> 2 logs	O	P
Q	R	<a href="#">S</a> 1 logs	T
U	<a href="#">V</a> 11 logs	<a href="#">W</a> 6 logs	X
Y		Z	

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Audit logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Audit logs

The following logs are generated for this source:

- [Audit data initialized \(bad checksum\)](#)
- [Audit data initialized \(bad magic number\)](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# L3Mgr logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## L3Mgr logs

There are 70 logs for this source. To simplify navigation, all logs are organized alphabetically by their name. Select the letter to navigate to the list of all logs starting with that letter for this source.

<a href="#">A</a> 2 logs	<a href="#">B</a> 1 logs	C	<a href="#">D</a> 4 logs
<a href="#">E</a> 7 logs	<a href="#">F</a> 9 logs	<a href="#">G</a> 5 logs	H
<a href="#">I</a> 7 logs	J	K	<a href="#">L</a> 9 logs
<a href="#">M</a> 6 logs	<a href="#">N</a> 1 logs	<a href="#">O</a> 1 logs	P
Q	<a href="#">R</a> 3 logs	<a href="#">S</a> 1 logs	<a href="#">T</a> 2 logs
U	<a href="#">V</a> 8 logs	<a href="#">W</a> 3 logs	<a href="#">X</a> 1 logs
Y		Z	

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP logs

There are 69 logs for this source. To simplify navigation, all logs are organized alphabetically by their name. Select the letter to navigate to the list of all logs starting with that letter for this source.

A	B	C	D
E	F	G	H
<u>I</u>	J	K	L
M	N	O	P
Q	R	S	T
U	V	W	X
Y	Z		

69 logs



# Bay secure logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Bay secure logs

The following logs are generated for this source:

- [BaySec cdtInit 0x%0x 0x%0x 0x%0x](#)
- [BaySec cdtIntruder 0x%0x 0x%0x 0x%0x](#)
- [BaySec cdtMigrate 0x%0x 0x%0x 0x%0x](#)
- [BaySec cdtNewMac 0x%0x 0x%0x 0x%0x](#)
- [BaySec Exceeded number MAC addresses on unit# port#](#)
- [BaySec IMC cmd error %0x](#)
- [BaySec msgQ error: 0x%x](#)
- [BaySec Not enough resource on port port# . Check QOS cfg](#)
- [Bay Secure:](#)
- [Bay Secure: add](#)
- [Bay Secure: current=%d localPortMacNumber=%d](#)
- [Bay Secure: del](#)
- [Bay Secure: del \(entry\)](#)
- [Bay Secure: del\(LINK-DOWN\)](#)
- [Bay Secure: error](#)
- [Bay Secure error line line# # of octets read from NVRAM](#)
- [Bay Secure: Exceeded %d per-port MAC addresses](#)
- [Bay Secure Exceeded number per-port MAC addresses on port unit# port#](#)
- [Bay Secure intruder](#)
- [Bay Secure intruder MAC](#)
- [Bay Secure MAC DA filtering not enough resources](#)
- [Bay Secure: MAC DA filtering not enough resources](#)
- [Bay Secure per-port address deleted:](#)
- [Bay Secure per-port addresses deleted](#)
- [Bay Secure Policy Error error type line line# 0](#)
- [Bay Secure Policy Error %s line %u 0x%X](#)
- [Bay Secure Resource Error error# line line# resource ID](#)
- [Bay Secure Resource Error %s line %u 0x%X](#)
- [Bay Secure %s line %u 0x%X](#)
- [MAC security table full](#)
- [Trap: bsDhcpSnoopingExtSaveSFTPSyncSuccess](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT logs

There are 67 logs for this source. To simplify navigation, all logs are organized alphabetically by their name. Select the letter to navigate to the list of all logs starting with that letter for this source.

A	B	C	<b>D</b> 2 logs
<b>E</b> 1 logs	F	G	H
I	J	K	<b>L</b> 2 logs
<b>M</b> 61 logs	N	O	<b>P</b> 1 logs
Q	R	S	T
U	V	W	X
Y		Z	

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# BAYSECURE, DCE logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## BAYSECURE, DCE logs

The following logs are generated for this source:

- [Trap s5EtrSbsMacAccessViolation](#)
- [Trap s5EtrSbsMacAccessViolation](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH logs

There are 64 logs for this source. To simplify navigation, all logs are organized alphabetically by their name. Select the letter to navigate to the list of all logs starting with that letter for this source.

A	B	C	D
E	F	G	H
I	J	K	L
M	N	O	P
Q	R	<a href="#">S</a>	T
U	V	W	X
Y		Z	

64 logs

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Boot Ascii logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Boot Ascii logs

The following logs are generated for this source:

- [ASCFG - Error: Failed to get file from TFTP](#)
- [ASCFG - Error: Failed to get file from USB](#)
- [ASCFG - Error: Failed to get script buffer](#)
- [ASCFG - Error: Failed to get the flash resource](#)
- [ASCFG - Error: Failed to give sem semBAutoSaveAscDone](#)
- [ASCFG - Error: Failed to init ascii file system](#)
- [ASCFG - Error: Failed to malloc memory for ram drive](#)
- [ASCFG - Error: Failed to open ascii file system](#)
- [ASCFG - Error: Failed to open record file](#)
- [ASCFG - Error: Failed to open script file](#)
- [ASCFG - Error: Failed to read record file](#)
- [ASCFG - Error: Failed to read script file](#)
- [ASCFG - Error: Failed to release the flash resource](#)
- [ASCFG - Error: Failed to run script file](#)
- [ASCFG - Error: Failed to save ascii file system](#)
- [ASCFG - Error: Failed to send msg to ascfg queue](#)
- [ASCFG - Error: Failed to send notice to NBU](#)
- [ASCFG - Error: Failed to take sem semBAutoSaveAscDone](#)
- [ASCFG - Error: Failed to update the status](#)
- [ASCFG - Error: Failed to write record file](#)
- [ASCFG - Error: Failed to write script file](#)
- [ASCFG - Error: File larger max file size](#)
- [ASCFG - Error: Invalid file system. Init](#)
- [ASCFG - Error: Invalid script entry 0](#)
- [ASCFG - Error: Invalid script entry 1](#)
- [ASCFG - Info: Run Boot Script Successfully](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## HMOD logs

The following logs are generated for this source:

- [Cannot access instance data for Port #%u](#)
- [Cannot access port data for unit](#)
- [Cannot create dead timer for port %u](#)
- [Cannot delete dead timer for port %u](#)
- [Cannot get dead timer ID for port %u](#)
- [Cannot set dead timer to %u for port %u](#)
- [Downstream direction is logically down](#)
- [Downstream direction is logically up](#)
- [Downstream Port #%u is unexpectedly logically up](#)
- [Downstream stack direction is down, cable removed or neighbor powered off](#)
- [Downstream stack direction is misconfigured](#)
- [Downstream stack direction is up, cable inserted or neighbor powered on](#)
- [Downstream Stack Port #%u is logically down](#)
- [Downstream Stack Port #%u is logically up](#)
- [Downstream stack port %u is misconfigured](#)
- [Hello Module unable to communicate with neighbor\(s\), unit reset](#)
- [Hello Module unable to read from configuration file](#)
- [Hello Module unable to write to configuration file](#)
- [HMOD: error: %s line %d %d](#)
- [HMOD: error: %s line %d 0x%X](#)
- [HMOD: event received msg\\_src=0x%X num= 0x%X](#)
- [HMOD: IMC ack msg failed: status %d](#)
- [HMOD: info: %s line %d %d](#)
- [HMOD: initialized arg1= %d arg2 = %d arg3 = %d](#)
- [HMOD: queue creation failed %s line %d](#)
- [HMOD: queue rec error qid= 0x%X errno=0x%X](#)
- [HMOD: queue send error qid= 0x%X errno=0x%X](#)
- [HMOD: %s](#)
- [HMOD: semaphore creation failed %s line %d](#)
- [HMOD: %s msg send failed](#)
- [HMOD: startup event failed type: 0x%08X option: %d](#)
- [HMOD: STEG\\_GO event missed](#)
- [HMOD: 0x%X 0x%X 0x%X](#)
- [Ignored event %s for state %s, arg: %d](#)
- [No stack ports available](#)
- [Stack cable "Down 1" is misconfigured](#)
- [Stack cable "Down 2" is misconfigured](#)
- [Stack cable "Up 1" is misconfigured](#)
- [Stack cable "Up 2" is misconfigured](#)
- [Stack Port %d: event %s causes state transition to %s](#)
- [Stack Port %d: ignored event %s for state %s](#)
- [Upstream direction is logically down](#)
- [Upstream direction is logically up](#)
- [Upstream Port #%u is unexpectedly logically up](#)
- [Upstream stack direction is down, cable removed or neighbor powered off](#)
- [Upstream stack direction is misconfigured](#)
- [Upstream stack direction is up, cable inserted or neighbor powered on](#)
- [Upstream Stack Port #%u is logically down](#)
- [Upstream Stack Port #%u is logically up](#)

- [Upstream stack port %u is misconfigured](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CAMPOLICY logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CAMPOLICY logs

The following logs are generated for this source:

- [cam policies executing code that has not been completed \(code=%d\)](#)
- [cam policies initialized](#)
- [cam policy initialization failed \(code=%d,argument=%d\)](#)
- [cam policy initialization failed \(code=%d,argument=%d\)](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC logs

The following logs are generated for this source:

- [LAC: Allocated trunk with id %d for aggregator %d](#)
- [LAC: API error: %d-%d-%d.](#)
- [LAC: Deallocated trunk with id %d for aggregator %d](#)
- [LAC: Failed to release trunk group: %d - %d - %d](#)
- [LAC: get buffer fail: %d-%d-%d](#)
- [LAC: input parameter error: %d-%d-%d](#)
- [LAC: lac\\_log\\_add\\_link: %d - %d - %d](#)
- [LAC: lac\\_log\\_link\\_change: %d - %d - %d](#)
- [LAC: lac\\_log\\_rem\\_link: %d - %d - %d](#)
- [LAC: MLT %d error on far end.](#)
- [LAC: MLT %d error, partner aggregation bit not set.](#)
- [LAC: MLT %d error, partner expired bit set.](#)
- [LAC: MLT %d error, partner synchronization bit not set.](#)
- [LAC MLT error on far end. 0 - 0 - 0](#)
- [LAC: MLT remove port: unit %d, port %d, trunk group %d](#)
- [LAC: MLT set port: unit %d, port %d, trunk group %d](#)
- [LAC: msgQ error: %d-%d-%d](#)
- [LAC: Msg Type Err: %s : %d, msgid = %d](#)
- [LAC: Mux event: %d - %d - %d](#)
- [LAC No more trunk group available for LAC. 0 - 0 - 0](#)
- [LAC: No more trunk group available for LAC.](#)
- [LAC: nvRam file error %d %d](#)
- [LAC: RX event: %d - %d - %d](#)
- [LAC: Stack event: %d - %d - 0x%x](#)
- [LAC: Start](#)
- [LAC: TMR event: %d - %d - %d](#)
- [LAC: Trunk %d is disabled](#)
- [LAC: Trunk %d is enabled](#)
- [LAC: TX event: %d - %d - %d](#)
- [LAC with admin key %d failed configuration verification. Bad EGRESS settings.](#)
- [LAC with admin key %d failed configuration verification. Bad MAC Security configuration.](#)
- [LAC with admin key %d failed configuration verification. Cannot set admin key to the value used by ADAC Uplink.](#)
- [LAC with admin key %d failed configuration verification. Ports have different FA configuration.](#)
- [LAC with admin key %d failed configuration verification. Ports have different IPSG configurations.](#)
- [LAC with admin key %d failed configuration verification. Ports have different MAC learning status.](#)
- [LAC with admin key %d failed configuration verification. Ports have different mac security learning status.](#)
- [LAC with admin key %d failed configuration verification. Ports have different mac security settings.](#)
- [LAC with admin key %d failed configuration verification. Ports have different mac security status.](#)
- [LAC with admin key %d failed configuration verification. Ports have different private-vlan port type.](#)
- [LAC with admin key %d failed configuration verification. Ports have different SLPP-guard configurations.](#)
- [LAC with admin key %d failed configuration verification. Ports have different VLACP admin enable state.](#)
- [LAC with admin key %d failed configuration verification. Ports have different VLACP ethertype.](#)
- [LAC with admin key %d failed configuration verification. Ports have different VLACP fast periodic time value.](#)
- [LAC with admin key %d failed configuration verification. Ports have different VLACP mac address.](#)
- [LAC with admin key %d failed configuration verification. Ports have different VLACP slow periodic time value.](#)
- [LAC with admin key %d failed configuration verification. Ports have different VLACP timeout scale.](#)
- [LAC with admin key %d failed configuration verification. Ports have different VLACP timeout type.](#)
- [LAC with admin key %d failed configuration verification. Ports have different vlan filter tag frames settings.](#)
- [LAC with admin key %d failed configuration verification. Ports have different vlan filter unreg frames settings.](#)

- [LAC with admin key %d failed configuration verification. Ports have different vlan filter untag frames settings.](#)
- [LAC with admin key %d failed configuration verification. Ports have different vlan priorities.](#)
- [LAC with admin key %d failed configuration verification. Ports have different vlan PVIDs.](#)
- [LAC with admin key %d failed configuration verification. Ports have different vlan tagging.](#)
- [LAC with admin key %d failed configuration verification. Same key is used by ports belonging to different VLAN.](#)
- [Port %s of LAC with key %d is disabled because it has wrong configuration](#)
- [Trap bsnLacPortDisabledDueToLossOfVLACPDU](#)
- [Trap bsnLacPortEnabledDueToReceiptOfVLACPDU](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CDT logs

The following logs are generated for this source:

- [address add was aborted. \(an event callback instructed the driver to remove the address\)](#)
- [address add was aborted. \(the address was being inserted into an inactive FID, code=%d\)](#)
- [call to cdt api function failed due to lock timeout \(code=%d, total failures=%d, task=%s\)](#)
- [call to IDT LearnAddress has failed \(code=%d, total failures=%d, errno=%x\)](#)
- [cam block lookup first 8 chars of mac=%08x, fid=0x%04x, num returned=%d](#)
- [cam database manager reached processing capacity; delaying some actions](#)
- [CAM driver control initialization failed \(code=%d, argument=%d\)](#)
- [cam driver initialization failed \(code=%d, argument=%d\)](#)
- [cam driver initialization failed \(code= error type argument= line# \)](#)
- [cam driver initialized](#)
- [cam imc allocation error \(code=%d, total failures=%d\)](#)
- [cam imc failed to receive to message queue](#)
- [cam imc failed to send to message queue \(code=%d, total failures=%d, errno=%x\)](#)
- [cam lookup error first 8 chars of mac=%08x, fid=0x%04x \(code=%d\)](#)
- [cam processing aborted \(code=%d, argument=0\)](#)
- [cam processing aborted \(code= error type argument= line# \)](#)
- [cam processing error \(code=%d, argument=%d\)](#)
- [cam synchronization disabled: cam will operate as standalone driver](#)
- [cam synchronization enabled](#)
- [cam synchronization temporarily disabled](#)
- [CDT AgeTime set failed \(line = %d\)](#)
- [CDT MAC address mac address was removed because LAG trunk trunked has disaggregated.](#)
- [CDT MAC address mac address was removed because port port no has aggregated in LAG](#)
- [CDT The static FDB entry MAC mac address VLAN vlan Id trunk trunkId was deleted because LAG has disaggregated](#)
- [CDT The static FDB entry MAC mac address VLAN vlan id was deleted because Unit Port unit port has aggregated](#)
- [code execution took unexpected, but safe, execution path \(code=%d, argument=0\)](#)
- [EAP CDT Error](#)
- [Error: CML gw bcmx chip to modid unit %d chip %d rv %d](#)
- [Error: CML lppm get unit chip %d port %d p->port 0x%x](#)
- [Error: CML received MAC with unit %d on unit %d](#)
- [Error in DMA transfer](#)
- [Error in XGS3 memory DMA transfer](#)
- [failed to add address to preinsertion table, table is probably full \(code=%d\)](#)
- [forwarding database message queue failure \(code=%d, total failures=%d, errno=%x\)](#)
- [imc cam processing aborted \(code=%d, argument=0\)](#)
- [keep alive expired](#)
- [mac address appears twice in cam \(this has happened a total of %d times\)](#)
- [mlt look up database has been attached to CDT \(fn addr=0x%08x\)](#)
- [no room in cam, cannot add address](#)
- [Receive sync packet for L2 entry: MAC:%02x-%02x-%02x-%02x-%02x-%02x trunk %d modid %d from Remote modid %d](#)
- [The static FDB entry MAC %02x-%02x-%02x-%02x-%02x-%02x VLAN %d trunk %d was deleted because LAG has disaggregated](#)
- [The static FDB entry MAC %02x-%02x-%02x-%02x-%02x-%02x VLAN %d was deleted because Port: %d has aggregated](#)
- [The static FDB entry MAC %02x-%02x-%02x-%02x-%02x-%02x VLAN %d was deleted because Unit/Port: %d/%d has aggregated](#)
- [Trap: s5EtrMacAddressTablesThresholdReached](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Telnet logs

The following logs are generated for this source:

- [CLI pswd: A unified authentication method is now used. The local switch credentials are no longer supported](#)
- [CLI pswd: Stack authentication parameter is obsolete: unified changes have been applied to both stack and switch](#)
- [CLI pswd: Stack authentication parameter is obsolete: unified changes have been applied to both stack and switch](#)
- [CLI pswd: Stack auth type RADIUS/TACACS+ won't apply partially \(stack IP addr not set\). Local user/pass used](#)
- [CLI pswd: Stack auth type RADIUS/TACACS+ won't apply partially \(switch IP addr not set\). Local user/pass used](#)
- [CLI pswd: Switch authentication parameter is obsolete: changes have not been applied](#)
- [Connection closed \(lost connection\), IP address:](#)
- [Failed login from IP address:](#)
- [Failed login \(local auth\) from IP address:](#)
- [Failed login\(RADIUS auth\) from IP add:](#)
- [Failed login\(RADIUS auth\) from serial connection](#)
- [Failed login\(TACACS+ auth\) from IP add:](#)
- [Failed login\(TACACS+ auth\) from serial connection](#)
- [Local authentication disabled on stack serial](#)
- [Local authentication disabled on stack TELNET/WEB/SSH](#)
- [Local authentication disabled on switch serial](#)
- [Local authentication disabled on switch TELNET/WEB/SSH](#)
- [Local authentication disabled on TELNET/WEB/SSH](#)
- [Local authentication enabled on stack serial](#)
- [Local authentication enabled on stack TELNET/WEB/SSH](#)
- [Local authentication enabled on switch serial](#)
- [Local authentication enabled on switch TELNET/WEB/SSH](#)
- [Local authentication enabled on TELNET/WEB/SSH](#)
- [Login timeout, serial connection](#)
- [Remote access on this device has been](#)
- [Reset initiated through SSH by IP address:](#)
- [Reset initiated through telnet by IP address:](#)
- [Reset to default initiated through SSH by IP address:](#)
- [Reset to default initiated through telnet by IP address:](#)
- [Session closed \(inactivity logout\), IP address:](#)
- [Session closed \(inactivity logout\), serial connection](#)
- [Session closed \(lost connection\), IP address:](#)
- [Session closed \(serial console disconnected\)](#)
- [Session closed \(user logout\), IP address:](#)
- [Session closed \(user logout\), serial connection](#)
- [Session negotiation failure from IP address:](#)
- [Session opened from IP address:](#)
- [Session opened \(local auth\) from IP address:](#)
- [Session opened\(RADIUS auth\) from IP add:](#)
- [Session opened\(RADIUS auth\) from serial connection](#)
- [Session opened\(RADIUS fallback auth\) from IP add:](#)
- [Session opened\(RADIUS fallback auth\) from serial connection](#)
- [Session opened\(TACACS+ auth\) from IP add:](#)
- [Session opened\(TACACS+ auth\) from serial connection](#)
- [Session opened\(TACACS+ fallback auth\) from IP add:](#)
- [Session opened\(TACACS+ fallback auth\) from serial connection](#)
- [Stack RO password changed from IP add:](#)
- [Stack RO password changed from serial connection](#)
- [Stack RW password changed from IP add:](#)

- [Stack RW password changed from serial connection](#)
- [Switch RO password changed from serial connection](#)
- [Switch RW password changed from IP add:](#)
- [Switch RW password changed from serial connection](#)
- [Telnet-access is disabled](#)
- [Telnet-access is enabled](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CFC logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFC logs

The following logs are generated for this source:

- [FSH - Some files are not closed. MsgType #%](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop logs

The following logs are generated for this source:

- [Bay Secure: Exceeded %d per-trunk MAC addresses on trunk %d](#)
- [DHCP packet with mismatch MAC address dropped on un-trusted port %d/%d mac\(0x%08x\)](#)
- [DHCP packet with mismatch MAC address dropped on un-trusted port unit# port# mac\(MAC ADDRESS\)](#)
- [DHCP reply packet received without request on port %d/%d mac\(0x%08x\)](#)
- [DHCP Snoop DHCP ACK dropped on untrusted port unit# port# \(not allowed on untrusted port\)](#)
- [DHCP Snoop DHCP binding table is full additional DHCP clients will not be added to the binding table](#)
- [DHCP Snoop:DHCP binding table is full, additional DHCP clients will not be added to the binding table](#)
- [DHCP Snoop: DHCP DISCOVER dropped on port %d/%d \(source MAC not matching client MAC\)](#)
- [DHCP Snoop DHCP NAK dropped on untrusted port unit# port# \(not allowed on untrusted port\)](#)
- [DHCP Snoop DHCP OFFER dropped on untrusted port unit# port# \(not allowed on untrusted port\)](#)
- [DHCP Snoop: DHCP packet dropped on port %d/%d - static entry with the same MAC %02x-%02x-%02x-%02x-%02x-%02x in binding table](#)
- [DHCP Snoop:DHCP RELEASE/DECLINE dropped on untrusted port %d/%d because MAC Addr\(0x%08x\) is associated to port %d/%d](#)
- [DHCP Snoop:DHCP RELEASE/DECLINE dropped on untrusted port %d/%d \(MAC Addr\(0x%08x\) does not exist in binding table\)](#)
- [DHCP Snoop DHCP RELEASE DECLINE dropped on untrusted port unit# port# because MAC Addr\( MACaddress \) is associated to port unit# port#](#)
- [DHCP Snoop DHCP RELEASE DECLINE dropped on untrusted port unit# port# \(MAC Addr\(MACaddress \) does not exist in binding table\)](#)
- [DHCP Snoop: DHCP REQUEST dropped on untrusted port %d/%d due to Source MAC Address \(0x%08x\) not matching DHCP client MAC Address \(0x%08x\)](#)
- [DHCP Snoop DHCP REQUEST dropped on un-trusted port unit# port# due to source MAC address\(MAC ADDRESS\) not matching DHCP client](#)
- [DHCP Snoop DHCP snooping binding table restored successfully from TFTP address](#)
- [DHCP Snoop DHCP snooping binding table restored successfully from USB unit unit#](#)
- [DHCP Snoop: DHCP snooping binding table restore from SFTP address](#)
- [DHCP Snoop: DHCP snooping binding table restore from SFTP address](#)
- [DHCP Snoop DHCP snooping binding table restore from TFTP address A.B.C.D IPv6 address failed](#)
- [DHCP Snoop DHCP snooping binding table restore from USB unit unit# failed](#)
- [DHCP Snoop: DHCP snooping binding table saved successfully to SFTP address](#)
- [DHCP Snoop: DHCP snooping binding table saved successfully to SFTP address](#)
- [DHCP Snoop DHCP snooping binding table saved successfully to TFTP address](#)
- [DHCP Snoop DHCP snooping binding table saved successfully to USB unit unit#](#)
- [DHCP Snoop: DHCP snooping binding table save to SFTP address](#)
- [DHCP Snoop: DHCP snooping binding table save to SFTP address](#)
- [DHCP Snoop DHCP snooping binding table save to TFTP address A.B.C.D IPv6 address failed](#)
- [DHCP Snoop: DHCP snooping binding table save to TFTP address, failed](#)
- [DHCP Snoop DHCP snooping binding table save to USB unit unit# failed](#)
- [DHCP Snoop: DHCP snooping binding table succesfully restored from SFTP address](#)
- [DHCP Snoop: DHCP snooping binding table succesfully restored from SFTP address](#)
- [DHCP Snoop DHCP snooping entry entry number not restored due to expired lease](#)
- [DHCP Snoop DHCP snooping entry entry number not restored due to MAC conflict](#)
- [DHCP Snoop DHCP snooping entry entry number not restored due to parsing failure](#)
- [DHCP Snoop DHCP snooping entry with MAC MacAddress not restored on invalid interface unit# port#](#)
- [DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored \(invalid Vlan %d\)](#)
- [DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored on trusted interface %d/%d](#)
- [DHCP Snoop: DHCP snooping entry 0x%08x not restored due to expired lease](#)
- [DHCP Snoop: DHCP snooping entry 0x%08x not restored due to MAC conflict](#)
- [DHCP Snoop: DHCP snooping entry 0x%08x not restored due to parsing failure](#)

- [DHCP Snoop: DHCP snooping entry 0x%08x not restored on invalid interface %d/%d](#)
- [DHCP Snoop: DHCP snooping entry 0x%08x not restored on trusted interface %d/%d](#)
- [DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored \(invalid Vlan %d\)](#)
- [DHCP Snoop: NTP is not synchronized: external save of DHCP snooping entries not possible](#)
- [DHCP Snoop NTP is not synchronized: external save restore of DHCP snooping entries not possible](#)
- [Trap: bsDhcpSnoopingExtSaveSFTPRestoreFailure](#)
- [Trap: bsDhcpSnoopingExtSaveSFTPRestoreSuccess](#)
- [Trap: bsDhcpSnoopingExtSaveSFTPSyncFailure](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CFG logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFG logs

The following logs are generated for this source:

- [CFG - Backup Configuration files are corrupted. Restore backup from primary config.](#)
- [CFG - Backup Configuration files are corrupted. Restored to default.](#)
- [CFG - Configuration files are corrupted. Restored from backup.](#)
- [CFG - Could not acquire FLASH sem](#)
- [CFG - Could not acquire FLASH sem.](#)
- [CFG - Could not create ram copy buffer.](#)
- [CFG has No Error %d, %d, %d](#)
- [CFG layer - invalid error %d, %d, %d](#)
- [CFG - NVRAM file system check: errors detected. Please reboot the system!](#)
- [CFG - NVRAM file system check: errors detected. Restored to default.](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## port driver logs

The following logs are generated for this source:

- [SFP internal supply voltage is at high alarm level on s](#)
- [SFP internal supply voltage is at high warning level on %s](#)
- [SFP internal supply voltage is at low alarm level on %s](#)
- [SFP internal supply voltage is at low warning level on %s](#)
- [SFP internal supply voltage is no longer at the high alarm level](#)
- [SFP internal supply voltage is no longer at the high warning level](#)
- [SFP internal supply voltage is no longer at the low alarm level](#)
- [SFP internal supply voltage is no longer at the low warning level](#)
- [SFP internal temperature is at high alarm level on %s](#)
- [SFP internal temperature is at high warning level on %s](#)
- [SFP internal temperature is at low alarm level on %s](#)
- [SFP internal temperature is at low warning level on %s](#)
- [SFP internal temperature is no longer at the high alarm level](#)
- [SFP internal temperature is no longer at the high warning level](#)
- [SFP internal temperature is no longer at the low alarm level](#)
- [SFP internal temperature is no longer at the low warning level](#)
- [SFP Received power is at high alarm level on %s](#)
- [SFP Received power is at high warning level on %s](#)
- [SFP Received power is at low alarm level on %s](#)
- [SFP Received power is at low warning level on %s](#)
- [SFP Received power is no longer at the high alarm level](#)
- [SFP Received power is no longer at the high warning level](#)
- [SFP Received power is no longer at the low alarm level](#)
- [SFP Received power is no longer at the low warning level](#)
- [SFP TX Bias current is at high alarm level on %s](#)
- [SFP TX Bias current is at high warning level on %s](#)
- [SFP TX Bias current is at low alarm level on %s](#)
- [SFP TX Bias current is at low warning level on %s](#)
- [SFP TX Bias is no longer at the high alarm level](#)
- [SFP TX Bias is no longer at the high warning level](#)
- [SFP TX Bias is no longer at the low alarm level](#)
- [SFP TX Bias is no longer at the low warning level](#)
- [SFP TX output power is at high alarm level on %s](#)
- [SFP TX output power is at high warning level on %s](#)
- [SFP TX output power is at low alarm level on %s](#)
- [SFP TX output power is at low warning level on %s](#)
- [SFP TX output power is no longer at the high alarm level](#)
- [SFP TX output power is no longer at the high warning level](#)
- [SFP TX output power is no longer at the low alarm level](#)
- [SFP TX output power is no longer at the low warning level](#)
- [Trap: SFP Transceiver's Bias is no longer at warning/alarm level](#)
- [Trap: \\$:#160:SFP Transceiver's Bias is no longer at warning/alarm level](#)
- [Trap: SFP Transceiver's Temperature is no longer at warning/alarm level](#)
- [Trap: \\$:#160:SFP Transceiver's Temperature is no longer at warning/alarm level](#)
- [Trap: SFP Transceiver's Tx Power is no longer at warning/alarm level](#)
- [Trap: \\$:#160:SFP Transceiver's Tx Power is no longer at warning/alarm level](#)
- [Unicast block unit port unit\\_port level level watermark watermark](#)
- [Unicast unblock unit port unit\\_port level level watermark watermark](#)
- [USC Install SET fail unit port unit\\_port status = status](#)

- [USC Install TEST fail unit port unit port status = status](#)
- [USC UnInst SET failed for port port status = status](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFGSO logs

The following logs are generated for this source:

- [CFGSO - Error: Failed to cancel watchdog timer](#)
- [CFGSO - Error: Failed to create message queue](#)
- [CFGSO - Error: Failed to create watchdog timer](#)
- [CFGSO - Error: Failed to get an imc buffer](#)
- [CFGSO - Error: Failed to save data to NBU](#)
- [CFGSO - Error: Failed to send message to queue](#)
- [CFGSO - Error: Failed to spawn cfgso task](#)
- [CFGSO - Error: Failed to start watchdog timer](#)
- [CFGSO - Error: file not close](#)
- [CFGSO - Error: File not open](#)
- [CFGSO - Error: File not read](#)
- [CFGSO - Error: File not write](#)
- [CFGSO - Error: Invalid value](#)
- [CFGSO - Warning Invalid Msg Id](#)
- [CFGSO - Warning: Invalid Msg Id](#)
- [CFGSO - Warning Watchdog timer expire](#)
- [CFGSO - Warning: Watchdog timer expire](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## OSPF logs

The following logs are generated for this source:

- [Ospf Area Mismatch:](#)
- [Ospf Auth Failed:](#)
- [Ospf Auth Type Mismatch in Hello](#)
- [Ospf Auth Type Mismatch in Hello:](#)
- [Ospf Auto Virt Link Failed:](#)
- [Ospf Bad Version](#)
- [Ospf Bad Version:](#)
- [OSPF Callback function of timer is NULL](#)
- [OSPF Callback function of timer is NULL:](#)
- [Ospf Cost Exceeds Limit:](#)
- [OspfDbg Done Filter Init](#)
- [OspfDbg Done Global Init](#)
- [OspfDbg Done Global Init](#)
- [OspfDbg Done NV-Restore](#)
- [OspfDbg Done NV-Restore](#)
- [OspfDbg Done ReDist Init](#)
- [OspfDbg Done ReDist Init](#)
- [OspfDbg Init Instance vrfId=%d nodeP=0x%0x](#)
- [OspfDbg Init Instance vrfId=%d nodeP=0x%0x](#)
- [OspfDbg PostInit Done vrfId=%d nodeP=0x%0x](#)
- [OspfDbg PostInit Done vrfId=%d nodeP=0x%0x](#)
- [OspfDbg PostInit EnableOspf vrfId=%d nodeP=0x%0x](#)
- [OspfDbg PostInit EnableOspf vrfId=%d nodeP=0x%0x](#)
- [OspfDbg Started ospfTxHelloTimerTask](#)
- [OspfDbg Started ospfTxHelloTimerTask](#)
- [Ospf Dead Int Mismatch in Hello](#)
- [Ospf Dead Int Mismatch in Hello:](#)
- [Ospf Hello Int Mismatch in Hello](#)
- [Ospf Hello Int Mismatch in Hello:](#)
- [Ospf Hello: RId Same as Neighbor:](#)
- [Ospf Invalid packet received:](#)
- [Ospf Nbr State Change:](#)
- [Ospf Netmask Mismatch in Hello:](#)
- [Ospf Option Mismatch in Hello:](#)
- [OSPF Timer Link Error](#)
- [OSPF Timer Link Error:](#)
- [OSPF Timer List is corrupted](#)
- [OSPF Timer List is corrupted:](#)
- [OSPF Timer Unlink Error](#)
- [OSPF Timer Unlink Error:](#)
- [Ospf Virt Nbr State Change:](#)
- [Trap ospfIfAuthFailure](#)
- [Trap ospfIfConfigError](#)
- [Trap ospfIfStateChange](#)
- [Trap ospfNbrStateChange](#)
- [Trap ospfVirtIfAuthFailure](#)
- [Trap ospfVirtIfConfigError](#)
- [Trap ospfVirtIfStateChange](#)
- [Trap ospfVirtNbrStateChange](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CFM logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFM logs

The following logs are generated for this source:

- [CFM SPBM failed to install pdu capture filter\(s\) on port %d for vlan %d](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP logs

The following logs are generated for this source:

- [ASTP debug: %d - %d - %x](#)
- [ASTP error: %d - %d - %d](#)
- [ASTP state: %d - %d - %d](#)
- [BPDU received on port with BPDU-Filtering enabled.](#)
- [BPDU received on port with BPDU-Filtering enabled. Port %d has been disabled](#)
- [EAP Vlan Change Aborted](#)
- [STP add Mlt link: %d - %d - %d](#)
- [STP CDT interface error](#)
- [STP Config Chk: %d - %d - %d](#)
- [STP dbrcv error: %d - %d - %d](#)
- [STP db record done: %d - %d - %d](#)
- [STP db remove: %d - %d - %d](#)
- [STP db remove done: %d - %d - %d](#)
- [STP dbxc error: %d - %d - %d](#)
- [STP db xchg: %d - %d - %d](#)
- [STP db xchg done: %d - %d - %d](#)
- [STP db xchg mask empty: %d - %d - %d](#)
- [STP db xchg rcv last pkt: %d - %d - %d](#)
- [STP different op mode remote-local-Module: %d - %d - %d](#)
- [STP Fatal Error: taskSupend\(0\) called %s line %d: %d](#)
- [STP get buffer fail: %d - %d - %d](#)
- [STP group %d disabled, empty vlans or no vlans %d - %d](#)
- [STP IMC error: %d - %d - %d](#)
- [STP join: %d - %d - %d](#)
- [STP join done: %d - %d - %d](#)
- [STP join timeout : %d - %d - %d](#)
- [STP leave: %d - %d - %d](#)
- [STP leave done: %d - %d - %d](#)
- [STP Mlt create: %d - %d - %d](#)
- [STP Mlt remove: %d - %d - %d](#)
- [STP mod inactive: %d - %d - %d](#)
- [STP mod ina done: %d - %d - %d](#)
- [STP msgQ error: %d - %d - %d](#)
- [STP NV port clr: %d - %d - %d](#)
- [STP nvRam file error: %d - %d - %d](#)
- [STP parameter error: %d - %d - %d](#)
- [STP PDT interface error: %d - %d - %d](#)
- [STP port disable: %d - %d - %d](#)
- [STP STKM mask error: %d - %d - %d](#)
- [STP stpMlt create: %d - %d - %d](#)
- [STP Task Error: %d - %d - %d](#)
- [STP Timer 1st: %d - %d - %d](#)
- [STP Tx BPDU Alloc Fail: %d - %d - %d](#)
- [STP Tx BPDU IMC Fail: %d - %d - %d](#)
- [STP update cnfg: %d - %d - %d](#)
- [STP vlan clr cnfg: %d - %d - %d](#)
- [STP VLAN error: %d - %d - %d](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series

9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# CLI logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CLI logs

The following logs are generated for this source:

- [Local authentication disabled on serial](#)
- [Local authentication disabled on telnet](#)
- [Local authentication enabled on serial](#)
- [Local authentication enabled on telnet](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC logs

The following logs are generated for this source:

- [EAP IMC Failed to send message](#)
- [EAP IMC Memory allocation error](#)
- [IMC ack pool alloc failed %s line %d](#)
- [IMC ack timeout msgType= %d imcSeq= %d ackExpected= 0x%02X](#)
- [IMC app rcv routine error, type= %s\(%d\)](#)
- [IMC buffers of size buffer size have been exhausted buffer pool size pool size](#)
- [IMC buffers of size %u have been exhausted, buffer pool size %u](#)
- [IMC destination error rcvMsgDest= %d myUnitId= %d type= %s](#)
- [IMC error: %s line %d %s](#)
- [IMC IMC\\_ackedXmt\(\) failed status= %d dest= 0x%02X](#)
- [IMC imc\\_ackReceive\(\) ackRcvd= %d rcvSrcModule= %d](#)
- [IMC imc\\_idtPacketDispatch\(\) incorrect rcvMsgType= %s\(%d\)](#)
- [IMC imc\\_idtPacketDispatch\(\) NULL routine rcvMsgType= %s\(%d\)](#)
- [IMC IMC\\_idtPktRcv\(\) high queue imcType= %s\(%d\) length = %d](#)
- [IMC IMC\\_idtPktRcv\(\) low queue imcType= %s\(%d\) length = %d](#)
- [IMC IMC\\_idtPktRcv\(\) %s line %d length = %d](#)
- [IMC incorrect message type file = %s line = %d MsgType = %s](#)
- [IMC initialized arg1= %d arg2 = %d arg3 = %d](#)
- [IMC jumbo pool alloc failed %s line %d](#)
- [IMC memory allocation error packetLength = %d file %s line %d](#)
- [IMC msg pool creation failed %s line %d](#)
- [IMC normal pool alloc failed %s line %d](#)
- [IMC normal-small pool alloc failed %s line %d](#)
- [IMC packet alloc failed %s line %d](#)
- [IMC packet length too large file = %s line = %d size = %d](#)
- [IMC pkt dump offset= %d 0x%08X 0x%08X](#)
- [IMC priority pool alloc failed %s line %d](#)
- [IMC queue creation failed %s line %d](#)
- [IMC quick buffers maximum number of tasks %d to be traced reachead for IMC buffer of size %u](#)
- [IMC rcv checksum error rcvMsgChksum= 0x%08X calcMsgChksum= 0x%08X type= %s](#)
- [IMC rcv msg sequence error rcvMsgSeq= %d rcvMsgType= %s\(%d\)](#)
- [IMC rcv status error rcvStatus= %d rcvMsgType= %s\(%d\)](#)
- [IMC retries exceeded msgType= %d imcSeq= %d ackExpected= 0x%02X](#)
- [IMC semaphore creation failed %s line %d](#)
- [IMC sending ACK pkt\(s\) %d %s line %d](#)
- [IMC sending pkt: bad dest. 0x%02X %s line %d](#)
- [IMC sending pkt imcSeq= %d imcMsgType= %d dest= 0x%02X](#)
- [IMC send pkt error imcSeq= %d imcMsgType= %d dest= 0x%02X](#)
- [IMC send pkt fmt error imcSeq= %d imcMsgType= %d status= 0x%02X](#)
- [IMC small pool alloc failed %s line %d](#)
- [IMC source error rcvMsgSrc= %d type= %s\(%d\)](#)
- [IMC timer creation failed %s line %d](#)
- [IMC type error rcvMsgType= %s\(%d\) rcvMsgSrc= %d](#)
- [IMC version error rcvMsgVersion= %d type= %s src= %d](#)
- [RPC app rcv routine error, type= %s\(%d\)](#)







# CLI Audit logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CLI Audit logs

The following logs are generated for this source:

- [Audit commit failed \(cannot erase flash sector\(s\)\)](#)
- [Audit commit failed \(cannot take audit semaphore\)](#)
- [Audit commit failed \(cannot take flash semaphore\)](#)
- [Audit commit failed \(cannot write flash sector\(s\)\)](#)
- [Audit log disabled](#)
- [Audit log enabled](#)
- [Audit message add failed \(audit header too long\)](#)
- [Audit message send failed \(cannot resend data to remote syslog server\)](#)
- [Audit message send failed \(cannot send data to remote syslog server\)](#)
- [Trap: bsnAuditShutDownTrap](#)
- [Trap: bsnAuditStorageAlarm](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CLOCK logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CLOCK logs

The following logs are generated for this source:

- [New time:%s, old:%s, src:%s.](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKE logs

The following logs are generated for this source:

- [IKE CRL validate of peer %d.%d.%d.%d certificate status OK](#)
- [IKE CRL validate of peer %d.%d.%d.%d certificate status revoked](#)
- [IKE CRL validate of peer %s certificate status OK](#)
- [IKE CRL validate of peer %s certificate status revoked](#)
- [IKE CRL validation of peer %d.%d.%d.%d failed to get certificate status](#)
- [IKE CRL validation of peer %s failed to get certificate status](#)
- [IKE init done with auth-method only as PSK](#)
- [IKE OSCP validate of peer %d.%d.%d.%d certificate status OK](#)
- [IKE OSCP validate of peer %d.%d.%d.%d certificate status revoked](#)
- [IKE OSCP validate of peer %s certificate status OK](#)
- [IKE OSCP validate of peer %s certificate status revoked](#)
- [IKE OSCP validation of peer %d.%d.%d.%d failed to get certificate status](#)
- [IKE OSCP validation of peer %s failed to get certificate status](#)
- [IKE P2 SA failed status:%s](#)
- [IKE P2 SA lifetime expired. P2 SA rekey initiated. I/R: %s IAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d](#)
- [IKE P2 SA rekey due to DPD. I/R: %s IAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d](#)
- [IKE server listening for data](#)
- [IKE trust anchor created successfully](#)
- [IKEv%d P1 DPD - Dead Peer Detected I/R: %s IAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d](#)
- [IKEv%d P1 IPv6 SA Created. IAddr:%s status:%s](#)
- [IKEv%d P2 IPv6 SA Created. IAddr:%s status:%s](#)
- [IKEv%d P1 IPv6 SA Deleted. IAddr:%s status:%s](#)
- [IKEv%d P2 IPv6 SA Deleted. IAddr:%s status:%s](#)
- [IKEv%d P1 IPv6 SA Failed. IAddr:%s status:%s](#)
- [IKEv%d P2 IPv6 SA Failed. IAddr:%s status:%s](#)
- [IKEv%d P1 IPv6 SA lifetime expired. IAddr:%s status:%s](#)
- [IKEv%d P1 SA Created. I/R: %s IAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d](#)
- [IKEv%d P2 SA Created. I/R: %s IAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d Src Port:%d Dest Port:%d Protocol:%d status:%s](#)
- [IKEv%d P2 SA Deleted. I/R: %s IAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d](#)
- [IKEv%d P1 SA Deleted. I/R: %s IAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d status:%s](#)
- [IKEv%d P2 SA Failed. I/R: %s IAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d Src Port: %d Dest Port: %d Protocol: %d](#)
- [IKEv%d P1 SA Failed. I/R: %s IAddr:%d.%d.%d.%d rAddr: %d.%d.%d.%d status:%s](#)
- [IKEv%d P1 SA lifetime expired. I/R: %s IAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d](#)
- [Peer certificate validation against same CA, expiry and chain order is success](#)
- [Peer certificate validation failed with status:%s](#)
- [P1 IPv6 Dead Peer Detected. I/R: %s rAddr:%s status:%s](#)
- [P1 IPv6 SA Created. I/R: %s rAddr:%s status:%s](#)
- [P2 IPv6 SA Created. I/R: %s rAddr:%s status:%s](#)
- [P1 IPv6 SA Deleted. I/R: %s rAddr:%s status:%s](#)
- [P2 IPv6 SA Deleted. I/R: %s rAddr:%s status:%s](#)
- [P1 IPv6 SA Failed. I/R: %s rAddr:%s status:%s](#)
- [P2 IPv6 SA Failed. I/R: %s rAddr:%s status:%s](#)
- [P1 IPv6 SA lifetime expired. I/R: %s rAddr:%s status:%s](#)





# config logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## config logs

The following logs are generated for this source:

- [Backup Configuration Version is updated](#)
- [Configuration saved to nv block # block\\_number](#)
- [Error loading configuration block %d](#)
- [Error loading primary configuration block # block\\_number](#)
- [Error saving configuration to block # block\\_number](#)
- [Invalid Configuration Block Number %d](#)
- [Invalid Configuration Magic Number](#)
- [Invalid Configuration Version Number](#)
- [Loading configuration block # block\\_number](#)
- [Primary Configuration files are corrupted. Restored to default](#)
- [Primary Configuration Version is updated](#)
- [Restore Backup Configuration to Manufacture Default](#)
- [Restore Primary Configuration to Manufacture Default](#)
- [Toggle the Agent Primary Image](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack Manager logs

The following logs are generated for this source:

- [Another BU tried to join the stack. Unit ignored](#)
- [application-name failed DB-exchange stack failed to form](#)
- [application-name failed DB-exchange stack formation delayed](#)
- [Base unit has loopback port mode %s and the current unit %s. Unit reconfigured and rebooted](#)
- [BECOME\\_TEMP BU event sent unit mask value appl mask value](#)
- [Change of active config block and or reset failed block-number](#)
- [Different enhanced secure mode settings than BU. Unit reconfigured and rebooted.](#)
- [Different spanning-tree mode configured than BU. Unit re-configured and rebooted](#)
- [Different spanning-tree mode configured than BU. Unit reconfigured and rebooted.](#)
- [DISTRIBUTE\\_DB event sent unit mask value appl mask value](#)
- [Filter limiting mode not supported on 5510-XX unit cannot join stack](#)
- [Front-panel UI selected use rear-panel base non-base switch](#)
- [JOIN event sent unit mask value appl mask value](#)
- [LEAVE event sent unit mask value appl mask value](#)
- [MODULE\\_INACTIVE event sent unit mask value appl mask value](#)
- [More than value units discovered](#)
- [Multiple base units detected](#)
- [Multiple Waverunner units detected when base is a Flagship](#)
- [QOS filter-limiting mode modified and unit reset](#)
- [REMOVE\\_DATA event sent unit mask value appl mask value](#)
- [Replaced "Wrong QoS Agent buffer setting, expected %u, actual %u, unit cannot join stack" with "Wrong QoS Agent buffer setting, expected %s, actual %s, unit cannot join stack"](#)
- [Stack must have a configured base unit!](#)
- [Stack operation mode modified to Hybrid and unit reset](#)
- [Stack operation mode modified to Pure and unit reset](#)
- [Stack sync failed stack failed to form](#)
- [Stack synchronization failed Exp value Act value Missing value](#)
- [The base \(unit# number \) has left the stack. Unit# number is now the base](#)
- [The BU switch is enabled. Cannot join existing stack](#)
- [This unit has wrong F W version expected version actual version](#)
- [This unit has wrong S W version expected version actual version](#)
- [Trap bsnStackManagerReconfiguration](#)
- [Wrong QoS Agent buffer setting, expected %s, actual %s, unit re-configured and reboot](#)
- [Wrong QoS Agent buffer setting, expected %s, actual %s, unit re-configured and reboot](#)
- [Wrong QoS Agent buffer setting expected value actual value unit cannot join stack.](#)
- [Wrong QoS Agent queue setting, expected %u, actual %u, unit reconfigured and reboot](#)
- [Wrong QoS Agent queue setting, expected %u, actual %u, unit re-configured and reboot](#)
- [Wrong QoS Agent queue setting, expected %u, actual %u, unit reconfigured and reboot](#)
- [Wrong QoS Agent queue setting, expected %u, actual %u, unit re-configured and reboot](#)



# CONFIG DATA logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CONFIG DATA logs

The following logs are generated for this source:

- [Trap\\_bsnConfigurationSavedToNvram](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Radius logs

The following logs are generated for this source:

- [Allowed connection attempt from user :](#)
- [Disallowed connection Access Reject for user :](#)
- [Disallowed connection Invalid SvcType for user :](#)
- [EAP Error Radius - ifIndex not found](#)
- [No Response from RADIUS Server](#)
- [RADIUS authentication on serial port disabled](#)
- [RADIUS authentication on serial port enabled](#)
- [RADIUS authentication on stack serial disabled](#)
- [RADIUS authentication on stack serial enabled](#)
- [RADIUS authentication on stack telnet disabled](#)
- [RADIUS authentication on stack telnet enabled](#)
- [RADIUS authentication on stack TELNET/WEB/SSH disabled](#)
- [RADIUS authentication on stack TELNET/WEB/SSH enabled](#)
- [RADIUS authentication on switch serial disabled](#)
- [RADIUS authentication on switch serial enabled](#)
- [RADIUS authentication on switch telnet disabled](#)
- [RADIUS authentication on switch telnet enabled](#)
- [RADIUS authentication on switch TELNET/WEB/SSH disabled](#)
- [RADIUS authentication on switch TELNET/WEB/SSH enabled](#)
- [RADIUS authentication on TELNET/WEB/SSH disabled](#)
- [RADIUS authentication on TELNET/WEB/SSH enabled](#)
- [RADIUS: ERROR - Couldn't create RADIUS Acct semaphore, errno %d](#)
- [RADIUS: ERROR - Couldn't create RADIUS semaphore, errno %d](#)
- [RADIUS: ERROR - Couldn't start RADIUS AcctClient\(\) task, errno %d](#)
- [RADIUS: ERROR - Couldn't start RADIUS client\(\) task, errno %d](#)
- [RADIUS: ERROR - Couldn't start radius\\_recv\(\) task, errno %d](#)
- [RADIUS: ERROR - Couldn't start RADIUS ServerCheck\(\) task, errno %d](#)
- [RADIUS MS-CHAPv2: Failed to change password](#)
- [RADIUS MS-CHAPv2: No response from RADIUS server](#)
- [RADIUS MS-CHAPv2: Password changed succesfully](#)
- [RADIUS MS-CHAPv2: RADIUS server not properly configured](#)
- [RADIUS MS-CHAPv2: Server does not speak RADIUS](#)
- [RADIUS MS-CHAPv2: Unable to change password at RADIUS server](#)
- [Radius: Server with index %d is down](#)
- [Radius: Server with index %d is up](#)



# Console logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Console logs

The following logs are generated for this source:

- [Error accessing Image File](#)
- [Error Bad Image Checksum](#)
- [Error reading Image File](#)
- [Failed login from serial connection](#)
- [Failed login \(local auth\) from serial connection](#)
- [Failed to Create a Watchdog](#)
- [Failed to Read Image from Memory](#)
- [Login timeout serial connection](#)
- [Memory Allocation Error](#)
- [Not Enough Memory](#)
- [Reset initiated by console](#)
- [Reset to default initiated by console](#)
- [Session closed \(user logout\) serial connection](#)
- [Session opened from serial connection](#)
- [Session opened \(local auth\) from serial connection](#)
- [Session opened\(radius auth\) from serial conn](#)
- [Stack RO password changed from serial conn](#)
- [Stack RW password changed from serial conn](#)
- [Switch RO password changed from serial connection](#)
- [Switch RW password changed from serial conn](#)
- [TFTP Failed](#)
- [The user <%s> was locked.](#)
- [Trap: bsnAaaAlreadyConnected](#)
- [Trap: bsnAaaIncorrectLogOnThresholdExceeded](#)
- [Trap: bsnAaaMaxNoOfSessionsExceeded](#)
- [Trap: bsnAaaUserAccountNotUsed](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## WEB logs

The following logs are generated for this source:

- [OCP server running.](#)
- [Reset initiated through http by IP address](#)
- [Reset initiated through http by IP address](#)
- [Reset to default initiated through http by IP address](#)
- [Stack RO password changed from IP address](#)
- [Stack RW password changed from IP address](#)
- [Switch RO password changed from IP address](#)
- [Switch RW password changed from IP address](#)
- [User allowed \(fallback authentication\) to log in from Web from Src IP](#)
- [User allowed \(radius authentication pass\) to log in from Web from Src IP](#)
- [User allowed \(radius authentication pass\) to log in from Web from Src IP](#)
- [User disallowed \(radius authentication fail\) to log in from Web from Src IP](#)
- [WEB-access is disabled](#)
- [WEB-access is disabled](#)
- [WEB-access is enabled](#)
- [WEB-access is enabled](#)
- [Web authentication fail from IP address](#)
- [Web authentication fail from IP address](#)
- [Web authentication from IP address](#)
- [Web authentication from IP address](#)
- [Web authentication \(RADIUS auth\) from IP address](#)
- [Web connection from IP address](#)
- [Web connection from IP address](#)
- [WebControl server running.](#)
- [Web disconnect from IP address](#)
- [Web disconnect from IP address](#)
- [Web server attempting to open socket for port %d.](#)
- [Web server attempting to open socket for port HTTP port](#)
- [Web server starts service on port %d.](#)
- [Web server starts service on port HTTP port](#)
- [Web server starts service on ports: %d for HTTP and %d for HTTPS.](#)
- [Web timeout from IP address](#)
- [Web timeout from IP address](#)



# DAI logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAI logs

The following logs are generated for this source:

- [DAI: ARP packet with invalid IP/MAC binding dropped on untrusted port %d/%d. ARP packet has MAC source %02x-%02x-%02x-%02x-%02x-%02x.](#)
- [DAI ARP packet with invalid IP MAC binding dropped on untrusted port unit# port#](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TACACS logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS logs

The following logs are generated for this source:

- [TACACS+ accounting disabled](#)
- [TACACS+ accounting enabled](#)
- [TACACS+ authenticated serial connection closed](#)
- [TACACS+ authenticated ssh session closed](#)
- [TACACS+ authenticated telnet session closed](#)
- [TACACS+ authenticated telnet session max retries exceeded](#)
- [TACACS+ authentication on serial port disabled](#)
- [TACACS+ authentication on serial port enabled](#)
- [TACACS+ authentication on stack serial disabled](#)
- [TACACS+ authentication on stack serial enabled](#)
- [TACACS+ authentication on stack TELNET/WEB/SSH disabled](#)
- [TACACS+ authentication on stack TELNET/WEB/SSH enabled](#)
- [TACACS+ authentication on switch serial disabled](#)
- [TACACS+ authentication on switch serial enabled](#)
- [TACACS+ authentication on switch serial port disabled](#)
- [TACACS+ authentication on switch serial port enabled](#)
- [TACACS+ authentication on switch telnet disabled](#)
- [TACACS+ authentication on switch telnet enabled](#)
- [TACACS+ authentication on switch telnet enabled](#)
- [TACACS+ authentication on switch TELNET/WEB/SSH disabled](#)
- [TACACS+ authentication on switch TELNET/WEB/SSH enabled](#)
- [TACACS+ authentication on TELNET/WEB/SSH disabled](#)
- [TACACS+ authentication on TELNET/WEB/SSH enabled](#)
- [TACACS+ authorization disabled](#)
- [TACACS+ authorization enabled](#)
- [TACACS+ successful authentication](#)
- [TACACS+ unsuccessful authentication](#)
- [TACACS authenticated SSH session closed](#)
- [TACACS authentication on stack serial disabled](#)
- [TACACS authentication on stack serial enabled](#)
- [TACACS authentication on stack telnet disabled](#)
- [TACACS authentication on stack telnet enabled](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# DCE logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DCE logs

The following logs are generated for this source:

- [Trap: s5CtrFanDirectionError](#)
- [Trap: s5CtrHighTemperatureError](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP logs

The following logs are generated for this source:

- [DHCP relay is now disabled](#)
- [Error disabling global DHCP relay %d](#)
- [Error disabling global DHCP relay errCode](#)
- [Error enabling global DHCP relay %d](#)
- [Error enabling global DHCP relay errCode](#)
- [Resource unavailable DHCP relay %d err %d](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ipsg logs

The following logs are generated for this source:

- [Cannot disable IP Source Guard on Unit %d Port %d](#)
- [Cannot disable IP Source Guard on Unit unit# Port port#](#)
- [Cannot enable IP Source Guard on Unit %d Port %d](#)
- [IPSG: Admin Cmd Event Error %x %x %x](#)
- [IPSG: Db exchange %d %d 0x%x](#)
- [IPSG: Debug %d %d 0x%x](#)
- [IPSG: DHCP Event Error %x %x %x](#)
- [IPSG: Fatal Error %d %d %d](#)
- [IPSG: IMC Error %d %d 0x%x](#)
- [IPSG Insufficient resources available to enable IPSG on port unit# port#](#)
- [IPSG: Invalid Stack Event %d %d %d](#)
- [IPSG: Join Stack %d %d 0x%x](#)
- [IPSG: Leave Stack %d %d 0x%x](#)
- [IPSG: Log Start](#)
- [IPSG Maximum IP entries on port unit# port# has been reached](#)
- [IPSG: Message Queue Rcv Error %d %d %d](#)
- [IPSG: Message Queue Send Error %d %d %d](#)
- [IPSG: nvRam file error: %d %d %d](#)
- [IPSG nvRam file error param1 param2 param3](#)
- [IPSG: Reached Max. IP entries supported on this port %d](#)
- [IPSG Reached Max. IP entries supported on this port port#](#)
- [IPSG Reached Max. IP entries supported on this port unit# port#](#)
- [IPSG: Reached Max. IP entries supported on this port %x/%d](#)
- [IPSG Resource allocated for Ports unit# port#](#)
- [IPSG: Resource allocated for Ports %x %x](#)
- [IPSG: Unit %d leave stack %d 0x%x](#)
- [IP Source Guard disabled on Unit %d Port %d](#)
- [IP Source Guard disabled on Unit unit# Port port#](#)
- [IP Source Guard enabled on Unit %d Port %d](#)
- [IP Source Guard enabled on Unit unit# Port port#](#)





# Telnet server logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Telnet server logs

The following logs are generated for this source:

- [Connection closed \(failed login\) IP address:](#)
- [Connection closed \(inactivity logout\) IP address](#)
- [Connection closed \(login timeout\) IP address:](#)
- [Connection closed \(lost connection\) IP address](#)
- [Connection closed. Maximum number of sessions reached. IP address:](#)
- [Connection closed. Maximum number of sessions reached. IP address:](#)
- [Connection closed \(user logout\). IP address:](#)
- [Disallowed connection attempt from IP address:](#)
- [Disallowed connection attempt - too many telnet sessions](#)
- [Failed login from IP address](#)
- [Failed login \(local auth\) from IP address:](#)
- [Failed login\(radius auth\) from IP add](#)
- [Failed login\(radius auth\) from serial conn](#)
- [Reset initiated through SSH by IP address](#)
- [Reset initiated through telnet by IP address](#)
- [Reset to default initiated through telnet by IP address](#)
- [Session closed \(inactivity logout\) IP address](#)
- [Session closed \(lost connection\) IP address](#)
- [Session closed \(user logout\) IP address](#)
- [Session opened from IP address](#)
- [Session opened \(local auth\) from IP address:](#)
- [Session opened\(radius auth\) from IP add](#)
- [Stack RO password changed from IP add](#)
- [Stack RW password changed from IP add](#)
- [Successful connection from IP address:](#)
- [Switch RO password changed from IP add:](#)
- [Switch RW password changed from IP add](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series

9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# DIGICERT logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DIGICERT logs

The following logs are generated for this source:

- [Auto-renew for CA %s failed with message: %s](#)
- [Auto-renew for CA %s was successful](#)
- [%s %s in %s%s has expired](#)
- [%s %s in %s%s will expire in %d days](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DOWNLOAD logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DOWNLOAD logs

The following logs are generated for this source:

- [FSH - NULL version for next reboot \(could not get semaphore\)](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Download Task logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Download Task logs

The following logs are generated for this source:

- [Download - %s image %sprogrammed successfully](#)
- [Download - TFTP timeout OR image file not found](#)
- [FSH - Time to Download the Image: %d seconds](#)
- [FSH - Time to Program the Image to flash: %d seconds](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Flash Driver logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Flash Driver logs

The following logs are generated for this source:

- [Download - DL\\_CKSUM\\_ACK\\_ERROR](#)
- [Download - DL\\_HASH\\_ACK\\_ERROR](#)
- [Download - DL\\_PROGRAM\\_STATUS\\_ACK\\_ERROR](#)
- [Download - DL\\_START\\_PROGRAM\\_FLASH\\_ACK\\_ERROR](#)
- [Download - Error: Failed to get FLASH sem](#)
- [Download - Error: Failed to get the dl resource.](#)
- [Download - Error: Failed to get the Reset sem](#)
- [Download - Error: Failed to send message to dlQueue](#)
- [Download - Error: Image is invalid](#)
- [Download - Error: Watchdog expire: No Ack from NBUs, download MSG # %d](#)
- [Download - Failed to get buffer](#)
- [Download - Failed to malloc for buffer](#)
- [Download - Failed to start a watchdog](#)
- [Download - Image Checksum Error](#)
- [Download - Image Hash Error](#)
- [Download - Largest mem blk < DL\\_SYSMEM\\_RESERVED](#)
- [Download - NBU: Block Checksum Error](#)
- [Download - NBU: DL\\_PROGRAM\\_STATUS: ERROR](#)
- [Download - tftpXfer failed](#)
- [FSH - Error: Calling taskLock\(\) returns Error](#)
- [FSH - Error: Failed to erase flash sector](#)
- [FSH - Error: Failed to lock flash sector](#)
- [FSH - Error: Failed to program flash](#)
- [FSH - Error: Failed to unlock flash sector](#)
- [FSH - Error: Failed to write to flash address](#)
- [Reset - Error Failed to get the Reset sem](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DRIVER logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DRIVER logs

The following logs are generated for this source:

- [Trap bsUnicastStormControlAboveHighWatermark](#)
- [Trap bsUnicastStormControlBelowLowWatermark](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# GBIC logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## GBIC logs

The following logs are generated for this source:

- [Info: Transceiver inserted on %s](#)
- [Info: Transceiver removed from %s](#)
- [SFP internal supply voltage is at high alarm level on %s](#)
- [SFP internal supply voltage is no longer at the high alarm level on %s](#)
- [SFP internal supply voltage is no longer at the high warning level on %s](#)
- [SFP internal supply voltage is no longer at the low alarm level on %s](#)
- [SFP internal supply voltage is no longer at the low warning level on %s](#)
- [SFP internal temperature is no longer at the high alarm level on %s](#)
- [SFP internal temperature is no longer at the high warning level on %s](#)
- [SFP internal temperature is no longer at the low alarm level on %s](#)
- [SFP internal temperature is no longer at the low warning level on %s](#)
- [SFP Received power is no longer at the high alarm level on %s](#)
- [SFP Received power is no longer at the high warning level on %s](#)
- [SFP Received power is no longer at the low alarm level on %s](#)
- [SFP Received power is no longer at the low warning level on %s](#)
- [SFP TX Bias current is no longer at the high warning level on %s](#)
- [SFP TX Bias current is no longer at the low warning level on %s](#)
- [SFP TX Bias is no longer at the high alarm level on %s](#)
- [SFP TX Bias is no longer at the low alarm level on %s](#)
- [SFP TX output power is no longer at the high alarm level on %s](#)
- [SFP TX output power is no longer at the high warning level on %s](#)
- [SFP TX output power is no longer at the low alarm level on %s](#)
- [SFP TX output power is no longer at the low warning level on %s](#)
- [Warning: non-supported qsfp inserted on %s. Port will not link up.](#)
- [Warning: non-supported stack cable inserted on %s. Stacking port will be admin disabled.](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Quick Install logs

The following logs are generated for this source:

- [QuickInstall console configuration error.](#)
- [QuickInstall: console configuration error.](#)
- [QuickInstall: console configuration success.](#)
- [QuickInstall:console configuration success.](#)
- [QuickInstall: console SNMP duplicate community error.](#)
- [QuickInstall: Error! Unable to locate agent software file](#)
- [QuickInstall: Error! Unable to locate agent software file.](#)
- [QuickInstall: Error! Unable to locate ASCII configuration file](#)
- [QuickInstall: Error! Unable to locate ASCII configuration file.](#)
- [QuickInstall: Error! Unable to locate diagnostics software file.](#)
- [QuickInstall: Processing of USB config file has commenced.](#)
- [QuickInstall: Processing of USB config file is complete](#)
- [QuickInstall: Processing of USB config file is complete.](#)
- [QuickInstall: USB config file not entirely executed](#)
- [QuickInstall USB config file not found.](#)
- [QuickInstall: USB config file not found.](#)
- [QuickInstall: USB file config error at line: %d.](#)
- [QuickInstall USB file config error at line line#](#)
- [QuickInstall: USB file config error: %d.](#)
- [QuickInstall USB file config error - file exceed 4096 bytes](#)
- [QuickInstall USB file config error - file exceed 200 lines.](#)
- [QuickInstall: USB file config error - file exceeds 4096 bytes](#)
- [QuickInstall: USB file config error - file exceeds 200 lines.](#)
- [QuickInstall: USB file config success.](#)
- [QuickInstall:USB file config success.](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>





# EAP-Filter Manager logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP-Filter Manager logs

The following logs are generated for this source:

- [EAP Failed qpa-RoleAssociation unitPort ifIndex macHi xx-xx macLo xx-xx-xx-xx](#)
- [EAP Unable to Reserve EapAdmin Filter Resources rc retCode unitPort ifIndex](#)
- [EAP Unable to Reserve Filter Resources rc retCode unitPort ifIndex Force- Unauthorised](#)
- [EAP Unable to UnReserve EapAdmin Filter Resources rc retCode unitPort ifIndex](#)
- [EAP Unable to UnReserve Filter Resources rc retCode unitPort unit-portnum](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPFIX logs

The following logs are generated for this source:

- [IPFIX: disable failure](#)
- [IPFIX: enable fail since NSNA enabled](#)
- [IPFIX enable failure](#)
- [IPFIX: enable failure](#)
- [IPFIX: enable failure due to invalid license](#)
- [IPFIX: error setting observation port](#)
- [IPFIX: init info failure](#)
- [IPFIX: malloc failure](#)
- [IPFIX: msgQSend failure](#)
- [IPFIX: port %d/%d is NNI. IPFIX is disabled on NNI ports](#)
- [IPFIX: port %d is NNI. IPFIX is disabled on NNI ports](#)
- [IPFIX: queue create failure](#)
- [IPFIX: read from nvram failed](#)
- [IPFIX: semaphore create failure](#)
- [IPFIX: semTake failure](#)
- [IPFIX: socket failure error=%d](#)
- [IPFIX: task spawn failure](#)
- [IPFIX: timer cancel failure](#)
- [IPFIX: timer create failure](#)
- [IPFIX: timer set failure](#)
- [IPFIX: too many entries requested](#)
- [IPFIX: write to nvram failed](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP-VLAN (QDT) logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP-VLAN (QDT) logs

The following logs are generated for this source:

- [EAP GVlan Disabled for unitPort ifIndex - GVlan\( vid \) in different stg\( id \)](#)
- [EAP Invalid RAV ID](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# PIM logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PIM logs

The following logs are generated for this source:

- [Pim Active RP change:](#)
- [Pim Assert change:](#)
- [Pim E-BSR change](#)
- [Pim E-BSR change:](#)
- [Pim Invalid packet received](#)
- [Pim Invalid packet received:](#)
- [Pim License Is Missing Disable PIM](#)
- [Pim License Is Missing Disable PIM](#)
- [Pim Mode Change](#)
- [Pim Mode Change:](#)
- [Pim Nbr State Change:](#)
- [Pim Nbr State Change Up](#)
- [PIM Neighbor status change Down](#)
- [PIM Neighbor status change Up](#)
- [Pim not enabled due to HW resources on port](#)
- [Pim RP type change:](#)
- [Pim RP type state](#)
- [Pim Unicast route change](#)
- [Pim Unicast route change:](#)
- [Pim Virt Nbr State Change:](#)
- [Pim Virt Nbr State Change Down](#)
- [Pim Virt Nbr State Change Up](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Energy Server logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Energy Server logs

The following logs are generated for this source:

- [Energy Server activated by schedule](#)
- [Energy Server deactivated by schedule](#)
- [Energy Server globally disabled](#)
- [Energy Server globally enabled](#)
- [Energy Server manually activated](#)
- [Energy Server manually deactivated](#)
- [Energy Server not applying schedule because SNTP not synchronized](#)
- [Energy Server time is synchronized applying schedule](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SC logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SC logs

The following logs are generated for this source:

- [Broadcast block unit/port %d/%d level %u watermark %u](#)
- [Broadcast over high watermark unit/port %d/%d level %u watermark %u](#)
- [Broadcast still blocked unit/port %d/%d level %u watermark %u](#)
- [Broadcast still over low watermark unit/port %d/%d level %u watermark %u](#)
- [Broadcast unblock unit/port %d/%d level %u watermark %u](#)
- [Broadcast under low watermark unit/port %d/%d level %u watermark %u](#)
- [Multicast block unit/port %d/%d level %u watermark %u](#)
- [Multicast over high watermark unit/port %d/%d level %u watermark %u](#)
- [Multicast still blocked unit/port %d/%d level %u watermark %u](#)
- [Multicast still over low watermark unit/port %d/%d level %u watermark %u](#)
- [Multicast unblock unit/port %d/%d level %u watermark %u](#)
- [Multicast under low watermark unit/port %d/%d level %u watermark %u](#)
- [SC Install SET fail unit/port %d/%d status=%d](#)
- [SC Install TEST fail unit/port %d/%d status=%d](#)
- [SC UnInst SET failed for port %u status=%d](#)
- [Unicast block unit/port %d/%d level %u watermark %u](#)
- [Unicast over high watermark unit/port %d/%d level %u watermark %u](#)
- [Unicast still blocked unit/port %d/%d level %u watermark %u](#)
- [Unicast still over low watermark unit/port %d/%d level %u watermark %u](#)
- [Unicast unblock unit/port %d/%d level %u watermark %u](#)
- [Unicast under low watermark unit/port %d/%d level %u watermark %u](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ENGMENU logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ENGMENU logs

The following logs are generated for this source:

- [Eng Menu Generation Test - Customer Message %d](#)
- [Eng Menu Test Msg #1 : Hi there! This is 1st test message .](#)
- [Eng Menu Test Msg #2 : Hi there! This is 2st test message .](#)
- [Eng Menu Test Msg #3 : Hi there! This is 3st test message .](#)
- [Eng Menu Test Msg #4 : Hi there! This is 4st test message .](#)
- [Eng Menu Test Msg #0 : No Error](#)
- [NSX Retrieve Events ... cur=0x%08X error=%d errno=0x%X.](#)
- [NSX Retrieve Events ERR event\\_group:%p req=0x%08X op=%d...](#)
- [Syslog Stress Test customer message .](#)
- [Syslog Stress Test engineering message .](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPv6 logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPv6 logs

The following logs are generated for this source:

- [Duplicate address deletion failed ipv6 address](#)
- [Duplicate address detection failed:](#)
- [Duplicate address detection succeeded:](#)
- [Duplicate address detection succeeded ipv6 address](#)
- [IPv6 enabled with hardware support and FMGR filters](#)
- [IPv6 enabled with hardware support and FMGR filters.](#)
- [IPv6 enabled with hardware support only](#)
- [IPv6 enabled with hardware support only.](#)
- [IPv6 FHS filters could NOT be installed](#)
- [IPv6 FHS filters successfully installed](#)
- [IPv6 FHS nvram failure.](#)
- [IPv6 Forwarding disabled due to inadequate license](#)
- [IPv6 Forwarding disabled due to inadequate license.](#)
- [IPv6 in IPv4 tunnel SIP mismatch](#)
- [IPv6 malloc failure](#)
- [IPv6 malloc failure.](#)
- [IPv6 over SPBM filters could NOT be installed.](#)
- [IPv6 over SPBM filters successfully installed.](#)
- [IPv6 SG filters could NOT be installed](#)
- [IPv6 SG filters successfully installed](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# ENTMIB logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ENTMIB logs

The following logs are generated for this source:

- [Trap\\_entConfigChange](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Exception logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Exception logs

The following logs are generated for this source:

- [Sw Exception](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MCFG logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MCFG logs

The following logs are generated for this source:

- [Backup configuration block %d in use](#)
- [Backup Configuration files are corrupted. Restored to default](#)
- [Backup configuration restored from primary configuration block %d](#)
- [Backup configuration updated for next active configuration block %d](#)
- [Config areas already remapped on unit %d](#)
- [Configuration block %d is now in use](#)
- [Configuration saved to nv block %d](#)
- [Error clearing the configuration counters from flash history on unit %d](#)
- [Error copying the configuration to new flash areas on unit %d](#)
- [Error loading backup configuration block %d](#)
- [Error loading primary configuration block %d](#)
- [Error saving configuration to block %d](#)
- [Error setting the remap flag in flash on unit %d](#)
- [Flash Erase Failed Sector %d Address 0x%x](#)
- [Flash Erase Warning Sector %d Address 0x%x Erase time %d ms](#)
- [Flash Erase Warning Sector %d Address 0x%x Erase time %d ms](#)
- [Loading configuration block %d](#)
- [Successfully remapped config areas on unit %d](#)
- [System: Rear-Port Mode has been set to disable \(reboot required to take effect\).](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FAA logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FAA logs

The following logs are generated for this source:

- [Fabric Attach: zero touch mgmt VLAN distribution disabled](#)
- [Fabric Attach: zero touch mgmt VLAN distribution enabled](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# SLAMon logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SLAMon logs

The following logs are generated for this source:

- [SLAMon Agent: agent IP address reset to default value](#)
- [SLAMon Agent: CLI support not available](#)
- [SLAMon Agent: CLI timeout value out-of-range](#)
- [SLAMon Agent: disabled](#)
- [SLAMon Agent: enabled](#)
- [SLAMon Agent: inconsistent IP address data specified](#)
- [SLAMon Agent: inconsistent UDP port data specified](#)
- [SLAMon Agent: info: %d %d %d](#)
- [SLAMon Agent: invalid agent-to-agent port \(must be even value\)](#)
- [SLAMon Agent: message channel creation failure](#)
- [SLAMon Agent: operation is restricted \(CLI-only\)](#)
- [SLAMon Agent: platform CLI command interface initialization issue](#)
- [SLAMon Agent: platform timer initialization issue](#)
- [SLAMon Agent: terminated](#)
- [SLAMon Agent: terminated - command/frame processing issue detected](#)
- [SLAMon Agent: terminated - NTR test exception detected](#)
- [SLAMon Agent: terminated - resources unavailable](#)
- [SLAMon Agent: terminated - RTP test exception detected](#)
- [Trap: slaMonitorAgentExceptionDetected](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Source Based Routing logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Source Based Routing logs

The following logs are generated for this source:

- [IpFwdNhop Err Filter Install mod\\_inst=0x%08x vid=%d rv=%d](#)
- [IpFwdNhop Err Filter Modify mod\\_inst=0x%08x vid=%d rv=%d](#)
- [IpFwdNhop Err Filter UnInstall mod\\_inst=0x%08x vid=%d rv=%d](#)
- [IpFwdNhop Err Save DB to NVRAM General File myMod=%d isBU=%d rw=%d](#)
- [IpFwdNhop Err Save DB to NVRAM Instance File myMod=%d isBU=%d rw=%d](#)
- [IpFwdNhop Err Save DB to NVRAM Policy File myMod=%d isBU=%d rw=%d](#)
- [IpFwdNhop: Feature enable temporarily blocked - resources unavailable](#)
- [IpFwdNhop: Filter installation issue - resources unavailable](#)
- [IpFwdNhop: Issue detected during data restore \(interface entry %d\)](#)
- [IpFwdNhop: Issue detected during enable retry \(interface entry %d\)](#)
- [IpFwdNhop: Issue detected during feature enable \(interface entry %d\)](#)
- [IpFwdNhop: Issue detected during interface creation \(interface entry %d\)](#)
- [IpFwdNhop: Issue detected during VLAN %d routing status update](#)
- [IpFwdNhop: Issue detected during VLAN membership addition \(VID %d\)](#)
- [IpFwdNhop: Issue detected during VLAN membership deletion \(VID %d\)](#)
- [IpFwdNhop: Issue detected during VLAN policy association \(entry %d\)](#)
- [IpFwdNhop: Requested precedence and/or filter resources unavailable](#)
- [IpFwdNhop: Requested range checking resources unavailable](#)
- [IpFwdNhop: VLAN membership update \(VID %d\) issue - resources unavailable](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FCoE Redirect logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FCoE Redirect logs

The following logs are generated for this source:

- [Conflicting egress interface and egress trunk data specified](#)
- [Egress interface or trunk data is required - data missing](#)
- [FCoE controller ifIndex not set - FCoE redirection enable prohibited](#)
- [FCoE controller VLAN not set - FCoE redirection enable prohibited](#)
- [FCoE redirection default frame filter deletion failure detected](#)
- [FCoE redirection default frame filter installation failure detected](#)
- [FCoE redirection - egress interface issue detected \(ifIndex %d\)](#)
- [FCoE redirection - egress trunk issue detected \(trunk ID %d\)](#)
- [Invalid FCoE controller ingress interface specified](#)
- [Invalid FCoE controller VLAN specified](#)
- [Invalid/unknown FCoE redirection egress trunk ID specified](#)
- [Network access settings for FCoE Redirect must be modified locally](#)
- [Trap: FCoE - Egress Issue Detected](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SPB logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPB logs

The following logs are generated for this source:

- [Cannot delete ISID used by EAP Fail Open VLAN](#)
- [Cannot delete ISID used by EAP Guest VLAN](#)
- [Cannot delete ISID used by EAP VoIP VLAN](#)
- [Cannot enable SPBM: EAP Guest, FailOpen or Voice VLANs are not default](#)
- [Cannot enable SPBM while MVR is enabled](#)
- [Cannot set IP source address to zero when IP Shortcut is enabled](#)
- [CFM: ERROR adding port filters for VLAN %d - no resources](#)
- [Nickname range 3.33.xx is reserved: corresponding mac used by IPv6 multicast](#)
- [SPBM: Configuration on unit %d does not match BU configuration - SPBM local config discarded](#)
- [SPBM: ERROR adding Transparent UNI for i-sid %d, port %d - no resources](#)
- [SPBM: ERROR same value for System ID and SMLT VIRTUAL BMAC - ISIS disabled](#)
- [SPBM: ERROR Trying to delete a non existing entry](#)
- [SPBM: ERROR updating UNIs for trunk %d - no resources](#)
- [SPBM: IPFIX over port %d/%d is disabled. IPFIX cannot be enabled over NNI](#)
- [SPBM: IPFIX over port %d is disabled. IPFIX cannot be enabled over NNI](#)
- [SPBM: Node already present on unit %d – will not add again](#)
- [Trap: rclsisPlsbSmltPeerBmacMismatchTrap](#)
- [Trap: rclsisPlsbSmltVirtBmacMismatchTrap](#)
- [Vlan is already a RSPAN vlan](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Flash logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Flash logs

The following logs are generated for this source:

- [FSH - Error: Failed to erase flash address %x located in the %s](#)
- [FSH - Error: Failed to write to %s, at address:%x](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# Stack Monitor logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack Monitor logs

The following logs are generated for this source:

- [application\\_name failed DB-exchange stack formation delayed](#)
- [Hello Module unable to communicate with neighbor\(s\) unit reset](#)
- [IMC buffers of size size have been exhausted buffer pool size size](#)
- [Stack synchronization failed stack formation delayed](#)
- [STKMON: Could not get available buffer](#)
- [STKMON: End](#)
- [STKMON: Failed to open config file](#)
- [STKMON: Failed to write to config file](#)
- [STKMON: Failed to xmit packet in stack](#)
- [STKMON: msgQReceive failed](#)
- [STKMON: Received unknown message into STKMON msg queue](#)
- [STKMON: Start](#)
- [Task %s is suspended](#)
- [Task task\\_name is suspended](#)
- [Task task-name is suspended](#)
- [Task whose index is %d.%d is suspended](#)
- [The number of stack units is %d instead of expected %d](#)
- [The number of stack units is number instead of expected number](#)
- [Trap bsnStackConfigurationError](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPT logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPT logs

The following logs are generated for this source:

- [Gateway IP changed](#)
- [IPT BootP Disabled \(response not received from server\)](#)
- [IPT: BootP Disabled \(response not received from server\)](#)
- [IPT: error: %s line %d %d](#)
- [IPT: info: %s arg1 %d arg2 %d](#)
- [IPT IP Address changed by BOOTP Server](#)
- [IPT: IP Address changed by BOOTP Server](#)
- [IPT: IP Address changed by DHCP Server](#)
- [IPT: Join Mac Add: inStack %d, isBase %d, port id %d](#)
- [IPT: Leave Mac Add: inStack %d, isBase %d, port id %d](#)
- [IPT: MVLAN Mac Add: inStack %d, isBase %d, port id %d](#)
- [IPT: Startup Mac Add: inStack %d, isBase %d, port id %d](#)
- [IPT: Temp BU Mac Add: inStack %d, isBase %d, port id %d](#)
- [IPT: Upd NBU\(Temp BU\) Mac Add: inStack %d, isBase %d, port id %d](#)
- [IPT: Using the last BOOTP/DHCP assigned IP address \(BOOTP server not reachable\)](#)
- [Stack IP changed](#)
- [Switch IP changed](#)
- [Trap Device has entered Forced Stack Mode \( MAC Address \)](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# FNC logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FNC logs

The following logs are generated for this source:

- [FSH – Error: Failed to get flash sem. tName %x. tName %x owns sem](#)
- [FSH – Error: Failed to release the flash resource](#)
- [FSH - File not closed :](#)
- [GLB – Error: Failed to get glb data sem tName: %x](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SMLT logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SMLT logs

The following logs are generated for this source:

- [SLPP Warning - PDU was received on Vlan VlanId Unit UnitNo Port PortNo .](#)
- [SMLT IMC invalid cmd 1- StkCmd](#)
- [SMLT IMC tx error](#)
- [SMLT input parameter error mlt port vlan](#)
- [SMLT Stack db ex event num -0 -0\\*22221111](#)
- [SMLT stackEventNotify Invalid Msg Cmd - 0 - 0](#)
- [SMLT Stack inactive event 0-0- modMask](#)
- [SMLT Stack joined event num - 0 - 0\\*33331111](#)
- [SMLT Stack leaved event 0 - 0 - modMask](#)
- [SMLT STP enabled on IST trunk trkNo stp group grp](#)
- [SMLT Warning - LAC SMLT with more than 8 links - key - count](#)
- [SMLT Warning - smltEnable Software License Error- 0 - 0](#)
- [SMLT Warning - SMLT mismatched Lac Sys ID error shutdown all SMLT lac po](#)
- [Trap SLPP Port Down Event](#)
- [Trap Smlt Ist Link Down](#)
- [Trap Smlt Ist Link Up](#)
- [Trap Smlt Link Down](#)
- [Trap Smlt Link Up](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLACP logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLACP logs

The following logs are generated for this source:

- [Port %d blocked by VLACP due to end-partner down state](#)
- [Port %d blocked by VLACP until end-partner connection reestablished](#)
- [Port %d/%d blocked by VLACP due to end-partner down state](#)
- [Port %d/%d blocked by VLACP until end-partner connection reestablished](#)
- [Port %d/%d reenabled by VLACP](#)
- [Port %d reenabled by VLACP](#)
- [Port unit# port# blocked by VLACP until end-partner connection reestablished](#)
- [Port unit# port# reenabled by VLACP](#)
- [VLACP: API error: %d-%d-%d](#)
- [VLACP: input parameter error: %d-%d-%d](#)
- [VLACP: msgQ error: %d-%d-%d](#)
- [VLACP: nvRam file error](#)
- [VLACP: RX event: %d - %d - %d](#)
- [VLACP: Stack event: %d - %d - 0x%x](#)
- [VLACP: Start](#)
- [VLACP: TMR event: %d - %d - %d](#)
- [VLACP: TX event: %d - %d - %d](#)
- [VLACP: vlacp log link change: %d - %d - %d](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# Hello Module logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Hello Module logs

The following logs are generated for this source:

- [Downstream stack direction is down cable removed or neighbor powered off](#)
- [Downstream stack direction is mis-configured](#)
- [Downstream stack direction is up cable inserted or neighbor powered on](#)
- [Hello Module unable to communicate with neighbor\(s\) unit reset](#)
- [Stack cable Down 1 is misconfigured](#)
- [Stack cable Down 2 is misconfigured](#)
- [Stack cable Up 1 is misconfigured](#)
- [Stack cable Up 2 is misconfigured](#)
- [Upstream stack direction is down cable removed or neighbor powered off](#)
- [Upstream stack direction is mis-configured](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IDT logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IDT logs

The following logs are generated for this source:

- [IDT: End](#)
- [IDT: Start](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PMT logs

The following logs are generated for this source:

- [PM in port mirroring the old data were modified - feature Allow Traffic in mirror port was added.](#)
- [PM in port mirroring the old data were modified - feature Many to Many was added.](#)
- [PM in port mirroring the old data were modified - feature Many to One was added.](#)
- [PM in port mirroring the old data were modified - feature Many to One with 128bits was added.](#)
- [PM in port mirroring the old data were modified - mode type was out of range.](#)
- [PM in port mirroring the old data were modified - monitored portA was out of range.](#)
- [PM in port mirroring the old data were modified - monitored portB was out of range.](#)
- [PM in port mirroring the old data were modified - NVRAM file structure was changed.](#)
- [PM in port mirroring the old data were modified - probe port was out of range.](#)
- [PM: mirroring data modified - all data were changed to default.](#)
- [PM: mirroring data modified - mode type was out of range.](#)
- [PM: mirroring data modified - monitored portA was out of range.](#)
- [PM: mirroring data modified - monitored portB was out of range.](#)
- [PM: mirroring data modified - probe port was out of range.](#)
- [PM: mirroring data modified - RSPAN was corrupted](#)
- [PM some port mirroring messages were stored to be displayd with delay.](#)
- [PM: unable to create mirror for instance %d due to lack of available filter resources](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# IFMGR, SNMP logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IFMGR, SNMP logs

The following logs are generated for this source:

- [Link Down Trap](#)
- [Link Up Trap](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VRRP logs

The following logs are generated for this source:

- [Trap bsveVrrpTrapStateTransition](#)
- [Trap vrrpTrapNewMaster](#)
- [VRRP Feature globally disabled due to missing license](#)
- [VRRP: Feature globally disabled due to missing license](#)
- [VRRP: IP address is changed to \(0x%08X\), different than Phy IP Address. Decreasing automatically priority from 255 to 254.](#)
- [VRRP: VR %d/%d: Received mismatching advertisement interval \(%d\)](#)
- [VRRP: VR %d/%d: Received mismatching advertisement type \(%d\)](#)
- [VRRP: VR %d/%d: Received mismatching fast advertisement interval \(%d\)](#)
- [VRRP: VR %d/%d: Received mismatching virtual IP address \(0x%08X\)](#)
- [VRRP: VR %d/%d: Received unknown VRRP packet type \(%d\)](#)
- [VRRP: vrrpAdvtQueue is FULL. RX advertisement dropped in vlan %d!](#)
- [VRRP: vrrpQueue is FULL. Message dropped.](#)
- [VRRP VR VR Id VLAN Id Received mismatching advertisement interval \( advertisement interval\)](#)
- [VRRP VR VR Id VLAN Id Received mismatching advertisement type \( advertisement type \)](#)
- [VRRP VR VR Id VLAN Id Received mismatching fast advertisement interval \( fast advertisement interval\)](#)
- [VRRP VR VR Id VLAN Id Received mismatching virtual IP address \( received virtual ip address \)](#)
- [VRRP VR VR Id VLAN Id Received unknown VRRP packet type \( vrrp packet type \)](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# NES logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NES logs

The following logs are generated for this source:

- [Energy Saver: activated by schedule](#)
- [Energy Saver: activated by schedule](#)
- [Energy Saver: deactivated by schedule](#)
- [Energy Saver: deactivated by schedule](#)
- [Energy Saver: globally disabled](#)
- [Energy Saver: globally disabled](#)
- [Energy Saver: globally enabled](#)
- [Energy Saver: globally enabled](#)
- [Energy Saver: manually activated](#)
- [Energy Saver: manually activated](#)
- [Energy Saver: manually deactivated](#)
- [Energy Saver: manually deactivated](#)
- [Energy Saver: not applying schedule because NTP/SNTP not synchronized](#)
- [Energy Saver: not applying schedule because NTP/SNTP not synchronized](#)
- [Energy Saver: time is synchronized, applying schedule](#)
- [Energy Saver: time is synchronized, applying schedule](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Run scripts: IP Office, LLDP, ADAC logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Run scripts: IP Office, LLDP, ADAC logs

The following logs are generated for this source:

- [Error creating Data VLAN](#)
- [Error creating Voice VLAN](#)
- [Error deleting previously created cost 1 default route](#)
- [Error deleting previously created Voice and Data VLANs](#)
- [Error executing script](#)
- [Error restoring management vlan to 1 or disabling ip routing](#)
- [Error saving configuration](#)
- [Error setting Data VLAN Gateway IP address and network mask](#)
- [Error setting default IP Route](#)
- [Error setting IP Office Call-Server IP address](#)
- [Error setting IP Office File-Server IP address](#)
- [Error setting spanning-tree learning to fast on all ports](#)
- [Error setting VLAN attributes](#)
- [Error setting Voice VLAN Gateway IP address and network mask](#)
- [Script was successfully executed](#)
- [Voice VLAN ID and Data VLAN ID cannot have the same value](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPIGMP logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPIGMP logs

The following logs are generated for this source:

- [IGMP: Last member query interval changed](#)
- [IGMP: Maximum number of igmp enabled interfaces reached](#)
- [IGMP: No hardware resource available](#)
- [IGMP: Proxy disabled](#)
- [IGMP: Proxy enabled](#)
- [IGMP: Query max response changed](#)
- [IGMP: Query Time changed](#)
- [IGMP: Robust Value changed](#)
- [IGMP: Router Alert changed](#)
- [IGMP: Snooping disabled](#)
- [IGMP: Snooping enabled](#)
- [IGMP: SSM Range changed](#)
- [IGMP: Static Router ports](#)
- [IGMP: Unknown Query received on SPBM Multicast C-VLAN](#)
- [IGMP: Version changed](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Inband IP address logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Inband IP address logs

The following logs are generated for this source:

- [IPT: IP Address not in use \(duplicate detected\)](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LACP logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LACP logs

The following logs are generated for this source:

- [LAC: MLT error, partner aggregation bit not set](#)
- [LAC: MLT error, partner expired bit set](#)
- [LAC: MLT error, partner synchronization bit not set](#)
- [LAC with admin key %d failed configuration verification. Bad ARP INSPECTION configuration.](#)
- [LAC with admin key %d failed configuration verification. Bad DHCP-SNOOPING configuration.](#)
- [LAC with admin key %d failed configuration verification. Bad IGMP configuration.](#)
- [LAC with admin key %d failed configuration verification. Bad MAC Security configuration.](#)
- [LAC with admin key %d failed configuration verification. Bad qos status.](#)
- [LAC with admin key %d failed configuration verification. Bad rate-limiting configuration.](#)
- [LAC with admin key %d failed configuration verification. Bad VLAN configuration.](#)
- [LAC with admin key %d failed configuration verification. Error #: %d-%d](#)
- [LAC with admin key %d failed configuration verification. Ports have different qos config.](#)
- [LAC with admin key %d failed configuration verification. Ports have different SPBM configurations.](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# ipmc (igmp) logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ipmc (igmp) logs

The following logs are generated for this source:

- [IGMP Maximum number of igmp enabled interfaces reached](#)
- [IGMP No hardware resource available](#)
- [IGMP SSM Range changed](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ospf(drpmgr) logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ospf(drpmgr) logs

The following logs are generated for this source:

- [Ospf Area Mismatch RxArea ra.rb.rc.rd IntfArea ia.ib.ic.id](#)
- [Ospf Auth Failed IpAddr ia.ib.ic.id](#)
- [Ospf Auto Virt Link Failed area a1.a2.a3.a4 rtid r1.r2.r3.r4](#)
- [Ospf Cost Exceeds Limit Skip route Lsid l1.l2.l3.l4 Adv-rtr a1.a2.a3.a4](#)
- [Ospf Enable Failed as Resource Unavailable](#)
- [Ospf Hello: RId Same as Neighbor: rtid <r1.r2.r3.r4>, IpAddr <i1.i2.i3.i4>](#)
- [Ospf HW Mode Change:](#)
- [Ospf Invalid packet received: Pkt type <ospfPacketType>](#)
- [Ospf License Is Missing. Disable OSPF](#)
- [Ospf Nbr State Change: rtid <ra.rb.rc.rd> ipa <ia.ib.ic.id> state <neighborState>](#)
- [Ospf Netmask Mismatch in Hello IpAddr ia.ib.ic.id](#)
- [Ospf Option Mismatch in Hello IpAddr ia.ib.ic.id RxOption optionVal IntfOption optionVal](#)
- [Ospf Virt Nbr State Change: rtid <r1.r2.r3.r4>, virtAreaId <v1.v2.v3.v4>, state <neighborState>](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPMGR logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPMGR logs

The following logs are generated for this source:

- [Unauthorized connection attempt from IP address:](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Link State Tracking logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Link State Tracking logs

The following logs are generated for this source:

- [LinkStateTracking: First interface %d/d went up in link state group %d, enabling downstream ports](#)
- [LinkStateTracking: First interface mlt %d went up in link state group %d, enabling downstream interfaces](#)
- [LinkStateTracking: First interface %s went up in link state group %d, enabling downstream interfaces](#)
- [LinkStateTracking: Interface %d/d went down in link state group %d](#)
- [LinkStateTracking: Interface %d/d went up in link state group %d](#)
- [LinkStateTracking: Interface mlt %d went down in link state group %d](#)
- [LinkStateTracking: Interface mlt %d went up in link state group %d](#)
- [LinkStateTracking: Interface %s went down in link state group %d](#)
- [LinkStateTracking: Interface %s went up in link state group %d](#)
- [LinkStateTracking: Last interface %d/d went down in link state group %d, disabling downstream interfaces](#)
- [LinkStateTracking: Last interface mlt %d went down in link state group %d, disabling downstream interfaces](#)
- [LinkStateTracking: Last interface %s went down in link state group %d, disabling downstream interfaces](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPSEC logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPSEC logs

The following logs are generated for this source:

- [IPSEC - Packet dropped: lAddr:%04x:%04x:%04x:%04x:%04x:%04x:%04x  
rAddr:%04x:%04x:%04x:%04x:%04x:%04x:%04x Src Port:%d Dest Port:%d Protocol:%d](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# SSHC (SFTP and SSH Client) logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC (SFTP and SSH Client) logs

The following logs are generated for this source:

- [SSHC ASCII CFG download SFTP failure](#)
- [SSHC ASCII CFG upload SFTP failure](#)
- [SSHC CFG download SFTP failure](#)
- [SSHC CFG upload SFTP failure](#)
- [SSHC DSA key generation failure](#)
- [SSHC DSA key save failure](#)
- [SSHC DSA key upload TFTP failure](#)
- [SSHC DSA key upload USB failure](#)
- [SSHC RSA key generation failure](#)
- [SSHC RSA key save failure](#)
- [SSHC RSA key upload TFTP failure](#)
- [SSHC RSA key upload USB failure](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH Client logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH Client logs

The following logs are generated for this source:

- [SSHC: CFG download SFTP failure](#)
- [SSHC: CFG upload SFTP failure](#)
- [SSH CLIENT Key couldnt be saved for host ip address](#)
- [SSH CLIENT SSH Connection to IP ip address was closed because parent console session console session ID was closed](#)
- [SSH CLIENT SSH Connection to %s was disconnected](#)
- [SSH CLIENT: SSH Connection to %s was disconnected by host. Connection time: %s](#)
- [SSH CLIENT: SSH Connection to %s was disconnected by user. Connection time: %s.](#)
- [SSH CLIENT Successful SSH Connection to %s using %s authentication](#)
- [SSHC: Password Authentication failure](#)
- [SSHC: RSA Authentication failure](#)
- [SSH session closed by ip address remote host. Connection time h hours m minutes](#)
- [Successful SSH connection to ip address](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPv4 Routing logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPv4 Routing logs

The following logs are generated for this source:

- [Assertion Failure in bcm\\_l3\\_hit\\_check- l3sw ip=%#x.l3hw ip=%#x](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IPv6 Data Tunneling logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPv6 Data Tunneling logs

The following logs are generated for this source:

- [IPv6 in IPV4 tunnel SIP mismatch](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPv6 First Hop Security logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPv6 First Hop Security logs

The following logs are generated for this source:

- [IPv6 FHS filters could NOT be installed](#)
- [IPv6 FHS filters successfully installed](#)
- [Trap: bsIpv6DHCPGNotif%s MAC:%02x:%02x:%02x:%02x:%02x:%02x Addr:%s Port:%hhu/%hhu](#)
- [Trap: bsIpv6NDNotificationSBTTableFull - MAC:%02x:%02x:%02x:%02x:%02x:%02x Addr:%s Port:%hhu/%hhu](#)
- [Trap: bsIpv6NDNotificationUntrustedPort - MAC:%02x:%02x:%02x:%02x:%02x:%02x Addr:%s Port:%hhu/%hhu](#)
- [Trap: bsIpv6RAGNotif%s MAC:%02x:%02x:%02x:%02x:%02x:%02x Addr:%s Port:%hhu/%hhu](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# PoE logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PoE logs

The following logs are generated for this source:

- [PoE Main Power Usage Off](#)
- [PoE Main Power Usage On](#)
- [PoE Module Reset](#)
- [PoE Port Detection Status port# Status powerStatus](#)
- [PoE The PoE power limit for port unit port has been changed to x Watts based on IP phone discovery settings](#)
- [PoE The PoE power limit for port unit port has been restored to previous value x Watts](#)
- [PoE The PoE priority for port unit port has been changed to x based on IP phone discovery settings](#)
- [PoE The PoE priority for port unit port has been restored to previous value x](#)
- [The IP phone PoE limit has been changed to x Watts due to the stack modules configuration](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPv6 management over SPB (routing mode) logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPv6 management over SPB (routing mode) logs

The following logs are generated for this source:

- [IPv6 DST MAC filters could NOT be installed.](#)
- [IPv6 DST MAC filters successfully installed.](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# SSL logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSL logs

The following logs are generated for this source:

- [SSL certificate creation completed](#)
- [SSL certificate creation failed](#)
- [SSL certificate deleted](#)
- [SSL connection was closed from](#)
- [SSL disabled](#)
- [SSL enabled](#)
- [SSL negotiation failure from](#)
- [SSL server reset](#)
- [SSL successful connection from](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPv6 Source Guard logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPv6 Source Guard logs

The following logs are generated for this source:

- [IPv6 SG filters could NOT be installed](#)
- [IPv6 SG filters successfully installed](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# L3, MLT logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## L3, MLT logs

The following logs are generated for this source:

- [Trap s5CtrUnitDown](#)
- [Trap s5CtrUnitDown](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# PDT logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PDT logs

The following logs are generated for this source:

- [Info: Transceiver inserted on %s](#)
- [Info: Transceiver removed from %s](#)
- [Management IP: excess traffic received on Management port%s](#)
- [Management IP: OOB port%s](#)
- [Management IP: OOB port%s](#)
- [Notice: DAC Cable on %s is below HW rev "H" and may cause link issues with a small number of PHYs](#)
- [Warning:non-supported transceiver on %s has been detected.](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SPBM logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM logs

The following logs are generated for this source:

- [SPBM: ERROR adding C-VLAN UNI for i-sid %d, vlan %d - no resources](#)
- [SPBM: ERROR adding i-sid %x to i-sid table - table full](#)
- [SPBM: ERROR adding NNI on port %d vlan %d - no resources](#)
- [SPBM: ERROR adding peer %04x.%04x.%04x - no resources](#)
- [SPBM: ERROR adding switched UNI for i-sid %d, port %d, vlan %d - no resources](#)
- [SPBM: ERROR enabling SPBM due to Software License error](#)
- [SPBM: ERROR updating UNI for port %d/%d - no resources](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ZTP logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ZTP logs

The following logs are generated for this source:

- [ZTP+: failed to connect to the XMC server](#)
- [ZTP+: failed to start the auto-provisioning process](#)
- [ZTP+: failed to upgrade the firmware](#)
- [ZTP+: successfully connected to the XMC server](#)
- [ZTP+: successfully upgraded the firmware](#)
- [ZTP+: the auto-provisioning process has started](#)
- [ZTP+: the firmware upgrade has started](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LST logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LST logs

The following logs are generated for this source:

- [Trap: bsLstGroupOperStateChanged](#)
- [Trap: bsLstInterfaceStatusChanged](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# MLD logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLD logs

The following logs are generated for this source:

- [MLD: Filters could NOT be installed.](#)
- [MLD: Filters successfully installed.](#)
- [MLD: HW ipmc entries exceeded](#)
- [MLD: Maximum number of mld enabled interfaces reached](#)
- [MLD: The maximum number of available hardware MLD entries has been reached](#)
- [MLD: The maximum number of available hardware MLD entries has been reached](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MCFG (Second INFO BLOCK) logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MCFG (Second INFO BLOCK) logs

The following logs are generated for this source:

- [Boot: system boot status 0x%x](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# POL logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## POL logs

The following logs are generated for this source:

- [PoE Port Detection Status:](#)
- [PoL nvRam file error](#)
- [Trap bspePethPsePortCurrentStatusNotification](#)
- [Trap\\_pethMainPowerUsageOffNotification](#)
- [Trap\\_pethMainPowerUsageOnNotification](#)
- [Trap\\_pethPsePortOnOffNotification](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MCM logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MCM logs

The following logs are generated for this source:

- [MCM group node corrupted:](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Run scripts: LLDP, ADAC logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Run scripts: LLDP, ADAC logs

The following logs are generated for this source:

- [Error configuring LLDP MED policies](#)
- [Error configuring Management IP Address](#)
- [Error enabling IP Routing](#)
- [Error setting Management VLAN](#)
- [Error setting uplink ports](#)
- [Error setting VLAN Gateway IP address and network mask](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# MCMGR, DRPMGR logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MCMGR, DRPMGR logs

The following logs are generated for this source:

- [Trap\\_s5CtrHotSwap](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SBR logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SBR logs

The following logs are generated for this source:

- [IpFwdNhop Err Get NxtHopId mod inst=0x%08x vid=%d nhop=0x%08x](#)
- [IpFwdNhop Err Unknown](#)
- [IpFwdNhop: Invalid/inconsistent VLAN admin status specified](#)
- [IpFwdNhop: Issue detected during VLAN admin status enable \(VID %d\)](#)
- [IpFwdNhop: VLAN %d admin status enable failure - resources unavailable](#)
- [Trap: rclsisPlsbSmltSplitBebMismatchTrap](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MCMGR/IGMP logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MCMGR/IGMP logs

The following logs are generated for this source:

- [IGMP: V2 report drop on reserved GA](#)
- [IGMP: V3 report group skip on invalid GA](#)
- [IGMP: V3 report group skip on reserved GA](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MDA logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MDA logs

The following logs are generated for this source:

- [%s card inserted \(in unit %s\)](#)
- [%s card removed \(from unit %s\)](#)
- [Warning failed to connect to %s card \(in unit %s\)](#)
- [Warning: non-supported qsfp inserted on %s. Port will be disabled.](#)
- [Warning %s card unsafely removed \(from unit %s\)](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Memory Tool logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Memory Tool logs

The following logs are generated for this source:

- [Memory on unit %d is under %d MBytes.](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# NNCLI logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NNCLI logs

The following logs are generated for this source:

- [Trap\\_newRoot](#)
- [Trap\\_s5EtrSbsMacRemoved](#)
- [Trap\\_s5EtrSbsMacTableCleared](#)
- [Trap\\_s5EtrSbsMacTableClearedForPort](#)
- [Trap\\_topologyChange](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# NNRST logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NNRST logs

The following logs are generated for this source:

- [Trap RSTP Error Event](#)
- [Trap RSTP General Event](#)
- [Trap RSTP New Root](#)
- [Trap RSTP Protocol Migration](#)
- [Trap RSTP Topology Change](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Multi Config logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Multi Config logs

The following logs are generated for this source:

- [Successfully loaded backup configuration files](#)
- [Successfully loaded configuration files from block %d](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Run scripts: ADAC logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Run scripts: ADAC logs

The following logs are generated for this source:

- [Error creating MLT](#)
- [Error enabling ADAC](#)
- [Error enabling ADAC on ports](#)
- [Error setting ADAC operating mode](#)
- [Error setting call server ports](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# NTP logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NTP logs

The following logs are generated for this source:

- [NTP\\_synchronized](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# NUQC logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NUQC logs

The following logs are generated for this source:

- [NUQC - Disabled](#)
- [NUQC - Enabled](#)
- [NUQC - Execution of the cli template failed](#)
- [NUQC - Execution of the cli template succeeded](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# PLATFORM logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PLATFORM logs

The following logs are generated for this source:

- [Accessing information that has not been initialized.](#)
- [Failed to create paltform\\_info task.](#)
- [Failed to create platform\\_info message queue.](#)
- [Failed to set platform\\_info. FLASH sem not acquired.](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Password Security logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Password Security logs

The following logs are generated for this source:

- [Trap: bsnROPASSWORDExpired: Read-only password expired](#)
- [Trap: bsnRWPasswordExpired: Read-write password expired](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QPAV2 logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QPAV2 logs

The following logs are generated for this source:

- [Trap DAPP - DoS Attack Detected](#)
- [Trap ntnQosPolicyEvolLocalUbpSessionFailure](#)
- [Trap ubpEAPSessionEnd](#)
- [Trap ubpEAPSessionStart](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Run scripts: IP Office logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Run scripts: IP Office logs

The following logs are generated for this source:

- [Error configuring port names](#)
- [Error enabling mstp learning on all ports](#)
- [Error enabling rstp learning on all ports](#)
- [Error setting poe-priority high on ports](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFTP Client logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFTP Client logs

The following logs are generated for this source:

- [SSHC DSA Authentication failure](#)
- [SSHC Password Authentication failure](#)
- [SSHC RSA Authentication failure](#)
- [SSHC server connection failure](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# USB logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## USB logs

The following logs are generated for this source:

- [USB device inserted](#)
- [USB device removed](#)
- [USB nvRam file error](#)
- [USB unsupported file system](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# PM logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PM logs

The following logs are generated for this source:

- [PM unable to create mirror for instance instance number due to lack of available filter resources](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QoS Agent logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QoS Agent logs

The following logs are generated for this source:

- [Issue detected enabling/disabling DSCP Mapping Table usage \(port %d\)](#)
- [Issue detected setting native DSCP Mapping Table values](#)
- [Unable to inform SPB of ifc assignment change \(%d/%d\)](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SLOG logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SLOG logs

The following logs are generated for this source:

- [After agent change message became invalid:](#)
- [Event logging disabled](#)
- [Event logging enabled](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SLPP Guard logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SLPP Guard logs

The following logs are generated for this source:

- [SLPP-guard: hold-down timer has expired on port with SLPP-guard enabled. Port %s has been re-enabled](#)
- [SLPP-guard: SLPP-guard has not been enabled on port %s as no filters or filter precedences are available to setup an Ethertype filter](#)
- [SLPP-guard: SLPP packet received on port with SLPP-guard enabled. Port %s has been disabled](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Port Mirroring logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Port Mirroring logs

The following logs are generated for this source:

- [PM: in port mirroring the old data were modified - feature RSPAN was added](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SNTP logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SNTP logs

The following logs are generated for this source:

- [SNTP Could not sync to NTP servers.](#)
- [SNTP: Could not sync to SNTP servers.](#)
- [SNTP: First synchronization successful.](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# System Logging logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## System Logging logs

The following logs are generated for this source:

- [After agent change message became invalid:](#)
- [System memory on unit %d is under %d MBytes.](#)
- [Used stack size of task %s is \(%d%%\).](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Rear-Port logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Rear-Port logs

The following logs are generated for this source:

- [System: Rear-Port Mode has been set to disable \(reboot required to take effect\)](#)
- [System: Rear-Port Mode has been set to enable \(reboot required to take effect\)](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# RMON logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RMON logs

The following logs are generated for this source:

- [Trap fallingAlarm](#)
- [Trap risingAlarm](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Run scripts: IP Office, LLDP logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Run scripts: IP Office, LLDP logs

The following logs are generated for this source:

- [Error configuring 802.1AB](#)
- [Error setting QoS](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# SFTP logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFTP logs

The following logs are generated for this source:

- [SSHC: ASCII CFG download SFTP failure](#)
- [SSHC: ASCII CFG upload SFTP failure](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# SLPP logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SLPP logs

The following logs are generated for this source:

- [SLPP: \(Continued\) - PDU was sent on Vlan %d.](#)
- [SLPP: Warning - PDU was received on Unit %d, Port %d, Vlan %d.](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# SOFTLIC logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SOFTLIC logs

The following logs are generated for this source:

- [Trap bsnTrialLicenseExpiration Trial license license# has expired. Disable licensed features to avoid network interruption](#)
- [Trap bsnTrialLicenseExpiration Trial license license# will expire in # days day\(s\)](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SPAD logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPAD logs

The following logs are generated for this source:

- [Scratchpad failed to copy sector \(%x, %d\)](#)
- [Scratchpad failed to erase sector \(%x, %x, %d\)](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VRRPv3 logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VRRPv3 logs

The following logs are generated for this source:

- [VRRPv3 filters have NOT been installed.](#)
- [VRRPv3 filters successfully installed.](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# source logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## source logs

The following logs are generated for this source:

- [name](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SWEXCEPTION logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SWEXCEPTION logs

The following logs are generated for this source:

- [Sw Exception:](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TOTAL SYS UPTIME (TSU) logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TOTAL SYS UPTIME (TSU) logs

The following logs are generated for this source:

- [Trap: bsnSystemUp365Days sent from unit %d](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Information logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Information logs

There are 1077 logs for this severity. To simplify navigation, all logs are organized alphabetically by their name. Select the letter to navigate to the list of all logs starting with that letter for this severity.

<a href="#">A</a> 63 logs	<a href="#">B</a> 14 logs	<a href="#">C</a> 66 logs	<a href="#">D</a> 64 logs
<a href="#">E</a> 138 logs	<a href="#">F</a> 39 logs	<a href="#">G</a> 2 logs	<a href="#">H</a> 1 logs
<a href="#">I</a> 90 logs	<a href="#">J</a> 1 logs	K	<a href="#">L</a> 70 logs
<a href="#">M</a> 48 logs	<a href="#">N</a> 16 logs	<a href="#">O</a> 29 logs	<a href="#">P</a> 41 logs
<a href="#">Q</a> 15 logs	<a href="#">R</a> 23 logs	<a href="#">S</a> 166 logs	<a href="#">T</a> 128 logs
<a href="#">U</a> 19 logs	<a href="#">V</a> 20 logs	<a href="#">W</a> 20 logs	X
Y	Z		

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Console logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Console logs

The following logs are generated for this severity:

- [Failed login\(radius auth\) from serial conn](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Serious logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Serious logs

There are 525 logs for this severity. To simplify navigation, all logs are organized alphabetically by their name. Select the letter to navigate to the list of all logs starting with that letter for this severity.

<a href="#">A</a> 28 logs	<a href="#">B</a> 11 logs	<a href="#">C</a> 26 logs	<a href="#">D</a> 26 logs
<a href="#">E</a> 22 logs	<a href="#">F</a> 22 logs	G	H
<a href="#">I</a> 141 logs	J	K	<a href="#">L</a> 3 logs
<a href="#">M</a> 11 logs	<a href="#">N</a> 18 logs	<a href="#">O</a> 5 logs	<a href="#">P</a> 27 logs
<a href="#">Q</a> 6 logs	<a href="#">R</a> 24 logs	<a href="#">S</a> 34 logs	<a href="#">T</a> 19 logs
<a href="#">U</a> 90 logs	<a href="#">V</a> 2 logs	<a href="#">W</a> 6 logs	X
Y	Z		

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Critical logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Critical logs

There are 184 logs for this severity. To simplify navigation, all logs are organized alphabetically by their name. Select the letter to navigate to the list of all logs starting with that letter for this severity.

<a href="#">A</a> 7 logs	<a href="#">B</a> 2 logs	<a href="#">C</a> 12 logs	<a href="#">D</a> 21 logs
<a href="#">E</a> 1 logs	<a href="#">F</a> 12 logs	G	<a href="#">H</a> 1 logs
<a href="#">I</a> 53 logs	J	K	<a href="#">L</a> 1 logs
<a href="#">M</a> 4 logs	N	O	<a href="#">P</a> 5 logs
<a href="#">Q</a> 2 logs	<a href="#">R</a> 3 logs	<a href="#">S</a> 17 logs	<a href="#">T</a> 4 logs
<a href="#">U</a> 39 logs	V	W	X
Y		Z	

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error logs

The following logs are generated for this severity:

- [CFGSO - Warning Watchdog timer expire](#)
- [SPBM: ERROR adding C-VLAN UNI for i-sid %d, vlan %d - no resources](#)
- [SPBM: ERROR adding NNI on port %d vlan %d - no resources](#)
- [SPBM: ERROR adding peer %04x.%04x.%04x - no resources](#)
- [SPBM: ERROR adding switched UNI for i-sid %d, port %d, vlan %d - no resources](#)
- [SPBM: ERROR updating UNI for port %d/%d - no resources](#)
- [Stack cable Down 1 is misconfigured](#)
- [Stack cable Down 2 is misconfigured](#)
- [Stack cable Up 1 is misconfigured](#)
- [Stack cable Up 2 is misconfigured](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Warning logs

The following logs are generated for this severity:

- [Composite filter set addition failure seed filter set unknown](#)
- [Failed route add <ip addr/ip mask> to HW <hw error code>](#)
- [Failed to restore dynamic role combination post QoS reset](#)
- [FSH – Error: Failed to get flash sem. tName %x. tName %x owns sem](#)
- [FSH – Error: Failed to release the flash resource](#)
- [GLB – Error: Failed to get glb data sem tName: %x](#)
- [Got dynamic UBP but it's not enabled for EAP clients, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x](#)
- [Got dynamic UBP but it's not enabled for Non-EAP clients, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x](#)
- [IMC imc\\_idtPacketDispatch\(\) incorrect rcvMsgType = %s\(%d\)](#)
- [IMC memory allocation error packetLength = %d file %s line %d](#)
- [Insufficient dynamic UBP attributes in CoA, need ACL, UROL and SET](#)
- [Insufficient dynamic UBP attributes, need ACL, UROL and SET, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x](#)
- [Queue set value modification prohibited](#)
- [Trap s5CtrUnitDown](#)
- [UBP CoA cannot proceed, dynamic UBP not enabled either for EAP or Non-EAP clients](#)
- [Unable to restore dynamic ifc to default role association \(%d/%d\)](#)
- [Unable to restore dynamic ifc to static role association \(%d/%d\)](#)
- [Unsupported field for ACL in dynamic CoA UBP](#)
- [Unsupported field for ACL in dynamic UBP, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x](#)
- [Unsupported field for SET in dynamic CoA UBP](#)
- [Unsupported field for SET in dynamic UBP, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x](#)
- [Unsupported value for ACL field in dynamic CoA UBP](#)
- [Unsupported value for ACL field in dynamic UBP, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x](#)
- [Unsupported value for SET field in dynamic CoA UBP](#)
- [Unsupported value for SET field in dynamic UBP, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Inform logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Inform logs

The following logs are generated for this severity:

- [ZTP+: failed to connect to the XMC server](#)
- [ZTP+: failed to start the auto-provisioning process](#)
- [ZTP+: failed to upgrade the firmware](#)
- [ZTP+: successfully connected to the XMC server](#)
- [ZTP+: successfully upgraded the firmware](#)
- [ZTP+: the auto-provisioning process has started](#)
- [ZTP+: the firmware upgrade has started](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Minor logs

The following logs are generated for this severity:

- [Fabric Attach: auto attach operations not completed \(VLAN <VID>\)](#)
- [Fabric Attach: interface-specific I-SID/VLAN assignments not allowed](#)
- [Fabric Attach: invalid VLAN data \(unknown or incompatible type\)](#)
- [Fabric Attach: message authentication support not available](#)
- [Fabric Attach: operation failure detected](#)
- [Fabric Attach: operation rejected - client-owned entry](#)
- [Fabric Attach: operation rejected - CVLAN already exists](#)
- [Fabric Attach: operation rejected - entry does not exist](#)
- [Fabric Attach: operation rejected - not supported by element type](#)
- [Fabric Attach: operation rejected - service not enabled](#)
- [Fabric Attach: operation rejected - table entry limits reached](#)
- [Fabric Attach: server asgn \(<ISID>/<VID>\) rejection](#)
- [Fabric Attach: server asgn \(<ISID>/<VID>\) rejection - application interactions](#)
- [Fabric Attach: server asgn \(<ISID>/<VID>\) rejection - invalid VLAN](#)
- [Fabric Attach: server asgn \(<ISID>/<VID>\) rejection - no FA resources](#)
- [Fabric Attach: server asgn \(<ISID>/<VID>\) rejection - no VLAN resources](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Major logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Major logs

The following logs are generated for this severity:

- [Fabric Attach: agent settings reset incomplete](#)
- [Fabric Attach: I-SID/VLAN assignment creation failure \(unexpected\)](#)
- [Fabric Attach: I-SID/VLAN assignment deletion failure \(unexpected\)](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Warning/Information logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Warning/Information logs

The following logs are generated for this severity:

- [Bay Secure: Exceeded %d per-trunk MAC addresses on trunk %d](#)
- [Trap: bsDhcpSnoopingExtSaveSFTPSyncSuccess](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# Serious/Critical logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Serious/Critical logs

The following logs are generated for this severity:

- [After agent change message became invalid:](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# severity logs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## severity logs

The following logs are generated for this severity:

- [name](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AAUR - Info: AAUR default

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AAUR - Info: AAUR default log

AAUR - Info: AAUR default

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# AAUR-Info AAUR default

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AAUR-Info AAUR default log

AAUR-Info AAUR default

AAUR default.

Source	Severity
AUR	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AAUR - Info: AAUR disable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AAUR - Info: AAUR disable log

AAUR - Info: AAUR disable

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AAUR-Info AAUR disable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AAUR-Info AAUR disable log

AAUR-Info AAUR disable

The AAUR is disabled.

Source	Severity
AUR	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AAUR - Info: AAUR enable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AAUR - Info: AAUR enable log

AAUR - Info: AAUR enable

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AAUR-Info AAUR enable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AAUR-Info AAUR enable log

AAUR-Info AAUR enable

The AAUR is enabled.

Source	Severity
AUR	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AAUR - Info: Agent transfer finished

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AAUR - Info: Agent transfer finished log

AAUR - Info: Agent transfer finished

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AAUR-Info Agent transfer finished

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AAUR-Info Agent transfer finished log

AAUR-Info Agent transfer finished

The agent transfer is completed.

Source	Severity
AUR	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AAUR - Info: Receive request for agent image, start transfer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AAUR - Info: Receive request for agent image, start transfer log

AAUR - Info: Receive request for agent image, start transfer

Source	Severity
AUR	Information

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# AAUR-Info Receive request for agent image start transfer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AAUR-Info Receive request for agent image start transfer log

AAUR-Info Receive request for agent image start transfer

The system received request for an agent image and the transfer is started.

Source	Severity
AUR	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AAUR - Info: Receive request for agent image. Unable to start transfer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AAUR - Info: Receive request for agent image. Unable to start transfer log

AAUR - Info: Receive request for agent image. Unable to start transfer

A unit joining the stack, having a different version of agent image, is requesting to download the correct agent image version. The download cannot proceed due to various reasons.

Source	Severity
AUR	Serious

### Remedial action

Unplug and then reconnect the stack cable(s) connecting that unit to the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AAUR-Info Receive request for agent image. Unable to start transfer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AAUR-Info Receive request for agent image. Unable to start transfer log

AAUR-Info Receive request for agent image. Unable to start transfer

The system received request for an agent image. Unable to start transfer.

Source	Severity
AUR	Information

### Remedial action

No action required.



# AAUR-Info Send request for new agent image

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AAUR-Info Send request for new agent image log

AAUR-Info Send request for new agent image

The system is sending request for a new agent image.

Source	Severity
AUR	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AAUR - Info: Slave refuse transfer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AAUR - Info: Slave refuse transfer log

AAUR - Info: Slave refuse transfer

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AAUR-Info Slave refuse transfer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AAUR-Info Slave refuse transfer log

AAUR-Info Slave refuse transfer

Slave refuse transfer.

Source	Severity
AUR	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AAUR - Info: Start receive image

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AAUR - Info: Start receive image log

AAUR - Info: Start receive image

**Source    Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AAUR-Info The hardware is not compatible with the image\_version\_number version

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AAUR-Info The hardware is not compatible with the image\_version\_number version log

AAUR-Info The hardware is not compatible with the image\_version\_number version

The hardware is not compatible.

Source	Severity
AUR	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# AAUR - The hardware is not compatible with the %s version

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AAUR - The hardware is not compatible with the %s version log

AAUR - The hardware is not compatible with the %s version

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AAUR - Warning Agent image check sum ERROR

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AAUR - Warning Agent image check sum ERROR log

AAUR - Warning Agent image check sum ERROR

Agent image check sum error.

Source	Severity
AUR	Serious

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AAUR - Warning: Agent image check sum ERROR

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AAUR - Warning: Agent image check sum ERROR log

AAUR - Warning: Agent image check sum ERROR

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AAUR - Warning: Agent image hash ERROR

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AAUR - Warning: Agent image hash ERROR log

AAUR - Warning: Agent image hash ERROR

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AAUR - Warning: Cannot get FLASH resource

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AAUR - Warning: Cannot get FLASH resource log

AAUR - Warning: Cannot get FLASH resource

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AAUR-Warning Cannot get FLASH resource

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AAUR-Warning Cannot get FLASH resource log

AAUR-Warning Cannot get FLASH resource

The system cannot get the flash resource.

Source	Severity
AUR	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AAUR - Warning Slave agent image check sum ERROR

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AAUR - Warning Slave agent image check sum ERROR log

AAUR - Warning Slave agent image check sum ERROR

Slave agent image check sum error.

Source	Severity
AUR	Serious

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AAUR - Warning: Slave agent image check sum ERROR

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AAUR - Warning: Slave agent image check sum ERROR log

AAUR - Warning: Slave agent image check sum ERROR

**Source    Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# AAUR - Warning: Slave agent image hash ERROR

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AAUR - Warning: Slave agent image hash ERROR log

AAUR - Warning: Slave agent image hash ERROR

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Access assignment distribution across stack failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Access assignment distribution across stack failed log

Access assignment distribution across stack failed

Unable to carry out the access assignment distribution across the stack.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Access assignment modifications not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Access assignment modifications not supported log

Access assignment modifications not supported

The system detected an internal error; The Specified modifier option is not supported.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent, or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Access assignment modification support limited

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Access assignment modification support limited log

Access assignment modification support limited

Access assignment entries under system control may be deleted but not modified. The same goes for templates.

Source	Severity
QoS	Serious

### Remedial action

Create a different access assignment entry with the wanted parameters.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Access assignment name contains unacceptable characters

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Access assignment name contains unacceptable characters log

Access assignment name contains unacceptable characters

Only printable characters are allowed.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Enter valid characters for the access element block label.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Access assignment name length outside of acceptable limits

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Access assignment name length outside of acceptable limits log

Access assignment name length outside of acceptable limits

The maximum length for the access assignment name is 16.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Enter an access assignment label within the limit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Access assignment name not acceptable - reserved

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Access assignment name not acceptable - reserved log

Access assignment name not acceptable - reserved

The label is reserved in the system.

Source	Severity
QoS	Serious

### Remedial action

Enter a different label.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Access assignment template still in use (siblings active)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Access assignment template still in use (siblings active) log

Access assignment template still in use (siblings active)

Cannot delete an access assignment entry if it has one or more active siblings in use.

Source	Severity
QoS	Serious

### Remedial action

Remove the sibling(s) first.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Access element block label contains unacceptable characters

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Access element block label contains unacceptable characters log

Access element block label contains unacceptable characters

Only printable characters are allowed.

Source	Severity
QoS	Serious

### Remedial action

Enter valid characters for the access element block label.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Access element block label length outside of acceptable limits

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Access element block label length outside of acceptable limits log

Access element block label length outside of acceptable limits

The maximum length for the access element block name is 16.

Source	Severity
QoS	Serious

### Remedial action

Enter a smaller access element block label.



# Access element cluster count ( cluster count ) exceeds limit ( cluster limit )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Access element cluster count ( cluster count ) exceeds limit ( cluster limit ) log

Access element cluster count ( cluster count ) exceeds limit ( cluster limit )

The cluster limit of the access element depends on the target hardware platform.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Check the documentation for the maximum number of access elements allowed.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Access element cluster count (%d) exceeds limit (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Access element cluster count (%d) exceeds limit (%d) log

Access element cluster count (%d) exceeds limit (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Access element cluster is referenced (addition prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Access element cluster is referenced (addition prohibited) log

Access element cluster is referenced (addition prohibited)

The access-list can not be modified if it is currently referenced (assigned).

Source	Severity
QoS	Serious

### Remedial action

Remove the referee before requesting any modifications.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Access element cluster is referenced (deletion prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Access element cluster is referenced (deletion prohibited) log

Access element cluster is referenced (deletion prohibited)

Access element can not be removed if it is currently referenced.

Source	Severity
QoS	Serious

### Remedial action

Remove the conflicting element first.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Access element distribution across stack failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Access element distribution across stack failed log

Access element distribution across stack failed

Unable to access the element distribution across the stack.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Access element modifications not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Access element modifications not supported log

Access element modifications not supported

The system detected an Internal error; The specified modifier option is not supported.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Access element name contains unacceptable characters

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Access element name contains unacceptable characters log

Access element name contains unacceptable characters

Only printable characters are allowed.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Enter valid characters for the access element's label.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Access element name length outside of acceptable limits

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Access element name length outside of acceptable limits log

Access element name length outside of acceptable limits

The maximum length for the access element name is 16.

Source	Severity
QoS	Serious

### Remedial action

Enter a smaller access element label.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Access element name not acceptable - reserved

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Access element name not acceptable - reserved log

Access element name not acceptable - reserved

The label is reserved in the system.

Source	Severity
QoS	Serious

### Remedial action

Enter a different label.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Accessing information that has not been initialized.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Accessing information that has not been initialized. log

Accessing information that has not been initialized.

**Source**      **Severity**

PLATFORM

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Access not granted. Contact  
www.extremenetworks.com to update  
Software license.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Access not granted. Contact www.extremenetworks.com to update Software license. log

Access not granted. Contact www.extremenetworks.com to update Software license.

**Source   Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Action not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Action not supported log

Action not supported

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ADAC: ADAC of IP Phones not functional

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ADAC: ADAC of IP Phones not functional log

ADAC: ADAC of IP Phones not functional

**Source**   **Severity**

ADAC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ADAC: ADAC of Nortel IP Phones not functional

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ADAC: ADAC of Nortel IP Phones not functional log

ADAC: ADAC of Nortel IP Phones not functional

ADAC is not working.

Source	Severity
ADAC	Serious

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# ADAC: Error applying main %s configuration

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ADAC: Error applying main %s configuration log

ADAC: Error applying main %s configuration

**Source**   **Severity**

ADAC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ADAC Error applying main VLAN QoS configuration

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ADAC Error applying main VLAN QoS configuration log

ADAC Error applying main VLAN QoS configuration

The system detected an error while applying QoS or VLAN global configuration.

Source	Severity
ADAC	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ADAC: Error applying %s configuration for unit/port: %d/%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ADAC: Error applying %s configuration for unit/port: %d/%d log

ADAC: Error applying %s configuration for unit/port: %d/%d

**Source**   **Severity**

ADAC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ADAC Error applying VLAN QoS configuration for unit port unit# port#

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ADAC Error applying VLAN QoS configuration for unit port unit# port# log

ADAC Error applying VLAN QoS configuration for unit port unit# port#

The system detected an error while applying QoS or VLAN configuration from unit or port.

Source	Severity
--------	----------

ADAC	Information
------	-------------

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ADAC Error forcing administrative state to disable enable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ADAC Error forcing administrative state to disable enable log

ADAC Error forcing administrative state to disable enable

The system detected an error when forcing the administrative state to disable/enable.

Source	Severity
ADAC	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ADAC: Error forcing administrative state to %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ADAC: Error forcing administrative state to %s log

ADAC: Error forcing administrative state to %s

**Source**   **Severity**

ADAC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ADAC: Error registering CDT handlers

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ADAC: Error registering CDT handlers log

ADAC: Error registering CDT handlers

The system detected an error when registering the CDT handlers.

Source	Severity
--------	----------

ADAC	Serious
------	---------

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ADAC: Error removing main %s configuration

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ADAC: Error removing main %s configuration log

ADAC: Error removing main %s configuration

**Source**   **Severity**

ADAC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# ADAC Error removing main VLAN QoS configuration

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ADAC Error removing main VLAN QoS configuration log

ADAC Error removing main VLAN QoS configuration

The system detected an error while removing QoS or VLAN global configuration.

Source	Severity
ADAC	Information

### Remedial action

No action required.



# ADAC: Error removing %s configuration for unit/port: %d/%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ADAC: Error removing %s configuration for unit/port: %d/%d log

ADAC: Error removing %s configuration for unit/port: %d/%d

**Source**   **Severity**

ADAC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ADAC Error removing VLAN QoS configuration for unit port unit# port#

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ADAC Error removing VLAN QoS configuration for unit port unit# port# log

ADAC Error removing VLAN QoS configuration for unit port unit# port#

The system detected an error while removing QoS or VLAN configuration to unit or port.

Source	Severity
ADAC	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ADAC Forced administrative state to disable enable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ADAC Forced administrative state to disable enable log

ADAC Forced administrative state to disable enable

The administrative state of ADAC feature is forced to disable/enable.

Source	Severity
ADAC	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ADAC: Forced administrative state to %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ADAC: Forced administrative state to %s log

ADAC: Forced administrative state to %s

**Source**   **Severity**

ADAC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ADAC System operationally disable enable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ADAC System operationally disable enable log

ADAC System operationally disable enable

The system is operating with ADAC as disabled/enabled.

Source	Severity
ADAC	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ADAC: System operationally %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ADAC: System operationally %s log

ADAC: System operationally %s

**Source**   **Severity**

ADAC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Additional metering data needed for specified metering mode

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Additional metering data needed for specified metering mode log

Additional metering data needed for specified metering mode

**Source   Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





address add was aborted, (an event callback instructed the driver to remove the address)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## address add was aborted, (an event callback instructed the driver to remove the address) log

address add was aborted, (an event callback instructed the driver to remove the address)

**Source**   **Severity**  
CDT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



address add was aborted, (the  
addresswas being inserted into an  
inactive FID, code=%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## address add was aborted, (the addresswas being inserted into an inactive FID, code=%d) log

address add was aborted, (the addresswas being inserted into an inactive FID, code=%d)

**Source   Severity**

CDT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# After agent change message became invalid:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## After agent change message became invalid: log

After agent change message became invalid:

After upgrade/intermediary downgrade, if the Application id or message id are out of range, the message is replaced in order to avoid DAE.

Source	Severity
System Logging	Serious/Critical

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# After agent change message became invalid:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## After agent change message became invalid: log

After agent change message became invalid:

**Source**   **Severity**

SLOG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Agent configuration distribution across stack failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Agent configuration distribution across stack failed log

Agent configuration distribution across stack failed

Unable to commit changes across the stack.

Source	Severity
QoS	Information

### Remedial action

Unable to commit changes across the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



!Alert! file=%s line=%d msg=%s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## !Alert! file=%s line=%d msg=%s log

!Alert! file=%s line=%d msg=%s

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Allowed connection attempt from user :

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Allowed connection attempt from user : log

Allowed connection attempt from user :

RADIUS: allowed connection attempt for the user starting with the given name.

Source	Severity
RADIUS	Information

### Remedial action

No action required.



# Another BU tried to join the stack. Unit ignored

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Another BU tried to join the stack. Unit ignored log

Another BU tried to join the stack. Unit ignored

A switch having BU switch selected was added to an existing stack.

Source	Severity
Stack Manager	Information

### Remedial action

Unset BU switch from the new added unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





An SPBM instance must be configured before the requested operation can proceed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## An SPBM instance must be configured before the requested operation can proceed log

An SPBM instance must be configured before the requested operation can proceed

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# application-name failed DB-exchange stack failed to form

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## application-name failed DB-exchange stack failed to form log

application-name failed DB-exchange stack failed to form

The stack did not form, as the application <application-name> did not exchange its database successfully.

Source	Severity
Stack Manager	Critical

### Remedial action

Reboot the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# application\_name failed DB-exchange stack formation delayed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## application\_name failed DB-exchange stack formation delayed log

application\_name failed DB-exchange stack formation delayed

The application name in the Stack Monitor failed the DB exchange for three times simultaneously.

Source	Severity
Stack Monitor	Information

### Remedial action

No action required. The Stack Manager will wait for 3 minutes after a DB-exchange failure and then restart the stack formation process. The logs are saved to NVRAM for future reference.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# application-name failed DB-exchange stack formation delayed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## application-name failed DB-exchange stack formation delayed log

application-name failed DB-exchange stack formation delayed

The application <application-name> failed to exchange its database.

Source	Severity
Stack Manager	Serious

### Remedial action

Reboot the unit if it is unsuccessful in joining the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# App-Telemetry: Configuration file missing or cannot be read. No config file will be used

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## App-Telemetry: Configuration file missing or cannot be read. No config file will be used log

App-Telemetry: Configuration file missing or cannot be read. No config file will be used

Both policy files, "apptel\_user.pol" and "apptel\_default.pol" are missing.

Source	Severity
APPTEL	Critical

### Remedial action

Download a fresh copy of the currently installed image on the switch/stack, so the default policy file would be restored.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# App-Telemetry: Default configuration file is missing

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## App-Telemetry: Default configuration file is missing log

App-Telemetry: Default configuration file is missing

The default policy file, 'apptel\_default.pol' is missing.

Source	Severity
APPTTEL	Critical

### Remedial action

Download a fresh copy of the currently installed image on the switch/stack, so the default policy file would be restored.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# App-Telemetry: Default configuration file loaded

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## App-Telemetry: Default configuration file loaded log

App-Telemetry: Default configuration file loaded

The user-defined policy file, 'apptel\_user.pol', is missing.

Source	Severity
--------	----------

APPTTEL	Serious
---------	---------

### Remedial action

Load the user-defined policy file that best suits your needs.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# App-Telemetry: Maximum number of entries has been reached

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## App-Telemetry: Maximum number of entries has been reached log

App-Telemetry: Maximum number of entries has been reached

The policy file has more than the maximum number of entries allowed per ACL.

Source	Severity
--------	----------

APPTel	Critical
--------	----------

### Remedial action

Adjust the number of entries in the user-defined policy file and then try to reload it.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# App-Telemetry: Parse error detected in policy file at line

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## App-Telemetry: Parse error detected in policy file at line log

App-Telemetry: Parse error detected in policy file at line

The policy file parser encounters a syntax error. Will display the specific error encountered at the current line.

Source	Severity
--------	----------

APPTel	Critical
--------	----------

### Remedial action

Disable App-Telemetry and then load the default policy file. Correct the error in the customer defined policy file and the reload it.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# App-Telemetry: Policy file is empty

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## App-Telemetry: Policy file is empty log

App-Telemetry: Policy file is empty

The policy file has no entries.

Source	Severity
APPTEL	Serious

### Remedial action

Load the default policy file.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# App-Telemetry: User configuration file loaded

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## App-Telemetry: User configuration file loaded log

App-Telemetry: User configuration file loaded

The user-defined policy file, 'apptel\_user.pol', is found.

Source	Severity
APPTTEL	Information

### Remedial action

No action required.



# ASCFG - Error: Failed to get file from TFTP

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCFG - Error: Failed to get file from TFTP log

ASCFG - Error: Failed to get file from TFTP

The system failed to get file from TFTP.

Source	Severity
Boot Ascii	Information

### Remedial action

None



# ASCFG - Error: Failed to get file from USB

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCFG - Error: Failed to get file from USB log

ASCFG - Error: Failed to get file from USB

The system failed to get file from USB.

Source	Severity
Boot Ascii	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ASCFG - Error: Failed to get script buffer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCFG - Error: Failed to get script buffer log

ASCFG - Error: Failed to get script buffer

The system failed to get the script buffer.

Source	Severity
Boot Ascii	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ASCFG - Error: Failed to get the flash resource

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCFG - Error: Failed to get the flash resource log

ASCFG - Error: Failed to get the flash resource

The system failed to get the flash resource.

Source	Severity
Boot Ascii	Information

### Remedial action

None



# ASCFG - Error: Failed to give sem semBAutoSaveAscDone

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCFG - Error: Failed to give sem semBAutoSaveAscDone log

ASCFG - Error: Failed to give sem semBAutoSaveAscDone

The system failed to give application semaphore.

Source	Severity
Boot Ascii	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# ASCFG - Error: Failed to init ascii file system

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCFG - Error: Failed to init ascii file system log

ASCFG - Error: Failed to init ascii file system

The system failed to init ascii file system.

Source	Severity
Boot Ascii	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ASCFG - Error: Failed to malloc memory for ram drive

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCFG - Error: Failed to malloc memory for ram drive log

ASCFG - Error: Failed to malloc memory for ram drive

Failed to allocate memory for Ascii ram drive.

Source	Severity
Boot Ascii	Information

### Remedial action

None



# ASCFG - Error: Failed to open ascii file system

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCFG - Error: Failed to open ascii file system log

ASCFG - Error: Failed to open ascii file system

The system failed to open ascii file system.

Source	Severity
Boot Ascii	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ASCFG - Error: Failed to open record file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCFG - Error: Failed to open record file log

ASCFG - Error: Failed to open record file

The system failed to open record file.

Source	Severity
Boot Ascii	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ASCFG - Error: Failed to open script file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCFG - Error: Failed to open script file log

ASCFG - Error: Failed to open script file

The system failed to open script file.

Source	Severity
Boot Ascii	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ASCFG - Error: Failed to read record file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCFG - Error: Failed to read record file log

ASCFG - Error: Failed to read record file

The system failed to read record file.

Source	Severity
Boot Ascii	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ASCFG - Error: Failed to read script file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCFG - Error: Failed to read script file log

ASCFG - Error: Failed to read script file

The system failed to read the script file.

Source	Severity
Boot Ascii	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ASCFG - Error: Failed to release the flash resource

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCFG - Error: Failed to release the flash resource log

ASCFG - Error: Failed to release the flash resource

The system failed to release the flash resource.

Source	Severity
Boot Ascii	Information

### Remedial action

None





# ASCFG - Error: Failed to run script file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCFG - Error: Failed to run script file log

ASCFG - Error: Failed to run script file

The system failed to run the script file.

Source	Severity
Boot Ascii	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ASCFG - Error: Failed to save ascii file system

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCFG - Error: Failed to save ascii file system log

ASCFG - Error: Failed to save ascii file system

The system failed to save ascii file system.

Source	Severity
Boot Ascii	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ASCFG - Error: Failed to send msg to ascfg queue

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCFG - Error: Failed to send msg to ascfg queue log

ASCFG - Error: Failed to send msg to ascfg queue

The system failed to send message to the ascfg queue.

Source	Severity
Boot Ascii	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ASCFG - Error: Failed to send notice to NBU

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCFG - Error: Failed to send notice to NBU log

ASCFG - Error: Failed to send notice to NBU

The system failed to send notice to NBU.

Source	Severity
Boot Ascii	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ASCFG - Error: Failed to take sem semBAutoSaveAscDone

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCFG - Error: Failed to take sem semBAutoSaveAscDone log

ASCFG - Error: Failed to take sem semBAutoSaveAscDone

The system failed to take application semaphore.

Source	Severity
Boot Ascii	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ASCFG - Error: Failed to update the status

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCFG - Error: Failed to update the status log

ASCFG - Error: Failed to update the status

The system failed to update the status.

Source	Severity
Boot Ascii	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ASCFG - Error: Failed to write record file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCFG - Error: Failed to write record file log

ASCFG - Error: Failed to write record file

The system failed to write record file.

Source	Severity
Boot Ascii	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ASCFG - Error: Failed to write script file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCFG - Error: Failed to write script file log

ASCFG - Error: Failed to write script file

The system failed to write script file.

Source	Severity
Boot Ascii	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# ASCFG - Error: File larger max file size

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCFG - Error: File larger max file size log

ASCFG - Error: File larger max file size

The file size is larger than the maximum size.

Source	Severity
Boot Ascii	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ASCFG - Error: Invalid file system, Init

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCFG - Error: Invalid file system, Init log

ASCFG - Error: Invalid file system, Init

Invalid file system. Initialize the file system.

Source	Severity
Boot Ascii	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ASCFG - Error: Invalid file system, Init

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCFG - Error: Invalid file system, Init log

ASCFG - Error: Invalid file system, Init

**Source**   **Severity**

ASCFG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ASCFG - Error: Invalid script entry 0

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCFG - Error: Invalid script entry 0 log

ASCFG - Error: Invalid script entry 0

Script table entry 0 is invalid.

Source	Severity
Boot Ascii	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ASCFG - Error: Invalid script entry 1

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCFG - Error: Invalid script entry 1 log

ASCFG - Error: Invalid script entry 1

Script table entry 1 is invalid.

Source	Severity
Boot Ascii	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ASCFG - Info: Run Boot Script Successfully

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCFG - Info: Run Boot Script Successfully log

ASCFG - Info: Run Boot Script Successfully

The script run successfully.

Source	Severity
Boot Ascii	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ASCII failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCII failed log

ASCII failed

The ASCII configuration file contains syntax errors or inconsistent/incorrect configuration data.

Source	Severity
ACG	Information

### Remedial action

Attempt to load the ASCII configuration file manually from a console and look for error messages.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ASCII finished successfully

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCII finished successfully log

ASCII finished successfully

The ASCII configuration file is successfully loaded and processed during manual configuration.

Source	Severity
ACG	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# ASCII finished successfully at load on boot

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCII finished successfully at load on boot log

ASCII finished successfully at load on boot

The ASCII configuration file is successfully loaded and processed at boot time.

Source	Severity
ACG	Information

### Remedial action

No action required.



# ASCII transfer failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCII transfer failed log

ASCII transfer failed

The ASCII configuration file could not be transferred from the TFTP server (or USB port on the switch) during manual configuration.

Source	Severity
ACG	Information

### Remedial action

Check if the TFTP server is accessible.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ASCII transfer failed at load on boot

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCII transfer failed at load on boot log

ASCII transfer failed at load on boot

The ASCII configuration file could not be transferred from the TFTP server (or USB port on the switch) at boot time.

Source	Severity
ACG	Information

### Remedial action

Check if the TFTP server is accessible.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ASCII transfer OK

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCII transfer OK log

ASCII transfer OK

The ASCII configuration file was successfully transferred from the TFTP server (or USB port on the switch) during manual configuration.

Source	Severity
ACG	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ASCII transfer OK at load on boot

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASCII transfer OK at load on boot log

ASCII transfer OK at load on boot

ASCII config file was transferred successfully from TFTP server (or USB port on ERS45xx and ERS5xxx) at boot time.

Source	Severity
ACG	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Assertion Failure in bcm\_l3\_hit\_check- l3sw ip=%#x,l3hw ip=%#x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Assertion Failure in bcm\_l3\_hit\_check- l3sw ip=%#x,l3hw ip=%#x log

Assertion Failure in bcm\_l3\_hit\_check- l3sw ip=%#x,l3hw ip=%#x

Inconsistency between software and hardware IP values at some index. The software IP address and hardware IP address are displayed in the log.

Source	Severity
IPv4 Routing	Serious

### Remedial action

Do not connect a host for which you have a host route configured directly to the switch.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ASTP debug: %d - %d - %x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASTP debug: %d - %d - %x log

ASTP debug: %d - %d - %x

**Source**   **Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ASTP error: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASTP error: %d - %d - %d log

ASTP error: %d - %d - %d

**Source**   **Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





ASTP state: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ASTP state: %d - %d - %d log

ASTP state: %d - %d - %d

**Source**   **Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Attempt to create an element that already exists (prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Attempt to create an element that already exists (prohibited) log

Attempt to create an element that already exists (prohibited)

An entry with the same characteristics already exists in the system.

Source	Severity
QoS	Serious

### Remedial action

Remove the existing entry if necessary.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Attempt to delete modify non-existing element (prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Attempt to delete modify non-existing element (prohibited) log

Attempt to delete modify non-existing element (prohibited)

You cannot remove or modify an inexistent element.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

If this is a modification attempt create a new element.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Attempt to delete/modify non-existing element (prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Attempt to delete/modify non-existing element (prohibited) log

Attempt to delete/modify non-existing element (prohibited)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Attempt to delete referenced NSNA filter set (prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Attempt to delete referenced NSNA filter set (prohibited) log

Attempt to delete referenced NSNA filter set (prohibited)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Attempt to delete referenced UBP filter set (prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Attempt to delete referenced UBP filter set (prohibited) log

Attempt to delete referenced UBP filter set (prohibited)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Attempt to manipulate system-owned interface (prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Attempt to manipulate system-owned interface (prohibited) log

Attempt to manipulate system-owned interface (prohibited)

Modification of the system-owned interfaces is prohibited.

Source	Severity
QoS	Serious

### Remedial action

Enter a different interface index.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Attempt to manipulate user policy data rejected (disabled)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Attempt to manipulate user policy data rejected (disabled) log

Attempt to manipulate user policy data rejected (disabled)

All user based policy data modifications are prohibited when the UPB support is disabled.

Source	Severity
QoS	Serious

### Remedial action

Enable the UPB support.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Audit commit failed (cannot erase flash sector(s))

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Audit commit failed (cannot erase flash sector(s)) log

Audit commit failed (cannot erase flash sector(s))

**Source**      **Severity**

CLI Audit

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Audit commit failed (cannot take audit semaphore)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Audit commit failed (cannot take audit semaphore) log

Audit commit failed (cannot take audit semaphore)

**Source**      **Severity**

CLI Audit

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Audit commit failed (cannot take flash semaphore)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Audit commit failed (cannot take flash semaphore) log

Audit commit failed (cannot take flash semaphore)

**Source**      **Severity**

CLI Audit

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Audit commit failed (cannot write flash sector(s))

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Audit commit failed (cannot write flash sector(s)) log

Audit commit failed (cannot write flash sector(s))

**Source**      **Severity**

CLI Audit

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Audit data initialized (bad checksum)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Audit data initialized (bad checksum) log

Audit data initialized (bad checksum)

The audit data is corrupt.

Source	Severity
Audit	Serious

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Audit data initialized (bad magic number)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Audit data initialized (bad magic number) log

Audit data initialized (bad magic number)

The audit data is corrupt.

Source	Severity
Audit	Serious

### Remedial action

No action required.



# Audit log disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Audit log disabled log

Audit log disabled

Source	Severity
--------	----------

CLI Audit	
-----------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Audit log enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Audit log enabled log

Audit log enabled

**Source**      **Severity**

CLI Audit

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Audit message add failed (audit header too long)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Audit message add failed (audit header too long) log

Audit message add failed (audit header too long)

**Source**      **Severity**

CLI Audit

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Audit message send failed (cannot resend data to remote syslog server)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Audit message send failed (cannot resend data to remote syslog server) log

Audit message send failed (cannot resend data to remote syslog server)

Source	Severity
CLI Audit	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Audit message send failed (cannot send data to remote syslog server)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Audit message send failed (cannot send data to remote syslog server) log

Audit message send failed (cannot send data to remote syslog server)

**Source**      **Severity**

CLI Audit

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Error: Checksum Error. Could not restore the old config. Using the default cfg

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Error: Checksum Error. Could not restore the old config. Using the default cfg log

AUR - Error: Checksum Error. Could not restore the old config. Using the default cfg

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Error: Failed process MAC

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Error: Failed process MAC log

AUR - Error: Failed process MAC

**Source    Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Error: Failed to cancel delay watchdog timer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Error: Failed to cancel delay watchdog timer log

AUR - Error: Failed to cancel delay watchdog timer

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Error: Failed to cancel process watchdog timer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Error: Failed to cancel process watchdog timer log

AUR - Error: Failed to cancel process watchdog timer

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Error: Failed to cancel watchdog timer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Error: Failed to cancel watchdog timer log

AUR - Error: Failed to cancel watchdog timer

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# AUR - Error: Failed to create a new MAC record

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Error: Failed to create a new MAC record log

AUR - Error: Failed to create a new MAC record

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Error: Failed to create message queue

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Error: Failed to create message queue log

AUR - Error: Failed to create message queue

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Error: Failed to create watchdog timer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Error: Failed to create watchdog timer log

AUR - Error: Failed to create watchdog timer

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Error: Failed to disable AUR

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Error: Failed to disable AUR log

AUR - Error: Failed to disable AUR

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Error: Failed to enable AUR

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Error: Failed to enable AUR log

AUR - Error: Failed to enable AUR

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Error: Failed to get an imc buffer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Error: Failed to get an imc buffer log

AUR - Error: Failed to get an imc buffer

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Error: Failed to save data to NBU

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Error: Failed to save data to NBU log

AUR - Error: Failed to save data to NBU

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Error: Failed to send msg to IMC

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Error: Failed to send msg to IMC log

AUR - Error: Failed to send msg to IMC

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# AUR - Error: Failed to spawn cfgso task

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Error: Failed to spawn cfgso task log

AUR - Error: Failed to spawn cfgso task

**Source    Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Error: Failed to start delay watchdog timer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Error: Failed to start delay watchdog timer log

AUR - Error: Failed to start delay watchdog timer

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Error: Failed to start process watchdog timer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Error: Failed to start process watchdog timer log

AUR - Error: Failed to start process watchdog timer

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Error: Failed to start watchdog timer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Error: Failed to start watchdog timer log

AUR - Error: Failed to start watchdog timer

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Error: file not close

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Error: file not close log

AUR - Error: file not close

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Error: File not open

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Error: File not open log

AUR - Error: File not open

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Error: File not read

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Error: File not read log

AUR - Error: File not read

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Error: File not write

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Error: File not write log

AUR - Error: File not write

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# AUR - Error: Invalid value

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Error: Invalid value log

AUR - Error: Invalid value

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Error: Next BU ID is 0

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Error: Next BU ID is 0 log

AUR - Error: Next BU ID is 0

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR-Info AUR disable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR-Info AUR disable log

AUR-Info AUR disable

AUR is disabled.

Source	Severity
AUR	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR-Info AUR enable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR-Info AUR enable log

AUR-Info AUR enable

AUR is enabled.

Source	Severity
AUR	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Info: AUR Restored to default

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Info: AUR Restored to default log

AUR - Info: AUR Restored to default

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR-Info AUR Restored to default

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR-Info AUR Restored to default log

AUR-Info AUR Restored to default

AUR is restored to default.

Source	Severity
AUR	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Info: Base Unit refused configuration transfer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Info: Base Unit refused configuration transfer log

AUR - Info: Base Unit refused configuration transfer

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Info: Busy - Wait for the next sync

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Info: Busy - Wait for the next sync log

AUR - Info: Busy - Wait for the next sync

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# AUR - Info: Configuration transfer finished

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Info: Configuration transfer finished log

AUR - Info: Configuration transfer finished

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Info: Configuration transfer from Unit %d finished

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Info: Configuration transfer from Unit %d finished log

AUR - Info: Configuration transfer from Unit %d finished

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Info: Configuration transfer to Base Unit finished

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Info: Configuration transfer to Base Unit finished log

AUR - Info: Configuration transfer to Base Unit finished

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Info: Configuration transfer to Unit %d finished

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Info: Configuration transfer to Unit %d finished log

AUR - Info: Configuration transfer to Unit %d finished

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Info: Do MIRROR

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Info: Do MIRROR log

AUR - Info: Do MIRROR

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Info: Do Restore

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Info: Do Restore log

AUR - Info: Do Restore

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Info: New unit has different HW config, Using cfg from the new unit

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Info: New unit has different HW config, Using cfg from the new unit log

AUR - Info: New unit has different HW config, Using cfg from the new unit

**Source**   **Severity**  
AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR-Info New unit has different HW config Using cfg from the new unit

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR-Info New unit has different HW config Using cfg from the new unit log

AUR-Info New unit has different HW config Using cfg from the new unit

The new unit has a different HW configuration.

Source	Severity
--------	----------

AUR	Information
-----	-------------

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# AUR - Info: No VALID\_INACTIVE - do MIRROR

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Info: No VALID\_INACTIVE - do MIRROR log

AUR - Info: No VALID\_INACTIVE - do MIRROR

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Info: process flash sync

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Info: process flash sync log

AUR - Info: process flash sync

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Info: Receive request for configuration transfer. Start transfer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Info: Receive request for configuration transfer. Start transfer log

AUR - Info: Receive request for configuration transfer. Start transfer

Source	Severity
AUR	

Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Info: Receive request for configuration transfer. Unable to start transfer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Info: Receive request for configuration transfer. Unable to start transfer log

AUR - Info: Receive request for configuration transfer. Unable to start transfer

Source	Severity
AUR	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Info: same MAC - do MIRROR

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Info: same MAC - do MIRROR log

AUR - Info: same MAC - do MIRROR

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Info: Send configuration request to restore Base Unit

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Info: Send configuration request to restore Base Unit log

AUR - Info: Send configuration request to restore Base Unit

**Source   Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Info: Send configuration to restore Unit %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Info: Send configuration to restore Unit %d log

AUR - Info: Send configuration to restore Unit %d

**Source    Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Info: sending MAC to slave

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Info: sending MAC to slave log

AUR - Info: sending MAC to slave

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# AUR - Info: Slave Unit %d refused configuration transfer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Info: Slave Unit %d refused configuration transfer log

AUR - Info: Slave Unit %d refused configuration transfer

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Warning: Cannot get FLASH resource

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Warning: Cannot get FLASH resource log

AUR - Warning: Cannot get FLASH resource

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Warning: Configuration check sum ERROR

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Warning: Configuration check sum ERROR log

AUR - Warning: Configuration check sum ERROR

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Warning: Delay Watchdog timer expire

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Warning: Delay Watchdog timer expire log

AUR - Warning: Delay Watchdog timer expire

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Warning: Invalid Msg Id

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Warning: Invalid Msg Id log

AUR - Warning: Invalid Msg Id

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Warning: No matched MAC

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Warning: No matched MAC log

AUR - Warning: No matched MAC

**Source   Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Warning: Process Watchdog timer expire

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Warning: Process Watchdog timer expire log

AUR - Warning: Process Watchdog timer expire

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AUR - Warning: Watchdog timer expire

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR - Warning: Watchdog timer expire log

AUR - Warning: Watchdog timer expire

**Source    Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Authentication Failure Trap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Authentication Failure Trap log

Authentication Failure Trap

Authentication Failure.

Source	Severity
SNMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# AutoQoS mode enable failure - inadequate resources

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AutoQoS mode enable failure - inadequate resources log

AutoQoS mode enable failure - inadequate resources

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Auto-renew for CA %s failed with message: %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Auto-renew for CA %s failed with message: %s log

Auto-renew for CA %s failed with message: %s

**Source**      **Severity**

DIGICERT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Auto-renew for CA %s was successful

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Auto-renew for CA %s was successful log

Auto-renew for CA %s was successful

**Source**      **Severity**

DIGICERT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Backup configuration block %d in use

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Backup configuration block %d in use log

Backup configuration block %d in use

The back up configuration is in use.

Source	Severity
MCFG	Information

### Remedial action

No action required.



# Backup Configuration files are corrupted. Restored to default

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Backup Configuration files are corrupted. Restored to default log

Backup Configuration files are corrupted. Restored to default

**Source   Severity**

MCFG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Backup configuration restored from primary configuration block %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Backup configuration restored from primary configuration block %d log

Backup configuration restored from primary configuration block %d

Copy the back up primary configuration to the backup configuration.

Source	Severity
MCFG	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Backup configuration updated for next active configuration block %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Backup configuration updated for next active configuration block %d log

Backup configuration updated for next active configuration block %d

The back up configuration will be used for the next active configuration.

Source	Severity
--------	----------

MCFG	Information
------	-------------

### Remedial action

No action required.





# Backup Configuration Version is updated

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Backup Configuration Version is updated log

Backup Configuration Version is updated

The back up configuration version is updated.

Source	Severity
config	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Bad Param %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Bad Param %d log

Bad Param %d

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Base action distribution across stack failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Base action distribution across stack failed log

Base action distribution across stack failed

Unable to commit base action distribution across the stack.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Base action entry referenced by clfr block (deletion prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Base action entry referenced by clfr block (deletion prohibited) log

Base action entry referenced by clfr block (deletion prohibited)

Cannot delete a base action if it's referenced by a classifier block.

Source	Severity
QoS	Serious

### Remedial action

Remove the classifier block first.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Base action entry referenced by meter (deletion prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Base action entry referenced by meter (deletion prohibited) log

Base action entry referenced by meter (deletion prohibited)

Cannot delete a base action if it's referenced in a meter.

Source	Severity
QoS	Serious

### Remedial action

Remove the meter first.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Base action entry referenced by policy (deletion prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Base action entry referenced by policy (deletion prohibited) log

Base action entry referenced by policy (deletion prohibited)

Cannot delete a base action if it's referenced by a policy.

Source	Severity
QoS	Serious

### Remedial action

Remove the policy first.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Base action extension identifier invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Base action extension identifier invalid log

Base action extension identifier invalid

The specified base action extension identifier is invalid

Source	Severity
QoS	Serious

### Remedial action

Enter a valid base action extension identifier.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Base action modification prohibited due to action usage

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Base action modification prohibited due to action usage log

Base action modification prohibited due to action usage

Cannot modify a base action if it's in use.

Source	Severity
QoS	Serious

### Remedial action

Remove the QoS entries that are using the base action first.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Base action modifications not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Base action modifications not supported log

Base action modifications not supported

The system detected an internal error; The specified modifier option is not supported.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent, or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Base requesting re-discovery, this unit becoming base

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Base requesting re-discovery, this unit becoming base log

Base requesting re-discovery, this unit becoming base

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Base unit has loopback port mode %s and the current unit %s. Unit reconfigured and rebooted

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Base unit has loopback port mode %s and the current unit %s. Unit reconfigured and rebooted log

Base unit has loopback port mode %s and the current unit %s. Unit reconfigured and rebooted

The loopback port mode of the current unit is different than the BU's. Current unit will reconfigure and will be rebooted. Loopback port modes are: stack, rear, MDA, none.

Source	Severity
Stack Manager	Serious

### Remedial action

No action required.



# BaySec cdtInit 0x%0x 0x%0x 0x%0x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## BaySec cdtInit 0x%0x 0x%0x 0x%0x log

BaySec cdtInit 0x%0x 0x%0x 0x%0x

Source	Severity
--------	----------

Bay Secure	
------------	--

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# BaySec cdtIntruder 0x%0x 0x%0x 0x%0x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## BaySec cdtIntruder 0x%0x 0x%0x 0x%0x log

BaySec cdtIntruder 0x%0x 0x%0x 0x%0x

**Source**      **Severity**

Bay Secure

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# BaySec cdtMigrate 0x%0x 0x%0x 0x%0x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## BaySec cdtMigrate 0x%0x 0x%0x 0x%0x log

BaySec cdtMigrate 0x%0x 0x%0x 0x%0x

Source	Severity
--------	----------

Bay Secure	
------------	--

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



BaySec cdtNewMac 0x%0x 0x%0x  
0x%0x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## BaySec cdtNewMac 0x%0x 0x%0x 0x%0x log

BaySec cdtNewMac 0x%0x 0x%0x 0x%0x

**Source**      **Severity**

Bay Secure

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# BaySec Exceeded number MAC addresses on unit# port#

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## BaySec Exceeded number MAC addresses on unit# port# log

BaySec Exceeded number MAC addresses on unit# port#

This message appears when the system is trying to set too many security roles on a port.

Source	Severity
Bay Secure	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# BaySec IMC cmd error %0x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## BaySec IMC cmd error %0x log

BaySec IMC cmd error %0x

Source	Severity
--------	----------

Bay Secure	
------------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# BaySec msgQ error: 0x%x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## BaySec msgQ error: 0x%x log

BaySec msgQ error: 0x%x

Source	Severity
--------	----------

Bay Secure	
------------	--

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# BaySec Not enough resource on port port# . Check QOS cfg

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## BaySec Not enough resource on port port# . Check QOS cfg log

BaySec Not enough resource on port port# . Check QOS cfg

The system detected an error when reserving the policy on port. (This is generated by an error in creating the Filter Manager database information for a policy and installing that policy to the hardware)

Source	Severity
Bay Secure	Serious

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Bay Secure:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Bay Secure: log

Bay Secure:

Source	Severity
--------	----------

Bay Secure	
------------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Bay Secure: add

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Bay Secure: add log

Bay Secure: add

Source	Severity
--------	----------

Bay Secure	
------------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Bay Secure: current=%d localPortMacNumber=%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Bay Secure: current=%d localPortMacNumber=%d log

Bay Secure: current=%d localPortMacNumber=%d

Source	Severity
--------	----------

Bay Secure	
------------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Bay Secure: del

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Bay Secure: del log

Bay Secure: del

Source	Severity
--------	----------

Bay Secure	
------------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Bay Secure: del (entry)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Bay Secure: del (entry) log

Bay Secure: del (entry)

**Source**      **Severity**

Bay Secure

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Bay Secure: del(LINK-DOWN)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Bay Secure: del(LINK-DOWN) log

Bay Secure: del(LINK-DOWN)

Source	Severity
--------	----------

Bay Secure	
------------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Bay Secure: error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Bay Secure: error log

Bay Secure: error

Source	Severity
--------	----------

Bay Secure	
------------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Bay Secure error line line# # of octets read from NVRAM

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Bay Secure error line line# # of octets read from NVRAM log

Bay Secure error line line# # of octets read from NVRAM

The system is facing problem in reading the data saved in the NVRAM.

Source	Severity
Bay Secure	Serious

### Remedial action

Activate the default configuration.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Bay Secure: Exceeded %d per-port MAC addresses

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Bay Secure: Exceeded %d per-port MAC addresses log

Bay Secure: Exceeded %d per-port MAC addresses

**Source**      **Severity**

Bay Secure

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Bay Secure: Exceeded %d per-trunk MAC addresses on trunk %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Bay Secure: Exceeded %d per-trunk MAC addresses on trunk %d log

Bay Secure: Exceeded %d per-trunk MAC addresses on trunk %d

This notification is generated after successfully saving the DHCP snooping binding table to a SFTP server external file.

Source	Severity
DHCP Snoop	Warning/Information

### Remedial action

No action required.



# Bay Secure Exceeded number per-port MAC addresses on port unit# port#

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Bay Secure Exceeded number per-port MAC addresses on port unit# port# log

Bay Secure Exceeded number per-port MAC addresses on port unit# port#

The maximum number of MAC addresses that can be learned on a port is reached.

Source	Severity
Bay Secure	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Bay Secure intruder

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Bay Secure intruder log

Bay Secure intruder

The system detected an intruder.

Source	Severity
Bay Secure	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Bay Secure intruder MAC

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Bay Secure intruder MAC log

Bay Secure intruder MAC

The system detected an intruder.

Source	Severity
Bay Secure	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Bay Secure MAC DA filtering not enough resources

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Bay Secure MAC DA filtering not enough resources log

Bay Secure MAC DA filtering not enough resources

The system detected an error when trying to add a MAC DA filtering address. (This is generated by an error in creating the Filter Manager database information for a policy and installing that policy to the hardware)

Source	Severity
Bay Secure	Serious

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Bay Secure: MAC DA filtering not enough resources

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Bay Secure: MAC DA filtering not enough resources log

Bay Secure: MAC DA filtering not enough resources

**Source**      **Severity**

Bay Secure

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Bay Secure per-port address deleted:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Bay Secure per-port address deleted: log

Bay Secure per-port address deleted:

Source	Severity
--------	----------

Bay Secure	
------------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Bay Secure per-port addresses deleted

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Bay Secure per-port addresses deleted log

Bay Secure per-port addresses deleted

An auto-learned address is deleted (This warning appears only on the BU or stand-alone switch).

Source	Severity
Bay Secure	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Bay Secure Policy Error error type line line# 0

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Bay Secure Policy Error error type line line# 0 log

Bay Secure Policy Error error type line line# 0

The system detected an error in getting or setting a policy.

Source	Severity
Bay Secure	Serious

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Bay Secure Policy Error %s line %u 0x%X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Bay Secure Policy Error %s line %u 0x%X log

Bay Secure Policy Error %s line %u 0x%X

Source	Severity
--------	----------

Bay Secure	
------------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Bay Secure Resource Error error# line line# resource ID

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Bay Secure Resource Error error# line line# resource ID log

Bay Secure Resource Error error# line line# resource ID

The system detected an error when operating with the task resource.

Source	Severity
Bay Secure	Critical

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Bay Secure Resource Error %s line %u 0x%X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Bay Secure Resource Error %s line %u 0x%X log

Bay Secure Resource Error %s line %u 0x%X

**Source**      **Severity**

Bay Secure

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Bay Secure %s line %u 0x%X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Bay Secure %s line %u 0x%X log

Bay Secure %s line %u 0x%X

**Source**      **Severity**

Bay Secure

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# BECOME\_TEMP\_BU event sent unit mask value appl mask value

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## BECOME\_TEMP\_BU event sent unit mask value appl mask value log

BECOME\_TEMP\_BU event sent unit mask value appl mask value

The unit on which this message is logged has become the temporary base unit.

Source	Severity
Stack Manager	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Boot: system boot status 0x%x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Boot: system boot status 0x%x log

Boot: system boot status 0x%x

Presents the state of all configs; ex: which config is active. The boot status is displayed in the log.

### Source

MCFG (Second INFO BLOCK)

### Severity

Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# BPDU received on port with BPDU-Filtering enabled.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## BPDU received on port with BPDU-Filtering enabled. log

BPDU received on port with BPDU-Filtering enabled.

BPDU received on port with BPDU-Filtering enabled.

Source	Severity
STP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



BPDU received on port with BPDU-Filtering enabled. Port %d has been disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## BPDU received on port with BPDU-Filtering enabled. Port %d has been disabled log

BPDU received on port with BPDU-Filtering enabled. Port %d has been disabled

Source	Severity
STP	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Broadcast block unit/port %d/%d level %u watermark %u

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Broadcast block unit/port %d/%d level %u watermark %u log

Broadcast block unit/port %d/%d level %u watermark %u

**Source    Severity**

SC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Broadcast over high watermark unit/port %d/%d level %u watermark %u

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Broadcast over high watermark unit/port %d/%d level %u watermark %u log

Broadcast over high watermark unit/port %d/%d level %u watermark %u

**Source**   **Severity**

SC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Broadcast still blocked unit/port %d/%d level %u watermark %u

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Broadcast still blocked unit/port %d/%d level %u watermark %u log

Broadcast still blocked unit/port %d/%d level %u watermark %u

**Source**   **Severity**

SC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





Broadcast still over low watermark  
unit/port %d/%d level %u watermark  
%u

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Broadcast still over low watermark unit/port %d/%d level %u watermark %u log

Broadcast still over low watermark unit/port %d/%d level %u watermark %u

Source	Severity
SC	

Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Broadcast unblock unit/port %d/%d level %u watermark %u

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Broadcast unblock unit/port %d/%d level %u watermark %u log

Broadcast unblock unit/port %d/%d level %u watermark %u

**Source**   **Severity**

SC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Broadcast under low watermark unit/port %d/%d level %u watermark %u

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Broadcast under low watermark unit/port %d/%d level %u watermark %u log

Broadcast under low watermark unit/port %d/%d level %u watermark %u

Source	Severity
SC	

Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Buffer configuration inconsistency detected (local buffer conf stack buffer conf )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Buffer configuration inconsistency detected (local buffer conf stack buffer conf ) log

Buffer configuration inconsistency detected (local buffer conf stack buffer conf )

The buffering configuration is not the same on all units in stack.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Buffer configuration inconsistency detected (local %d, stack %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Buffer configuration inconsistency detected (local %d, stack %d) log

Buffer configuration inconsistency detected (local %d, stack %d)

**Source**   **Severity**  
QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# BU was unable to send IMC for NBUs VLAN/Port configuration

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## BU was unable to send IMC for NBUs VLAN/Port configuration log

BU was unable to send IMC for NBUs VLAN/Port configuration

There was an error when sending VLAN configuration to stack.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



call to cdt api function failed due to lock timeout (code=%d, total failures=%d, task=%s)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## call to cdt api function failed due to lock timeout (code=%d, total failures=%d, task=%s) log

call to cdt api function failed due to lock timeout (code=%d, total failures=%d, task=%s)

The system detected an error caused by failure in the mutual exclusion lock mechanisms.

Source	Severity
--------	----------

CDT	Serious
-----	---------

### Remedial action

No action required.



call to IDT\_LearnAddress has failed  
(code=%d, total failures=%d,  
errno=%x)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## call to IDT\_LearnAddress has failed (code=%d, total failures=%d, errno=%x) log

call to IDT\_LearnAddress has failed (code=%d, total failures=%d, errno=%x)

**Source**   **Severity**  
CDT

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





cam block lookup first 8 chars of  
mac=%08x, fid=0x%04x, num  
returned=%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## cam block lookup first 8 chars of mac=%08x, fid=0x%04x, num returned=%d log

cam block lookup first 8 chars of mac=%08x, fid=0x%04x, num returned=%d

**Source**   **Severity**  
CDT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



cam database manager reached  
processing capacity; delaying some  
actions

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## cam database manager reached processing capacity; delaying some actions log

cam database manager reached processing capacity; delaying some actions

**Source**   **Severity**  
CDT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CAM driver control initialization failed (code=%d,argument=%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CAM driver control initialization failed (code=%d,argument=%d) log

CAM driver control initialization failed (code=%d,argument=%d)

**Source**   **Severity**

CDT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# cam driver initialization failed (code=%d,argument=%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## cam driver initialization failed (code=%d,argument=%d) log

cam driver initialization failed (code=%d,argument=%d)

**Source    Severity**

CDT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# cam driver initialization failed (code= error type argument= line# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## cam driver initialization failed (code= error type argument= line# ) log

cam driver initialization failed (code= error type argument= line# )

The CAM driver initialization critically failed, as the system resources were unavailable.

Source	Severity
CDT	Critical

### Remedial action

Restart the system.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# cam driver initialized

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## cam driver initialized log

cam driver initialized

The system initialized the CAM driver.

Source	Severity
CDT	Information

### Remedial action

No action required.



# cam imc allocation error (code=%d, total failures=%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## cam imc allocation error (code=%d, total failures=%d) log

cam imc allocation error (code=%d, total failures=%d)

**Source**   **Severity**

CDT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# cam imc failed to receive to message queue

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## cam imc failed to receive to message queue log

cam imc failed to receive to message queue

**Source**   **Severity**

CDT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





cam imc failed to send to message queue (code=%d, total failures=%d, errno=%x)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## cam imc failed to send to message queue (code=%d, total failures=%d, errno=%x) log

cam imc failed to send to message queue (code=%d, total failures=%d, errno=%x)

**Source**   **Severity**  
CDT

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



cam lookup error first 8 chars of  
mac=%08x, fid=0x%04x (code=%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## cam lookup error first 8 chars of mac=%08x, fid=0x%04x (code=%d) log

cam lookup error first 8 chars of mac=%08x, fid=0x%04x (code=%d)

**Source**   **Severity**  
CDT

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



cam policies executing code that has not been completed (code=%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## cam policies executing code that has not been completed (code=%d) log

cam policies executing code that has not been completed (code=%d)

Source	Severity
CAMPOLICY	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# cam policies initialized

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## cam policies initialized log

cam policies initialized

**Source**      **Severity**

CAMPOLICY

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# cam policy initialization failed (code=%d,argument=%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## cam policy initialization failed (code=%d,argument=%d) log

cam policy initialization failed (code=%d,argument=%d)

**Source**      **Severity**

CAMPOLICY

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# cam policy initialization failed (code=%d,argument=%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## cam policy initialization failed (code=%d,argument=%d) log

cam policy initialization failed (code=%d,argument=%d)

**Source**      **Severity**

CAMPOLICY

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# cam processing aborted (code=%d,argument=0)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## cam processing aborted (code=%d,argument=0) log

cam processing aborted (code=%d,argument=0)

### Source    Severity

CDT

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# cam processing aborted (code= error type argument= line# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## cam processing aborted (code= error type argument= line# ) log

cam processing aborted (code= error type argument= line# )

The system could not process the MAC address, due to repeated internal failures.

Source	Severity
CDT	Critical

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# cam processing error (code=%d,argument=%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## cam processing error (code=%d,argument=%d) log

cam processing error (code=%d,argument=%d)

**Source    Severity**

CDT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



cam synchronization disabled; cam will  
operate as standalone driver

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## cam synchronization disabled; cam will operate as standalone driver log

cam synchronization disabled; cam will operate as standalone driver

**Source**   **Severity**  
CDT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# cam synchronization enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## cam synchronization enabled log

cam synchronization enabled

**Source**   **Severity**

CDT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# cam synchronization temporarily disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## cam synchronization temporarily disabled log

cam synchronization temporarily disabled

**Source**   **Severity**

CDT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot access instance data for Port # %u

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot access instance data for Port # %u log

Cannot access instance data for Port # %u

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot access port data for unit

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot access port data for unit log

Cannot access port data for unit

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot add C-VLAN to ETREE

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot add C-VLAN to ETREE log

Cannot add C-VLAN to ETREE

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot add C-VLAN to ISID. IGMP Snooping is enabled on C-VLAN from I-SID

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot add C-VLAN to ISID. IGMP Snooping is enabled on C-VLAN from I-SID log

Cannot add C-VLAN to ISID. IGMP Snooping is enabled on C-VLAN from I-SID

Source	Severity
ISIS	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Cannot add C-VLAN with IGMP Snooping to ISID with multiple VLANs configured

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot add C-VLAN with IGMP Snooping to ISID with multiple VLANs configured log

Cannot add C-VLAN with IGMP Snooping to ISID with multiple VLANs configured

**Source**   **Severity**  
ISIS

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot add ETREE to ISID with multiple VLANs configured

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot add ETREE to ISID with multiple VLANs configured log

Cannot add ETREE to ISID with multiple VLANs configured

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot add SWITCHED UNI to ISIS. IGMP Snooping is enabled on C-VLAN from I-SID

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot add SWITCHED UNI to ISIS. IGMP Snooping is enabled on C-VLAN from I-SID log

Cannot add SWITCHED UNI to ISIS. IGMP Snooping is enabled on C-VLAN from I-SID

Source	Severity
ISIS	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot change metric type from wide to narrow

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot change metric type from wide to narrow log

Cannot change metric type from wide to narrow

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot change system ID with nodal MEP MIP association

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot change system ID with nodal MEP MIP association log

Cannot change system ID with nodal MEP MIP association

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot config i-sid for spbm vlan

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot config i-sid for spbm vlan log

Cannot config i-sid for spbm vlan

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot configure ethertype without SPBM globally enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot configure ethertype without SPBM globally enabled log

Cannot configure ethertype without SPBM globally enabled

**Source   Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot configure SPBM in non SPBM mode

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot configure SPBM in non SPBM mode log

Cannot configure SPBM in non SPBM mode

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Cannot configure without loopback port available

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot configure without loopback port available log

Cannot configure without loopback port available

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot configure without SPBM globally enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot configure without SPBM globally enabled log

Cannot configure without SPBM globally enabled

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot create an SPBM VLAN from a regular VLAN that has static MAC addresses

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot create an SPBM VLAN from a regular VLAN that has static MAC addresses log

Cannot create an SPBM VLAN from a regular VLAN that has static MAC addresses

**Source**   **Severity**  
ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot create circuit interface on eap port

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot create circuit interface on eap port log

Cannot create circuit interface on eap port

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot create circuit interface on port %i. Maximum circ number exceeded

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot create circuit interface on port %i. Maximum circ number exceeded log

Cannot create circuit interface on port %i. Maximum circ number exceeded

Source	Severity
ISIS	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot create circuit interface on unit %i port %i. Maximum circ number exceeded

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot create circuit interface on unit %i port %i. Maximum circ number exceeded log

Cannot create circuit interface on unit %i port %i. Maximum circ number exceeded

Source	Severity
ISIS	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot create CVLAN if the indicated VLAN contains NNI

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot create CVLAN if the indicated VLAN contains NNI log

Cannot create CVLAN if the indicated VLAN contains NNI

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot create CVLAN on L3 VLAN

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot create CVLAN on L3 VLAN log

Cannot create CVLAN on L3 VLAN

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Cannot create CVLAN on vlan: IGMP Snooping enabled and SPBM Mcast disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot create CVLAN on vlan: IGMP Snooping enabled and SPBM Mcast disabled log

Cannot create CVLAN on vlan: IGMP Snooping enabled and SPBM Mcast disabled

Source	Severity
ISIS	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot create CVLAN on VLAN that is part of SMLT

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot create CVLAN on VLAN that is part of SMLT log

Cannot create CVLAN on VLAN that is part of SMLT

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot create dead timer for port %u

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot create dead timer for port %u log

Cannot create dead timer for port %u

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot create IS-IS interface on IST interface

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot create IS-IS interface on IST interface log

Cannot create IS-IS interface on IST interface

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot create IS-IS interface on MLT which has port member with IS-IS interface

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot create IS-IS interface on MLT which has port member with IS-IS interface log

Cannot create IS-IS interface on MLT which has port member with IS-IS interface

Source	Severity
ISIS	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot create IS-IS interface on port which is member of MLT with IS-IS interface

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot create IS-IS interface on port which is member of MLT with IS-IS interface log

Cannot create IS-IS interface on port which is member of MLT with IS-IS interface

Source	Severity
ISIS	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot create IS-IS interface on port with IPFIX enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot create IS-IS interface on port with IPFIX enabled log

Cannot create IS-IS interface on port with IPFIX enabled

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot create IS-IS interface on private vlan isolated/promiscuous port

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot create IS-IS interface on private vlan isolated/promiscuous port log

Cannot create IS-IS interface on private vlan isolated/promiscuous port

**Source**   **Severity**  
ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Cannot create IS-IS interface on SMLT interface

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot create IS-IS interface on SMLT interface log

Cannot create IS-IS interface on SMLT interface

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot create switched UNI on NNI interface

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot create switched UNI on NNI interface log

Cannot create switched UNI on NNI interface

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot create transparent UNI as port belongs to at least one VLAN

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot create transparent UNI as port belongs to at least one VLAN log

Cannot create transparent UNI as port belongs to at least one VLAN

**Source**   **Severity**  
ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot create UNI on VLAN with IGMP SNOOP enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot create UNI on VLAN with IGMP SNOOP enabled log

Cannot create UNI on VLAN with IGMP SNOOP enabled

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot create UNI on VLAN with IPV6 VRRPV3 configured

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot create UNI on VLAN with IPV6 VRRPV3 configured log

Cannot create UNI on VLAN with IPV6 VRRPV3 configured

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot create UNI on VLAN with MLD SNOOP configured

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot create UNI on VLAN with MLD SNOOP configured log

Cannot create UNI on VLAN with MLD SNOOP configured

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Can not create user

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Can not create user log

Can not create user

**Source   Severity**

AAA

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot delete dead timer for port %u

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot delete dead timer for port %u log

Cannot delete dead timer for port %u

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Cannot delete ISID used by EAP Fail Open VLAN

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot delete ISID used by EAP Fail Open VLAN log

Cannot delete ISID used by EAP Fail Open VLAN

Cannot delete a VLAN configured as Voice VLAN

Source	Severity
SPB	Information

### Remedial action

Change the Voice VLAN to other value and then remove the VLAN

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot delete ISID used by EAP Guest VLAN

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot delete ISID used by EAP Guest VLAN log

Cannot delete ISID used by EAP Guest VLAN

Cannot delete a VLAN configured as Guest VLAN

Source	Severity
SPB	Information

### Remedial action

Change the Guest VLAN to other value and then remove the VLAN

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot delete ISID used by EAP VoIP VLAN

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot delete ISID used by EAP VoIP VLAN log

Cannot delete ISID used by EAP VoIP VLAN

Cannot delete a VLAN configured as Fail Open VLAN

Source	Severity
SPB	Information

### Remedial action

Change the Fail Open VLAN to other value and then remove the VLAN

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot delete SPBM instance, IS-IS interface is configured

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot delete SPBM instance, IS-IS interface is configured log

Cannot delete SPBM instance, IS-IS interface is configured

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot delete SPBM instance, system ID is configured

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot delete SPBM instance, system ID is configured log

Cannot delete SPBM instance, system ID is configured

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Can not delete user, user does not exist

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Can not delete user, user does not exist log

Can not delete user, user does not exist

**Source   Severity**

AAA

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot disable IP Shortcut without first disabling IP routing

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot disable IP Shortcut without first disabling IP routing log

Cannot disable IP Shortcut without first disabling IP routing

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot disable IP Source Guard on Unit %d Port %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot disable IP Source Guard on Unit %d Port %d log

Cannot disable IP Source Guard on Unit %d Port %d

**Source    Severity**

IPSg

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Cannot disable IP Source Guard on Unit unit# Port port#

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot disable IP Source Guard on Unit unit# Port port# log

Cannot disable IP Source Guard on Unit unit# Port port#

The IPSG cannot be disabled on the specified unit/port.

Source	Severity
ipsg	Information

### Remedial action

Disable the MLT (if it enabled) and try again. If it fails, then reboot the switch.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot disable SPBM globally while i-sid and UNI configuration exists

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot disable SPBM globally while i-sid and UNI configuration exists log

Cannot disable SPBM globally while i-sid and UNI configuration exists

**Source**   **Severity**  
ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot disable SPBM multicast - IGMP Snooping is enabled on C-VLANs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot disable SPBM multicast - IGMP Snooping is enabled on C-VLANs log

Cannot disable SPBM multicast - IGMP Snooping is enabled on C-VLANs

**Source**   **Severity**  
ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Can not disable user, user does not exist

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Can not disable user, user does not exist log

Can not disable user, user does not exist

**Source   Severity**

AAA

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot enable IP Source Guard on Unit %d Port %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot enable IP Source Guard on Unit %d Port %d log

Cannot enable IP Source Guard on Unit %d Port %d

**Source    Severity**

IPSG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot enable IS-IS interface on port with mac-security settings

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot enable IS-IS interface on port with mac-security settings log

Cannot enable IS-IS interface on port with mac-security settings

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot enable IS-IS interface without SPBM instance

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot enable IS-IS interface without SPBM instance log

Cannot enable IS-IS interface without SPBM instance

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot enable SPBM: EAP Guest, FailOpen or Voice VLANs are not default

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot enable SPBM: EAP Guest, FailOpen or Voice VLANs are not default log

Cannot enable SPBM: EAP Guest, FailOpen or Voice VLANs are not default

VLANs used by EAP as Guest VLAN, Fail Open VLAN or Voice VLAN must be of SPB type when SPB is used

Source	Severity
SPB	Information

### Remedial action

Before enabling SPB ensure that all of them are set to the default value.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Cannot enable SPBM globally if next STP operation mode is RSTP

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot enable SPBM globally if next STP operation mode is RSTP log

Cannot enable SPBM globally if next STP operation mode is RSTP

**Source**   **Severity**  
ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot enable SPBM globally on RSTP mode

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot enable SPBM globally on RSTP mode log

Cannot enable SPBM globally on RSTP mode

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot enable SPBM globally on stack mode

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot enable SPBM globally on stack mode log

Cannot enable SPBM globally on stack mode

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot enable SPBM globally while L3 is enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot enable SPBM globally while L3 is enabled log

Cannot enable SPBM globally while L3 is enabled

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot enable SPBM multicast: feature unsupported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot enable SPBM multicast: feature unsupported log

Cannot enable SPBM multicast: feature unsupported

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot enable SPBM multicast while unknown-mcast-no-flood is enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot enable SPBM multicast while unknown-mcast-no-flood is enabled log

Cannot enable SPBM multicast while unknown-mcast-no-flood is enabled

Source	Severity
ISIS	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot enable SPBM while MVR is enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot enable SPBM while MVR is enabled log

Cannot enable SPBM while MVR is enabled

MVR is not supported whilst SPBM is configured.

Source	Severity
SPB	Information

### Remedial action

Disable MVR before enabling SPBM.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot enable SPBM while PIM is enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot enable SPBM while PIM is enabled log

Cannot enable SPBM while PIM is enabled

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Cannot enable the SPBM instance on a IS-IS interface configured 'UntagAll'

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot enable the SPBM instance on a IS-IS interface configured 'UntagAll' log

Cannot enable the SPBM instance on a IS-IS interface configured 'UntagAll'

Source	Severity
ISIS	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Can not enable user, user does not exist

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Can not enable user, user does not exist log

Can not enable user, user does not exist

**Source   Severity**

AAA

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot get dead timer ID for port %u

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot get dead timer ID for port %u log

Cannot get dead timer ID for port %u

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot set dead timer to %u for port %u

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot set dead timer to %u for port %u log

Cannot set dead timer to %u for port %u

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot set IP source address to zero when IP Shortcut is enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot set IP source address to zero when IP Shortcut is enabled log

Cannot set IP source address to zero when IP Shortcut is enabled

IP Shortcut requires non-zero IP source address.

Source	Severity
SPB	Information

### Remedial action

Set the IP Shourtcut address source to a loopback interface IP address.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot set SPBM instance on adac call server port

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot set SPBM instance on adac call server port log

Cannot set SPBM instance on adac call server port

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot set SPBM instance on adac phone port

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot set SPBM instance on adac phone port log

Cannot set SPBM instance on adac phone port

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot set SPBM instance on adac uplink port

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot set SPBM instance on adac uplink port log

Cannot set SPBM instance on adac uplink port

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Cannot set SPBM instance on a monitor port with allow traffic disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot set SPBM instance on a monitor port with allow traffic disabled log

Cannot set SPBM instance on a monitor port with allow traffic disabled

**Source**   **Severity**  
ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot set SPBM instance on MLT which is in a CVLAN

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot set SPBM instance on MLT which is in a CVLAN log

Cannot set SPBM instance on MLT which is in a CVLAN

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot set SPBM instance on port of CVLAN

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot set SPBM instance on port of CVLAN log

Cannot set SPBM instance on port of CVLAN

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot set SPBM instance on transparent UNI port

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot set SPBM instance on transparent UNI port log

Cannot set SPBM instance on transparent UNI port

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot update settings with the same data

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot update settings with the same data log

Cannot update settings with the same data

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cannot use multicast address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cannot use multicast address log

Cannot use multicast address

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Capabilities determined by agent (not-writable)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Capabilities determined by agent (not-writable) log

Capabilities determined by agent (not-writable)

The interface type capabilities cannot be modified.

Source	Severity
QoS	Information

### Remedial action

Eliminate option.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Capabilities value invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Capabilities value invalid log

Capabilities value invalid

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# CDT AgeTime set failed (line = %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CDT AgeTime set failed (line = %d) log

CDT AgeTime set failed (line = %d)

**Source**   **Severity**

CDT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



CDT MAC address mac\_address was removed because LAG trunk trunked has disaggregated.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CDT MAC address mac\_address was removed because LAG trunk trunked has disaggregated. log

CDT MAC address mac\_address was removed because LAG trunk trunked has disaggregated.

The static MAC address for a LAG trunk was deleted because the specific LAG trunk is disaggregated.

Source	Severity
--------	----------

CDT	Information
-----	-------------

### Remedial action

No action required.



CDT MAC address mac\_address was removed because port port\_no has aggregated in LAG

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CDT MAC address mac\_address was removed because port port\_no has aggregated in LAG log

CDT MAC address mac\_address was removed because port port\_no has aggregated in LAG

The static MAC address for a port is deleted, because the specific port is aggregated in a LAG

Source	Severity
--------	----------

CDT	Information
-----	-------------

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CDT The static FDB entry MAC mac\_address VLAN vlan Id trunk trunkId was deleted because LAG has disaggregated

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CDT The static FDB entry MAC mac\_address VLAN vlan Id trunk trunkId was deleted because LAG has disaggregated log

CDT The static FDB entry MAC mac\_address VLAN vlan Id trunk trunkId was deleted because LAG has disaggregated

The static MAC address for a LAG trunk was deleted because the specific LAG trunk has disaggregated.

### Source Severity

CDT Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CDT The static FDB entry MAC mac\_address VLAN vlan id was deleted because Unit Port unit port has aggregated

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CDT The static FDB entry MAC mac\_address VLAN vlan id was deleted because Unit Port unit port has aggregated log

CDT The static FDB entry MAC mac\_address VLAN vlan id was deleted because Unit Port unit port has aggregated

The static MAC address for a port was deleted as the specific port has aggregated in a LAG.

Source	Severity
--------	----------

CDT	Information
-----	-------------

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



CFG - Backup Configuration files are corrupted. Restore backup from primary config.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFG - Backup Configuration files are corrupted. Restore backup from primary config. log

CFG - Backup Configuration files are corrupted. Restore backup from primary config.

**Source**   **Severity**  
CFG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CFG - Backup Configuration files are corrupted. Restored to default.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFG - Backup Configuration files are corrupted. Restored to default. log

CFG - Backup Configuration files are corrupted. Restored to default.

Source	Severity
CFG	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CFG - Configuration files are corrupted. Restored from backup.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFG - Configuration files are corrupted. Restored from backup. log

CFG - Configuration files are corrupted. Restored from backup.

**Source   Severity**

CFG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# CFG - Could not acquire FLASH sem

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFG - Could not acquire FLASH sem log

CFG - Could not acquire FLASH sem

An extreme concurrency faced when you copy or auto-synchronize the configuration.

Source	Severity
CFG	Information

### Remedial action

Retry the last command.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CFG - Could not acquire FLASH sem.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFG - Could not acquire FLASH sem. log

CFG - Could not acquire FLASH sem.

**Source    Severity**

CFG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CFG - Could not create ram copy buffer.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFG - Could not create ram copy buffer. log

CFG - Could not create ram copy buffer.

**Source    Severity**

CFG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CFG has No Error %d, %d, %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFG has No Error %d, %d, %d log

CFG has No Error %d, %d, %d

**Source**   **Severity**

CFG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CFG layer - invalid error %d, %d, %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFG layer - invalid error %d, %d, %d log

CFG layer - invalid error %d, %d, %d

**Source**   **Severity**

CFG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CFG - NVRAM file system check: errors detected. Please reboot the system!

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFG - NVRAM file system check: errors detected. Please reboot the system! log

CFG - NVRAM file system check: errors detected. Please reboot the system!

Source	Severity
CFG	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CFG - NVRAM file system check: errors detected. Restored to default.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFG - NVRAM file system check: errors detected. Restored to default. log

CFG - NVRAM file system check: errors detected. Restored to default.

Source	Severity
CFG	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CFGSO - Error: Failed to cancel watchdog timer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFGSO - Error: Failed to cancel watchdog timer log

CFGSO - Error: Failed to cancel watchdog timer

**Source**   **Severity**

CFGSO

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# CFGSO - Error: Failed to create message queue

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFGSO - Error: Failed to create message queue log

CFGSO - Error: Failed to create message queue

**Source**   **Severity**

CFGSO

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CFGSO - Error: Failed to create watchdog timer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFGSO - Error: Failed to create watchdog timer log

CFGSO - Error: Failed to create watchdog timer

The system failed to create a watchdog timer.

Source	Severity
CFGSO	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CFGSO - Error: Failed to get an imc buffer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFGSO - Error: Failed to get an imc buffer log

CFGSO - Error: Failed to get an imc buffer

The system failed to get an IMC buffer.

Source	Severity
CFGSO	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CFGSO - Error: Failed to save data to NBU

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFGSO - Error: Failed to save data to NBU log

CFGSO - Error: Failed to save data to NBU

The system failed to save data to NBU.

Source	Severity
CFGSO	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CFGSO - Error: Failed to send message to queue

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFGSO - Error: Failed to send message to queue log

CFGSO - Error: Failed to send message to queue

**Source**   **Severity**

CFGSO

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CFGSO - Error: Failed to spawn cfgso task

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFGSO - Error: Failed to spawn cfgso task log

CFGSO - Error: Failed to spawn cfgso task

**Source**   **Severity**

CFGSO

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CFGSO - Error: Failed to start watchdog timer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFGSO - Error: Failed to start watchdog timer log

CFGSO - Error: Failed to start watchdog timer

The system failed to start the watchdog timer.

Source	Severity
CFGSO	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CFGSO - Error: file not close

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFGSO - Error: file not close log

CFGSO - Error: file not close

**Source**   **Severity**

CFGSO

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# CFGSO - Error: File not open

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFGSO - Error: File not open log

CFGSO - Error: File not open

**Source**   **Severity**

CFGSO

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CFGSO - Error: File not read

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFGSO - Error: File not read log

CFGSO - Error: File not read

The system could not read the file.

Source	Severity
CFGSO	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CFGSO - Error: File not write

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFGSO - Error: File not write log

CFGSO - Error: File not write

The system could not write the file.

Source	Severity
CFGSO	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CFGSO - Error: Invalid value

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFGSO - Error: Invalid value log

CFGSO - Error: Invalid value

**Source**   **Severity**

CFGSO

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CFGSO - Warning Invalid Msg Id

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFGSO - Warning Invalid Msg Id log

CFGSO - Warning Invalid Msg Id

The system detected an invalid message Id.

Source	Severity
CFGSO	Serious

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CFGSO - Warning: Invalid Msg Id

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFGSO - Warning: Invalid Msg Id log

CFGSO - Warning: Invalid Msg Id

**Source**   **Severity**

CFGSO

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CFGSO - Warning Watchdog timer expire

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFGSO - Warning Watchdog timer expire log

CFGSO - Warning Watchdog timer expire

The watchdog timer expired.

Source	Severity
CFGSO	Error

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CFGSO - Warning: Watchdog timer expire

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFGSO - Warning: Watchdog timer expire log

CFGSO - Warning: Watchdog timer expire

**Source   Severity**

CFGSO

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# CFM: ERROR adding port filters for VLAN %d - no resources

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFM: ERROR adding port filters for VLAN %d - no resources log

CFM: ERROR adding port filters for VLAN %d - no resources

Error adding port filters.

Source	Severity
SPB	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CFM SPBM failed to install pdu capture filter(s) on port %d for vlan %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CFM SPBM failed to install pdu capture filter(s) on port %d for vlan %d log

CFM SPBM failed to install pdu capture filter(s) on port %d for vlan %d

Source	Severity
CFM	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Change of active config block and or reset failed block-number

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Change of active config block and or reset failed block-number log

Change of active config block and or reset failed block-number

Active configuration block was changed and the unit was restarted.

Source	Severity
Stack Manager	Information

### Remedial action

No action required.



# Change of active config block failed %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Change of active config block failed %d log

Change of active config block failed %d

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Change rear-port mode before setting SPBM globally

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Change rear-port mode before setting SPBM globally log

Change rear-port mode before setting SPBM globally

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Classifier block component set ID out-of-range ( clfr comp set ID )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Classifier block component set ID out-of-range ( clfr comp set ID ) log

Classifier block component set ID out-of-range ( clfr comp set ID )

Set ID must be between 1 and 55000.

Source	Severity
QoS	Serious

### Remedial action

Enter a valid classifier block component setID.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Classifier block component set ID out-of-range (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Classifier block component set ID out-of-range (%d) log

Classifier block component set ID out-of-range (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Classifier block distribution across stack failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Classifier block distribution across stack failed log

Classifier block distribution across stack failed

Unable to commit changes across the stack.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Classifier block modifications not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Classifier block modifications not supported log

Classifier block modifications not supported

The system detected an internal error; The specified modifier option is not supported.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent, or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Classifier block number out-of-range ( block# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Classifier block number out-of-range ( block# ) log

Classifier block number out-of-range ( block# )

Classifier block number must be between 1 and 55000.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Enter a valid classifier block number.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Classifier block number out-of-range (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Classifier block number out-of-range (%d) log

Classifier block number out-of-range (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Classifier block precedence value not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Classifier block precedence value not supported log

Classifier block precedence value not supported

Classifier block precedence range depends on the platform.

Source	Severity
QoS	Serious

### Remedial action

Check documentation and use a valid classifier block precedence or ignore option.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Classifier component distribution across stack failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Classifier component distribution across stack failed log

Classifier component distribution across stack failed

Unable to commit changes across the stack.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Classifier component modifications not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Classifier component modifications not supported log

Classifier component modifications not supported

The system detected an internal error; The specified modifier option is not supported.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent, or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Classifier component set ID out-of-range ( clfsr comp set ID )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Classifier component set ID out-of-range ( clfsr comp set ID ) log

Classifier component set ID out-of-range ( clfsr comp set ID )

Set ID must be between 1 and 55000.

Source	Severity
QoS	Serious

### Remedial action

Specify a valid set ID.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Classifier component set ID out-of-range (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Classifier component set ID out-of-range (%d) log

Classifier component set ID out-of-range (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Classifier conflict (duplicate clfr data in block) detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Classifier conflict (duplicate clfr data in block) detected log

Classifier conflict (duplicate clfr data in block) detected

A classifier with the same characteristics already exists in the specified block.

Source	Severity
QoS	Serious

### Remedial action

Remove the existing classifier or use a different block.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Classifier content incompatible with target interface(s)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Classifier content incompatible with target interface(s) log

Classifier content incompatible with target interface(s)

The classifier element options not supported by the specified interface(s).

Source	Severity
QoS	Serious

### Remedial action

Change the classifier content and try again or change the interface(s).



# Classifier inconsistency detected (conflicting allocation modes)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Classifier inconsistency detected (conflicting allocation modes) log

Classifier inconsistency detected (conflicting allocation modes)

The configured allocation mode must be the same for all classifier components in a classifier block.

Source	Severity
QoS	Information

### Remedial action

Use the same allocation mode for all classifier block members.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Classifier set block reference out-of-range ( clfr setblock# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Classifier set block reference out-of-range ( clfr setblock# ) log

Classifier set block reference out-of-range ( clfr setblock# )

Classifier set/block id must be between 1 and 55000.

Source	Severity
QoS	Serious

### Remedial action

Enter a valid classifier set/block id.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Classifier set/block reference out-of-range (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Classifier set/block reference out-of-range (%d) log

Classifier set/block reference out-of-range (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Classifier type unknown

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Classifier type unknown log

Classifier type unknown

The valid classifier types are individual and block.

Source	Severity
QoS	Serious

### Remedial action

Specify a valid classifier type.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Clearing MC unicast IMC entries, unit %d, end\_type %s, stk\_type %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Clearing MC unicast IMC entries, unit %d, end\_type %s, stk\_type %s log

Clearing MC unicast IMC entries, unit %d, end\_type %s, stk\_type %s

Source	Severity
SMGR	

Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Clearing VLAN entries, end\_type %s, stk\_type %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Clearing VLAN entries, end\_type %s, stk\_type %s log

Clearing VLAN entries, end\_type %s, stk\_type %s

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Clfr content (system) incompatible with target interface(s)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Clfr content (system) incompatible with target interface(s) log

Clfr content (system) incompatible with target interface(s)

The system classifier element options not supported by the specified interface(s).

Source	Severity
QoS	Serious

### Remedial action

Change the system classifier content and try again or change the interface(s).

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cli add vlan vlan id members port mask

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cli add vlan vlan id members port mask log

Cli add vlan vlan id members port mask

Add new members indicated in port list to VLAN.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cli create vlan vlan id type port

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cli create vlan vlan id type port log

Cli create vlan vlan id type port

A new VLAN type port is created.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cli delete vlan vlan id members port mask

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cli delete vlan vlan id members port mask log

Cli delete vlan vlan id members port mask

Remove members indicated in port list from VLAN.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cli delete vlan vlan id type port

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cli delete vlan vlan id type port log

Cli delete vlan vlan id type port

The existing VLAN type port is deleted.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CLI pswd: A unified authentication method is now used. The local switch credentials are no longer supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CLI pswd: A unified authentication method is now used. The local switch credentials are no longer supported log

CLI pswd: A unified authentication method is now used. The local switch credentials are no longer supported

**Source**   **Severity**  
Telnet

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CLI pswd: Stack authentication parameter is obsolete; unified changes have been applied to both stack and switch

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CLI pswd: Stack authentication parameter is obsolete; unified changes have been applied to both stack and switch log

CLI pswd: Stack authentication parameter is obsolete; unified changes have been applied to both stack and switch

Stack authentication parameter is obsolete; unified changes have been applied to both stack and switch.

Source	Severity
--------	----------

Telnet	Information
--------	-------------

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CLI pswd:Stack authentication parameter is obsolete;unified changes have been applied to both stack and switch

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CLI pswd:Stack authentication parameter is obsolete;unified changes have been applied to both stack and switch log

CLI pswd:Stack authentication parameter is obsolete;unified changes have been applied to both stack and switch

### Source    Severity

Telnet

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





CLI pswd: Stack auth type  
RADIUS/TACACS+ won't apply partially  
(stack IP addr not set). Local user/pass  
used

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CLI pswd: Stack auth type RADIUS/TACACS+ won't apply partially (stack IP addr not set). Local user/pass used log

CLI pswd: Stack auth type RADIUS/TACACS+ won't apply partially (stack IP addr not set). Local user/pass used

Stack IP address is not set

Source	Severity
Telnet	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



CLI pswd: Stack auth type  
RADIUS/TACACS+ won't apply partially  
(switch IP addr not set). Local user/pass  
used

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CLI pswd: Stack auth type RADIUS/TACACS+ won't apply partially (switch IP addr not set). Local user/pass used log

CLI pswd: Stack auth type RADIUS/TACACS+ won't apply partially (switch IP addr not set). Local user/pass used

Switch IP address is not set

Source	Severity
Telnet	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CLI pswd: Switch authentication parameter is obsolete; changes have not been applied

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CLI pswd: Switch authentication parameter is obsolete; changes have not been applied log

CLI pswd: Switch authentication parameter is obsolete; changes have not been applied

Switch authentication parameter is obsolete; changes have not been applied.

Source	Severity
--------	----------

Telnet	Information
--------	-------------

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cli set autopvid disable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cli set autopvid disable log

Cli set autopvid disable

Disable the auto PVID.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cli set autopvid enable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cli set autopvid enable log

Cli set autopvid enable

Enable auto PVID.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cli set management vlan vlan id

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cli set management vlan vlan id log

Cli set management vlan vlan id

Set the management VLAN.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cli set ports port mask tagging disable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cli set ports port mask tagging disable log

Cli set ports port mask tagging disable

Port tagging is disabled.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cli set ports port mask tagging enable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cli set ports port mask tagging enable log

Cli set ports port mask tagging enable

Port tagging is enabled.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Cli set pvid vlan id ports port mask

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cli set pvid vlan id ports port mask log

Cli set pvid vlan id ports port mask

Port PVID is set.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cli set vlan vlan id members port mask

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cli set vlan vlan id members port mask log

Cli set vlan vlan id members port mask

VLAN ports are set.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



code execution took unexpected, but  
safe, execution path  
(code=%d,argument=0)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## code execution took unexpected, but safe, execution path (code=%d,argument=0) log

code execution took unexpected, but safe, execution path (code=%d,argument=0)

**Source   Severity**  
CDT

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cold Start Trap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cold Start Trap log

Cold Start Trap

Cold Start

Source	Severity
SNMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Composite filter set addition failure comp filter set unknown

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set addition failure comp filter set unknown log

Composite filter set addition failure comp filter set unknown

One of the components in the specified composite filter set does not exist.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Composite filter set addition failure: comp filter set unknown

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set addition failure: comp filter set unknown log

Composite filter set addition failure: comp filter set unknown

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Composite filter set addition failure data consistency issue

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set addition failure data consistency issue log

Composite filter set addition failure data consistency issue

The system detected inconsistent data; Following are the possible reasons: Filter set duplication, Conflicting MAC data (the same filter set cannot be added with or without MAC data).

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Check the parameters, and resolve if any possible invalid values.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Composite filter set addition failure: data consistency issue

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set addition failure: data consistency issue log

Composite filter set addition failure: data consistency issue

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Composite filter set addition failure data invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set addition failure data invalid log

Composite filter set addition failure data invalid

The system detected invalid data; Following are the possible reasons: Source MAC address and mask length with different values, Seed name must be specified, and within the limited length, Clone name must be specified, and within the limited length (0-16).

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Check the parameters and resolve if any possible invalid values.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Composite filter set addition failure: data invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set addition failure: data invalid log

Composite filter set addition failure: data invalid

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Composite filter set addition failure replication failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set addition failure replication failure log

Composite filter set addition failure replication failure

The system failed to clone the composite filter member.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent, or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Composite filter set addition failure: replication failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set addition failure: replication failure log

Composite filter set addition failure: replication failure

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Composite filter set addition failure resources unavailable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set addition failure resources unavailable log

Composite filter set addition failure resources unavailable

Unable to add any more members to the specified filter set as the resources are unavailable.

Source	Severity
QoS	Serious

### Remedial action

Check for and remove the resources that are not needed.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Composite filter set addition failure: resources unavailable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set addition failure: resources unavailable log

Composite filter set addition failure: resources unavailable

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Composite filter set addition failure seed filter set unknown

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set addition failure seed filter set unknown log

Composite filter set addition failure seed filter set unknown

The seed filter for the specified composite filter set does not exist.

Source	Severity
QoS	Warning

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Composite filter set addition failure: seed filter set unknown

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set addition failure: seed filter set unknown log

Composite filter set addition failure: seed filter set unknown

**Source   Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Composite filter set creation failure data invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set creation failure data invalid log

Composite filter set creation failure data invalid

The system detected invalid data; Following are the possible reasons: Source MAC address and mask length with different values, Seed name must be specified; and within the limited length, Clone name must be specified, and within the limited length.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Check the parameters, and resolve if any possible invalid values.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Composite filter set creation failure: data invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set creation failure: data invalid log

Composite filter set creation failure: data invalid

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Composite filter set creation failure MAC data not allowed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set creation failure MAC data not allowed log

Composite filter set creation failure MAC data not allowed

MAC data is not allowed in the base composite filter set.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Remove the MAC data filter or classifier.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Composite filter set creation failure: MAC data not allowed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set creation failure: MAC data not allowed log

Composite filter set creation failure: MAC data not allowed

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Composite filter set creation failure replication failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set creation failure replication failure log

Composite filter set creation failure replication failure

The system failed to clone the filter set.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent, or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Composite filter set creation failure: replication failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set creation failure: replication failure log

Composite filter set creation failure: replication failure

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Composite filter set creation failure seed filter set unknown

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set creation failure seed filter set unknown log

Composite filter set creation failure seed filter set unknown

The seed filter for the specified composite filter set does not exist.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Composite filter set creation failure: seed filter set unknown

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set creation failure: seed filter set unknown log

Composite filter set creation failure: seed filter set unknown

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Composite filter set creation failure: set already exists

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set creation failure: set already exists log

Composite filter set creation failure: set already exists

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Composite filter set deletion failure base set target invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set deletion failure base set target invalid log

Composite filter set deletion failure base set target invalid

The base composite filter set is on target. The base composite filter set can not be deleted without destroying the entire composite filter set.

Source	Severity
QoS	Serious

### Remedial action

Remove the filter set dependencies if any before deleting the base filter set.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Composite filter set deletion failure: base set target invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set deletion failure: base set target invalid log

Composite filter set deletion failure: base set target invalid

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Composite filter set deletion failure comp filter set unknown

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set deletion failure comp filter set unknown log

Composite filter set deletion failure comp filter set unknown

One of the components in the specified composite filter set does not exist.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent, or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Composite filter set deletion failure: comp filter set unknown

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set deletion failure: comp filter set unknown log

Composite filter set deletion failure: comp filter set unknown

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Composite filter set deletion failure data invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set deletion failure data invalid log

Composite filter set deletion failure data invalid

The system detected invalid data; Following are the possible reasons: Source MAC address and mask length with different values, Seed name must be specified and within the limited length, Clone name must be specified and within the limited length (0-16).

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Check the parameters and resolve, if any possible invalid values.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Composite filter set deletion failure: data invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set deletion failure: data invalid log

Composite filter set deletion failure: data invalid

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Composite filter set deletion failure seed filter set unknown

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set deletion failure seed filter set unknown log

Composite filter set deletion failure seed filter set unknown

The seed filter for the specified composite filter set does not exist.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent, or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Composite filter set deletion failure: seed filter set unknown

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set deletion failure: seed filter set unknown log

Composite filter set deletion failure: seed filter set unknown

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Composite filter set destruction failure data invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set destruction failure data invalid log

Composite filter set destruction failure data invalid

The system detected invalid data detected; Following is the possible reason: The Clone name must be specified and within the limited length (0-16).

Source	Severity
QoS	Serious

### Remedial action

Check the parameters and resolve, if any possible invalid values.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Composite filter set destruction failure: data invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set destruction failure: data invalid log

Composite filter set destruction failure: data invalid

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Composite filter set membership limits exceeded

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Composite filter set membership limits exceeded log

Composite filter set membership limits exceeded

The maximum number of composite members in a filter set is 16.

Source	Severity
QoS	Serious

### Remedial action

Enter at the most 16 composite members in a filter set.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Config areas already remapped on unit %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Config areas already remapped on unit %d log

Config areas already remapped on unit %d

Config areas were already remapped on this unit

Source	Severity
MCFG	Information

### Remedial action

No action required.



# Configuration block %d is now in use

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Configuration block %d is now in use log

Configuration block %d is now in use

Logs the configuration block currently used.

Source	Severity
MCFG	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Configuration does not exist

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Configuration does not exist log

Configuration does not exist

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Configuration saved to nv block # block\_number

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Configuration saved to nv block # block\_number log

Configuration saved to nv block # block\_number

This message appears when the configuration is saved to block n.

Source	Severity
config	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Configuration saved to nv block %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Configuration saved to nv block %d log

Configuration saved to nv block %d

**Source   Severity**

MCFG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Configured base unit detected, drop its discovery msg - %s line %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Configured base unit detected, drop its discovery msg - %s line %d log

Configured base unit detected, drop its discovery msg - %s line %d

Source	Severity
SMGR	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Conflicting action sources detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Conflicting action sources detected log

Conflicting action sources detected

Multiple actions specified from different sources (via policy match action, policy meter or classifier block) A combination of sources if prohibited.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Remove conflicts by using a single action source.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Conflicting egress interface and egress trunk data specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Conflicting egress interface and egress trunk data specified log

Conflicting egress interface and egress trunk data specified

FCoE Redirect profile element data is not correct.

Source	Severity
FCoE Redirect	Information

### Remedial action

Specify all required profile data.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Conflicting master block member information detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Conflicting master block member information detected log

Conflicting master block member information detected

Multiple master blocks detected.

Source	Severity
QoS	Serious

### Remedial action

Enter a single master block.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Conflicting policy role policy interface index data detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Conflicting policy role policy interface index data detected log

Conflicting policy role policy interface index data detected

Both role and interface index were specified.

Source	Severity
QoS	Serious

### Remedial action

Enter either a role or an interface index.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Conflicting policy role/policy interface index data detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Conflicting policy role/policy interface index data detected log

Conflicting policy role/policy interface index data detected

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Connection closed (failed login) IP address:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Connection closed (failed login) IP address: log

Connection closed (failed login) IP address:

The connection was disconnected after three login attempts failed.

Source	Severity
Telnet Server	Information

### Remedial action

Enter a valid username and password.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Connection closed (inactivity logout) IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Connection closed (inactivity logout) IP address log

Connection closed (inactivity logout) IP address

Client was disconnected by the server after 15 minutes of terminal inactivity.

Source	Severity
Telnet Server	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Connection closed (login timeout) IP address:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Connection closed (login timeout) IP address: log

Connection closed (login timeout) IP address:

The Telnet Login prompt message is available for the user input for one minute with maximum of three attempts. If you do not provide a valid username and password the connection will be disconnected.

Source	Severity
Telnet Server	Information

### Remedial action

Enter the correct username and password within one minute.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Connection closed (lost connection) IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Connection closed (lost connection) IP address log

Connection closed (lost connection) IP address

Client aborted the connection (RST message is sent).

Source	Severity
Telnet Server	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Connection closed (lost connection), IP address:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Connection closed (lost connection), IP address: log

Connection closed (lost connection), IP address:

Source	Severity
--------	----------

Telnet	
--------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Connection closed. Maximum number of sessions reached. IP address:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Connection closed. Maximum number of sessions reached. IP address: log

Connection closed. Maximum number of sessions reached. IP address:

The maximum number of active telnet connections has been reached.

Source	Severity
Telnet server	Information

### Remedial action

Close other active sessions in order to free Telnet server slots.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Connection closed. Maximum number of sessions reached. IP address:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Connection closed. Maximum number of sessions reached. IP address: log

Connection closed. Maximum number of sessions reached. IP address:

Telnet server has reached its maximum connections. No new connections currently allowed for the IP Address displayed in the log message.

Source	Severity
Telnet Server	Information

### Remedial action

Disconnect at least one telnet connection.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Connection closed (user logout), IP address:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Connection closed (user logout), IP address: log

Connection closed (user logout), IP address:

User ends telnet session. The connection is lost.

Source	Severity
Telnet Server	Information

### Remedial action

No action required.



# Cons activate vlan vlan id

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cons activate vlan vlan id log

Cons activate vlan vlan id

VLAN is activated.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Cons add vlan vlan id port unit port

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cons add vlan vlan id port unit port log

Cons add vlan vlan id port unit port

Port is added to VLAN.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cons create vlan vlan id type port

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cons create vlan vlan id type port log

Cons create vlan vlan id type port

New VLAN type port is created.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cons delete vlan vlan id port unit port

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cons delete vlan vlan id port unit port log

Cons delete vlan vlan id port unit port

Port is removed from VLAN.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cons delete vlan vlan id type port

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cons delete vlan vlan id type port log

Cons delete vlan vlan id type port

Existing VLAN type port is deleted.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cons set autopvid disable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cons set autopvid disable log

Cons set autopvid disable

Disable auto PVID.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cons set autopvid enable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cons set autopvid enable log

Cons set autopvid enable

Enable auto PVID.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cons set management vlan vlan id

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cons set management vlan vlan id log

Cons set management vlan vlan id

Management VLAN is set.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cons set port unit port pvid vlan id

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cons set port unit port pvid vlan id log

Cons set port unit port pvid vlan id

Port PVID is set.

Source	Severity
VLAN	Information

### Remedial action

No action required.





# Cons set port unit port tagging disable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cons set port unit port tagging disable log

Cons set port unit port tagging disable

Port tagging is disabled.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Cons set port unit port tagging enable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Cons set port unit port tagging enable log

Cons set port unit port tagging enable

Port tagging enabled.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Control VLAN does not exist

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Control VLAN does not exist log

Control VLAN does not exist

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# COS mapping distribution across stack failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## COS mapping distribution across stack failed log

COS mapping distribution across stack failed

Unable to commit COS mapping distribution across the stack.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CoS shaping distribution across stack failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CoS shaping distribution across stack failed log

CoS shaping distribution across stack failed

Unable to make CoS shaping distribution across the stack.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CoS shaping modifications not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CoS shaping modifications not supported log

CoS shaping modifications not supported

The system detected an internal error; The specified modifier option is not supported.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent, or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CoS shaping not supported with specified interface

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CoS shaping not supported with specified interface log

CoS shaping not supported with specified interface

The specified interface is unable to support the CoS shaping.

Source	Severity
QoS	Serious

### Remedial action

Enter a different interface.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Count action distribution across stack failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Count action distribution across stack failed log

Count action distribution across stack failed

Unable to commit changes across the stack.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Count action entry referenced by meter (deletion prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Count action entry referenced by meter (deletion prohibited) log

Count action entry referenced by meter (deletion prohibited)

Cannot delete a count action entry if it's referenced by a meter.

Source	Severity
QoS	Serious

### Remedial action

Remove the meter first.



# Count action entry referenced by policy (deletion prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Count action entry referenced by policy (deletion prohibited) log

Count action entry referenced by policy (deletion prohibited)

Cannot delete a count action if it's referenced by a policy.

Source	Severity
QoS	Serious

### Remedial action

Remove the policy first.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Count action modifications not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Count action modifications not supported log

Count action modifications not supported

The system detected an internal error; The specified modifier option is not supported.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# CVLAN already exists

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## CVLAN already exists log

CVLAN already exists

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# C-VLAN UNI already configured with same I-SID

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## C-VLAN UNI already configured with same I-SID log

C-VLAN UNI already configured with same I-SID

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



DAI: ARP packet with invalid IP/MAC binding dropped on untrusted port %d/%d. ARP packet has MAC source %02x-%02x-%02x-%02x-%02x-%02x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAI: ARP packet with invalid IP/MAC binding dropped on untrusted port %d/%d. ARP packet has MAC source %02x-%02x-%02x-%02x-%02x-%02x log

DAI: ARP packet with invalid IP/MAC binding dropped on untrusted port %d/%d. ARP packet has MAC source %02x-%02x-%02x-%02x-%02x-%02x

### Source    Severity

SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



DAI: ARP packet with invalid IP/MAC binding dropped on untrusted port %d/%d. ARP packet has MAC source %02x-%02x-%02x-%02x-%02x-%02x.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAI: ARP packet with invalid IP/MAC binding dropped on untrusted port %d/%d. ARP packet has MAC source %02x-%02x-%02x-%02x-%02x-%02x. log

DAI: ARP packet with invalid IP/MAC binding dropped on untrusted port %d/%d. ARP packet has MAC source %02x-%02x-%02x-%02x-%02x-%02x.

ARP packet is ingressed on a DAI untrusted port with a MAC address and IP address that does not match any entries in the binding table. This causes the packet to be dropped.

Source	Severity
DAI	Information

### Remedial action

Potential intruder. Isolate the offender.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DAI ARP packet with invalid IP MAC binding dropped on untrusted port unit# port#

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAI ARP packet with invalid IP MAC binding dropped on untrusted port unit# port# log

DAI ARP packet with invalid IP MAC binding dropped on untrusted port unit# port#

ARP packet ingressed on a DAI untrusted port with a hardware MAC address and IP address does not match any entries in the DHCP binding table. This violates the DAI integrity check and the packet is dropped.

Source	Severity
DAI	Information

### Remedial action

Isolate the offender.





# DAPP-detected DoS attack blocked: unit %d (many ports)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAPP-detected DoS attack blocked: unit %d (many ports) log

DAPP-detected DoS attack blocked: unit %d (many ports)

**Source   Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DAPP-detected DoS attack blocked: unit %d port %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAPP-detected DoS attack blocked: unit %d port %d log

DAPP-detected DoS attack blocked: unit %d port %d

**Source   Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DAPP-detected DoS attack blocked unit unit# (many ports)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAPP-detected DoS attack blocked unit unit# (many ports) log

DAPP-detected DoS attack blocked unit unit# (many ports)

A Denial of Service attack was blocked on the specified unit and on multiple ports.

Source	Severity
QoS	Information

### Remedial action

No action required.



# DAPP-detected DoS attack blocked unit unit# port port#

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAPP-detected DoS attack blocked unit unit# port port# log

DAPP-detected DoS attack blocked unit unit# port port#

A Denial of Service attack was blocked on the specified unit and port.

Source	Severity
QoS	Information

### Remedial action

No action required.



# DAPP resources not available (unit %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAPP resources not available (unit %d) log

DAPP resources not available (unit %d)

**Source   Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DAPP resources not available (unit unit# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAPP resources not available (unit unit# ) log

DAPP resources not available (unit unit# )

Some of the resources required are not available on all the interfaces.

Source	Severity
QoS	Serious

### Remedial action

Check for and remove unneeded resources.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DAPP support disable failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAPP support disable failure log

DAPP support disable failure

Unable to commit changes (disable DAAP) across the stack.

Source	Severity
QoS	Information

### Remedial action

Try again later, reset the QoS agent, reset the unit or check stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DAPP support enable failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAPP support enable failure log

DAPP support enable failure

Unable to commit changes (enable DAAP) across the stack.

Source	Severity
QoS	Information

### Remedial action

Try again later, reset the QoS agent, reset the unit or check stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# DAPP with statistics tracking in use (QoS disable prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAPP with statistics tracking in use (QoS disable prohibited) log

DAPP with statistics tracking in use (QoS disable prohibited)

Cannot disable the QoS system if DAAP with tracking statistics is enable.

Source	Severity
QoS	Serious

### Remedial action

Disable DAAP or change it's enabled state before disabling QoS.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Data distribution class class# across stack failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Data distribution class class# across stack failed log

Data distribution class class# across stack failed

Unable to commit changes across the stack.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Data distribution (class %d) across stack failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Data distribution (class %d) across stack failed log

Data distribution (class %d) across stack failed

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Data model version attribute value not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Data model version attribute value not supported log

Data model version attribute value not supported

Data versions 1 and 2 are currently supported in the system.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DAUR - Info Diag transfer finished

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAUR - Info Diag transfer finished log

DAUR - Info Diag transfer finished

Diag transfer finished.

Source	Severity
AUR	Information

### Remedial action

No action required.



# DAUR - Info: Diag transfer finished

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAUR - Info: Diag transfer finished log

DAUR - Info: Diag transfer finished

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DAUR - Info Receive request for diag image start transfer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAUR - Info Receive request for diag image start transfer log

DAUR - Info Receive request for diag image start transfer

The system received request for the diag image and started transferring.

Source	Severity
AUR	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DAUR - Info: Receive request for diag image, start transfer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAUR - Info: Receive request for diag image, start transfer log

DAUR - Info: Receive request for diag image, start transfer

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# DAUR - Info: Receive request for diag image. Unable to start transfer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAUR - Info: Receive request for diag image. Unable to start transfer log

DAUR - Info: Receive request for diag image. Unable to start transfer

Source	Severity
AUR	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DAUR - Info Receive request for diag image. Unable to transfer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAUR - Info Receive request for diag image. Unable to transfer log

DAUR - Info Receive request for diag image. Unable to transfer

Received request for diag image, unable to start transfer.

Source	Severity
AUR	Information

### Remedial action

No action required.



# DAUR - Info Send request for new diag image

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAUR - Info Send request for new diag image log

DAUR - Info Send request for new diag image

The system is sending request for new diag image.

Source	Severity
AUR	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DAUR - Info: Send request for new diag image

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAUR - Info: Send request for new diag image log

DAUR - Info: Send request for new diag image

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DAUR - Info Slave refuse transfer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAUR - Info Slave refuse transfer log

DAUR - Info Slave refuse transfer

Slave refuse transfer.

Source	Severity
AUR	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DAUR - Info: Slave refuse transfer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAUR - Info: Slave refuse transfer log

DAUR - Info: Slave refuse transfer

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DAUR - Info Start receive image

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAUR - Info Start receive image log

DAUR - Info Start receive image

The image is being received.

Source	Severity
AUR	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DAUR - Info: Start receive image

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAUR - Info: Start receive image log

DAUR - Info: Start receive image

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# DAUR - The hardware is not compatible with the image\_version\_number version

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAUR - The hardware is not compatible with the image\_version\_number version log

DAUR - The hardware is not compatible with the image\_version\_number version

The hardware is not compatible.

Source	Severity
AUR	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DAUR - The hardware is not compatible with the %s version

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAUR - The hardware is not compatible with the %s version log

DAUR - The hardware is not compatible with the %s version

**Source**   **Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DAUR - Warning: Cannot get FLASH resource

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAUR - Warning: Cannot get FLASH resource log

DAUR - Warning: Cannot get FLASH resource

The system cannot get the flash resource.

Source	Severity
AUR	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DAUR - Warning Diag image check sum ERROR

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAUR - Warning Diag image check sum ERROR log

DAUR - Warning Diag image check sum ERROR

Diag image check sum error.

Source	Severity
AUR	Serious

### Remedial action

No action required.



# DAUR - Warning: Diag image check sum ERROR

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAUR - Warning: Diag image check sum ERROR log

DAUR - Warning: Diag image check sum ERROR

**Source   Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DAUR - Warning Slave diag image check sum ERROR

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAUR - Warning Slave diag image check sum ERROR log

DAUR - Warning Slave diag image check sum ERROR

Slave diag image check sum error.

Source	Severity
AUR	Serious

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DAUR - Warning: Slave diag image check sum ERROR

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DAUR - Warning: Slave diag image check sum ERROR log

DAUR - Warning: Slave diag image check sum ERROR

**Source   Severity**

AUR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DB Ack from %s for unit #%d, mask 0x%X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DB Ack from %s for unit #%d, mask 0x%X log

DB Ack from %s for unit #%d, mask 0x%X

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Default ifc assignment failure [%d port(s)]: ifc QoS-disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Default ifc assignment failure [%d port(s)]: ifc QoS-disabled log

Default ifc assignment failure [%d port(s)]: ifc QoS-disabled

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Default ifc assignment failure port# port(s) ifc QoS-disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Default ifc assignment failure port# port(s) ifc QoS-disabled log

Default ifc assignment failure port# port(s) ifc QoS-disabled

Unable to set the specified port to it's default state.

Source	Severity
QoS	Serious

### Remedial action

Reset the QoS agent or reset the unit.



# Default VRF Name can not be changed.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Default VRF Name can not be changed. log

Default VRF Name can not be changed.

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Delayed filter set installation completed (time %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Delayed filter set installation completed (time %d) log

Delayed filter set installation completed (time %d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Delayed filter set installation started (time %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Delayed filter set installation started (time %d) log

Delayed filter set installation started (time %d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Delete all interfaces before set SPBM globally

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Delete all interfaces before set SPBM globally log

Delete all interfaces before set SPBM globally

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Delete manual area before set SPBM globally

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Delete manual area before set SPBM globally log

Delete manual area before set SPBM globally

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Delete SPBM instance before set SPBM globally

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Delete SPBM instance before set SPBM globally log

Delete SPBM instance before set SPBM globally

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Delete SPBM VLAN before set SPBM globally

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Delete SPBM VLAN before set SPBM globally log

Delete SPBM VLAN before set SPBM globally

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Delete summary address before set SPBM globally

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Delete summary address before set SPBM globally log

Delete summary address before set SPBM globally

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Destination MAC address and mask values out-of-sync

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Destination MAC address and mask values out-of-sync log

Destination MAC address and mask values out-of-sync

The destination MAC address and mask do not correspond (at least one address bit not included in mask is set).

Source	Severity
QoS	Serious

### Remedial action

Modify the destination MAC address or mask.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Destination unit not found

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Destination unit not found log

Destination unit not found

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



%d event sent, unit mask 0x%02X, appl  
mask 0x%08X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## %d event sent, unit mask 0x%02X, appl mask 0x%08X log

%d event sent, unit mask 0x%02X, appl mask 0x%08X

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



DHCP Option 82 information could not be added to the DHCP packet because the resulting packet would be too long

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Option 82 information could not be added to the DHCP packet because the resulting packet would be too long log

DHCP Option 82 information could not be added to the DHCP packet because the resulting packet would be too long

**Source**   **Severity**  
SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP packet with mismatch MAC address dropped on un-trusted port %d/%d mac(0x%08x)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP packet with mismatch MAC address dropped on un-trusted port %d/%d mac(0x%08x) log

DHCP packet with mismatch MAC address dropped on un-trusted port %d/%d mac(0x%08x)

**Source**                      **Severity**

DHCP Snoop

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP packet with mismatch MAC address dropped on un-trusted port unit# port# mac(MAC ADDRESS)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP packet with mismatch MAC address dropped on un-trusted port unit# port# mac(MAC ADDRESS) log

DHCP packet with mismatch MAC address dropped on un-trusted port unit# port# mac(MAC ADDRESS)

DHCP packet with the ethernet source MAC address not matching with the DHCP client hardware MAC address ingressed on an DHCP Snoop untrusted port. This violates the DHCP Snoop integrity check and the packet is dropped.

Source	Severity
DHCP Snoop	Information

### Remedial action

Isolate the offender.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# DHCP relay is now disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP relay is now disabled log

DHCP relay is now disabled

**Source**   **Severity**

DHCPR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP reply packet received without request on port %d/%d mac(0x%08x)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP reply packet received without request on port %d/%d mac(0x%08x) log

DHCP reply packet received without request on port %d/%d mac(0x%08x)

Source	Severity
--------	----------

DHCP Snoop	
------------	--

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop: DHCP ACK dropped on untrusted port %d/%d (not allowed on untrusted port)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP ACK dropped on untrusted port %d/%d (not allowed on untrusted port) log

DHCP Snoop: DHCP ACK dropped on untrusted port %d/%d (not allowed on untrusted port)

**Source**   **Severity**  
SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop DHCP ACK dropped on untrusted port unit# port# (not allowed on untrusted port)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop DHCP ACK dropped on untrusted port unit# port# (not allowed on untrusted port) log

DHCP Snoop DHCP ACK dropped on untrusted port unit# port# (not allowed on untrusted port)

DHCP ACK reply packet ingressed on an untrusted DHCP Snoop port. This violates the DHCP Snoop integrity check and the packet is dropped.

Source	Severity
DHCP Snoop	Information

### Remedial action

Isolate the offender.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop DHCP binding table is full additional DHCP clients will not be added to the binding table

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop DHCP binding table is full additional DHCP clients will not be added to the binding table log

DHCP Snoop DHCP binding table is full additional DHCP clients will not be added to the binding table

The maximum number of DHCP binding entries (1024) reached. Any additional DHCP client entries will not be added to the binding table.

Source	Severity
DHCP Snoop	Information

### Remedial action

Scale down the number of DHCP clients.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop:DHCP binding table is full, additional DHCP clients will not be added to the binding table

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop:DHCP binding table is full, additional DHCP clients will not be added to the binding table log

DHCP Snoop:DHCP binding table is full, additional DHCP clients will not be added to the binding table

Source	Severity
DHCP Snoop	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



DHCP Snoop: DHCP binding table is full on unit %d, additional DHCP clients will not be added on this unit

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP binding table is full on unit %d, additional DHCP clients will not be added on this unit log

DHCP Snoop: DHCP binding table is full on unit %d, additional DHCP clients will not be added on this unit

**Source**   **Severity**  
SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop: DHCP DISCOVER dropped on port %d/%d (source MAC not matching client MAC)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP DISCOVER dropped on port %d/%d (source MAC not matching client MAC) log

DHCP Snoop: DHCP DISCOVER dropped on port %d/%d (source MAC not matching client MAC)

A DHCP Discover packet was received on port %d/%d but the source MAC Address displayed in the log message did not match the client MAC address.

Source	Severity
DHCP Snoop	Information

### Remedial action

Check the sending client. It may be an intrusion.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





DHCP Snoop: DHCP DISCOVER dropped on port %d/%d (source MAC %02x-%02x-%02x-%02x-%02x not matching client MAC %02x-%02x-%02x-%02x-%02x)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP DISCOVER dropped on port %d/%d (source MAC %02x-%02x-%02x-%02x-%02x-%02x not matching client MAC %02x-%02x-%02x-%02x-%02x-%02x) log

DHCP Snoop: DHCP DISCOVER dropped on port %d/%d (source MAC %02x-%02x-%02x-%02x-%02x-%02x not matching client MAC %02x-%02x-%02x-%02x-%02x-%02x)

### Source    Severity

SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



DHCP Snoop: DHCP INFORM dropped on port %d/%d (source MAC %02x-%02x-%02x-%02x-%02x-%02x not matching client MAC %02x-%02x-%02x-%02x-%02x-%02x)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP INFORM dropped on port %d/%d (source MAC %02x-%02x-%02x-%02x-%02x-%02x not matching client MAC %02x-%02x-%02x-%02x-%02x-%02x) log

DHCP Snoop: DHCP INFORM dropped on port %d/%d (source MAC %02x-%02x-%02x-%02x-%02x-%02x not matching client MAC %02x-%02x-%02x-%02x-%02x-%02x)

### Source    Severity

SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop: DHCP LEASEACTIVE dropped on untrusted port %d/%d (not allowed on untrusted port)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP LEASEACTIVE dropped on untrusted port %d/%d (not allowed on untrusted port) log

DHCP Snoop: DHCP LEASEACTIVE dropped on untrusted port %d/%d (not allowed on untrusted port)

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop: DHCP LEASEQUERY dropped on untrusted port %d/%d (not allowed on untrusted port)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP LEASEQUERY dropped on untrusted port %d/%d (not allowed on untrusted port) log

DHCP Snoop: DHCP LEASEQUERY dropped on untrusted port %d/%d (not allowed on untrusted port)

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop: DHCP LEASEUNASSIGNED dropped on untrusted port %d/%d (not allowed on untrusted port)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP LEASEUNASSIGNED dropped on untrusted port %d/%d (not allowed on untrusted port) log

DHCP Snoop: DHCP LEASEUNASSIGNED dropped on untrusted port %d/%d (not allowed on untrusted port)

**Source**   **Severity**  
SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop: DHCP LEASEUNKNOWN dropped on untrusted port %d/%d (not allowed on untrusted port)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP LEASEUNKNOWN dropped on untrusted port %d/%d (not allowed on untrusted port) log

DHCP Snoop: DHCP LEASEUNKNOWN dropped on untrusted port %d/%d (not allowed on untrusted port)

**Source**   **Severity**  
SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop: DHCP NAK dropped on untrusted port %d/%d (not allowed on untrusted port)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP NAK dropped on untrusted port %d/%d (not allowed on untrusted port) log

DHCP Snoop: DHCP NAK dropped on untrusted port %d/%d (not allowed on untrusted port)

**Source**   **Severity**  
SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop DHCP NAK dropped on untrusted port unit# port# (not allowed on untrusted port)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop DHCP NAK dropped on untrusted port unit# port# (not allowed on untrusted port) log

DHCP Snoop DHCP NAK dropped on untrusted port unit# port# (not allowed on untrusted port)

DHCP NAK reply packet ingressed on an DHCP Snoop untrusted port. This violates the DHCP Snoop integrity check and the packet is dropped.

Source	Severity
DHCP Snoop	Information

### Remedial action

Isolate the offender.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# DHCP Snoop: DHCP OFFER dropped on untrusted port %d/%d (not allowed on untrusted port)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP OFFER dropped on untrusted port %d/%d (not allowed on untrusted port) log

DHCP Snoop: DHCP OFFER dropped on untrusted port %d/%d (not allowed on untrusted port)

**Source**   **Severity**  
SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop DHCP OFFER dropped on untrusted port unit# port# (not allowed on untrusted port)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop DHCP OFFER dropped on untrusted port unit# port# (not allowed on untrusted port) log

DHCP Snoop DHCP OFFER dropped on untrusted port unit# port# (not allowed on untrusted port)

DHCP OFFER reply packet ingressed on an DHCP Snoop untrusted port. This violates the DHCP Snoop integrity check and the packet is dropped.

Source	Severity
DHCP Snoop	Information

### Remedial action

Isolate the offender.



DHCP Snoop: DHCP packet dropped on port %d/%d - static entry with the same MAC %02x-%02x-%02x-%02x-%02x-%02x in binding table

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP packet dropped on port %d/%d - static entry with the same MAC %02x-%02x-%02x-%02x-%02x-%02x in binding table log

DHCP Snoop: DHCP packet dropped on port %d/%d - static entry with the same MAC %02x-%02x-%02x-%02x-%02x-%02x in binding table

DHCP packet ingressed on the specified port is dropped as a static entry with the same MAC address as the DHCP client MAC address is found in the binding table. This violates the DHCP Snoop integrity check and the packet is dropped.

Source	Severity
DHCP Snoop	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



DHCP Snoop: DHCP packet dropped on port %d/%d - static entry with the same MAC %02x-%02x-%02x-%02x-%02x-%02x in binding table

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP packet dropped on port %d/%d - static entry with the same MAC %02x-%02x-%02x-%02x-%02x-%02x in binding table log

DHCP Snoop: DHCP packet dropped on port %d/%d - static entry with the same MAC %02x-%02x-%02x-%02x-%02x-%02x in binding table

Drop static entry.

Source	Severity
SNMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



DHCP Snoop: DHCP RELEASE/DECLINE  
dropped on port %d/%d (MAC %02x-  
%02x-%02x-%02x-%02x-%02x does  
not exist in binding table)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP RELEASE/DECLINE dropped on port %d/%d (MAC %02x-%02x-%02x-%02x-%02x-%02x does not exist in binding table) log

DHCP Snoop: DHCP RELEASE/DECLINE dropped on port %d/%d (MAC %02x-%02x-%02x-%02x-%02x-%02x does not exist in binding table)

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



DHCP Snoop: DHCP RELEASE/DECLINE  
dropped on port %d/%d (MAC %02x-  
%02x-%02x-%02x-%02x-%02x is  
associated to port %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP RELEASE/DECLINE dropped on port %d/%d (MAC %02x-%02x-%02x-%02x-%02x-%02x is associated to port %d/%d) log

DHCP Snoop: DHCP RELEASE/DECLINE dropped on port %d/%d (MAC %02x-%02x-%02x-%02x-%02x-%02x is associated to port %d/%d)

**Source**   **Severity**  
SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



DHCP Snoop: DHCP RELEASE/DECLINE  
dropped on untrusted port %d/%d  
because MAC Addr(0x%08x) is  
associated to port %d/%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop:DHCP RELEASE/DECLINE dropped on untrusted port %d/%d because MAC Addr(0x%08x) is associated to port %d/%d log

DHCP Snoop:DHCP RELEASE/DECLINE dropped on untrusted port %d/%d because MAC Addr(0x%08x) is associated to port %d/%d

**Source**                      **Severity**

DHCP Snoop

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop:DHCP RELEASE/DECLINE dropped on untrusted port %d/%d (MAC Addr(0x%08x) does not exist in binding table)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop:DHCP RELEASE/DECLINE dropped on untrusted port %d/%d (MAC Addr(0x%08x) does not exist in binding table) log

DHCP Snoop:DHCP RELEASE/DECLINE dropped on untrusted port %d/%d (MAC Addr(0x%08x) does not exist in binding table)

**Source**                      **Severity**

DHCP Snoop

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





DHCP Snoop DHCP RELEASE DECLINE  
dropped on untrusted port unit# port#  
because MAC Addr( MACaddress ) is  
associated to port unit# port#

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop DHCP RELEASE DECLINE dropped on untrusted port unit# port# because MAC Addr( MACaddress ) is associated to port unit# port# log

DHCP Snoop DHCP RELEASE DECLINE dropped on untrusted port unit# port# because MAC Addr( MACaddress ) is associated to port unit# port#

DHCP RELEASE or DECLINE packet with the DHCP client hardware MAC address and client port from the binding table ingressed on a different DHCP Snoop untrusted port. This violates the DHCP Snoop integrity check and the packet is dropped.

Source	Severity
DHCP Snoop	Information

### Remedial action

Isolate the offender.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop DHCP RELEASE DECLINE dropped on untrusted port unit# port# (MAC Addr(MACaddress ) does not exist in binding table)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop DHCP RELEASE DECLINE dropped on untrusted port unit# port# (MAC Addr(MACaddress ) does not exist in binding table) log

DHCP Snoop DHCP RELEASE DECLINE dropped on untrusted port unit# port# (MAC Addr(MACaddress ) does not exist in binding table)

DHCP RELEASE or DECLINE packet with the DHCP client hardware MAC address is not found in the binding table ingressed on a DHCP Snoop untrusted port. This violates the DHCP Snoop integrity check and the packet is dropped.

Source	Severity
DHCP Snoop	Information

### Remedial action

Isolate the offender.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



DHCP Snoop: DHCP REPLY with MAC %02x-%02x-%02x-%02x-%02x-%02x and IP Lease %d.%d.%d.%d dropped (no DHCP REQUEST was received)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP REPLY with MAC %02x-%02x-%02x-%02x-%02x-%02x and IP Lease %d.%d.%d.%d dropped (no DHCP REQUEST was received) log

DHCP Snoop: DHCP REPLY with MAC %02x-%02x-%02x-%02x-%02x-%02x and IP Lease %d.%d.%d.%d dropped (no DHCP REQUEST was received)

**Source**   **Severity**  
SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



DHCP Snoop: DHCP REQUEST dropped on port %d/%d (source MAC %02x-%02x-%02x-%02x-%02x not matching client MAC %02x-%02x-%02x-%02x-%02x)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP REQUEST dropped on port %d/%d (source MAC %02x-%02x-%02x-%02x-%02x-%02x not matching client MAC %02x-%02x-%02x-%02x-%02x-%02x) log

DHCP Snoop: DHCP REQUEST dropped on port %d/%d (source MAC %02x-%02x-%02x-%02x-%02x-%02x not matching client MAC %02x-%02x-%02x-%02x-%02x-%02x)

### Source    Severity

SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



DHCP Snoop: DHCP REQUEST dropped on untrusted port %d/%d due to Source MAC Address (0x%08x) not matching DHCP client MAC Address (0x%08x)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP REQUEST dropped on untrusted port %d/%d due to Source MAC Address (0x%08x) not matching DHCP client MAC Address (0x%08x) log

DHCP Snoop: DHCP REQUEST dropped on untrusted port %d/%d due to Source MAC Address (0x%08x) not matching DHCP client MAC Address (0x%08x)

Source	Severity
DHCP Snoop	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop DHCP REQUEST dropped on un-trusted port unit# port# due to source MAC address(MAC ADDRESS) not matching DHCP client

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop DHCP REQUEST dropped on un-trusted port unit# port# due to source MAC address(MAC ADDRESS) not matching DHCP client log

DHCP Snoop DHCP REQUEST dropped on un-trusted port unit# port# due to source MAC address(MAC ADDRESS) not matching DHCP client

DHCP packet with the ethernet source MAC address not matching with the DHCP client hardware MAC address ingressed on an DHCP Snoop untrusted port. This violates the DHCP Snoop integrity check and the packet is dropped.

Source	Severity
DHCP Snoop	Information

### Remedial action

Isolate the offender.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop DHCP snooping binding table restored successfully from TFTP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop DHCP snooping binding table restored successfully from TFTP address log

DHCP Snoop DHCP snooping binding table restored successfully from TFTP address

External-save/restore was unsuccessful.

Source	Severity
DHCP Snoop	Information

### Remedial action

Check TFTP connection or the USB target for availability.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop: DHCP snooping binding table restored successfully from TFTP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP snooping binding table restored successfully from TFTP address log

DHCP Snoop: DHCP snooping binding table restored successfully from TFTP address

Source	Severity
SNMP	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# DHCP Snoop: DHCP snooping binding table restored successfully from USB unit %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP snooping binding table restored successfully from USB unit %d log

DHCP Snoop: DHCP snooping binding table restored successfully from USB unit %d

**Source**   **Severity**  
SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop DHCP snooping binding table restored successfully from USB unit unit#

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop DHCP snooping binding table restored successfully from USB unit unit# log

DHCP Snoop DHCP snooping binding table restored successfully from USB unit unit#

External-save/restore was unsuccessful on the mentioned target.

Source	Severity
DHCP Snoop	Information

### Remedial action

Check TFTP connection or the USB target for availability.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop: DHCP snooping binding table restore from SFTP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP snooping binding table restore from SFTP address log

DHCP Snoop: DHCP snooping binding table restore from SFTP address

The message is logged with the SNMP Trap: bsDhcpSnoopingExtSaveSFTPRestoreFailure / \* 1.3.6.1.4.1.45.5.17.0.21 \* / This notification is generated when a DHCP snooping binding entry is not restored from an external file with SFTP.

Source	Severity
DHCP Snoop	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop: DHCP snooping binding table restore from SFTP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP snooping binding table restore from SFTP address log

DHCP Snoop: DHCP snooping binding table restore from SFTP address

Source	Severity
DHCP Snoop	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop: DHCP snooping binding table restore from TFTP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP snooping binding table restore from TFTP address log

DHCP Snoop: DHCP snooping binding table restore from TFTP address

Source	Severity
SNMP	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop DHCP snooping binding table restore from TFTP address A.B.C.D IPv6\_address failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop DHCP snooping binding table restore from TFTP address A.B.C.D IPv6\_address failed log

DHCP Snoop DHCP snooping binding table restore from TFTP address A.B.C.D IPv6\_address failed

External-save/restore was unsuccessful on the mentioned target.

Source	Severity
DHCP Snoop	Information

### Remedial action

Check TFTP connection or the USB target for availability.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop: DHCP snooping binding table restore from USB unit %d, failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP snooping binding table restore from USB unit %d, failed log

DHCP Snoop: DHCP snooping binding table restore from USB unit %d, failed

Source	Severity
SNMP	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop DHCP snooping binding table restore from USB unit unit# failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop DHCP snooping binding table restore from USB unit unit# failed log

DHCP Snoop DHCP snooping binding table restore from USB unit unit# failed

External-save/restore was unsuccessful.

Source	Severity
DHCP Snoop	Information

### Remedial action

Check TFTP connection or the USB target for availability.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# DHCP Snoop: DHCP snooping binding table saved successfully to SFTP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP snooping binding table saved successfully to SFTP address log

DHCP Snoop: DHCP snooping binding table saved successfully to SFTP address

The message is logged with the SNMP Trap: bsDhcpSnoopingExtSaveSFTPSyncSuccess. /\* 1.3.6.1.4.1.45.5.17.0.18 \*/ This notification is generated when a DHCP snooping binding entry is successfully saved to external file with SFTP.

Source	Severity
DHCP Snoop	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop: DHCP snooping binding table saved successfully to SFTP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP snooping binding table saved successfully to SFTP address log

DHCP Snoop: DHCP snooping binding table saved successfully to SFTP address

Source	Severity
DHCP Snoop	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop DHCP snooping binding table saved successfully to TFTP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop DHCP snooping binding table saved successfully to TFTP address log

DHCP Snoop DHCP snooping binding table saved successfully to TFTP address

External-save/restore was unsuccessful on the mentioned target.

Source	Severity
DHCP Snoop	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop: DHCP snooping binding table saved successfully to TFTP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP snooping binding table saved successfully to TFTP address log

DHCP Snoop: DHCP snooping binding table saved successfully to TFTP address

Source	Severity
SNMP	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop: DHCP snooping binding table saved successfully to USB unit %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP snooping binding table saved successfully to USB unit %d log

DHCP Snoop: DHCP snooping binding table saved successfully to USB unit %d

**Source**   **Severity**  
SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop DHCP snooping binding table saved successfully to USB unit unit#

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop DHCP snooping binding table saved successfully to USB unit unit# log

DHCP Snoop DHCP snooping binding table saved successfully to USB unit unit#

External-save/restore was unsuccessful on the mentioned target.

Source	Severity
DHCP Snoop	Information

### Remedial action

No action required.



# DHCP Snoop: DHCP snooping binding table save to SFTP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP snooping binding table save to SFTP address log

DHCP Snoop: DHCP snooping binding table save to SFTP address

Error while saving the DHCP binding table to SFTP server.

Source	Severity
DHCP Snoop	Information

### Remedial action

Check connection and configuration.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop: DHCP snooping binding table save to SFTP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP snooping binding table save to SFTP address log

DHCP Snoop: DHCP snooping binding table save to SFTP address

Source	Severity
DHCP Snoop	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# DHCP Snoop: DHCP snooping binding table save to TFTP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP snooping binding table save to TFTP address log

DHCP Snoop: DHCP snooping binding table save to TFTP address

**Source**   **Severity**  
SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop DHCP snooping binding table save to TFTP address A.B.C.D IPv6\_address failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop DHCP snooping binding table save to TFTP address A.B.C.D IPv6\_address failed log

DHCP Snoop DHCP snooping binding table save to TFTP address A.B.C.D IPv6\_address failed

External-save/restore was unsuccessful on the mentioned target.

Source	Severity
DHCP Snoop	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop: DHCP snooping binding table save to TFTP address, failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP snooping binding table save to TFTP address, failed log

DHCP Snoop: DHCP snooping binding table save to TFTP address, failed

External-save/restore occurred successfully on the mentioned target.

Source	Severity
DHCP Snoop	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop: DHCP snooping binding table save to USB unit %d, failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP snooping binding table save to USB unit %d, failed log

DHCP Snoop: DHCP snooping binding table save to USB unit %d, failed

Source	Severity
SNMP	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop DHCP snooping binding table save to USB unit unit# failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop DHCP snooping binding table save to USB unit unit# failed log

DHCP Snoop DHCP snooping binding table save to USB unit unit# failed

External-save/restore was unsuccessful on the mentioned target.

Source	Severity
DHCP Snoop	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop: DHCP snooping binding table successfully restored from SFTP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP snooping binding table successfully restored from SFTP address log

DHCP Snoop: DHCP snooping binding table successfully restored from SFTP address

The message is logged with the SNMP Trap: bsDhcpSnoopingExtSaveSFTPRestoreSuccess /\* 1.3.6.1.4.1.45.5.17.0.20 \*/ This notification is generated when a DHCP snooping binding entry is restored successfully from an external file with SFTP.

Source	Severity
DHCP Snoop	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop: DHCP snooping binding table successfully restored from SFTP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP snooping binding table successfully restored from SFTP address log

DHCP Snoop: DHCP snooping binding table successfully restored from SFTP address

### Source

DHCP Snoop

### Severity

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop DHCP snooping entry entry number not restored due to expired lease

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop DHCP snooping entry entry number not restored due to expired lease log

DHCP Snoop DHCP snooping entry entry number not restored due to expired lease

Binding entry could not be restored as the lease expired.

Source	Severity
DHCP Snoop	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# DHCP Snoop DHCP snooping entry entry number not restored due to MAC conflict

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop DHCP snooping entry entry number not restored due to MAC conflict log

DHCP Snoop DHCP snooping entry entry number not restored due to MAC conflict

Binding entry could not be restored due to MAC conflict.

Source	Severity
DHCP Snoop	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop DHCP snooping entry entry number not restored due to parsing failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop DHCP snooping entry entry number not restored due to parsing failure log

DHCP Snoop DHCP snooping entry entry number not restored due to parsing failure

Binding entry could not be restored due to various parsing failures.

Source	Severity
DHCP Snoop	Information

### Remedial action

Check and modify the external-save file for unexpected modifications in entry syntax.



# DHCP Snoop DHCP snooping entry with MAC MacAddress not restored on invalid interface unit# port#

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop DHCP snooping entry with MAC MacAddress not restored on invalid interface unit# port# log

DHCP Snoop DHCP snooping entry with MAC MacAddress not restored on invalid interface unit# port#

Binding entry could not be restored due to an invalid interface (unit/ port combination read from external file is no longer available or invalid altogether).

Source	Severity
DHCP Snoop	Information

### Remedial action

Check the unit/port combinations in the external-save file with your actual topology, and modify the external-save file if necessary.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored (expired lease)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored (expired lease) log

DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored (expired lease)

**Source**   **Severity**  
SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored (invalid interface %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored (invalid interface %d/%d) log

DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored (invalid interface %d/%d)

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored (invalid Vlan %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored (invalid Vlan %d) log

DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored (invalid Vlan %d)

External-save entry could not be restored due to an invalid VLAN.

Source	Severity
DHCP Snoop	Information

### Remedial action

Compare external entry VLAN against currently configured VLANs and change configuration if necessary.



# DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored (MAC conflict)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored (MAC conflict) log

DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored (MAC conflict)

**Source**   **Severity**  
SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored on trusted interface %d/%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored on trusted interface %d/%d log

DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored on trusted interface %d/%d

The message is logged with the SNMP trap bsDhcpSnoopingExtSaveEntryIfTrustedConflict. This notification is generated when a DHCP snooping binding entry fails to restore from an external file on a trusted interface.

Source	Severity
DHCP Snoop	Information

### Remedial action

No action required.





# DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored (parsing failure)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored (parsing failure) log

DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored (parsing failure)

**Source**   **Severity**  
SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop: DHCP snooping entry 0x%08x not restored due to expired lease

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP snooping entry 0x%08x not restored due to expired lease log

DHCP Snoop: DHCP snooping entry 0x%08x not restored due to expired lease

**Source**                      **Severity**

DHCP Snoop

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop: DHCP snooping entry 0x%08x not restored due to MAC conflict

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP snooping entry 0x%08x not restored due to MAC conflict log

DHCP Snoop: DHCP snooping entry 0x%08x not restored due to MAC conflict

**Source**                      **Severity**

DHCP Snoop

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop: DHCP snooping entry 0x%08x not restored due to parsing failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP snooping entry 0x%08x not restored due to parsing failure log

DHCP Snoop: DHCP snooping entry 0x%08x not restored due to parsing failure

Source	Severity
--------	----------

DHCP Snoop	
------------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop: DHCP snooping entry 0x%08x not restored on invalid interface %d/%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP snooping entry 0x%08x not restored on invalid interface %d/%d log

DHCP Snoop: DHCP snooping entry 0x%08x not restored on invalid interface %d/%d

Source	Severity
--------	----------

DHCP Snoop	
------------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop: DHCP snooping entry 0x%08x not restored on trusted interface %d/%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: DHCP snooping entry 0x%08x not restored on trusted interface %d/%d log

DHCP Snoop: DHCP snooping entry 0x%08x not restored on trusted interface %d/%d

Binding entry could not be restored because the interface of the externally saved entry is currently configured as DHCPSPN trusted

Source	Severity
DHCP Snoop	Information

### Remedial action

Check configuration.



# DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x not restored (invalid Vlan %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored (invalid Vlan %d) log

DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored (invalid Vlan %d)

The message is logged with the SNMP trap bsDhcpSnoopingExtSaveEntryInvalidVlan. /\* b45.5.17.0.17 \*/ This notification is generated when a DHCP snooping binding entry is not restored from an external file on a invalid VLAN.

Source	Severity
DHCP Snoop	Information

### Remedial action

No action required.



# DHCP Snoop: NTP is not synchronized; external save of DHCP snooping entries not possible

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: NTP is not synchronized; external save of DHCP snooping entries not possible log

DHCP Snoop: NTP is not synchronized; external save of DHCP snooping entries not possible

**Source**                      **Severity**

DHCP Snoop

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# DHCP Snoop NTP is not synchronized; external save restore of DHCP snooping entries not possible

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop NTP is not synchronized; external save restore of DHCP snooping entries not possible log

DHCP Snoop NTP is not synchronized; external save restore of DHCP snooping entries not possible

The external actions (Restore or Save) not possible, as the Unit (S)NTP server is not synchronized.

Source	Severity
DHCP Snoop	Information

### Remedial action

Make sure time source is properly set to (S)NTP and the server is synchronized.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DHCP Snoop: NTP is not synchronized; external save/restore of DHCP snooping entries not possible

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DHCP Snoop: NTP is not synchronized; external save/restore of DHCP snooping entries not possible log

DHCP Snoop: NTP is not synchronized; external save/restore of DHCP snooping entries not possible

**Source**   **Severity**  
SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Different classifier component masks keys in block detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Different classifier component masks keys in block detected log

Different classifier component masks keys in block detected

Examines classifier criteria to determine whether the specified data is supported in the context of the target interface(s).

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Use a compatible interface or change the conflicting filter criteria.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Different classifier component masks/keys in block detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Different classifier component masks/keys in block detected log

Different classifier component masks/keys in block detected

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Different enhanced secure mode settings than BU. Unit reconfigured and rebooted.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Different enhanced secure mode settings than BU. Unit reconfigured and rebooted. log

Different enhanced secure mode settings than BU. Unit reconfigured and rebooted.

The unit joining the stack was in a different enhanced secure mode compared to BU. Set BU enhanced secure mode, reset to factory configuration and rebooted.

Source	Severity
Stack Manager	Serious

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Different spanning-tree mode configured than BU. Unit re-configured and rebooted

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Different spanning-tree mode configured than BU. Unit re-configured and rebooted log

Different spanning-tree mode configured than BU. Unit re-configured and rebooted

Spanning tree mode is different than BU's.

Source	Severity
Stack Manager	Serious

### Remedial action

Wait for re-configuration and reboot cycle.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Different spanning-tree mode configured than BU. Unit reconfigured and rebooted.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Different spanning-tree mode configured than BU. Unit reconfigured and rebooted. log

Different spanning-tree mode configured than BU. Unit reconfigured and rebooted.

Current unit has different spanning-tree mode than the one used by BU. Unit will be reconfigured and rebooted.

Source	Severity
Stack Manager	Serious

### Remedial action

No action required.



# Different SPBM operating mode than BU. Unit reconfigured and rebooted %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Different SPBM operating mode than BU. Unit reconfigured and rebooted %s log

Different SPBM operating mode than BU. Unit reconfigured and rebooted %s

**Source**   **Severity**  
SMGR

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Disable IS-IS before set SPBM globally

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Disable IS-IS before set SPBM globally log

Disable IS-IS before set SPBM globally

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Disabling trunk ports for loop prevention:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Disabling trunk ports for loop prevention: log

Disabling trunk ports for loop prevention:

**Source**   **Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Disallowed connection Access Reject for user :

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Disallowed connection Access Reject for user : log

Disallowed connection Access Reject for user :

RADIUS - disallowed connection attempt for the user starting with the given name due to invalid user credentials.

Source	Severity
RADIUS	Information

### Remedial action

Correct the user-configuration at the radius server when needed and retry entering valid user credentials.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Disallowed connection attempt from IP address:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Disallowed connection attempt from IP address: log

Disallowed connection attempt from IP address:

Telnet-access is disabled or the client IP address does not pass the telnet-access/IP manager rules. Hence, the client connection is dropped.

Source	Severity
Telnet Server	Information

### Remedial action

Check the telnet-access/IP manager configuration and modify the settings accordingly.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Disallowed connection attempt - too many telnet sessions

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Disallowed connection attempt - too many telnet sessions log

Disallowed connection attempt - too many telnet sessions

The attempt to telnet session connection is disallowed, as the maximum number of telnet sessions is reached.

Source	Severity
Telnet Server	Information

### Remedial action

No action required.



# Disallowed connection Invalid SvcType for user :

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Disallowed connection Invalid SvcType for user : log

Disallowed connection Invalid SvcType for user :

RADIUS - disallowed connection attempt for the user starting with the given name due to invalid service type

Source	Severity
RADIUS	Information

### Remedial action

Send the correct svc-type from the radius server when needed.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Discovery delayed due to NSNA configuration in progress

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Discovery delayed due to NSNA configuration in progress log

Discovery delayed due to NSNA configuration in progress

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Discovery ignored due to agent image download in progress

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Discovery ignored due to agent image download in progress log

Discovery ignored due to agent image download in progress

**Source    Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Discovery message not received

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Discovery message not received log

Discovery message not received

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Discovery Msg dropped, expiry time exceeded %d ticks, actual %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Discovery Msg dropped, expiry time exceeded %d ticks, actual %d log

Discovery Msg dropped, expiry time exceeded %d ticks, actual %d

Source	Severity
SMGR	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DISTRIBUTE\_DB event sent unit mask value appl mask value

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DISTRIBUTE\_DB event sent unit mask value appl mask value log

DISTRIBUTE\_DB event sent unit mask value appl mask value

The DISTRIBUTE\_DB event is sent during the stack formation process.

Source	Severity
Stack Manager	Information

### Remedial action

No action required.



DMLT:%d disabled due stack failure  
keep unit:%d port:%d enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DMLT:%d disabled due stack failure keep unit:%d port:%d enabled log

DMLT:%d disabled due stack failure keep unit:%d port:%d enabled

Source	Severity
MLT	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Do not configure more than two VLANs per SPBM instance

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Do not configure more than two VLANs per SPBM instance log

Do not configure more than two VLANs per SPBM instance

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DosFs - Error File not closed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DosFs - Error File not closed log

DosFs - Error File not closed

The system detected an error in closing the file.

Source	Severity
Information	

### Remedial action

Retry the operation.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Download - DL\_CKSUM\_ACK\_ERROR

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Download - DL\_CKSUM\_ACK\_ERROR log

Download - DL\_CKSUM\_ACK\_ERROR

This message appears when the image on NBU fails checksum validation.

Source	Severity
Flash Driver	Critical

### Remedial action

Retry or download another image.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Download – DL\_HASH\_ACK\_ERROR

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Download – DL\_HASH\_ACK\_ERROR log

Download – DL\_HASH\_ACK\_ERROR

Source	Severity
Flash Driver	Critical

### Remedial action

Retry or download another image.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Download - DL\_PROGRAM\_STATUS\_ACK\_ERROR

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Download - DL\_PROGRAM\_STATUS\_ACK\_ERROR log

Download - DL\_PROGRAM\_STATUS\_ACK\_ERROR

This message appears when all NBUs succeed in programming the image.

Source	Severity
Flash Driver	Critical

### Remedial action

Retry or reboot the switch

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Download - DL\_START\_PROGRAM\_FLASH\_ACK\_ERROR

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Download - DL\_START\_PROGRAM\_FLASH\_ACK\_ERROR log

Download - DL\_START\_PROGRAM\_FLASH\_ACK\_ERROR

This message appears when not all NBUs succeed in programming image.

Source	Severity
Flash Driver	Critical

### Remedial action

Retry or reboot the switch.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Download – Error: Failed to get FLASH sem

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Download – Error: Failed to get FLASH sem log

Download – Error: Failed to get FLASH sem

Possible hardware issues.

Source	Severity
Flash Driver	Serious

### Remedial action

Reboot the unit if faulty operation is observed, call support.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Download – Error: Failed to get the dl resource.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Download – Error: Failed to get the dl resource. log

Download – Error: Failed to get the dl resource.

The system failed to access flash for the image download.

Source	Severity
Flash Driver	Critical

### Remedial action

Retry or reboot the switch

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Download – Error: Failed to get the Reset sem

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Download – Error: Failed to get the Reset sem log

Download – Error: Failed to get the Reset sem

Possible download in progress.

Source	Severity
Flash Driver	Critical

### Remedial action

Wait.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Download – Error: Failed to send message to dlQueue

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Download – Error: Failed to send message to dlQueue log

Download – Error: Failed to send message to dlQueue

High CPU utilization, IMC queues full while a download is in progress

Source	Severity
Flash Driver	Critical

### Remedial action

Wait or reboot the unit and try the download again, call support

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Download – Error: Image is invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Download – Error: Image is invalid log

Download – Error: Image is invalid

The image you are trying to download is not suitable for this platform.

Source	Severity
Flash Driver	Critical

### Remedial action

Download an image that is suitable for the platform you are working on.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Download – Error: Watchdog expire: No Ack from NBUs, download MSG # %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Download – Error: Watchdog expire: No Ack from NBUs, download MSG # %d log

Download – Error: Watchdog expire: No Ack from NBUs, download MSG # %d

The watchdog timer expired waiting for acknowledgements from the NBUs during the image programming.

Source	Severity
Flash Driver	Critical

### Remedial action

Retry or reboot the switch

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Download - Failed to get buffer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Download - Failed to get buffer log

Download - Failed to get buffer

The system failed to obtain the data buffer for downloading the image.

Source	Severity
Flash Driver	Critical

### Remedial action

Retry or reboot the switch

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Download - Failed to malloc for buffer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Download - Failed to malloc for buffer log

Download - Failed to malloc for buffer

The system does not have enough memory to download the image in to it.

Source	Severity
Flash Driver	Critical

### Remedial action

Retry or reboot the switch.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Download - Failed to start a watchdog

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Download - Failed to start a watchdog log

Download - Failed to start a watchdog

The system failed to start the watchdog timer for image programming process.

Source	Severity
Flash Driver	Critical

### Remedial action

Retry or reboot the switch

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Download - Image Checksum Error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Download - Image Checksum Error log

Download - Image Checksum Error

This message appears when the Checksum in the image is not the same as the computed one.

Source	Severity
Flash Driver	Critical

### Remedial action

Retry or download another image.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Download – Image Hash Error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Download – Image Hash Error log

Download – Image Hash Error

A corrupt image file is being downloaded.

Source	Severity
Flash Driver	Critical

### Remedial action

Try downloading a different image file.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Download - Largest mem blk < DL\_SYSMEM\_RESERVED

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Download - Largest mem blk < DL\_SYSMEM\_RESERVED log

Download - Largest mem blk < DL\_SYSMEM\_RESERVED

The system does not have enough memory to download the image into it.

Source	Severity
Flash Driver	Critical

### Remedial action

Retry or reboot the switch.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Download – NBU: Block Checksum Error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Download – NBU: Block Checksum Error log

Download – NBU: Block Checksum Error

The image on NBU failed the Checksum validation.

Source	Severity
Flash Driver	Critical

### Remedial action

Retry or download another image.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Download – NBU: DL\_PROGRAM\_STATUS: ERROR

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Download – NBU: DL\_PROGRAM\_STATUS: ERROR log

Download – NBU: DL\_PROGRAM\_STATUS: ERROR

This message appears when not all NBUs succeed in programming the image.

Source	Severity
Flash Driver	Critical

### Remedial action

Retry, download another image, or reboot the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Download - %s image %sprogrammed successfully

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Download - %s image %sprogrammed successfully log

Download - %s image %sprogrammed successfully

This is an informational message.

Source	Severity
Download Task	Serious

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Download - TFTP timeout OR image file not found

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Download - TFTP timeout OR image file not found log

Download - TFTP timeout OR image file not found

The system detected an error: TFTP timeout

Source	Severity
Download Task	Critical

### Remedial action

Retry or reboot the switch

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Download - tftpXfer failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Download - tftpXfer failed log

Download - tftpXfer failed

The system detected an error in fetching the download resource.

Source	Severity
Flash Driver	Critical

### Remedial action

Retry or reboot the switch.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Downstream direction is logically down

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Downstream direction is logically down log

Downstream direction is logically down

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Downstream direction is logically up

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Downstream direction is logically up log

Downstream direction is logically up

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Downstream Port #%u is unexpectedly logically up

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Downstream Port #%u is unexpectedly logically up log

Downstream Port #%u is unexpectedly logically up

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Downstream stack direction is down cable removed or neighbor powered off

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Downstream stack direction is down cable removed or neighbor powered off log

Downstream stack direction is down cable removed or neighbor powered off

The Downstream stack direction is down, cable removed or neighbor powered off.

Source	Severity
Hello Module	Information

### Remedial action

Connect the downstream port to the upstream port of the neighbor. Also check if the neighbor is powered on.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Downstream stack direction is down, cable removed or neighbor powered off

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Downstream stack direction is down, cable removed or neighbor powered off log

Downstream stack direction is down, cable removed or neighbor powered off

Source	Severity
HMOD	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Downstream stack direction is misconfigured

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Downstream stack direction is misconfigured log

Downstream stack direction is misconfigured

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Downstream stack direction is mis-configured

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Downstream stack direction is mis-configured log

Downstream stack direction is mis-configured

This message appears when a downstream port is mis-configured.

Source	Severity
Hello Module	Information

### Remedial action

Connect the downstream port to the upstream port of the neighbor.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Downstream stack direction is up cable inserted or neighbor powered on

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Downstream stack direction is up cable inserted or neighbor powered on log

Downstream stack direction is up cable inserted or neighbor powered on

The Downstream stack direction is up, cable inserted and neighbor powered on. Physical link is up now.

Source	Severity
Hello Module	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Downstream stack direction is up, cable inserted or neighbor powered on

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Downstream stack direction is up, cable inserted or neighbor powered on log

Downstream stack direction is up, cable inserted or neighbor powered on

Source	Severity
HMOD	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Downstream stack ports down, wait for stack ports before processing

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Downstream stack ports down, wait for stack ports before processing log

Downstream stack ports down, wait for stack ports before processing

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Downstream Stack Port #%u is logically down

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Downstream Stack Port #%u is logically down log

Downstream Stack Port #%u is logically down

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Downstream Stack Port #%u is logically up

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Downstream Stack Port #%u is logically up log

Downstream Stack Port #%u is logically up

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Downstream stack port %u is misconfigured

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Downstream stack port %u is misconfigured log

Downstream stack port %u is misconfigured

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# DSCP mapping distribution across stack failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DSCP mapping distribution across stack failed log

DSCP mapping distribution across stack failed

Unable to commit DSCP mapping distribution across the stack.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DSCP mapping modifications not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DSCP mapping modifications not supported log

DSCP mapping modifications not supported

The system detected an internal error; The specified modifier option is not supported.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DSCP remarking not supported for IPv6 (green action)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DSCP remarking not supported for IPv6 (green action) log

DSCP remarking not supported for IPv6 (green action)

Match action (green) containing DSCP remarking cannot be used on a filter with Ipv6 fields.

Source	Severity
QoS	Serious

### Remedial action

Enter a different match action or a different classifier.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DSCP remarking not supported for IPv6 (in-profile action)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DSCP remarking not supported for IPv6 (in-profile action) log

DSCP remarking not supported for IPv6 (in-profile action)

In-profile action containing DSCP remarking cannot be used on a filter with Ipv6 fields.

Source	Severity
QoS	Serious

### Remedial action

Enter a different in-profile action or a different classifier.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DSCP remarking not supported for IPv6 (match action)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DSCP remarking not supported for IPv6 (match action) log

DSCP remarking not supported for IPv6 (match action)

Match action containing DSCP remarking cannot be used on a filter with Ipv6 fields.

Source	Severity
QoS	Serious

### Remedial action

Enter a different match action or a different classifier.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DSCP remarking not supported for IPv6 (non-match action)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DSCP remarking not supported for IPv6 (non-match action) log

DSCP remarking not supported for IPv6 (non-match action)

Non-match action containing DSCP remarking cannot be used on a filter with Ipv6 fields.

Source	Severity
QoS	Serious

### Remedial action

Enter a different non-match action or a different classifier.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DSCP remarking not supported for IPv6 (out-of-profile action)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DSCP remarking not supported for IPv6 (out-of-profile action) log

DSCP remarking not supported for IPv6 (out-of-profile action)

Out-of-profile action containing DSCP remarking cannot be used on a filter with Ipv6 fields.

Source	Severity
QoS	Serious

### Remedial action

Enter a different out-of-profile action or a different classifier.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DSCP remarking not supported for IPv6 (red action)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DSCP remarking not supported for IPv6 (red action) log

DSCP remarking not supported for IPv6 (red action)

Match action (red) containing DSCP remarking cannot be used on a filter with Ipv6 fields.

Source	Severity
QoS	Serious

### Remedial action

Enter a different match action or a different classifier.





# DSCP remarking not supported for IPv6 (yellow action)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DSCP remarking not supported for IPv6 (yellow action) log

DSCP remarking not supported for IPv6 (yellow action)

Match action (yellow) containing DSCP remarking cannot be used on a filter with Ipv6 fields.

Source	Severity
QoS	Serious

### Remedial action

Enter a different match action or a different classifier.



# DSCP value modification prohibited

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DSCP value modification prohibited log

DSCP value modification prohibited

Since the qset/dscp-to-queue assignment association is created when the qset (queue set) is defined including the creation of an element per DSCP value, the DSCP may not be modified. Also, only IPv4/IPv6 packets can have the DSCP value updated.

Source	Severity
QoS	Information

### Remedial action

Verify that the DSCP being specified is indeed the original DSCP or eliminate option if not an Ipv4/IPv6 packet.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DS/L2 entry mismatch detected (NSNA filter set data)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DS/L2 entry mismatch detected (NSNA filter set data) log

DS/L2 entry mismatch detected (NSNA filter set data)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# DS/L2 entry mismatch detected (UBP filter set data)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## DS/L2 entry mismatch detected (UBP filter set data) log

DS/L2 entry mismatch detected (UBP filter set data)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Dst IP addr matching not supported with IP addr type data

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Dst IP addr matching not supported with IP addr type data log

Dst IP addr matching not supported with IP addr type data

Filters with pattern matching (Dst IP) cannot be used with data of the IP address type .

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Separate the conflicting elements into multiple filters.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Dst Layer 4 port min max values invalid (max must be = to min)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Dst Layer 4 port min max values invalid (max must be = to min) log

Dst Layer 4 port min max values invalid (max must be = to min)

The maximum destination port must be bigger than the minimum destination port.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Correct destination port range limits.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Dst Layer 4 port min/max values invalid (max must be $\geq$ to min)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Dst Layer 4 port min/max values invalid (max must be $\geq$ to min) log

Dst Layer 4 port min/max values invalid (max must be  $\geq$  to min)

Source	Severity
QoS	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Dst MAC addr matching not supported with address type data

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Dst MAC addr matching not supported with address type data log

Dst MAC addr matching not supported with address type data

Destination MAC address matching and the address type matching is prohibited in the same classifier element.

Source	Severity
QoS	Serious

### Remedial action

Separate the conflicting elements into multiple filters.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Duplicate access asgn name type index detected (prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Duplicate access asgn name type index detected (prohibited) log

Duplicate access asgn name type index detected (prohibited)

Multiple entries with the same name, type, or index are prohibited.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Enter a different name, type, index compared to the ones already installed in the system.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Duplicate access asgn name/type/index detected (prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Duplicate access asgn name/type/index detected (prohibited) log

Duplicate access asgn name/type/index detected (prohibited)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Duplicate address deletion failed ipv6\_address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Duplicate address deletion failed ipv6\_address log

Duplicate address deletion failed ipv6\_address

The Duplicate Address Detection procedure found a duplicate for the IPv6\_address on the link.

Source	Severity
IPv6	Information

### Remedial action

Change the link-local ID for the IPv6 interface if the ipv6\_address is in link-local scope. Remove and assign a different ipv6\_address if the ipv6\_address is in global scope.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Duplicate address detection failed:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Duplicate address detection failed: log

Duplicate address detection failed:

**Source    Severity**

IPV6

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Duplicate address detection succeeded:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Duplicate address detection succeeded: log

Duplicate address detection succeeded:

**Source    Severity**

IPV6

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Duplicate address detection succeeded ipv6\_address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Duplicate address detection succeeded ipv6\_address log

Duplicate address detection succeeded ipv6\_address

The Duplicate Address Detection procedure is successfully completed for the ipv6\_address, and no duplicate is found on the link.

Source	Severity
IPV6	Information

### Remedial action

No action required.



# Duplicate classifier class values in set detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Duplicate classifier class values in set detected log

Duplicate classifier class values in set detected

A classifier with the same class already exists in the specified set-id.

Source	Severity
QoS	Serious

### Remedial action

Remove the existing classifier or use a different set-id.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Duplicate DB Ack for %s(%d) detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Duplicate DB Ack for %s(%d) detected log

Duplicate DB Ack for %s(%d) detected

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Duplicate entry detected (prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Duplicate entry detected (prohibited) log

Duplicate entry detected (prohibited)

The QoS entry already exists.

Source	Severity
QoS	Information

### Remedial action

Use the existing entry if possible.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Duplicate FCoE redirection entry detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Duplicate FCoE redirection entry detected log

Duplicate FCoE redirection entry detected

Duplicate FCoE redirection entry detected.

Source	Severity
QOS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Duplicate FCoE redirection entry detected (prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Duplicate FCoE redirection entry detected (prohibited) log

Duplicate FCoE redirection entry detected (prohibited)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Duplicate set values in block detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Duplicate set values in block detected log

Duplicate set values in block detected

The specified set value already exists in classifier block.

Source	Severity
QoS	Serious

### Remedial action

Enter a different set value or remove the existing one.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Duplicate users (different port, same user name) prohibited

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Duplicate users (different port, same user name) prohibited log

Duplicate users (different port, same user name) prohibited

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Dynamic ARP could not be learned, maximum dynamic ARP limit is reached.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Dynamic ARP could not be learned, maximum dynamic ARP limit is reached. log

Dynamic ARP could not be learned, maximum dynamic ARP limit is reached.

### Source    Severity

L3Mgr

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Dynamic interface assignment failure (%d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Dynamic interface assignment failure (%d/%d) log

Dynamic interface assignment failure (%d/%d)

QoS failed to apply the external dynamic interface assignment request.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Check the log for related QoS or FA messages and resolve possible conflicts.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Dynamic role combination cannot be used in explicit assignment

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Dynamic role combination cannot be used in explicit assignment log

Dynamic role combination cannot be used in explicit assignment

Dynamic role combinations are system owned and used for interaction with other features, such as FA.

Source	Severity
QoS	Information

### Remedial action

Use or create a legacy role combination.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Dynamic route could not be learned, maximum dynamic route is reached.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Dynamic route could not be learned, maximum dynamic route is reached. log

Dynamic route could not be learned, maximum dynamic route is reached.

**Source**   **Severity**  
L3Mgr

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: AdminfMgr Install Set Failed on port:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: AdminfMgr Install Set Failed on port: log

EAP: AdminfMgr Install Set Failed on port:

**Source    Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: AdminfMgr Install Test Failed on port:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: AdminfMgr Install Test Failed on port: log

EAP: AdminfMgr Install Test Failed on port:

**Source    Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Bad pkt id

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Bad pkt id log

EAP Bad pkt id

EAP received a packet with another ID than expected.

Source	Severity
EAP	Information

### Remedial action

No action required.



# EAP Bad pkt len

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Bad pkt len log

EAP Bad pkt len

EAP received an EAPoL packet greater than 1500 bytes.

Source	Severity
EAP	Information

### Remedial action

No action required.



# EAP: Bad pkt len

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Bad pkt len log

EAP: Bad pkt len

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



EAP: cannot add Isolated %s to multiple VLANs. Port already assigned to one Private VLAN.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: cannot add Isolated %s to multiple VLANs. Port already assigned to one Private VLAN. log

EAP: cannot add Isolated %s to multiple VLANs. Port already assigned to one Private VLAN.

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: cannot add Isolated %s to non-Private VLAN %d.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: cannot add Isolated %s to non-Private VLAN %d. log

EAP: cannot add Isolated %s to non-Private VLAN %d.

**Source    Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# EAP: cannot add non-Isolated %s to private VLAN %d.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: cannot add non-Isolated %s to private VLAN %d. log

EAP: cannot add non-Isolated %s to private VLAN %d.

### Source    Severity

EAP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: cannot apply contradictory Egress Vid %d on port %d.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: cannot apply contradictory Egress Vid %d on port %d. log

EAP: cannot apply contradictory Egress Vid %d on port %d.

**Source   Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: cannot apply contradictory Egress Vid %d on port %d.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: cannot apply contradictory Egress Vid %d on port %d. log

EAP: cannot apply contradictory Egress Vid %d on port %d.

Source	Severity
EAP	Information

### Remedial action

Check for tagging conflicts on that vlan for other clients.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: cannot apply Egress Vids on ADAC port %d.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: cannot apply Egress Vids on ADAC port %d. log

EAP: cannot apply Egress Vids on ADAC port %d.

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: cannot apply Egress Vids on ADAC port %d.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: cannot apply Egress Vids on ADAC port %d. log

EAP: cannot apply Egress Vids on ADAC port %d.

Source	Severity
EAP	Information

### Remedial action

Disable ADAC on port.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: cannot apply inexistent Egress Vid %d on port %d.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: cannot apply inexistent Egress Vid %d on port %d. log

EAP: cannot apply inexistent Egress Vid %d on port %d.

**Source   Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: cannot apply inexistent Egress Vid %d on port %d.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: cannot apply inexistent Egress Vid %d on port %d. log

EAP: cannot apply inexistent Egress Vid %d on port %d.

Source	Severity
EAP	Information

### Remedial action

Make sure VID exists.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: cannot apply inexistent Egress VLAN Name on port %d.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: cannot apply inexistent Egress VLAN Name on port %d. log

EAP: cannot apply inexistent Egress VLAN Name on port %d.

**Source    Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# EAP: cannot apply inexistent Egress VLAN Name on port %d.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: cannot apply inexistent Egress VLAN Name on port %d. log

EAP: cannot apply inexistent Egress VLAN Name on port %d.

Source	Severity
EAP	Information

### Remedial action

Make sure VLAN named that way exists.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Cannot assign PVID %d, on port %d it is in another STP group

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Cannot assign PVID %d, on port %d it is in another STP group log

EAP: Cannot assign PVID %d, on port %d it is in another STP group

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: cannot autocreate a Non-Private VLAN for Isolated %s.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: cannot autocreate a Non-Private VLAN for Isolated %s. log

EAP: cannot autocreate a Non-Private VLAN for Isolated %s.

**Source    Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Cannot auto-create VLAN %d, it is mapped to another STP group

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Cannot auto-create VLAN %d, it is mapped to another STP group log

EAP: Cannot auto-create VLAN %d, it is mapped to another STP group

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Cannot enable IP source guard on port %s: DHCP snooping is not enabled globally

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Cannot enable IP source guard on port %s: DHCP snooping is not enabled globally log

EAP: Cannot enable IP source guard on port %s: DHCP snooping is not enabled globally

Source	Severity
EAP	Information

### Remedial action

Enable DHCP snooping globally.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Cannot enable IP source guard on port %s: the port is not a member of a DHCP Snooping enabled VLAN

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Cannot enable IP source guard on port %s: the port is not a member of a DHCP Snooping enabled VLAN log

EAP: Cannot enable IP source guard on port %s: the port is not a member of a DHCP Snooping enabled VLAN

Source	Severity
EAP	Information

### Remedial action

Check DHCP snooping settings on all port VLANs.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Cannot enable IP source guard on port %s: the port is not a member of an ARP Inspection enabled VLAN

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Cannot enable IP source guard on port %s: the port is not a member of an ARP Inspection enabled VLAN log

EAP: Cannot enable IP source guard on port %s: the port is not a member of an ARP Inspection enabled VLAN

Source	Severity
EAP	Information

### Remedial action

Check ARP inspection settings on all port VLANs.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Cannot enable IP source guard on port %s: unable to apply the new setting

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Cannot enable IP source guard on port %s: unable to apply the new setting log

EAP: Cannot enable IP source guard on port %s: unable to apply the new setting

Source	Severity
EAP	Information

### Remedial action

Check DHCP snooping and ARP inspection settings on all port VLANs.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# EAP: Cannot set DHCP Snooping on non-autocreated VLAN %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Cannot set DHCP Snooping on non-autocreated VLAN %d log

EAP: Cannot set DHCP Snooping on non-autocreated VLAN %d

Source	Severity
EAP	Information

### Remedial action

Delete that VLAN and send it from RADIUS with the auto-create option or enable it manually.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Cannot set DHCP Snooping option82 on non-autocreated VLAN %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Cannot set DHCP Snooping option82 on non-autocreated VLAN %d log

EAP: Cannot set DHCP Snooping option82 on non-autocreated VLAN %d

Source	Severity
EAP	Information

### Remedial action

Delete that VLAN and send it from RADIUS with the auto-create option or enable it manually.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Cannot set Dynamic ARP Inspection on non-autocreated VLAN %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Cannot set Dynamic ARP Inspection on non-autocreated VLAN %d log

EAP: Cannot set Dynamic ARP Inspection on non-autocreated VLAN %d

Source	Severity
EAP	Information

### Remedial action

Delete that VLAN and send it from RADIUS with the auto-create option or enable it manually.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Cannot set IGMP Snooping on non-autocreated VLAN %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Cannot set IGMP Snooping on non-autocreated VLAN %d log

EAP: Cannot set IGMP Snooping on non-autocreated VLAN %d

Source	Severity
EAP	Information

### Remedial action

Delete that VLAN and send it from RADIUS with the auto-create option or enable it manually.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Cannot set IGMP Snooping on Switched UNI VLAN %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Cannot set IGMP Snooping on Switched UNI VLAN %d log

EAP: Cannot set IGMP Snooping on Switched UNI VLAN %d

Source	Severity
EAP	Information

### Remedial action

Disable SPBm to be able to use IGMP Snooping on autocreated VLANs.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Cannot set option 82 subscriber ID longer than %d characters on port %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Cannot set option 82 subscriber ID longer than %d characters on port %d log

EAP: Cannot set option 82 subscriber ID longer than %d characters on port %d

Source	Severity
EAP	Information

### Remedial action

Send subscriber ID of up to 64 characters in length

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



EAP: cannot set PVID %d to %s. VLAN is Private and port is not Isolated.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: cannot set PVID %d to %s. VLAN is Private and port is not Isolated. log

EAP: cannot set PVID %d to %s. VLAN is Private and port is not Isolated.

**Source    Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Cannot set speed/duplex on port %s: cannot retrieve current configuration

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Cannot set speed/duplex on port %s: cannot retrieve current configuration log

EAP: Cannot set speed/duplex on port %s: cannot retrieve current configuration

Source	Severity
EAP	Information

### Remedial action

Retry action.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# EAP: Cannot set speed/duplex on port %s: memory allocation error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Cannot set speed/duplex on port %s: memory allocation error log

EAP: Cannot set speed/duplex on port %s: memory allocation error

Source	Severity
EAP	Information

### Remedial action

Check memory usage.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Cannot set speed/duplex on port %s: speed or duplex value missing

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Cannot set speed/duplex on port %s: speed or duplex value missing log

EAP: Cannot set speed/duplex on port %s: speed or duplex value missing

Source	Severity
EAP	Information

### Remedial action

Make sure you specified valid speed and duplex.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Cannot set speed/duplex on port %s: unable to apply the new port configuration

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Cannot set speed/duplex on port %s: unable to apply the new port configuration log

EAP: Cannot set speed/duplex on port %s: unable to apply the new port configuration

Source	Severity
EAP	Information

### Remedial action

Make sure you specified valid speed and duplex.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Cannot set speed/duplex on port %s: unsupported values

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Cannot set speed/duplex on port %s: unsupported values log

EAP: Cannot set speed/duplex on port %s: unsupported values

Source	Severity
EAP	Information

### Remedial action

Make sure you specified valid speed and duplex.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP CDT Error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP CDT Error log

EAP CDT Error

EAP will not correctly receive events about MACs from CDT.

Source	Severity
CDT	Information

### Remedial action

No Action Required

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: CDT Error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: CDT Error log

EAP: CDT Error

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Client blocked (Block Subsequent MAC Authentication): Different VID than expected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Client blocked (Block Subsequent MAC Authentication): Different VID than expected log

EAP Client blocked (Block Subsequent MAC Authentication): Different VID than expected

An EAP client was blocked because it had a different Radius Assigned VLAN than the previous one.

Source	Severity
EAP	Information

### Remedial action

Check the Attributes sent by RADIUS Server.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Client blocked (Block Subsequent MAC Authentication): Invalid VID

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Client blocked (Block Subsequent MAC Authentication): Invalid VID log

EAP Client blocked (Block Subsequent MAC Authentication): Invalid VID

An EAP client was blocked because it had an invalid Radius Assigned VLAN.

Source	Severity
EAP	Information

### Remedial action

Check the Attributes sent by RADIUS Server.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





EAP Client blocked - MAC  
%02x:%02x:%02x:%02x:%02x:%02x.  
All bindings have been rejected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. All bindings have been rejected log

EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. All bindings have been rejected

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. All RAVs or Bindings from RADIUS are invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. All RAVs or Bindings from RADIUS are invalid log

EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. All RAVs or Bindings from RADIUS are invalid

**Source    Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Client blocked - MAC %02x: %02x: %02x: %02x: %02x: %02x. Cannot use FA bindings in Legacy networks

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Cannot use FA bindings in Legacy networks log

EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Cannot use FA bindings in Legacy networks

### Source    Severity

EAP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



EAP Client blocked - MAC  
%02x:%02x:%02x:%02x:%02x:%02x.  
EAP FA context unknown network

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. EAP FA context unknown network log

EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. EAP FA context unknown network

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



EAP Client blocked - MAC  
%02x:%02x:%02x:%02x:%02x:%02x.  
Maximum number of VLANs reached

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Maximum number of VLANs reached log

EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Maximum number of VLANs reached

**Source    Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Only MHSA mode supports multiple RAVs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Only MHSA mode supports multiple RAVs log

EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Only MHSA mode supports multiple RAVs

### Source    Severity

EAP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Receiving unconfigured VLAN from Radius without Autocreate

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Receiving unconfigured VLAN from Radius without Autocreate log

EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Receiving unconfigured VLAN from Radius without Autocreate

### Source    Severity

EAP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



EAP Client blocked - MAC  
%02x:%02x:%02x:%02x:%02x:%02x.  
Vlan:Isid bindings exceeded the  
maximum threshold of 16

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid bindings exceeded the maximum threshold of 16 log

EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid bindings exceeded the maximum threshold of 16

### Source    Severity

EAP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





EAP Client blocked - MAC  
%02x:%02x:%02x:%02x:%02x:%02x.  
Vlan:Isid bindings exceeded the  
maximum threshold of 94

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid bindings exceeded the maximum threshold of 94 log

EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid bindings exceeded the maximum threshold of 94

Source	Severity
EAP	Information

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid not supported in MHMA and SHSA

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid not supported in MHMA and SHSA log

EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid not supported in MHMA and SHSA

### Source    Severity

EAP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with different Isid from the configured one is invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with different Isid from the configured one is invalid log

EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with different Isid from the configured one is invalid

The VLAN/ISID binding received from RADIUS Server is different from the switch configured binding.

Source	Severity
EAP	Information

### Remedial action

Make the VLAN/ISID binding on the RADIUS Server consistent with the value configured on the switch.



# EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with Isid equal to 0 not supported in FA SPB networks

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with Isid equal to 0 not supported in FA SPB networks log

EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with Isid equal to 0 not supported in FA SPB networks

### Source   Severity

EAP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with Isid <> 0 not supported in Standalone Proxy or Autoprov

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with Isid <> 0 not supported in Standalone Proxy or Autoprov log

EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with Isid <> 0 not supported in Standalone Proxy or Autoprov

In Standalone Proxy or Autoprov topologies, (VLAN:ISID) bindings are supported only if ISID is equal with 0

Source	Severity
EAP	Information

### Remedial action

Change the attributes on RADIUS Server to set ISID to a value of 0.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



## EAP Client

%02x:%02x:%02x:%02x:%02x:%02x:  
Vlan %d not created. Maximum number  
of VLANs reached

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Client %02x:%02x:%02x:%02x:%02x:%02x: Vlan %d not created. Maximum number of VLANs reached log

EAP Client %02x:%02x:%02x:%02x:%02x:%02x: Vlan %d not created. Maximum number of VLANs reached

### Source    Severity

EAP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Could not process pkt

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Could not process pkt log

EAP Could not process pkt

EAP received a packet with length smaller than the header size or greater than the maximum limit.

Source	Severity
EAP	Information

### Remedial action

No action required.



# EAP: Could not process pkt

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Could not process pkt log

EAP: Could not process pkt

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# EAP: Done Read From NVRAM - readVer %d in %s: cfgVer %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Done Read From NVRAM - readVer %d in %s: cfgVer %d log

EAP: Done Read From NVRAM - readVer %d in %s: cfgVer %d

### Source    Severity

EAP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Error - Default

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Error - Default log

EAP Error - Default

Wrong EAP parameter.

Source	Severity
EAP	Information

### Remedial action

No Action Required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Error - Failed to free mac info memory

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Error - Failed to free mac info memory log

EAP Error - Failed to free mac info memory

A NEAP client could not be deleted from the list.

Source	Severity
EAP	Information

### Remedial action

Reboot the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Error initializing dynamic settings semaphore

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Error initializing dynamic settings semaphore log

EAP: Error initializing dynamic settings semaphore

Unable to create a semaphore in the initialization stage.

Source	Severity
--------	----------

EAP	Critical
-----	----------

### Remedial action

A reboot is necessary.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Error initializing semaphore

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Error initializing semaphore log

EAP: Error initializing semaphore

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Error Radius - ifIndex not found

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Error Radius - ifIndex not found log

EAP Error Radius - ifIndex not found

Radius received a wrong port number for which to send a response

Source	Severity
Radius	Information

### Remedial action

No action required.



# EAP: Error Radius - ifIndex not found

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Error Radius - ifIndex not found log

EAP: Error Radius - ifIndex not found

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Error: Reached maximum number of messages in the queue

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Error: Reached maximum number of messages in the queue log

EAP Error: Reached maximum number of messages in the queue

EAP received too many messages from other applications.

Source	Severity
--------	----------

EAP	Serious
-----	---------

### Remedial action

Reboot the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# EAP Error while sending Access Violation Trap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Error while sending Access Violation Trap log

EAP Error while sending Access Violation Trap

EAP cannot send an Access Violation Trap

Source	Severity
EAP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Error while sending Access Violation Trap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Error while sending Access Violation Trap log

EAP: Error while sending Access Violation Trap

**Source    Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Error while sending RAV Error Trap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Error while sending RAV Error Trap log

EAP Error while sending RAV Error Trap

EAP cannot send a Radius Assigned VLAN Error Trap.

Source	Severity
EAP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Error while sending RAV Error Trap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Error while sending RAV Error Trap log

EAP: Error while sending RAV Error Trap

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: FA bind conflict between

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: FA bind conflict between log

EAP: FA bind conflict between

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Failed initialize global arrays

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Failed initialize global arrays log

EAP Failed initialize global arrays

EAP could not initialize data about global or ports admin state

Source	Severity
EAP	Serious

### Remedial action

Reboot the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Failed initialize global arrays

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Failed initialize global arrays log

EAP: Failed initialize global arrays

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Failed installing FOV UBP,

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Failed installing FOV UBP, log

EAP: Failed installing FOV UBP,

QoS hardware resources are not enough to install the configured FOV UBP on the port.

Source	Severity
EAP	Information

### Remedial action

Check the QoS resources and free some precedences. If this action does not solve the issue, lower the FOV UBP complexity or configure it with double-wide mode.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





EAP: Failed qpa-RoleAssociation on  
port: %s, MAC  
%02x:%02x:%02x:%02x:%02x:%02x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Failed qpa-RoleAssociation on port: %s, MAC %02x:%02x:%02x:%02x:%02x:%02x log

EAP: Failed qpa-RoleAssociation on port: %s, MAC %02x:%02x:%02x:%02x:%02x:%02x

**Source    Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Failed qpa-RoleAssociation unitPort ifIndex macHi xx-xx macLo xx-xx-xx-xx

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Failed qpa-RoleAssociation unitPort ifIndex macHi xx-xx macLo xx-xx-xx-xx log

EAP Failed qpa-RoleAssociation unitPort ifIndex macHi xx-xx macLo xx-xx-xx-xx

The EAP User Based Policy Role Association failed at the given unit port (ifIndex) for given MAC address

Source	Severity
EAP-Filter Manager	Information

### Remedial action

Show QoS agent; make sure the UBP is enabled; or enable as needed; Show QoS diag and check if filters are available.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Failed qpa-RoleAssociation unitPort 0x%x mac %08x%04x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Failed qpa-RoleAssociation unitPort 0x%x mac %08x%04x log

EAP Failed qpa-RoleAssociation unitPort 0x%x mac %08x%04x

A UBP filter could not be installed because of a QoS specific error.

Source	Severity
QoS	Information

### Remedial action

Check QoS resources on port.



# EAP Failed to add host, max number of clients reached

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Failed to add host, max number of clients reached log

EAP Failed to add host, max number of clients reached

EAP already reached the maximum number of clients limit on a port.

Source	Severity
EAP	Information

### Remedial action

Increase the number of eap-mac-max clients.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Failed to add host, max number of clients reached

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Failed to add host, max number of clients reached log

EAP: Failed to add host, max number of clients reached

**Source   Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Failed to add host, memory allocation error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Failed to add host, memory allocation error log

EAP Failed to add host, memory allocation error

EAP could not allocate memory for a new EAP client.

Source	Severity
EAP	Information

### Remedial action

Reboot the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Failed to add host, memory allocation error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Failed to add host, memory allocation error log

EAP: Failed to add host, memory allocation error

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Failed to create dyna global arrays

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Failed to create dyna global arrays log

EAP Failed to create dyna global arrays

EAP could not initialize some of the data regarding global or port-specific info detailed in the “Could not create global arrays” log.

Source	Severity
EAP	Serious

### Remedial action

Reboot the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# EAP: Failed to create dyna global arrays

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Failed to create dyna global arrays log

EAP: Failed to create dyna global arrays

**Source    Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: GVlan Deleted

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: GVlan Deleted log

EAP: GVlan Deleted

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: GVlan Disabled for

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: GVlan Disabled for log

EAP: GVlan Disabled for

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP GVlan Disabled for unitPort ifIndex - GVlan( vid ) in different stg( id )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP GVlan Disabled for unitPort ifIndex - GVlan( vid ) in different stg( id ) log

EAP GVlan Disabled for unitPort ifIndex - GVlan( vid ) in different stg( id )

The EAP failed to apply Guest VLAN since new Guest VLAN ID is in a different spanning tree group than the current port VLAN; GVLAN disabled for that port.

Source	Severity
EAP-VLAN (QDT)	Information

### Remedial action

Show VLAN; show interfaces; show spanning-tree commands ; reconfigure VLANs in spanning tree groups as needed, and re-enable EAP on the port.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP IMC Failed to send message

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP IMC Failed to send message log

EAP IMC Failed to send message

EAP could not send an Inter Module Communication message.

Source	Severity
IMC	Information

### Remedial action

Reboot the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: IMC Failed to send message

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: IMC Failed to send message log

EAP: IMC Failed to send message

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP IMC Memory allocation error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP IMC Memory allocation error log

EAP IMC Memory allocation error

EAP could not allocate memory for an Inter Module Communication message

Source	Severity
IMC	Information

### Remedial action

Reboot the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: IMC Memory allocation error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: IMC Memory allocation error log

EAP: IMC Memory allocation error

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# EAP: Invalid NRAV ID

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Invalid NRAV ID log

EAP: Invalid NRAV ID

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Invalid RAV ID

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Invalid RAV ID log

EAP Invalid RAV ID

The EAP failed to apply Radius Assigned VLAN since it is not an active VLAN at the switch.

Source	Severity
EAP-VLAN (QDT)	Information

### Remedial action

show VLAN VID; show interfaces; show spanning tree commands; And make sure the VLAN is active.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Invalid RAV ID

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Invalid RAV ID log

EAP: Invalid RAV ID

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Invalid Vlan ID %d configured for port %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Invalid Vlan ID %d configured for port %d log

EAP: Invalid Vlan ID %d configured for port %d

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Invalid Vlan ID vid configured for port num

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Invalid Vlan ID vid configured for port num log

EAP Invalid Vlan ID vid configured for port num

The EAP VLAN ID received is not active for that port.

Source	Severity
EAP	Information

### Remedial action

Show VLAN VID; show interfaces; show spanning-tree commands ; make sure that the VLAN is active; then re-authenticate at the port.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Mac Authenticated - port %d mac %08x%04x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Mac Authenticated - port %d mac %08x%04x log

EAP: Mac Authenticated - port %d mac %08x%04x

**Source   Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Mac AuthFail -

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Mac AuthFail - log

EAP: Mac AuthFail -

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



EAP Mac AuthFail - unitPort <unit-portnum> macHi <xx-xx> macLo <xx-xx-xx-xx>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Mac AuthFail - unitPort <unit-portnum> macHi <xx-xx> macLo <xx-xx-xx-xx> log

EAP Mac AuthFail - unitPort <unit-portnum> macHi <xx-xx> macLo <xx-xx-xx-xx>

EAP Debug only - Eng Menu - EAP removed MAC on given port for given mac address on aborting PAE state machine - Not Used

Source	Severity
--------	----------

EAP	Information
-----	-------------

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# EAP: Mac Deleted - Aborted - port %d mac %08x%04x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Mac Deleted - Aborted - port %d mac %08x%04x log

EAP: Mac Deleted - Aborted - port %d mac %08x%04x

### Source    Severity

EAP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Mac Deleted - Bkend Timeout - port %d mac %08x%04x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Mac Deleted - Bkend Timeout - port %d mac %08x%04x log

EAP: Mac Deleted - Bkend Timeout - port %d mac %08x%04x

### Source    Severity

EAP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Mac Deleted - Disconnected - port %d mac %08x%04x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Mac Deleted - Disconnected - port %d mac %08x%04x log

EAP: Mac Deleted - Disconnected - port %d mac %08x%04x

### Source   Severity

EAP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Mac Intruder -

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Mac Intruder - log

EAP: Mac Intruder -

**Source    Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Maximum number of FA Table entries reached

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Maximum number of FA Table entries reached log

EAP: Maximum number of FA Table entries reached

**Source   Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Memory allocation error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Memory allocation error log

EAP Memory allocation error

EAP could not allocate memory to receive or send a packet.

Source	Severity
--------	----------

EAP	Serious
-----	---------

### Remedial action

Reboot the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Memory allocation error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Memory allocation error log

EAP: Memory allocation error

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Message queue error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Message queue error log

EAP Message queue error

EAP could not initialize the EAP message queue.

Source	Severity
EAP	Serious

### Remedial action

Reboot the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# EAP: Message queue error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Message queue error log

EAP: Message queue error

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



EAP: NEAP port %s not member of any VLAN. Added to VLAN %d for NEAP authentication

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: NEAP port %s not member of any VLAN. Added to VLAN %d for NEAP authentication log

EAP: NEAP port %s not member of any VLAN. Added to VLAN %d for NEAP authentication

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Neap port was not member of any vlan

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Neap port was not member of any vlan log

EAP Neap port was not member of any vlan

A Non-EAP port was added to either GuestVLAN or VLAN 1, because it was not a member of any VLAN.

Source	Severity
EAP	Information

### Remedial action

No action required.



# EAP NULL pkt to send on Success

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP NULL pkt to send on Success log

EAP NULL pkt to send on Success

An error appeared when creating the message to be sent for supplicant

Source	Severity
EAP	Information

### Remedial action

No action required.



# EAP: NULL pkt to send on Success

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: NULL pkt to send on Success log

EAP: NULL pkt to send on Success

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP NVRAM open error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP NVRAM open error log

EAP NVRAM open error

EAP could not open the NVRAM file to write settings.

Source	Severity
EAP	Serious

### Remedial action

Reboot the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: NVRAM open error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: NVRAM open error log

EAP: NVRAM open error

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP NVRAM read port admin state error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP NVRAM read port admin state error log

EAP NVRAM read port admin state error

EAP could not read the port EAP admin setting from NVRAM

Source	Severity
EAP	Serious

### Remedial action

Reboot the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# EAP: NVRAM read port admin state error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: NVRAM read port admin state error log

EAP: NVRAM read port admin state error

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP NVRAM read system admin state error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP NVRAM read system admin state error log

EAP NVRAM read system admin state error

EAP could not read the global EAP setting from NVRAM

Source	Severity
EAP	Serious

### Remedial action

Reboot the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: NVRAM read system admin state error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: NVRAM read system admin state error log

EAP: NVRAM read system admin state error

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP NVRAM read system ubp state error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP NVRAM read system ubp state error log

EAP NVRAM read system ubp state error

EAP could not read the global UBP setting from NVRAM

Source	Severity
EAP	Serious

### Remedial action

Reboot the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: NVRAM read system ubp state error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: NVRAM read system ubp state error log

EAP: NVRAM read system ubp state error

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP NVRAM write error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP NVRAM write error log

EAP NVRAM write error

EAP could not write settings in the NVRAM file.

Source	Severity
--------	----------

EAP	Serious
-----	---------

### Remedial action

Reboot the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: NVRAM write error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: NVRAM write error log

EAP: NVRAM write error

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Pvid attribute from RADIUS ignored,

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Pvid attribute from RADIUS ignored, log

EAP: Pvid attribute from RADIUS ignored,

The PVID attribute is processed only in MHSA mode. In other EAP modes it's ignored.

Source	Severity
EAP	Information

### Remedial action

None





# EAP: Pvid attribute from RADIUS ignored,

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Pvid attribute from RADIUS ignored, log

EAP: Pvid attribute from RADIUS ignored,

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: RAV not configured on switch for MHSA and Isolated %s.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: RAV not configured on switch for MHSA and Isolated %s. log

EAP: RAV not configured on switch for MHSA and Isolated %s.

### Source    Severity

EAP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Reached Mac Intruder Count

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Reached Mac Intruder Count log

EAP Reached Mac Intruder Count

EAP reached the maximum number of intruders on a port.

Source	Severity
EAP	Information

### Remedial action

Check the number of intruders per port.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Reached MAC intruder count on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Reached MAC intruder count on %s log

EAP: Reached MAC intruder count on %s

The limit of intruders per port is reached and port is move in force unauthorized.

Source	Severity
EAP	Information

### Remedial action

Investigate the cause of so many MACs learn on that port.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Reached maximum number of VLAN ranges for ARP inspection

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Reached maximum number of VLAN ranges for ARP inspection log

EAP: Reached maximum number of VLAN ranges for ARP inspection

Source	Severity
EAP	Information

### Remedial action

Send less ranges from RADIUS.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Reached maximum number of VLAN ranges for DHCP snooping

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Reached maximum number of VLAN ranges for DHCP snooping log

EAP: Reached maximum number of VLAN ranges for DHCP snooping

Source	Severity
EAP	Information

### Remedial action

Send less ranges from RADIUS.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Reached maximum number of VLAN ranges for DHCP snooping option 82

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Reached maximum number of VLAN ranges for DHCP snooping option 82 log

EAP: Reached maximum number of VLAN ranges for DHCP snooping option 82

Source	Severity
EAP	Information

### Remedial action

Send less ranges from RADIUS.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Reached maximum number of VLAN ranges for IGMP snooping

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Reached maximum number of VLAN ranges for IGMP snooping log

EAP: Reached maximum number of VLAN ranges for IGMP snooping

Source	Severity
EAP	Information

### Remedial action

Send less ranges from RADIUS.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# EAP: Receiving unsupported Auto-Create-VLAN VSA in SHSA or MHMA

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Receiving unsupported Auto-Create-VLAN VSA in SHSA or MHMA log

EAP: Receiving unsupported Auto-Create-VLAN VSA in SHSA or MHMA

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Task spawn error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Task spawn error log

EAP Task spawn error

The EAP application task could not be started.

Source	Severity
EAP	Serious

### Remedial action

Reboot the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Task spawn error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Task spawn error log

EAP: Task spawn error

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Timer error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Timer error log

EAP: Timer error

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Unable to Reserve EapAdmin Filter Resources

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Unable to Reserve EapAdmin Filter Resources log

EAP: Unable to Reserve EapAdmin Filter Resources

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Unable to Reserve EapAdmin Filter Resources rc retCode unitPort ifIndex

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Unable to Reserve EapAdmin Filter Resources rc retCode unitPort ifIndex log

EAP Unable to Reserve EapAdmin Filter Resources rc retCode unitPort ifIndex

The EAP Filter Reservation Failed (5520 and 5530) with the given filter manager return code for the given unit port (ifIndex) upon admin change from authorised to unauthorised or auto

Source	Severity
EAP-Filter Manager	Information

### Remedial action

Show QoS diag and check if filters are available; adjust the resource usage if required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Unable to Reserve Filter Resources rc retCode unitPort ifIndex Force- Unauthorised

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Unable to Reserve Filter Resources rc retCode unitPort ifIndex Force- Unauthorised log

EAP Unable to Reserve Filter Resources rc retCode unitPort ifIndex Force- Unauthorised

The EAP Filter Reservation Failure (5520 and 5530) with given filter manager return code for given unit-port (ifIndex); port is now set to force unauthorised and is blocking.

### Source

EAP-Filter Manager

### Severity

Information

### Remedial action

Show QoS diag and check if filters are available; adjust the resource usage if required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# EAP: Unable to UnReserve EapAdmin Filter Resources

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Unable to UnReserve EapAdmin Filter Resources log

EAP: Unable to UnReserve EapAdmin Filter Resources

**Source   Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# EAP Unable to UnReserve EapAdmin Filter Resources rc retCode unitPort ifIndex

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Unable to UnReserve EapAdmin Filter Resources rc retCode unitPort ifIndex log

EAP Unable to UnReserve EapAdmin Filter Resources rc retCode unitPort ifIndex

The EAP Filter Release Failure with the given filter manager return code for given unit port (ifIndex) upon admin change to force authorised.

Source	Severity
EAP-Filter Manager	Information

### Remedial action

Show QoS diag and check if filters are available; try filter allocations again and disable or enable EAP.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Unable to UnReserve Filter Resources rc retCode unitPort unit-portnum

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Unable to UnReserve Filter Resources rc retCode unitPort unit-portnum log

EAP Unable to UnReserve Filter Resources rc retCode unitPort unit-portnum

The EAP is unable to release filters with given filter manager return code for given unit port (ifIndex).

Source	Severity
EAP-Filter Manager	Information

### Remedial action

Show QoS diag and check if filters are available; adjust the resource usage if required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP Vlan Change Aborted

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP Vlan Change Aborted log

EAP Vlan Change Aborted

EAP could not add a port to a VLAN that is in a different STG than the STG where the port is.

Source	Severity
STP	Information

### Remedial action

Change the STG of the VLAN.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Vlan Change Aborted, it is in another STP Group

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Vlan Change Aborted, it is in another STP Group log

EAP: Vlan Change Aborted, it is in another STP Group

**Source    Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Vlan Change Aborted on brouter,

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Vlan Change Aborted on brouter, log

EAP: Vlan Change Aborted on brouter,

**Source    Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Warning, trying to set DHCP Snooping on VLAN %d not from client's attributes

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Warning, trying to set DHCP Snooping on VLAN %d not from client's attributes log

EAP: Warning, trying to set DHCP Snooping on VLAN %d not from client's attributes

Source	Severity
EAP	Information

### Remedial action

Check if you really intended to make this setting on a different VLAN. If possible, the setting will be applied anyway.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Warning, trying to set DHCP Snooping option82 on VLAN %d not from client's attributes

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Warning, trying to set DHCP Snooping option82 on VLAN %d not from client's attributes log

EAP: Warning, trying to set DHCP Snooping option82 on VLAN %d not from client's attributes

Source	Severity
EAP	Information

### Remedial action

Check if you really intended to make this setting on a different VLAN. If possible, the setting will be applied anyway.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP: Warning, trying to set Dynamic ARP Inspection on VLAN %d not from client's attributes

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Warning, trying to set Dynamic ARP Inspection on VLAN %d not from client's attributes log

EAP: Warning, trying to set Dynamic ARP Inspection on VLAN %d not from client's attributes

Source	Severity
EAP	Information

### Remedial action

Check if you really intended to make this setting on a different VLAN. If possible, the setting will be applied anyway.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# EAP: Warning, trying to set IGMP Snooping on VLAN %d not from client's attributes

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP: Warning, trying to set IGMP Snooping on VLAN %d not from client's attributes log

EAP: Warning, trying to set IGMP Snooping on VLAN %d not from client's attributes

Source	Severity
EAP	Information

### Remedial action

Check if you really intended to make this setting on a different VLAN. If possible, the setting will be applied anyway.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ECMP features disabled due to inadequate license

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ECMP features disabled due to inadequate license log

ECMP features disabled due to inadequate license

This message appears if the ECMP is enabled and the license is not available.

Source	Severity
L3Mgr	Information

### Remedial action

Acquire License for ECMP to enable this feature.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ECMP features disabled due to inadequate license.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ECMP features disabled due to inadequate license. log

ECMP features disabled due to inadequate license.

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Egp Neighbor Loss Trap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Egp Neighbor Loss Trap log

Egp Neighbor Loss Trap

Egp Neighbor Loss.

Source	Severity
SNMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Egp Neighbor Loss Trap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Egp Neighbor Loss Trap log

Egp Neighbor Loss Trap

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Egress interface and egress mask are mutually exclusive

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Egress interface and egress mask are mutually exclusive log

Egress interface and egress mask are mutually exclusive

Invalid egress mask.

Source	Severity
QoS	Serious

### Remedial action

Enter both options (egress unicast and egress non-unicast) with the same port.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Egress interface or trunk data is required - data missing

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Egress interface or trunk data is required - data missing log

Egress interface or trunk data is required - data missing

FCoE Redirect profile element data is not complete.

Source	Severity
FCoE Redirect	Information

### Remedial action

Specify all required profile data.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Element deletion prohibited (permanent read-only system entry)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Element deletion prohibited (permanent read-only system entry) log

Element deletion prohibited (permanent read-only system entry)

" System-owned policies cannot be deleted via the normal commands. Some of them may be removed through certain "disable" commands. "

Source	Severity
QoS	Information

### Remedial action

Check the documentation if necessary and use the appropriate disable command(s) where possible.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Element deletion prohibited (permanent/read-only/system entry)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Element deletion prohibited (permanent/read-only/system entry) log

Element deletion prohibited (permanent/read-only/system entry)

Source	Severity
QoS	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Element enable prohibited. Please delete and re-enter data

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Element enable prohibited. Please delete and re-enter data log

Element enable prohibited. Please delete and re-enter data

Request rejected as no underlying policies are configured.

Source	Severity
QoS	Serious

### Remedial action

Delete and re-enter valid data.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Element label contains unacceptable characters

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Element label contains unacceptable characters log

Element label contains unacceptable characters

Only printable characters are allowed

Source	Severity
QoS	Serious

### Remedial action

Enter valid characters for the access element's label.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Element label length outside of acceptable limits (max 16 chars)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Element label length outside of acceptable limits (max 16 chars) log

Element label length outside of acceptable limits (max 16 chars)

The maximum length for QoS labels is 16 characters.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Enter a smaller label in order for it to be accepted by the system.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Element label not acceptable - reserved

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Element label not acceptable - reserved log

Element label not acceptable - reserved

The label is reserved in the system.

Source	Severity
QoS	Information

### Remedial action

Enter a different label.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Element may only be modified not created or deleted

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Element may only be modified not created or deleted log

Element may only be modified not created or deleted

The specified element can only be modified. Possible entries: COS-to-DSCP assignment default values created at initialization; default DSCP-to-queue assignments and default CoS-to-queue assignments created when a new queue set is defined.

Source	Severity
QoS	Information

### Remedial action

Modify the existing entry if necessary.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Element modification prohibited (read-only or system entry)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Element modification prohibited (read-only or system entry) log

Element modification prohibited (read-only or system entry)

You cannot modify or remove a read-only or system entry.

Source	Severity
QoS	Information

### Remedial action

Create a similar entry with the proper modifications if necessary.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Enabling trunk ports:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Enabling trunk ports: log

Enabling trunk ports:

**Source**   **Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Energy Saver: activated by schedule

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Energy Saver: activated by schedule log

Energy Saver: activated by schedule

**Source**   **Severity**

NES

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Energy Saver: activated by schedule

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Energy Saver: activated by schedule log

Energy Saver: activated by schedule

**Source**   **Severity**

NES

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Energy Saver: deactivated by schedule

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Energy Saver: deactivated by schedule log

Energy Saver: deactivated by schedule

**Source**   **Severity**

NES

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Energy Saver: deactivated by schedule

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Energy Saver: deactivated by schedule log

Energy Saver: deactivated by schedule

**Source**   **Severity**

NES

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Energy Saver: globally disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Energy Saver: globally disabled log

Energy Saver: globally disabled

**Source**   **Severity**

NES

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Energy Saver: globally disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Energy Saver: globally disabled log

Energy Saver: globally disabled

**Source**   **Severity**

NES

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Energy Saver: globally enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Energy Saver: globally enabled log

Energy Saver: globally enabled

**Source**   **Severity**

NES

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Energy Saver: globally enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Energy Saver: globally enabled log

Energy Saver: globally enabled

**Source**   **Severity**

NES

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Energy Saver: manually activated

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Energy Saver: manually activated log

Energy Saver: manually activated

**Source**   **Severity**

NES

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Energy Saver: manually activated

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Energy Saver: manually activated log

Energy Saver: manually activated

**Source**   **Severity**

NES

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Energy Saver: manually deactivated

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Energy Saver: manually deactivated log

Energy Saver: manually deactivated

**Source**   **Severity**

NES

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Energy Saver: manually deactivated

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Energy Saver: manually deactivated log

Energy Saver: manually deactivated

**Source**   **Severity**

NES

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Energy Saver: not applying schedule because NTP/SNTP not synchronized

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Energy Saver: not applying schedule because NTP/SNTP not synchronized log

Energy Saver: not applying schedule because NTP/SNTP not synchronized

**Source**   **Severity**  
NES

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Energy Saver: not applying schedule because NTP/SNTP not synchronized

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Energy Saver: not applying schedule because NTP/SNTP not synchronized log

Energy Saver: not applying schedule because NTP/SNTP not synchronized

**Source**   **Severity**  
NES

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Energy Saver: time is synchronized, applying schedule

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Energy Saver: time is synchronized, applying schedule log

Energy Saver: time is synchronized, applying schedule

**Source**   **Severity**

NES

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Energy Saver: time is synchronized, applying schedule

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Energy Saver: time is synchronized, applying schedule log

Energy Saver: time is synchronized, applying schedule

**Source**   **Severity**

NES

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Energy Server activated by schedule

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Energy Server activated by schedule log

Energy Server activated by schedule

The Engery Saver is activated by the schedule.

Source	Severity
Energy Server	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Energy Server deactivated by schedule

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Energy Server deactivated by schedule log

Energy Server deactivated by schedule

The Energy Saver is deactivated by the schedule.

Source	Severity
Energy Server	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Energy Server globally disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Energy Server globally disabled log

Energy Server globally disabled

The Energy Saver is disabled.

Source	Severity
Energy Server	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Energy Server globally enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Energy Server globally enabled log

Energy Server globally enabled

The Engery Saver is enabled.

Source	Severity
Energy Server	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Energy Server manually activated

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Energy Server manually activated log

Energy Server manually activated

The Energy Saver is manually activated.

Source	Severity
Energy Server	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Energy Server manually deactivated

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Energy Server manually deactivated log

Energy Server manually deactivated

The Engery Saver is manually deactivated.

Source	Severity
Energy Server	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Energy Server not applying schedule because SNTP not synchronized

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Energy Server not applying schedule because SNTP not synchronized log

Energy Server not applying schedule because SNTP not synchronized

The Energy Saver cannot be activated, as the internal clock is not synchronized with SNTP Server

Source	Severity
Energy Server	Information

### Remedial action

Check the availability of the SNTP server, and wait for the clock to be synchronized with SNTP Server.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Energy Server time is synchronized applying schedule

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Energy Server time is synchronized applying schedule log

Energy Server time is synchronized applying schedule

The Energy Saver schedule is applied, as the clock is synchronized with the SNTP.

Source	Severity
Energy Server	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Eng Menu Generation Test - Customer Message %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Eng Menu Generation Test - Customer Message %d log

Eng Menu Generation Test - Customer Message %d

**Source**      **Severity**

ENGMENU

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Eng Menu Test Msg #1 : Hi there! This is 1st test message .

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Eng Menu Test Msg #1 : Hi there! This is 1st test message . log

Eng Menu Test Msg #1 : Hi there! This is 1st test message .

**Source**      **Severity**

ENGMENU

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Eng Menu Test Msg #2 : Hi there! This is 2st test message .

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Eng Menu Test Msg #2 : Hi there! This is 2st test message . log

Eng Menu Test Msg #2 : Hi there! This is 2st test message .

**Source**      **Severity**

ENGMENU

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Eng Menu Test Msg #3 : Hi there! This is 3st test message .

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Eng Menu Test Msg #3 : Hi there! This is 3st test message . log

Eng Menu Test Msg #3 : Hi there! This is 3st test message .

**Source**      **Severity**

ENGMENU

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Eng Menu Test Msg #4 : Hi there! This is 4st test message .

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Eng Menu Test Msg #4 : Hi there! This is 4st test message . log

Eng Menu Test Msg #4 : Hi there! This is 4st test message .

**Source**      **Severity**

ENGMENU

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Eng Menu Test Msg #0 : No Error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Eng Menu Test Msg #0 : No Error log

Eng Menu Test Msg #0 : No Error

Source	Severity
--------	----------

ENGMENU	
---------	--

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Enterprise Specific Trap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Enterprise Specific Trap log

Enterprise Specific Trap

Enterprise Specific Trap.

Source	Severity
SNMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Enterprise Specific Trap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Enterprise Specific Trap log

Enterprise Specific Trap

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Entry already exists

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Entry already exists log

Entry already exists

Source	Severity
--------	----------

L3Mgr	
-------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Entry does not exist

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Entry does not exist log

Entry does not exist

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Entry is not active

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Entry is not active log

Entry is not active

Source	Severity
--------	----------

L3Mgr	
-------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error log

Error

Source	Severity
--------	----------

L3Mgr	
-------	--

Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error accessing Image File

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error accessing Image File log

Error accessing Image File

The system could not find the image file.

Source	Severity
Console	Serious

### Remedial action

Enter a valid image file name

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error Bad Image Checksum

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error Bad Image Checksum log

Error Bad Image Checksum

The system indicated a Bad Image Checksum.

Source	Severity
Console	Serious

### Remedial action

Enter a different image.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error clearing the configuration counters from flash history on unit %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error clearing the configuration counters from flash history on unit %d log

Error clearing the configuration counters from flash history on unit %d

After a config area remap, resetting the config counters from flash history fails

Source	Severity
MCFG	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error: CML gw\_bcmx\_chip\_to\_modid unit %d chip %d rv %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error: CML gw\_bcmx\_chip\_to\_modid unit %d chip %d rv %d log

Error: CML gw\_bcmx\_chip\_to\_modid unit %d chip %d rv %d

### Source    Severity

CDT

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Error: CML lppm\_get\_unit chip %d port %d p->port 0x%x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error: CML lppm\_get\_unit chip %d port %d p->port 0x%x log

Error: CML lppm\_get\_unit chip %d port %d p->port 0x%x

**Source**   **Severity**

CDT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error: CML received MAC with unit %d on unit %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error: CML received MAC with unit %d on unit %d log

Error: CML received MAC with unit %d on unit %d

**Source**   **Severity**

CDT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error configuring 802.1AB

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error configuring 802.1AB log

Error configuring 802.1AB

Cannot configure LLDP med-network-policies or dot1q-framing tagging

### Source

Run scripts: IP Office, LLDP

### Severity

Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error configuring LLDP MED policies

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error configuring LLDP MED policies log

Error configuring LLDP MED policies

Cannot configure LLDP med-network-policies parameters.

Source	Severity
Run scripts: LLDP, ADAC	Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error configuring Management IP Address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error configuring Management IP Address log

Error configuring Management IP Address

IP address conflict

### Source

Run scripts: LLDP, ADAC

### Severity

Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error configuring port names

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error configuring port names log

Error configuring port names

Cannot set port names.

Source	Severity
Run scripts: IP Office	Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error copying the configuration to new flash areas on unit %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error copying the configuration to new flash areas on unit %d log

Error copying the configuration to new flash areas on unit %d

Due to exhaustion of old flash config areas, sometimes we're unable to copy the existing config to a new flash area.

Source	Severity
MCFG	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error creating Data VLAN

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error creating Data VLAN log

Error creating Data VLAN

Cannot create new Data VLAN.

### Source

Run scripts: IP Office, LLDP, ADAC

### Severity

Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Error creating MLT

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error creating MLT log

Error creating MLT

Cannot create new trunk for uplink ports.

Source	Severity
Run scripts: ADAC	Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error creating Voice VLAN

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error creating Voice VLAN log

Error creating Voice VLAN

Cannot create new Voice VLAN. (Maximum number of Voice Vlan reached)

### Source

Run scripts: IP Office, LLDP, ADAC

### Severity

Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error deleting previously created cost 1 default route

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error deleting previously created cost 1 default route log

Error deleting previously created cost 1 default route

Error delting default ip route.

### Source

Run scripts: IP Office, LLDP, ADAC

### Severity

Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error deleting previously created Voice and Data VLANs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error deleting previously created Voice and Data VLANs log

Error deleting previously created Voice and Data VLANs

Error deleting existing VLAN.

### Source

Run scripts: IP Office, LLDP, ADAC

### Severity

Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error disabling global DHCP relay %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error disabling global DHCP relay %d log

Error disabling global DHCP relay %d

**Source**   **Severity**

DHCPR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error disabling global DHCP relay errCode

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error disabling global DHCP relay errCode log

Error disabling global DHCP relay errCode

The DHCP relay cannot be globally disabled as the appropriate filter could not be uninstalled (other DHCP application is using it).

Source	Severity
DHCPR	Information

### Remedial action

Redo the QoS filter allocations, and retry to disable the DHCPR.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error enabling ADAC

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error enabling ADAC log

Error enabling ADAC

Cannot enable ADAC.

### Source

Run scripts: ADAC

### Severity

Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error enabling ADAC on ports

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error enabling ADAC on ports log

Error enabling ADAC on ports

Cannot configure telephony ports.

Source	Severity
Run scripts: ADAC	Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Error enabling global DHCP relay %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error enabling global DHCP relay %d log

Error enabling global DHCP relay %d

**Source**   **Severity**

DHCPR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error enabling global DHCP relay errCode

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error enabling global DHCP relay errCode log

Error enabling global DHCP relay errCode

The DHCP relay cannot be enabled globally as the appropriate filter cannot be installed (other DHCP application has already installed it).

Source	Severity
DHCPR	Information

### Remedial action

Redo the QoS filter allocations, and retry to enable the DHCPR.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error enabling IP Routing

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error enabling IP Routing log

Error enabling IP Routing

Cannot enable IP routing.

### Source

Run scripts: LLDP, ADAC

### Severity

Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error enabling mstp learning on all ports

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error enabling mstp learning on all ports log

Error enabling mstp learning on all ports

Cannot configure MSTP on ports.

Source	Severity
Run scripts: IP Office	Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error enabling rstp learning on all ports

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error enabling rstp learning on all ports log

Error enabling rstp learning on all ports

Cannot configure RSTP on ports.

Source	Severity
Run scripts: IP Office	Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error executing script

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error executing script log

Error executing script

Cannot continue with the script execution.

### Source

Run scripts: IP Office, LLDP, ADAC

### Severity

Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error getting VLAN info for Port's pvid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error getting VLAN info for Port's pvid log

Error getting VLAN info for Port's pvid

There was an error when reading the VLAN configuration from NVRAM.

Source	Severity
VLAN	Information

### Remedial action

No action required.



# Error in DMA transfer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error in DMA transfer log

Error in DMA transfer

**Source**   **Severity**

CDT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Error in q\_smgr.c - line %d, p1 = %d, p2 = %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error in q\_smgr.c - line %d, p1 = %d, p2 = %d log

Error in q\_smgr.c - line %d, p1 = %d, p2 = %d

### Source    Severity

VLAN

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error in XGS3 memory DMA transfer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error in XGS3 memory DMA transfer log

Error in XGS3 memory DMA transfer

Logs an error for XGS3 switches in case of DMA error.

Source	Severity
CDT	Serious

### Remedial action

Reboot device

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error loading backup configuration block %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error loading backup configuration block %d log

Error loading backup configuration block %d

The system failed to load the backup configuration.

Source	Severity
MCFG	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error loading configuration block %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error loading configuration block %d log

Error loading configuration block %d

The system failed to load configuration from block n.

Source	Severity
config	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error loading primary configuration block # block\_number

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error loading primary configuration block # block\_number log

Error loading primary configuration block # block\_number

The system failed to load the primary configuration.

Source	Severity
config	Information

### Remedial action

No action required.



# Error loading primary configuration block %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error loading primary configuration block %d log

Error loading primary configuration block %d

**Source**   **Severity**

MCFG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error reading Image File

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error reading Image File log

Error reading Image File

The system could not read the image file.

Source	Severity
Console	Serious

### Remedial action

Enter a valid image.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error reading nvq\_ObjDescr from VLAN file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error reading nvq\_ObjDescr from VLAN file log

Error reading nvq\_ObjDescr from VLAN file

There was an error when reading the VLAN configuration from NVRAM.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Error reading prec from VLAN file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error reading prec from VLAN file log

Error reading prec from VLAN file

There was an error when reading the VLAN configuration from NVRAM.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error reading vmrec from VLAN file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error reading vmrec from VLAN file log

Error reading vmrec from VLAN file

There was an error when reading the VLAN configuration from NVRAM.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error reading vrec from VLAN file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error reading vrec from VLAN file log

Error reading vrec from VLAN file

There was an error when reading the VLAN configuration from NVRAM.

Source	Severity
VLAN	Information

### Remedial action

No action required.



# Error restoring from VLAN file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error restoring from VLAN file log

Error restoring from VLAN file

There was an error when reading the VLAN configuration from NVRAM.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error restoring from VLAN file. Wrong nvq.Descr.devVer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error restoring from VLAN file. Wrong nvq.Descr.devVer log

Error restoring from VLAN file. Wrong nvq.Descr.devVer

There was an error when reading the VLAN configuration from NVRAM.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error restoring from VLAN file. Wrong nvq.Descr.notBlank

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error restoring from VLAN file. Wrong nvq.Descr.notBlank log

Error restoring from VLAN file. Wrong nvq.Descr.notBlank

There was an error when reading the VLAN configuration from NVRAM.

Source	Severity
VLAN	Information

### Remedial action

No action required.



# Error restoring management vlan to 1 or disabling ip routing

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error restoring management vlan to 1 or disabling ip routing log

Error restoring management vlan to 1 or disabling ip routing

Previously configured settings (by user or another execution of the script) must be deleted at the beginning of the script to allow other settings to be made. In this case, IP routing cannot be disabled or the management vlan restored to VID 1.

### Source

Run scripts: IP Office, LLDP, ADAC

### Severity

Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error restoring nvq.Descr from VLAN file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error restoring nvq.Descr from VLAN file log

Error restoring nvq.Descr from VLAN file

There was an error when reading the VLAN configuration from NVRAM.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Error restoring object from VLAN file - bad file pointer or mode

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error restoring object from VLAN file - bad file pointer or mode log

Error restoring object from VLAN file - bad file pointer or mode

There was an error when reading the VLAN configuration from NVRAM.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error restoring object from VLAN file - bad file pointer or mode.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error restoring object from VLAN file - bad file pointer or mode. log

Error restoring object from VLAN file - bad file pointer or mode.

**Source**   **Severity**

VLAN

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error restoring object from VLAN NVRAM file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error restoring object from VLAN NVRAM file log

Error restoring object from VLAN NVRAM file

There was an error when reading the VLAN configuration from NVRAM.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error restoring Port from VLAN NVRAM file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error restoring Port from VLAN NVRAM file log

Error restoring Port from VLAN NVRAM file

There was an error when reading the VLAN configuration from NVRAM.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error restoring Ports from VLAN file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error restoring Ports from VLAN file log

Error restoring Ports from VLAN file

There was an error when reading the VLAN configuration from NVRAM.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error restoring VLANs from VLAN file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error restoring VLANs from VLAN file log

Error restoring VLANs from VLAN file

There was an error when reading the VLAN configuration from NVRAM.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error restoring VMACs from VLAN file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error restoring VMACs from VLAN file log

Error restoring VMACs from VLAN file

There was an error when reading the VLAN configuration from NVRAM.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error saving configuration

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error saving configuration log

Error saving configuration

Cannot save current configuration.

### Source

Run scripts: IP Office, LLDP, ADAC

### Severity

Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Error saving configuration to block # block\_number

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error saving configuration to block # block\_number log

Error saving configuration to block # block\_number

The system failed to save the configuration to block n.

Source	Severity
config	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error saving configuration to block %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error saving configuration to block %d log

Error saving configuration to block %d

**Source**   **Severity**

MCFG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error seeking object in VLAN file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error seeking object in VLAN file log

Error seeking object in VLAN file

There was an error when reading the VLAN configuration from NVRAM.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error seeking Ports in VLAN file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error seeking Ports in VLAN file log

Error seeking Ports in VLAN file

There was an error when reading the VLAN configuration from NVRAM.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error seeking VLANs in VLAN file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error seeking VLANs in VLAN file log

Error seeking VLANs in VLAN file

There was an error when reading the VLAN configuration from NVRAM.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error seeking VMACs in VLAN file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error seeking VMACs in VLAN file log

Error seeking VMACs in VLAN file

There was an error when reading the VLAN configuration from NVRAM.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error setting ADAC operating mode

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error setting ADAC operating mode log

Error setting ADAC operating mode

Cannot set ADAC tagged frames operating mode.

Source	Severity
Run scripts: ADAC	Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error setting call server ports

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error setting call server ports log

Error setting call server ports

Cannot configure ports as Call-Server ports..

Source	Severity
Run scripts: ADAC	Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Error setting Data VLAN Gateway IP address and network mask

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error setting Data VLAN Gateway IP address and network mask log

Error setting Data VLAN Gateway IP address and network mask

IP address conflict.

### Source

Run scripts: IP Office, LLDP, ADAC

### Severity

Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error setting default IP Route

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error setting default IP Route log

Error setting default IP Route

IP address conflict.

### Source

Run scripts: IP Office, LLDP, ADAC

### Severity

Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error setting IP Office Call-Server IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error setting IP Office Call-Server IP address log

Error setting IP Office Call-Server IP address

Cannot configure Call-Server IP Address.

### Source

Run scripts: IP Office, LLDP, ADAC

### Severity

Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error setting IP Office File-Server IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error setting IP Office File-Server IP address log

Error setting IP Office File-Server IP address

Cannot configure File-Server IP Address.

### Source

Run scripts: IP Office, LLDP, ADAC

### Severity

Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error setting Management VLAN

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error setting Management VLAN log

Error setting Management VLAN

Cannot set Data V:AM as Management VLAN.

Source	Severity
Run scripts: LLDP, ADAC	Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error setting poe-priority high on ports

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error setting poe-priority high on ports log

Error setting poe-priority high on ports

Cannot configure poe priority

Source	Severity
Run scripts: IP Office	Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error setting QoS

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error setting QoS log

Error setting QoS

Cannot add new QoS interface group of trusted.

Source	Severity
Run scripts: IP Office, LLDP	Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error setting spanning-tree learning to fast on all ports

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error setting spanning-tree learning to fast on all ports log

Error setting spanning-tree learning to fast on all ports

Cannot configure STP on ports.

### Source

Run scripts: IP Office, LLDP, ADAC

### Severity

Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Error setting the remap flag in flash on unit %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error setting the remap flag in flash on unit %d log

Error setting the remap flag in flash on unit %d

Due to exhaustion of flash areas, sometimes we're unable to remap the unit.

Source	Severity
MCFG	Information

### Remedial action

Retry the operation.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error setting uplink ports

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error setting uplink ports log

Error setting uplink ports

Cannot configure ports as Uplinks.

Source	Severity
Run scripts: LLDP, ADAC	Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error setting VLAN attributes

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error setting VLAN attributes log

Error setting VLAN attributes

Error setting port vlan membership and tagging or (only for Ip Office script) setting the Data VLAN as management VLAN.

### Source

Run scripts: IP Office, LLDP, ADAC

### Severity

Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error setting VLAN Gateway IP address and network mask

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error setting VLAN Gateway IP address and network mask log

Error setting VLAN Gateway IP address and network mask

IP address conflict.

### Source

Run scripts: LLDP, ADAC

### Severity

Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error setting Voice VLAN Gateway IP address and network mask

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error setting Voice VLAN Gateway IP address and network mask log

Error setting Voice VLAN Gateway IP address and network mask

IP address conflict.

### Source

Run scripts: IP Office, LLDP, ADAC

### Severity

Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# Error updating Private VLAN configuration when transitioning from

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error updating Private VLAN configuration when transitioning from log

Error updating Private VLAN configuration when transitioning from

**Source**   **Severity**  
VLAN

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error updating Private VLAN configuration when trying to

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error updating Private VLAN configuration when trying to log

Error updating Private VLAN configuration when trying to

**Source**   **Severity**

VLAN

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error/Warning - Eap File Read: readVer %d in %s:cfgVer %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error/Warning - Eap File Read: readVer %d in %s:cfgVer %d log

Error/Warning - Eap File Read: readVer %d in %s:cfgVer %d

### Source    Severity

EAP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Error/Warning - Eap File signals a software downgrade:%d (%s:%d), default all eap settings

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error/Warning - Eap File signals a software downgrade:%d (%s:%d), default all eap settings log

Error/Warning - Eap File signals a software downgrade:%d (%s:%d), default all eap settings

The EAP Settings are defaulted as a result of downgrade.

Source	Severity
EAP	Information

### Remedial action

None



# Error/Warning - Eap File Version Mismatch:%d (%s:%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error/Warning - Eap File Version Mismatch:%d (%s:%d) log

Error/Warning - Eap File Version Mismatch:%d (%s:%d)

**Source    Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Error/Warning - Eap File Write:%d (%s:%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Error/Warning - Eap File Write:%d (%s:%d) log

Error/Warning - Eap File Write:%d (%s:%d)

**Source    Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



## Error/Warning - Param:%d (%s:%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

### Error/Warning - Param:%d (%s:%d) log

Error/Warning - Param:%d (%s:%d)

**Source    Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Evaluation precedence conflict detected (NSNA filter set data)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Evaluation precedence conflict detected (NSNA filter set data) log

Evaluation precedence conflict detected (NSNA filter set data)

**Source   Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Evaluation precedence conflict detected (UBP filter set data)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Evaluation precedence conflict detected (UBP filter set data) log

Evaluation precedence conflict detected (UBP filter set data)

Unable to make the required changes.

Source	Severity
QoS	Serious

### Remedial action

Check the availability of resources on the specified port or use a different interface index.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Evaluation precedence conflict (Traffic Prof filter set data)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Evaluation precedence conflict (Traffic Prof filter set data) log

Evaluation precedence conflict (Traffic Prof filter set data)

The system detected a Precedence conflict - multiple entries cannot occupy the same precedence on the same port.

Source	Severity
QoS	Serious

### Remedial action

Check for the available precedence, and remove the resources that are not needed if any.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Evaluation precedence value required but not specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Evaluation precedence value required but not specified log

Evaluation precedence value required but not specified

A precedence must be assigned to the access classifier (similar to the policy), else it cannot be installed on the interface.

Source	Severity
QoS	Serious

### Remedial action

Enter a specific or the next available precedence.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Event logging disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Event logging disabled log

Event logging disabled

**Source**   **Severity**

SLOG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Event logging enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Event logging enabled log

Event logging enabled

**Source**   **Severity**

SLOG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Event %s(%d) causes state transition to %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Event %s(%d) causes state transition to %s log

Event %s(%d) causes state transition to %s

### Source    Severity

SMGR

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Exception tid=%p vec=%#x esf=%#x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Exception tid=%p vec=%#x esf=%#x log

Exception tid=%p vec=%#x esf=%#x

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: agent settings reset incomplete

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: agent settings reset incomplete log

Fabric Attach: agent settings reset incomplete

Previously established settings were not completely cleaned-up as expected.

Source	Severity
Fabric Attach	Major

### Remedial action

Check VLAN and/or SPBM settings restored after a reset and delete settings that are no longer needed.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: application discovery notification (event %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: application discovery notification (event %d) log

Fabric Attach: application discovery notification (event %d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: application state notification (event %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: application state notification (event %d) log

Fabric Attach: application state notification (event %d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: asgn activation failure (port tagging)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: asgn activation failure (port tagging) log

Fabric Attach: asgn activation failure (port tagging)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Fabric Attach: asgn activation failure (PVID update)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: asgn activation failure (PVID update) log

Fabric Attach: asgn activation failure (PVID update)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: asgn activation failure (switched UNI creation)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: asgn activation failure (switched UNI creation) log

Fabric Attach: asgn activation failure (switched UNI creation)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: asgn activation failure (VLAN creation)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: asgn activation failure (VLAN creation) log

Fabric Attach: asgn activation failure (VLAN creation)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: asgn activation failure (VLAN membership)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: asgn activation failure (VLAN membership) log

Fabric Attach: asgn activation failure (VLAN membership)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: asgn rejection failure (port PVID update)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: asgn rejection failure (port PVID update) log

Fabric Attach: asgn rejection failure (port PVID update)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: asgn rejection failure (switched UNI deletion)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: asgn rejection failure (switched UNI deletion) log

Fabric Attach: asgn rejection failure (switched UNI deletion)

### Source                      Severity

Fabric Attach

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: asgn rejection failure (VLAN deletion)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: asgn rejection failure (VLAN deletion) log

Fabric Attach: asgn rejection failure (VLAN deletion)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: asgn rejection failure (VLAN membership)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: asgn rejection failure (VLAN membership) log

Fabric Attach: asgn rejection failure (VLAN membership)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Fabric Attach: asgn reset issues (%d asgns)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: asgn reset issues (%d asgns) log

Fabric Attach: asgn reset issues (%d asgns)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: Auto Attach capabilities disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: Auto Attach capabilities disabled log

Fabric Attach: Auto Attach capabilities disabled

The Fabric Attach Auto Attach service was disabled.

Source	Severity
Fabric Attach	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: Auto Attach capabilities enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: Auto Attach capabilities enabled log

Fabric Attach: Auto Attach capabilities enabled

The Fabric Attach Auto Attach service was enabled.

Source	Severity
Fabric Attach	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: auto attach operations not completed (VLAN <VID>)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: auto attach operations not completed (VLAN <VID>) log

Fabric Attach: auto attach operations not completed (VLAN <VID>)

Auto Attach processing failed.

Source	Severity
Fabric Attach	Minor

### Remedial action

Verify that the data provided by the FA Server does not cause any conflicts on the device. Resolve conflicts and retry.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: auto provision setting not supported by platform

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: auto provision setting not supported by platform log

Fabric Attach: auto provision setting not supported by platform

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: binding acceptance failure (ifc %d %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: binding acceptance failure (ifc %d %d/%d) log

Fabric Attach: binding acceptance failure (ifc %d %d/%d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: binding acceptance failure (port %d %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: binding acceptance failure (port %d %d/%d) log

Fabric Attach: binding acceptance failure (port %d %d/%d)

Identified I-SID/VLAN binding rejected by FA Server on identified standalone port

Source	Severity
Fabric Attach	Information

### Remedial action

No action required



# Fabric Attach: binding acceptance failure (port %d/%d %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: binding acceptance failure (port %d/%d %d/%d) log

Fabric Attach: binding acceptance failure (port %d/%d %d/%d)

Identified I-SID/VLAN binding rejected by FA Server on identified stack port

Source	Severity
Fabric Attach	Information

### Remedial action

No action required





# Fabric Attach: binding accepted (ifc %d %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: binding accepted (ifc %d %d/%d) log

Fabric Attach: binding accepted (ifc %d %d/%d)

**Source**      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: binding accepted (port %d %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: binding accepted (port %d %d/%d) log

Fabric Attach: binding accepted (port %d %d/%d)

Identified I-SID/VLAN binding accepted by FA Server on identified standalone port

Source	Severity
Fabric Attach	Information

### Remedial action

No action required



# Fabric Attach: binding accepted (port %d/%d %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: binding accepted (port %d/%d %d/%d) log

Fabric Attach: binding accepted (port %d/%d %d/%d)

Identified I-SID/VLAN binding accepted by FA Server on identified stack port

Source	Severity
Fabric Attach	Information

### Remedial action

No action required



# Fabric Attach: binding activation failure (%d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: binding activation failure (%d/%d) log

Fabric Attach: binding activation failure (%d/%d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: binding activation success (ifc %d %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: binding activation success (ifc %d %d/%d) log

Fabric Attach: binding activation success (ifc %d %d/%d)

**Source**      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: binding activation success (port %d %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: binding activation success (port %d %d/%d) log

Fabric Attach: binding activation success (port %d %d/%d)

Identified I-SID/VLAN binding activated (VLAN settings updated) on FA Proxy for identified standalone port

Source	Severity
Fabric Attach	Information

### Remedial action

No action required



# Fabric Attach: binding activation success (port %d/%d %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: binding activation success (port %d/%d %d/%d) log

Fabric Attach: binding activation success (port %d/%d %d/%d)

Identified I-SID/VLAN binding activated (VLAN settings updated) on FA Proxy for identified stack port

Source	Severity
Fabric Attach	Information

### Remedial action

No action required

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: binding activation success (trunk %d %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: binding activation success (trunk %d %d/%d) log

Fabric Attach: binding activation success (trunk %d %d/%d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Fabric Attach: binding deactivation failure (ifc %d %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: binding deactivation failure (ifc %d %d/%d) log

Fabric Attach: binding deactivation failure (ifc %d %d/%d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: binding deactivation failure (port %d %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: binding deactivation failure (port %d %d/%d) log

Fabric Attach: binding deactivation failure (port %d %d/%d)

Identified I-SID/VLAN binding rejection cleanup failed on FA Proxy for identified standalone port

Source	Severity
Fabric Attach	Information

### Remedial action

No action required

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: binding deactivation failure (port %d/%d %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: binding deactivation failure (port %d/%d %d/%d) log

Fabric Attach: binding deactivation failure (port %d/%d %d/%d)

Identified I-SID/VLAN binding rejection cleanup failed on FA Proxy for identified stack port

Source	Severity
Fabric Attach	Information

### Remedial action

No action required

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: binding deactivation failure (trunk %d %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: binding deactivation failure (trunk %d %d/%d) log

Fabric Attach: binding deactivation failure (trunk %d %d/%d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: binding deactivation success (ifc %d %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: binding deactivation success (ifc %d %d/%d) log

Fabric Attach: binding deactivation success (ifc %d %d/%d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: binding deactivation success (port %d %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: binding deactivation success (port %d %d/%d) log

Fabric Attach: binding deactivation success (port %d %d/%d)

Identified I-SID/VLAN binding deactivated (VLAN settings updated) on FA Proxy for identified standalone port

Source	Severity
Fabric Attach	Information

### Remedial action

No action required

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: binding deactivation success (port %d/%d %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: binding deactivation success (port %d/%d %d/%d) log

Fabric Attach: binding deactivation success (port %d/%d %d/%d)

Identified I-SID/VLAN binding deactivated (VLAN settings updated) on FA Proxy for identified stack port

Source	Severity
Fabric Attach	Information

### Remedial action

No action required

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: binding deactivation success (trunk %d %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: binding deactivation success (trunk %d %d/%d) log

Fabric Attach: binding deactivation success (trunk %d %d/%d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Fabric Attach: binding deleted (ifc %d %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: binding deleted (ifc %d %d/%d) log

Fabric Attach: binding deleted (ifc %d %d/%d)

**Source**      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: binding expiration (ifc %d %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: binding expiration (ifc %d %d/%d) log

Fabric Attach: binding expiration (ifc %d %d/%d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: binding expiration (port %d %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: binding expiration (port %d %d/%d) log

Fabric Attach: binding expiration (port %d %d/%d)

Identified I-SID/VLAN binding deleted by FA Server on identified standalone port

Source	Severity
Fabric Attach	Information

### Remedial action

No action required



# Fabric Attach: binding expiration (port %d/%d %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: binding expiration (port %d/%d %d/%d) log

Fabric Attach: binding expiration (port %d/%d %d/%d)

Identified I-SID/VLAN binding deleted by FA Server on identified stack port

Source	Severity
Fabric Attach	Information

### Remedial action

No action required



# Fabric Attach: binding updated (ifc %d %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: binding updated (ifc %d %d/%d) log

Fabric Attach: binding updated (ifc %d %d/%d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: can't transition to server from standalone mode

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: can't transition to server from standalone mode log

Fabric Attach: can't transition to server from standalone mode

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: can't update standalone mode setting in server mode

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: can't update standalone mode setting in server mode log

Fabric Attach: can't update standalone mode setting in server mode

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: client attach delete failure - Type %d (VLAN deletion)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: client attach delete failure - Type %d (VLAN deletion) log

Fabric Attach: client attach delete failure - Type %d (VLAN deletion)

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Fabric Attach: client attach delete failure - Type %d (VLAN membership)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: client attach delete failure - Type %d (VLAN membership) log

Fabric Attach: client attach delete failure - Type %d (VLAN membership)

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: client attach install failure - Type %d (I-SID/VLAN binding install)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: client attach install failure - Type %d (I-SID/VLAN binding install) log

Fabric Attach: client attach install failure - Type %d (I-SID/VLAN binding install)

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: client attach install failure - Type %d (priority update)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: client attach install failure - Type %d (priority update) log

Fabric Attach: client attach install failure - Type %d (priority update)

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: client attach install failure - Type %d (PVID update)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: client attach install failure - Type %d (PVID update) log

Fabric Attach: client attach install failure - Type %d (PVID update)

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: client attach install failure - Type %d (tagging mode update)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: client attach install failure - Type %d (tagging mode update) log

Fabric Attach: client attach install failure - Type %d (tagging mode update)

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: client attach install failure - Type %d (VLAN creation)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: client attach install failure - Type %d (VLAN creation) log

Fabric Attach: client attach install failure - Type %d (VLAN creation)

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: client attach install failure - Type %d (VLAN membership)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: client attach install failure - Type %d (VLAN membership) log

Fabric Attach: client attach install failure - Type %d (VLAN membership)

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: client binding accepted (%d/%d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: client binding accepted (%d/%d/%d) log

Fabric Attach: client binding accepted (%d/%d/%d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Fabric Attach: client binding conflict detected (%d/%d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: client binding conflict detected (%d/%d/%d) log

Fabric Attach: client binding conflict detected (%d/%d/%d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: client binding deleted (%d/%d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: client binding deleted (%d/%d/%d) log

Fabric Attach: client binding deleted (%d/%d/%d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: client detection settings update failed (type %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: client detection settings update failed (type %d) log

Fabric Attach: client detection settings update failed (type %d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: client settings update failed (type %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: client settings update failed (type %d) log

Fabric Attach: client settings update failed (type %d)

**Source**      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: client update requires global zero touch option be enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: client update requires global zero touch option be enabled log

Fabric Attach: client update requires global zero touch option be enabled

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: conflicting uplink data detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: conflicting uplink data detected log

Fabric Attach: conflicting uplink data detected

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: device deleted (port %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: device deleted (port %d) log

Fabric Attach: device deleted (port %d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: device deleted (port %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: device deleted (port %d/%d) log

Fabric Attach: device deleted (port %d/%d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Fabric Attach: device deleted (stack operations)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: device deleted (stack operations) log

Fabric Attach: device deleted (stack operations)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: device deleted (trunk %d port %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: device deleted (trunk %d port %d) log

Fabric Attach: device deleted (trunk %d port %d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: device deleted (trunk %d port %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: device deleted (trunk %d port %d/%d) log

Fabric Attach: device deleted (trunk %d port %d/%d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: device discovered (Auth Fail - element %d port %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: device discovered (Auth Fail - element %d port %d) log

Fabric Attach: device discovered (Auth Fail - element %d port %d)

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: device discovered (Auth Fail - element %d port %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: device discovered (Auth Fail - element %d port %d/%d) log

Fabric Attach: device discovered (Auth Fail - element %d port %d/%d)

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: device discovered (Auth Fail - element %d trunk %d port %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: device discovered (Auth Fail - element %d trunk %d port %d) log

Fabric Attach: device discovered (Auth Fail - element %d trunk %d port %d)

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Fabric Attach: device discovered (Auth Fail - element %d trunk %d port %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: device discovered (Auth Fail - element %d trunk %d port %d/%d) log

Fabric Attach: device discovered (Auth Fail - element %d trunk %d port %d/%d)

Source	Severity
Fabric Attach	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: device discovered (Auth Pass - element %d port %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: device discovered (Auth Pass - element %d port %d) log

Fabric Attach: device discovered (Auth Pass - element %d port %d)

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Fabric Attach: device discovered (Auth Pass - element %d port %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: device discovered (Auth Pass - element %d port %d/%d) log

Fabric Attach: device discovered (Auth Pass - element %d port %d/%d)

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: device discovered (Auth Pass - element %d trunk %d port %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: device discovered (Auth Pass - element %d trunk %d port %d) log

Fabric Attach: device discovered (Auth Pass - element %d trunk %d port %d)

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Fabric Attach: device discovered (Auth  
Pass - element %d trunk %d port  
%d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: device discovered (Auth Pass - element %d trunk %d port %d/%d) log

Fabric Attach: device discovered (Auth Pass - element %d trunk %d port %d/%d)

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: device discovered (Not Auth - element %d port %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: device discovered (Not Auth - element %d port %d) log

Fabric Attach: device discovered (Not Auth - element %d port %d)

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: device discovered (Not Auth - element %d port %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: device discovered (Not Auth - element %d port %d/%d) log

Fabric Attach: device discovered (Not Auth - element %d port %d/%d)

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: device discovered (Not Auth - element %d trunk %d port %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: device discovered (Not Auth - element %d trunk %d port %d) log

Fabric Attach: device discovered (Not Auth - element %d trunk %d port %d)

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Fabric Attach: device discovered (Not Auth - element %d trunk %d port %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: device discovered (Not Auth - element %d trunk %d port %d/%d) log

Fabric Attach: device discovered (Not Auth - element %d trunk %d port %d/%d)

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: device expired (port %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: device expired (port %d) log

Fabric Attach: device expired (port %d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Fabric Attach: device expired (port %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: device expired (port %d/%d) log

Fabric Attach: device expired (port %d/%d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: device expired (trunk %d port %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: device expired (trunk %d port %d) log

Fabric Attach: device expired (trunk %d port %d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: device expired (trunk %d port %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: device expired (trunk %d port %d/%d) log

Fabric Attach: device expired (trunk %d port %d/%d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: EAP notification - discovery (ifc %d type %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: EAP notification - discovery (ifc %d type %d) log

Fabric Attach: EAP notification - discovery (ifc %d type %d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: EAP notification - expiration (ifc %d type %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: EAP notification - expiration (ifc %d type %d) log

Fabric Attach: EAP notification - expiration (ifc %d type %d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: element type updated

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: element type updated log

Fabric Attach: element type updated

The Fabric Attach element type has been updated.

Source	Severity
Fabric Attach	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: expiration cleanup issue detected (%d secs)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: expiration cleanup issue detected (%d secs) log

Fabric Attach: expiration cleanup issue detected (%d secs)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: incompatible device advertisement (port %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: incompatible device advertisement (port %d) log

Fabric Attach: incompatible device advertisement (port %d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Fabric Attach: incompatible device advertisement (port %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: incompatible device advertisement (port %d/%d) log

Fabric Attach: incompatible device advertisement (port %d/%d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: incompatible (non-EAP) zero touch options cleared during restore

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: incompatible (non-EAP) zero touch options cleared during restore log

Fabric Attach: incompatible (non-EAP) zero touch options cleared during restore

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: interface-specific I-SID/VLAN assignments not allowed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: interface-specific I-SID/VLAN assignments not allowed log

Fabric Attach: interface-specific I-SID/VLAN assignments not allowed

Attempt to create a port-specific I-SID/VLAN assignment on a FA Proxy was rejected.

Source	Severity
Fabric Attach	Minor

### Remedial action

Specify non-port specific I-SID/VLAN assignments during creation on FA Proxy.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: internal client (%d/%d/%d) creation failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: internal client (%d/%d/%d) creation failure log

Fabric Attach: internal client (%d/%d/%d) creation failure

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: internal client (%d/%d/%d) creation success

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: internal client (%d/%d/%d) creation success log

Fabric Attach: internal client (%d/%d/%d) creation success

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: internal client (%d/%d/%d) deletion failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: internal client (%d/%d/%d) deletion failure log

Fabric Attach: internal client (%d/%d/%d) deletion failure

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: internal client (%d/%d/%d) deletion success

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: internal client (%d/%d/%d) deletion success log

Fabric Attach: internal client (%d/%d/%d) deletion success

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: invalid client detection data (type %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: invalid client detection data (type %d) log

Fabric Attach: invalid client detection data (type %d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Fabric Attach: invalid client detection element type (type %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: invalid client detection element type (type %d) log

Fabric Attach: invalid client detection element type (type %d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: invalid MAC address range data (type %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: invalid MAC address range data (type %d) log

Fabric Attach: invalid MAC address range data (type %d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: invalid VLAN data (unknown or incompatible type)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: invalid VLAN data (unknown or incompatible type) log

Fabric Attach: invalid VLAN data (unknown or incompatible type)

An unknown/incompatible VLAN was specified in a I-SID/VLAN assignment.

Source	Severity
Fabric Attach	Minor

### Remedial action

Ensure appropriate VLAN data is specified in requests.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: invalid zero touch client custom ID (type %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: invalid zero touch client custom ID (type %d) log

Fabric Attach: invalid zero touch client custom ID (type %d)

### Source                      Severity

Fabric Attach

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: invalid zero touch client description (type %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: invalid zero touch client description (type %d) log

Fabric Attach: invalid zero touch client description (type %d)

### Source                      Severity

Fabric Attach

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: invalid zero touch client name (type %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: invalid zero touch client name (type %d) log

Fabric Attach: invalid zero touch client name (type %d)

### Source      Severity

Fabric Attach

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: invalid zero touch client options (type %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: invalid zero touch client options (type %d) log

Fabric Attach: invalid zero touch client options (type %d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: I-SID/VLAN assignment creation failure (unexpected)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: I-SID/VLAN assignment creation failure (unexpected) log

Fabric Attach: I-SID/VLAN assignment creation failure (unexpected)

A valid I-SID/VLAN assignment creation request was rejected.

Source	Severity
Fabric Attach	Major

### Remedial action

Reset the device and retry.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Fabric Attach: I-SID/VLAN assignment deletion failure (unexpected)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: I-SID/VLAN assignment deletion failure (unexpected) log

Fabric Attach: I-SID/VLAN assignment deletion failure (unexpected)

A valid I-SID/VLAN assignment deletion request was rejected.

Source	Severity
Fabric Attach	Major

### Remedial action

Reset the device and retry.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: LLDP sync issue - add (%d/%d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: LLDP sync issue - add (%d/%d/%d) log

Fabric Attach: LLDP sync issue - add (%d/%d/%d)

Source	Severity
--------	----------

Fabric Attach	
---------------	--

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: LLDP sync issue - delete (%d/%d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: LLDP sync issue - delete (%d/%d/%d) log

Fabric Attach: LLDP sync issue - delete (%d/%d/%d)

### Source                      Severity

Fabric Attach

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: LLDP sync issue - update (%d/%d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: LLDP sync issue - update (%d/%d/%d) log

Fabric Attach: LLDP sync issue - update (%d/%d/%d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: local asgn - created (%d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: local asgn - created (%d/%d) log

Fabric Attach: local asgn - created (%d/%d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: local asgn - deleted (%d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: local asgn - deleted (%d/%d) log

Fabric Attach: local asgn - deleted (%d/%d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: management VLAN updated (was %d, now %d) by zero touch auto-attach

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: management VLAN updated (was %d, now %d) by zero touch auto-attach log

Fabric Attach: management VLAN updated (was %d, now %d) by zero touch auto-attach

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: management VLAN updated (was <VID>, now <VID>) by Auto Attach

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: management VLAN updated (was <VID>, now <VID>) by Auto Attach log

Fabric Attach: management VLAN updated (was <VID>, now <VID>) by Auto Attach

Auto Attach functionality updated the management VLAN on a FA Proxy.

Source	Severity
Fabric Attach	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Fabric Attach: message authentication support not available

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: message authentication support not available log

Fabric Attach: message authentication support not available

Request to enable message authentication failed.

Source	Severity
Fabric Attach	Minor

### Remedial action

Use a secure (SSH) image for the FA device or allow FA exchanges to proceed without being authenticated.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: message processing (msgId %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: message processing (msgId %d) log

Fabric Attach: message processing (msgId %d)

**Source**            **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: multiple FA Servers detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: multiple FA Servers detected log

Fabric Attach: multiple FA Servers detected

Multiple devices advertising FA Server capabilities were found.

Source	Severity
Fabric Attach	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: non-deterministic client detection data (type %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: non-deterministic client detection data (type %d) log

Fabric Attach: non-deterministic client detection data (type %d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: non-MLT trunk uplink requires MLT ID/LACP key binding (missing)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: non-MLT trunk uplink requires MLT ID/LACP key binding (missing) log

Fabric Attach: non-MLT trunk uplink requires MLT ID/LACP key binding (missing)

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: NVRAM port data restore failure detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: NVRAM port data restore failure detected log

Fabric Attach: NVRAM port data restore failure detected

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: NVRAM port data save failure detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: NVRAM port data save failure detected log

Fabric Attach: NVRAM port data save failure detected

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: NVRAM restore failure detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: NVRAM restore failure detected log

Fabric Attach: NVRAM restore failure detected

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Fabric Attach: NVRAM save failure detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: NVRAM save failure detected log

Fabric Attach: NVRAM save failure detected

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: NVRAM save success (%d local %d remote)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: NVRAM save success (%d local %d remote) log

Fabric Attach: NVRAM save success (%d local %d remote)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: NVRAM save success (port-specific data)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: NVRAM save success (port-specific data) log

Fabric Attach: NVRAM save success (port-specific data)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: operation failure detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: operation failure detected log

Fabric Attach: operation failure detected

The requested operation was rejected in a non-specific manner.

Source	Severity
Fabric Attach	Minor

### Remedial action

Verify that the request data is correct and retry.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: operation not supported (server-only operation)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: operation not supported (server-only operation) log

Fabric Attach: operation not supported (server-only operation)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: operation not supported (switch-only operation)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: operation not supported (switch-only operation) log

Fabric Attach: operation not supported (switch-only operation)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: operation rejected - client-owned entry

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: operation rejected - client-owned entry log

Fabric Attach: operation rejected - client-owned entry

An attempt was made to delete a client-specified I-SID/VLAN binding.

Source	Severity
Fabric Attach	Minor

### Remedial action

Deletion of client-owned I-SID/VLAN bindings must be done through the client.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: operation rejected - CVLAN already exists

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: operation rejected - CVLAN already exists log

Fabric Attach: operation rejected - CVLAN already exists

Attempt was made to create an I-SID/VLAN assignment with duplicate VLAN data.

Source	Severity
Fabric Attach	Minor

### Remedial action

Specify unique data when creating I-SID/VLAN assignments.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Fabric Attach: operation rejected - entry does not exist

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: operation rejected - entry does not exist log

Fabric Attach: operation rejected - entry does not exist

An attempt was made to delete an unknown I-SID/VLAN assignment.

Source	Severity
Fabric Attach	Minor

### Remedial action

Specify valid data when deleting I-SID/VLAN assignments.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: operation rejected - not supported by element type

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: operation rejected - not supported by element type log

Fabric Attach: operation rejected - not supported by element type

An unsupported operation (based on the FA element type) was attempted.

Source	Severity
Fabric Attach	Minor

### Remedial action

Only initiate operations that are supported by the FA element.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: operation rejected - service not enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: operation rejected - service not enabled log

Fabric Attach: operation rejected - service not enabled

The requested operation was rejected because the FA service was disabled.

Source	Severity
Fabric Attach	Minor

### Remedial action

Enable the FA service and retry.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: operation rejected - table entry limits reached

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: operation rejected - table entry limits reached log

Fabric Attach: operation rejected - table entry limits reached

Table limits have been reached.

Source	Severity
Fabric Attach	Minor

### Remedial action

Delete non-necessary data and retry.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: option incompatible with other options (type %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: option incompatible with other options (type %d) log

Fabric Attach: option incompatible with other options (type %d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: port authentication update - data flushed (MLT %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: port authentication update - data flushed (MLT %d) log

Fabric Attach: port authentication update - data flushed (MLT %d)

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: port authentication update - data flushed (port %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: port authentication update - data flushed (port %d) log

Fabric Attach: port authentication update - data flushed (port %d)

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: port authentication update - data flushed (port %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: port authentication update - data flushed (port %d/%d) log

Fabric Attach: port authentication update - data flushed (port %d/%d)

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Fabric Attach: potential incomplete binding cleanup

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: potential incomplete binding cleanup log

Fabric Attach: potential incomplete binding cleanup

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: primary FA Server lost

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: primary FA Server lost log

Fabric Attach: primary FA Server lost

The connection to the primary server has timed-out. Data has been reset and a new primary server will be selected if one is available.

Source	Severity
Fabric Attach	Information

### Remedial action

None



# Fabric Attach: primary FA server selected (port %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: primary FA server selected (port %d) log

Fabric Attach: primary FA server selected (port %d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: primary FA server selected (port %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: primary FA server selected (port %d/%d) log

Fabric Attach: primary FA server selected (port %d/%d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: primary FA server selected (trunk %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: primary FA server selected (trunk %d) log

Fabric Attach: primary FA server selected (trunk %d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: proxy not supported by element type

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: proxy not supported by element type log

Fabric Attach: proxy not supported by element type

External client proxy setting can only be manipulated a FA Proxy.

Source	Severity
Fabric Attach	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: proxy sync issue - update (%d/%d - %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: proxy sync issue - update (%d/%d - %d) log

Fabric Attach: proxy sync issue - update (%d/%d - %d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: rcvd invalid I-SID/VLAN asgn state (%d - %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: rcvd invalid I-SID/VLAN asgn state (%d - %d/%d) log

Fabric Attach: rcvd invalid I-SID/VLAN asgn state (%d - %d/%d)

### Source                      Severity

Fabric Attach

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Fabric Attach: remote asgn - switch removal (%d/%d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: remote asgn - switch removal (%d/%d/%d) log

Fabric Attach: remote asgn - switch removal (%d/%d/%d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: remote smlt peer asgn - acceptance failure (%d/%d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: remote smlt peer asgn - acceptance failure (%d/%d/%d) log

Fabric Attach: remote smlt peer asgn - acceptance failure (%d/%d/%d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: remote smlt peer asgn - accepted (%d/%d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: remote smlt peer asgn - accepted (%d/%d/%d) log

Fabric Attach: remote smlt peer asgn - accepted (%d/%d/%d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: remote smlt peer asgn - deleted (%d/%d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: remote smlt peer asgn - deleted (%d/%d/%d) log

Fabric Attach: remote smlt peer asgn - deleted (%d/%d/%d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: remote smlt peer asgn - updated (%d/%d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: remote smlt peer asgn - updated (%d/%d/%d) log

Fabric Attach: remote smlt peer asgn - updated (%d/%d/%d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: remote smlt peer removal (%d/%d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: remote smlt peer removal (%d/%d/%d) log

Fabric Attach: remote smlt peer removal (%d/%d/%d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: remote smlt peer removal issue detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: remote smlt peer removal issue detected log

Fabric Attach: remote smlt peer removal issue detected

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: server asgn (%d/%d) rejection

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: server asgn (%d/%d) rejection log

Fabric Attach: server asgn (%d/%d) rejection

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Fabric Attach: server asgn (%d/%d) rejection - application interactions

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: server asgn (%d/%d) rejection - application interactions log

Fabric Attach: server asgn (%d/%d) rejection - application interactions

Source	Severity
Fabric Attach	

Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: server asgn (%d/%d) rejection - invalid binding with SPBM provisioning

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: server asgn (%d/%d) rejection - invalid binding with SPBM provisioning log

Fabric Attach: server asgn (%d/%d) rejection - invalid binding with SPBM provisioning

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: server asgn (%d/%d) rejection - invalid VLAN

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: server asgn (%d/%d) rejection - invalid VLAN log

Fabric Attach: server asgn (%d/%d) rejection - invalid VLAN

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: server asgn (%d/%d) rejection - no FA resources

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: server asgn (%d/%d) rejection - no FA resources log

Fabric Attach: server asgn (%d/%d) rejection - no FA resources

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: server asgn (%d/%d) rejection - no VLAN resources

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: server asgn (%d/%d) rejection - no VLAN resources log

Fabric Attach: server asgn (%d/%d) rejection - no VLAN resources

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: server asgn (%d/%d) rejection - peer acceptance

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: server asgn (%d/%d) rejection - peer acceptance log

Fabric Attach: server asgn (%d/%d) rejection - peer acceptance

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: server asgn (<ISID>/<VID>) rejection

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: server asgn (<ISID>/<VID>) rejection log

Fabric Attach: server asgn (<ISID>/<VID>) rejection

The I-SID/VLAN binding request was rejected by the server in a non-specific manner.

Source	Severity
Fabric Attach	Minor

### Remedial action

Verify that the request data is correct and can be supported by the server. Retry.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: server asgn (<ISID>/<VID>) rejection - application interactions

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: server asgn (<ISID>/<VID>) rejection - application interactions log

Fabric Attach: server asgn (<ISID>/<VID>) rejection - application interactions

The I-SID/VLAN assignment request was rejected by the server because VLAN application and/or SPBM application issues were reported.

Source	Severity
Fabric Attach	Minor

### Remedial action

Verify that the request data is correct and can be supported by the server. Retry.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Fabric Attach: server asgn (<ISID>/<VID>) rejection - invalid VLAN

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: server asgn (<ISID>/<VID>) rejection - invalid VLAN log

Fabric Attach: server asgn (<ISID>/<VID>) rejection - invalid VLAN

The I-SID/VLAN assignment request was rejected by the server due to an issue with the specified VLAN (already defined but wrong type).

Source	Severity
Fabric Attach	Minor

### Remedial action

Verify that the request data is correct and can be supported by the server. Retry.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: server asgn (<ISID>/<VID>) rejection - no FA resources

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: server asgn (<ISID>/<VID>) rejection - no FA resources log

Fabric Attach: server asgn (<ISID>/<VID>) rejection - no FA resources

The I-SID/VLAN assignment request was rejected by the server due to a lack of available FA resources.

Source	Severity
Fabric Attach	Minor

### Remedial action

Verify that the request data is correct and can be supported by the server. Retry.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: server asgn (<ISID>/<VID>) rejection - no VLAN resources

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: server asgn (<ISID>/<VID>) rejection - no VLAN resources log

Fabric Attach: server asgn (<ISID>/<VID>) rejection - no VLAN resources

The I-SID/VLAN assignment request was rejected by the server because a new VLAN could not be created.

Source	Severity
Fabric Attach	Minor

### Remedial action

Verify that the request data is correct and can be supported by the server. Retry.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: server connection type change

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: server connection type change log

Fabric Attach: server connection type change

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: server connection type change (different ports)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: server connection type change (different ports) log

Fabric Attach: server connection type change (different ports)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: server connection type change (different trunks)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: server connection type change (different trunks) log

Fabric Attach: server connection type change (different trunks)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: server connection type change (non-trunk to trunk)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: server connection type change (non-trunk to trunk) log

Fabric Attach: server connection type change (non-trunk to trunk)

Source	Severity
Fabric Attach	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: server connection type change (trunk to non-trunk)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: server connection type change (trunk to non-trunk) log

Fabric Attach: server connection type change (trunk to non-trunk)

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Fabric Attach: service disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: service disabled log

Fabric Attach: service disabled

The Fabric Attach service was disabled.

Source	Severity
Fabric Attach	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: service enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: service enabled log

Fabric Attach: service enabled

The Fabric Attach service was enabled.

Source	Severity
Fabric Attach	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: specified element type not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: specified element type not supported log

Fabric Attach: specified element type not supported

The specified Fabric Attach element type is not supported by the platform.

Source	Severity
Fabric Attach	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: specified uplink currently a trunk member

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: specified uplink currently a trunk member log

Fabric Attach: specified uplink currently a trunk member

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: specified uplink currently invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: specified uplink currently invalid log

Fabric Attach: specified uplink currently invalid

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: standalone/non-standalone proxy transition (service reset)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: standalone/non-standalone proxy transition (service reset) log

Fabric Attach: standalone/non-standalone proxy transition (service reset)

Source	Severity
Fabric Attach	

Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: standalone proxy unavailable when SPBM is enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: standalone proxy unavailable when SPBM is enabled log

Fabric Attach: standalone proxy unavailable when SPBM is enabled

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: static uplink addition failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: static uplink addition failure log

Fabric Attach: static uplink addition failure

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Fabric Attach: static uplink deletion failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: static uplink deletion failure log

Fabric Attach: static uplink deletion failure

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: switch removal issue detected (switch %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: switch removal issue detected (switch %d/%d) log

Fabric Attach: switch removal issue detected (switch %d/%d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: temporary I-SID/VLAN binding deletion failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: temporary I-SID/VLAN binding deletion failure log

Fabric Attach: temporary I-SID/VLAN binding deletion failure

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: timer-related services unavailable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: timer-related services unavailable log

Fabric Attach: timer-related services unavailable

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: trunk link automatically enabled (MLT %d port %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: trunk link automatically enabled (MLT %d port %d/%d) log

Fabric Attach: trunk link automatically enabled (MLT %d port %d/%d)

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: trusted client bindings (%d) exceed limit (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: trusted client bindings (%d) exceed limit (%d) log

Fabric Attach: trusted client bindings (%d) exceed limit (%d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: Trusted interface update - clear (ifc %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: Trusted interface update - clear (ifc %d) log

Fabric Attach: Trusted interface update - clear (ifc %d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: Trusted interface update failure - clear (ifc %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: Trusted interface update failure - clear (ifc %d) log

Fabric Attach: Trusted interface update failure - clear (ifc %d)

### Source                      Severity

Fabric Attach

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Fabric Attach: Trusted interface update failure - set (ifc %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: Trusted interface update failure - set (ifc %d) log

Fabric Attach: Trusted interface update failure - set (ifc %d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: Trusted interface update - set (ifc %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: Trusted interface update - set (ifc %d) log

Fabric Attach: Trusted interface update - set (ifc %d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: unknown I-SID/VLAN asgn (update %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: unknown I-SID/VLAN asgn (update %d/%d) log

Fabric Attach: unknown I-SID/VLAN asgn (update %d/%d)

### Source      Severity

Fabric Attach

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: unknown message rcvd (msgId %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: unknown message rcvd (msgId %d) log

Fabric Attach: unknown message rcvd (msgId %d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: uplink operation only supported by FA Proxy

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: uplink operation only supported by FA Proxy log

Fabric Attach: uplink operation only supported by FA Proxy

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: zero touch auto-attach capabilities disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: zero touch auto-attach capabilities disabled log

Fabric Attach: zero touch auto-attach capabilities disabled

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: zero touch auto-attach capabilities enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: zero touch auto-attach capabilities enabled log

Fabric Attach: zero touch auto-attach capabilities enabled

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: zero touch auto-attach failure (DHCP initiation)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: zero touch auto-attach failure (DHCP initiation) log

Fabric Attach: zero touch auto-attach failure (DHCP initiation)

### Source                      Severity

Fabric Attach

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Fabric Attach: zero touch auto-attach failure (mgmt VLAN update)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: zero touch auto-attach failure (mgmt VLAN update) log

Fabric Attach: zero touch auto-attach failure (mgmt VLAN update)

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: zero touch auto-attach failure (port tagging)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: zero touch auto-attach failure (port tagging) log

Fabric Attach: zero touch auto-attach failure (port tagging)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: zero touch auto-attach failure (PVID update)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: zero touch auto-attach failure (PVID update) log

Fabric Attach: zero touch auto-attach failure (PVID update)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: zero touch auto-attach failure (VLAN creation)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: zero touch auto-attach failure (VLAN creation) log

Fabric Attach: zero touch auto-attach failure (VLAN creation)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: zero touch auto-attach failure (VLAN membership)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: zero touch auto-attach failure (VLAN membership) log

Fabric Attach: zero touch auto-attach failure (VLAN membership)

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: zero touch auto-attach operations not completed (mgmt VLAN %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: zero touch auto-attach operations not completed (mgmt VLAN %d) log

Fabric Attach: zero touch auto-attach operations not completed (mgmt VLAN %d)

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: zero touch client already exists (type %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: zero touch client already exists (type %d) log

Fabric Attach: zero touch client already exists (type %d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: zero touch client attach creation (Type %d) failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: zero touch client attach creation (Type %d) failure log

Fabric Attach: zero touch client attach creation (Type %d) failure

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Fabric Attach: zero touch client attach creation (Type %d) success

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: zero touch client attach creation (Type %d) success log

Fabric Attach: zero touch client attach creation (Type %d) success

Source	Severity
Fabric Attach	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: zero touch client attach deletion (Type %d) failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: zero touch client attach deletion (Type %d) failure log

Fabric Attach: zero touch client attach deletion (Type %d) failure

Source	Severity
Fabric Attach	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: zero touch client attach deletion (Type %d) success

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: zero touch client attach deletion (Type %d) success log

Fabric Attach: zero touch client attach deletion (Type %d) success

Source	Severity
Fabric Attach	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: zero touch client attach failure - operation not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: zero touch client attach failure - operation not supported log

Fabric Attach: zero touch client attach failure - operation not supported

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: zero touch client attach failure - Type %d Port %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: zero touch client attach failure - Type %d Port %d log

Fabric Attach: zero touch client attach failure - Type %d Port %d

Source	Severity
Fabric Attach	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: zero touch client attach failure - Type %d Port %d/%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: zero touch client attach failure - Type %d Port %d/%d log

Fabric Attach: zero touch client attach failure - Type %d Port %d/%d

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: zero touch client attach success - Type %d Port %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: zero touch client attach success - Type %d Port %d log

Fabric Attach: zero touch client attach success - Type %d Port %d

Source	Severity
Fabric Attach	

Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: zero touch client attach success - Type %d Port %d/%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: zero touch client attach success - Type %d Port %d/%d log

Fabric Attach: zero touch client attach success - Type %d Port %d/%d

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Fabric Attach: zero touch client unknown (type %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: zero touch client unknown (type %d) log

Fabric Attach: zero touch client unknown (type %d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: zero touch custom client deletion rejected (type %d referenced)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: zero touch custom client deletion rejected (type %d referenced) log

Fabric Attach: zero touch custom client deletion rejected (type %d referenced)

Source	Severity
Fabric Attach	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: zero touch failure (trusted connection)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: zero touch failure (trusted connection) log

Fabric Attach: zero touch failure (trusted connection)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: zero touch mgmt VLAN distribution disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: zero touch mgmt VLAN distribution disabled log

Fabric Attach: zero touch mgmt VLAN distribution disabled

Source	Severity
FAA	Information

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: zero touch mgmt VLAN distribution enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: zero touch mgmt VLAN distribution enabled log

Fabric Attach: zero touch mgmt VLAN distribution enabled

Source	Severity
FAA	Information

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: zero touch option failure (PVID update ifc %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: zero touch option failure (PVID update ifc %d) log

Fabric Attach: zero touch option failure (PVID update ifc %d)

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: zero touch option processing failure detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: zero touch option processing failure detected log

Fabric Attach: zero touch option processing failure detected

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fabric Attach: zero touch setting read-only for FA element type

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach: zero touch setting read-only for FA element type log

Fabric Attach: zero touch setting read-only for FA element type

**Source**                      **Severity**

Fabric Attach

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Failed ARP add ip addr 0xFFFFFFFF to HW hw error code

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Failed ARP add ip addr 0xFFFFFFFF to HW hw error code log

Failed ARP add ip addr 0xFFFFFFFF to HW hw error code

The configuration of L3 ARP(1) into hardware failed.

Source	Severity
L3Mgr	Information

### Remedial action

Try deleting the ARP from the software and check if the hardware configuration is successful after re-learning the ARP.



# Failed ARP add %#x/%#x to HW (%d).

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Failed ARP add %#x/%#x to HW (%d). log

Failed ARP add %#x/%#x to HW (%d).

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Failed login from IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Failed login from IP address log

Failed login from IP address

You have entered an incorrect username or password.

Source	Severity
Telnet Server	Information

### Remedial action

Enter a valid username and password.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Failed login from IP address:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Failed login from IP address: log

Failed login from IP address:

**Source**   **Severity**

Telnet

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Failed login from serial connection

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Failed login from serial connection log

Failed login from serial connection

You have entered an incorrect username or password on the serial interface.

Source	Severity
Console	Information

### Remedial action

Enter a valid username and password.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Failed login (local auth) from IP address:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Failed login (local auth) from IP address: log

Failed login (local auth) from IP address:

Failed authentication with local credentials over telnet session.

Source	Severity
Telnet server	Information

### Remedial action

Enter correct local username and password.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Failed login (local auth) from IP address:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Failed login (local auth) from IP address: log

Failed login (local auth) from IP address:

**Source**   **Severity**

Telnet

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Failed login (local auth) from serial connection

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Failed login (local auth) from serial connection log

Failed login (local auth) from serial connection

Failed authentication with local credentials on serial port.

Source	Severity
Console	Information

### Remedial action

Enter correct local username and password.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Failed login(radius auth) from IP add

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Failed login(radius auth) from IP add log

Failed login(radius auth) from IP add

You have failed to login as the Radius Server authentication is required for the telnet connections.

Source	Severity
Telnet Server	Information

### Remedial action

Enter a valid username and password.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Failed login(RADIUS auth) from IP add:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Failed login(RADIUS auth) from IP add: log

Failed login(RADIUS auth) from IP add:

**Source**   **Severity**

Telnet

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Failed login(radius auth) from serial conn

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Failed login(radius auth) from serial conn log

Failed login(radius auth) from serial conn

You failed to login as the Radius Server authentication is required for serial connections.

Source	Severity
Telnet Server	Console

### Remedial action

Enter a valid username and password.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Failed login(RADIUS auth) from serial connection

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Failed login(RADIUS auth) from serial connection log

Failed login(RADIUS auth) from serial connection

### Source    Severity

Telnet

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Failed login(TACACS+ auth) from IP add:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Failed login(TACACS+ auth) from IP add: log

Failed login(TACACS+ auth) from IP add:

### Source    Severity

Telnet

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Failed login(TACACS+ auth) from serial connection

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Failed login(TACACS+ auth) from serial connection log

Failed login(TACACS+ auth) from serial connection

### Source    Severity

Telnet

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Failed MVLAN(%d) L3 %d.%d.%d.%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Failed MVLAN(%d) L3 %d.%d.%d.%d log

Failed MVLAN(%d) L3 %d.%d.%d.%d

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Failed MVLAN( vid ) L3 ip addr ip mask

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Failed MVLAN( vid ) L3 ip addr ip mask log

Failed MVLAN( vid ) L3 ip addr ip mask

The system failed to configure or restore the primary or secondary management VLAN from the NVRAM. It indicates parameter (IP address or Mask) with an incorrect or conflicting value if appeared during provisioning the message on screen.

Source	Severity
--------	----------

L3Mgr	Information
-------	-------------

### Remedial action

Re-configure with correct values if the message appears during provisioning the message on the screen. Re-configure the management VLAN IP/Mask if the message appears during ERS device startup.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Failed route add <ip addr/ip mask> to HW <hw error code>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Failed route add <ip addr/ip mask> to HW <hw error code> log

Failed route add <ip addr/ip mask> to HW <hw error code>

The configuration of L3 interface(0) into hardware failed.

Source	Severity
L3Mgr	Warning

### Remedial action

No action required.



Failed route add %#x/%#x nh %#x,  
vlan %d, port %#x to HW (%d).

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Failed route add %#x/%#x nh %#x, vlan %d, port %#x to HW (%d). log

Failed route add %#x/%#x nh %#x, vlan %d, port %#x to HW (%d).

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



failed to add address to preinsertion  
table, table is probably full (code=%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## failed to add address to preinsertion table, table is probably full (code=%d) log

failed to add address to preinsertion table, table is probably full (code=%d)

**Source**   **Severity**  
CDT

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Failed to Create a Watchdog

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Failed to Create a Watchdog log

Failed to Create a Watchdog

The system failed to create a watchdog.

Source	Severity
Console	Serious

### Remedial action

Report the error.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Failed to create IP intf %d:%#x in HW (%d).

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Failed to create IP intf %d:%#x in HW (%d). log

Failed to create IP intf %d:%#x in HW (%d).

### Source    Severity

L3Mgr

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Failed to create IP intf vid ip addr in HW hw error code

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Failed to create IP intf vid ip addr in HW hw error code log

Failed to create IP intf vid ip addr in HW hw error code

The interface and the L3 interface(0) configuration failed.

Source	Severity
L3Mgr	Information

### Remedial action

Check by toggling routing on the VLAN to which the interface belongs, if it still fails then use global routing toggling.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Failed to create paltform\_info task.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Failed to create paltform\_info task. log

Failed to create paltform\_info task.

**Source**      **Severity**

PLATFORM

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Failed to create platform\_info message queue.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Failed to create platform\_info message queue. log

Failed to create platform\_info message queue.

**Source**      **Severity**

PLATFORM

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Failed to Read Image from Memory

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Failed to Read Image from Memory log

Failed to Read Image from Memory

The system failed to read image from memory.

Source	Severity
Console	Serious

### Remedial action

Retry the process again.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Failed to restore dynamic role combination post QoS reset

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Failed to restore dynamic role combination post QoS reset log

Failed to restore dynamic role combination post QoS reset

QoS was unable to restore all dynamic interface roles after a user data reset request.

Source	Severity
QoS	Warning

### Remedial action

Check the log for other messages since this could affect FA functionality.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Failed to set platform\_info. FLASH sem not acquired.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Failed to set platform\_info. FLASH sem not acquired. log

Failed to set platform\_info. FLASH sem not acquired.

**Source**      **Severity**

PLATFORM

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Fatal in %s at line %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fatal in %s at line %d log

Fatal in %s at line %d

**Source**   **Severity**

VLAN

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FCoE controller ifIndex not set - FCoE redirection enable prohibited

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FCoE controller ifIndex not set - FCoE redirection enable prohibited log

FCoE controller ifIndex not set - FCoE redirection enable prohibited

Required FCoE controller data not defined.

Source	Severity
FCoE Redirect	Information

### Remedial action

Specify FCoE controller data.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FCoE controller MAC not set - FCoE redirection enable prohibited

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FCoE controller MAC not set - FCoE redirection enable prohibited log

FCoE controller MAC not set - FCoE redirection enable prohibited

**Source**   **Severity**  
QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FCoE controller VLAN not set - FCoE redirection enable prohibited

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FCoE controller VLAN not set - FCoE redirection enable prohibited log

FCoE controller VLAN not set - FCoE redirection enable prohibited

Required FCoE controller data not defined.

Source	Severity
FCoE Redirect	Information

### Remedial action

Specify FCoE controller data.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FCoE FNC access disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FCoE FNC access disabled log

FCoE FNC access disabled

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# FCoE FNC access enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FCoE FNC access enabled log

FCoE FNC access enabled

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FCoE ingress interface list content issue - ifIndex %d invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FCoE ingress interface list content issue - ifIndex %d invalid log

FCoE ingress interface list content issue - ifIndex %d invalid

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FCoE redirection controller filter deletion failure detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FCoE redirection controller filter deletion failure detected log

FCoE redirection controller filter deletion failure detected

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FCoE redirection controller filter installation failure detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FCoE redirection controller filter installation failure detected log

FCoE redirection controller filter installation failure detected

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FCoE redirection default frame filter deletion failure detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FCoE redirection default frame filter deletion failure detected log

FCoE redirection default frame filter deletion failure detected

Unable to delete installed FCoE Redirect policy data.

Source	Severity
FCoE Redirect	Serious

### Remedial action

Toggle feature enable and retry.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FCoE redirection default frame filter installation failure detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FCoE redirection default frame filter installation failure detected log

FCoE redirection default frame filter installation failure detected

Unable to install required FCoE Redirect policy data.

Source	Severity
FCoE Redirect	Serious

### Remedial action

Toggle feature enable and retry.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FCoE redirection disable issue - incomplete FCoE entry deletion

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FCoE redirection disable issue - incomplete FCoE entry deletion log

FCoE redirection disable issue - incomplete FCoE entry deletion

**Source**   **Severity**  
QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FCoE redirection - egress interface issue detected (ifIndex %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FCoE redirection - egress interface issue detected (ifIndex %d) log

FCoE redirection - egress interface issue detected (ifIndex %d)

Issue detected with interface used with FCoE Redirect.

Source	Severity
FCoE Redirect	Serious

### Remedial action

Check status of identified interface.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# FCoE redirection - egress trunk issue detected (trunk ID %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FCoE redirection - egress trunk issue detected (trunk ID %d) log

FCoE redirection - egress trunk issue detected (trunk ID %d)

Issue detected with trunk used with FCoE Redirect. The trunk ID is displayed in the log message.

Source	Severity
FCoE Redirect	Serious

### Remedial action

Check status of identified trunk.



# FCoE redirection element manipulation blocked (operation mode is disabled)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FCoE redirection element manipulation blocked (operation mode is disabled) log

FCoE redirection element manipulation blocked (operation mode is disabled)

**Source**   **Severity**  
QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FCoE redirection element name contains unacceptable characters

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FCoE redirection element name contains unacceptable characters log

FCoE redirection element name contains unacceptable characters

**Source**   **Severity**  
QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FCoE redirection element name length outside of acceptable limits

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FCoE redirection element name length outside of acceptable limits log

FCoE redirection element name length outside of acceptable limits

**Source**   **Severity**  
QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FCoE redirection element name not acceptable - reserved

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FCoE redirection element name not acceptable - reserved log

FCoE redirection element name not acceptable - reserved

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FCoE redirection enable issue - incomplete FCoE entry installation

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FCoE redirection enable issue - incomplete FCoE entry installation log

FCoE redirection enable issue - incomplete FCoE entry installation

**Source**   **Severity**  
QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FCoE redirection entry modification not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FCoE redirection entry modification not supported log

FCoE redirection entry modification not supported

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FCoE redirection traffic filter deletion failure detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FCoE redirection traffic filter deletion failure detected log

FCoE redirection traffic filter deletion failure detected

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# FCoE redirection traffic filter installation failure detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FCoE redirection traffic filter installation failure detected log

FCoE redirection traffic filter installation failure detected

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FCoE traffic redirection disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FCoE traffic redirection disabled log

FCoE traffic redirection disabled

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FCoE traffic redirection enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FCoE traffic redirection enabled log

FCoE traffic redirection enabled

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



File=%s line=%d val=0x%X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## File=%s line=%d val=0x%X log

File=%s line=%d val=0x%X

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Filter control block resources exhausted

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Filter control block resources exhausted log

Filter control block resources exhausted

Not enough resources to create the specified filter control block.

Source	Severity
QoS	Serious

### Remedial action

Check for and remove unneeded resources.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Filter creation issue detected - in-profile action component

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Filter creation issue detected - in-profile action component log

Filter creation issue detected - in-profile action component

Unable to create filter because of a conflicting in-profile action component.

Source	Severity
QoS	Serious

### Remedial action

Identify and remove the conflicting component(s).



# Filter creation issue detected - match action component

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Filter creation issue detected - match action component log

Filter creation issue detected - match action component

Unable to create filter because of a conflicting match action component.

Source	Severity
QoS	Serious

### Remedial action

Identify and remove the conflicting component(s).



# Filter creation issue detected - metering component

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Filter creation issue detected - metering component log

Filter creation issue detected - metering component

Unable to create filter because of a conflicting meter component.

Source	Severity
QoS	Serious

### Remedial action

Identify and remove the conflicting component(s).

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Filter creation issue detected - non-match action component

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Filter creation issue detected - non-match action component log

Filter creation issue detected - non-match action component

Unable to create filter because of a conflicting non-match action component.

Source	Severity
QoS	Serious

### Remedial action

Identify and remove the conflicting component(s).

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Filter creation issue detected - out-of-profile action component

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Filter creation issue detected - out-of-profile action component log

Filter creation issue detected - out-of-profile action component

Unable to create filter because of a conflicting out-of-profile action component.

Source	Severity
QoS	Serious

### Remedial action

Identify and remove the conflicting component(s).

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Filter limiting mode not supported on 5510-XX unit cannot join stack

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Filter limiting mode not supported on 5510-XX unit cannot join stack log

Filter limiting mode not supported on 5510-XX unit cannot join stack

Filter limiting mode is different than the base unit's mode. Some modes are not supported in the ERS 55XX..

Source	Severity
Stack Manager	Information

### Remedial action

Modify the Filter Limiting mode on the base unit or remove the ERS 55XX.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Filter limiting mode not supported on 5510-XX, unit cannot join stack

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Filter limiting mode not supported on 5510-XX, unit cannot join stack log

Filter limiting mode not supported on 5510-XX, unit cannot join stack

Source	Severity
SMGR	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Filter manager internal error encountered

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Filter manager internal error encountered log

Filter manager internal error encountered

Internal filter manager error.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Filter manager memory resources exhausted

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Filter manager memory resources exhausted log

Filter manager memory resources exhausted

Not enough resources or inconsistent memory.

Source	Severity
QoS	Serious

### Remedial action

Check for and remove the unneeded resources.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Filter manager metering or policy rule space exhausted

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Filter manager metering or policy rule space exhausted log

Filter manager metering or policy rule space exhausted

There is no more space available for rule allocation.

Source	Severity
QoS	Serious

### Remedial action

Check for and remove unneeded resources.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Filter manager metering resources exhausted

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Filter manager metering resources exhausted log

Filter manager metering resources exhausted

The filter manager meter support reached it's limit.

Source	Severity
QoS	Serious

### Remedial action

Check for and remove unneeded meters.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Filter manager policy rule space potentially exhausted

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Filter manager policy rule space potentially exhausted log

Filter manager policy rule space potentially exhausted

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Filter manager request parameter invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Filter manager request parameter invalid log

Filter manager request parameter invalid

Invalid parameter detected during processing on the filter manager level.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Filter manager statistics tracking resources exhausted

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Filter manager statistics tracking resources exhausted log

Filter manager statistics tracking resources exhausted

The statistics tracking/counter table is full.

Source	Severity
QoS	Serious

### Remedial action

Check for and remove unneeded statistics related entries.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Filter set data inconsistent (conflicting IP/non-IP data)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Filter set data inconsistent (conflicting IP/non-IP data) log

Filter set data inconsistent (conflicting IP/non-IP data)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Filter set installation timeout detected (ID %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Filter set installation timeout detected (ID %d) log

Filter set installation timeout detected (ID %d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Filter set (NSNA) was not restored/installed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Filter set (NSNA) was not restored/installed log

Filter set (NSNA) was not restored/installed

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Filter set requirements incompatible with target interface

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Filter set requirements incompatible with target interface log

Filter set requirements incompatible with target interface

The requirements are not compatible with the target interface.

Source	Severity
QoS	Serious

### Remedial action

Enter a different interface or a compatible set of requirements.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Filter set (Traffic Profile) was not restored/installed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Filter set (Traffic Profile) was not restored/installed log

Filter set (Traffic Profile) was not restored/installed

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Filter set (User Based Policy) was not restored/installed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Filter set (User Based Policy) was not restored/installed log

Filter set (User Based Policy) was not restored/installed

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# First TrTCM Meter Index must be in range 1-5000

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## First TrTCM Meter Index must be in range 1-5000 log

First TrTCM Meter Index must be in range 1-5000

The maximum valid index for the first TrTCM meter is 5000

Source	Severity
QoS	Serious

### Remedial action

Specify a valid index.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Flash Erase Failed Sector %d Address 0x%x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Flash Erase Failed Sector %d Address 0x%x log

Flash Erase Failed Sector %d Address 0x%x

Logs a failed flash sector erase.

Source	Severity
MCFG	Information

### Remedial action

Call Extreme Networks.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Flash Erase Warning Sector %d Address 0x%x Erase time %d ms

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Flash Erase Warning Sector %d Address 0x%x Erase time %d ms log

Flash Erase Warning Sector %d Address 0x%x Erase time %d ms

**Source**   **Severity**  
MCFG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Flash Erase Warning Sector %d Address 0x%x Erase time %d ms

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Flash Erase Warning Sector %d Address 0x%x Erase time %d ms log

Flash Erase Warning Sector %d Address 0x%x Erase time %d ms

Logs a slow and successful flash sector erase.

Source	Severity
MCFG	Information

### Remedial action

Message indicates that the flash sector is nearing its end of life. No immediate action is required, but that sector may soon become unprogrammable.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Flow ID filtering not supported for IPv4

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Flow ID filtering not supported for IPv4 log

Flow ID filtering not supported for IPv4

Flow ID is supported only for IPV6.

Source	Severity
QoS	Serious

### Remedial action

Enter a Ipv6 address or specify the address type (must be Ipv6).

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Flow ID out-of-range (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Flow ID out-of-range (%d) log

Flow ID out-of-range (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Flow ID out-of-range ( Flow ID )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Flow ID out-of-range ( Flow ID ) log

Flow ID out-of-range ( Flow ID )

Invalid flow ID specified.

Source	Severity
QoS	Serious

### Remedial action

Enter a flow ID between 0x00-0xfffff (1048575).

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# FMGR: CoSQ Init - CoS Mapping: unit(%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FMGR: CoSQ Init - CoS Mapping: unit(%d) log

FMGR: CoSQ Init - CoS Mapping: unit(%d)

**Source**   **Severity**

VLAN

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FMGR: CoSQ Init - CoS Queues: unit(%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FMGR: CoSQ Init - CoS Queues: unit(%d) log

FMGR: CoSQ Init - CoS Queues: unit(%d)

**Source**   **Severity**

VLAN

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FMGR: CoSQ Init - CoS Schedule: unit(%d) port(%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FMGR: CoSQ Init - CoS Schedule: unit(%d) port(%d) log

FMGR: CoSQ Init - CoS Schedule: unit(%d) port(%d)

**Source**   **Severity**

VLAN

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FMGR: CoSQ Init - end

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FMGR: CoSQ Init - end log

FMGR: CoSQ Init - end

**Source**   **Severity**

VLAN

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FMGR: CoSQ Init - HOL Cell Limit: unit(%d) port(%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FMGR: CoSQ Init - HOL Cell Limit: unit(%d) port(%d) log

FMGR: CoSQ Init - HOL Cell Limit: unit(%d) port(%d)

**Source**   **Severity**

VLAN

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FMGR: CoSQ Init - HOL Packet Limit: unit(%d) port(%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FMGR: CoSQ Init - HOL Packet Limit: unit(%d) port(%d) log

FMGR: CoSQ Init - HOL Packet Limit: unit(%d) port(%d)

**Source**   **Severity**

VLAN

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FMGR: CoSQ Init - IBP Cell Limit: unit(%d) port(%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FMGR: CoSQ Init - IBP Cell Limit: unit(%d) port(%d) log

FMGR: CoSQ Init - IBP Cell Limit: unit(%d) port(%d)

**Source**   **Severity**

VLAN

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FMGR: CoSQ Init - IBP Discard Limit: unit(%d) port(%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FMGR: CoSQ Init - IBP Discard Limit: unit(%d) port(%d) log

FMGR: CoSQ Init - IBP Discard Limit: unit(%d) port(%d)

**Source**   **Severity**

VLAN

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# FMGR: CoSQ Init - IBP Packet Limit: unit(%d) port(%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FMGR: CoSQ Init - IBP Packet Limit: unit(%d) port(%d) log

FMGR: CoSQ Init - IBP Packet Limit: unit(%d) port(%d)

**Source**   **Severity**

VLAN

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FMGR: CoSQ Init - Packet Maximum: unit(%d) port(%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FMGR: CoSQ Init - Packet Maximum: unit(%d) port(%d) log

FMGR: CoSQ Init - Packet Maximum: unit(%d) port(%d)

**Source**   **Severity**

VLAN

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FMGR: CoSQ Init - start

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FMGR: CoSQ Init - start log

FMGR: CoSQ Init - start

**Source**   **Severity**

VLAN

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



forwarding database message queue  
failure (code=%d,total  
failures=%d,errno=%x)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## forwarding database message queue failure (code=%d,total failures=%d,errno=%x) log

forwarding database message queue failure (code=%d,total failures=%d,errno=%x)

**Source    Severity**

CDT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Found MAC in NAP entry %d of %d stkCfg is "%s"

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Found MAC in NAP entry %d of %d stkCfg is "%s" log

Found MAC in NAP entry %d of %d stkCfg is "%s"

**Source    Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Front-panel UI requested stack reset

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Front-panel UI requested stack reset log

Front-panel UI requested stack reset

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Front-panel UI selected Base unit

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Front-panel UI selected Base unit log

Front-panel UI selected Base unit

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Front-panel UI selected non-Base unit

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Front-panel UI selected non-Base unit log

Front-panel UI selected non-Base unit

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Front-panel UI selected use rear-panel base non-base switch

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Front-panel UI selected use rear-panel base non-base switch log

Front-panel UI selected use rear-panel base non-base switch

The stack has been reset using the front-panel push-button.

Source	Severity
Stack Manager	Serious

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Front-panel UI selected use rear-panel base/non-base switch

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Front-panel UI selected use rear-panel base/non-base switch log

Front-panel UI selected use rear-panel base/non-base switch

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FSH – Error: Calling taskLock() returns Error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FSH – Error: Calling taskLock() returns Error log

FSH – Error: Calling taskLock() returns Error

This message appears when the task is unable to disable the context switching for the flash access.

Source	Severity
Flash Driver	Critical

### Remedial action

Retry or reboot the switch.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FSH - Error: Failed to erase flash address %x located in the %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FSH - Error: Failed to erase flash address %x located in the %s log

FSH - Error: Failed to erase flash address %x located in the %s

System failed to erase the flash at specified address, which is part of the specified region.

Source	Severity
--------	----------

Flash	Critical
-------	----------

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FSH – Error: Failed to erase flash sector

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FSH – Error: Failed to erase flash sector log

FSH – Error: Failed to erase flash sector

The system is unable to erase the flash sector to program the agent image.

Source	Severity
Flash Driver	Critical

### Remedial action

Retry or reboot the switch.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FSH – Error: Failed to get flash sem. tName %x. tName %x owns sem

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FSH – Error: Failed to get flash sem. tName %x. tName %x owns sem log

FSH – Error: Failed to get flash sem. tName %x. tName %x owns sem

Another task is using the same flash sector.

Source	Severity
FNC	Warning

### Remedial action

Reboot the unit if faulty operation is observed, call support.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FSH – Error: Failed to lock flash sector

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FSH – Error: Failed to lock flash sector log

FSH – Error: Failed to lock flash sector

The system is unable to lock the flash sector in order to prevent programming or erasing.

Source	Severity
Flash Driver	Critical

### Remedial action

Retry or reboot the switch.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FSH – Error: Failed to program flash

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FSH – Error: Failed to program flash log

FSH – Error: Failed to program flash

The system is unable to write the image on flash.

Source	Severity
Flash Driver	Critical

### Remedial action

Retry or reboot the switch.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# FSH – Error: Failed to release the flash resource

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FSH – Error: Failed to release the flash resource log

FSH – Error: Failed to release the flash resource

Should not happen.

Source	Severity
FNC	Warning

### Remedial action

Reboot the unit if faulty operation is observed, call support.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FSH – Error: Failed to unlock flash sector

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FSH – Error: Failed to unlock flash sector log

FSH – Error: Failed to unlock flash sector

The system failed to unlock the flash sector in order to allow programming or erasing.

Source	Severity
Flash Driver	Critical

### Remedial action

Retry or reboot the switch.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FSH – Error: Failed to write to flash address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FSH – Error: Failed to write to flash address log

FSH – Error: Failed to write to flash address

The system could not program the flash memory.

Source	Severity
Flash Driver	Critical

### Remedial action

Reboot the switch.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FSH - Error: Failed to write to %s, at address: %x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FSH - Error: Failed to write to %s, at address:%x log

FSH - Error: Failed to write to %s, at address:%x

System failed to write in the flash at specified address, which is a part of the specified region.

Source	Severity
--------	----------

Flash	Critical
-------	----------

### Remedial action

None



# FSH - File not closed :

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FSH - File not closed : log

FSH - File not closed :

This notification is generated while trying to load/save the configuration, indicating the files which are opened.

Source	Severity
FNC	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FSH - NULL version for next reboot (could not get semaphore)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FSH - NULL version for next reboot (could not get semaphore) log

FSH - NULL version for next reboot (could not get semaphore)

Version check error – new image version cannot be identified

Source	Severity
DOWNLOAD	Serious

### Remedial action

Retry downloading the same image or another available version.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FSH - Some files are not closed. MsgType #%%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FSH - Some files are not closed. MsgType #%%d log

FSH - Some files are not closed. MsgType #%%d

This notification is generated while trying to load/save the configuration, if some files remain open. The configuration cannot be saved if the files remain open.

Source	Severity
CFC	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# FSH - Time to Download the Image: %d seconds

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FSH - Time to Download the Image: %d seconds log

FSH - Time to Download the Image: %d seconds

This message indicates the time needed to download the image.

Source	Severity
Download Task	Critical

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# FSH - Time to Program the Image to flash: %d seconds

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## FSH - Time to Program the Image to flash: %d seconds log

FSH - Time to Program the Image to flash: %d seconds

This message indicates the time needed to program the image.

Source	Severity
Download Task	Critical

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Gateway IP changed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Gateway IP changed log

Gateway IP changed

This message indicates that the Gateway IP has changed.

Source	Severity
IPT	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Gateway=%#x cost=%d line=%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Gateway=%#x cost=%d line=%d log

Gateway=%#x cost=%d line=%d

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# General Error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## General Error log

General Error

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# GLB – Error: Failed to get glb data sem tName: %x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## GLB – Error: Failed to get glb data sem tName: %x log

GLB – Error: Failed to get glb data sem tName: %x

Possible hardware issues.

Source	Severity
FNC	Warning

### Remedial action

Reboot the unit if faulty operation is observed, call support.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Got dynamic UBP but it's not enabled  
for EAP clients, port %s, MAC  
%02x:%02x:%02x:%02x:%02x:%02x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Got dynamic UBP but it's not enabled for EAP clients, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x log

Got dynamic UBP but it's not enabled for EAP clients, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x

Dynamic UBP is not enabled for EAP clients.

Source	Severity
EAP	Warning

### Remedial action

The user needs to enable dynamic UBP for EAP clients.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Got dynamic UBP but it's not enabled  
for Non-EAP clients, port %s, MAC  
%02x:%02x:%02x:%02x:%02x:%02x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Got dynamic UBP but it's not enabled for Non-EAP clients, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x log

Got dynamic UBP but it's not enabled for Non-EAP clients, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x

Dynamic UBP is not enabled for non-EAP clients.

Source	Severity
EAP	Warning

### Remedial action

The user needs to enable dynamic UBP for non-EAP clients.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Got UserPolicy from Radius but QosOperMode disabled - unitPort %08x%04x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Got UserPolicy from Radius but QosOperMode disabled - unitPort %08x%04x log

Got UserPolicy from Radius but QosOperMode disabled - unitPort %08x%04x

Source	Severity
EAP	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Got UserPolicy from Radius but UBP disabled - unitPort 0x%x mac %08x%04x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Got UserPolicy from Radius but UBP disabled - unitPort 0x%x mac %08x%04x log

Got UserPolicy from Radius but UBP disabled - unitPort 0x%x mac %08x%04x

A UBP filter could not be installed because UBP is not enabled from EAP.

Source	Severity
QoS	Information

### Remedial action

Enable UBP.



# Got UserPolicy from Radius but UBP disabled - unitPort 0x%x mac %08x%04x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Got UserPolicy from Radius but UBP disabled - unitPort 0x%x mac %08x%04x log

Got UserPolicy from Radius but UBP disabled - unitPort 0x%x mac %08x%04x

**Source**   **Severity**  
EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



GWL3 failed at %d, IP %#x, vid %d  
unit %d (%d).

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## GWL3 failed at %d, IP %#x, vid %d unit %d (%d). log

GWL3 failed at %d, IP %#x, vid %d unit %d (%d).

### Source    Severity

L3Mgr

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



GWL3 failed at %d, MAC %08x%04x,  
vid %d unit %d (%d).

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## GWL3 failed at %d, MAC %08x%04x, vid %d unit %d (%d). log

GWL3 failed at %d, MAC %08x%04x, vid %d unit %d (%d).

### Source    Severity

L3Mgr

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



GWL3 failed at %d, NET %#x/%#x, vid %d unit %d (%d).

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## GWL3 failed at %d, NET %#x/%#x, vid %d unit %d (%d). log

GWL3 failed at %d, NET %#x/%#x, vid %d unit %d (%d).

### Source    Severity

L3Mgr

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Hello module detected %s stack direction %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Hello module detected %s stack direction %s log

Hello module detected %s stack direction %s

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Hello Module unable to communicate with neighbor(s) unit reset

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Hello Module unable to communicate with neighbor(s) unit reset log

Hello Module unable to communicate with neighbor(s) unit reset

This message appears under the following instances: When both stack port directions are physically up but unable to communicate with the neighboring unit(s); When one stack port direction is unable to communicate with its neighbor and the other stack port direction is not connected. The message is stored in a non-volatile memory; the presence of the message means the unit was reset.

Source	Severity
Hello Module	Critical

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Hello Module unable to communicate with neighbor(s) unit reset

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Hello Module unable to communicate with neighbor(s) unit reset log

Hello Module unable to communicate with neighbor(s) unit reset

The Hello module is unable to communicate with the neighbor(s), as the stack port direction(s) are logically down for more than 5 minutes.

Source	Severity
Stack Monitor	Information

### Remedial action

No action required. The switch/stack reboots itself. The logs are saved to NVRAM for future reference.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Hello Module unable to communicate with neighbor(s), unit reset

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Hello Module unable to communicate with neighbor(s), unit reset log

Hello Module unable to communicate with neighbor(s), unit reset

Source	Severity
HMOD	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Hello Module unable to read from configuration file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Hello Module unable to read from configuration file log

Hello Module unable to read from configuration file

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Hello Module unable to write to configuration file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Hello Module unable to write to configuration file log

Hello Module unable to write to configuration file

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# HMOD: error: %s line %d %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## HMOD: error: %s line %d %d log

HMOD: error: %s line %d %d

Source	Severity
--------	----------

HMOD	
------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# HMOD: error: %s line %d 0x%X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## HMOD: error: %s line %d 0x%X log

HMOD: error: %s line %d 0x%X

Source	Severity
--------	----------

HMOD	
------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# HMOD: event received msg\_src=0x%X num= 0x%X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## HMOD: event received msg\_src=0x%X num= 0x%X log

HMOD: event received msg\_src=0x%X num= 0x%X

### Source    Severity

HMOD

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# HMOD: IMC ack msg failed: status %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## HMOD: IMC ack msg failed: status %d log

HMOD: IMC ack msg failed: status %d

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



HMOD: info: %s line %d %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## HMOD: info: %s line %d %d log

HMOD: info: %s line %d %d

Source	Severity
--------	----------

HMOD	
------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





HMOD: initialized arg1= %d arg2 = %d  
arg3 = %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## HMOD: initialized arg1= %d arg2 = %d arg3 = %d log

HMOD: initialized arg1= %d arg2 = %d arg3 = %d

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# HMOD: queue creation failed %s line %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## HMOD: queue creation failed %s line %d log

HMOD: queue creation failed %s line %d

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# HMOD: queue rec error qid= 0x%X errno=0x%X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## HMOD: queue rec error qid= 0x%X errno=0x%X log

HMOD: queue rec error qid= 0x%X errno=0x%X

### Source    Severity

HMOD

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# HMOD: queue send error qid= 0x%X errno=0x%X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## HMOD: queue send error qid= 0x%X errno=0x%X log

HMOD: queue send error qid= 0x%X errno=0x%X

### Source    Severity

HMOD

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



HMOD: %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## HMOD: %s log

HMOD: %s

Source	Severity
--------	----------

HMOD	
------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# HMOD: semaphore creation failed %s line %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## HMOD: semaphore creation failed %s line %d log

HMOD: semaphore creation failed %s line %d

### Source    Severity

HMOD

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# HMOD: %s msg send failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## HMOD: %s msg send failed log

HMOD: %s msg send failed

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# HMOD: startup event failed type: 0x%08X option: %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## HMOD: startup event failed type: 0x%08X option: %d log

HMOD: startup event failed type: 0x%08X option: %d

### Source    Severity

HMOD

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# HMOD: STEG\_GO event missed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## HMOD: STEG\_GO event missed log

HMOD: STEG\_GO event missed

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



HMOD: 0x%X 0x%X 0x%X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## HMOD: 0x%X 0x%X 0x%X log

HMOD: 0x%X 0x%X 0x%X

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IDT: End

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IDT: End log

IDT: End

**Source**   **Severity**

IDT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IDT: Start

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IDT: Start log

IDT: Start

**Source**   **Severity**

IDT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ifc app modification issue (inconsistent default gateway data)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ifc app modification issue (inconsistent default gateway data) log

Ifc app modification issue (inconsistent default gateway data)

Modification is prohibited as an inconsistent default gateway data is detected.

Source	Severity
QoS	Serious

### Remedial action

Remove the entry and add a new one with the modified default gateway value.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ifc app modification issue (inconsistent DHCP server data)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ifc app modification issue (inconsistent DHCP server data) log

Ifc app modification issue (inconsistent DHCP server data)

Modification is not allowed as the system detected inconsistent DHCP server data.

Source	Severity
QoS	Serious

### Remedial action

Remove the entry and add a new one to the modified DHCP server.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ifc app modification issue (inconsistent ifType data)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ifc app modification issue (inconsistent ifType data) log

Ifc app modification issue (inconsistent ifType data)

Modification is not allowed as an inconsistent interface type data is detected.

Source	Severity
QoS	Serious

### Remedial action

Remove the entry and add a new one with the modified interface type data.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ifc app support not currently available on interface (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ifc app support not currently available on interface (%d) log

Ifc app support not currently available on interface (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Ifc app support not currently available on interface ( ifc# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ifc app support not currently available on interface ( ifc# ) log

Ifc app support not currently available on interface ( ifc# )

Interface application support is not available on the specified interface as it is incompatible or disabled.

Source	Severity
QoS	Serious

### Remedial action

Enter a different interface index.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ifc assignment issue - prec conflict (policy %d disabled)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ifc assignment issue - prec conflict (policy %d disabled) log

Ifc assignment issue - prec conflict (policy %d disabled)

**Source   Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ifc assignment issue - prec conflict (policy policy# disabled)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ifc assignment issue - prec conflict (policy policy# disabled) log

Ifc assignment issue - prec conflict (policy policy# disabled)

The interface assignment change needs to install a policy on a precedence that is already occupied by a different one, as a result the conflicting policy was disabled.

Source	Severity
QoS	Serious

### Remedial action

Analyze the conflict and choose an appropriate solution (the interface assignment or the policy).

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



IGAP : Acct started - Group = 0x%x,  
UsrIP = 0x%x, port = %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGAP : Acct started - Group = 0x%x, UsrIP = 0x%x, port = %d log

IGAP : Acct started - Group = 0x%x, UsrIP = 0x%x, port = %d

**Source    Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



IGAP : Acct stopped - Group = 0x%x,  
UsrIP = 0x%x, port = %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGAP : Acct stopped - Group = 0x%x, UsrIP = 0x%x, port = %d log

IGAP : Acct stopped - Group = 0x%x, UsrIP = 0x%x, port = %d

**Source    Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGAP : Enabled(1)/Disabled(0) - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGAP : Enabled(1)/Disabled(0) - %d log

IGAP : Enabled(1)/Disabled(0) - %d

**Source   Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGAP : Join Failed. Same m/c MAC-vlan=%d,OldGrp=0x%x,NewGrp=0x%x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGAP : Join Failed. Same m/c MAC-vlan=%d,OldGrp=0x%x,NewGrp=0x%x log

IGAP : Join Failed. Same m/c MAC-vlan=%d,OldGrp=0x%x,NewGrp=0x%x

**Source    Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGAP : Set Router Port - vlan = %d, port = %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGAP : Set Router Port - vlan = %d, port = %d log

IGAP : Set Router Port - vlan = %d, port = %d

**Source**   **Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IGAP : Stacking is not supported but detected stack!

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGAP : Stacking is not supported but detected stack! log

IGAP : Stacking is not supported but detected stack!

**Source   Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



IGAP : User Join - Group = 0x%x, UsrIP = 0x%x, port = %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGAP : User Join - Group = 0x%x, UsrIP = 0x%x, port = %d log

IGAP : User Join - Group = 0x%x, UsrIP = 0x%x, port = %d

**Source   Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



IGAP : User Leave - Group = 0x%x,  
UsrIP = 0x%x, port = %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGAP : User Leave - Group = 0x%x, UsrIP = 0x%x, port = %d log

IGAP : User Leave - Group = 0x%x, UsrIP = 0x%x, port = %d

**Source    Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



IGAP : User Timeout - Group = 0x%x,  
UsrIP = 0x%x, port = %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGAP : User Timeout - Group = 0x%x, UsrIP = 0x%x, port = %d log

IGAP : User Timeout - Group = 0x%x, UsrIP = 0x%x, port = %d

**Source    Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP Added reserved multicast address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP Added reserved multicast address log

IGMP Added reserved multicast address

This message appears when the unknown multicast allowed address is successfully registered on the switch.

Source	Severity
IGMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Added reserved multicast address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Added reserved multicast address log

IGMP: Added reserved multicast address

**Source**   **Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Config. database exchanged between all units of the stack

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Config. database exchanged between all units of the stack log

IGMP: Config. database exchanged between all units of the stack

**Source**   **Severity**  
IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Config. database received on unit %d from %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Config. database received on unit %d from %d log

IGMP: Config. database received on unit %d from %d

**Source**   **Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IGMP: Config. database sent by unit %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Config. database sent by unit %d log

IGMP: Config. database sent by unit %d

**Source   Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Config. failed. Loaded to factory default

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Config. failed. Loaded to factory default log

IGMP: Config. failed. Loaded to factory default

**Source**   **Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Config. loaded successfully

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Config. loaded successfully log

IGMP: Config. loaded successfully

**Source**   **Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Dynamic router port %d added

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Dynamic router port %d added log

IGMP: Dynamic router port %d added

**Source    Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Dynamic router port %d removed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Dynamic router port %d removed log

IGMP: Dynamic router port %d removed

**Source**   **Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Error sending database from unit %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Error sending database from unit %d log

IGMP: Error sending database from unit %d

**Source**   **Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP Error sending database from unit unit#

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP Error sending database from unit unit# log

IGMP Error sending database from unit unit#

The IGMP database cannot be sent to a unit in the stack.

Source	Severity
IGMP	Serious

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Error sending group database from unit %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Error sending group database from unit %d log

IGMP: Error sending group database from unit %d

**Source**   **Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IGMP Error sending group database from unit unit#

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP Error sending group database from unit unit# log

IGMP Error sending group database from unit unit#

The IGMP Group database cannot be transmitted from one unit to the other in the stack.

Source	Severity
--------	----------

IGMP	Serious
------	---------

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



IGMP: Exceeded reserved multicast  
address range: #Addr %d \* #VLANs  
%d > %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Exceeded reserved multicast address range: #Addr %d \* #VLANs %d > %d log

IGMP: Exceeded reserved multicast address range: #Addr %d \* #VLANs %d > %d

**Source    Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



IGMP Exceeded reserved multicast  
address range #Addr  
numResAddrEntries+1 \* #VLANs  
numActiveVLANs maxReservedRange

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP Exceeded reserved multicast address range #Addr numResAddrEntries+1 \* #VLANs numActiveVLANs maxReservedRange log

IGMP Exceeded reserved multicast address range #Addr numResAddrEntries+1 \* #VLANs numActiveVLANs maxReservedRange

The maximum number of registered unknown allowed multicast addresses are reached.

Source	Severity
IGMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Group database received from all non-base units

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Group database received from all non-base units log

IGMP: Group database received from all non-base units

**Source    Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Group database received on unit %d from %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Group database received on unit %d from %d log

IGMP: Group database received on unit %d from %d

**Source    Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Group database sent by unit %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Group database sent by unit %d log

IGMP: Group database sent by unit %d

**Source**   **Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Initialization failed: Error code %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Initialization failed: Error code %d log

IGMP: Initialization failed: Error code %d

**Source**   **Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP Initialization failed Error code errCode

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP Initialization failed Error code errCode log

IGMP Initialization failed Error code errCode

The IGMP initialization failed due to unavailable system resources.

Source	Severity
IGMP	Critical

### Remedial action

Restart the system.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IGMP: Initialization success

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Initialization success log

IGMP: Initialization success

**Source**   **Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Join stack completed. Database synchronized

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Join stack completed. Database synchronized log

IGMP: Join stack completed. Database synchronized

**Source   Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Last member query interval changed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Last member query interval changed log

IGMP: Last member query interval changed

**Source**   **Severity**

IPIGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: LEAVE received for Group 0x%x on VLAN %d and port %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: LEAVE received for Group 0x%x on VLAN %d and port %d log

IGMP: LEAVE received for Group 0x%x on VLAN %d and port %d

**Source**   **Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP Maximum number of igmp enabled interfaces reached

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP Maximum number of igmp enabled interfaces reached log

IGMP Maximum number of igmp enabled interfaces reached

The IGMP-enabled interfaces reached the maximum limit of 256.

Source	Severity
ipmc (igmp)	Serious

### Remedial action

Disable the IGMP on interfaces that no longer need to be IGMP-enabled.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Maximum number of igmp enabled interfaces reached

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Maximum number of igmp enabled interfaces reached log

IGMP: Maximum number of igmp enabled interfaces reached

**Source**   **Severity**

IPIGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Mirror port %d set

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Mirror port %d set log

IGMP: Mirror port %d set

**Source**   **Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Multicast table full, dropping streams

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Multicast table full, dropping streams log

IGMP: Multicast table full, dropping streams

Maximum supported number of multicast streams was reached.

Source	Severity
IGMP	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IGMP: new Querier IP learned on port %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: new Querier IP learned on port %d log

IGMP: new Querier IP learned on port %d

**Source**   **Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP No hardware resource available

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP No hardware resource available log

IGMP No hardware resource available

The IGMP Hardware Resource Allocation Failed.

Source	Severity
ipmc (igmp)	Information

### Remedial action

Redo the QoS filter allocations.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: No hardware resource available

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: No hardware resource available log

IGMP: No hardware resource available

**Source**   **Severity**

IPIGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Not able to join stack: Error code %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Not able to join stack: Error code %d log

IGMP: Not able to join stack: Error code %d

### Source    Severity

IGMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Policy initialization failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Policy initialization failed log

IGMP: Policy initialization failed

**Source**   **Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Policy initialization success

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Policy initialization success log

IGMP: Policy initialization success

**Source**   **Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Port %d added to VLAN %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Port %d added to VLAN %d log

IGMP: Port %d added to VLAN %d

**Source    Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Port %d removed from VLAN %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Port %d removed from VLAN %d log

IGMP: Port %d removed from VLAN %d

**Source    Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IGMP: Proxy disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Proxy disabled log

IGMP: Proxy disabled

**Source**   **Severity**

IPIGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Proxy disabled on VLAN %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Proxy disabled on VLAN %d log

IGMP: Proxy disabled on VLAN %d

**Source**   **Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP Proxy disabled on VLAN vlan#

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP Proxy disabled on VLAN vlan# log

IGMP Proxy disabled on VLAN vlan#

The IGMP proxy is disabled for a VLAN.

Source	Severity
IGMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Proxy enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Proxy enabled log

IGMP: Proxy enabled

**Source**   **Severity**

IPIGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Proxy enabled on VLAN %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Proxy enabled on VLAN %d log

IGMP: Proxy enabled on VLAN %d

**Source**   **Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP Proxy enabled on VLAN vlan#

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP Proxy enabled on VLAN vlan# log

IGMP Proxy enabled on VLAN vlan#

The IGMP proxy is enabled for a VLAN.

Source	Severity
IGMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Query max response changed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Query max response changed log

IGMP: Query max response changed

**Source**   **Severity**

IPIGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: QUERY received for Group 0x%x on VLAN %d and port %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: QUERY received for Group 0x%x on VLAN %d and port %d log

IGMP: QUERY received for Group 0x%x on VLAN %d and port %d

Source	Severity
IGMP	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IGMP: Query Time changed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Query Time changed log

IGMP: Query Time changed

**Source**   **Severity**

IPIGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Query Time set to %d on VLAN %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Query Time set to %d on VLAN %d log

IGMP: Query Time set to %d on VLAN %d

**Source**   **Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP Query Time set to num on VLAN vlan#

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP Query Time set to num on VLAN vlan# log

IGMP Query Time set to num on VLAN vlan#

The "Query Time" parameter is modified for a VLAN.

Source	Severity
IGMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP Removed reserved multicast address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP Removed reserved multicast address log

IGMP Removed reserved multicast address

The unknown allowed multicast address is unregistered on the switch.

Source	Severity
IGMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Removed reserved multicast address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Removed reserved multicast address log

IGMP: Removed reserved multicast address

**Source**   **Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: REPORT received for Group 0x%x on VLAN %d and port %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: REPORT received for Group 0x%x on VLAN %d and port %d log

IGMP: REPORT received for Group 0x%x on VLAN %d and port %d

**Source    Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Robust Value changed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Robust Value changed log

IGMP: Robust Value changed

**Source**   **Severity**

IPIGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Robust Value set to %d on VLAN %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Robust Value set to %d on VLAN %d log

IGMP: Robust Value set to %d on VLAN %d

**Source**   **Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IGMP Robust Value set to num on VLAN vlan#

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP Robust Value set to num on VLAN vlan# log

IGMP Robust Value set to num on VLAN vlan#

The "Robust Value" parameter is modified for a VLAN.

Source	Severity
IGMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Router Alert changed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Router Alert changed log

IGMP: Router Alert changed

**Source**   **Severity**

IPIGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Snooping disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Snooping disabled log

IGMP: Snooping disabled

**Source**   **Severity**

IPIGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Snooping disabled on VLAN %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Snooping disabled on VLAN %d log

IGMP: Snooping disabled on VLAN %d

**Source    Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP Snooping disabled on VLAN vlan#

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP Snooping disabled on VLAN vlan# log

IGMP Snooping disabled on VLAN vlan#

The IGMP snooping is disabled for a VLAN.

Source	Severity
IGMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Snooping enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Snooping enabled log

IGMP: Snooping enabled

**Source**   **Severity**

IPIGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Snooping enabled on VLAN %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Snooping enabled on VLAN %d log

IGMP: Snooping enabled on VLAN %d

**Source**   **Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP Snooping enabled on VLAN vlan#

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP Snooping enabled on VLAN vlan# log

IGMP Snooping enabled on VLAN vlan#

The IGMP snooping is enabled for a VLAN.

Source	Severity
IGMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IGMP SSM Range changed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP SSM Range changed log

IGMP SSM Range changed

The group range for IP IGMP SSM has changed.

Source	Severity
IGMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP SSM Range changed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP SSM Range changed log

IGMP SSM Range changed

The IGMP global allowable SSM range is changed.

Source	Severity
ipmc (igmp)	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: SSM Range changed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: SSM Range changed log

IGMP: SSM Range changed

**Source**   **Severity**

IPIGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Static Router ports

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Static Router ports log

IGMP: Static Router ports

**Source**   **Severity**

IPIGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Trunk %d created. IGMP groups added on all trunk ports

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Trunk %d created. IGMP groups added on all trunk ports log

IGMP: Trunk %d created. IGMP groups added on all trunk ports

**Source**   **Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Trunk %d removed. IGMP groups removed on all trunk ports

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Trunk %d removed. IGMP groups removed on all trunk ports log

IGMP: Trunk %d removed. IGMP groups removed on all trunk ports

Source	Severity
IGMP	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP Unable to add reserved multicast address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP Unable to add reserved multicast address log

IGMP Unable to add reserved multicast address

This message appears when an unknown multicast address registration fails.

Source	Severity
IGMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Unable to add reserved multicast address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Unable to add reserved multicast address log

IGMP: Unable to add reserved multicast address

**Source**   **Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IGMP Unknown Multicast Filter disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP Unknown Multicast Filter disabled log

IGMP Unknown Multicast Filter disabled

The "Unknown Multicast No Flood" feature is disabled from the user interface.

Source	Severity
IGMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Unknown Multicast Filter disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Unknown Multicast Filter disabled log

IGMP: Unknown Multicast Filter disabled

**Source    Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP Unknown Multicast Filter enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP Unknown Multicast Filter enabled log

IGMP Unknown Multicast Filter enabled

This message appears when the “Unknown Multicast No Flood” feature is enabled from the user interface.

Source	Severity
IGMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Unknown Multicast Filter enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Unknown Multicast Filter enabled log

IGMP: Unknown Multicast Filter enabled

**Source**   **Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Unknown Query received on SPBM Multicast C-VLAN

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Unknown Query received on SPBM Multicast C-VLAN log

IGMP: Unknown Query received on SPBM Multicast C-VLAN

**Source**   **Severity**

IPIGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: Version changed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: Version changed log

IGMP: Version changed

**Source**   **Severity**

IPIGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: V2 report drop on reserved GA

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: V2 report drop on reserved GA log

IGMP: V2 report drop on reserved GA

IGMP V2 report for reserved group IP was dropped.

Source	Severity
MCMGR/IGMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: V3 report group skip on invalid GA

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: V3 report group skip on invalid GA log

IGMP: V3 report group skip on invalid GA

A group record in an IGMP V3 report was skipped, as the group address is not multicast.

Source	Severity
MCMGR/IGMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IGMP: V3 report group skip on reserved GA

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: V3 report group skip on reserved GA log

IGMP: V3 report group skip on reserved GA

A group record in an IGMP V3 report was skipped, as the group address is reserved.

Source	Severity
MCMGR/IGMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP V1 router ports mask

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP V1 router ports mask log

IGMP V1 router ports mask

This message appears when the list of IGMP version 1 router ports are modified.

Source	Severity
IGMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP V2 router ports mask

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP V2 router ports mask log

IGMP V2 router ports mask

This message appears when the list of IGMP version 2 router ports are modified.

Source	Severity
IGMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: V1 router ports mask

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: V1 router ports mask log

IGMP: V1 router ports mask

**Source**   **Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IGMP: V2 router ports mask

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP: V2 router ports mask log

IGMP: V2 router ports mask

**Source**   **Severity**

IGMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ignored event %s for state %s, arg: %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ignored event %s for state %s, arg: %d log

Ignored event %s for state %s, arg: %d

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IKE CRL validate of peer %d.%d.%d.%d certificate status OK

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKE CRL validate of peer %d.%d.%d.%d certificate status OK log

IKE CRL validate of peer %d.%d.%d.%d certificate status OK

**Source**   **Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IKE CRL validate of peer %d.%d.%d.%d certificate status revoked

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKE CRL validate of peer %d.%d.%d.%d certificate status revoked log

IKE CRL validate of peer %d.%d.%d.%d certificate status revoked

**Source**   **Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IKE CRL validate of peer %s certificate status OK

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKE CRL validate of peer %s certificate status OK log

IKE CRL validate of peer %s certificate status OK

**Source**   **Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IKE CRL validate of peer %s certificate status revoked

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKE CRL validate of peer %s certificate status revoked log

IKE CRL validate of peer %s certificate status revoked

**Source**   **Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IKE CRL validation of peer %d.%d.%d.%d failed to get certificate status

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKE CRL validation of peer %d.%d.%d.%d failed to get certificate status log

IKE CRL validation of peer %d.%d.%d.%d failed to get certificate status

**Source    Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IKE CRL validation of peer %s failed to get certificate status

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKE CRL validation of peer %s failed to get certificate status log

IKE CRL validation of peer %s failed to get certificate status

**Source**   **Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IKE init done with auth-method only as PSK

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKE init done with auth-method only as PSK log

IKE init done with auth-method only as PSK

**Source    Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IKE OSCP validate of peer %d.%d.%d.%d certificate status OK

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKE OSCP validate of peer %d.%d.%d.%d certificate status OK log

IKE OSCP validate of peer %d.%d.%d.%d certificate status OK

**Source    Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



IKE OSCP validate of peer  
%d.%d.%d.%d certificate status  
revoked

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKE OSCP validate of peer %d.%d.%d.%d certificate status revoked log

IKE OSCP validate of peer %d.%d.%d.%d certificate status revoked

**Source   Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IKE OSCP validate of peer %s certificate status OK

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKE OSCP validate of peer %s certificate status OK log

IKE OSCP validate of peer %s certificate status OK

**Source**   **Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IKE OCSP validate of peer %s certificate status revoked

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKE OCSP validate of peer %s certificate status revoked log

IKE OCSP validate of peer %s certificate status revoked

**Source   Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IKE OCSP validation of peer %d.%d.%d.%d failed to get certificate status

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKE OCSP validation of peer %d.%d.%d.%d failed to get certificate status log

IKE OCSP validation of peer %d.%d.%d.%d failed to get certificate status

**Source**   **Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IKE OCSP validation of peer %s failed to get certificate status

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKE OCSP validation of peer %s failed to get certificate status log

IKE OCSP validation of peer %s failed to get certificate status

### Source   Severity

IKE

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IKE P2 SA failed status:%s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKE P2 SA failed status:%s log

IKE P2 SA failed status:%s

**Source    Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



IKE P2 SA lifetime expired. P2 SA rekey initiated. I/R: %s IAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKE P2 SA lifetime expired. P2 SA rekey initiated. I/R: %s IAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d log

IKE P2 SA lifetime expired. P2 SA rekey initiated. I/R: %s IAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d

**Source    Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



IKE P2 SA rekey due to DPD. I/R: %s  
lAddr: %d.%d.%d.%d  
rAddr: %d.%d.%d.%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKE P2 SA rekey due to DPD. I/R: %s lAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d log

IKE P2 SA rekey due to DPD. I/R: %s lAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d

**Source    Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IKE server listening for data

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKE server listening for data log

IKE server listening for data

**Source**   **Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IKE trust anchor created successfully

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKE trust anchor created successfully log

IKE trust anchor created successfully

**Source**   **Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





IKEv%d P1 DPD - Dead Peer Detected  
I/R: %s IAddr:%d.%d.%d.%d  
rAddr:%d.%d.%d.%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKEv%d P1 DPD - Dead Peer Detected I/R: %s IAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d log

IKEv%d P1 DPD - Dead Peer Detected I/R: %s IAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d

**Source    Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IKEv%d P1 IPv6 SA Created. IAddr:%s status:%s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKEv%d P1 IPv6 SA Created. IAddr:%s status:%s log

IKEv%d P1 IPv6 SA Created. IAddr:%s status:%s

**Source    Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IKEv%d P2 IPv6 SA Created. IAddr:%s status:%s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKEv%d P2 IPv6 SA Created. IAddr:%s status:%s log

IKEv%d P2 IPv6 SA Created. IAddr:%s status:%s

**Source    Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IKEv%d P1 IPv6 SA Deleted. IAddr:%s status:%s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKEv%d P1 IPv6 SA Deleted. IAddr:%s status:%s log

IKEv%d P1 IPv6 SA Deleted. IAddr:%s status:%s

**Source    Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IKEv%d P2 IPv6 SA Deleted. IAddr:%s status:%s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKEv%d P2 IPv6 SA Deleted. IAddr:%s status:%s log

IKEv%d P2 IPv6 SA Deleted. IAddr:%s status:%s

**Source   Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IKEv%d P1 IPv6 SA Failed. IAddr:%s status:%s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKEv%d P1 IPv6 SA Failed. IAddr:%s status:%s log

IKEv%d P1 IPv6 SA Failed. IAddr:%s status:%s

### Source    Severity

IKE

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IKEv%d P2 IPv6 SA Failed. IAddr:%s status:%s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKEv%d P2 IPv6 SA Failed. IAddr:%s status:%s log

IKEv%d P2 IPv6 SA Failed. IAddr:%s status:%s

### Source    Severity

IKE

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IKEv%d P1 IPv6 SA lifetime expired. IAddr: %s status: %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKEv%d P1 IPv6 SA lifetime expired. IAddr:%s status:%s log

IKEv%d P1 IPv6 SA lifetime expired. IAddr:%s status:%s

### Source    Severity

IKE

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





IKEv%d P1 SA Created. I/R: %s  
IAddr: %d.%d.%d.%d  
rAddr: %d.%d.%d.%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKEv%d P1 SA Created. I/R: %s IAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d log

IKEv%d P1 SA Created. I/R: %s IAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d

**Source    Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



IKEv%d P2 SA Created. I/R: %s  
lAddr: %d.%d.%d.%d  
rAddr: %d.%d.%d.%d Src Port: %d Dest  
Port: %d Protocol: %d status: %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKEv%d P2 SA Created. I/R: %s lAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d Src Port:%d Dest Port:%d Protocol:%d status:%s log

IKEv%d P2 SA Created. I/R: %s lAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d Src Port:%d Dest Port:%d Protocol:%d status:%s

**Source    Severity**

IKE

**Remedial action**



IKEv%d P2 SA Deleted. I/R: %s  
lAddr: %d.%d.%d.%d  
rAddr: %d.%d.%d.%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKEv%d P2 SA Deleted. I/R: %s lAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d log

IKEv%d P2 SA Deleted. I/R: %s lAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d

**Source    Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



IKEv%d P1 SA Deleted. I/R: %s  
lAddr: %d.%d.%d.%d  
rAddr: %d.%d.%d.%d status: %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKEv%d P1 SA Deleted. I/R: %s lAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d status:%s log

IKEv%d P1 SA Deleted. I/R: %s lAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d status:%s

**Source    Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



IKEv%d P2 SA Failed. I/R: %s  
lAddr: %d.%d.%d.%d  
rAddr: %d.%d.%d.%d Src Port: %d  
Dest Port: %d Protocol: %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

**IKEv%d P2 SA Failed. I/R: %s lAddr:%d.%d.%d.%d  
rAddr:%d.%d.%d.%d Src Port: %d Dest Port: %d Protocol: %d log**

IKEv%d P2 SA Failed. I/R: %s lAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d Src Port: %d Dest Port: %d Protocol: %d

**Source    Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



IKEv%d P1 SA Failed. I/R: %s  
lAddr: %d.%d.%d.%d rAddr:  
%d.%d.%d.%d status: %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKEv%d P1 SA Failed. I/R: %s lAddr:%d.%d.%d.%d rAddr: %d.%d.%d.%d status:%s log

IKEv%d P1 SA Failed. I/R: %s lAddr:%d.%d.%d.%d rAddr: %d.%d.%d.%d status:%s

### Source    Severity

IKE

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



IKEv%d P1 SA lifetime expired. I/R: %s  
lAddr: %d.%d.%d.%d  
rAddr: %d.%d.%d.%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IKEv%d P1 SA lifetime expired. I/R: %s lAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d log

IKEv%d P1 SA lifetime expired. I/R: %s lAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d

**Source    Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IMC ack pool alloc failed %s line %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC ack pool alloc failed %s line %d log

IMC ack pool alloc failed %s line %d

Source	Severity
IMC	Information

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





IMC ack timeout msgType= %d  
imcSeq= %d ackExpected= 0x%02X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC ack timeout msgType= %d imcSeq= %d ackExpected= 0x%02X log

IMC ack timeout msgType= %d imcSeq= %d ackExpected= 0x%02X

Source	Severity
IMC	Information

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IMC app rcv routine error, type= %s(%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC app rcv routine error, type= %s(%d) log

IMC app rcv routine error, type= %s(%d)

Source	Severity
IMC	Information

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IMC buffers of size buffer size have been exhausted buffer pool size pool size

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC buffers of size buffer size have been exhausted buffer pool size pool size log

IMC buffers of size buffer size have been exhausted buffer pool size pool size

This message appears when memory buffers used for communication between units in a stack are exhausted. The <buffer size> > varies and is measured in bytes. The <pool size> can vary for different buffer sizes and different models (ERS 25XX / 45XX / 55XX / 56XX).

Source	Severity
IMC	Critical

### Remedial action

Restart the system.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# IMC buffers of size size have been exhausted buffer pool size size

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC buffers of size size have been exhausted buffer pool size size log

IMC buffers of size size have been exhausted buffer pool size size

Stack Monitor detected a depleted IMC (Inter-Module Communication) buffer pool.

Source	Severity
Stack Monitor	Information

### Remedial action

No action required. The switch/stack reboots itself. The logs are saved to NVRAM for future reference.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



IMC buffers of size %u have been exhausted, buffer pool size %u

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC buffers of size %u have been exhausted, buffer pool size %u log

IMC buffers of size %u have been exhausted, buffer pool size %u

Source	Severity
IMC	Information

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# imc cam processing aborted (code=%d,argument=0)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## imc cam processing aborted (code=%d,argument=0) log

imc cam processing aborted (code=%d,argument=0)

**Source    Severity**

CDT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IMC destination error rcvMsgDest= %d myUnitId= %d type= %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC destination error rcvMsgDest= %d myUnitId= %d type= %s log

IMC destination error rcvMsgDest= %d myUnitId= %d type= %s

### Source    Severity

IMC

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IMC Error (mem or send)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC Error (mem or send) log

IMC Error (mem or send)

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IMC error: %s line %d %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC error: %s line %d %s log

IMC error: %s line %d %s

Source	Severity
--------	----------

IMC	
-----	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IMC IMC\_ackedXmt() failed status= %d dest= 0x%02X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC IMC\_ackedXmt() failed status= %d dest= 0x%02X log

IMC IMC\_ackedXmt() failed status= %d dest= 0x%02X

### Source    Severity

IMC

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IMC imc\_ackReceive() ackRcvd= %d rcvSrcModule= %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC imc\_ackReceive() ackRcvd= %d rcvSrcModule= %d log

IMC imc\_ackReceive() ackRcvd= %d rcvSrcModule= %d

**Source    Severity**

IMC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IMC imc\_idtPacketDispatch() incorrect rcvMsgType = %s(%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC imc\_idtPacketDispatch() incorrect rcvMsgType = %s(%d) log

IMC imc\_idtPacketDispatch() incorrect rcvMsgType = %s(%d)

An incorrect message type was received.

Source	Severity
--------	----------

IMC	Warning
-----	---------

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IMC imc\_idtPacketDispatch() NULL routine rcvMsgType= %s(%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC imc\_idtPacketDispatch() NULL routine rcvMsgType= %s(%d) log

IMC imc\_idtPacketDispatch() NULL routine rcvMsgType= %s(%d)

**Source    Severity**

IMC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IMC IMC\_idtPktRecv() high queue imcType= %s(%d) length = %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC IMC\_idtPktRecv() high queue imcType= %s(%d) length = %d log

IMC IMC\_idtPktRecv() high queue imcType= %s(%d) length = %d

**Source    Severity**

IMC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IMC IMC\_idtPktRecv() low queue imcType= %s(%d) length = %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC IMC\_idtPktRecv() low queue imcType= %s(%d) length = %d log

IMC IMC\_idtPktRecv() low queue imcType= %s(%d) length = %d

### Source    Severity

IMC

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IMC IMC\_idtPktRecv() %s line %d length = %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC IMC\_idtPktRecv() %s line %d length = %d log

IMC IMC\_idtPktRecv() %s line %d length = %d

### Source    Severity

IMC

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IMC incorrect message type file = %s line = %d MsgType = %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC incorrect message type file = %s line = %d MsgType = %s log

IMC incorrect message type file = %s line = %d MsgType = %s

### Source    Severity

IMC

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



IMC initialized arg1= %d arg2 = %d  
arg3 = %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC initialized arg1= %d arg2 = %d arg3 = %d log

IMC initialized arg1= %d arg2 = %d arg3 = %d

**Source   Severity**

IMC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IMC jumbo pool alloc failed %s line %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC jumbo pool alloc failed %s line %d log

IMC jumbo pool alloc failed %s line %d

**Source   Severity**

IMC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IMC memory allocation error packetLength = %d file %s line %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC memory allocation error packetLength = %d file %s line %d log

IMC memory allocation error packetLength = %d file %s line %d

An error occurred on IMC packet allocation.

Source	Severity
--------	----------

IMC	Warning
-----	---------

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IMC msg pool creation failed %s line %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC msg pool creation failed %s line %d log

IMC msg pool creation failed %s line %d

**Source    Severity**

IMC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IMC normal pool alloc failed %s line %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC normal pool alloc failed %s line %d log

IMC normal pool alloc failed %s line %d

**Source    Severity**

IMC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IMC normal-small pool alloc failed %s line %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC normal-small pool alloc failed %s line %d log

IMC normal-small pool alloc failed %s line %d

**Source   Severity**

IMC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IMC packet alloc failed %s line %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC packet alloc failed %s line %d log

IMC packet alloc failed %s line %d

**Source    Severity**

IMC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





IMC packet length too large file = %s  
line = %d size = %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC packet length too large file = %s line = %d size = %d log

IMC packet length too large file = %s line = %d size = %d

**Source    Severity**

IMC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



IMC pkt dump offset= %d 0x%08X  
0x%08X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC pkt dump offset= %d 0x%08X 0x%08X log

IMC pkt dump offset= %d 0x%08X 0x%08X

**Source    Severity**

IMC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IMC priority pool alloc failed %s line %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC priority pool alloc failed %s line %d log

IMC priority pool alloc failed %s line %d

**Source**   **Severity**

IMC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IMC queue creation failed %s line %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC queue creation failed %s line %d log

IMC queue creation failed %s line %d

**Source**   **Severity**

IMC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



IMC quick buffers maximum number of tasks %d to be traced reachead for IMC buffer of size %u

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC quick buffers maximum number of tasks %d to be traced reachead for IMC buffer of size %u log

IMC quick buffers maximum number of tasks %d to be traced reachead for IMC buffer of size %u

**Source**   **Severity**

IMC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



IMC rcv checksum error  
rcvMsgChksum= 0x%08X  
calcMsgChksum= 0x%08X type= %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC rcv checksum error rcvMsgChksum= 0x%08X calcMsgChksum= 0x%08X type= %s log

IMC rcv checksum error rcvMsgChksum= 0x%08X calcMsgChksum= 0x%08X type= %s

### Source    Severity

IMC

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IMC rcv msg sequence error rcvMsgSeq= %d rcvMsgType= %s(%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC rcv msg sequence error rcvMsgSeq= %d rcvMsgType= %s(%d) log

IMC rcv msg sequence error rcvMsgSeq= %d rcvMsgType= %s(%d)

### Source    Severity

IMC

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IMC rcv status error rcvStatus= %d rcvMsgType= %s(%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC rcv status error rcvStatus= %d rcvMsgType= %s(%d) log

IMC rcv status error rcvStatus= %d rcvMsgType= %s(%d)

### Source    Severity

IMC

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





IMC retries exceeded msgType= %d  
imcSeq= %d ackExpected= 0x%02X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC retries exceeded msgType= %d imcSeq= %d ackExpected= 0x%02X log

IMC retries exceeded msgType= %d imcSeq= %d ackExpected= 0x%02X

Source	Severity
IMC	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IMC semaphore creation failed %s line %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC semaphore creation failed %s line %d log

IMC semaphore creation failed %s line %d

**Source**   **Severity**

IMC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



IMC sending ACK pkt(s) %d %s line %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC sending ACK pkt(s) %d %s line %d log

IMC sending ACK pkt(s) %d %s line %d

**Source    Severity**

IMC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IMC sending pkt: bad dest. 0x%02X %s line %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC sending pkt: bad dest. 0x%02X %s line %d log

IMC sending pkt: bad dest. 0x%02X %s line %d

**Source    Severity**

IMC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



IMC sending pkt imcSeq= %d  
imcMsgType= %d dest= 0x%02X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC sending pkt imcSeq= %d imcMsgType= %d dest= 0x%02X log

IMC sending pkt imcSeq= %d imcMsgType= %d dest= 0x%02X

### Source   Severity

IMC

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



IMC send pkt error imcSeq= %d  
imcMsgType= %d dest= 0x%02X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC send pkt error imcSeq= %d imcMsgType= %d dest= 0x%02X log

IMC send pkt error imcSeq= %d imcMsgType= %d dest= 0x%02X

**Source    Severity**

IMC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



IMC send pkt fmt error imcSeq= %d  
imcMsgType= %d status= 0x%02X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC send pkt fmt error imcSeq= %d imcMsgType= %d status= 0x%02X log

IMC send pkt fmt error imcSeq= %d imcMsgType= %d status= 0x%02X

Source	Severity
IMC	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IMC small pool alloc failed %s line %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC small pool alloc failed %s line %d log

IMC small pool alloc failed %s line %d

**Source**   **Severity**

IMC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IMC source error rcvMsgSrc= %d type= %s(%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC source error rcvMsgSrc= %d type= %s(%d) log

IMC source error rcvMsgSrc= %d type= %s(%d)

### Source    Severity

IMC

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IMC timer creation failed %s line %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC timer creation failed %s line %d log

IMC timer creation failed %s line %d

**Source**   **Severity**

IMC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IMC type error rcvMsgType= %s(%d) rcvMsgSrc= %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC type error rcvMsgType= %s(%d) rcvMsgSrc= %d log

IMC type error rcvMsgType= %s(%d) rcvMsgSrc= %d

### Source    Severity

IMC

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IMC version error rcvMsgVersion= %d type= %s src= %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IMC version error rcvMsgVersion= %d type= %s src= %d log

IMC version error rcvMsgVersion= %d type= %s src= %d

### Source    Severity

IMC

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Inadequate resources available for application policy criteria

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Inadequate resources available for application policy criteria log

Inadequate resources available for application policy criteria

The resources potentially consumed by a legacy filter set are not available on the specified interface (on the base or the non-base unit).

Source	Severity
QoS	Serious

### Remedial action

Check log for the possible related details on the issue. Check the available resources.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Inappropriate status transition specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Inappropriate status transition specified log

Inappropriate status transition specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Incompatible base action extension specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Incompatible base action extension specified log

Incompatible base action extension specified

The storage types are not compatible. For example only system-level entries can reference other system-level entries.

Source	Severity
QoS	Serious

### Remedial action

Check the documentation if necessary and use compatible entries.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Incompatible classifier reference (agent-defined clfr)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Incompatible classifier reference (agent-defined clfr) log

Incompatible classifier reference (agent-defined clfr)

It's forbidden to reference an system/agent defined classifier element.

Source	Severity
QoS	Serious

### Remedial action

Create a similar user defined classifier element.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Incompatible data model version values (referenced clfr data)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Incompatible data model version values (referenced clfr data) log

Incompatible data model version values (referenced clfr data)

The data model version of the classifier is unknown.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Incompatible data model version values (referenced meter data)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Incompatible data model version values (referenced meter data) log

Incompatible data model version values (referenced meter data)

The data model version of the meter is unknown

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Incompatible in-profile action (trusted ifc)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Incompatible in-profile action (trusted ifc) log

Incompatible in-profile action (trusted ifc)

The specified in-profile action is not supported on the associated interface type (trusted).

Source	Severity
QoS	Serious

### Remedial action

Enter a different in-profile action or change interface group assignment.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Incompatible in-profile action (unrestricted ifc)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Incompatible in-profile action (unrestricted ifc) log

Incompatible in-profile action (unrestricted ifc)

The specified in-profile action is not supported on the associated interface type (unrestricted).

Source	Severity
QoS	Serious

### Remedial action

Enter a different in-profile action or change interface group assignment.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Incompatible in-profile action (untrusted ifc)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Incompatible in-profile action (untrusted ifc) log

Incompatible in-profile action (untrusted ifc)

The specified in-profile action is not supported on the associated interface type (untrusted).

Source	Severity
QoS	Serious

### Remedial action

Enter a different in-profile action or change interface group assignment.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Incompatible in-profile action (untrustedv4v6 ifc)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Incompatible in-profile action (untrustedv4v6 ifc) log

Incompatible in-profile action (untrustedv4v6 ifc)

The specified in-profile action is not compatible with the associated interface type (untrustedv4v6).

Source	Severity
QoS	Serious

### Remedial action

Enter a different in-profile action or change the interface group assignment.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Incompatible match action (trusted ifc)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Incompatible match action (trusted ifc) log

Incompatible match action (trusted ifc)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Incompatible match action (unrestricted ifc)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Incompatible match action (unrestricted ifc) log

Incompatible match action (unrestricted ifc)

The specified action is not supported on the associated interface type (unrestricted).

Source	Severity
QoS	Serious

### Remedial action

Enter a different action or change interface group assignment.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Incompatible match action (untrusted ifc)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Incompatible match action (untrusted ifc) log

Incompatible match action (untrusted ifc)

The specified action is not supported on the associated interface type (untrusted).

Source	Severity
QoS	Serious

### Remedial action

Enter a different action or change interface group assignment.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Incompatible match action (untrustedv4v6 ifc)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Incompatible match action (untrustedv4v6 ifc) log

Incompatible match action (untrustedv4v6 ifc)

The specified action is not compatible with the associated interface type (untrustedv4v6).

Source	Severity
QoS	Serious

### Remedial action

Enter a different action or change the interface group assignment.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Incompatible non-match action (trusted ifc)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Incompatible non-match action (trusted ifc) log

Incompatible non-match action (trusted ifc)

The specified non-match action is not supported on the associated interface type (trusted)

Source	Severity
QoS	Serious

### Remedial action

Enter a different non-match action or change interface group assignment.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Incompatible non-match action (unrestricted ifc)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Incompatible non-match action (unrestricted ifc) log

Incompatible non-match action (unrestricted ifc)

The specified non-match action is not supported on the associated interface type (unrestricted).

Source	Severity
QoS	Serious

### Remedial action

Enter a different non-match action or change interface group assignment.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Incompatible non-match action (untrusted ifc)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Incompatible non-match action (untrusted ifc) log

Incompatible non-match action (untrusted ifc)

The specified non-match action is not supported on the associated interface type (untrusted).

Source	Severity
QoS	Serious

### Remedial action

Enter a different non-match action or change interface group assignment.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Incompatible non-match action (untrustedv4v6 ifc)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Incompatible non-match action (untrustedv4v6 ifc) log

Incompatible non-match action (untrustedv4v6 ifc)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Incompatible out-of-profile action (trusted ifc)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Incompatible out-of-profile action (trusted ifc) log

Incompatible out-of-profile action (trusted ifc)

The specified out-of-profile action is not supported on the associated interface type (trusted).

Source	Severity
QoS	Serious

### Remedial action

Enter a different out-of-profile action or change interface group assignment.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Incompatible out-of-profile action (unrestricted ifc)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Incompatible out-of-profile action (unrestricted ifc) log

Incompatible out-of-profile action (unrestricted ifc)

The specified out-of-profile action is not supported on the associated interface type (unrestricted).

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Enter a different out-of-profile action or change interface group assignment.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Incompatible out-of-profile action (untrusted ifc)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Incompatible out-of-profile action (untrusted ifc) log

Incompatible out-of-profile action (untrusted ifc)

The specified out-of-profile action is not supported on the associated interface type (untrusted).

Source	Severity
QoS	Serious

### Remedial action

Enter a different out-of-profile action or change interface group assignment.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Incompatible out-of-profile action (untrustedv4v6 ifc)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Incompatible out-of-profile action (untrustedv4v6 ifc) log

Incompatible out-of-profile action (untrustedv4v6 ifc)

The specified out-of-profile action is not compatible with the associated interface type (untrustedv4v6).

Source	Severity
QoS	Serious

### Remedial action

Enter a different out-of-profile action or change the interface group assignment.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Incompatible range requirements detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Incompatible range requirements detected log

Incompatible range requirements detected

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Incompatible StorageType specified (re classifier)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Incompatible StorageType specified (re classifier) log

Incompatible StorageType specified (re classifier)

The policy and classifier have incompatible storage types. As a general rule only system-level entries can reference other system-level entries.

Source	Severity
QoS	Serious

### Remedial action

Enter a compatible classifier or create a new one.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Incompatible StorageType specified (re: classifier)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Incompatible StorageType specified (re: classifier) log

Incompatible StorageType specified (re: classifier)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Inconsistency detected between SPBM instance VLAN data and primary SPBM BVLAN

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Inconsistency detected between SPBM instance VLAN data and primary SPBM BVLAN log

Inconsistency detected between SPBM instance VLAN data and primary SPBM BVLAN

**Source    Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Inconsistent action criteria detected across block members

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Inconsistent action criteria detected across block members log

Inconsistent action criteria detected across block members

The action options within a block entry must be consistent. For instance you cannot specify an action and a meter for a block in the same time.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Enter only an action or a meter across block.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Inconsistent classifier component ( clfr comp# ) state detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Inconsistent classifier component ( clfr comp# ) state detected log

Inconsistent classifier component ( clfr comp# ) state detected

Unable to commit changes because of an invalid/inconsistent state.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Inconsistent classifier component (%d) state detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Inconsistent classifier component (%d) state detected log

Inconsistent classifier component (%d) state detected

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Inconsistent labels detected for members of same block

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Inconsistent labels detected for members of same block log

Inconsistent labels detected for members of same block

The members of the same classifier-block must have the same label.

Source	Severity
QoS	Serious

### Remedial action

Enter the same label for all members.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Inconsistent labels detected for members of same set

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Inconsistent labels detected for members of same set log

Inconsistent labels detected for members of same set

Entries of the same set must have the same labels.

Source	Severity
QoS	Serious

### Remedial action

Enter the same labels for all members in the set or separate the conflicting components into multiple sets.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Inconsistent MAC data detected across filter set members

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Inconsistent MAC data detected across filter set members log

Inconsistent MAC data detected across filter set members

Inconsistent MAC data detected across the filter sets; Following are the possible reasons: Different users are on the same interface with different MAC data length, Different users on the same interface with the same MAC data source.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Check for and remove the possible MAC data conflicts.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Inconsistent metering criteria detected across block members

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Inconsistent metering criteria detected across block members log

Inconsistent metering criteria detected across block members

Invalid metering option specified. QPA internal error.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Enter a valid meter or ignore option.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Inconsistent value

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Inconsistent value log

Inconsistent value

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Index value out-of-range

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Index value out-of-range log

Index value out-of-range

Invalid QoS entry index value. Either system index for a non-system entry, or index out of the supported range.

Source	Severity
QoS	Information

### Remedial action

Enter a different entry index.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Index value out-of-range or permanent/read-only/system entry

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Index value out-of-range or permanent/read-only/system entry log

Index value out-of-range or permanent/read-only/system entry

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Info: Transceiver inserted on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Info: Transceiver inserted on %s log

Info: Transceiver inserted on %s

The transceiver has been inserted on a certain unit/port, having a specific vendor and type.

Source	Severity
PDT	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Info: Transceiver inserted on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Info: Transceiver inserted on %s log

Info: Transceiver inserted on %s

**Source    Severity**

GBIC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Info: Transceiver removed from %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Info: Transceiver removed from %s log

Info: Transceiver removed from %s

The transceiver has been removed from a certain unit/port.

Source	Severity
PDT	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Info: Transceiver removed from %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Info: Transceiver removed from %s log

Info: Transceiver removed from %s

**Source**   **Severity**

GBIC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Inner VLAN ID filtering requires double tag

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Inner VLAN ID filtering requires double tag log

Inner VLAN ID filtering requires double tag

Inner VLAN ID is used in double tagged packets.

Source	Severity
QoS	Serious

### Remedial action

Remove inner VLAN ID option or specify double tagged mode.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Inner VLAN ID min/max values invalid (%d !< %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Inner VLAN ID min/max values invalid (%d !< %d) log

Inner VLAN ID min/max values invalid (%d !< %d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Inner VLAN ID min max values invalid ( min VLAN ID ! max VLAN ID )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Inner VLAN ID min max values invalid ( min VLAN ID ! max VLAN ID ) log

Inner VLAN ID min max values invalid ( min VLAN ID ! max VLAN ID )

Max inner VLAN ID value must be bigger than min value.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Correct inner VLAN ID range limits.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# In-profile action contains conflicting data

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## In-profile action contains conflicting data log

In-profile action contains conflicting data

Unable to install the specified in-profile action, conflicting data detected.

Source	Severity
QoS	Serious

### Remedial action

Identify conflicts and separate them into different in-profile actions.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Insufficient dynamic UBP attributes in CoA, need ACL, UROL and SET

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Insufficient dynamic UBP attributes in CoA, need ACL, UROL and SET log

Insufficient dynamic UBP attributes in CoA, need ACL, UROL and SET

UBP in relation to CoA cannot be dynamically created because not all the mentioned attributes (ACL, UROL and SET) were given.

Source	Severity
EAP	Warning

### Remedial action

ACL, UROL and SET must all be provided in order for an UBP in relation to CoA to be dynamically created.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Insufficient dynamic UBP attributes,  
need ACL, UROL and SET, port %s, MAC  
%02x:%02x:%02x:%02x:%02x:%02x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Insufficient dynamic UBP attributes, need ACL, UROL and SET, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x log

Insufficient dynamic UBP attributes, need ACL, UROL and SET, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x

UBP cannot be dynamically created because not all the mentioned attributes (ACL, UROL and SET) were given.

Source	Severity
--------	----------

EAP	Warning
-----	---------

### Remedial action

ACL, UROL and SET must all be provided in order for an UBP to be dynamically created.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Insufficient HW resources to support port role association

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Insufficient HW resources to support port role association log

Insufficient HW resources to support port role association

Not all the resources required for the interface assignment change are available.

Source	Severity
QoS	Serious

### Remedial action

Check for conflicts and remove the un-needed resources if any.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Insufficient HW resources to support port/role association

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Insufficient HW resources to support port/role association log

Insufficient HW resources to support port/role association

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Insufficient policy space available to support access assignment

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Insufficient policy space available to support access assignment log

Insufficient policy space available to support access assignment

Not enough resources to support the policy installation on base or non-base unit.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Check the policy resource availability and try to remove any resources that are not needed.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Insufficient resources available to support policy installation

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Insufficient resources available to support policy installation log

Insufficient resources available to support policy installation

Not all the resources required for the policy are available on the base or non-base unit(s).

Source	Severity
QoS	Serious

### Remedial action

Modify either the interfaces or the demanding resources.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Interface action distribution across stack failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Interface action distribution across stack failed log

Interface action distribution across stack failed

Unable to perform action distribution changes across the stack.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Interface action entry referenced by base action

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Interface action entry referenced by base action log

Interface action entry referenced by base action

Cannot modify or delete an interface action if it is referenced by a base action.

Source	Severity
QoS	Serious

### Remedial action

Remove the base action first.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Interface action extension identifier invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Interface action extension identifier invalid log

Interface action extension identifier invalid

The interface action extension identifier is invalid.

Source	Severity
QoS	Critical

### Remedial action

Enter a valid interface action extension.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Interface action modifications not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Interface action modifications not supported log

Interface action modifications not supported

The system detected an internal error; The specified modifier option not supported.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent, or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Interface Application data in use (QoS disable prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Interface Application data in use (QoS disable prohibited) log

Interface Application data in use (QoS disable prohibited)

Cannot disable the QoS system if there are Interface Applications in use.

Source	Severity
QoS	Serious

### Remedial action

Disable all the Interface Applications before disabling QoS.



# Interface application distribution across stack failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Interface application distribution across stack failed log

Interface application distribution across stack failed

Unable to carry out the interface application distribution across the stack.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Interface application modifications not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Interface application modifications not supported log

Interface application modifications not supported

The system detected an internal error; The specified modifier option is not supported.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent, or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Interface application Undo failure (app app# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Interface application Undo failure (app app# ) log

Interface application Undo failure (app app# )

Unable to perform the "Undo" action due to the the specified interface application.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, or reset the stack.



# Interface application Undo failure (app %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Interface application Undo failure (app %d) log

Interface application Undo failure (app %d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Interface assignment distribution across stack failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Interface assignment distribution across stack failed log

Interface assignment distribution across stack failed

Unable to commit changes (interface assignment) across the stack.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Interface assignment failure - precedence conflict detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Interface assignment failure - precedence conflict detected log

Interface assignment failure - precedence conflict detected

The interface assignment change needs to install a policy on a precedence already occupied by a different one.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Remove or disable if possible the conflicting policy.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Interface assignment modifications not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Interface assignment modifications not supported log

Interface assignment modifications not supported

The system detected an internal error; The specified modifier option is not supported.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent, or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Interface capabilities incompatible with policy data

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Interface capabilities incompatible with policy data log

Interface capabilities incompatible with policy data

The policy and the specified interface have different version capabilities.

Source	Severity
QoS	Serious

### Remedial action

Enter either a compatible interface or adapt the policy to match the required interface.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Interface data out-of-sync in Policy and User Policy entries

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Interface data out-of-sync in Policy and User Policy entries log

Interface data out-of-sync in Policy and User Policy entries

The interface data associated with the policy and the session must be the same.

Source	Severity
QoS	Serious

### Remedial action

Specify the same interface data.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Interface queue modifications not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Interface queue modifications not supported log

Interface queue modifications not supported

The system detected an internal error; the specified modifier option is not supported.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Interface resources inadequate to support application enable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Interface resources inadequate to support application enable log

Interface resources inadequate to support application enable

The resources required for interface application support are not available on the specified interface.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue, or use a different interface.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Interface shaping and CoS shaping conflict (same ifc specified)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Interface shaping and CoS shaping conflict (same ifc specified) log

Interface shaping and CoS shaping conflict (same ifc specified)

Interface shaping and CoS shaping can not be applied to the same interface at the same time.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Enter different interfaces for the two shaping types.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Interface shaping and queue shaping conflict (same ifc specified)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Interface shaping and queue shaping conflict (same ifc specified) log

Interface shaping and queue shaping conflict (same ifc specified)

Both Interface and queue shaping can not be applied to the one interface at the same time.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Enter different interfaces for the two shaping types.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Interface shaping distribution across stack failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Interface shaping distribution across stack failed log

Interface shaping distribution across stack failed

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Interface shaping modifications not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Interface shaping modifications not supported log

Interface shaping modifications not supported

The system detected an Internal error; specified modifier option not supported.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent, or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Interface shaping not supported with specified interface

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Interface shaping not supported with specified interface log

Interface shaping not supported with specified interface

The specified interface is unable to support the shaping.

Source	Severity
QoS	Serious

### Remedial action

Enter a different interface.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Interfaces QoS-disabled (%d on unit %d) - restoration issue

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Interfaces QoS-disabled (%d on unit %d) - restoration issue log

Interfaces QoS-disabled (%d on unit %d) - restoration issue

**Source   Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Interfaces QoS-disabled ( port# on unit# ) - restoration issue

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Interfaces QoS-disabled ( port# on unit# ) - restoration issue log

Interfaces QoS-disabled ( port# on unit# ) - restoration issue

Failed to disable the Policy/Interface.

Source	Severity
QoS	Serious

### Remedial action

Check for the conflicting entries, try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Internal Error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Internal Error log

Internal Error

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid access assignment type option specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid access assignment type option specified log

Invalid access assignment type option specified

The access assignment type option specified is invalid.

Source	Severity
QoS	Serious

### Remedial action

Check the documentation and use a supported access assignment type.



# Invalid access element type option specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid access element type option specified log

Invalid access element type option specified

There are 4 supported access element types: ACL, APP, MMC, and UDC; Check through the documentation for further clarifications on the issue.

Source	Severity
QoS	Serious

### Remedial action

Remove the classifier block first.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Invalid authentication type

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid authentication type log

Invalid authentication type

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid classifier ID specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid classifier ID specified log

Invalid classifier ID specified

Unable to find the specified classifier ID in the Filter Manager database.

Source	Severity
QoS	Critical

### Remedial action

Enter a valid classifier ID or if you are sure it exists try resetting the QoS agent or the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid classifier reference

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid classifier reference log

Invalid classifier reference

The only valid classifiers type are: ip, l2 and system.

Source	Severity
QoS	Serious

### Remedial action

Specify a valid classifier type.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid classifier reference (unknown class)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid classifier reference (unknown class) log

Invalid classifier reference (unknown class)

There are 30 supported classes, check documentation for a full support class description.

Source	Severity
QoS	Critical

### Remedial action

Specify a valid classifier class.



# Invalid classifier reference (unknown incompatible set)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid classifier reference (unknown incompatible set) log

Invalid classifier reference (unknown incompatible set)

The referenced classifier set must exist prior to being used.

Source	Severity
QoS	Serious

### Remedial action

Enter an existing classifier set or create a new one.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid classifier reference (unknown/incompatible set)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid classifier reference (unknown/incompatible set) log

Invalid classifier reference (unknown/incompatible set)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid classifier reference (unknown instance)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid classifier reference (unknown instance) log

Invalid classifier reference (unknown instance)

The referenced classifier element (ip, l2 or system) must exist prior to being used.

Source	Severity
QoS	Serious

### Remedial action

Enter an existing classifier element or create a new one.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid clear QoS statistics value specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid clear QoS statistics value specified log

Invalid clear QoS statistics value specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Invalid Configuration Block Number %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid Configuration Block Number %d log

Invalid Configuration Block Number %d

Invalid configuration block number entered.

Source	Severity
config	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid Configuration Magic Number

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid Configuration Magic Number log

Invalid Configuration Magic Number

The number that identifies the block number is incorrect and is not as expected.

Source	Severity
config	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid Configuration Version Number

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid Configuration Version Number log

Invalid Configuration Version Number

The block version number is not recognized.

Source	Severity
config	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid CSNP interval

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid CSNP interval log

Invalid CSNP interval

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid DAPP state transition detected (prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid DAPP state transition detected (prohibited) log

Invalid DAPP state transition detected (prohibited)

Can only move between disabled and enabled, not between different enable modes.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Disable DAPP before changing the enabled state.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid datapath identifier specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid datapath identifier specified log

Invalid datapath identifier specified

Invalid/Unknown datapath identifier detected. Internal Filter Manager error.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid default DSCP value specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid default DSCP value specified log

Invalid default DSCP value specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid default packet format value specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid default packet format value specified log

Invalid default packet format value specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Invalid destination MAC address length specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid destination MAC address length specified log

Invalid destination MAC address length specified

Destination MAC address length is bigger than 6.

Source	Severity
QoS	Serious

### Remedial action

Specify a valid MAC address.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid destination MAC address mask length specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid destination MAC address mask length specified log

Invalid destination MAC address mask length specified

Destination MAC address mask length is bigger than 6.

Source	Severity
QoS	Serious

### Remedial action

Specify a valid MAC address mask.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid drop action option specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid drop action option specified log

Invalid drop action option specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid drop action option specifiedInvalid drop action option specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid drop action option specifiedInvalid drop action option specified log

Invalid drop action option specifiedInvalid drop action option specified

The valid/supported drop options are drop, don't drop and deferred. Take into account that for certain action types the deferred option is not valid.

Source	Severity
QoS	Information

### Remedial action

Check the documentation if necessary and use a compatible/valid drop action option.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid drop precedence value specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid drop precedence value specified (%d) log

Invalid drop precedence value specified (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid drop precedence value specified ( precedence )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid drop precedence value specified ( precedence ) log

Invalid drop precedence value specified ( precedence )

Valid drop precedence values are low and high.

Source	Severity
QoS	Serious

### Remedial action

Specify a valid drop precedence value.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid DSCP value specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid DSCP value specified (%d) log

Invalid DSCP value specified (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid DSCP value specified ( DSCP value )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid DSCP value specified ( DSCP value ) log

Invalid DSCP value specified ( DSCP value )

The valid DSCP values are between 0 and 63.

Source	Severity
QoS	Serious

### Remedial action

Enter a valid DSCP value in the range specified.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Invalid egress interface specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid egress interface specified (%d) log

Invalid egress interface specified (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid egress interface specified ( ifc# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid egress interface specified ( ifc# ) log

Invalid egress interface specified ( ifc# )

The interface index does not exist.

Source	Severity
QoS	Serious

### Remedial action

Check the platform's/stack's port range and use a valid interface index.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid egress interface tag option specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid egress interface tag option specified log

Invalid egress interface tag option specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid egress interface type specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid egress interface type specified (%d) log

Invalid egress interface type specified (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid egress interface type specified (<ifc type>)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid egress interface type specified (<ifc type>) log

Invalid egress interface type specified (<ifc type>)

Interface can not be associated with action specifications(prohibited).

Source	Severity
QoS	Serious

### Remedial action

Enter a different port.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid egress mask value specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid egress mask value specified log

Invalid egress mask value specified

The egress mask must be either null or 64 in length.

Source	Severity
QoS	Serious

### Remedial action

Specify a valid egress mask.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid entry creation attempted (index %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid entry creation attempted (index %d) log

Invalid entry creation attempted (index %d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid entry creation attempted (index index# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid entry creation attempted (index index# ) log

Invalid entry creation attempted (index index# )

Creation of the specified QoS entry is not allowed (modifications may be supported) – possible entries: COS-to-DSCP assignment default values created at initialization; default DSCP-to-queue assignments and default CoS-to-queue assignments created when a new queue set is defined.

Source	Severity
QoS	Information

### Remedial action

Modify the existing entry if necessary.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Invalid Ethertype

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid Ethertype log

Invalid Ethertype

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid EtherType value specified ( Ether Type 0xFFFF )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid EtherType value specified ( Ether Type 0xFFFF ) log

Invalid EtherType value specified ( Ether Type 0xFFFF )

EtherType must be between 0x0-0xFFFF.

Source	Severity
QoS	Serious

### Remedial action

Specify an EtherType value between 0x0-0xFFFF.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid EtherType value specified (%04x)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid EtherType value specified (%04x) log

Invalid EtherType value specified (%04x)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid expired session data specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid expired session data specified log

Invalid expired session data specified

The session data provided does not exist or has expired.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Specify a current session data.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/expired session data specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/expired session data specified log

Invalid/expired session data specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid FCoE controller ingress interface specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid FCoE controller ingress interface specified log

Invalid FCoE controller ingress interface specified

An invalid FCoE controller ingress interface was specified.

Source	Severity
FCoE Redirect	Information

### Remedial action

Specify a valid interface.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid FCoE controller MAC address specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid FCoE controller MAC address specified log

Invalid FCoE controller MAC address specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid FCoE controller VLAN specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid FCoE controller VLAN specified log

Invalid FCoE controller VLAN specified

An invalid FCoE controller VLAN was specified..

Source	Severity
FCoE Redirect	Information

### Remedial action

Specify a valid VLAN.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Invalid FCoE D\_ID data specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid FCoE D\_ID data specified log

Invalid FCoE D\_ID data specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid FCoE redirection destination MAC address specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid FCoE redirection destination MAC address specified log

Invalid FCoE redirection destination MAC address specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid FCoE redirection source MAC address specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid FCoE redirection source MAC address specified log

Invalid FCoE redirection source MAC address specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid FCoE S\_ID data specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid FCoE S\_ID data specified log

Invalid FCoE S\_ID data specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid filter set priority value detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid filter set priority value detected log

Invalid filter set priority value detected

The filter set priority must be within 1 to 255.

Source	Severity
QoS	Serious

### Remedial action

Check the log for related details on the issue. Try again later, reset the QoS agent, or reset the stack

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/incompatible queue reference detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/incompatible queue reference detected log

Invalid/incompatible queue reference detected

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid interface found in egress mask (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid interface found in egress mask (%d) log

Invalid interface found in egress mask (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid interface found in egress mask ( egress mask bit# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid interface found in egress mask ( egress mask bit# ) log

Invalid interface found in egress mask ( egress mask bit# )

The Interface doesn't exist or is not supported.

Source	Severity
QoS	Serious

### Remedial action

Enter a different interface/port number.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Invalid interface index

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid interface index log

Invalid interface index

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid interface index data specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid interface index data specified (%d) log

Invalid interface index data specified (%d)

The interface index not in range (1-1024).

Source	Severity
QoS	Serious

### Remedial action

Check unit/stack limitations.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid interface index data specified ( ifc index )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid interface index data specified ( ifc index ) log

Invalid interface index data specified ( ifc index )

The interface index does not exist.

Source	Severity
QoS	Serious

### Remedial action

Check the port range of the platform or stack, and use a valid interface index.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid interface index data (system-owned) specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid interface index data (system-owned) specified log

Invalid interface index data (system-owned) specified

Only system-owned policies can reference system-owned interfaces.

Source	Severity
QoS	Serious

### Remedial action

Enter an interface that is not system-owned.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid IP address log

Invalid IP address

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid IP address type

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid IP address type log

Invalid IP address type

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid IP destination address prefix detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid IP destination address prefix detected log

Invalid IP destination address prefix detected

The specified destination address prefix exceeds the maximum allowed for ipv4 addresses (32).

Source	Severity
QoS	Serious

### Remedial action

Enter the correct prefix.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid IP source address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid IP source address log

Invalid IP source address

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Invalid IP source address prefix detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid IP source address prefix detected log

Invalid IP source address prefix detected

The specified source address prefix exceeds the maximum allowed for ipv4 addresses (32).

Source	Severity
QoS	Serious

### Remedial action

Enter the correct prefix.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid IS-IS circuit ID

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid IS-IS circuit ID log

Invalid IS-IS circuit ID

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid IS-IS circuit type

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid IS-IS circuit type log

Invalid IS-IS circuit type

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid key ID

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid key ID log

Invalid key ID

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid manual area address length

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid manual area address length log

Invalid manual area address length

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid master block member value specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid master block member value specified log

Invalid master block member value specified

The master block member value can only have two values: True or False.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid maximum inner VLAN ID value specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid maximum inner VLAN ID value specified (%d) log

Invalid maximum inner VLAN ID value specified (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid maximum inner VLAN ID value specified ( VLAN ID )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid maximum inner VLAN ID value specified ( VLAN ID ) log

Invalid maximum inner VLAN ID value specified ( VLAN ID )

The maximum inner VLAN ID is 4094 .

Source	Severity
QoS	Serious

### Remedial action

Specify a valid VLAN ID value.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Invalid maximum VLAN ID value specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid maximum VLAN ID value specified (%d) log

Invalid maximum VLAN ID value specified (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid maximum VLAN ID value specified ( VLAN ID )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid maximum VLAN ID value specified ( VLAN ID ) log

Invalid maximum VLAN ID value specified ( VLAN ID )

The maximum VLAN ID is 4094.

Source	Severity
QoS	Serious

### Remedial action

Specify a valid VLAN ID value.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid metering data (bucket size) specified for interface(s)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid metering data (bucket size) specified for interface(s) log

Invalid metering data (bucket size) specified for interface(s)

The current metering bucket size is not supported on the current interface.

Source	Severity
QoS	Serious

### Remedial action

Change the target interface or modify the metering bucket size.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid metering data (granularity) specified for interface(s)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid metering data (granularity) specified for interface(s) log

Invalid metering data (granularity) specified for interface(s)

The metering granularity is not supported on the current interface.

Source	Severity
QoS	Serious

### Remedial action

Change the target interface or modify the metering granularity.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid metering data (rate) specified for interface(s)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid metering data (rate) specified for interface(s) log

Invalid metering data (rate) specified for interface(s)

The metering rate is not supported on the current interface.

Source	Severity
QoS	Serious

### Remedial action

Change the target interface or modify the metering rate.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid metering data (srTCM trTCM) specified for interface(s)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid metering data (srTCM trTCM) specified for interface(s) log

Invalid metering data (srTCM trTCM) specified for interface(s)

The metering type is not supported on the current interface.

Source	Severity
QoS	Serious

### Remedial action

Change the target interface or modify the metering type.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid metering data (srTCM/trTCM) specified for interface(s)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid metering data (srTCM/trTCM) specified for interface(s) log

Invalid metering data (srTCM/trTCM) specified for interface(s)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid minimum inner VLAN ID value specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid minimum inner VLAN ID value specified (%d) log

Invalid minimum inner VLAN ID value specified (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Invalid minimum inner VLAN ID value specified ( VLAN ID )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid minimum inner VLAN ID value specified ( VLAN ID ) log

Invalid minimum inner VLAN ID value specified ( VLAN ID )

The inner VLAN ID must be greater than 1.

Source	Severity
QoS	Serious

### Remedial action

Enter an VLAN ID greater than 1.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid minimum VLAN ID value specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid minimum VLAN ID value specified (%d) log

Invalid minimum VLAN ID value specified (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid minimum VLAN ID value specified ( VLAN ID )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid minimum VLAN ID value specified ( VLAN ID ) log

Invalid minimum VLAN ID value specified ( VLAN ID )

The VLAN ID must be bigger than.

Source	Severity
QoS	Serious

### Remedial action

Enter an ID bigger than 1.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid mix of classifiers (IPv4&IPv6) in block detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid mix of classifiers (IPv4&IPv6) in block detected log

Invalid mix of classifiers (IPv4&IPv6) in block detected

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid mix of IP address data (Dst IP type) in set detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid mix of IP address data (Dst IP type) in set detected log

Invalid mix of IP address data (Dst IP type) in set detected

Different filter criteria can be specified in the same classifier but they must be compatible. Conflict(s) detected when validating Dst IP/type data.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Separate the conflicting elements into multiple classifier sets.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid mix of IP address data (Dst IP/type) in set detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid mix of IP address data (Dst IP/type) in set detected log

Invalid mix of IP address data (Dst IP/type) in set detected

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid mix of IP and non-IP data in set detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid mix of IP and non-IP data in set detected log

Invalid mix of IP and non-IP data in set detected

Even though different classifier element types can be specified in the same classifier they must be compatible. IP and non-IP data are mutually exclusive.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Separate the IP and non-IP pattern data in different classifier sets.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid mix of IP data (IPv4 IPv6) in set detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid mix of IP data (IPv4 IPv6) in set detected log

Invalid mix of IP data (IPv4 IPv6) in set detected

Different filter criteria can be specified in the same classifier but they must be compatible. IPv4 and Ipv6 data are mutually exclusive.

Source	Severity
QoS	Serious

### Remedial action

Separate the conflicting elements into multiple classifier sets.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Invalid mix of IP data (IPv4/IPv6) in set detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid mix of IP data (IPv4/IPv6) in set detected log

Invalid mix of IP data (IPv4/IPv6) in set detected

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid mix of IP type data (options/non-IP) in set detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid mix of IP type data (options/non-IP) in set detected log

Invalid mix of IP type data (options/non-IP) in set detected

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid NRAV id %d, on port %d, cannot be B-VLAN

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid NRAV id %d, on port %d, cannot be B-VLAN log

Invalid NRAV id %d, on port %d, cannot be B-VLAN

### Source    Severity

EAP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid NRAV id %d, on port %d, it isn't a SPBM VLAN

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid NRAV id %d, on port %d, it isn't a SPBM VLAN log

Invalid NRAV id %d, on port %d, it isn't a SPBM VLAN

### Source    Severity

EAP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid option specified for BcastFrames attribute

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid option specified for BcastFrames attribute log

Invalid option specified for BcastFrames attribute

BcastFrames attribute must be true or false. QPA internal error.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid option specified for KnownIpMcast attribute

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid option specified for KnownIpMcast attribute log

Invalid option specified for KnownIpMcast attribute

KnownIpMcast attribute must be true or false. QPA internal error.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid option specified for KnownMcastFrames attribute

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid option specified for KnownMcastFrames attribute log

Invalid option specified for KnownMcastFrames attribute

KnownMcastFrames attribute must be true or false. QPA internal error.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid option specified for KnownNonIpMcast attribute

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid option specified for KnownNonIpMcast attribute log

Invalid option specified for KnownNonIpMcast attribute

KnownNonIpMcast attribute must be true or false. QPA internal error.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Invalid option specified for KnownUcastFrames attribute

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid option specified for KnownUcastFrames attribute log

Invalid option specified for KnownUcastFrames attribute

KnownUcastFrames attribute must be true or false. QPA internal error.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid option specified for NonIpPkt attribute

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid option specified for NonIpPkt attribute log

Invalid option specified for NonIpPkt attribute

NonIpPkts attribute must be true or false. QPA internal error.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid option specified for PatternIpVersion attribute

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid option specified for PatternIpVersion attribute log

Invalid option specified for PatternIpVersion attribute

Valid PatternIpVersion are non-ip, ipv4, ipv6.

Source	Severity
QoS	Serious

### Remedial action

Enter a valid version or remove option.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid option specified for PatternL2Format attribute

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid option specified for PatternL2Format attribute log

Invalid option specified for PatternL2Format attribute

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid option specified for UnknownIpMcast attribute

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid option specified for UnknownIpMcast attribute log

Invalid option specified for UnknownIpMcast attribute

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid option specified for UnknownMcastFrames attribute

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid option specified for UnknownMcastFrames attribute log

Invalid option specified for UnknownMcastFrames attribute

UnknownMcastFrames attribute must be true or false. QPA internal error.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid option specified for UnknownNonIpMcast attribute

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid option specified for UnknownNonIpMcast attribute log

Invalid option specified for UnknownNonIpMcast attribute

UnknownNonIpMcast attribute must be true or false. QPA internal error.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid option specified for UnknownUcastFrames attribute

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid option specified for UnknownUcastFrames attribute log

Invalid option specified for UnknownUcastFrames attribute

UnknownUcastFrames attribute must be true or false. QPA internal error.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Invalid or inconsistent value

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid or inconsistent value log

Invalid or inconsistent value

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid parameters on egress stage (not currently supported)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid parameters on egress stage (not currently supported) log

Invalid parameters on egress stage (not currently supported)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid password

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid password log

Invalid password

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid pattern data length (untagged format) specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid pattern data length (untagged format) specified log

Invalid pattern data length (untagged format) specified

Pattern data length does not correspond with the specified data format (untagged).

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Modify the pattern data or use the correct data format.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid pattern data string length specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid pattern data string length specified log

Invalid pattern data string length specified

Patter data string length must be between 0 and 128.

Source	Severity
QoS	Serious

### Remedial action

Specify a valid length.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid pattern format data specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid pattern format data specified log

Invalid pattern format data specified

Supported formats: untagged, tagged or double tagged.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Specify a supported format data.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid pattern position string length specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid pattern position string length specified log

Invalid pattern position string length specified

Patter position string length must be between 0 and 128.

Source	Severity
QoS	Serious

### Remedial action

Specify a valid length.



# Invalid port

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid port log

Invalid port

Source	Severity
ISIS	

Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Invalid port detected in specified port mask

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid port detected in specified port mask log

Invalid port detected in specified port mask

An unknown/invalid port was detected in the specified port mask.

Source	Severity
QoS	Serious

### Remedial action

Inspect the mask and remove the invalid port(s).

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid 802.1p user priority value specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid 802.1p user priority value specified (%d) log

Invalid 802.1p user priority value specified (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid 802.1p user priority value specified ( priority value )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid 802.1p user priority value specified ( priority value ) log

Invalid 802.1p user priority value specified ( priority value )

The only valid user priorities values are between 0 and 7.

Source	Severity
QoS	Serious

### Remedial action

Specify a valid user priority.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid RAV id %d, on port %d, cannot be B-VLAN

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid RAV id %d, on port %d, cannot be B-VLAN log

Invalid RAV id %d, on port %d, cannot be B-VLAN

The VLAN received from RADIUS Server is configured as B-VLAN.

Source	Severity
EAP	Information

### Remedial action

Change the value of the VLAN assigned on the RADIUS Server.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid RAV id %d, on port %d, it isn't a SPBM VLAN

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid RAV id %d, on port %d, it isn't a SPBM VLAN log

Invalid RAV id %d, on port %d, it isn't a SPBM VLAN

**Source    Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid resetToDefaults value specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid resetToDefaults value specified log

Invalid resetToDefaults value specified

ResetToDefaults must be "true" when trying to reset the QoS agent. This also goes for the partial reset.

Source	Severity
QoS	Critical

### Remedial action

Try again later or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid RXMT LSP interval

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid RXMT LSP interval log

Invalid RXMT LSP interval

Source	Severity
ISIS	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid set drop precedence value specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid set drop precedence value specified log

Invalid set drop precedence value specified

The drop precedence can have two values, low or high.

Source	Severity
QoS	Serious

### Remedial action

Check the documentation if necessary and use a valid drop precedence value.





# Invalid shaping data (bucket size) specified for interface(s)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid shaping data (bucket size) specified for interface(s) log

Invalid shaping data (bucket size) specified for interface(s)

The shaping bucket size is not supported on the current interface.

Source	Severity
QoS	Serious

### Remedial action

Change the target interface or modify the shaping bucket size.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid shaping data (granularity) specified for interface(s)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid shaping data (granularity) specified for interface(s) log

Invalid shaping data (granularity) specified for interface(s)

The shaping granularity is not supported on the current interface.

Source	Severity
QoS	Serious

### Remedial action

Change the target interface or modify the shaping granularity.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid shaping data (minimum rate granularity) specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid shaping data (minimum rate granularity) specified log

Invalid shaping data (minimum rate granularity) specified

The minimum shaping rate granularity is invalid or not supported.

Source	Severity
QoS	Serious

### Remedial action

Modify the minimum shaping rate granularity to a valid or supported value.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid shaping data (minimum rate > maximum rate) specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid shaping data (minimum rate > maximum rate) specified log

Invalid shaping data (minimum rate > maximum rate) specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid shaping data (minimum rate maximum rate) specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid shaping data (minimum rate maximum rate) specified log

Invalid shaping data (minimum rate maximum rate) specified

The limits of the shaping rate are not in order; the minimum rate must be lesser than the maximum rate.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Change the shaping rate limits.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid shaping data (minimum rate) specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid shaping data (minimum rate) specified log

Invalid shaping data (minimum rate) specified

The minimum shaping rate is not supported on the current interface.

Source	Severity
QoS	Serious

### Remedial action

Change the target interface or modify the minimum shaping rate.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid shaping data (rate) specified for interface(s)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid shaping data (rate) specified for interface(s) log

Invalid shaping data (rate) specified for interface(s)

The shaping rate is not supported on the current interface.

Source	Severity
QoS	Serious

### Remedial action

Change the target interface or modify the shaping rate.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid source interface id

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid source interface id log

Invalid source interface id

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Invalid source interface type

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid source interface type log

Invalid source interface type

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid source MAC address length specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid source MAC address length specified log

Invalid source MAC address length specified

Source MAC address length is greater than 6.

Source	Severity
QoS	Serious

### Remedial action

Specify a valid MAC address.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid source MAC address mask length specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid source MAC address mask length specified log

Invalid source MAC address mask length specified

Source MAC address mask length is greater than 6.

Source	Severity
QoS	Serious

### Remedial action

Specify a valid MAC address mask.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid SPF delay, should be multiple of hundred

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid SPF delay, should be multiple of hundred log

Invalid SPF delay, should be multiple of hundred

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid statistics counter identification specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid statistics counter identification specified log

Invalid statistics counter identification specified

The statistics counter identifier provided is invalid.

Source	Severity
QoS	Serious

### Remedial action

Enter a valid statistics tracking identifier.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid statistics tracking value

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid statistics tracking value log

Invalid statistics tracking value

Invalid policy tracking statistics. The supported types are: individual aggregate or disabled.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Specify a supported policy tracking statistics.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid statistics type value

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid statistics type value log

Invalid statistics type value

The only valid statistics types are individual and aggregate.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Enter a valid statistics type or ignore option.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid track statistics value specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid track statistics value specified log

Invalid track statistics value specified

The only valid tracking statistics values are disabled, individual and aggregate.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Assign a valid tracking statistics value.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Invalid/unknown access assignment entry state encountered (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unknown access assignment entry state encountered (%d) log

Invalid/unknown access assignment entry state encountered (%d)

**Source**   **Severity**  
QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unknown access assignment entry state encountered ( entry state )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unknown access assignment entry state encountered ( entry state ) log

Invalid unknown access assignment entry state encountered ( entry state )

Unable to make changes because of an invalid or inconsistent state.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent, or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unknown access element entry state encountered (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unknown access element entry state encountered (%d) log

Invalid/unknown access element entry state encountered (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unknown access element entry state encountered ( entry state )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unknown access element entry state encountered ( entry state ) log

Invalid unknown access element entry state encountered ( entry state )

Unable to make any changes due to of the invalid or inconsistent state.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# Invalid/unknown action entry state encountered (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unknown action entry state encountered (%d) log

Invalid/unknown action entry state encountered (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unknown action entry state encountered ( entry state )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unknown action entry state encountered ( entry state ) log

Invalid unknown action entry state encountered ( entry state )

Unable to make changes because of an invalid/inconsistent action entry state.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unknown bandwidth type specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unknown bandwidth type specified log

Invalid unknown bandwidth type specified

Two bandwidth types are supported: absolute and relative.

Source	Severity
QoS	Serious

### Remedial action

Enter a valid bandwidth type.



# Invalid/unknown bandwidth type specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unknown bandwidth type specified log

Invalid/unknown bandwidth type specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Invalid/unknown classifier block entry state encountered (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unknown classifier block entry state encountered (%d) log

Invalid/unknown classifier block entry state encountered (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unknown classifier block entry state encountered ( entry state )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unknown classifier block entry state encountered ( entry state ) log

Invalid unknown classifier block entry state encountered ( entry state )

Unable to make changes because of an invalid/inconsistent state.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unknown CoS shaping entry state encountered (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unknown CoS shaping entry state encountered (%d) log

Invalid/unknown CoS shaping entry state encountered (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unknown CoS shaping entry state encountered ( entry state )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unknown CoS shaping entry state encountered ( entry state ) log

Invalid unknown CoS shaping entry state encountered ( entry state )

Unable to make changes because of an invalid or inconsistent state.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unknown count action entry state encountered (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unknown count action entry state encountered (%d) log

Invalid/unknown count action entry state encountered (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unknown DSCP mapping entry state encountered (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unknown DSCP mapping entry state encountered (%d) log

Invalid/unknown DSCP mapping entry state encountered (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unknown DSCP mapping entry state encountered ( entry state )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unknown DSCP mapping entry state encountered ( entry state ) log

Invalid unknown DSCP mapping entry state encountered ( entry state )

Unable to make changes because of an invalid/inconsistent DSCP mapping entry state.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# Invalid unknown entry state (class class# ) encountered ( entry state )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unknown entry state (class class# ) encountered ( entry state ) log

Invalid unknown entry state (class class# ) encountered ( entry state )

Unable to make the changes because of an invalid/inconsistent state.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent, or reset the unit.





# Invalid/unknown entry state (class %d) encountered (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unknown entry state (class %d) encountered (%d) log

Invalid/unknown entry state (class %d) encountered (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unknown FCoE redirection egress trunk ID specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unknown FCoE redirection egress trunk ID specified log

Invalid/unknown FCoE redirection egress trunk ID specified

An invalid FCoE redirection trunk ID was specified.

Source	Severity
FCoE Redirect	Information

### Remedial action

Specify a valid trunk ID.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unknown FCoE redirection entry state encountered (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unknown FCoE redirection entry state encountered (%d) log

Invalid/unknown FCoE redirection entry state encountered (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unknown interface action entry state encountered (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unknown interface action entry state encountered (%d) log

Invalid/unknown interface action entry state encountered (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unknown interface action entry state encountered ( entry state )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unknown interface action entry state encountered ( entry state ) log

Invalid unknown interface action entry state encountered ( entry state )

Unable to make changes because of an invalid state.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unknown interface app entry state encountered (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unknown interface app entry state encountered (%d) log

Invalid/unknown interface app entry state encountered (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unknown interface app entry state encountered (<entry state>)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unknown interface app entry state encountered (<entry state>) log

Invalid/unknown interface app entry state encountered (<entry state>)

Unable to make the changes because of an invalid or inconsistent state.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent, or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# Invalid/unknown interface assignment entry state encountered (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unknown interface assignment entry state encountered (%d) log

Invalid/unknown interface assignment entry state encountered (%d)

**Source**   **Severity**  
QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Invalid unknown interface assignment entry state encountered ( entry state )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unknown interface assignment entry state encountered ( entry state ) log

Invalid unknown interface assignment entry state encountered ( entry state )

Unable to make changes because of an invalid/inconsistent state.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unknown interface queue entry state encountered (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unknown interface queue entry state encountered (%d) log

Invalid/unknown interface queue entry state encountered (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unknown interface queue entry state encountered ( entry state )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unknown interface queue entry state encountered ( entry state ) log

Invalid unknown interface queue entry state encountered ( entry state )

Unable to make changes because of an invalid/inconsistent interface queue entry state.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# Invalid/unknown interface shaping entry state encountered (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unknown interface shaping entry state encountered (%d) log

Invalid/unknown interface shaping entry state encountered (%d)

**Source**   **Severity**  
QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unknown interface shaping entry state encountered ( entry# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unknown interface shaping entry state encountered ( entry# ) log

Invalid unknown interface shaping entry state encountered ( entry# )

Unable to make changes because of an invalid or inconsistent state.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unknown IP filter entry state encountered (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unknown IP filter entry state encountered (%d) log

Invalid/unknown IP filter entry state encountered (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unknown IP filter entry state encountered ( entry state )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unknown IP filter entry state encountered ( entry state ) log

Invalid unknown IP filter entry state encountered ( entry state )

Unable to make changes because of an invalid/inconsistent state.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unknown Layer 2 filter entry state encountered (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unknown Layer 2 filter entry state encountered (%d) log

Invalid/unknown Layer 2 filter entry state encountered (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Invalid unknown Layer 2 filter entry state encountered ( entry state )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unknown Layer 2 filter entry state encountered ( entry state ) log

Invalid unknown Layer 2 filter entry state encountered ( entry state )

Unable to make changes because of an invalid/inconsistent state.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unknown meter entry state encountered (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unknown meter entry state encountered (%d) log

Invalid/unknown meter entry state encountered (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unknown meter entry state encountered ( entry state )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unknown meter entry state encountered ( entry state ) log

Invalid unknown meter entry state encountered ( entry state )

Unable to make changes because of an invalid/inconsistent state.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unknown policy entry state encountered (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unknown policy entry state encountered (%d) log

Invalid/unknown policy entry state encountered (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unknown policy entry state encountered ( entry state )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unknown policy entry state encountered ( entry state ) log

Invalid unknown policy entry state encountered ( entry state )

Unable to make changes because of an invalid/inconsistent state.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unknown 802.1p user priority mapping entry state (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unknown 802.1p user priority mapping entry state (%d) log

Invalid/unknown 802.1p user priority mapping entry state (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unknown 802.1p user priority mapping entry state ( entry state )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unknown 802.1p user priority mapping entry state ( entry state ) log

Invalid unknown 802.1p user priority mapping entry state ( entry state )

Unable to make changes because of an invalid/inconsistent 802.1p user priority state.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent or reset the unit.



# Invalid/unknown queue set assignment entry state encountered (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unknown queue set assignment entry state encountered (%d) log

Invalid/unknown queue set assignment entry state encountered (%d)

Source	Severity
QoS	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Invalid unknown queue set assignment entry state encountered ( entry state )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unknown queue set assignment entry state encountered ( entry state ) log

Invalid unknown queue set assignment entry state encountered ( entry state )

Unable to make changes because of an invalid/inconsistent state.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unknown queue shaping entry state encountered (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unknown queue shaping entry state encountered (%d) log

Invalid/unknown queue shaping entry state encountered (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unknown queue shaping entry state encountered ( entry state )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unknown queue shaping entry state encountered ( entry state ) log

Invalid unknown queue shaping entry state encountered ( entry state )

Unable to make changes because of an invalid/inconsistent state.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unknown queuing discipline enum specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unknown queuing discipline enum specified (%d) log

Invalid/unknown queuing discipline enum specified (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unknown queuing discipline enum specified ( queuing discipline )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unknown queuing discipline enum specified ( queuing discipline ) log

Invalid unknown queuing discipline enum specified ( queuing discipline )

Only the following queuing disciplines are valid: FIFO, Priority Queuing, Fair Queuing, Weighted Fair Queuing and Weighted Round Robin Queuing.

Source	Severity
QoS	Critical

### Remedial action

Enter a valid/supported queuing discipline.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unknown role combination entry state encountered (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unknown role combination entry state encountered (%d) log

Invalid/unknown role combination entry state encountered (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unknown role combination entry state encountered ( entry state )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unknown role combination entry state encountered ( entry state ) log

Invalid unknown role combination entry state encountered ( entry state )

Unable to make changes because of an invalid/inconsistent role combination state.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unknown System filter entry state encountered (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unknown System filter entry state encountered (%d) log

Invalid/unknown System filter entry state encountered (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Invalid unknown System filter entry state encountered ( entry state )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unknown System filter entry state encountered ( entry state ) log

Invalid unknown System filter entry state encountered ( entry state )

Invalid entry state detected. Unable to commit changes.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent or reset the unit.



# Invalid/unknown token bucket entry state encountered (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unknown token bucket entry state encountered (%d) log

Invalid/unknown token bucket entry state encountered (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unknown token bucket entry state encountered ( entry state )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unknown token bucket entry state encountered ( entry state ) log

Invalid unknown token bucket entry state encountered ( entry state )

Unable to make changes because of an invalid/inconsistent state.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unknown user policy entry state encountered (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unknown user policy entry state encountered (%d) log

Invalid/unknown user policy entry state encountered (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unknown user policy entry state encountered ( entry state )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unknown user policy entry state encountered ( entry state ) log

Invalid unknown user policy entry state encountered ( entry state )

Unable to make the changes because of an invalid or inconsistent state.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent, or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unsupported AutoQoS mode value specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported AutoQoS mode value specified log

Invalid/unsupported AutoQoS mode value specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unsupported buffering capabilities value specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unsupported buffering capabilities value specified log

Invalid unsupported buffering capabilities value specified

The buffering capabilities are not supported.

Source	Severity
QoS	Serious

### Remedial action

Check platform documentation and use a compatible buffering setting.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unsupported buffering capabilities value specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported buffering capabilities value specified log

Invalid/unsupported buffering capabilities value specified

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Invalid/unsupported classifier allocation mode specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported classifier allocation mode specified log

Invalid/unsupported classifier allocation mode specified

The allocation mode used is unknown or unsupported..

Source	Severity
QoS	Serious

### Remedial action

Use a supported attribute for that QoS class.



# Invalid/unsupported classifier meter type specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported classifier meter type specified log

Invalid/unsupported classifier meter type specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unsupported copy-to-cpu option specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unsupported copy-to-cpu option specified log

Invalid unsupported copy-to-cpu option specified

The copy-to-CPU can have two values, true or false. It's possible that the only supported value for the target entry is false.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Check the documentation if necessary and use a valid copy-to-CPU option.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unsupported copy-to-cpu option specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported copy-to-cpu option specified log

Invalid/unsupported copy-to-cpu option specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unsupported DAPP enable value specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unsupported DAPP enable value specified log

Invalid unsupported DAPP enable value specified

DAAP can be enabled with or without status.

Source	Severity
QoS	Serious

### Remedial action

Specify a valid enable value or disable DAAP.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unsupported DAPP enable value specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported DAPP enable value specified log

Invalid/unsupported DAPP enable value specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unsupported DAPP maximum IPv4 ICMP length specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unsupported DAPP maximum IPv4 ICMP length specified log

Invalid unsupported DAPP maximum IPv4 ICMP length specified

The maximum IPv4 ICMP length must be between 0 and 1023.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Enter a valid/supported length in that range.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unsupported DAPP maximum IPv6 ICMP length specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unsupported DAPP maximum IPv6 ICMP length specified log

Invalid unsupported DAPP maximum IPv6 ICMP length specified

The maximum Ipv6 ICMP length must be between 0 and 16383.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Enter a valid/supported length in that range.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Invalid/unsupported DAPP maximum IPv4 ICMP length specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported DAPP maximum IPv4 ICMP length specified log

Invalid/unsupported DAPP maximum IPv4 ICMP length specified

**Source**   **Severity**  
QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unsupported DAPP maximum IPv6 ICMP length specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported DAPP maximum IPv6 ICMP length specified log

Invalid/unsupported DAPP maximum IPv6 ICMP length specified

**Source**   **Severity**  
QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unsupported DAPP minimum TCP header length specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unsupported DAPP minimum TCP header length specified log

Invalid unsupported DAPP minimum TCP header length specified

The minimum TCP header length must be within 0 to 255.

Source	Severity
QoS	Serious

### Remedial action

Enter a valid/supported length in the specified range.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unsupported DAPP minimum TCP header length specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported DAPP minimum TCP header length specified log

Invalid/unsupported DAPP minimum TCP header length specified

**Source**   **Severity**  
QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unsupported default gateway address length specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unsupported default gateway address length specified log

Invalid unsupported default gateway address length specified

The default gateway address length must be 4 (IPv4) and 16 (IPv6).

Source	Severity
QoS	Serious

### Remedial action

Specify a valid default gateway address length.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unsupported default gateway address length specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported default gateway address length specified log

Invalid/unsupported default gateway address length specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unsupported default gateway address specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unsupported default gateway address specified log

Invalid unsupported default gateway address specified

The default gateway provided is not a valid interface application IP address.

Source	Severity
QoS	Serious

### Remedial action

Specify a valid IP default gateway address.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unsupported default gateway address specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported default gateway address specified log

Invalid/unsupported default gateway address specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Invalid unsupported destination IP address length specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unsupported destination IP address length specified log

Invalid unsupported destination IP address length specified

Destination address is too short/long.

Source	Severity
QoS	Serious

### Remedial action

Enter a proper address with length 4 (ipv4) or 16 (ipv6).

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unsupported destination IP address length specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported destination IP address length specified log

Invalid/unsupported destination IP address length specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unsupported DHCP server address length specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unsupported DHCP server address length specified log

Invalid unsupported DHCP server address length specified

The DHCP server address length must be 4 (IPv4) and 16 (IPv6).

Source	Severity
QoS	Serious

### Remedial action

Specify a valid DHCP server address length.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unsupported DHCP server address length specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported DHCP server address length specified log

Invalid/unsupported DHCP server address length specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unsupported DHCP server address specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unsupported DHCP server address specified log

Invalid unsupported DHCP server address specified

The DHCP address provided is not a valid interface application IP address.

Source	Severity
QoS	Serious

### Remedial action

Specify a valid IP DHCP server address.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unsupported DHCP server address specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported DHCP server address specified log

Invalid/unsupported DHCP server address specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unsupported FCoE accessibility mode value specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported FCoE accessibility mode value specified log

Invalid/unsupported FCoE accessibility mode value specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unsupported FCoE ingress interface list specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported FCoE ingress interface list specified log

Invalid/unsupported FCoE ingress interface list specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Invalid/unsupported FCoE redirection egress interface specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported FCoE redirection egress interface specified log

Invalid/unsupported FCoE redirection egress interface specified

**Source**   **Severity**  
QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unsupported FCoE redirection etherType detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported FCoE redirection etherType detected log

Invalid/unsupported FCoE redirection etherType detected

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unsupported FCoE redirection mode value specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported FCoE redirection mode value specified log

Invalid/unsupported FCoE redirection mode value specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unsupported interface type specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unsupported interface type specified log

Invalid unsupported interface type specified

The valid interface types for the interface applications are access and core.

Source	Severity
QoS	Serious

### Remedial action

Enter one of the valid interface types.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unsupported interface type specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported interface type specified log

Invalid/unsupported interface type specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unsupported IP address/mask length specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported IP address/mask length specified log

Invalid/unsupported IP address/mask length specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unsupported metering mode value specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported metering mode value specified log

Invalid/unsupported metering mode value specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unsupported mirror frame option specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unsupported mirror frame option specified log

Invalid unsupported mirror frame option specified

The mirror frame option can have two values, true or false. It's possible that the only supported value for the target entry is false.

Source	Severity
QoS	Serious

### Remedial action

Check the documentation if necessary and use a valid mirror frame option.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Invalid/unsupported mirror frame option specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported mirror frame option specified log

Invalid/unsupported mirror frame option specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unsupported NT application mode value specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unsupported NT application mode value specified log

Invalid unsupported NT application mode value specified

The only supported AutoQoS modes are disabled, pure and mixed.

Source	Severity
QoS	Serious

### Remedial action

The only supported AutoQoS modes are disabled, pure and mixed.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unsupported packet type value specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unsupported packet type value specified log

Invalid unsupported packet type value specified

Invalid value specified. Packet-types supported: etherII, llc, snap.

Source	Severity
QoS	Serious

### Remedial action

Specify a supported packet type.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unsupported packet type value specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported packet type value specified log

Invalid/unsupported packet type value specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unsupported QoS system operational mode value specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unsupported QoS system operational mode value specified log

Invalid unsupported QoS system operational mode value specified

If the current platforms supports QoS system disabled state then the operational mode can be either disabled or enabled. Otherwise the QoS system operational mode can only be enabled.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Specify a supported QoS operational mode regarding the current platform.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# Invalid/unsupported QoS system operational mode value specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported QoS system operational mode value specified log

Invalid/unsupported QoS system operational mode value specified

**Source**   **Severity**  
QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unsupported queue configuration value specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unsupported queue configuration value specified log

Invalid unsupported queue configuration value specified

The queue set value must be between 1 and 8.

Source	Severity
QoS	Serious

### Remedial action

Specify a queue set value in the range described.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unsupported queue configuration value specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported queue configuration value specified log

Invalid/unsupported queue configuration value specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Invalid unsupported role assoc compatibility specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unsupported role assoc compatibility specified log

Invalid unsupported role assoc compatibility specified

The supported role association are loose and strict.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Specify a supported/valid role association.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unsupported role assoc compatibility specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported role assoc compatibility specified log

Invalid/unsupported role assoc compatibility specified

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unsupported source IP address length specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unsupported source IP address length specified log

Invalid unsupported source IP address length specified

Source address is too short/long.

Source	Severity
QoS	Serious

### Remedial action

Enter a proper address with length 4 (ipv4) or 16 (ipv6).

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unsupported source IP address length specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported source IP address length specified log

Invalid/unsupported source IP address length specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unsupported stage specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported stage specified log

Invalid/unsupported stage specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unsupported Trusted processing mode value specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unsupported Trusted processing mode value specified log

Invalid unsupported Trusted processing mode value specified

Trusted processing modes can be partial or full. Any other modes are invalid or unsupported.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Specify a valid trusted processing mode.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unsupported Trusted processing mode value specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported Trusted processing mode value specified log

Invalid/unsupported Trusted processing mode value specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unsupported UBP support level value specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unsupported UBP support level value specified log

Invalid unsupported UBP support level value specified

There are 4 user based policies levels supported, the first one being "disabled".

Source	Severity
QoS	Serious

### Remedial action

Enter a valid user based policy support.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Invalid/unsupported UBP support level value specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported UBP support level value specified log

Invalid/unsupported UBP support level value specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid/unsupported VLAN tag value specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid/unsupported VLAN tag value specified (%d) log

Invalid/unsupported VLAN tag value specified (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid unsupported VLAN tag value specified ( VLAN tag )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid unsupported VLAN tag value specified ( VLAN tag ) log

Invalid unsupported VLAN tag value specified ( VLAN tag )

Invalid VLAN tag, it must be tagged, untagged or not specified (ignore).

Source	Severity
QoS	Serious

### Remedial action

Enter an appropriate VLAN tag (tagged, untagged or ignore).

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid update DSCP value specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid update DSCP value specified (%d) log

Invalid update DSCP value specified (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid update DSCP value specified ( DSCP value )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid update DSCP value specified ( DSCP value ) log

Invalid update DSCP value specified ( DSCP value )

The valid DSCP values are between 0 and 63.

Source	Severity
QoS	Information

### Remedial action

Enter a valid DSCP value (in the specified range).

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid update DSCP value specified (not currently supported)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid update DSCP value specified (not currently supported) log

Invalid update DSCP value specified (not currently supported)

The specified update DSCP value is currently not supported.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Check the documentation if necessary and use a supported update DSCP value.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid update priority value specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid update priority value specified log

Invalid update priority value specified

The only valid update priorities values are between 0 and 7.

Source	Severity
QoS	Serious

### Remedial action

Enter a valid update priority value.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid update VLAN Id specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid update VLAN Id specified (%d) log

Invalid update VLAN Id specified (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Invalid update VLAN Id specified ( VLAN Id )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid update VLAN Id specified ( VLAN Id ) log

Invalid update VLAN Id specified ( VLAN Id )

The update VLAN Id must be between 1 and 4094.

Source	Severity
QoS	Serious

### Remedial action

Enter a valid update VLAN Id in that range.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid user priority match selection specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid user priority match selection specified (%d) log

Invalid user priority match selection specified (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid user priority match selection specified ( priority value )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid user priority match selection specified ( priority value ) log

Invalid user priority match selection specified ( priority value )

The user priority value must be between 0 and 7 or all.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Enter a valid user priority value.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Invalid VLAN ID

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Invalid VLAN ID log

Invalid VLAN ID

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



IP blocking now %d (1=ON,2=OFF).

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IP blocking now %d (1=ON,2=OFF). log

IP blocking now %d (1=ON,2=OFF).

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



## IP blocking now 1 2 (1=ON 2=OFF)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

### IP blocking now 1 2 (1=ON 2=OFF) log

IP blocking now 1 2 (1=ON 2=OFF)

The IP status is blocked on the unit when it leaves a stack.

Source	Severity
L3Mgr	Information

#### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IP classifier distribution across stack failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IP classifier distribution across stack failed log

IP classifier distribution across stack failed

Unable to commit changes across the stack.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IP classifier entry still referenced (deletion prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IP classifier entry still referenced (deletion prohibited) log

IP classifier entry still referenced (deletion prohibited)

Cannot delete an ip classifier element if it's referenced in a classifier.

Source	Severity
QoS	Serious

### Remedial action

Remove the classifier first.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IP classifier modifications not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IP classifier modifications not supported log

IP classifier modifications not supported

The system detected an internal error; The specified modifier option not supported.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IP destination address and mask values out-of-sync

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IP destination address and mask values out-of-sync log

IP destination address and mask values out-of-sync

The destination address and prefix do not correspond (at least one address bit not included in mask is set).

Source	Severity
QoS	Serious

### Remedial action

Modify the address or mask.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IP destination Layer 4 port maximum value out-of-range (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IP destination Layer 4 port maximum value out-of-range (%d) log

IP destination Layer 4 port maximum value out-of-range (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IP destination Layer 4 port maximum value out-of-range ( dest port#

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IP destination Layer 4 port maximum value out-of-range ( dest port# log

IP destination Layer 4 port maximum value out-of-range ( dest port#

The maximum IP protocol destination port value must be between 0 and 65535.

Source	Severity
QoS	Serious

### Remedial action

Enter a valid maximum IP protocol destination port in the range specified.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IP destination Layer 4 port minimum value out-of-range (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IP destination Layer 4 port minimum value out-of-range (%d) log

IP destination Layer 4 port minimum value out-of-range (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IP destination Layer 4 port minimum value out-of-range ( dest port# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IP destination Layer 4 port minimum value out-of-range ( dest port# ) log

IP destination Layer 4 port minimum value out-of-range ( dest port# )

The minimum IP protocol destination port value must be between 0 and 65535.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Enter a valid minimum IP protocol destination port in the range specified.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPFIX: disable failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPFIX: disable failure log

IPFIX: disable failure

**Source**   **Severity**

IPFIX

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPFIX: enable fail since NSNA enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPFIX: enable fail since NSNA enabled log

IPFIX: enable fail since NSNA enabled

**Source**   **Severity**

IPFIX

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IPFIX enable failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPFIX enable failure log

IPFIX enable failure

This message indicates that the task cannot start.

Source	Severity
IPFIX	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPFIX: enable failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPFIX: enable failure log

IPFIX: enable failure

**Source**   **Severity**

IPFIX

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPFIX: enable failure due to invalid license

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPFIX: enable failure due to invalid license log

IPFIX: enable failure due to invalid license

**Source**   **Severity**

IPFIX

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPFIX: error setting observation port

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPFIX: error setting observation port log

IPFIX: error setting observation port

**Source**   **Severity**

IPFIX

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPFIX: init info failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPFIX: init info failure log

IPFIX: init info failure

**Source**   **Severity**

IPFIX

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPFIX: malloc failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPFIX: malloc failure log

IPFIX: malloc failure

**Source**   **Severity**

IPFIX

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPFIX: msgQSend failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPFIX: msgQSend failure log

IPFIX: msgQSend failure

**Source**   **Severity**

IPFIX

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPFIX: port %d/%d is NNI. IPFIX is disabled on NNI ports

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPFIX: port %d/%d is NNI. IPFIX is disabled on NNI ports log

IPFIX: port %d/%d is NNI. IPFIX is disabled on NNI ports

### Source    Severity

IPFIX

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IPFIX: port %d is NNI. IPFIX is disabled on NNI ports

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPFIX: port %d is NNI. IPFIX is disabled on NNI ports log

IPFIX: port %d is NNI. IPFIX is disabled on NNI ports

### Source    Severity

IPFIX

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPFIX: queue create failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPFIX: queue create failure log

IPFIX: queue create failure

**Source**   **Severity**

IPFIX

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPFIX: read from nvram failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPFIX: read from nvram failed log

IPFIX: read from nvram failed

**Source**   **Severity**

IPFIX

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPFIX: semaphore create failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPFIX: semaphore create failure log

IPFIX: semaphore create failure

**Source**   **Severity**

IPFIX

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPFIX: semTake failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPFIX: semTake failure log

IPFIX: semTake failure

**Source**   **Severity**

IPFIX

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPFIX: socket failure error=%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPFIX: socket failure error=%d log

IPFIX: socket failure error=%d

**Source**   **Severity**

IPFIX

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPFIX: task spawn failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPFIX: task spawn failure log

IPFIX: task spawn failure

**Source**   **Severity**

IPFIX

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPFIX: timer cancel failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPFIX: timer cancel failure log

IPFIX: timer cancel failure

**Source**   **Severity**

IPFIX

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IPFIX: timer create failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPFIX: timer create failure log

IPFIX: timer create failure

**Source**   **Severity**

IPFIX

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPFIX: timer set failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPFIX: timer set failure log

IPFIX: timer set failure

**Source**   **Severity**

IPFIX

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPFIX: too many entries requested

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPFIX: too many entries requested log

IPFIX: too many entries requested

**Source**   **Severity**

IPFIX

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPFIX: write to nvram failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPFIX: write to nvram failed log

IPFIX: write to nvram failed

**Source**   **Severity**

IPFIX

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IpFwdNhop Err Filter Install mod\_inst=0x%08x vid=%d rv=%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IpFwdNhop Err Filter Install mod\_inst=0x%08x vid=%d rv=%d log

IpFwdNhop Err Filter Install mod\_inst=0x%08x vid=%d rv=%d

Error when installing policy based routing filter in hardware.

Source	Severity
Source Based Routing	Information

### Remedial action

No action required.



# IpFwdNhop Err Filter Modify mod\_inst=0x%08x vid=%d rv=%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IpFwdNhop Err Filter Modify mod\_inst=0x%08x vid=%d rv=%d log

IpFwdNhop Err Filter Modify mod\_inst=0x%08x vid=%d rv=%d

Error when modifying policy based routing filter in hardware.

Source	Severity
Source Based Routing	Information

### Remedial action

No action required.



# IpFwdNhop Err Filter UnInstall mod\_inst=0x%08x vid=%d rv=%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IpFwdNhop Err Filter UnInstall mod\_inst=0x%08x vid=%d rv=%d log

IpFwdNhop Err Filter UnInstall mod\_inst=0x%08x vid=%d rv=%d

Error when uninstalling policy based routing filter in hardware.

Source	Severity
Source Based Routing	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



IpFwdNhop Err Get NxtHopId  
mod\_inst=0x%08x vid=%d  
nhop=0x%08x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IpFwdNhop Err Get NxtHopId mod\_inst=0x%08x vid=%d nhop=0x%08x log

IpFwdNhop Err Get NxtHopId mod\_inst=0x%08x vid=%d nhop=0x%08x

**Source    Severity**

SBR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IpFwdNhop Err Save DB to NVRAM General File myMod=%d isBU=%d rw=%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IpFwdNhop Err Save DB to NVRAM General File myMod=%d isBU=%d rw=%d log

IpFwdNhop Err Save DB to NVRAM General File myMod=%d isBU=%d rw=%d

Error when saving global SBR settings to NVRAM.

### Source

Source Based Routing

### Severity

Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IpFwdNhop Err Save DB to NVRAM Instance File myMod=%d isBU=%d rw=%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IpFwdNhop Err Save DB to NVRAM Instance File myMod=%d isBU=%d rw=%d log

IpFwdNhop Err Save DB to NVRAM Instance File myMod=%d isBU=%d rw=%d

Error when saving SBR instances to NVRAM.

Source	Severity
Source Based Routing	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IpFwdNhop Err Save DB to NVRAM Policy File myMod=%d isBU=%d rw=%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IpFwdNhop Err Save DB to NVRAM Policy File myMod=%d isBU=%d rw=%d log

IpFwdNhop Err Save DB to NVRAM Policy File myMod=%d isBU=%d rw=%d

Error when saving SBR policies to NVRAM.

### Source

Source Based Routing

### Severity

Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IpFwdNhop Err Unknown

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IpFwdNhop Err Unknown log

IpFwdNhop Err Unknown

**Source**   **Severity**

SBR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IpFwdNhop: Feature enable temporarily blocked - resources unavailable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IpFwdNhop: Feature enable temporarily blocked - resources unavailable log

IpFwdNhop: Feature enable temporarily blocked - resources unavailable

Indicates that the required resources for enabling the SBR feature are not available.

### Source

Source Based Routing

### Severity

Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IpFwdNhop: Filter installation issue - resources unavailable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IpFwdNhop: Filter installation issue - resources unavailable log

IpFwdNhop: Filter installation issue - resources unavailable

Error when installing policy based routing filter in hardware.

Source	Severity
Source Based Routing	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IpFwdNhop: Invalid/inconsistent VLAN admin status specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IpFwdNhop: Invalid/inconsistent VLAN admin status specified log

IpFwdNhop: Invalid/inconsistent VLAN admin status specified

**Source    Severity**

SBR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IpFwdNhop: Issue detected during data restore (interface entry %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IpFwdNhop: Issue detected during data restore (interface entry %d) log

IpFwdNhop: Issue detected during data restore (interface entry %d)

Indicates an error when try to install filters for attached policies after boot.

### Source

Source Based Routing

### Severity

Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IpFwdNhop: Issue detected during enable retry (interface entry %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IpFwdNhop: Issue detected during enable retry (interface entry %d) log

IpFwdNhop: Issue detected during enable retry (interface entry %d)

Indicates an error when try to install filters for instances missing them.

### Source

Source Based Routing

### Severity

Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IpFwdNhop: Issue detected during feature enable (interface entry %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IpFwdNhop: Issue detected during feature enable (interface entry %d) log

IpFwdNhop: Issue detected during feature enable (interface entry %d)

Indicates an error when enabling the SBR feature globally (failed installing filter).

### Source

Source Based Routing

### Severity

Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IpFwdNhop: Issue detected during interface creation (interface entry %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IpFwdNhop: Issue detected during interface creation (interface entry %d) log

IpFwdNhop: Issue detected during interface creation (interface entry %d)

When create interface event is processed, this indicates a failure when installing the filter for SBR policy.

Source	Severity
Source Based Routing	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IpFwdNhop: Issue detected during VLAN admin status enable (VID %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IpFwdNhop: Issue detected during VLAN admin status enable (VID %d) log

IpFwdNhop: Issue detected during VLAN admin status enable (VID %d)

**Source    Severity**

SBR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IpFwdNhop: Issue detected during VLAN %d routing status update

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IpFwdNhop: Issue detected during VLAN %d routing status update log

IpFwdNhop: Issue detected during VLAN %d routing status update

When ip routing enable (per VLAN interface) event is processed, this Indicates a failure when installing the filter for SBR policy.

### Source

Source Based Routing

### Severity

Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IpFwdNhop: Issue detected during VLAN membership addition (VID %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IpFwdNhop: Issue detected during VLAN membership addition (VID %d) log

IpFwdNhop: Issue detected during VLAN membership addition (VID %d)

Indicates an error when adding a port to an installed ip-fwd policy.

### Source

Source Based Routing

### Severity

Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IpFwdNhop: Issue detected during VLAN membership deletion (VID %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IpFwdNhop: Issue detected during VLAN membership deletion (VID %d) log

IpFwdNhop: Issue detected during VLAN membership deletion (VID %d)

Indicates an error when deleting a port from an installed ip-fwd policy.

### Source

Source Based Routing

### Severity

Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IpFwdNhop: Issue detected during VLAN policy association (entry %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IpFwdNhop: Issue detected during VLAN policy association (entry %d) log

IpFwdNhop: Issue detected during VLAN policy association (entry %d)

Indicates an error when attaching a SBR policy to a VLAN (failed installing filter).

Source	Severity
Source Based Routing	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IpFwdNhop: Requested precedence and/or filter resources unavailable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IpFwdNhop: Requested precedence and/or filter resources unavailable log

IpFwdNhop: Requested precedence and/or filter resources unavailable

Indicates that no valid precedence values are available.

### Source

Source Based Routing

### Severity

Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IpFwdNhop: Requested range checking resources unavailable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IpFwdNhop: Requested range checking resources unavailable log

IpFwdNhop: Requested range checking resources unavailable

Indicates that range check resources are not available.

Source	Severity
Source Based Routing	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IpFwdNhop: VLAN %d admin status enable failure - resources unavailable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IpFwdNhop: VLAN %d admin status enable failure - resources unavailable log

IpFwdNhop: VLAN %d admin status enable failure - resources unavailable

Source	Severity
SBR	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IpFwdNhop: VLAN membership update (VID %d) issue - resources unavailable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IpFwdNhop: VLAN membership update (VID %d) issue - resources unavailable log

IpFwdNhop: VLAN membership update (VID %d) issue - resources unavailable

When a VLAN membership update event is processed, this indicates that the required resources for port addition are not available.

Source	Severity
Source Based Routing	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IP protocol value out-of-range (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IP protocol value out-of-range (%d) log

IP protocol value out-of-range (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IP protocol value out-of-range ( IP protocol# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IP protocol value out-of-range ( IP protocol# ) log

IP protocol value out-of-range ( IP protocol# )

The IP protocol must be between 0 and 255.

Source	Severity
QoS	Serious

### Remedial action

Enter a valid IP protocol value.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IP protocol value TCP or UDP needed with Layer 4 port filtering

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IP protocol value TCP or UDP needed with Layer 4 port filtering log

IP protocol value TCP or UDP needed with Layer 4 port filtering

Port filtering can only be used with TCP or UDP protocols.

Source	Severity
QoS	Information

### Remedial action

Specify the IP protocol to avoid any confusions.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



IPSEC - Packet dropped:

lAddr: %d.%d.%d.%d

rAddr: %d.%d.%d.%d Src Port: %d Dest

Port: %d Protocol: %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPSEC - Packet dropped: lAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d Src Port:%d Dest Port:%d Protocol:%d log

IPSEC - Packet dropped: lAddr:%d.%d.%d.%d rAddr:%d.%d.%d.%d Src Port:%d Dest Port:%d Protocol:%d

**Source    Severity**

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





IPSEC - Packet dropped:

IAddr: %04x: %04x: %04x: %04x: %04x: %04x: %04x: %04x  
rAddr: %04x: %04x: %04x: %04x: %04x: %04x: %04x: %04x: %04x  
Src Port: %d Dest Port: %d Protocol: %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPSEC - Packet dropped: IAddr:%04x:%04x:%04x:%04x:%04x:%04x:%04x:%04x rAddr:%04x:%04x:%04x:%04x:%04x:%04x:%04x:%04x Src Port:%d Dest Port:%d Protocol:%d log

IPSEC - Packet dropped: IAddr:%04x:%04x:%04x:%04x:%04x:%04x:%04x:%04x rAddr:%04x:%04x:%04x:%04x:%04x:%04x:%04x:%04x Src Port:%d Dest Port:%d Protocol:%d

**Source**   **Severity**

IPSEC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPSG: Admin Cmd Event Error %x %x %x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPSG: Admin Cmd Event Error %x %x %x log

IPSG: Admin Cmd Event Error %x %x %x

**Source**   **Severity**

IPSG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPSG: Db exchange %d %d 0x%x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPSG: Db exchange %d %d 0x%x log

IPSG: Db exchange %d %d 0x%x

**Source    Severity**

IPSG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPSG: Debug %d %d 0x%x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPSG: Debug %d %d 0x%x log

IPSG: Debug %d %d 0x%x

**Source    Severity**

IPSG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPSG: DHCP Event Error %x %x %x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPSG: DHCP Event Error %x %x %x log

IPSG: DHCP Event Error %x %x %x

**Source**   **Severity**

IPSG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPSG: Fatal Error %d %d %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPSG: Fatal Error %d %d %d log

IPSG: Fatal Error %d %d %d

**Source**   **Severity**

IPSG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPSG: IMC Error %d %d 0x%x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPSG: IMC Error %d %d 0x%x log

IPSG: IMC Error %d %d 0x%x

**Source    Severity**

IPSG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPSG: Insufficient resources available to enable IPSG on port %d/%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPSG: Insufficient resources available to enable IPSG on port %d/%d log

IPSG: Insufficient resources available to enable IPSG on port %d/%d

Source	Severity
SNMP	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IPSG Insufficient resources available to enable IPSG on port unit# port#

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPSG Insufficient resources available to enable IPSG on port unit# port# log

IPSG Insufficient resources available to enable IPSG on port unit# port#

There are not enough resources available to enable the IPSG on the specified port.

Source	Severity
ipsg	Information

### Remedial action

Verify Qos masks and filter usage using the command:

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPSG: Invalid Stack Event %d %d %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPSG: Invalid Stack Event %d %d %d log

IPSG: Invalid Stack Event %d %d %d

**Source**   **Severity**

IPSG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPSG: Join Stack %d %d 0x%x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPSG: Join Stack %d %d 0x%x log

IPSG: Join Stack %d %d 0x%x

**Source**   **Severity**

IPSG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPSG: Leave Stack %d %d 0x%x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPSG: Leave Stack %d %d 0x%x log

IPSG: Leave Stack %d %d 0x%x

**Source    Severity**

IPSG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPSG: Log End

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPSG: Log End log

IPSG: Log End

**Source   Severity**

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPSG: Log Start

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPSG: Log Start log

IPSG: Log Start

**Source**   **Severity**

IPSG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPSG: Maximum IP entries on port %d/%d has been reached

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPSG: Maximum IP entries on port %d/%d has been reached log

IPSG: Maximum IP entries on port %d/%d has been reached

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPSG Maximum IP entries on port unit# port# has been reached

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPSG Maximum IP entries on port unit# port# has been reached log

IPSG Maximum IP entries on port unit# port# has been reached

Maximum IP entries on port has been reached.

Source	Severity
IPSG	Information

### Remedial action

Scale down the number of IP entries on port.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IPSG: Message Queue Rcv Error %d %d %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPSG: Message Queue Rcv Error %d %d %d log

IPSG: Message Queue Rcv Error %d %d %d

**Source**   **Severity**

IPSG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPSG: Message Queue Send Error %d %d %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPSG: Message Queue Send Error %d %d %d log

IPSG: Message Queue Send Error %d %d %d

**Source**   **Severity**

IPSG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPSG: nvRam file error: %d %d %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPSG: nvRam file error: %d %d %d log

IPSG: nvRam file error: %d %d %d

Source	Severity
--------	----------

IPSG	
------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPSG nvRam file error param1 param2 param3

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPSG nvRam file error param1 param2 param3 log

IPSG nvRam file error param1 param2 param3

The system detected an error while trying to access the IPSG NVRAM file param1=0 (open error), param1=1 (write error), param1=2 (read error).

Source	Severity
ipsg	Information

### Remedial action

Retry again and if it fails, then reboot the switch.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPSG: Reached Max. IP entries supported on this port %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPSG: Reached Max. IP entries supported on this port %d log

IPSG: Reached Max. IP entries supported on this port %d

**Source    Severity**

IPSG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPSG Reached Max. IP entries supported on this port port#

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPSG Reached Max. IP entries supported on this port port# log

IPSG Reached Max. IP entries supported on this port port#

The port reached the maximum number of IP entries.

Source	Severity
ipsg	Information

### Remedial action

Scale down the number of IPSG clients.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPSG Reached Max. IP entries supported on this port unit# port#

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPSG Reached Max. IP entries supported on this port unit# port# log

IPSG Reached Max. IP entries supported on this port unit# port#

The unit/port reached the maximum number of IP entries.

Source	Severity
ipsg	Information

### Remedial action

Scale down the number of IPSG clients.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPSG: Reached Max. IP entries supported on this port %x/%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPSG: Reached Max. IP entries supported on this port %x/%d log

IPSG: Reached Max. IP entries supported on this port %x/%d

**Source    Severity**

IPSG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IPSG Resource allocated for Ports unit# port#

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPSG Resource allocated for Ports unit# port# log

IPSG Resource allocated for Ports unit# port#

The resources necessary for the specified ports cannot be allocated by the QoS application.

Source	Severity
ipsg	Information

### Remedial action

Retry and if it fails, then reboot the switch.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPSG: Resource allocated for Ports %x %x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPSG: Resource allocated for Ports %x %x log

IPSG: Resource allocated for Ports %x %x

**Source**   **Severity**

IPSG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPSG: Unit %d leave stack %d 0x%x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPSG: Unit %d leave stack %d 0x%x log

IPSG: Unit %d leave stack %d 0x%x

**Source    Severity**

IPSG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IP source address and mask values out-of-sync

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IP source address and mask values out-of-sync log

IP source address and mask values out-of-sync

The source address and prefix do not correspond (at least one bit not included in mask is set).

Source	Severity
QoS	Serious

### Remedial action

Modify the address or mask.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IP source address must be configured before enable IP SC

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IP source address must be configured before enable IP SC log

IP source address must be configured before enable IP SC

**Source   Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IP Source Guard disabled on Unit %d Port %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IP Source Guard disabled on Unit %d Port %d log

IP Source Guard disabled on Unit %d Port %d

**Source    Severity**

IPSG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IP Source Guard disabled on Unit unit# Port port#

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IP Source Guard disabled on Unit unit# Port port# log

IP Source Guard disabled on Unit unit# Port port#

The IP Source Guard has been disabled on the specified Unit Port.

Source	Severity
ipsg	Information

### Remedial action

No action required.



# IP Source Guard enabled on Unit %d Port %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IP Source Guard enabled on Unit %d Port %d log

IP Source Guard enabled on Unit %d Port %d

**Source    Severity**

IPSG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IP Source Guard enabled on Unit unit# Port port#

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IP Source Guard enabled on Unit unit# Port port# log

IP Source Guard enabled on Unit unit# Port port#

The IP Source Guard has been enabled on the specified Unit Port.

Source	Severity
ipsg	Information

### Remedial action

No action required.



# IP source Layer 4 port maximum value out-of-range (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IP source Layer 4 port maximum value out-of-range (%d) log

IP source Layer 4 port maximum value out-of-range (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IP source Layer 4 port minimum value out-of-range (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IP source Layer 4 port minimum value out-of-range (%d) log

IP source Layer 4 port minimum value out-of-range (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IP source Layer 4 port minimum value out-of-range ( src port# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IP source Layer 4 port minimum value out-of-range ( src port# ) log

IP source Layer 4 port minimum value out-of-range ( src port# )

The minimum IP protocol source port value must be between 0 and 65535.

Source	Severity
QoS	Serious

### Remedial action

Enter a valid minimum IP protocol source port in the range specified.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPT BootP Disabled (response not received from server)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPT BootP Disabled (response not received from server) log

IPT BootP Disabled (response not received from server)

This message appears when the BootP mode is disabled after the stack is reset and for 10 minutes no BootP/DHCP messages are received (DUT stops sending BootP Requests).

Source	Severity
--------	----------

IPT	Information
-----	-------------

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPT: BootP Disabled (response not received from server)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPT: BootP Disabled (response not received from server) log

IPT: BootP Disabled (response not received from server)

**Source    Severity**

IPT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPT: error: %s line %d %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPT: error: %s line %d %d log

IPT: error: %s line %d %d

Source	Severity
--------	----------

IPT	
-----	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPT: info: %s arg1 %d arg2 %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPT: info: %s arg1 %d arg2 %d log

IPT: info: %s arg1 %d arg2 %d

Source	Severity
--------	----------

IPT	
-----	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IPT IP Address changed by BOOTP Server

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPT IP Address changed by BOOTP Server log

IPT IP Address changed by BOOTP Server

The switch or the stack has received the IP address from the BOOTP Server.

Source	Severity
IPT	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPT: IP Address changed by BOOTP Server

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPT: IP Address changed by BOOTP Server log

IPT: IP Address changed by BOOTP Server

**Source    Severity**

IPT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPT: IP Address changed by DHCP Server

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPT: IP Address changed by DHCP Server log

IPT: IP Address changed by DHCP Server

**Source    Severity**

IPT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPT: IP Address not in use (duplicate detected)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPT: IP Address not in use (duplicate detected) log

IPT: IP Address not in use (duplicate detected)

The IP address configured on the management VLAN was also found configured on another unit in the network.

Source	Severity
Inband IP address	Information

### Remedial action

Use different IP addresses.



# IPT: Join Mac Add: inStack %d, isBase %d, port id %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPT: Join Mac Add: inStack %d, isBase %d, port id %d log

IPT: Join Mac Add: inStack %d, isBase %d, port id %d

**Source    Severity**

IPT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPT: Leave Mac Add: inStack %d, isBase %d, port id %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPT: Leave Mac Add: inStack %d, isBase %d, port id %d log

IPT: Leave Mac Add: inStack %d, isBase %d, port id %d

**Source    Severity**

IPT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPT: MVLAN Mac Add: inStack %d, isBase %d, port id %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPT: MVLAN Mac Add: inStack %d, isBase %d, port id %d log

IPT: MVLAN Mac Add: inStack %d, isBase %d, port id %d

**Source    Severity**

IPT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPT: Startup Mac Add: inStack %d, isBase %d, port id %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPT: Startup Mac Add: inStack %d, isBase %d, port id %d log

IPT: Startup Mac Add: inStack %d, isBase %d, port id %d

**Source    Severity**

IPT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IPT: Temp BU Mac Add: inStack %d, isBase %d, port id %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPT: Temp BU Mac Add: inStack %d, isBase %d, port id %d log

IPT: Temp BU Mac Add: inStack %d, isBase %d, port id %d

**Source    Severity**

IPT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



IPT: Upd NBU(Temp BU) Mac Add:  
inStack %d, isBase %d, port id %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPT: Upd NBU(Temp BU) Mac Add: inStack %d, isBase %d, port id %d log

IPT: Upd NBU(Temp BU) Mac Add: inStack %d, isBase %d, port id %d

**Source    Severity**

IPT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPT: Using the last BOOTP/DHCP assigned IP address (BOOTP server not reachable)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPT: Using the last BOOTP/DHCP assigned IP address (BOOTP server not reachable) log

IPT: Using the last BOOTP/DHCP assigned IP address (BOOTP server not reachable)

In-use IP address for mgmt VLAN is the last BOOTP/DHCP obtained address.

Source	Severity
--------	----------

IPT	Information
-----	-------------

### Remedial action

No action required



# IPv6 DST MAC filters could NOT be installed.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPv6 DST MAC filters could NOT be installed. log

IPv6 DST MAC filters could NOT be installed.

Filters for IPv6 mgmt over SPB (routing mode) cannot be installed.

### Source

IPv6 management over SPB (routing mode)

### Severity

Information

### Remedial action

Check the filters availability.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPv6 DST MAC filters successfully installed.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPv6 DST MAC filters successfully installed. log

IPv6 DST MAC filters successfully installed.

Filters for IPv6 mgmt over SPB (routing mode) installed.

Source	Severity
IPv6 management over SPB (routing mode)	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPv6 enabled with hardware support and FMGR filters

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPv6 enabled with hardware support and FMGR filters log

IPv6 enabled with hardware support and FMGR filters

IPv6 enabled with hardware support and FMGR filters.

Source	Severity
IPv6	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPv6 enabled with hardware support and FMGR filters.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPv6 enabled with hardware support and FMGR filters. log

IPv6 enabled with hardware support and FMGR filters.

**Source**   **Severity**

IPV6

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPv6 enabled with hardware support only

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPv6 enabled with hardware support only log

IPv6 enabled with hardware support only

IPv6 enabled with hardware support only.

Source	Severity
IPv6	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IPv6 enabled with hardware support only.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPv6 enabled with hardware support only. log

IPv6 enabled with hardware support only.

**Source   Severity**

IPv6

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPV6 FHS filters could NOT be installed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPV6 FHS filters could NOT be installed log

IPV6 FHS filters could NOT be installed

FHS filters cannot be installed.

Source	Severity
IPv6 First Hop Security	Information

### Remedial action

Check the filters availability.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPV6 FHS filters could NOT be installed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPV6 FHS filters could NOT be installed log

IPV6 FHS filters could NOT be installed

**Source**   **Severity**

IPV6

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPV6 FHS filters successfully installed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPV6 FHS filters successfully installed log

IPV6 FHS filters successfully installed

FHS filters installed.

Source	Severity
IPv6 First Hop Security	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPV6 FHS filters successfully installed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPV6 FHS filters successfully installed log

IPV6 FHS filters successfully installed

**Source**   **Severity**

IPV6

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPv6 FHS nvram failure.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPv6 FHS nvram failure. log

IPv6 FHS nvram failure.

**Source**   **Severity**

IPV6

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPv6 Forwarding disabled due to inadequate license

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPv6 Forwarding disabled due to inadequate license log

IPv6 Forwarding disabled due to inadequate license

The IPV6 Forwarding mode is automatically disabled as there is no valid license.

Source	Severity
IPV6	Information

### Remedial action

Install a valid license and enable the IPV6 forwarding.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPv6 Forwarding disabled due to inadequate license.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPv6 Forwarding disabled due to inadequate license. log

IPv6 Forwarding disabled due to inadequate license.

**Source   Severity**

IPV6

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IPV6 in IPV4 tunnel SIP mismatch

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPV6 in IPV4 tunnel SIP mismatch log

IPV6 in IPV4 tunnel SIP mismatch

Address mismatch detected.

Source	Severity
IPv6 Data Tunneling	Serious

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPV6 in IPV4 tunnel SIP mismatch

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPV6 in IPV4 tunnel SIP mismatch log

IPV6 in IPV4 tunnel SIP mismatch

**Source**   **Severity**

IPV6

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPv6 malloc failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPv6 malloc failure log

IPv6 malloc failure

IPv6 malloc failure.

Source	Severity
IPv6	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPv6 malloc failure.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPv6 malloc failure. log

IPv6 malloc failure.

**Source**   **Severity**

IPV6

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPv4-only filter criteria mixed with IPv6 criteria

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPv4-only filter criteria mixed with IPv6 criteria log

IPv4-only filter criteria mixed with IPv6 criteria

Ipv4 and IPv6 fields detected in the same filter.

Source	Severity
QoS	Serious

### Remedial action

Separate IPv4 and Ipv6 options in two filters.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPv6 over SPBM filters could NOT be installed.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPv6 over SPBM filters could NOT be installed. log

IPv6 over SPBM filters could NOT be installed.

### Source   Severity

IPV6

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPv6 over SPBM filters successfully installed.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPv6 over SPBM filters successfully installed. log

IPv6 over SPBM filters successfully installed.

**Source    Severity**

IPV6

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPV6 SG filters could NOT be installed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPV6 SG filters could NOT be installed log

IPV6 SG filters could NOT be installed

SG filters cannot be installed.

### Source

IPv6 Source Guard

### Severity

Information

### Remedial action

Check the filters availability.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IPV6 SG filters could NOT be installed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPV6 SG filters could NOT be installed log

IPV6 SG filters could NOT be installed

**Source**   **Severity**

IPV6

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPV6 SG filters successfully installed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPV6 SG filters successfully installed log

IPV6 SG filters successfully installed

SG filters installed.

Source	Severity
IPv6 Source Guard	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IPv6 SG filters successfully installed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IPv6 SG filters successfully installed log

IPv6 SG filters successfully installed

**Source**   **Severity**

IPv6

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IS-IS cannot be enabled when SPBM is globally disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IS-IS cannot be enabled when SPBM is globally disabled log

IS-IS cannot be enabled when SPBM is globally disabled

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IS-IS circuit already exists

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IS-IS circuit already exists log

IS-IS circuit already exists

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IS-IS circuit does not exist

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IS-IS circuit does not exist log

IS-IS circuit does not exist

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IS-IS circuit level hello timer should be in seconds

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IS-IS circuit level hello timer should be in seconds log

IS-IS circuit level hello timer should be in seconds

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IS-IS interface is enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IS-IS interface is enabled log

IS-IS interface is enabled

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IS-IS interface type cannot be changed: point-to-point interface type only

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IS-IS interface type cannot be changed: point-to-point interface type only log

IS-IS interface type cannot be changed: point-to-point interface type only

**Source**   **Severity**  
ISIS

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IS-IS is enabled on this interface

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IS-IS is enabled on this interface log

IS-IS is enabled on this interface

**Source   Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IS-IS is enabled, runtime change not allowed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IS-IS is enabled, runtime change not allowed log

IS-IS is enabled, runtime change not allowed

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IS-IS Level-2 circuits defined (Level-1 only operation request rejected)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IS-IS Level-2 circuits defined (Level-1 only operation request rejected) log

IS-IS Level-2 circuits defined (Level-1 only operation request rejected)

Source	Severity
ISIS	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IS-IS Level-1 only operation supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IS-IS Level-1 only operation supported log

IS-IS Level-1 only operation supported

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IS-IS Level-1 operation is required for SPBM

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IS-IS Level-1 operation is required for SPBM log

IS-IS Level-1 operation is required for SPBM

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IS-IS manual area must be configured before the requested operation can proceed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IS-IS manual area must be configured before the requested operation can proceed log

IS-IS manual area must be configured before the requested operation can proceed

**Source**   **Severity**  
ISIS

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IS-IS max LSP generation interval must be $\geq$ to the min LSP interval

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IS-IS max LSP generation interval must be $\geq$ to the min LSP interval log

IS-IS max LSP generation interval must be  $\geq$  to the min LSP interval

Source	Severity
ISIS	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# IS-IS system ID cannot be a multicast address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IS-IS system ID cannot be a multicast address log

IS-IS system ID cannot be a multicast address

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# IS-IS system ID must be configured before the requested operation can proceed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IS-IS system ID must be configured before the requested operation can proceed log

IS-IS system ID must be configured before the requested operation can proceed

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Issue detected during QoS stack synchronization

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Issue detected during QoS stack synchronization log

Issue detected during QoS stack synchronization

Delays are exhausted and the stack synchronization could not be verified.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Issue detected enabling/disabling DSCP Mapping Table usage (port %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Issue detected enabling/disabling DSCP Mapping Table usage (port %d) log

Issue detected enabling/disabling DSCP Mapping Table usage (port %d)

Unable to enable/disable usage of the DSCP Mapping table for the port number displayed in the log message.

Source	Severity
QoS Agent	Serious

### Remedial action

Reset device and retry.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Issue detected enabling disabling DSCP table usage (port#)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Issue detected enabling disabling DSCP table usage (port#) log

Issue detected enabling disabling DSCP table usage (port#)

" Failed to set on the specified interface the port mode for usage of the global DSCP mapping table. "

Source	Severity
QoS	Information

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Issue detected restoring QPA data from NV (class class# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Issue detected restoring QPA data from NV (class class# ) log

Issue detected restoring QPA data from NV (class class# )

Unable to restore the QPA data from NVRAM (possible corrupt table(s)).

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Issue detected restoring QPA data from NV (class %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Issue detected restoring QPA data from NV (class %d) log

Issue detected restoring QPA data from NV (class %d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Issue detected setting native DSCP Mapping Table values

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Issue detected setting native DSCP Mapping Table values log

Issue detected setting native DSCP Mapping Table values

Unable to update settings in the DSCP Mapping table.

Source	Severity
QoS Agent	Serious

### Remedial action

Reset device and retry.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Issue detected setting native DSCP table values

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Issue detected setting native DSCP table values log

Issue detected setting native DSCP table values

Unable to set the native/default DSCP table values.

Source	Severity
QoS	Information

### Remedial action

Reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Issues detected with QoS operational mode disable (%d ifcs)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Issues detected with QoS operational mode disable (%d ifcs) log

Issues detected with QoS operational mode disable (%d ifcs)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Issues detected with QoS operational mode disable ( ifcs# ifcs)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Issues detected with QoS operational mode disable ( ifcs# ifcs) log

Issues detected with QoS operational mode disable ( ifcs# ifcs)

Unable to make changes (disable QoS) because of the specified interface configuration.

Source	Severity
QoS	Critical

### Remedial action

Check log for possible related details on the issue for and remove the conflicting configurations.



# Issues detected with QoS operational mode enable (%d ifcs)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Issues detected with QoS operational mode enable (%d ifcs) log

Issues detected with QoS operational mode enable (%d ifcs)

**Source   Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Issues detected with QoS operational mode enable ( ifcs# ifcs)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Issues detected with QoS operational mode enable ( ifcs# ifcs) log

Issues detected with QoS operational mode enable ( ifcs# ifcs)

Unable to make changes (enable QoS) because of the specified interface configuration.

Source	Severity
QoS	Critical

### Remedial action

Check log for possible related details on the issue and remove the conflicting configurations.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Issue with classifier component mask detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Issue with classifier component mask detected log

Issue with classifier component mask detected

Unable to create the classifier data mask structure form the classifier data provided.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Identify and separate the conflicting elements into multiple classifier blocks.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# JOIN event sent unit mask value appl mask value

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## JOIN event sent unit mask value appl mask value log

JOIN event sent unit mask value appl mask value

The Join event is sent during the stack formation process.

Source	Severity
Stack Manager	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Join event sent, unit mask 0x%02X, appl mask 0x%08X 0x%08X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Join event sent, unit mask 0x%02X, appl mask 0x%08X 0x%08X log

Join event sent, unit mask 0x%02X, appl mask 0x%08X 0x%08X

### Source    Severity

SMGR

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# keep alive expired

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## keep alive expired log

keep alive expired

**Source**   **Severity**

CDT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LAC: Allocated trunk with id %d for aggregator %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: Allocated trunk with id %d for aggregator %d log

LAC: Allocated trunk with id %d for aggregator %d

An MLT trunk was allocated for a LAG. The trunk is not yet enabled.

Source	Severity
LAC	Information

### Remedial action

No action required.



LAC: API error: %d-%d-%d.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: API error: %d-%d-%d. log

LAC: API error: %d-%d-%d.

Source	Severity
--------	----------

LAC	
-----	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LAC: Deallocated trunk with id %d for aggregator %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: Deallocated trunk with id %d for aggregator %d log

LAC: Deallocated trunk with id %d for aggregator %d

A LAG was removed from an MLT trunk.

Source	Severity
LAC	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LAC: Failed to release trunk group: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: Failed to release trunk group: %d - %d - %d log

LAC: Failed to release trunk group: %d - %d - %d

**Source    Severity**

LAC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LAC: get buffer fail: %d-%d-%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: get buffer fail: %d-%d-%d log

LAC: get buffer fail: %d-%d-%d

**Source    Severity**

LAC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LAC: input parameter error: %d-%d-%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: input parameter error: %d-%d-%d log

LAC: input parameter error: %d-%d-%d

Source	Severity
--------	----------

LAC	
-----	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



LAC: lac\_log\_add\_link: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: lac\_log\_add\_link: %d - %d - %d log

LAC: lac\_log\_add\_link: %d - %d - %d

**Source**   **Severity**

LAC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





LAC: lac\_log\_link\_change: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: lac\_log\_link\_change: %d - %d - %d log

LAC: lac\_log\_link\_change: %d - %d - %d

Source	Severity
--------	----------

LAC	
-----	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



LAC: lac\_log\_rem\_link: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: lac\_log\_rem\_link: %d - %d - %d log

LAC: lac\_log\_rem\_link: %d - %d - %d

Source	Severity
--------	----------

LAC	
-----	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LAC: MLT %d error on far end.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: MLT %d error on far end. log

LAC: MLT %d error on far end.

The LACP trunk encountered a problem in exchanging PDUs with partner.

Source	Severity
LAC	Information

### Remedial action

No action required. It is resolved by PDUs exchange between systems.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LAC: MLT %d error, partner aggregation bit not set.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: MLT %d error, partner aggregation bit not set. log

LAC: MLT %d error, partner aggregation bit not set.

The LACP PDU from partner system does not have the Aggregation bit set. The partner port does not have the ability to aggregate.

Source	Severity
LAC	Information

### Remedial action

No action required.



# LAC: MLT %d error, partner expired bit set.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: MLT %d error, partner expired bit set. log

LAC: MLT %d error, partner expired bit set.

The LACP PDU from partner system has the Expired bit set. The parter's information is outdated.

Source	Severity
LAC	Information

### Remedial action

No action required. It is resolved by PDUs exchange between systems.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LAC: MLT %d error, partner synchronization bit not set.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: MLT %d error, partner synchronization bit not set. log

LAC: MLT %d error, partner synchronization bit not set.

The LACP PDU from partner system does not have the Synchronization bit set. The two systems do not agree on the LACP information about each other.

Source	Severity
LAC	Information

### Remedial action

No action required. It is resolved by PDUs exchange between systems.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LAC MLT error on far end. 0 - 0 - 0

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC MLT error on far end. 0 - 0 - 0 log

LAC MLT error on far end. 0 - 0 - 0

The LACP link is selected by the system, but not participating in traffic rx/tx.

Source	Severity
LAC	Information

### Remedial action

Check LACP settings on both sides. Disable/re-enable LACP on ports.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LAC: MLT error, partner aggregation bit not set

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: MLT error, partner aggregation bit not set log

LAC: MLT error, partner aggregation bit not set

The LACP link is selected by the system, but not participating in the traffic rx/tx because the partner port is marked as not aggregable.

Source	Severity
LACP	Information

### Remedial action

Check LACP settings on both sides. Disable/re-enable LACP on ports.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# LAC: MLT error, partner expired bit set.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: MLT error, partner expired bit set. log

LAC: MLT error, partner expired bit set.

The LACP link is selected by the system, but not participating in the traffic rx/tx because the partner port is marked as expired.

Source	Severity
LACP	Information

### Remedial action

Check LACP settings on both sides. Disable/re-enable LACP on ports.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LAC: MLT error, partner synchronization bit not set.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: MLT error, partner synchronization bit not set. log

LAC: MLT error, partner synchronization bit not set.

The LACP link is selected by the system, but not participating in the traffic rx/tx because the partner port is marked as not synchronized.

Source	Severity
--------	----------

LACP	Information
------	-------------

### Remedial action

Check LACP settings on both sides. Disable/re-enable LACP on ports.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LAC: MLT remove port: unit %d, port %d, trunk group %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: MLT remove port: unit %d, port %d, trunk group %d log

LAC: MLT remove port: unit %d, port %d, trunk group %d

**Source   Severity**

LAC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LAC: MLT set port: unit %d, port %d, trunk group %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: MLT set port: unit %d, port %d, trunk group %d log

LAC: MLT set port: unit %d, port %d, trunk group %d

**Source   Severity**

LAC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LAC: msgQ error: %d-%d-%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: msgQ error: %d-%d-%d log

LAC: msgQ error: %d-%d-%d

**Source**   **Severity**

LAC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



LAC: Msg Type Err: %s : %d, msgid = %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: Msg Type Err: %s : %d, msgid = %d log

LAC: Msg Type Err: %s : %d, msgid = %d

**Source    Severity**

LAC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LAC: Mux event: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: Mux event: %d - %d - %d log

LAC: Mux event: %d - %d - %d

Source	Severity
--------	----------

LAC	
-----	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LAC No more trunk group available for LAC. 0 - 0 - 0

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC No more trunk group available for LAC. 0 - 0 - 0 log

LAC No more trunk group available for LAC. 0 - 0 - 0

All trunk group IDs are already allocated.

Source	Severity
LAC	Information

### Remedial action

Check if an unnecessary trunk ID is used.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# LAC: No more trunk group available for LAC.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: No more trunk group available for LAC. log

LAC: No more trunk group available for LAC.

**Source**   **Severity**

LAC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LAC: nvRam file error %d %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: nvRam file error %d %d log

LAC: nvRam file error %d %d

**Source    Severity**

LAC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LAC: RX event: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: RX event: %d - %d - %d log

LAC: RX event: %d - %d - %d

Source	Severity
--------	----------

LAC	
-----	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



LAC: Stack event: %d - %d - 0x%x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: Stack event: %d - %d - 0x%x log

LAC: Stack event: %d - %d - 0x%x

**Source   Severity**

LAC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LAC: Start

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: Start log

LAC: Start

**Source**   **Severity**

LAC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LAC: TMR event: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: TMR event: %d - %d - %d log

LAC: TMR event: %d - %d - %d

Source	Severity
--------	----------

LAC	
-----	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LAC: Trunk %d is disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: Trunk %d is disabled log

LAC: Trunk %d is disabled

A dynamic LACP trunk is disabled.

Source	Severity
LAC	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LAC: Trunk %d is enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: Trunk %d is enabled log

LAC: Trunk %d is enabled

A dynamic LACP trunk is enabled.

Source	Severity
LAC	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





LAC: TX event: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC: TX event: %d - %d - %d log

LAC: TX event: %d - %d - %d

**Source**   **Severity**

LAC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LAC with admin key %d failed configuration verification. Bad ARP INSPECTION configuration.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification. Bad ARP INSPECTION configuration. log

LAC with admin key %d failed configuration verification. Bad ARP INSPECTION configuration.

ARP-Inspection configuration is not consistent on all trunk members.

Source	Severity
--------	----------

LACP	Information
------	-------------

### Remedial action

Check ARP-Inspection config and set the same ARP-Inspection parameters for all trunk members.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



LAC with admin key %d failed configuration verification. Bad DHCP-SNOOPING configuration.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification. Bad DHCP-SNOOPING configuration. log

LAC with admin key %d failed configuration verification. Bad DHCP-SNOOPING configuration.

DHCP-snooping configuration is not consistent on all trunk members.

### Source    Severity

LACP        Information

### Remedial action

Check DHCP-snooping configuration and set the same DHCP-snooping parameters for all trunk members.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



LAC with admin key %d failed configuration verification. Bad EGRESS settings.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification. Bad EGRESS settings. log

LAC with admin key %d failed configuration verification. Bad EGRESS settings.

**Source    Severity**

LAC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



LAC with admin key %d failed configuration verification. Bad IGMP configuration.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification. Bad IGMP configuration. log

LAC with admin key %d failed configuration verification. Bad IGMP configuration.

IGMP configuration is not consistent on all trunk members.

Source	Severity
--------	----------

LACP	Information
------	-------------

### Remedial action

Check IGMP configuration and set the same IGMP parameters for all trunk members.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



LAC with admin key %d failed  
configuration verification. Bad MAC  
Security configuration.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification. Bad MAC Security configuration. log

LAC with admin key %d failed configuration verification. Bad MAC Security configuration.

**Source    Severity**

LAC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LAC with admin key %d failed configuration verification. Bad MAC Security configuration.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification. Bad MAC Security configuration. log

LAC with admin key %d failed configuration verification. Bad MAC Security configuration.

MAC Security configuration is not consistent on all trunk members.

Source	Severity
--------	----------

LACP	Information
------	-------------

### Remedial action

Check MAC Security configuration and set the same MAC Security parameters for all trunk members.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



LAC with admin key %d failed configuration verification. Bad qos status.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification. Bad qos status. log

LAC with admin key %d failed configuration verification. Bad qos status.

QOS status is not consistent on all trunk members.

Source	Severity
--------	----------

LACP	Information
------	-------------

### Remedial action

Check QOS status and set the same QOS status for all trunk members.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





LAC with admin key %d failed configuration verification. Bad rate-limiting configuration.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification. Bad rate-limiting configuration. log

LAC with admin key %d failed configuration verification. Bad rate-limiting configuration.

Rate-limiting configuration is not consistent on all trunk members.

Source	Severity
--------	----------

LACP	Information
------	-------------

### Remedial action

Check Rate-limiting configuration and set the same Rate-limiting parameters for all trunk members.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



LAC with admin key %d failed configuration verification. Bad VLAN configuration.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification. Bad VLAN configuration. log

LAC with admin key %d failed configuration verification. Bad VLAN configuration.

VLAN configuration is not consistent on all trunk members.

Source	Severity
--------	----------

LACP	Information
------	-------------

### Remedial action

Check VLAN config and set the same VLAN parameters for all trunk members.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



LAC with admin key %d failed configuration verification. Cannot set admin key to the value used by ADAC Uplink.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification. Cannot set admin key to the value used by ADAC Uplink. log

LAC with admin key %d failed configuration verification. Cannot set admin key to the value used by ADAC Uplink.

LACP ports sharing the same admin key do not belong to the same UpLink trunk.

Source	Severity
LAC	Information

### Remedial action

LACP ports sharing the same admin key should belong to the same ADAC UpLink trunk.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



LAC with admin key %d failed configuration verification. Error #: %d-%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification. Error #: %d-%d log

LAC with admin key %d failed configuration verification. Error #: %d-%d

An error not covered by other LAC inconsistency logs.

Source	Severity
--------	----------

LACP	Information
------	-------------

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



LAC with admin key %d failed configuration verification.Ports have different FA configuration.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification.Ports have different FA configuration. log

LAC with admin key %d failed configuration verification.Ports have different FA configuration.

**Source    Severity**

LAC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



LAC with admin key %d failed configuration verification. Ports have different IPSG configurations.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification. Ports have different IPSG configurations. log

LAC with admin key %d failed configuration verification. Ports have different IPSG configurations.

LACP ports sharing the same admin key have different IPSG settings.

Source	Severity
--------	----------

LAC	Information
-----	-------------

### Remedial action

Configure the same IPSG settings for LACP ports with the same admin key.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



LAC with admin key %d failed configuration verification. Ports have different MAC learning status.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification. Ports have different MAC learning status. log

LAC with admin key %d failed configuration verification. Ports have different MAC learning status.

LACP ports sharing the same admin key have different MAC learning status.

Source	Severity
--------	----------

LAC	Information
-----	-------------

### Remedial action

Configure the same MAC learning settings for LACP ports with the same admin key.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



LAC with admin key %d failed configuration verification.Ports have different mac security learning status.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification.Ports have different mac security learning status. log

LAC with admin key %d failed configuration verification.Ports have different mac security learning status.

LACP ports sharing the same admin key have different MAC security learning status.

### Source    Severity

LAC            Information

### Remedial action

Configure the same MAC security learning settings for LACP ports with the same admin key.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





LAC with admin key %d failed configuration verification.Ports have different mac security settings.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification.Ports have different mac security settings. log

LAC with admin key %d failed configuration verification.Ports have different mac security settings.

LACP ports sharing the same admin key have different MAC security list settings.

### Source    Severity

LAC            Information

### Remedial action

Configure the same MAC security list settings for LACP ports with the same admin key.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



LAC with admin key %d failed configuration verification.Ports have different mac security status.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification.Ports have different mac security status. log

LAC with admin key %d failed configuration verification.Ports have different mac security status.

LACP ports sharing the same admin key have different MAC security status.

Source	Severity
--------	----------

LAC	Information
-----	-------------

### Remedial action

Configure the same MAC security status for LACP ports with the same admin key.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



LAC with admin key %d failed configuration verification. Ports have different private-vlan port type.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification. Ports have different private-vlan port type. log

LAC with admin key %d failed configuration verification. Ports have different private-vlan port type.

The trunk ports have different private-vlan port type settings.

Source	Severity
--------	----------

LAC	Information
-----	-------------

### Remedial action

Configure the same private-vlan port type for LACP ports with the same admin key.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



LAC with admin key %d failed configuration verification. Ports have different qos config.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification. Ports have different qos config. log

LAC with admin key %d failed configuration verification. Ports have different qos config.

QOS configuration is not consistent on all trunk members.

Source	Severity
--------	----------

LACP	Information
------	-------------

### Remedial action

Check QOS configuration and set the same QOS parameters for all trunk members.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



LAC with admin key %d failed configuration verification.Ports have different SLPP-guard configurations.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification.Ports have different SLPP-guard configurations. log

LAC with admin key %d failed configuration verification.Ports have different SLPP-guard configurations.

LACP ports sharing the same admin key have different SLPP-guard settings.

### Source    Severity

LAC            Information

### Remedial action

Configure the same SLPP-guard settings for LACP ports with the same admin key.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



LAC with admin key %d failed configuration verification.Ports have different SPBM configurations.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification.Ports have different SPBM configurations. log

LAC with admin key %d failed configuration verification.Ports have different SPBM configurations.

SPBM configuration is not consistent on all trunk members.

Source	Severity
--------	----------

LACP	Information
------	-------------

### Remedial action

Check SPBM configuration and set the same SPBM parameters for all trunk members.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



LAC with admin key %d failed configuration verification.Ports have different VLACP admin enable state.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification.Ports have different VLACP admin enable state. log

LAC with admin key %d failed configuration verification.Ports have different VLACP admin enable state.

LACP ports sharing the same admin key have different VLACP admin state settings.

### Source    Severity

LAC            Information

### Remedial action

Configure the same VLACP admin state for LACP ports with the same admin key.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



LAC with admin key %d failed configuration verification.Ports have different VLACP ethertype.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification.Ports have different VLACP ethertype. log

LAC with admin key %d failed configuration verification.Ports have different VLACP ethertype.

LACP ports sharing the same admin key have different VLACP ethertype settings.

### Source    Severity

LAC            Information

### Remedial action

Configure the same VLACP ethertype for LACP ports with the same admin key.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





LAC with admin key %d failed configuration verification.Ports have different VLACP fast periodic time value.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification.Ports have different VLACP fast periodic time value. log

LAC with admin key %d failed configuration verification.Ports have different VLACP fast periodic time value.

LACP ports sharing the same admin key have different VLACP fast periodic time values.

### Source    Severity

LAC            Information

### Remedial action

Configure the same VLACP fast periodic time value for LACP ports with the same admin key.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



LAC with admin key %d failed configuration verification. Ports have different VLACP mac address.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification. Ports have different VLACP mac address. log

LAC with admin key %d failed configuration verification. Ports have different VLACP mac address.

LACP ports sharing the same admin key have different VLACP MAC address settings.

### Source    Severity

LAC            Information

### Remedial action

Configure the same VLACP MAC address for LACP ports with the same admin key.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



LAC with admin key %d failed configuration verification.Ports have different VLACP slow periodic time value.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification.Ports have different VLACP slow periodic time value. log

LAC with admin key %d failed configuration verification.Ports have different VLACP slow periodic time value.

LACP ports sharing the same admin key have different VLACP slow periodic time values.

Source	Severity
LAC	Information

### Remedial action

Configure the same VLACP slow periodic time value for LACP ports with the same admin key.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



LAC with admin key %d failed configuration verification.Ports have different VLACP timeout scale.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification.Ports have different VLACP timeout scale. log

LAC with admin key %d failed configuration verification.Ports have different VLACP timeout scale.

LACP ports sharing the same admin key have different VLACP timeout scale settings.

### Source    Severity

LAC            Information

### Remedial action

Configure the same VLACP timeout scale for LACP ports with the same admin key.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LAC with admin key %d failed configuration verification.Ports have different VLACP timeout type.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification.Ports have different VLACP timeout type. log

LAC with admin key %d failed configuration verification.Ports have different VLACP timeout type.

LACP ports sharing the same admin key have different VLACP timeout type settings.

Source	Severity
--------	----------

LAC	Information
-----	-------------

### Remedial action

Configure the same VLACP timeout type for LACP ports with the same admin key.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



LAC with admin key %d failed configuration verification. Ports have different vlan filter tag frames settings.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification. Ports have different vlan filter tag frames settings. log

LAC with admin key %d failed configuration verification. Ports have different vlan filter tag frames settings.

The trunk ports have different VLAN tag frames filter settings.

Source	Severity
--------	----------

LAC	Information
-----	-------------

### Remedial action

Configure the same VLAN tag frames filter for LACP ports with the same admin key.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



LAC with admin key %d failed configuration verification. Ports have different vlan filter unreg frames settings.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification. Ports have different vlan filter unreg frames settings. log

LAC with admin key %d failed configuration verification. Ports have different vlan filter unreg frames settings.

The trunk ports have different VLAN unreg frames filter settings.

Source	Severity
LAC	Information

### Remedial action

Configure the same VLAN unreg frames filter for LACP ports with the same admin key.



LAC with admin key %d failed configuration verification. Ports have different vlan filter untag frames settings.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification. Ports have different vlan filter untag frames settings. log

LAC with admin key %d failed configuration verification. Ports have different vlan filter untag frames settings.

The trunk ports have different VLAN untag frames filter settings.

Source	Severity
LAC	Information

### Remedial action

Configure the same VLAN untag frames filter for LACP ports with the same admin key.





# LAC with admin key %d failed configuration verification. Ports have different vlan priorities.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification. Ports have different vlan priorities. log

LAC with admin key %d failed configuration verification. Ports have different vlan priorities.

The trunk ports have different VLAN priority settings.

Source	Severity
LAC	Information

### Remedial action

Configure the same VLAN priority for LACP ports with the same admin key.



LAC with admin key %d failed configuration verification. Ports have different vlan PVIDs.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification. Ports have different vlan PVIDs. log

LAC with admin key %d failed configuration verification. Ports have different vlan PVIDs.

The trunk ports have different VLAN PVID settings.

Source	Severity
--------	----------

LAC	Information
-----	-------------

### Remedial action

Configure the same VLAN PVID for LACP ports with the same admin key.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



LAC with admin key %d failed configuration verification. Ports have different vlan tagging.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification. Ports have different vlan tagging. log

LAC with admin key %d failed configuration verification. Ports have different vlan tagging.

The trunk ports have different VLAN tagging settings.

Source	Severity
--------	----------

LAC	Information
-----	-------------

### Remedial action

Configure the same VLAN tagging for LACP ports with the same admin key.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



LAC with admin key %d failed configuration verification. Same key is used by ports belonging to different VLAN.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LAC with admin key %d failed configuration verification. Same key is used by ports belonging to different VLAN. log

LAC with admin key %d failed configuration verification. Same key is used by ports belonging to different VLAN.

The trunk ports belong to different VLANs.

Source	Severity
LAC	Information

### Remedial action

Configure the same VLAN IDs for LACP ports with the same admin key.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Last MLT trunk was allocated by LAC. No more free trunk groups.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Last MLT trunk was allocated by LAC. No more free trunk groups. log

Last MLT trunk was allocated by LAC. No more free trunk groups.

The last free trunk group was allocated by a dynamic LAC.

Source	Severity
MLT	Information

### Remedial action

Free a trunk group no longer in need to be able to allocate another MLT trunk group.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Last MLT trunk was allocated by MLT.  
No more free trunk groups.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Last MLT trunk was allocated by MLT. No more free trunk groups. log

Last MLT trunk was allocated by MLT. No more free trunk groups.

The last free trunk group was allocated by a static MLT.

Source	Severity
MLT	Information

### Remedial action

Free a trunk group no longer in need in order to be able to allocate another MLT trunk group.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Layer 2 classifier modifications not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Layer 2 classifier modifications not supported log

Layer 2 classifier modifications not supported

The system detected an internal error; The specified modifier option not supported.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Layer 2 classifier still referenced (deletion prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Layer 2 classifier still referenced (deletion prohibited) log

Layer 2 classifier still referenced (deletion prohibited)

Cannot delete a classifier if it is referenced in a classifier-block or policy.

Source	Severity
QoS	Serious

### Remedial action

Remove the classifier-block/policy first.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Layer 2 filter distribution across stack failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Layer 2 filter distribution across stack failed log

Layer 2 filter distribution across stack failed

Unable to commit changes across the stack.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Layer 4 port filtering with IPv6 requires UDP TCP Next Header

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Layer 4 port filtering with IPv6 requires UDP TCP Next Header log

Layer 4 port filtering with IPv6 requires UDP TCP Next Header

Port filtering is supported only for TCP and UDP protocols.

Source	Severity
QoS	Serious

### Remedial action

Specify next header: 6 for TCP or 17 for UDP or drop port filtering usage.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Layer 4 port filtering with IPv6 requires UDP/TCP Next Header

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Layer 4 port filtering with IPv6 requires UDP/TCP Next Header log

Layer 4 port filtering with IPv6 requires UDP/TCP Next Header

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Layer 4 port range could not be reduced sufficiently

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Layer 4 port range could not be reduced sufficiently log

Layer 4 port range could not be reduced sufficiently

The port range could not be reduce sufficiently for it's installation to be supported.

Source	Severity
QoS	Serious

### Remedial action

Modify the port range.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LEAVE event sent unit mask value appl mask value

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LEAVE event sent unit mask value appl mask value log

LEAVE event sent unit mask value appl mask value

The unit on which this message is logged has left the stack. The 'unit mask' is a bit mask representation of the unit that left the stack.

Source	Severity
Stack Manager	Information

### Remedial action

Make sure that the unit removal is intended.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Leave event sent, unit mask 0x%02X,  
appl mask 0x%08X 0x%08X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Leave event sent, unit mask 0x%02X, appl mask 0x%08X 0x%08X log

Leave event sent, unit mask 0x%02X, appl mask 0x%08X 0x%08X

Source	Severity
SMGR	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Level router does not support

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Level router does not support log

Level router does not support

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Limit reached for static routes.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Limit reached for static routes. log

Limit reached for static routes.

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Link Down Trap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Link Down Trap log

Link Down Trap

Link Down.

Source	Severity
IFMGR, SNMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Link Down Trap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Link Down Trap log

Link Down Trap

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LinkStateTracking: First interface %d/d went up in link state group %d, enabling downstream ports

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LinkStateTracking: First interface %d/d went up in link state group %d, enabling downstream ports log

LinkStateTracking: First interface %d/d went up in link state group %d, enabling downstream ports

The first upstream interface went up, downstream ports are enabled.

### Source

Link State Tracking

### Severity

Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LinkStateTracking: First interface mlt %d went up in link state group %d, enabling downstream interfaces

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LinkStateTracking: First interface mlt %d went up in link state group %d, enabling downstream interfaces log

LinkStateTracking: First interface mlt %d went up in link state group %d, enabling downstream interfaces

The first upstream interface (trunk) switches state to 'up' from 'down' state. LST group transitions to 'up' operational state.

### Source

Link State Tracking

### Severity

Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LinkStateTracking: First interface %s went up in link state group %d, enabling downstream interfaces

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LinkStateTracking: First interface %s went up in link state group %d, enabling downstream interfaces log

LinkStateTracking: First interface %s went up in link state group %d, enabling downstream interfaces

Issued when all upstream interfaces are in down state and one (trunk) switches state to up. This marks a LST group transition to up operational state.

Source	Severity
Link State Tracking	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LinkStateTracking: Interface %d/d went down in link state group %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LinkStateTracking: Interface %d/d went down in link state group %d log

LinkStateTracking: Interface %d/d went down in link state group %d

One upstream member (port) switches state to 'down', without affecting the LST group operational state.

Source	Severity
Link State Tracking	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LinkStateTracking: Interface %d/d went up in link state group %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LinkStateTracking: Interface %d/d went up in link state group %d log

LinkStateTracking: Interface %d/d went up in link state group %d

One upstream member (port) switches state to 'up', without affecting the LST group operational state.

Source	Severity
Link State Tracking	Information

### Remedial action

No action required.



# LinkStateTracking: Interface mlt %d went down in link state group %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LinkStateTracking: Interface mlt %d went down in link state group %d log

LinkStateTracking: Interface mlt %d went down in link state group %d

One upstream member (trunk) switches state to 'down', without affecting the LST group operational state.

Source	Severity
Link State Tracking	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# LinkStateTracking: Interface mlt %d went up in link state group %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LinkStateTracking: Interface mlt %d went up in link state group %d log

LinkStateTracking: Interface mlt %d went up in link state group %d

One upstream member (trunk) switches state to 'up', without affecting the LST group operational state.

### Source

Link State Tracking

### Severity

Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LinkStateTracking: Interface %s went down in link state group %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LinkStateTracking: Interface %s went down in link state group %d log

LinkStateTracking: Interface %s went down in link state group %d

Issued when one upstream member (port) switches state to

Source	Severity
Link State Tracking	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LinkStateTracking: Interface %s went up in link state group %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LinkStateTracking: Interface %s went up in link state group %d log

LinkStateTracking: Interface %s went up in link state group %d

Issued when one upstream member (port) switches state to

### Source

Link State Tracking

### Severity

Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LinkStateTracking: Last interface %d/d went down in link state group %d, disabling downstream interfaces

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LinkStateTracking: Last interface %d/d went down in link state group %d, disabling downstream interfaces log

LinkStateTracking: Last interface %d/d went down in link state group %d, disabling downstream interfaces

The last upstream interface (port) with an 'up' state switches to 'down' state. LST group transitions to 'down' operational state.

### Source

Link State Tracking

### Severity

Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LinkStateTracking: Last interface mlt %d went down in link state group %d, disabling downstream interfaces

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LinkStateTracking: Last interface mlt %d went down in link state group %d, disabling downstream interfaces log

LinkStateTracking: Last interface mlt %d went down in link state group %d, disabling downstream interfaces

The last upstream interface (trunk) with an 'up' state switches to 'down' state. LST group transitions to 'down' operational state.

### Source

Link State Tracking

### Severity

Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# LinkStateTracking: Last interface %s went down in link state group %d, disabling downstream interfaces

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## LinkStateTracking: Last interface %s went down in link state group %d, disabling downstream interfaces log

LinkStateTracking: Last interface %s went down in link state group %d, disabling downstream interfaces

Issued when the last upstream interface (port) with an up state switches to downstate. This marks a LST group transition to down operational state.

### Source

Link State Tracking

### Severity

Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# Link Up Trap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Link Up Trap log

Link Up Trap

Link up.

Source	Severity
IFMGR, SNMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Link Up Trap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Link Up Trap log

Link Up Trap

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





L3MGR is %s %s %#x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## L3MGR is %s %s %#x log

L3MGR is %s %s %#x

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# I3m\_smgr exp db %s 0x%X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## I3m\_smgr exp db %s 0x%X log

I3m\_smgr exp db %s 0x%X

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# I3m\_smgr rep db cat=%d cnt=%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## I3m\_smgr rep db cat=%d cnt=%d log

I3m\_smgr rep db cat=%d cnt=%d

Source	Severity
--------	----------

L3Mgr	
-------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# l3m\_smgr rx db cat=%d cnt=%d rxdb=0x%X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## l3m\_smgr rx db cat=%d cnt=%d rxdb=0x%X log

l3m\_smgr rx db cat=%d cnt=%d rxdb=0x%X

Source	Severity
--------	----------

L3Mgr	
-------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# I3m\_smgr stkev %d %x %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## I3m\_smgr stkev %d %x %s log

I3m\_smgr stkev %d %x %s

**Source    Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Loading configuration block # block\_number

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Loading configuration block # block\_number log

Loading configuration block # block\_number

This message appears when the configuration is loaded from block n.

Source	Severity
config	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Loading configuration block %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Loading configuration block %d log

Loading configuration block %d

**Source    Severity**

MCFG

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Local authentication disabled on serial

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Local authentication disabled on serial log

Local authentication disabled on serial

Authentication on serial port using local credentials has been disabled.

Source	Severity
CLI	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Local authentication disabled on stack serial

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Local authentication disabled on stack serial log

Local authentication disabled on stack serial

**Source**   **Severity**

Telnet

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Local authentication disabled on stack TELNET/WEB/SSH

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Local authentication disabled on stack TELNET/WEB/SSH log

Local authentication disabled on stack TELNET/WEB/SSH

### Source    Severity

Telnet

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Local authentication disabled on switch serial

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Local authentication disabled on switch serial log

Local authentication disabled on switch serial

### Source   Severity

Telnet

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Local authentication disabled on switch TELNET/WEB/SSH

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Local authentication disabled on switch TELNET/WEB/SSH log

Local authentication disabled on switch TELNET/WEB/SSH

**Source**   **Severity**

Telnet

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Local authentication disabled on telnet

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Local authentication disabled on telnet log

Local authentication disabled on telnet

Authentication over telnet using local credentials has been disabled.

Source	Severity
CLI	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Local authentication disabled on TELNET/WEB/SSH

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Local authentication disabled on TELNET/WEB/SSH log

Local authentication disabled on TELNET/WEB/SSH

**Source**   **Severity**

Telnet

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Local authentication enabled on serial

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Local authentication enabled on serial log

Local authentication enabled on serial

Authentication on serial port using local credentials has been enabled.

Source	Severity
CLI	Information

### Remedial action

No action required.



# Local authentication enabled on stack serial

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Local authentication enabled on stack serial log

Local authentication enabled on stack serial

**Source**   **Severity**

Telnet

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Local authentication enabled on stack TELNET/WEB/SSH

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Local authentication enabled on stack TELNET/WEB/SSH log

Local authentication enabled on stack TELNET/WEB/SSH

**Source**   **Severity**

Telnet

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Local authentication enabled on switch serial

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Local authentication enabled on switch serial log

Local authentication enabled on switch serial

**Source**   **Severity**

Telnet

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Local authentication enabled on switch TELNET/WEB/SSH

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Local authentication enabled on switch TELNET/WEB/SSH log

Local authentication enabled on switch TELNET/WEB/SSH

### Source    Severity

Telnet

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Local authentication enabled on telnet

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Local authentication enabled on telnet log

Local authentication enabled on telnet

Authentication over telnet using local credentials has been enabled.

Source	Severity
CLI	Information

### Remedial action

No action required.



# Local authentication enabled on TELNET/WEB/SSH

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Local authentication enabled on TELNET/WEB/SSH log

Local authentication enabled on TELNET/WEB/SSH

**Source**   **Severity**

Telnet

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Login timeout serial connection

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Login timeout serial connection log

Login timeout serial connection

The serial connection login prompt message is available for the user input for one minute with maximum of three attempts, if you fail to login the product banner is displayed.

Source	Severity
Console	Information

### Remedial action

Enter a valid username and password within a minute.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Login timeout, serial connection

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Login timeout, serial connection log

Login timeout, serial connection

**Source**   **Severity**

Telnet

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Lossless and Lossless-PFC modes are only supported in queue set 2

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Lossless and Lossless-PFC modes are only supported in queue set 2 log

Lossless and Lossless-PFC modes are only supported in queue set 2

Lossless and Lossless-PFC modes are only supported in queue set 2.

Source	Severity
QOS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# L3S event=%s state=%s new=%s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## L3S event=%s state=%s new=%s log

L3S event=%s state=%s new=%s

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# L3S unexpected event=%s state=%s enabled=%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## L3S unexpected event=%s state=%s enabled=%d log

L3S unexpected event=%s state=%s enabled=%d

### Source    Severity

L3Mgr

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



L3 %s %#x %#x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## L3 %s %#x %#x log

L3 %s %#x %#x

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



mac address appears twice in cam (this has happened a total of %d times)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## mac address appears twice in cam (this has happened a total of %d times) log

mac address appears twice in cam (this has happened a total of %d times)

**Source**   **Severity**  
CDT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MAC security table full

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MAC security table full log

MAC security table full

The MAC security table is full.

Source	Severity
Bay secure	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



MAC

%02x:%02x:%02x:%02x:%02x:%02x  
not authenticated; only one client is  
allowed in MHSA mode

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MAC %02x:%02x:%02x:%02x:%02x:%02x not authenticated; only one client is allowed in MHSA mode log

MAC %02x:%02x:%02x:%02x:%02x:%02x not authenticated; only one client is allowed in MHSA mode

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Management IP: excess traffic received on Management port%s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Management IP: excess traffic received on Management port%s log

Management IP: excess traffic received on Management port%s

Excess traffic received on the management port. The port is down.

Source	Severity
PDT	Serious

### Remedial action

Take notice of excess traffic and restart the port.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Management IP: OOB port%s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Management IP: OOB port%s log

Management IP: OOB port%s

Management port is down.

Source	Severity
PDT	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Management IP: OOB port%s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Management IP: OOB port%s log

Management IP: OOB port%s

Management port is up.

Source	Severity
PDT	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Manual area entry exists

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Manual area entry exists log

Manual area entry exists

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Manual area error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Manual area error log

Manual area error

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Martian packet detected with destination address mask %s on port %d/%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Martian packet detected with destination address mask %s on port %d/%d log

Martian packet detected with destination address mask %s on port %d/%d

**Source**   **Severity**  
QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Martian packet detected with source address mask %s and destination address mask %s on port %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Martian packet detected with source address mask %s and destination address mask %s on port %d log

Martian packet detected with source address mask %s and destination address mask %s on port %d

Source	Severity
QoS	

Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Martian packet detected with source address mask %s on port %d/%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Martian packet detected with source address mask %s on port %d/%d log

Martian packet detected with source address mask %s on port %d/%d

Source	Severity
QoS	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Martian packet logging does not support metering

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Martian packet logging does not support metering log

Martian packet logging does not support metering

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Martian packet logging requires individual tracking statistics

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Martian packet logging requires individual tracking statistics log

Martian packet logging requires individual tracking statistics

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Maximum number of dynamic routes reached

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Maximum number of dynamic routes reached log

Maximum number of dynamic routes reached

The maximum number of total routes (static or dynamic) supported on the platform are reached.

Source	Severity
L3Mgr	Information

### Remedial action

Reconfigure the network so that the routes on the ERS device remain within the maximum allowed.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Maximum number of dynamic routes reached.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Maximum number of dynamic routes reached. log

Maximum number of dynamic routes reached.

Source	Severity
--------	----------

L3Mgr	
-------	--

Remedial action
-----------------

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Maximum users-per-interface limit (%d) reached

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Maximum users-per-interface limit (%d) reached log

Maximum users-per-interface limit (%d) reached

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Max-local is smaller than local configured interfaces number.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Max-local is smaller than local configured interfaces number. log

Max-local is smaller than local configured interfaces number.

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Max number of dynamic routes increased.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Max number of dynamic routes increased. log

Max number of dynamic routes increased.

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Max-static is smaller than local configured static routes number.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Max-static is smaller than local configured static routes number. log

Max-static is smaller than local configured static routes number.

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MCM group node corrupted:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MCM group node corrupted: log

MCM group node corrupted:

The multicast manager group note is corrupted.

Source	Severity
--------	----------

MCM	Critical
-----	----------

### Remedial action

No action Required

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Memory Allocation Error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Memory Allocation Error log

Memory Allocation Error

The system failed to get memory buffer.

Source	Severity
Console	Serious

### Remedial action

Report the error.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Memory on unit %d is under %d MBytes.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Memory on unit %d is under %d MBytes. log

Memory on unit %d is under %d MBytes.

The system memory has dropped under a certain value.

Source	Severity
Memory Tool	Critical

### Remedial action

Call Extreme Networks to collect memory information. Monitor free memory and prepare for rebooting the device if the memory continues to drop.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Meter distribution across stack failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Meter distribution across stack failed log

Meter distribution across stack failed

Unable to commit changes across the stack.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Meter entry referenced by clfr block (deletion prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Meter entry referenced by clfr block (deletion prohibited) log

Meter entry referenced by clfr block (deletion prohibited)

Cannot delete a meter if it's referenced in a classifier block.

Source	Severity
QoS	Serious

### Remedial action

Remove the classifier block first.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Meter entry referenced by meter (deletion prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Meter entry referenced by meter (deletion prohibited) log

Meter entry referenced by meter (deletion prohibited)

Cannot delete a meter if it's referenced by another.

Source	Severity
QoS	Serious

### Remedial action

Delete the other meter first.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Meter entry referenced by policy (deletion prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Meter entry referenced by policy (deletion prohibited) log

Meter entry referenced by policy (deletion prohibited)

Cannot delete a meter if it's referenced by a policy.

Source	Severity
QoS	Serious

### Remedial action

Remove the policy first.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Meter (from clfr block) usage in multiple policies prohibited

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Meter (from clfr block) usage in multiple policies prohibited log

Meter (from clfr block) usage in multiple policies prohibited

The meter specified in classifier block is already used by a policy.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Specify a different meter/classifier block, create a new one or remove the conflicting policy.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Meter (from policy) usage in multiple policies prohibited

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Meter (from policy) usage in multiple policies prohibited log

Meter (from policy) usage in multiple policies prohibited

The meter specified is already used by a policy.

Source	Severity
QoS	Serious

### Remedial action

Specify a different meter, create a new one or remove the conflicting policy.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Meter identifier out-of-range (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Meter identifier out-of-range (%d) log

Meter identifier out-of-range (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Meter identifier out-of-range ( meter id )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Meter identifier out-of-range ( meter id ) log

Meter identifier out-of-range ( meter id )

If it is a user entry the meter identifier must be between 1 and 55000. For a system entry the range is 55001-65535.

Source	Severity
QoS	Serious

### Remedial action

Enter a valid meter identifier.



# Metering not supported with DS L2 access control lists

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Metering not supported with DS L2 access control lists log

Metering not supported with DS L2 access control lists

Metering is not supported for ACLs DS(IP) or L2.

Source	Severity
QoS	Serious

### Remedial action

Enter DS/L2 classifier element or drop metering option.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Metering not supported with DS/L2 access control lists

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Metering not supported with DS/L2 access control lists log

Metering not supported with DS/L2 access control lists

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Meter modifications not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Meter modifications not supported log

Meter modifications not supported

The system detected an internal error; The specified modifier option not supported.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Metric value is invalid for narrow type

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Metric value is invalid for narrow type log

Metric value is invalid for narrow type

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MHSA Auto-Configuration completed on port %s.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MHSA Auto-Configuration completed on port %s. log

MHSA Auto-Configuration completed on port %s.

MSA Autoconfiguration succeeded on a particular port.

Source	Severity
EAP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MHSA Auto-Configuration failed on port %s - eap status is unauthorized.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MHSA Auto-Configuration failed on port %s - eap status is unauthorized. log

MHSA Auto-Configuration failed on port %s - eap status is unauthorized.

MHSA Autoconfiguration failed because eap status is unauthorised.

Source	Severity
EAP	Information

### Remedial action

Manually change EAP status to force unauthorised. Disconnect and reconnect the FA client

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MHSA Auto-Configuration failed on port %s - port is RSPAN destination.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MHSA Auto-Configuration failed on port %s - port is RSPAN destination. log

MHSA Auto-Configuration failed on port %s - port is RSPAN destination.

MHSA Autoconfiguration failed because port is involved in RSPAN.

Source	Severity
EAP	Information

### Remedial action

Remove the port from RSPAN instance. Disconnect and reconnect the FA client.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# MHSA Auto-Configuration failed on port %s - port mirroring is enabled.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MHSA Auto-Configuration failed on port %s - port mirroring is enabled. log

MHSA Auto-Configuration failed on port %s - port mirroring is enabled.

MHSA Autoconfiguration failed because port is involved in port mirroring.

Source	Severity
EAP	Information

### Remedial action

Remove the port from port mirroring instance. Disconnect and reconnect the FA client.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Min LSP interval should not be $\geq$ max LSP

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Min LSP interval should not be $\geq$ max LSP log

Min LSP interval should not be  $\geq$  max LSP

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Mirroring (requested via action) not configured correctly

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Mirroring (requested via action) not configured correctly log

Mirroring (requested via action) not configured correctly

The metering is not configured correctly.

Source	Severity
QoS	Serious

### Remedial action

Inspect and correct the necessary entries, check documentation if necessary.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLD: Filters could NOT be installed.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLD: Filters could NOT be installed. log

MLD: Filters could NOT be installed.

Not enough QOS resources available.

Source	Severity
MLD	Information

### Remedial action

Disable other applications that requires QOS resources but are not actively used.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLD: Filters successfully installed.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLD: Filters successfully installed. log

MLD: Filters successfully installed.

MLD is enabled.

Source	Severity
MLD	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLD: HW ipmc entries exceeded

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLD: HW ipmc entries exceeded log

MLD: HW ipmc entries exceeded

**Source   Severity**

MLD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLD: Maximum number of mld enabled interfaces reached

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLD: Maximum number of mld enabled interfaces reached log

MLD: Maximum number of mld enabled interfaces reached

Maximum number of MLD enabled interfaces reached.

Source	Severity
MLD	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLD: The maximum number of available hardware MLD entries has been reached

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLD: The maximum number of available hardware MLD entries has been reached log

MLD: The maximum number of available hardware MLD entries has been reached

Ipmc entries exceeded.

Source	Severity
MLD	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# MLD: The maximum number of available hardware MLD entries has been reached

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLD: The maximum number of available hardware MLD entries has been reached log

MLD: The maximum number of available hardware MLD entries has been reached

The maximum number of available hardware MLD entries has been reached.

Source	Severity
MLD	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT %d disabled due to: %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d disabled due to: %s log

MLT %d disabled due to: %s

**Source    Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



MLT debug: %d, %d, %x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT debug: %d, %d, %x log

MLT debug: %d, %d, %x

**Source**   **Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT %d failed configuration verification.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. log

MLT %d failed configuration verification.

**Source    Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT %d failed configuration verification. Bad ARP INSPECTION configuration.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Bad ARP INSPECTION configuration. log

MLT %d failed configuration verification. Bad ARP INSPECTION configuration.

ARP INSPECTION config is not consistent on all trunk members for the displayed MLT trunk number.

Source	Severity
MLT	Information

### Remedial action

Check ARP INSPECTION config and set the same ARP INSPECTION parameters for all trunk members.



# MLT %d failed configuration verification. Bad DHCP-SNOOPING configuration.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Bad DHCP-SNOOPING configuration. log

MLT %d failed configuration verification. Bad DHCP-SNOOPING configuration.

DHCP-SNOOPING config is not consistent on all trunk members for the MLT trunk number.

Source	Severity
--------	----------

MLT	Information
-----	-------------

### Remedial action

Check DHCP-SNOOPING config and set the same DHCP-SNOOPING parameters for all trunk members.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT %d failed configuration verification. Bad IGMP configuration.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Bad IGMP configuration. log

MLT %d failed configuration verification. Bad IGMP configuration.

IGMP config is not consistent on all trunk members for the displayed MLT trunk number.

Source	Severity
--------	----------

MLT	Information
-----	-------------

### Remedial action

Check IGMP config and set the same IGMP parameters for all trunk members.



# MLT %d failed configuration verification. Bad IPSG CLASS configuration.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Bad IPSG CLASS configuration. log

MLT %d failed configuration verification. Bad IPSG CLASS configuration.

IPSG config is not consistent on all trunk members for the displayed MLT trunk number.

Source	Severity
MLT	Information

### Remedial action

Check IPSG CLASS config and set the same IPSG CLASS parameters for all trunk members.





MLT %d failed configuration verification.  
Bad ISPG CLASS configuration.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Bad ISPG CLASS configuration. log

MLT %d failed configuration verification. Bad ISPG CLASS configuration.

**Source    Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT %d failed configuration verification. Bad MAC learning configuration.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Bad MAC learning configuration. log

MLT %d failed configuration verification. Bad MAC learning configuration.

Mac-learning config is not consistent on all trunk members.

Source	Severity
--------	----------

MLT	Information
-----	-------------

### Remedial action

Check MAC-learning config and set the same MAC-learning parameters for all trunk members.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT %d failed configuration verification. Bad rate-limiting configuration.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Bad rate-limiting configuration. log

MLT %d failed configuration verification. Bad rate-limiting configuration.

Rate-limit config is not consistent on all trunk members for the displayed MLT trunk number.

Source	Severity
--------	----------

MLT	Information
-----	-------------

### Remedial action

Check rate-limit config and set the same rate-limit parameters for all trunk members.



# MLT %d failed configuration verification. Bad SLPP-guard configuration.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Bad SLPP-guard configuration. log

MLT %d failed configuration verification. Bad SLPP-guard configuration.

The trunk ports have different SLPP-guard settings.

Source	Severity
--------	----------

MLT	Information
-----	-------------

### Remedial action

Configure the same SLPP-guard mode and timeout for all ports belonging to the same trunk.



# MLT %d failed configuration verification. Bad SPBM configuration.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Bad SPBM configuration. log

MLT %d failed configuration verification. Bad SPBM configuration.

SPBM config is not consistent on all trunk members for the displayed MLT trunk number.

Source	Severity
MLT	Information

### Remedial action

Check SPBM config and set the same SPBM parameters for all trunk members.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



MLT %d failed configuration verification.  
Bad STORM CONTROL configuration.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Bad STORM CONTROL configuration. log

MLT %d failed configuration verification. Bad STORM CONTROL configuration.

Source	Severity
MLT	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT %d failed configuration verification. Bad VLACP configuration

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Bad VLACP configuration log

MLT %d failed configuration verification. Bad VLACP configuration

VLACP config is not consistent on all trunk members for the displayed MLT trunk number.

Source	Severity
--------	----------

MLT	Information
-----	-------------

### Remedial action

Check VLACP config and set the same VLACP parameters for all trunk members.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT %d failed configuration verification. Bad VLAN configuration.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Bad VLAN configuration. log

MLT %d failed configuration verification. Bad VLAN configuration.

VLAN config is not consistent on all trunk members for the displayed MLT trunk number.

Source	Severity
--------	----------

MLT	Information
-----	-------------

### Remedial action

Check VLAN config and set the same VLAN parameters for all trunk members.





# MLT %d failed configuration verification. Error #: %d-%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Error #: %d-%d log

MLT %d failed configuration verification. Error #: %d-%d

**Source    Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT %d failed configuration verification. Ports are in different static VLANs.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Ports are in different static VLANs. log

MLT %d failed configuration verification. Ports are in different static VLANs.

The trunk ports belong to different static VLANs.

Source	Severity
MLT	Information

### Remedial action

Configure the same static VLAN IDs for all ports belonging to the same trunk.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT %d failed configuration verification. Ports are in different VLANs.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Ports are in different VLANs. log

MLT %d failed configuration verification. Ports are in different VLANs.

The trunk ports belong to different VLANs.

Source	Severity
--------	----------

MLT	Information
-----	-------------

### Remedial action

Configure the same VLAN IDs for all ports belonging to the same trunk.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



MLT %d failed configuration verification.  
Ports have different private-vlan port  
type.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Ports have different private-vlan port type. log

MLT %d failed configuration verification. Ports have different private-vlan port type.

The trunk ports have different private-vlan port type settings.

Source	Severity
--------	----------

MLT	Information
-----	-------------

### Remedial action

Configure the same private-vlan port type for all ports belonging to the same trunk.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT %d failed configuration verification. Ports have different static vlan PVIDs.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Ports have different static vlan PVIDs. log

MLT %d failed configuration verification. Ports have different static vlan PVIDs.

The trunk ports have different static VALN PVID settings.

Source	Severity
--------	----------

MLT	Information
-----	-------------

### Remedial action

Configure the same static VLAN PVID for all ports belonging to the same trunk.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



MLT %d failed configuration verification.  
Ports have different static vlan tagging.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Ports have different static vlan tagging. log

MLT %d failed configuration verification. Ports have different static vlan tagging.

The trunk ports have different static VLAN tagging settings.

Source	Severity
--------	----------

MLT	Information
-----	-------------

### Remedial action

Configure the same static VLAN tagging for all ports belonging to the same trunk.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



MLT %d failed configuration verification.  
Ports have different VLACP admin  
enable state.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Ports have different VLACP admin enable state. log

MLT %d failed configuration verification. Ports have different VLACP admin enable state.

The trunk ports have different VLACP admin state settings.

Source	Severity
--------	----------

MLT	Information
-----	-------------

### Remedial action

Configure the same VLACP admin state for all ports belonging to the same trunk.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT %d failed configuration verification. Ports have different VLACP ethertype.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Ports have different VLACP ethertype. log

MLT %d failed configuration verification. Ports have different VLACP ethertype.

The trunk ports have different VLACP ethertype settings.

Source	Severity
MLT	Information

### Remedial action

Configure the same VLACP ethertype for all ports belonging to the same trunk.





MLT %d failed configuration verification.  
Ports have different VLACP fast periodic  
time value.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Ports have different VLACP fast periodic time value. log

MLT %d failed configuration verification. Ports have different VLACP fast periodic time value.

The trunk ports have different VLACP fast periodic time values.

Source	Severity
--------	----------

MLT	Information
-----	-------------

### Remedial action

Configure the same VLACP fast periodic time value for all ports belonging to the same trunk.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



MLT %d failed configuration verification.  
Ports have different VLACP mac  
address.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Ports have different VLACP mac address. log

MLT %d failed configuration verification. Ports have different VLACP mac address.

The trunk ports have different VLACP MAC address settings.

Source	Severity
--------	----------

MLT	Information
-----	-------------

### Remedial action

Configure the same VLACP MAC address for all ports belonging to the same trunk.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



MLT %d failed configuration verification.  
Ports have different VLACP slow periodic  
time value.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Ports have different VLACP slow periodic time value. log

MLT %d failed configuration verification. Ports have different VLACP slow periodic time value.

The trunk ports have different VLACP slow periodic time values.

Source	Severity
--------	----------

MLT	Information
-----	-------------

### Remedial action

Configure the same VLACP slow periodic time value for all ports belonging to the same trunk.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT %d failed configuration verification. Ports have different VLACP timeout scale.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Ports have different VLACP timeout scale. log

MLT %d failed configuration verification. Ports have different VLACP timeout scale.

The trunk ports have different VLACP timeout scale settings.

Source	Severity
MLT	Information

### Remedial action

Configure the same VLACP timeout scale for all ports belonging to the same trunk.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT %d failed configuration verification. Ports have different VLACP timeout type.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Ports have different VLACP timeout type. log

MLT %d failed configuration verification. Ports have different VLACP timeout type.

The trunk ports have different VLACP timeout type settings.

Source	Severity
--------	----------

MLT	Information
-----	-------------

### Remedial action

Configure the same VLACP timeout type for all ports belonging to the same trunk.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT %d failed configuration verification. Ports have different vlan priorities.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Ports have different vlan priorities. log

MLT %d failed configuration verification. Ports have different vlan priorities.

The trunk ports have different VLAN priority settings.

Source	Severity
--------	----------

MLT	Information
-----	-------------

### Remedial action

Configure the same VLAN priority for all ports belonging to the same trunk.



# MLT %d failed configuration verification. Ports have different vlan PVIDs.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Ports have different vlan PVIDs. log

MLT %d failed configuration verification. Ports have different vlan PVIDs.

The trunk ports have different VLAN PVID settings.

Source	Severity
MLT	Information

### Remedial action

Configure the same VLAN PVID for all ports belonging to the same trunk.



MLT %d failed configuration verification.  
Ports have different vlan tag frames  
filter settings.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Ports have different vlan tag frames filter settings. log

MLT %d failed configuration verification. Ports have different vlan tag frames filter settings.

The trunk ports have different VLAN tag frames filter settings.

Source	Severity
--------	----------

MLT	Information
-----	-------------

### Remedial action

Configure the same VLAN tag frames filter for all ports belonging to the same trunk.





# MLT %d failed configuration verification. Ports have different vlan tagging.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Ports have different vlan tagging. log

MLT %d failed configuration verification. Ports have different vlan tagging.

The trunk ports have different VLAN tagging settings.

Source	Severity
--------	----------

MLT	Information
-----	-------------

### Remedial action

Configure the same VLAN tagging for all ports belonging to the same trunk.



MLT %d failed configuration verification.  
Ports have different vlan unreg frames  
filter settings.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Ports have different vlan unreg frames filter settings. log

MLT %d failed configuration verification. Ports have different vlan unreg frames filter settings.

The trunk ports have different VLAN unreg frames filter settings.

Source	Severity
--------	----------

MLT	Information
-----	-------------

### Remedial action

Configure the same VLAN unreg frames filter for all ports belonging to the same trunk.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



MLT %d failed configuration verification.  
Ports have different vlan untag frames  
filter settings.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT %d failed configuration verification. Ports have different vlan untag frames filter settings. log

MLT %d failed configuration verification. Ports have different vlan untag frames filter settings.

The trunk ports have different VLAN untag frames filter settings.

Source	Severity
--------	----------

MLT	Information
-----	-------------

### Remedial action

Configure the same VLAN untag frames filter for all ports belonging to the same trunk.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT Distribute DB fail

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT Distribute DB fail log

MLT Distribute DB fail

**Source**   **Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT failed to get STP sync semaphore.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT failed to get STP sync semaphore. log

MLT failed to get STP sync semaphore.

**Source    Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT get buffer failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT get buffer failed log

MLT get buffer failed

**Source**   **Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT get module info fail

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT get module info fail log

MLT get module info fail

**Source**   **Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT get msgQ RX fail

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT get msgQ RX fail log

MLT get msgQ RX fail

**Source**   **Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# MLT get msgQ unknown cmd

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT get msgQ unknown cmd log

MLT get msgQ unknown cmd

**Source**   **Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT get stack event invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT get stack event invalid log

MLT get stack event invalid

**Source**   **Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT ID# failed configuration verification. Error # error num

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT ID# failed configuration verification. Error # error num log

MLT ID# failed configuration verification. Error # error num

The MLT #(1-32) verification check failed.

Source	Severity
MLT	Information

### Remedial action

Change the configuration and re-enable the MLT.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT IMC acknowledge error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT IMC acknowledge error log

MLT IMC acknowledge error

**Source**   **Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT IMC get buffer fail

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT IMC get buffer fail log

MLT IMC get buffer fail

**Source**   **Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT IMC invalid cmd

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT IMC invalid cmd log

MLT IMC invalid cmd

**Source**   **Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT IMC set link fail

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT IMC set link fail log

MLT IMC set link fail

**Source**   **Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT IMC set name fail

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT IMC set name fail log

MLT IMC set name fail

**Source**   **Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# MLT IMC set state fail

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT IMC set state fail log

MLT IMC set state fail

**Source**   **Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT IMC set STP fail

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT IMC set STP fail log

MLT IMC set STP fail

**Source**   **Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT IMC set trunk with bad parameters

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT IMC set trunk with bad parameters log

MLT IMC set trunk with bad parameters

**Source**   **Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT IMC subType invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT IMC subType invalid log

MLT IMC subType invalid

**Source**   **Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT IMC tx error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT IMC tx error log

MLT IMC tx error

**Source**   **Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT Join module DB fail

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT Join module DB fail log

MLT Join module DB fail

**Source**   **Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



mlt look up database has been attached  
to CDT (fn addr=0x%08x)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## mlt look up database has been attached to CDT (fn addr=0x%08x) log

mlt look up database has been attached to CDT (fn addr=0x%08x)

Source	Severity
CDT	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT misconfiguration may be on Trunk #1.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT misconfiguration may be on Trunk #1. log

MLT misconfiguration may be on Trunk #1.

**Source**   **Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# MLT misconfiguration may be on Trunk #2.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT misconfiguration may be on Trunk #2. log

MLT misconfiguration may be on Trunk #2.

**Source**   **Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT misconfiguration may be on Trunk #3.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT misconfiguration may be on Trunk #3. log

MLT misconfiguration may be on Trunk #3.

**Source**   **Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT misconfiguration may be on Trunk #4.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT misconfiguration may be on Trunk #4. log

MLT misconfiguration may be on Trunk #4.

**Source**   **Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT misconfiguration may be on Trunk #5.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT misconfiguration may be on Trunk #5. log

MLT misconfiguration may be on Trunk #5.

**Source**   **Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT misconfiguration may be on Trunk #6.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT misconfiguration may be on Trunk #6. log

MLT misconfiguration may be on Trunk #6.

**Source**   **Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT NV File error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT NV File error log

MLT NV File error

The system failed to read or write to the NVRAM file.

Source	Severity
MLT	Information

### Remedial action

Run the diagnostics to see if the NVRAM is still correct.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT NV File reset

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT NV File reset log

MLT NV File reset

**Source**   **Severity**

MLT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Modification of action (non-match usage) prohibited

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Modification of action (non-match usage) prohibited log

Modification of action (non-match usage) prohibited

The action can not be modified currently as it is associated with a policy and not an individual classifier.

Source	Severity
QoS	Serious

### Remedial action

Remove the policy or create a new action.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Modify the pattern data or use the correct data format

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Modify the pattern data or use the correct data format log

Modify the pattern data or use the correct data format

UnknownIpMcast attribute must be true or false. QPA internal error.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MODULE\_INACTIVE event sent unit mask value appl mask value

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MODULE\_INACTIVE event sent unit mask value appl mask value log

MODULE\_INACTIVE event sent unit mask value appl mask value

A unit has left the stack. The 'unit mask' is a bit mask representation of the unit that left the stack.

Source	Severity
Stack Manager	Information

### Remedial action

Make sure that the unit removal is intended.



# More than %d units discovered

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## More than %d units discovered log

More than %d units discovered

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# More than value units discovered

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## More than value units discovered log

More than value units discovered

Too many units are in the stack.

Source	Severity
Stack Manager	Information

### Remedial action

Remove the extra unit(s).

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Msg not sent, "numUnits" to big - %s line %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Msg not sent, "numUnits" to big - %s line %d log

Msg not sent, "numUnits" to big - %s line %d

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Multicast block unit/port %d/%d level %u watermark %u

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Multicast block unit/port %d/%d level %u watermark %u log

Multicast block unit/port %d/%d level %u watermark %u

**Source    Severity**

SC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Multicast over high watermark unit/port %d/%d level %u watermark %u

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Multicast over high watermark unit/port %d/%d level %u watermark %u log

Multicast over high watermark unit/port %d/%d level %u watermark %u

Source	Severity
SC	

Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Multicast still blocked unit/port %d/%d level %u watermark %u

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Multicast still blocked unit/port %d/%d level %u watermark %u log

Multicast still blocked unit/port %d/%d level %u watermark %u

**Source**   **Severity**

SC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





Multicast still over low watermark  
unit/port %d/%d level %u watermark  
%u

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Multicast still over low watermark unit/port %d/%d level %u watermark %u log

Multicast still over low watermark unit/port %d/%d level %u watermark %u

**Source**   **Severity**  
SC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Multicast unblock unit/port %d/%d level %u watermark %u

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Multicast unblock unit/port %d/%d level %u watermark %u log

Multicast unblock unit/port %d/%d level %u watermark %u

**Source   Severity**

SC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Multicast under low watermark unit/port %d/%d level %u watermark %u

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Multicast under low watermark unit/port %d/%d level %u watermark %u log

Multicast under low watermark unit/port %d/%d level %u watermark %u

Source	Severity
SC	

Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Multiple base units detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Multiple base units detected log

Multiple base units detected

The system detected more than one configured base unit.

Source	Severity
Stack Manager	Information

### Remedial action

Reconfigure the extra base unit(s) to non-base units.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Multiple Waverunner units detected when base is a Flagship

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Multiple Waverunner units detected when base is a Flagship log

Multiple Waverunner units detected when base is a Flagship

Too many ERS56XX units are in stack.

Source	Severity
Stack Manager	Information

### Remedial action

Remove the extra 56XX unit(s) or make 56XX the base unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Must change node nickname after updating the system ID

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Must change node nickname after updating the system ID log

Must change node nickname after updating the system ID

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



MVLAN vid=%d ip=%#x msk=%#x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MVLAN vid=%d ip=%#x msk=%#x log

MVLAN vid=%d ip=%#x msk=%#x

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



name

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## name log

name

description

Source	Severity
source	severity

### Remedial action

remedialAction





# Narrow metric is not supported in SPBM mode

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Narrow metric is not supported in SPBM mode log

Narrow metric is not supported in SPBM mode

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# NEAP Accounting - Memory allocation failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NEAP Accounting - Memory allocation failure log

NEAP Accounting - Memory allocation failure

A NEAP accounting packet could not be allocated.

Source	Severity
EAP	Serious

### Remedial action

Reboot the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# NEAP Accounting: Memory allocation failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NEAP Accounting: Memory allocation failure log

NEAP Accounting: Memory allocation failure

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



NEAP Client blocked - MAC  
%02x:%02x:%02x:%02x:%02x:%02x.  
All bindings have been rejected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. All bindings have been rejected log

NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. All bindings have been rejected

**Source   Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



NEAP Client blocked - MAC  
%02x:%02x:%02x:%02x:%02x:%02x.  
All NRAVs or Bindings from RADIUS are  
invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. All NRAVs or Bindings from RADIUS are invalid log

NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. All NRAVs or Bindings from RADIUS are invalid

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



NEAP Client blocked - MAC  
%02x:%02x:%02x:%02x:%02x:%02x.  
Already authenticated by other method.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Already authenticated by other method. log

NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Already authenticated by other method.

The NEAP client is already authenticated using other NEAP method.

Source	Severity
EAP	Information

### Remedial action

None



# NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Cannot use FA bindings in Legacy networks

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Cannot use FA bindings in Legacy networks log

NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Cannot use FA bindings in Legacy networks

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



NEAP Client blocked - MAC  
%02x:%02x:%02x:%02x:%02x:%02x.  
EAP FA context unknown network

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. EAP FA context unknown network log

NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. EAP FA context unknown network

**Source**   **Severity**  
EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





NEAP Client blocked - MAC  
%02x:%02x:%02x:%02x:%02x:%02x.  
Maximum number of VLANs reached

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Maximum number of VLANs reached log

NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Maximum number of VLANs reached

**Source    Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Only MHSA mode supports multiple NRAVs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Only MHSA mode supports multiple NRAVs log

NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Only MHSA mode supports multiple NRAVs

### Source   Severity

EAP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Receiving unconfigured VLAN from Radius without Autocreate

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Receiving unconfigured VLAN from Radius without Autocreate log

NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Receiving unconfigured VLAN from Radius without Autocreate

### Source    Severity

EAP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



NEAP Client blocked - MAC  
%02x:%02x:%02x:%02x:%02x:%02x.  
Vlan:Isid bindings exceeded the  
maximum threshold of 16

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid bindings exceeded the maximum threshold of 16 log

NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid bindings exceeded the maximum threshold of 16

### Source    Severity

EAP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



NEAP Client blocked - MAC  
%02x:%02x:%02x:%02x:%02x:%02x.  
Vlan:Isid bindings exceeded the  
maximum threshold of 94

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid bindings exceeded the maximum threshold of 94 log

NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid bindings exceeded the maximum threshold of 94

Source	Severity
EAP	Information

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid not supported in MHMA and SHSA

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid not supported in MHMA and SHSA log

NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid not supported in MHMA and SHSA

### Source    Severity

EAP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



NEAP Client blocked - MAC  
%02x:%02x:%02x:%02x:%02x:%02x.  
Vlan:Isid with different Isid from the  
configured one is invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with different Isid from the configured one is invalid log

NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with different Isid from the configured one is invalid

**Source    Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with Isid equal to 0 not supported in FA SPB networks

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with Isid equal to 0 not supported in FA SPB networks log

NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with Isid equal to 0 not supported in FA SPB networks

### Source    Severity

EAP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





NEAP Client blocked - MAC  
%02x:%02x:%02x:%02x:%02x:%02x.  
Vlan:Isid with Isid <> 0 not supported  
in Standalone Proxy or Autoprov

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with Isid <> 0 not supported in Standalone Proxy or Autoprov log

NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with Isid <> 0 not supported in Standalone Proxy or Autoprov

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



## NEAP Client

%02x:%02x:%02x:%02x:%02x:%02x:  
Vlan %d not created. Maximum number  
of VLANs reached

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NEAP Client %02x:%02x:%02x:%02x:%02x:%02x: Vlan %d not created. Maximum number of VLANs reached log

NEAP Client %02x:%02x:%02x:%02x:%02x:%02x: Vlan %d not created. Maximum number of VLANs reached

### Source    Severity

EAP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



NEAP: MAC -  
%02x:%02x:%02x:%02x:%02x:%02x.  
Binding already set for client, pushed  
trusted bindings will be ingored.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NEAP: MAC - %02x:%02x:%02x:%02x:%02x:%02x. Binding already set for client, pushed trusted bindings will be ingored. log

NEAP: MAC - %02x:%02x:%02x:%02x:%02x:%02x. Binding already set for client, pushed trusted bindings will be ingored.

### Source   Severity

EAP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



NEAP: MAC -  
%02x:%02x:%02x:%02x:%02x:%02x.  
Invalid Fabric-Attach-Client-Trust value

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NEAP: MAC - %02x:%02x:%02x:%02x:%02x:%02x. Invalid Fabric-Attach-Client-Trust value log

NEAP: MAC - %02x:%02x:%02x:%02x:%02x:%02x. Invalid Fabric-Attach-Client-Trust value

Source	Severity
EAP	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



NEAP: MAC -  
%02x:%02x:%02x:%02x:%02x:%02x.  
Multiple trusted bindings supported only  
in MHSA

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NEAP: MAC - %02x:%02x:%02x:%02x:%02x:%02x. Multiple trusted bindings supported only in MHSA log

NEAP: MAC - %02x:%02x:%02x:%02x:%02x:%02x. Multiple trusted bindings supported only in MHSA

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



NEAP: MAC -  
%02x:%02x:%02x:%02x:%02x:%02x.  
Number of ranges exceeded the  
maximum threshold of 10

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NEAP: MAC - %02x:%02x:%02x:%02x:%02x:%02x. Number of ranges exceeded the maximum threshold of 10 log

NEAP: MAC - %02x:%02x:%02x:%02x:%02x:%02x. Number of ranges exceeded the maximum threshold of 10

### Source    Severity

EAP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



NEAP: MAC -  
%02x:%02x:%02x:%02x:%02x:%02x.  
Ranges are ignored

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NEAP: MAC - %02x:%02x:%02x:%02x:%02x:%02x. Ranges are ignored log

NEAP: MAC - %02x:%02x:%02x:%02x:%02x:%02x. Ranges are ignored

**Source**   **Severity**  
EAP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



## NEAP Phone

%02x:%02x:%02x:%02x:%02x:%02x migrated from port %d/%d.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NEAP Phone %02x:%02x:%02x:%02x:%02x:%02x migrated from port %d/%d. log

NEAP Phone %02x:%02x:%02x:%02x:%02x:%02x migrated from port %d/%d.

The NEAP Phone is detected on a new port and is removed from the old one.

Source	Severity
--------	----------

EAP	Information
-----	-------------

### Remedial action

None





# NEAP: Pvid attribute from RADIUS ignored,

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NEAP: Pvid attribute from RADIUS ignored, log

NEAP: Pvid attribute from RADIUS ignored,

**Source**   **Severity**

EAP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# NEAP: Receiving unsupported Auto-Create-VLAN VSA in SHSA or MHMA

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NEAP: Receiving unsupported Auto-Create-VLAN VSA in SHSA or MHMA log

NEAP: Receiving unsupported Auto-Create-VLAN VSA in SHSA or MHMA

**Source**   **Severity**  
EAP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Network access settings for FCoE Redirect must be modified locally

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Network access settings for FCoE Redirect must be modified locally log

Network access settings for FCoE Redirect must be modified locally

Enable/disable of FCoE Redirect functionality limited to CLI.

Source	Severity
FCoE Redirect	Information

### Remedial action

Utilize CLI for feature enable/disable.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Network access to FCoE Redirect functionality is currently disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Network access to FCoE Redirect functionality is currently disabled log

Network access to FCoE Redirect functionality is currently disabled

**Source**   **Severity**  
QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# New IP Route Partitioning becomes effective on next L3/L2 mode change.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## New IP Route Partitioning becomes effective on next L3/L2 mode change. log

New IP Route Partitioning becomes effective on next L3/L2 mode change.

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



New time:%s, old:%s, src:%s.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## New time:%s, old:%s, src:%s. log

New time:%s, old:%s, src:%s.

**Source**   **Severity**

CLOCK

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Nickname range 3.33.xx is reserved:  
coresponding mac used by IPv6  
multicast

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Nickname range 3.33.xx is reserved: coresponding mac used by IPv6 multicast log

Nickname range 3.33.xx is reserved: coresponding mac used by IPv6 multicast

The nickname is reserved.

Source	Severity
SPB	Information

### Remedial action

Choose a different nickname.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# NNI is not supported over SMLT ports

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NNI is not supported over SMLT ports log

NNI is not supported over SMLT ports

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Non-EAP Client blocked (Block Subsequent MAC Authentication): Different VID than expected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Non-EAP Client blocked (Block Subsequent MAC Authentication): Different VID than expected log

Non-EAP Client blocked (Block Subsequent MAC Authentication): Different VID than expected

A Non-EAP client was blocked because it had a different Radius Assigned VLAN than the previous one

Source	Severity
EAP	Information

### Remedial action

Check the Attributes sent by RADIUS Server.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Non-EAP Client blocked (Block Subsequent MAC Authentication): EAP Use Rav Not enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Non-EAP Client blocked (Block Subsequent MAC Authentication): EAP Use Rav Not enabled log

Non-EAP Client blocked (Block Subsequent MAC Authentication): EAP Use Rav Not enabled

An EAP client was blocked because Non-EAP Radius Assigned VLAN is not enabled

Source	Severity
EAP	Information

### Remedial action

Check the Attributes sent by RADIUS Server.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Non-match action contains conflicting data

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Non-match action contains conflicting data log

Non-match action contains conflicting data

Unable to install the specified non-match action, conflicting data detected.

Source	Severity
QoS	Serious

### Remedial action

Identify conflicts and separate them into different non-match actions.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Non-match action not available for use with filter sets

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Non-match action not available for use with filter sets log

Non-match action not available for use with filter sets

The non-match action drop must be deferred for access assign type NSNA, user based policy and traffic profile.

Source	Severity
QoS	Serious

### Remedial action

Remove the non-match action option.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Non-match action support not available on certain interfaces

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Non-match action support not available on certain interfaces log

Non-match action support not available on certain interfaces

Non-match actions can only be applied to certain interfaces.

Source	Severity
QoS	Serious

### Remedial action

Specify a compatible interface or drop the non-match action.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Non-QoS interfaces may not be assigned to a role combination

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Non-QoS interfaces may not be assigned to a role combination log

Non-QoS interfaces may not be assigned to a role combination

Interface type is prohibited. For example cascade (internal) ports should not be associated with a roleCombination since classification is prohibited on these interfaces.

Source	Severity
QoS	Serious

### Remedial action

Enter an interface compatible with QoS.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Non-supported action option (green action) specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Non-supported action option (green action) specified log

Non-supported action option (green action) specified

Action criteria or storage type is not compatible with the action criteria type specified (green action).

Source	Severity
QoS	Serious

### Remedial action

Enter a compatible action.



# Non-supported action option (in-profile action) specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Non-supported action option (in-profile action) specified log

Non-supported action option (in-profile action) specified

Failed to validate the in-profile action that is associated. Certain actions may be required or forbidden.

Source	Severity
QoS	Serious

### Remedial action

Check documentation and use a valid in-profile action.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Non-supported action option (match action) specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Non-supported action option (match action) specified log

Non-supported action option (match action) specified

Failed to validate the match action that is associated. Certain actions may be required or forbidden.

Source	Severity
QoS	Serious

### Remedial action

Check documentation and use a valid match action.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Non-supported action option (out-of-profile action) specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Non-supported action option (out-of-profile action) specified log

Non-supported action option (out-of-profile action) specified

Failed to validate the out-of-profile action that is associated. Certain actions may be required or forbidden.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Check documentation and use a valid out-of-profile action.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Non-supported action option (policy non-match action) specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Non-supported action option (policy non-match action) specified log

Non-supported action option (policy non-match action) specified

Failed to validate the non-match action that is associated. Certain actions may be required or forbidden.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Check documentation and use a valid non-match action.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Non-supported action option (red action) specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Non-supported action option (red action) specified log

Non-supported action option (red action) specified

Action criteria or storage type is not compatible with the action criteria type specified (red action).

Source	Severity
QoS	Serious

### Remedial action

Enter a compatible action.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Non-supported action option (yellow action) specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Non-supported action option (yellow action) specified log

Non-supported action option (yellow action) specified

Action criteria or storage type is not compatible with the action criteria type specified (yellow action).

Source	Severity
QoS	Serious

### Remedial action

Enter a compatible action.



# Non-unique element label detected (prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Non-unique element label detected (prohibited) log

Non-unique element label detected (prohibited)

The same label is used to identify a different entry of the same type.

Source	Severity
QoS	Information

### Remedial action

Enter a different label.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Non-unique FCoE redirection entry name detected (prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Non-unique FCoE redirection entry name detected (prohibited) log

Non-unique FCoE redirection entry name detected (prohibited)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Non-unique precedence order value detected (prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Non-unique precedence order value detected (prohibited) log

Non-unique precedence order value detected (prohibited)

There is already an existing mask on the specified precedence on the current interface.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Enter a different precedence/interface or remove the conflicting mask.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Non-volatile QoS data discarded during restoration

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Non-volatile QoS data discarded during restoration log

Non-volatile QoS data discarded during restoration

Certain QoS data was discarded (possible because of an upgrade).

Source	Severity
QoS	Serious

### Remedial action

Check the QoS data and complete it manually.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Non-volatile storage commit delay too large

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Non-volatile storage commit delay too large log

Non-volatile storage commit delay too large

The maximum non-volatile storage commit delay is 604800.

Source	Severity
QoS	Serious

### Remedial action

Enter a smaller commit delay value.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Non-zero pattern data detected in masked position

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Non-zero pattern data detected in masked position log

Non-zero pattern data detected in masked position

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# No resources available for classifier port range checking

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## No resources available for classifier port range checking log

No resources available for classifier port range checking

The resources required are not available on all the ports in the specified range.

Source	Severity
QoS	Serious

### Remedial action

Modify either the port range or the demanding resources.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# No resources available for classifier range checking

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## No resources available for classifier range checking log

No resources available for classifier range checking

**Source   Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# No Response from RADIUS Server

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## No Response from RADIUS Server log

No Response from RADIUS Server

FailOpenVLAN Continuity mode was triggered because there was no response from Radius for a MAC address of a certain client.

Source	Severity
Radius	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



no room in cam, cannot add address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## no room in cam, cannot add address log

no room in cam, cannot add address

**Source   Severity**

CDT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# No stack ports available

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## No stack ports available log

No stack ports available

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Not Enough Memory

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Not Enough Memory log

Not Enough Memory

This message appears when there is not enough buffer

Source	Severity
Console	Serious

### Remedial action

Report the error.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Notice: DAC Cable on %s is below HW rev "H" and may cause link issues with a small number of PHYs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Notice: DAC Cable on %s is below HW rev "H" and may cause link issues with a small number of PHYs log

Notice: DAC Cable on %s is below HW rev "H" and may cause link issues with a small number of PHYs

Informs the user that he has inserted an outdated HW revision DAC.

Source	Severity
--------	----------

PDT	Information
-----	-------------

### Remedial action

Replace with DAC that has HW Revision "H" or above.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# NSNA filter set assignment failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NSNA filter set assignment failed log

NSNA filter set assignment failed

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# NSNA filter set count (%d) exceeds limit (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NSNA filter set count (%d) exceeds limit (%d) log

NSNA filter set count (%d) exceeds limit (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# NSNA filter set data in use (QoS disable prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NSNA filter set data in use (QoS disable prohibited) log

NSNA filter set data in use (QoS disable prohibited)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# NSNA filter set data in use (QoS reset prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NSNA filter set data in use (QoS reset prohibited) log

NSNA filter set data in use (QoS reset prohibited)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# NSNA filter set delete operation failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NSNA filter set delete operation failed log

NSNA filter set delete operation failed

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# NSNA filter set element count exceeds available resources

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NSNA filter set element count exceeds available resources log

NSNA filter set element count exceeds available resources

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# NSNA filter set install operation failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NSNA filter set install operation failed log

NSNA filter set install operation failed

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# NSNA filter set template does not exist

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NSNA filter set template does not exist log

NSNA filter set template does not exist

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# NSNA filter set update operation failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NSNA filter set update operation failed log

NSNA filter set update operation failed

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# NSNA system port transition failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NSNA system port transition failed log

NSNA system port transition failed

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



NSX\_Retrieve\_Events ... cur=0x%08X  
error=%d errno=0x%X.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NSX\_Retrieve\_Events ... cur=0x%08X error=%d errno=0x%X. log

NSX\_Retrieve\_Events ... cur=0x%08X error=%d errno=0x%X.

**Source**      **Severity**

ENGMENU

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



NSX\_Retrieve\_Events ERR  
event\_group: %p req=0x%08X  
op=%d...

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NSX\_Retrieve\_Events ERR event\_group:%p req=0x%08X op=%d... log

NSX\_Retrieve\_Events ERR event\_group:%p req=0x%08X op=%d...

Source	Severity
ENGMENU	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# NT application mode enable failure - inadequate resources

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NT application mode enable failure - inadequate resources log

NT application mode enable failure - inadequate resources

The required resources for AutoQos to become enable are not available.

Source	Severity
QoS	Serious

### Remedial action

Check for and remove unneeded resources and try again.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# NTP synchronized

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NTP synchronized log

NTP synchronized

**Source**   **Severity**

NTP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# numberAssignment ack received from unit #%%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## numberAssignment ack received from unit #%%d log

numberAssignment ack received from unit #%%d

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Number assignment message not received

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Number assignment message not received log

Number assignment message not received

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Number of VLANs does not match BU number of VLANs. VLAN config defaulted

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Number of VLANs does not match BU number of VLANs. VLAN config defaulted log

Number of VLANs does not match BU number of VLANs. VLAN config defaulted

VLAN configuration was defaulted because the current number of VLANs does not match the Base Unit number of VLANs.

Source	Severity
VLAN	Information

### Remedial action

No action required.



# Number of VLANs does not match BU number of VLANs. VLAN config defaulted

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Number of VLANs does not match BU number of VLANs. VLAN config defaulted log

Number of VLANs does not match BU number of VLANs. VLAN config defaulted

The Non-Base Unit has a different number of VLANs than the Base Unit at dbexchange point.

Source	Severity
VLAN	Information

### Remedial action

Reconfigure the port settings for this Non-Base Unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# NUQC - Disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NUQC - Disabled log

NUQC - Disabled

The NUQC feature is disabled.

Source	Severity
NUQC	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# NUQC - Enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NUQC - Enabled log

NUQC - Enabled

The NUQC feature is enabled.

Source	Severity
NUQC	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# NUQC - Execution of the cli template failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NUQC - Execution of the cli template failed log

NUQC - Execution of the cli template failed

The NUQC script execution failed.

Source	Severity
NUQC	Information

### Remedial action

Verify the syntax of the NUQC script.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# NUQC - Execution of the cli template succeeded

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## NUQC - Execution of the cli template succeeded log

NUQC - Execution of the cli template succeeded

The NUQC script executed succesfully.

Source	Severity
NUQC	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# OCP server running.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## OCP server running. log

OCP server running.

**Source   Severity**

WEB

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Ok

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ok log

Ok

**Source   Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Only one frame type supported per classifier

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Only one frame type supported per classifier log

Only one frame type supported per classifier

The maximum frame types supported in a classifier is one.

Source	Severity
QoS	Serious

### Remedial action

Separate the frame types into multiple system classifiers.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Only one SPBM instance allowed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Only one SPBM instance allowed log

Only one SPBM instance allowed

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ospf Area Mismatch:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf Area Mismatch: log

Ospf Area Mismatch:

**Source    Severity**

OSPF

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ospf Area Mismatch RxArea ra.rb.rc.rd IntfArea ia.ib.ic.id

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf Area Mismatch RxArea ra.rb.rc.rd IntfArea ia.ib.ic.id log

Ospf Area Mismatch RxArea ra.rb.rc.rd IntfArea ia.ib.ic.id

An OSPF Area mismatch is detected between the OSPF packet Area ID and the interface Area ID.

Source	Severity
ospf(drpmgr)	Information

### Remedial action

show ip ospf interface VLAN <VID>; reconfigure OSPF Area ID at the switch or at the neighbor to match.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ospf Auth Failed:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf Auth Failed: log

Ospf Auth Failed:

**Source    Severity**

OSPF

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ospf Auth Failed IpAddr ia.ib.ic.id

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf Auth Failed IpAddr ia.ib.ic.id log

Ospf Auth Failed IpAddr ia.ib.ic.id

OSPF authentication failed at the given Interface IP Address when verifying the OSPF packet.

Source	Severity
ospf(drpmgr)	Information

### Remedial action

show ip ospf interface VLAN <VID>; reconfigure OSPF authType and related information at the switch or at the neighbor to match.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Ospf Auth Type Mismatch in Hello

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf Auth Type Mismatch in Hello log

Ospf Auth Type Mismatch in Hello

Reports the OSPF authentication mismatch on the neighboring interfaces.

Source	Severity
OSPF	Information

### Remedial action

Verify that OSPF authentication parameters match on the neighboring interfaces.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ospf Auth Type Mismatch in Hello:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf Auth Type Mismatch in Hello: log

Ospf Auth Type Mismatch in Hello:

**Source    Severity**

OSPF

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ospf Auto Virt Link Failed:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf Auto Virt Link Failed: log

Ospf Auto Virt Link Failed:

**Source**   **Severity**

OSPF

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ospf Auto Virt Link Failed area a1.a2.a3.a4 rtid r1.r2.r3.r4

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf Auto Virt Link Failed area a1.a2.a3.a4 rtid r1.r2.r3.r4 log

Ospf Auto Virt Link Failed area a1.a2.a3.a4 rtid r1.r2.r3.r4

OSPF auto creation of virtual link failed as it exceeds the maximum 4 allowed.

Source	Severity
ospf(drpmgr)	Information

### Remedial action

Show IP OSPF virtual-link to see if any of the existing ones need to be removed; worst case, bounce OSPF to see if this clears it.



# Ospf Bad Version

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf Bad Version log

Ospf Bad Version

Reports the OSPF version mismatch.

Source	Severity
OSPF	Information

### Remedial action

Verify the OSPF version.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ospf Bad Version:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf Bad Version: log

Ospf Bad Version:

**Source    Severity**

OSPF

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# OSPF Callback function of timer is NULL

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## OSPF Callback function of timer is NULL log

OSPF Callback function of timer is NULL

Reports an OSPF bad timer failure (ex: bad LSA received).

Source	Severity
OSPF	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# OSPF Callback function of timer is NULL:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## OSPF Callback function of timer is NULL: log

OSPF Callback function of timer is NULL:

**Source**   **Severity**

OSPF

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Ospf Cost Exceeds Limit:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf Cost Exceeds Limit: log

Ospf Cost Exceeds Limit:

**Source**   **Severity**

OSPF

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ospf Cost Exceeds Limit Skip route Lsid I1.I2.I3.I4 Adv-rtr a1.a2.a3.a4

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf Cost Exceeds Limit Skip route Lsid I1.I2.I3.I4 Adv-rtr a1.a2.a3.a4 log

Ospf Cost Exceeds Limit Skip route Lsid I1.I2.I3.I4 Adv-rtr a1.a2.a3.a4

OSPF LSA Calculated cost exceeds limit of 0xFFFFFFFF.

Source	Severity
ospf(drpmgr)	Information

### Remedial action

Show IP OSPF redistribute and show route-map; check metric; correct as needed; may need actions at the neighbor.



# OspfDbg Done Filter Init

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## OspfDbg Done Filter Init log

OspfDbg Done Filter Init

Describes the start-up sequence of OSPF initializations on reboot.

Source	Severity
OSPF	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# OspfDbg Done Global Init

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## OspfDbg Done Global Init log

OspfDbg Done Global Init

Describes the start-up sequence of OSPF initializations on reboot.

Source	Severity
OSPF	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# OspfDbg Done Global Init

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## OspfDbg Done Global Init log

OspfDbg Done Global Init

**Source**   **Severity**

OSPF

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# OspfDbg Done NV-Restore

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## OspfDbg Done NV-Restore log

OspfDbg Done NV-Restore

Describes the start-up sequence of OSPF initializations on reboot.

Source	Severity
OSPF	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# OspfDbg Done NV-Restore

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## OspfDbg Done NV-Restore log

OspfDbg Done NV-Restore

**Source**   **Severity**

OSPF

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# OspfDbg Done ReDist Init

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## OspfDbg Done ReDist Init log

OspfDbg Done ReDist Init

Describes the start-up sequence of OSPF initializations on reboot.

Source	Severity
OSPF	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# OspfDbg Done ReDist Init

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## OspfDbg Done ReDist Init log

OspfDbg Done ReDist Init

**Source**   **Severity**

OSPF

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# OspfDbg Init Instance vrfId=%d nodeP=0x%0x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## OspfDbg Init Instance vrfId=%d nodeP=0x%0x log

OspfDbg Init Instance vrfId=%d nodeP=0x%0x

Describes the start-up sequence of OSPF initializations on reboot.

Source	Severity
OSPF	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# OspfDbg Init Instance vrfId=%d nodeP=0x%0x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## OspfDbg Init Instance vrfId=%d nodeP=0x%0x log

OspfDbg Init Instance vrfId=%d nodeP=0x%0x

**Source   Severity**

OSPF

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# OspfDbg PostInit Done vrfId=%d nodeP=0x%0x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## OspfDbg PostInit Done vrfId=%d nodeP=0x%0x log

OspfDbg PostInit Done vrfId=%d nodeP=0x%0x

Describes the start-up sequence of OSPF initializations on reboot.

Source	Severity
OSPF	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# OspfDbg PostInit Done vrfId=%d nodeP=0x%0x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## OspfDbg PostInit Done vrfId=%d nodeP=0x%0x log

OspfDbg PostInit Done vrfId=%d nodeP=0x%0x

**Source**   **Severity**

OSPF

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# OspfDbg PostInit EnableOspf vrfId=%d nodeP=0x%0x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## OspfDbg PostInit EnableOspf vrfId=%d nodeP=0x%0x log

OspfDbg PostInit EnableOspf vrfId=%d nodeP=0x%0x

Describes the start-up sequence of OSPF initializations on reboot.

Source	Severity
OSPF	Information

### Remedial action

No action required.



# OspfDbg PostInit EnableOspf vrflId=%d nodeP=0x%0x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## OspfDbg PostInit EnableOspf vrflId=%d nodeP=0x%0x log

OspfDbg PostInit EnableOspf vrflId=%d nodeP=0x%0x

### Source    Severity

OSPF

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# OspfDbg Started ospfTxHelloTimerTask

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## OspfDbg Started ospfTxHelloTimerTask log

OspfDbg Started ospfTxHelloTimerTask

Describes the start-up sequence of OSPF initializations on reboot.

Source	Severity
OSPF	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# OspfDbg Started ospfTxHelloTimerTask

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## OspfDbg Started ospfTxHelloTimerTask log

OspfDbg Started ospfTxHelloTimerTask

**Source**   **Severity**

OSPF

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ospf Dead Int Mismatch in Hello

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf Dead Int Mismatch in Hello log

Ospf Dead Int Mismatch in Hello

Reports the OSPF Dead interval mismatch on the neighboring interfaces.

Source	Severity
OSPF	Information

### Remedial action

Verify that OSPF Dead Int parameters match on the neighboring interfaces.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ospf Dead Int Mismatch in Hello:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf Dead Int Mismatch in Hello: log

Ospf Dead Int Mismatch in Hello:

**Source    Severity**

OSPF

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ospf Enable Failed as Resource Unavailable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf Enable Failed as Resource Unavailable log

Ospf Enable Failed as Resource Unavailable

The system detected an OSPF Hardware Resource Allocation Failure in the ERS5510 Mode.

Source	Severity
ospf(drpmgr)	Information

### Remedial action

Re-do QoS filter allocations and restart the switch or OSPF or global routing.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ospf Hello Int Mismatch in Hello

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf Hello Int Mismatch in Hello log

Ospf Hello Int Mismatch in Hello

Reports the OSPF Hello interval mismatch on the neighboring interfaces.

Source	Severity
OSPF	Information

### Remedial action

Verify that OSPF Hello parameters match on the neighboring interfaces.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ospf Hello Int Mismatch in Hello:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf Hello Int Mismatch in Hello: log

Ospf Hello Int Mismatch in Hello:

**Source    Severity**

OSPF

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ospf Hello: RId Same as Neighbor:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf Hello: RId Same as Neighbor: log

Ospf Hello: RId Same as Neighbor:

**Source**   **Severity**

OSPF

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ospf Hello: RId Same as Neighbor: rtid <r1.r2.r3.r4>, IpAddr <i1.i2.i3.i4>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf Hello: RId Same as Neighbor: rtid <r1.r2.r3.r4>, IpAddr <i1.i2.i3.i4> log

Ospf Hello: RId Same as Neighbor: rtid <r1.r2.r3.r4>, IpAddr <i1.i2.i3.i4>

Ospf Hello received at given Interface has the same RouterId as the switch.

Source	Severity
ospf(drpmgr)	Information

### Remedial action

Show IP OSPF at the switch and at the neighbor; ensure the router IDs are different.





# Ospf HW Mode Change:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf HW Mode Change: log

Ospf HW Mode Change:

The OSPF Hardware Mode changed to the given new mode.

Source	Severity
ospf(drpmgr)	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ospf Invalid packet received:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf Invalid packet received: log

Ospf Invalid packet received:

**Source    Severity**

OSPF

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ospf Invalid packet received: Pkt type <ospfPacketType>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf Invalid packet received: Pkt type <ospfPacketType> log

Ospf Invalid packet received: Pkt type <ospfPacketType>

The OSPF Link State Update packet received is invalid; packet is dropped.

Source	Severity
ospf(drpmgr)	Information

### Remedial action

Either lsa is too small (<20 bytes) or too big (> (1500-64 for headers); or wrong number of lsas; retry bouncing OSPF at the neighbor or redo parts of neighbor configuration.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ospf License Is Missing, Disable OSPF

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf License Is Missing, Disable OSPF log

Ospf License Is Missing, Disable OSPF

OSPF License is missing; inconsistency expected if the OSPF is enabled in the NVRAM configuration.

Source	Severity
ospf(drpmgr)	Information

### Remedial action

Show license; Check for available licenses; A valid license is needed for the OSPF functionality.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ospf Nbr State Change:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf Nbr State Change: log

Ospf Nbr State Change:

**Source    Severity**

OSPF

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ospf Nbr State Change: rtid <ra.rb.rc.rd> ipa <ia.ib.ic.id> state <neighborState>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf Nbr State Change: rtid <ra.rb.rc.rd> ipa <ia.ib.ic.id> state <neighborState> log

Ospf Nbr State Change: rtid <ra.rb.rc.rd> ipa <ia.ib.ic.id> state <neighborState>

OSPF Nbr State Change: for given Neighbor Router ID, Address and State.

Source	Severity
ospf(drpmgr)	Information

### Remedial action

No action required.



# Ospf Netmask Mismatch in Hello:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf Netmask Mismatch in Hello: log

Ospf Netmask Mismatch in Hello:

**Source   Severity**

OSPF

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ospf Netmask Mismatch in Hello IpAddr ia.ib.ic.id

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf Netmask Mismatch in Hello IpAddr ia.ib.ic.id log

Ospf Netmask Mismatch in Hello IpAddr ia.ib.ic.id

There is an OSPF Netmask Mismatch between the netmask of IP Address in the hello packet and the netmask of the Interface IP Address.

Source	Severity
ospf(drpmgr)	Information

### Remedial action

show VLAN IP VID <VLANID> at the switch and the neighbor - reconfigure IP address/mask as needed to match.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Ospf Option Mismatch in Hello:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf Option Mismatch in Hello: log

Ospf Option Mismatch in Hello:

**Source**   **Severity**

OSPF

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ospf Option Mismatch in Hello IpAddr ia.ib.ic.id RxOption optionVal IntfOption optionVal

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf Option Mismatch in Hello IpAddr ia.ib.ic.id RxOption optionVal IntfOption optionVal log

Ospf Option Mismatch in Hello IpAddr ia.ib.ic.id RxOption optionVal IntfOption optionVal

OSPF Hello option Mismatch for stub or nssa area selection in the packet vs that of the interface area.

Source	Severity
ospf(drpmgr)	Information

### Remedial action

show ip ospf interface VLAN <VID> to find areaId of interface; show ip ospf area <areaID> to check if area type ; reconfigure these as needed.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# OSPF Timer Link Error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## OSPF Timer Link Error log

OSPF Timer Link Error

Reports an OSPF bad timer failure (ex: bad LSA received).

Source	Severity
OSPF	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# OSPF Timer Link Error:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## OSPF Timer Link Error: log

OSPF Timer Link Error:

**Source**   **Severity**

OSPF

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# OSPF Timer List is corrupted

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## OSPF Timer List is corrupted log

OSPF Timer List is corrupted

Reports an OSPF bad timer failure (ex: bad LSA received).

Source	Severity
OSPF	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# OSPF Timer List is corrupted:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## OSPF Timer List is corrupted: log

OSPF Timer List is corrupted:

**Source   Severity**

OSPF

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# OSPF Timer Unlink Error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## OSPF Timer Unlink Error log

OSPF Timer Unlink Error

Reports an OSPF bad timer failure (ex: bad LSA received).

Source	Severity
OSPF	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# OSPF Timer Unlink Error:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## OSPF Timer Unlink Error: log

OSPF Timer Unlink Error:

**Source**   **Severity**

OSPF

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Ospf Virt Nbr State Change:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf Virt Nbr State Change: log

Ospf Virt Nbr State Change:

**Source    Severity**

OSPF

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Ospf Virt Nbr State Change: rtid <r1.r2.r3.r4>, virtAreaId <v1.v2.v3.v4>, state <neighborState>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Ospf Virt Nbr State Change: rtid <r1.r2.r3.r4>, virtAreaId <v1.v2.v3.v4>, state <neighborState> log

Ospf Virt Nbr State Change: rtid <r1.r2.r3.r4>, virtAreaId <v1.v2.v3.v4>, state <neighborState>

OSPF Virtual Neighbor of given routerID and areaID changed to a given state.

Source	Severity
ospf(drpmgr)	Information

### Remedial action

No action required.



# Out-of-profile action contains conflicting data

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Out-of-profile action contains conflicting data log

Out-of-profile action contains conflicting data

Unable to install the specified out-of-profile action, conflicting data detected.

Source	Severity
QoS	Serious

### Remedial action

Identify conflicts and separate them into different out-of-profile actions.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Out-of-range CoS index value ( COS index value )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Out-of-range CoS index value ( COS index value ) log

Out-of-range CoS index value ( COS index value )

The valid CoS index range is 0 to 7.

Source	Severity
QoS	Serious

### Remedial action

Enter a CoS index value within the specified valid range.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Out-of-range CoS index value (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Out-of-range CoS index value (%d) log

Out-of-range CoS index value (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Out-of-range queue index value (%d) for in-use queue set

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Out-of-range queue index value (%d) for in-use queue set log

Out-of-range queue index value (%d) for in-use queue set

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Out-of-range queue index value (%d) for pending queue set

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Out-of-range queue index value (%d) for pending queue set log

Out-of-range queue index value (%d) for pending queue set

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Out-of-range queue index value (%d) specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Out-of-range queue index value (%d) specified log

Out-of-range queue index value (%d) specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Out-of-range queue index value ( queue index ) for in-use queue set

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Out-of-range queue index value ( queue index ) for in-use queue set log

Out-of-range queue index value ( queue index ) for in-use queue set

The queue set must be between 1 and the runtime default queue set.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Check the agent default queue set and modify the value accordingly.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Out-of-range queue index value ( queue index ) for pending queue set

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Out-of-range queue index value ( queue index ) for pending queue set log

Out-of-range queue index value ( queue index ) for pending queue set

The queue set must be between 1 and the runtime default queue set.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Check the agent default queue set and modify your value accordingly.



# Overload cannot be disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Overload cannot be disabled log

Overload cannot be disabled

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Overload on startup is out of range

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Overload on startup is out of range log

Overload on startup is out of range

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Packet redirection support limited by target interfaces

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Packet redirection support limited by target interfaces log

Packet redirection support limited by target interfaces

Target interfaces are version 2 (Currently, all version 2 interfaces support redirection for all packet types or none) and do not support redirection for non-unicast packets.

Source	Severity
QoS	Serious

### Remedial action

Enter a different interface/port number.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Packet reordering detected (re: new mappings)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Packet reordering detected (re: new mappings) log

Packet reordering detected (re: new mappings)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Password exists

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Password exists log

Password exists

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Password policy has changed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Password policy has changed log

Password policy has changed

**Source   Severity**

AAA

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Pattern matching data in excess of bytes# bytes specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Pattern matching data in excess of bytes# bytes specified log

Pattern matching data in excess of bytes# bytes specified

The maximum pattern data length is 16 for 45XX and 32 for the rest of the platforms.

Source	Severity
QoS	Serious

### Remedial action

Separate the pattern matching data into multiple system classifiers so it fits the maximum length specified.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Pattern matching data in excess of %d bytes specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Pattern matching data in excess of %d bytes specified log

Pattern matching data in excess of %d bytes specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Pattern matching (Dst IP) not supported with IP addr type data

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Pattern matching (Dst IP) not supported with IP addr type data log

Pattern matching (Dst IP) not supported with IP addr type data

System classifiers with pattern matching (Dst IP) cannot be used with IP address type data.

Source	Severity
QoS	Serious

### Remedial action

Separate the conflicting elements into multiple classifier sets.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Pattern matching (Dst MAC) not supported with address type data

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Pattern matching (Dst MAC) not supported with address type data log

Pattern matching (Dst MAC) not supported with address type data

System classifiers with pattern matching (Dst MAC) cannot be used with address type data.

Source	Severity
QoS	Serious

### Remedial action

Separate the conflicting elements into multiple classifier sets.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Pattern matching (IP) not supported with non-IP addr type data

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Pattern matching (IP) not supported with non-IP addr type data log

Pattern matching (IP) not supported with non-IP addr type data

IP pattern matching (ipv4 or ipv6) used with UnknownNonIpMcast,NonIpMcast or NonIpPkt option.

Source	Severity
QoS	Serious

### Remedial action

Remove IP patter matching or non-IP type data from the system classifier.



# Pattern matching not supported with other classification data

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Pattern matching not supported with other classification data log

Pattern matching not supported with other classification data

System classifiers with pattern matching can only be used with default ip or/and I2 classifiers in the same classifier set.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Separate the conflicting elements into multiple classifier sets.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Pattern modifier data specified without actual pattern data

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Pattern modifier data specified without actual pattern data log

Pattern modifier data specified without actual pattern data

Pattern-related attributes have been set but pattern data is not specified.

Source	Severity
QoS	Serious

### Remedial action

Remove pattern-related attributes or specify patter data to avoid confusion.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Pattern position and data strings must be same length

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Pattern position and data strings must be same length log

Pattern position and data strings must be same length

Different lengths detected: pattern position and data strings.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Use pattern position and data strings of the same length.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Peer certificate validation against same CA, expiry and chain order is success

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Peer certificate validation against same CA, expiry and chain order is success log

Peer certificate validation against same CA, expiry and chain order is success

Source	Severity
IKE	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Peer certificate validation failed with status: %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Peer certificate validation failed with status:%s log

Peer certificate validation failed with status:%s

**Source    Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Pending filter control block already defined

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Pending filter control block already defined log

Pending filter control block already defined

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Pim Active RP change:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Pim Active RP change: log

Pim Active RP change:

**Source    Severity**

PIM

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Pim Assert change:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Pim Assert change: log

Pim Assert change:

**Source    Severity**

PIM

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Pim E-BSR change

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Pim E-BSR change log

Pim E-BSR change

A BSR with higher priority is detected. Logged only on BSR that changes.

Source	Severity
PIM	Information

### Remedial action

Check priority of the configured BSRs.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Pim E-BSR change:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Pim E-BSR change: log

Pim E-BSR change:

**Source    Severity**

PIM

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Pim Invalid packet received

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Pim Invalid packet received log

Pim Invalid packet received

PIM Control packets received are not conforming to the PIMv2 RFC 2362.

Source	Severity
PIM	Information

### Remedial action

Check if sending router conforms to PIMv2 specifications, or if packets are being corrupted in the network.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Pim Invalid packet received:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Pim Invalid packet received: log

Pim Invalid packet received:

**Source    Severity**

PIM

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Pim License Is Missing Disable PIM

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Pim License Is Missing Disable PIM log

Pim License Is Missing Disable PIM

PIM is a licensed feature. PIM can only be configured, but cannot be activated without a license.

Source	Severity
PIM	Information

### Remedial action

Contact the support personnel for an appropriate license.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Pim License Is Missing, Disable PIM

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Pim License Is Missing, Disable PIM log

Pim License Is Missing, Disable PIM

**Source**   **Severity**

PIM

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Pim Mode Change

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Pim Mode Change log

Pim Mode Change

Change from PIM SM mode to SSM or vice-versa.

Source	Severity
PIM	Information

### Remedial action

Check and ensure that a proper mode has been selected. Will lead to change in IP Multicast traffic flows in VLANs where mode has been changed.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Pim Mode Change:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Pim Mode Change: log

Pim Mode Change:

**Source    Severity**

PIM

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Pim Nbr State Change:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Pim Nbr State Change: log

Pim Nbr State Change:

**Source    Severity**

PIM

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Pim Nbr State Change Up

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Pim Nbr State Change Up log

Pim Nbr State Change Up

PIM\_NBR\_UP: A new neighbor is detected. It occurs when a PIM Hello message is received from an active PIM router. This can result in a change in IP multicast traffic flow if this neighbor is towards RP or BSR especially if combined with change in unicast routing.

Source	Severity
PIM	Information

### Remedial action

If the same neighbor is repeatedly appearing and disappearing, this is due to congestion in the link towards this neighbor. Check to see if unicast routing is also being affected as well as CPU utilization.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# PIM: Neighbor status change

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PIM: Neighbor status change log

PIM: Neighbor status change

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# PIM Neighbor status change Down

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PIM Neighbor status change Down log

PIM Neighbor status change Down

PIM\_NBR\_DOWN: An existing neighbor has timed out. This occurs when PIM Hello messages are not received from a neighbor within 3.5 times the query interval for an active PIM interface. This may lead to changes in the IP Multicast traffic flow.

Source	Severity
--------	----------

PIM	Information
-----	-------------

### Remedial action

Check if the neighbor router is functional and is sending out PIM Hellos.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# PIM Neighbor status change Up

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PIM Neighbor status change Up log

PIM Neighbor status change Up

PIM\_NBR\_UP: A new neighbor is detected, This occurs when a PIM Hello message is received from an active PIM router. This may result in change in IP multicast traffic flow if this neighbor is towards RP or BSR especially if combined with change in unicast routing.

Source	Severity
PIM	Information

### Remedial action

If the same neighbor is repeatedly appearing and disappearing, this is due to congestion in the link towards this neighbor. Check if unicast routing and CPU utilization is also being affected.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Pim not enabled due to HW resources on port

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Pim not enabled due to HW resources on port log

Pim not enabled due to HW resources on port

**Source    Severity**

PIM

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Pim RP type change:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Pim RP type change: log

Pim RP type change:

**Source**   **Severity**

PIM

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Pim RP type state

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Pim RP type state log

Pim RP type state

This message indicates the change from dynamic to static RP or the other way around.

Source	Severity
PIM	Information

### Remedial action

If changing to static RP, ensure this is configured in the entire PIM domain. Also, BSR information will be lost and will need to be re-configured if moving to Dynamic RPs.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Pim Unicast route change

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Pim Unicast route change log

Pim Unicast route change

Unicast route towards a source or RP has changed. This can result in changes in IP multicast traffic flow. Indicates if the route towards source or RP has been modified or deleted.

Source	Severity
PIM	Information

### Remedial action

Check unicast routing / ARP tables and ensure that these are correct.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Pim Unicast route change:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Pim Unicast route change: log

Pim Unicast route change:

**Source**   **Severity**

PIM

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Pim Virt Nbr State Change:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Pim Virt Nbr State Change: log

Pim Virt Nbr State Change:

**Source    Severity**

PIM

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Pim Virt Nbr State Change Down

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Pim Virt Nbr State Change Down log

Pim Virt Nbr State Change Down

PIM\_NBR\_DOWN: A configured virtual neighbor is deleted.

Source	Severity
PIM	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Pim Virt Nbr State Change Up

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Pim Virt Nbr State Change Up log

Pim Virt Nbr State Change Up

PIM\_NBR\_UP: A virtual neighbor has been configured.

Source	Severity
PIM	Information

### Remedial action

Check the multicast routes and ensure proper flows, especially if used with static unicast routes.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# P1 IPv6 Dead Peer Detected. I/R: %s rAddr:%s status:%s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## P1 IPv6 Dead Peer Detected. I/R: %s rAddr:%s status:%s log

P1 IPv6 Dead Peer Detected. I/R: %s rAddr:%s status:%s

**Source    Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# P1 IPv6 SA Created. I/R: %s rAddr:%s status:%s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## P1 IPv6 SA Created. I/R: %s rAddr:%s status:%s log

P1 IPv6 SA Created. I/R: %s rAddr:%s status:%s

**Source   Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# P2 IPv6 SA Created. I/R: %s rAddr:%s status:%s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## P2 IPv6 SA Created. I/R: %s rAddr:%s status:%s log

P2 IPv6 SA Created. I/R: %s rAddr:%s status:%s

**Source    Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# P1 IPv6 SA Deleted. I/R: %s rAddr:%s status:%s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## P1 IPv6 SA Deleted. I/R: %s rAddr:%s status:%s log

P1 IPv6 SA Deleted. I/R: %s rAddr:%s status:%s

**Source    Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# P2 IPv6 SA Deleted. I/R: %s rAddr:%s status:%s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## P2 IPv6 SA Deleted. I/R: %s rAddr:%s status:%s log

P2 IPv6 SA Deleted. I/R: %s rAddr:%s status:%s

**Source    Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# P1 IPv6 SA Failed. I/R: %s rAddr:%s status:%s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## P1 IPv6 SA Failed. I/R: %s rAddr:%s status:%s log

P1 IPv6 SA Failed. I/R: %s rAddr:%s status:%s

### Source    Severity

IKE

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# P2 IPv6 SA Failed. I/R: %s rAddr:%s status:%s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## P2 IPv6 SA Failed. I/R: %s rAddr:%s status:%s log

P2 IPv6 SA Failed. I/R: %s rAddr:%s status:%s

### Source    Severity

IKE

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# P1 IPv6 SA lifetime expired. I/R: %s rAddr: %s status: %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## P1 IPv6 SA lifetime expired. I/R: %s rAddr:%s status:%s log

P1 IPv6 SA lifetime expired. I/R: %s rAddr:%s status:%s

**Source    Severity**

IKE

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



PM in port mirroring the old data were modified - feature Allow Traffic in mirror port was added.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PM in port mirroring the old data were modified - feature Allow Traffic in mirror port was added. log

PM in port mirroring the old data were modified - feature Allow Traffic in mirror port was added.

The Feature Allow Traffic in mirror port was added. In the upgrade situations when current image file will be replaced by the other image file in port mirroring module some features are possible to be added.

Source	Severity
PMT	Information

### Remedial action

No action required.



PM in port mirroring the old data were modified - feature Many to Many was added.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PM in port mirroring the old data were modified - feature Many to Many was added. log

PM in port mirroring the old data were modified - feature Many to Many was added.

The Many to Many feature was added. In upgrade situations when current image file will be replaced by the other image file in port mirroring module some features are possible to be added.

Source	Severity
--------	----------

PMT	Information
-----	-------------

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



PM in port mirroring the old data were modified - feature Many to One was added.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PM in port mirroring the old data were modified - feature Many to One was added. log

PM in port mirroring the old data were modified - feature Many to One was added.

The Many to One feature was added. In upgrade situations when the current image file will be replaced by the other image file in port mirroring module ome features are possible to be added.

Source	Severity
PMT	Information

### Remedial action

No action required.



PM in port mirroring the old data were modified - feature Many to One with 128bits was added.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PM in port mirroring the old data were modified - feature Many to One with 128bits was added. log

PM in port mirroring the old data were modified - feature Many to One with 128bits was added.

The Many to One feature with 128bits was added. In upgrade situations when the current image file will be replaced by the other image file in port mirroring module some features is possible to be added.

Source	Severity
PMT	Information

### Remedial action

No action required.



# PM: in port mirroring the old data were modified - feature RSPAN was added

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PM: in port mirroring the old data were modified - feature RSPAN was added log

PM: in port mirroring the old data were modified - feature RSPAN was added

After upgrade, the RSPAN feature was added

Source	Severity
Port Mirroring	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# PM in port mirroring the old data were modified - mode type was out of range.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PM in port mirroring the old data were modified - mode type was out of range. log

PM in port mirroring the old data were modified - mode type was out of range.

The mode type data saved in NVRAM is out of range for one port mirroring instance (ERS 2500, ERS 4000, ERS 55xx) or for one of the four port mirroring instances (ERS56xx).

Source	Severity
--------	----------

PMT	Information
-----	-------------

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>





PM in port mirroring the old data were modified - monitored portA was out of range.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PM in port mirroring the old data were modified - monitored portA was out of range. log

PM in port mirroring the old data were modified - monitored portA was out of range.

The monitored port A data saved in the NVRAM is out of range for one port mirroring instance (ERS 2500,ERS 4000,ERS 55xx) or for one of the four ort mirroring instances (ERS56xx).

Source	Severity
--------	----------

PMT	Information
-----	-------------

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



PM in port mirroring the old data were modified - monitored portB was out of range.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PM in port mirroring the old data were modified - monitored portB was out of range. log

PM in port mirroring the old data were modified - monitored portB was out of range.

The monitored port B data saved in the NVRAM is out of range for one port mirroring instance (ERS 2500, ERS 4000, ERS 55xx) or for one of the four port mirroring instances (ERS 56xx).

Source	Severity
--------	----------

PMT	Information
-----	-------------

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



PM in port mirroring the old data were modified - NVRAM file structure was changed.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PM in port mirroring the old data were modified - NVRAM file structure was changed. log

PM in port mirroring the old data were modified - NVRAM file structure was changed.

NVRAM file structure was changed. This message appears when the downgrade/upgrade of images is completed.

Source	Severity
--------	----------

PMT	Information
-----	-------------

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# PM in port mirroring the old data were modified - probe port was out of range.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PM in port mirroring the old data were modified - probe port was out of range. log

PM in port mirroring the old data were modified - probe port was out of range.

The probe port data saved in the NVRAM is out of range for one port mirroring instance (ERS 2500, ERS 4000, ERS 55xx) or for one of the four port mirroring instances (ERS 56xx).

Source	Severity
PMT	Information

### Remedial action

No action required.



PM: mirroring data modified - all data were changed to default.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PM: mirroring data modified - all data were changed to default. log

PM: mirroring data modified - all data were changed to default.

**Source   Severity**

PMT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# PM: mirroring data modified - mode type was out of range.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PM: mirroring data modified - mode type was out of range. log

PM: mirroring data modified - mode type was out of range.

### Source    Severity

PMT

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



PM: mirroring data modified - monitored portA was out of range.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PM: mirroring data modified - monitored portA was out of range. log

PM: mirroring data modified - monitored portA was out of range.

Source	Severity
PMT	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



PM: mirroring data modified - monitored portB was out of range.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PM: mirroring data modified - monitored portB was out of range. log

PM: mirroring data modified - monitored portB was out of range.

Source	Severity
PMT	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# PM: mirroring data modified - probe port was out of range.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PM: mirroring data modified - probe port was out of range. log

PM: mirroring data modified - probe port was out of range.

**Source    Severity**

PMT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# PM: mirroring data modified - RSPAN was corrupted

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PM: mirroring data modified - RSPAN was corrupted log

PM: mirroring data modified - RSPAN was corrupted

**Source**   **Severity**

PMT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# PM some port mirroring messages were stored to be displayd with delay.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PM some port mirroring messages were stored to be displayd with delay. log

PM some port mirroring messages were stored to be displayd with delay.

This message appears when the SYSLOG task runs before the port mirroring initialization function is called from the PORT MIRRORING task. This message is written first and is succeeded every time by the other port mirroring messages.

Source	Severity
--------	----------

PMT	Information
-----	-------------

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



PM: unable to create mirror for instance  
%d due to lack of available filter  
resources

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PM: unable to create mirror for instance %d due to lack of available filter resources log

PM: unable to create mirror for instance %d due to lack of available filter resources

**Source**   **Severity**

PMT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# PM unable to create mirror for instance instance number due to lack of available filter resources

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PM unable to create mirror for instance instance number due to lack of available filter resources log

PM unable to create mirror for instance instance number due to lack of available filter resources

Port mirroring initialization failed due to lack of hardware filters.

Source	Severity
--------	----------

PM	Information
----	-------------

### Remedial action

Disable other features which are using the filter resources. Use

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# PoE Main Power Usage Off

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PoE Main Power Usage Off log

PoE Main Power Usage Off

The power usage drops below the previously set threshold.

Source	Severity
PoE	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# PoE Main Power Usage On

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PoE Main Power Usage On log

PoE Main Power Usage On

Power consumption exceeded the configured threshold.

Source	Severity
PoE	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# PoE Module Reset

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PoE Module Reset log

PoE Module Reset

The PoE controller has been reset.

Source	Severity
PoE	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# PoE Port Detection Status:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PoE Port Detection Status: log

PoE Port Detection Status:

**Source    Severity**

POL

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# PoE Port Detection Status port# Status powerStatus

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PoE Port Detection Status port# Status powerStatus log

PoE Port Detection Status port# Status powerStatus

The system reports the current PoE port status each time a status change occurs.

Source	Severity
PoE	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# PoE The PoE power limit for port unit port has been changed to x Watts based on IP phone discovery settings

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PoE The PoE power limit for port unit port has been changed to x Watts based on IP phone discovery settings log

PoE The PoE power limit for port unit port has been changed to x Watts based on IP phone discovery settings

The PoE power limit is changed according to the PoE IP phone settings, because of the IP phone discovery mechanism.

Source	Severity
PoE	Information

### Remedial action

No action required.



# PoE The PoE power limit for port unit port has been restored to previous value x Watts

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PoE The PoE power limit for port unit port has been restored to previous value x Watts log

PoE The PoE power limit for port unit port has been restored to previous value x Watts

The PoE power limit is restored to the previous value, because of the IP phone disconnection.

Source	Severity
--------	----------

PoE	Information
-----	-------------

### Remedial action

No action required.



# PoE The PoE priority for port unit port has been changed to x based on IP phone discovery settings

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PoE The PoE priority for port unit port has been changed to x based on IP phone discovery settings log

PoE The PoE priority for port unit port has been changed to x based on IP phone discovery settings

The PoE priority changed according to the PoE IP phone settings, because of the IP phone discovery mechanism.

Source	Severity
--------	----------

PoE	Information
-----	-------------

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# PoE The PoE priority for port unit port has been restored to previous value x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PoE The PoE priority for port unit port has been restored to previous value x log

PoE The PoE priority for port unit port has been restored to previous value x

The PoE power priority is restored to the previous value, as the IP phone is disconnected.

Source	Severity
--------	----------

PoE	Information
-----	-------------

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Policies with session data must be port-based

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Policies with session data must be port-based log

Policies with session data must be port-based

Session policies must be port-based.

Source	Severity
QoS	Serious

### Remedial action

Modify the user policy entry or remove the session data.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Policy action out-of-range ( action# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Policy action out-of-range ( action# ) log

Policy action out-of-range ( action# )

If this is a user policy the action id must be between 1 and 55000. For a system entry the range is 55001-65535.

Source	Severity
QoS	Serious

### Remedial action

Specify a valid action id.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Policy action out-of-range (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Policy action out-of-range (%d) log

Policy action out-of-range (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Policy content incompatible with precedence allocation mode

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Policy content incompatible with precedence allocation mode log

Policy content incompatible with precedence allocation mode

The first policy/filter installed on a precedence dictates the precedence allocation mode. All subsequent policies must have the same mode.

Source	Severity
QoS	Information

### Remedial action

Free the precedence or move the new policy to a compatible precedence.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Policy content incompatible with target interface(s)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Policy content incompatible with target interface(s) log

Policy content incompatible with target interface(s)

The classifier(s) filter options used in the policy are not compatible with the target interface.

Source	Severity
QoS	Serious

### Remedial action

Enter a different interface or adapt classifier/policy.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Policy distribution across stack failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Policy distribution across stack failed log

Policy distribution across stack failed

Unable to commit changes across the stack.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Policy mask availability issue (space exhausted)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Policy mask availability issue (space exhausted) log

Policy mask availability issue (space exhausted)

Unable to find next available mask precedence for the specified port.

Source	Severity
QoS	Serious

### Remedial action

Check for and remove unneeded resources on that port.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Policy mask issue (space exhausted/precedence conflict)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Policy mask issue (space exhausted/precedence conflict) log

Policy mask issue (space exhausted/precedence conflict)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Policy modifications not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Policy modifications not supported log

Policy modifications not supported

The system detected an Internal error; The specified modifier option not supported.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Policy modification support limited

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Policy modification support limited log

Policy modification support limited

Policies under system control can be deleted but not modified. For user policies only certain modification are supported (if-group, port, name).

Source	Severity
QoS	Serious

### Remedial action

To change a different option remove policy and create a new one.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Policy non-match action out-of-range (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Policy non-match action out-of-range (%d) log

Policy non-match action out-of-range (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Policy non-match action out-of-range ( non-match action# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Policy non-match action out-of-range ( non-match action# ) log

Policy non-match action out-of-range ( non-match action# )

If this is a user policy the non-match action id must be between 1 and 55000. For a system entry the range is 55001-65535.

Source	Severity
QoS	Serious

### Remedial action

Specify a valid non-match action id.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Policy precedence conflict detected with non-QoS application

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Policy precedence conflict detected with non-QoS application log

Policy precedence conflict detected with non-QoS application

A non-QoS application is already using the precedence specified.

Source	Severity
QoS	Serious

### Remedial action

Enter a different precedence.



# Policy precedence value out-of-range for target interface(s)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Policy precedence value out-of-range for target interface(s) log

Policy precedence value out-of-range for target interface(s)

Precedence limits differ based on the underlying hardware support.

Source	Severity
QoS	Serious

### Remedial action

Enter a precedence compatible with the hardware limits for the specified interface or use a different one.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Policy requirements exceed available resources (slot %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Policy requirements exceed available resources (slot %d) log

Policy requirements exceed available resources (slot %d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Policy requirements exceed available resources (slot slot# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Policy requirements exceed available resources (slot slot# ) log

Policy requirements exceed available resources (slot slot# )

Not all the resources required for the policy are available on the base or non-base unit(s).

Source	Severity
QoS	Serious

### Remedial action

Modify either the interfaces or the demanding resources.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Policy statistics index out-of-range (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Policy statistics index out-of-range (%d) log

Policy statistics index out-of-range (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Policy statistics index out-of-range ( stats index )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Policy statistics index out-of-range ( stats index ) log

Policy statistics index out-of-range ( stats index )

Invalid policy tracking statistics. The supported types are: individual aggregate or disabled.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Specify a supported policy tracking statistics.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





Policy with this filtering values is already installed on this precedence

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Policy with this filtering values is already installed on this precedence log

Policy with this filtering values is already installed on this precedence

An identical policy detected on the same precedence and port.

Source	Severity
QoS	Serious

### Remedial action

Enter the existing policy.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# PoL nvRam file error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## PoL nvRam file error log

PoL nvRam file error

**Source    Severity**

POL

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Port %d blocked by VLACP due to end-partner down state

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Port %d blocked by VLACP due to end-partner down state log

Port %d blocked by VLACP due to end-partner down state

**Source**   **Severity**

VLACP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Port %d blocked by VLACP until end-partner connection reestablished

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Port %d blocked by VLACP until end-partner connection reestablished log

Port %d blocked by VLACP until end-partner connection reestablished

Blocking displayed port due to not receiving VLACP packages from partner.

Source	Severity
--------	----------

VLACP	Information
-------	-------------

### Remedial action

Check links between units or settings.



# Port %d/%d blocked by VLACP due to end-partner down state

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Port %d/%d blocked by VLACP due to end-partner down state log

Port %d/%d blocked by VLACP due to end-partner down state

**Source**   **Severity**

VLACP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Port %d/%d blocked by VLACP until end-partner connection reestablished

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Port %d/%d blocked by VLACP until end-partner connection reestablished log

Port %d/%d blocked by VLACP until end-partner connection reestablished

Source	Severity
VLACP	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Port %d/%d of MLT %d is disabled  
because it has wrong configuration

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Port %d/%d of MLT %d is disabled because it has wrong configuration log

Port %d/%d of MLT %d is disabled because it has wrong configuration

Source	Severity
MLT	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Port %d/%d reenabled by VLACP

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Port %d/%d reenabled by VLACP log

Port %d/%d reenabled by VLACP

**Source**   **Severity**

VLACP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Port %d reenabled by VLACP

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Port %d reenabled by VLACP log

Port %d reenabled by VLACP

VLACP message received from partner, re-enabling the displayed port.

Source	Severity
VLACP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Port is not member of VLAN

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Port is not member of VLAN log

Port is not member of VLAN

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Port %s of LAC with key %d is disabled because it has wrong configuration

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Port %s of LAC with key %d is disabled because it has wrong configuration log

Port %s of LAC with key %d is disabled because it has wrong configuration

The LACP port is disabled because its settings do not match the configuration on LAC ports sharing the same LACP key.

Source	Severity
LAC	Information

### Remedial action

LACP ports with the same admin key should have the same settings.



# Port unit# port# blocked by VLACP until end-partner connection reestablished

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Port unit# port# blocked by VLACP until end-partner connection reestablished log

Port unit# port# blocked by VLACP until end-partner connection reestablished

Port put to Listening by VLACP.

Source	Severity
VLACP	Information

### Remedial action

No action required.



# Port unit# port# reenabled by VLACP

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Port unit# port# reenabled by VLACP log

Port unit# port# reenabled by VLACP

Port put back to its state by VLACP.

Source	Severity
VLACP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Post-join ACL installation issue detected (ifc %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Post-join ACL installation issue detected (ifc %d) log

Post-join ACL installation issue detected (ifc %d)

**Source   Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Post-join ACL installation issue detected (ifc ifc# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Post-join ACL installation issue detected (ifc ifc# ) log

Post-join ACL installation issue detected (ifc ifc# )

ACL installation failed after a join stack event.

Source	Severity
QoS	Serious

### Remedial action

Try again or check the stack health. Further conclusions are drawn as this message appears either on base, non-base, all or some units in stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Post-join filter set installation issue detected (ifc %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Post-join filter set installation issue detected (ifc %d) log

Post-join filter set installation issue detected (ifc %d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Post-join filter set installation issue detected (ifc ifc# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Post-join filter set installation issue detected (ifc ifc# ) log

Post-join filter set installation issue detected (ifc ifc# )

Filter set installation failed after a join stack event.

Source	Severity
QoS	Serious

### Remedial action

Try again or check the stack health. Further conclusions are drawn as this message appears either on base, non-base, all or some of the units in stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Post-join policy installation issue detected (ifc %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Post-join policy installation issue detected (ifc %d) log

Post-join policy installation issue detected (ifc %d)

Unable to configure policies after a join stack event.

Source	Severity
QoS	Critical

### Remedial action

Try again or check stack health. Further conclusions can be drawn if this message appears either on base, non-base, all or some units in stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Post-join traffic-profile installation issue detected (ifc %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Post-join traffic-profile installation issue detected (ifc %d) log

Post-join traffic-profile installation issue detected (ifc %d)

**Source   Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Post-join traffic-profile installation issue detected (ifc ifc# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Post-join traffic-profile installation issue detected (ifc ifc# ) log

Post-join traffic-profile installation issue detected (ifc ifc# )

Traffic-profile installation failed after a join stack event.

Source	Severity
QoS	Serious

### Remedial action

Try again or check the stack health. Further conclusions are drawn as this message appears either on base, non-base, all or some of the units in stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Potential inconsistent access asgn state (Undo fail) detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Potential inconsistent access asgn state (Undo fail) detected log

Potential inconsistent access asgn state (Undo fail) detected

Inconsistent access assign state detected on the non base unit.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Try again later, reset the QoS agent, reset the unit or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Potential inconsistent access asgn state (Undo fail - unit %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Potential inconsistent access asgn state (Undo fail - unit %d) log

Potential inconsistent access asgn state (Undo fail - unit %d)

**Source   Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Potential inconsistent access elem state (Undo fail) detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Potential inconsistent access elem state (Undo fail) detected log

Potential inconsistent access elem state (Undo fail) detected

The system detected inconsistent access element state on the non base unit.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent, or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Potential inconsistent access elem state (Undo fail - unit %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Potential inconsistent access elem state (Undo fail - unit %d) log

Potential inconsistent access elem state (Undo fail - unit %d)

**Source   Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Potential inconsistent block state (Undo fail) detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Potential inconsistent block state (Undo fail) detected log

Potential inconsistent block state (Undo fail) detected

Inconsistent block state detected on non base unit.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Potential inconsistent ifc assignment state (Undo fail) detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Potential inconsistent ifc assignment state (Undo fail) detected log

Potential inconsistent ifc assignment state (Undo fail) detected

Inconsistent interface assignment state detected on non base unit.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Potential inconsistent ifc assignment state (Undo fail - unit %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Potential inconsistent ifc assignment state (Undo fail - unit %d) log

Potential inconsistent ifc assignment state (Undo fail - unit %d)

**Source   Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Potential inconsistent policy state (Undo fail) detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Potential inconsistent policy state (Undo fail) detected log

Potential inconsistent policy state (Undo fail) detected

Inconsistent policy state detected on non base unit.

Source	Severity
QoS	Serious

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Potential inconsistent policy state (Undo fail - unit %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Potential inconsistent policy state (Undo fail - unit %d) log

Potential inconsistent policy state (Undo fail - unit %d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Precedence value out-of-range

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Precedence value out-of-range log

Precedence value out-of-range

Precedence range depends on the platform.

Source	Severity
QoS	Serious

### Remedial action

Check documentation and use a valid precedence.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Primary Configuration files are corrupted. Restored to default

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Primary Configuration files are corrupted. Restored to default log

Primary Configuration files are corrupted. Restored to default

The default primary configuration is restored.

Source	Severity
config	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Primary Configuration Version is updated

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Primary Configuration Version is updated log

Primary Configuration Version is updated

The primary configuration version is updated.

Source	Severity
config	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Primary VLAN does not match for the specified SPBM instance

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Primary VLAN does not match for the specified SPBM instance log

Primary VLAN does not match for the specified SPBM instance

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Primary VLAN is not added for the specified SPBM instance

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Primary VLAN is not added for the specified SPBM instance log

Primary VLAN is not added for the specified SPBM instance

**Source    Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Priority is only for broadcast type

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Priority is only for broadcast type log

Priority is only for broadcast type

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Provided metering information incomplete

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Provided metering information incomplete log

Provided metering information incomplete

Insufficient or invalid information provided.

Source	Severity
QoS	Serious

### Remedial action

Specify a valid meter.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# 802.1p user priority mapping modifications not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## 802.1p user priority mapping modifications not supported log

802.1p user priority mapping modifications not supported

The system detected an internal error; the specified modifier option is not supported.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# 802.1p user priority value modification prohibited

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## 802.1p user priority value modification prohibited log

802.1p user priority value modification prohibited

Since the COS-to-DSCP default assignment association is created at initialization, the CoS may not be modified.

Source	Severity
QoS	Information

### Remedial action

Verify that the COS being specified is indeed the original COS.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QOS filter-limiting mode modified and unit reset

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QOS filter-limiting mode modified and unit reset log

QOS filter-limiting mode modified and unit reset

The QOS filter-limiting mode was modified and the unit rebooted.

Source	Severity
Stack Manager	Serious

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QoS inter-module communication failure: class %d phase %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QoS inter-module communication failure: class %d phase %d log

QoS inter-module communication failure: class %d phase %d

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# QoS inter-module communication issue detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QoS inter-module communication issue detected log

QoS inter-module communication issue detected

Unable to make changes across the stack. If the request failed because of an RPC timeout, then this is due to a processing delay on the remote unit.

Source	Severity
QoS	Information

### Remedial action

Check if a timeout issue, else try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QoS policies may not be applied to uplink or daisy chain ports (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QoS policies may not be applied to uplink or daisy chain ports (%d) log

QoS policies may not be applied to uplink or daisy chain ports (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QoS policies may not be applied to uplink or daisy chain ports ( port# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QoS policies may not be applied to uplink or daisy chain ports ( port# ) log

QoS policies may not be applied to uplink or daisy chain ports ( port# )

ESU Policies cannot be applied on daisy chain ports.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Enter different ports.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Queue configuration inconsistency detected (local %d, stack %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Queue configuration inconsistency detected (local %d, stack %d) log

Queue configuration inconsistency detected (local %d, stack %d)

Source	Severity
QoS	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Queue configuration inconsistency detected (local queue conf stack queue conf )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Queue configuration inconsistency detected (local queue conf stack queue conf ) log

Queue configuration inconsistency detected (local queue conf stack queue conf )

The queue set is not same on all units in stack.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Queue data distribution across stack failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Queue data distribution across stack failed log

Queue data distribution across stack failed

Unable to commit queue data distribution across the stack.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Queue set assignment distribution across stack failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Queue set assignment distribution across stack failed log

Queue set assignment distribution across stack failed

Unable to make changes across the stack.

Source	Severity
QoS	Serious

### Remedial action

Try later or check stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Queue set assignment modifications not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Queue set assignment modifications not supported log

Queue set assignment modifications not supported

The system detected an Internal error; The specified modifier option not supported.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Queue set unacceptable - pending range excludes in-use queues

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Queue set unacceptable - pending range excludes in-use queues log

Queue set unacceptable - pending range excludes in-use queues

Cannot configure as a default queue set one that is currently used by a traffic shaping.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Enter an available queue set.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Queue set value modification prohibited

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Queue set value modification prohibited log

Queue set value modification prohibited

The queue set may not be modified since the queue set association is created when the queue set is defined.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Verify that the queue set being specified is indeed the original queue set.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Queue set value modification prohibited

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Queue set value modification prohibited log

Queue set value modification prohibited

The queue set may not be modified since the queue set association is created when the queue set is defined.

Source	Severity
--------	----------

QoS	Warning
-----	---------

### Remedial action

Verify that the queue set being specified is indeed the original queue set.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Queue shaping distribution across stack failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Queue shaping distribution across stack failed log

Queue shaping distribution across stack failed

Unable to commit queue shaping distribution across the stack.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Queue shaping modifications not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Queue shaping modifications not supported log

Queue shaping modifications not supported

The system detected an internal error; The specified modifier option not supported.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Queue shaping not supported with specified interface

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Queue shaping not supported with specified interface log

Queue shaping not supported with specified interface

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QuickInstall console configuration error.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QuickInstall console configuration error. log

QuickInstall console configuration error.

Quick Install could not use the configuration from the console menu.

Source	Severity
Quick Install	Information

### Remedial action

Use from console configuration or retry the menu with install command.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QuickInstall: console configuration error.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QuickInstall: console configuration error. log

QuickInstall: console configuration error.

Source	Severity
--------	----------

Quick Install	
---------------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# QuickInstall: console configuration success.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QuickInstall: console configuration success. log

QuickInstall: console configuration success.

Source	Severity
--------	----------

Quick Install	
---------------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QuickInstall:console configuration success.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QuickInstall:console configuration success. log

QuickInstall:console configuration success.

Quick Install successfully executed the configuration from the console menu.

Source	Severity
Quick Install	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QuickInstall: console SNMP duplicate community error.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QuickInstall: console SNMP duplicate community error. log

QuickInstall: console SNMP duplicate community error.

Source	Severity
--------	----------

Quick Install	
---------------	--

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QuickInstall: Error! Unable to locate agent software file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QuickInstall: Error! Unable to locate agent software file log

QuickInstall: Error! Unable to locate agent software file

The agent file specified in " ip.cfg" was not found.

Source	Severity
Quick Install	Information

### Remedial action

Put agent file specified in "ip.cfg" file on USB device.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QuickInstall: Error! Unable to locate agent software file.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QuickInstall: Error! Unable to locate agent software file. log

QuickInstall: Error! Unable to locate agent software file.

Source	Severity
--------	----------

Quick Install	
---------------	--

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QuickInstall: Error! Unable to locate ASCII configuration file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QuickInstall: Error! Unable to locate ASCII configuration file log

QuickInstall: Error! Unable to locate ASCII configuration file

The ASCII file specified in " ip.cfg" was not found.

Source	Severity
Quick Install	Information

### Remedial action

Put ASCII File specified in "ip.cfg" file on USB device.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QuickInstall: Error! Unable to locate ASCII configuration file.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QuickInstall: Error! Unable to locate ASCII configuration file. log

QuickInstall: Error! Unable to locate ASCII configuration file.

Source	Severity
--------	----------

Quick Install	
---------------	--

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QuickInstall: Error! Unable to locate diagnostics software file.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QuickInstall: Error! Unable to locate diagnostics software file. log

QuickInstall: Error! Unable to locate diagnostics software file.

The diagnostic file specified in " ip.cfg" was not found.

Source	Severity
Quick Install	Information

### Remedial action

Put diagnostic file specified in "ip.cfg" file on USB device.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# QuickInstall: Processing of USB config file has commenced.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QuickInstall: Processing of USB config file has commenced. log

QuickInstall: Processing of USB config file has commenced.

USB file "ip.cfg" was found and script execution has commenced.

Source	Severity
Quick Install	Information

### Remedial action

No action Required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QuickInstall: Processing of USB config file is complete

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QuickInstall: Processing of USB config file is complete log

QuickInstall: Processing of USB config file is complete

The execution of script from "ip.cfg" is finished.

Source	Severity
Quick Install	Information

### Remedial action

No action Required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QuickInstall: Processing of USB config file is complete.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QuickInstall: Processing of USB config file is complete. log

QuickInstall: Processing of USB config file is complete.

Source	Severity
--------	----------

Quick Install	
---------------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QuickInstall: USB config file not entirely executed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QuickInstall: USB config file not entirely executed log

QuickInstall: USB config file not entirely executed

**Source**                      **Severity**

Quick Install

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QuickInstall USB config file not found.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QuickInstall USB config file not found. log

QuickInstall USB config file not found.

Quick Install could not locate the USB file.

Source	Severity
Quick Install	Information

### Remedial action

Put a file to USB script and set it to default if you want to run Quick Install.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QuickInstall: USB config file not found.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QuickInstall: USB config file not found. log

QuickInstall: USB config file not found.

Source	Severity
--------	----------

Quick Install	
---------------	--

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QuickInstall: USB file config error at line: %d.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QuickInstall: USB file config error at line: %d. log

QuickInstall: USB file config error at line: %d.

Source	Severity
--------	----------

Quick Install	
---------------	--

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QuickInstall USB file config error at line line#

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QuickInstall USB file config error at line line# log

QuickInstall USB file config error at line line#

Quick Install detected an error in the script at the given line.

Source	Severity
Quick Install	Information

### Remedial action

Correct the detected error at the specified line on the USB script and set it to default.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# QuickInstall: USB file config error: %d.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QuickInstall: USB file config error: %d. log

QuickInstall: USB file config error: %d.

Source	Severity
--------	----------

Quick Install	
---------------	--

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QuickInstall USB file config error - file exceed 4096 bytes

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QuickInstall USB file config error - file exceed 4096 bytes log

QuickInstall USB file config error - file exceed 4096 bytes

The script file is too large and exceeds the limit of 4096 bytes.

Source	Severity
Quick Install	Information

### Remedial action

Remove some of the comments and the unnecessary lines.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QuickInstall USB file config error - file exceed 200 lines.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QuickInstall USB file config error - file exceed 200 lines. log

QuickInstall USB file config error - file exceed 200 lines.

The script file is too large and exceeds the limit of 200 lines.

Source	Severity
Quick Install	Information

### Remedial action

Remove some of the comments and the unnecessary lines.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QuickInstall: USB file config error - file exceeds 4096 bytes

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QuickInstall: USB file config error - file exceeds 4096 bytes log

QuickInstall: USB file config error - file exceeds 4096 bytes

Source	Severity
--------	----------

Quick Install	
---------------	--

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QuickInstall: USB file config error - file exceeds 200 lines.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QuickInstall: USB file config error - file exceeds 200 lines. log

QuickInstall: USB file config error - file exceeds 200 lines.

Source	Severity
--------	----------

Quick Install	
---------------	--

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QuickInstall: USB file config success.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QuickInstall: USB file config success. log

QuickInstall: USB file config success.

Source	Severity
--------	----------

Quick Install	
---------------	--

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QuickInstall:USB file config success.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QuickInstall:USB file config success. log

QuickInstall:USB file config success.

The script file from the USB is successfully executed by the Quick Install.

Source	Severity
Quick Install	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# RADIUS authentication on serial port disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RADIUS authentication on serial port disabled log

RADIUS authentication on serial port disabled

**Source**   **Severity**

RADIUS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# RADIUS authentication on serial port enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RADIUS authentication on serial port enabled log

RADIUS authentication on serial port enabled

**Source**   **Severity**

RADIUS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# RADIUS authentication on stack serial disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RADIUS authentication on stack serial disabled log

RADIUS authentication on stack serial disabled

Informs user that RADIUS authentication was disabled on stack serial.

Source	Severity
RADIUS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# RADIUS authentication on stack serial enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RADIUS authentication on stack serial enabled log

RADIUS authentication on stack serial enabled

Informs user that RADIUS authentication was enabled on stack serial.

Source	Severity
RADIUS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# RADIUS authentication on stack telnet disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RADIUS authentication on stack telnet disabled log

RADIUS authentication on stack telnet disabled

Informs user that RADIUS authentication was disabled on stack telnet.

Source	Severity
RADIUS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# RADIUS authentication on stack telnet enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RADIUS authentication on stack telnet enabled log

RADIUS authentication on stack telnet enabled

Informs user that RADIUS authentication was enabled on stack telnet.

Source	Severity
RADIUS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# RADIUS authentication on stack TELNET/WEB/SSH disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RADIUS authentication on stack TELNET/WEB/SSH disabled log

RADIUS authentication on stack TELNET/WEB/SSH disabled

**Source**   **Severity**

RADIUS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# RADIUS authentication on stack TELNET/WEB/SSH enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RADIUS authentication on stack TELNET/WEB/SSH enabled log

RADIUS authentication on stack TELNET/WEB/SSH enabled

**Source**   **Severity**

RADIUS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# RADIUS authentication on switch serial disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RADIUS authentication on switch serial disabled log

RADIUS authentication on switch serial disabled

Informs user that RADIUS authentication was disabled on switch serial.

Source	Severity
RADIUS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# RADIUS authentication on switch serial enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RADIUS authentication on switch serial enabled log

RADIUS authentication on switch serial enabled

Informs user that RADIUS authentication was enabled on switch serial.

Source	Severity
RADIUS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# RADIUS authentication on switch telnet disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RADIUS authentication on switch telnet disabled log

RADIUS authentication on switch telnet disabled

Informs user that RADIUS authentication was disabled on switch telnet.

Source	Severity
RADIUS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# RADIUS authentication on switch telnet enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RADIUS authentication on switch telnet enabled log

RADIUS authentication on switch telnet enabled

Informs user that RADIUS authentication was enabled on switch telnet.

Source	Severity
RADIUS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# RADIUS authentication on switch TELNET/WEB/SSH disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RADIUS authentication on switch TELNET/WEB/SSH disabled log

RADIUS authentication on switch TELNET/WEB/SSH disabled

**Source**   **Severity**

RADIUS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# RADIUS authentication on switch TELNET/WEB/SSH enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RADIUS authentication on switch TELNET/WEB/SSH enabled log

RADIUS authentication on switch TELNET/WEB/SSH enabled

**Source**   **Severity**

RADIUS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# RADIUS authentication on TELNET/WEB/SSH disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RADIUS authentication on TELNET/WEB/SSH disabled log

RADIUS authentication on TELNET/WEB/SSH disabled

**Source**   **Severity**

RADIUS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# RADIUS authentication on TELNET/WEB/SSH enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RADIUS authentication on TELNET/WEB/SSH enabled log

RADIUS authentication on TELNET/WEB/SSH enabled

**Source**   **Severity**

RADIUS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# RADIUS: ERROR - Couldn't create RADIUS Acct semaphore, errno %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RADIUS: ERROR - Couldn't create RADIUS Acct semaphore, errno %d log

RADIUS: ERROR - Couldn't create RADIUS Acct semaphore, errno %d

The Radius Accounting task synchronization semaphore could not be created.

Source	Severity
--------	----------

Radius	Information
--------	-------------

### Remedial action

Reboot the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# RADIUS: ERROR - Couldn't create RADIUS semaphore, errno %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RADIUS: ERROR - Couldn't create RADIUS semaphore, errno %d log

RADIUS: ERROR - Couldn't create RADIUS semaphore, errno %d

The Radius task synchronization semaphore could not be created.

Source	Severity
--------	----------

Radius	Information
--------	-------------

### Remedial action

Reboot the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# RADIUS: ERROR - Couldn't start RADIUS\_AcctClient() task, errno %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RADIUS: ERROR - Couldn't start RADIUS\_AcctClient() task, errno %d log

RADIUS: ERROR - Couldn't start RADIUS\_AcctClient() task, errno %d

The Radius Accounting task could not start.

Source	Severity
Radius	Information

### Remedial action

Reboot the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# RADIUS: ERROR - Couldn't start RADIUS\_client() task, errno %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RADIUS: ERROR - Couldn't start RADIUS\_client() task, errno %d log

RADIUS: ERROR - Couldn't start RADIUS\_client() task, errno %d

The Radius client task could not start.

Source	Severity
--------	----------

Radius	Information
--------	-------------

### Remedial action

Reboot the stack.



# RADIUS: ERROR - Couldn't start radius\_recv() task, errno %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RADIUS: ERROR - Couldn't start radius\_recv() task, errno %d log

RADIUS: ERROR - Couldn't start radius\_recv() task, errno %d

The Radius Receive task could not start.

Source	Severity
Radius	Information

### Remedial action

Reboot the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# RADIUS: ERROR - Couldn't start RADIUS\_ServerCheck() task, errno %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RADIUS: ERROR - Couldn't start RADIUS\_ServerCheck() task, errno %d log

RADIUS: ERROR - Couldn't start RADIUS\_ServerCheck() task, errno %d

The Radius periodic reachability check task could not start.

Source	Severity
Radius	Information

### Remedial action

Reboot the stack.



# RADIUS MS-CHAPv2: Failed to change password

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RADIUS MS-CHAPv2: Failed to change password log

RADIUS MS-CHAPv2: Failed to change password

**Source**   **Severity**

RADIUS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# RADIUS MS-CHAPv2: No response from RADIUS server

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RADIUS MS-CHAPv2: No response from RADIUS server log

RADIUS MS-CHAPv2: No response from RADIUS server

**Source**   **Severity**

RADIUS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# RADIUS MS-CHAPv2: Password changed successfully

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RADIUS MS-CHAPv2: Password changed successfully log

RADIUS MS-CHAPv2: Password changed successfully

**Source**   **Severity**

RADIUS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# RADIUS MS-CHAPv2: RADIUS server not properly configured

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RADIUS MS-CHAPv2: RADIUS server not properly configured log

RADIUS MS-CHAPv2: RADIUS server not properly configured

**Source**   **Severity**

RADIUS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# RADIUS MS-CHAPv2: Server does not speak RADIUS

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RADIUS MS-CHAPv2: Server does not speak RADIUS log

RADIUS MS-CHAPv2: Server does not speak RADIUS

**Source**   **Severity**

RADIUS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# RADIUS MS-CHAPv2: Unable to change password at RADIUS server

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RADIUS MS-CHAPv2: Unable to change password at RADIUS server log

RADIUS MS-CHAPv2: Unable to change password at RADIUS server

**Source**   **Severity**  
RADIUS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Radius: Server with index %d is down

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Radius: Server with index %d is down log

Radius: Server with index %d is down

The identified radius server is down.

Source	Severity
Radius	Information

### Remedial action

Check connectivity with server.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Radius: Server with index %d is up

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Radius: Server with index %d is up log

Radius: Server with index %d is up

The identified radius server is up.

Source	Severity
Radius	Information

### Remedial action

No action required.



# Radius use-mgmt-ip must be disabled first

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Radius use-mgmt-ip must be disabled first log

Radius use-mgmt-ip must be disabled first

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Rate granularity limited to increments of 1 Mbps or 64 Kbps

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Rate granularity limited to increments of 1 Mbps or 64 Kbps log

Rate granularity limited to increments of 1 Mbps or 64 Kbps

There are only two rate granularities supported: 1 Mbps and 64 Kbps.

Source	Severity
QoS	Serious

### Remedial action

Enter a rate with one of the supported granularities.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Rate (min) granularity limited (increments of 1 Mbps or 64 Kbps)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Rate (min) granularity limited (increments of 1 Mbps or 64 Kbps) log

Rate (min) granularity limited (increments of 1 Mbps or 64 Kbps)

There are only two rate granularities supported: 1 Mbps and 64 Kbps.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Enter a rate with one of the supported granularities.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RC\_SNMP\_CANNOT\_CONFIG\_PLSB\_ISIS\_INTF\_ON\_IST\_PORT log

RC\_SNMP\_CANNOT\_CONFIG\_PLSB\_ISIS\_INTF\_ON\_IST\_PORT

**Source**   **Severity**  
ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RC\_SNMP\_CANNOT\_CONFIG\_PLSB\_ISIS\_INTF\_ON\_SMLT log

RC\_SNMP\_CANNOT\_CONFIG\_PLSB\_ISIS\_INTF\_ON\_SMLT

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series

9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RC\_SNMP\_ISIS\_BCAST\_NOT\_SUPPORT\_OVER\_MLT log

RC\_SNMP\_ISIS\_BCAST\_NOT\_SUPPORT\_OVER\_MLT

**Source**   **Severity**  
ISIS

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Receive sync packet for L2 entry:  
MAC:%02x-%02x-%02x-%02x-%02x-%02x trunk %d modid %d from  
Remote\_modid %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Receive sync packet for L2 entry: MAC:%02x-%02x-%02x-%02x-%02x-%02x trunk %d modid %d from Remote\_modid %d log

Receive sync packet for L2 entry: MAC:%02x-%02x-%02x-%02x-%02x-%02x trunk %d modid %d from Remote\_modid %d

**Source**   **Severity**

CDT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Referenced block (by policy) deletion prohibited

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Referenced block (by policy) deletion prohibited log

Referenced block (by policy) deletion prohibited

Cannot delete a classifier-block if it's referenced in a policy.

Source	Severity
QoS	Serious

### Remedial action

Remove the policy first.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Referenced set (by block) modifications prohibited

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Referenced set (by block) modifications prohibited log

Referenced set (by block) modifications prohibited

No modifications can be made to a classifier set referenced in a classifier-block.

Source	Severity
QoS	Serious

### Remedial action

Remove block, perform modifications and recreate classifier-block.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Referenced set (by policy) modifications prohibited

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Referenced set (by policy) modifications prohibited log

Referenced set (by policy) modifications prohibited

No modifications can be made to a classifier set used by a policy.

Source	Severity
QoS	Serious

### Remedial action

Remove policy, perform modifications and recreate policy.



# Referenced token bucket data invalid (burst size)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Referenced token bucket data invalid (burst size) log

Referenced token bucket data invalid (burst size)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Remote access on this device has been

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Remote access on this device has been log

Remote access on this device has been

Source	Severity
--------	----------

Telnet	
--------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Remote QoS-disable request failure (%d on unit %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Remote QoS-disable request failure (%d on unit %d) log

Remote QoS-disable request failure (%d on unit %d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Remote QoS-disable request failure ( port# on unit unit# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Remote QoS-disable request failure ( port# on unit unit# ) log

Remote QoS-disable request failure ( port# on unit unit# )

Failed to disable the Policy/Interface.

Source	Severity
QoS	Serious

### Remedial action

Check for the conflicting entries, try again later, reset the QoS agent, reset the unit or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Remove Data Ack from unit # %d, mask 0x %X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Remove Data Ack from unit # %d, mask 0x %X log

Remove Data Ack from unit # %d, mask 0x %X

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# REMOVE\_DATA event sent unit mask value appl mask value

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## REMOVE\_DATA event sent unit mask value appl mask value log

REMOVE\_DATA event sent unit mask value appl mask value

The application could not exchange its database successfully.

Source	Severity
Stack Manager	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Remove event sent, unit mask 0x%02X, appl mask 0x%08X 0x%08X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Remove event sent, unit mask 0x%02X, appl mask 0x%08X 0x%08X log

Remove event sent, unit mask 0x%02X, appl mask 0x%08X 0x%08X

Source	Severity
SMGR	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Replaced "Wrong QoS Agent buffer setting, expected %u, actual %u, unit cannot join stack" with "Wrong QoS Agent buffer setting, expected %s, actual %s, unit cannot join stack"

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Replaced "Wrong QoS Agent buffer setting, expected %u, actual %u, unit cannot join stack" with "Wrong QoS Agent buffer setting, expected %s, actual %s, unit cannot join stack" log

Replaced "Wrong QoS Agent buffer setting, expected %u, actual %u, unit cannot join stack" with "Wrong QoS Agent buffer setting, expected %s, actual %s, unit cannot join stack"

Unit cannot join the stack because of the difference in buffer setting.

Source	Severity
Stack Manager	Information

### Remedial action

Re-configure QoS agent buffer setting to the expected value and power cycle unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Requested attribute usage is currently not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Requested attribute usage is currently not supported log

Requested attribute usage is currently not supported

The requested attribute is not compatible – attribute value support is limited.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Eliminate option or use a different attribute.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Requested filter manager support unavailable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Requested filter manager support unavailable log

Requested filter manager support unavailable

The requested operation is not supported on the current hardware.

Source	Severity
QoS	Serious

### Remedial action

Change/drop the request.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Requested operation succeeded

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Requested operation succeeded log

Requested operation succeeded

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Requested precedence mask reservation not available

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Requested precedence mask reservation not available log

Requested precedence mask reservation not available

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Requested reserve data invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Requested reserve data invalid log

Requested reserve data invalid

Trying to remove an entry that is not actually reserved.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Check if the specified entry wasn't already removed.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Request invalid - QoS interface apps enabled on interface(s)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Request invalid - QoS interface apps enabled on interface(s) log

Request invalid - QoS interface apps enabled on interface(s)

Request is denied as the interface applications are enabled on this port.

Source	Severity
QoS	Serious

### Remedial action

Enter a different interface or disable the interface application on this port.



# Request invalid - specified interface currently QoS-disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Request invalid - specified interface currently QoS-disabled log

Request invalid - specified interface currently QoS-disabled

All request are denied when the target interface is QoS disabled.

Source	Severity
QoS	Serious

### Remedial action

Enter a different interface index.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Request temporarily denied - QoS support is currently disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Request temporarily denied - QoS support is currently disabled log

Request temporarily denied - QoS support is currently disabled

All request are denied when QoS overall is disabled.

Source	Severity
QoS	Serious

### Remedial action

Enable QoS overall before committing any request.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Required application data not provided

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Required application data not provided log

Required application data not provided

**Source   Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Required bandwidth information not specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Required bandwidth information not specified log

Required bandwidth information not specified

The queue bandwidth parameter has not been provided.

Source	Severity
QoS	Serious

### Remedial action

Specify the queue bandwidth parameter based on the bandwidth allocation attribute.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Required FCoE filter resources unavailable - enable request denied

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Required FCoE filter resources unavailable - enable request denied log

Required FCoE filter resources unavailable - enable request denied

Source	Severity
QoS	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Required FCoE resources currently unavailable (unit %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Required FCoE resources currently unavailable (unit %d) log

Required FCoE resources currently unavailable (unit %d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Required range check resources are not currently available

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Required range check resources are not currently available log

Required range check resources are not currently available

**Source   Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Reset - Error Failed to get the Reset sem

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Reset - Error Failed to get the Reset sem log

Reset - Error Failed to get the Reset sem

The system failed to get ownership of the reset semaphore to prevent reset during download.

Source	Severity
Flash Driver	Critical

### Remedial action

Retry the operation.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Reset initiated by console

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Reset initiated by console log

Reset initiated by console

Reset is initiated through a serial connection.

Source	Severity
Console	Serious

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Reset initiated through http by IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Reset initiated through http by IP address log

Reset initiated through http by IP address

Reset is initiated through the EDM interface.

Source	Severity
WEB	

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Reset initiated through snmp

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Reset initiated through snmp log

Reset initiated through snmp

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Reset initiated through SSH by IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Reset initiated through SSH by IP address log

Reset initiated through SSH by IP address

Reset initiated through the SSH connection.

Source	Severity
Telnet Server	Serious

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Reset initiated through SSH by IP address:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Reset initiated through SSH by IP address: log

Reset initiated through SSH by IP address:

Source	Severity
--------	----------

Telnet	
--------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Reset initiated through telnet by IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Reset initiated through telnet by IP address log

Reset initiated through telnet by IP address

Reset is initiated through a telnet connection.

Source	Severity
Telnet Server	Serious

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Reset initiated through telnet by IP address:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Reset initiated through telnet by IP address: log

Reset initiated through telnet by IP address:

Source	Severity
--------	----------

Telnet	
--------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Reset initiated through http by IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Reset initiated through http by IP address log

Reset initiated through http by IP address

**Source**   **Severity**

WEB

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Reset to default initiated by console

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Reset to default initiated by console log

Reset to default initiated by console

Reset to the default settings initiated through serial connection.

Source	Severity
Console	Serious

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Reset to default initiated through SSH by IP address:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Reset to default initiated through SSH by IP address: log

Reset to default initiated through SSH by IP address:

Source	Severity
--------	----------

Telnet	
--------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Reset to default initiated through telnet by IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Reset to default initiated through telnet by IP address log

Reset to default initiated through telnet by IP address

Reset to default settings initiated through the telnet connection.

Source	Severity
Telnet Server	Serious

### Remedial action

No action required.





# Reset to default initiated through telnet by IP address:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Reset to default initiated through telnet by IP address: log

Reset to default initiated through telnet by IP address:

**Source**   **Severity**

Telnet

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Reset to default initiated through http by IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Reset to default initiated through http by IP address log

Reset to default initiated through http by IP address

**Source**   **Severity**

WEB

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Resource alloc event timeout (tgt all apps except QoS Agent rcv event )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Resource alloc event timeout (tgt all apps except QoS Agent rcv event ) log

Resource alloc event timeout (tgt all apps except QoS Agent rcv event )

Filter Manager failed to allocate the necessary resources in time.

Source	Severity
QoS	Critical

### Remedial action

Reset the unit.



# Resource alloc event timeout (tgt %08x rcv %08x)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Resource alloc event timeout (tgt %08x rcv %08x) log

Resource alloc event timeout (tgt %08x rcv %08x)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Resource not available

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Resource not available log

Resource not available

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Resources exhausted (maximum class entries reached)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Resources exhausted (maximum class entries reached) log

Resources exhausted (maximum class entries reached)

The maximum entries allowed for the class you are trying to configure an entry has been reached.

Source	Severity
QoS	Serious

### Remedial action

Check for and remove the related QoS entries that are not needed.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Resources exhausted (maximum dynamic class entries reached)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Resources exhausted (maximum dynamic class entries reached) log

Resources exhausted (maximum dynamic class entries reached)

The system reached the maximum supported dynamic QoS interface type entries.

Source	Severity
QoS	Information

### Remedial action

Verify that the data from FA Server regarding interface types is within supported limits.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Resources exhausted (out-of-memory)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Resources exhausted (out-of-memory) log

Resources exhausted (out-of-memory)

Memory allocation for the new entry failed.

Source	Severity
QoS	Serious

### Remedial action

Check for and remove the QoS entries that are not needed.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Resource unavailable DHCP relay %d err %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Resource unavailable DHCP relay %d err %d log

Resource unavailable DHCP relay %d err %d

**Source**   **Severity**

DHCPR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Restart discovery msg rcvd from unit #%d, "%s"

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Restart discovery msg rcvd from unit #%d, "%s" log

Restart discovery msg rcvd from unit #%d, "%s"

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Restarting discovery due to local stack port

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Restarting discovery due to local stack port log

Restarting discovery due to local stack port

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Restore Backup Configuration to Manufacture Default

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Restore Backup Configuration to Manufacture Default log

Restore Backup Configuration to Manufacture Default

The manufactured default back up configuration is restored.

Source	Severity
config	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Restore Primary Configuration to Manufacture Default

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Restore Primary Configuration to Manufacture Default log

Restore Primary Configuration to Manufacture Default

The manufactured default primary configuration is restored.

Source	Severity
config	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Role combination associated with interface (deletion prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Role combination associated with interface (deletion prohibited) log

Role combination associated with interface (deletion prohibited)

Cannot remove a role combination if it's associated with an interface.

Source	Severity
QoS	Serious

### Remedial action

Associate a different interface role combination to the interface before requesting the removal.



# Role combination contains unacceptable characters

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Role combination contains unacceptable characters log

Role combination contains unacceptable characters

A valid role combination contains letters, digits, special characters (period, line, plus, underline but not on the first position) and '\$' but only as the first character.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Enter valid characters for the access element's label.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Role combination distribution across stack failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Role combination distribution across stack failed log

Role combination distribution across stack failed

Unable to commit role combination distribution across the stack.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Role combination length outside of acceptable limits

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Role combination length outside of acceptable limits log

Role combination length outside of acceptable limits

The maximum role combination length supported is 32.

Source	Severity
QoS	Information

### Remedial action

Enter a valid role combination.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Role combination modifications not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Role combination modifications not supported log

Role combination modifications not supported

The system detected an internal error; The specified modifier option not supported.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



## Role combination referenced by policy (deletion prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

### Role combination referenced by policy (deletion prohibited) log

Role combination referenced by policy (deletion prohibited)

Cannot remove a role combination if it's referenced by a policy.

Source	Severity
QoS	Serious

#### Remedial action

Remove the policy first.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Role (interface) capabilities incompatible with policy data

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Role (interface) capabilities incompatible with policy data log

Role (interface) capabilities incompatible with policy data

The policy and the specified role(the component interfaces) have different version capabilities.

**Source**   **Severity**

QoS     Serious

### Remedial action

Enter either a role with compatible interface(s) or adapt the policy to match the required version.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# RPC app rcv routine error, type= %s(%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RPC app rcv routine error, type= %s(%d) log

RPC app rcv routine error, type= %s(%d)

**Source    Severity**

IMC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# RPC Error (mem or send)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## RPC Error (mem or send) log

RPC Error (mem or send)

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



%s Appl. unexpectedly set bit in DB  
exch. recv mask, bit 0x%08X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## %s Appl. unexpectedly set bit in DB exch. recv mask, bit 0x%08X log

%s Appl. unexpectedly set bit in DB exch. recv mask, bit 0x%08X

Source	Severity
SMGR	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Save/restore line=%d msg=%s val=0x%X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Save/restore line=%d msg=%s val=0x%X log

Save/restore line=%d msg=%s val=0x%X

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





## %s card inserted (in unit %s)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

### %s card inserted (in unit %s) log

%s card inserted (in unit %s)

This message appears when an MDA card is inserted.

Source	Severity
MDA	Information

#### Remedial action

No action required.



# %s card removed (from unit %s)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## %s card removed (from unit %s) log

%s card removed (from unit %s)

This message appears when MDA card is removed.

Source	Severity
MDA	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SC Install SET fail unit/port %d/%d status=%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SC Install SET fail unit/port %d/%d status=%d log

SC Install SET fail unit/port %d/%d status=%d

**Source    Severity**

SC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SC Install TEST fail unit/port %d/%d status=%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SC Install TEST fail unit/port %d/%d status=%d log

SC Install TEST fail unit/port %d/%d status=%d

**Source   Severity**

SC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Scratchpad failed to copy sector (%x, %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Scratchpad failed to copy sector (%x, %d) log

Scratchpad failed to copy sector (%x, %d)

**Source**   **Severity**

SPAD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Scratchpad failed to erase sector (%x, %x, %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Scratchpad failed to erase sector (%x, %x, %d) log

Scratchpad failed to erase sector (%x, %x, %d)

**Source**   **Severity**

SPAD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Script was successfully executed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Script was successfully executed log

Script was successfully executed

Script finished with success.

### Source

Run scripts: IP Office, LLDP, ADAC

### Severity

Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SC UnInst SET failed for port %u status=%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SC UnInst SET failed for port %u status=%d log

SC UnInst SET failed for port %u status=%d

**Source   Severity**

SC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





%s DB exchange succeeded for this unit, bit 0x%08X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## %s DB exchange succeeded for this unit, bit 0x%08X log

%s DB exchange succeeded for this unit, bit 0x%08X

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Sending restart discovery msg to base unit

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Sending restart discovery msg to base unit log

Sending restart discovery msg to base unit

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Session closed (inactivity logout) IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Session closed (inactivity logout) IP address log

Session closed (inactivity logout) IP address

The telnet session is disconnected after 15 minutes of console inactivity.

Source	Severity
Telnet Server	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Session closed (inactivity logout), IP address:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Session closed (inactivity logout), IP address: log

Session closed (inactivity logout), IP address:

Source	Severity
--------	----------

Telnet	
--------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Session closed (inactivity logout), serial connection

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Session closed (inactivity logout), serial connection log

Session closed (inactivity logout), serial connection

**Source**   **Severity**

Telnet

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Session closed (lost connection) IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Session closed (lost connection) IP address log

Session closed (lost connection) IP address

Client aborted the connection by sending a RST message. The server disconnected the session.

Source	Severity
Telnet Server	Information

### Remedial action

No action required.



# Session closed (lost connection), IP address:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Session closed (lost connection), IP address: log

Session closed (lost connection), IP address:

Source	Severity
--------	----------

Telnet	
--------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Session closed (serial console disconnected)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Session closed (serial console disconnected) log

Session closed (serial console disconnected)

**Source**   **Severity**

Telnet

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Session closed (user logout) IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Session closed (user logout) IP address log

Session closed (user logout) IP address

You have disconnected the telnet session.

Source	Severity
Telnet Server	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Session closed (user logout), IP address:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Session closed (user logout), IP address: log

Session closed (user logout), IP address:

**Source   Severity**

Telnet

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Session closed (user logout) serial connection

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Session closed (user logout) serial connection log

Session closed (user logout) serial connection

You have disconnected the serial connection session.

Source	Severity
Console	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Session closed (user logout), serial connection

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Session closed (user logout), serial connection log

Session closed (user logout), serial connection

**Source   Severity**

Telnet

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Session negotiation failure from IP address:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Session negotiation failure from IP address: log

Session negotiation failure from IP address:

Source	Severity
--------	----------

Telnet	
--------	--

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Session opened from IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Session opened from IP address log

Session opened from IP address

The telnet session has begun. You now have the access to the terminal using the CTRL-Y key or you have successfully logged-in, in case of authentication requirement.

Source	Severity
Telnet Server	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Session opened from IP address:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Session opened from IP address: log

Session opened from IP address:

Source	Severity
--------	----------

Telnet	
--------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Session opened from serial connection

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Session opened from serial connection log

Session opened from serial connection

Session has begun on the serial connection. You now have access to the terminal using the CTRL-Y key or successfully logged-in, in the case of uthentication requirement.

Source	Severity
Console	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Session opened (local auth) from IP address:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Session opened (local auth) from IP address: log

Session opened (local auth) from IP address:

Successful authentication with local credentials over telnet session.

Source	Severity
Telnet server	Information

### Remedial action

No action required.



# Session opened (local auth) from IP address:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Session opened (local auth) from IP address: log

Session opened (local auth) from IP address:

Source	Severity
--------	----------

Telnet	
--------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Session opened (local auth) from serial connection

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Session opened (local auth) from serial connection log

Session opened (local auth) from serial connection

Successful authentication with local credentials on serial port.

Source	Severity
Console	Information

### Remedial action

No action required.



# Session opened(radius auth) from IP add

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Session opened(radius auth) from IP add log

Session opened(radius auth) from IP add

You have successfully logged in with the Radius Server. Telnet session has begun.

Source	Severity
Telnet Server	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Session opened(RADIUS auth) from IP add:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Session opened(RADIUS auth) from IP add: log

Session opened(RADIUS auth) from IP add:

**Source**   **Severity**

Telnet

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Session opened(radius auth) from serial conn

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Session opened(radius auth) from serial conn log

Session opened(radius auth) from serial conn

You have successfully logged-in with the Radius Server. The serial connection session is opened.

Source	Severity
Console	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Session opened(RADIUS auth) from serial connection

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Session opened(RADIUS auth) from serial connection log

Session opened(RADIUS auth) from serial connection

### Source    Severity

Telnet

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Session opened(RADIUS fallback auth) from IP add:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Session opened(RADIUS fallback auth) from IP add: log

Session opened(RADIUS fallback auth) from IP add:

Source	Severity
--------	----------

Telnet	
--------	--

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Session opened(RADIUS fallback auth) from serial connection

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Session opened(RADIUS fallback auth) from serial connection log

Session opened(RADIUS fallback auth) from serial connection

### Source    Severity

Telnet

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Session opened(TACACS+ auth) from IP add:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Session opened(TACACS+ auth) from IP add: log

Session opened(TACACS+ auth) from IP add:

Source	Severity
--------	----------

Telnet	
--------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Session opened(TACACS+ auth) from serial connection

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Session opened(TACACS+ auth) from serial connection log

Session opened(TACACS+ auth) from serial connection

### Source    Severity

Telnet

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Session opened(TACACS+ fallback auth) from IP add:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Session opened(TACACS+ fallback auth) from IP add: log

Session opened(TACACS+ fallback auth) from IP add:

Source	Severity
--------	----------

Telnet	
--------	--

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Session opened(TACACS+ fallback auth) from serial connection

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Session opened(TACACS+ fallback auth) from serial connection log

Session opened(TACACS+ fallback auth) from serial connection

Source	Severity
Telnet	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Set drop precedence value and update DSCP value out-of-sync

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Set drop precedence value and update DSCP value out-of-sync log

Set drop precedence value and update DSCP value out-of-sync

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Set port to default

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Set port to default log

Set port to default

There was an error when reading the VLAN configuration from NVRAM.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Setting MC broadcast IMC entry, ports %X, end\_type %s, stk\_type %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Setting MC broadcast IMC entry, ports %X, end\_type %s, stk\_type %s log

Setting MC broadcast IMC entry, ports %X, end\_type %s, stk\_type %s

Source	Severity
SMGR	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Setting MC non-IMC entries, end\_type %s, stk\_type %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Setting MC non-IMC entries, end\_type %s, stk\_type %s log

Setting MC non-IMC entries, end\_type %s, stk\_type %s

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Setting MC unicast IMC entries, unit %d, end\_type %s, stk\_type %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Setting MC unicast IMC entries, unit %d, end\_type %s, stk\_type %s log

Setting MC unicast IMC entries, unit %d, end\_type %s, stk\_type %s

Source	Severity
SMGR	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Setting VLAN entries, end\_type %s, stk\_type %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Setting VLAN entries, end\_type %s, stk\_type %s log

Setting VLAN entries, end\_type %s, stk\_type %s

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# %s event NOT sent to %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## %s event NOT sent to %s log

%s event NOT sent to %s

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



%s event sent to %s, unit mask  
0x%02X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## %s event sent to %s, unit mask 0x%02X log

%s event sent to %s, unit mask 0x%02X

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



%s event sent, unit mask 0x%02X, appl  
mask 0x%08X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## %s event sent, unit mask 0x%02X, appl mask 0x%08X log

%s event sent, unit mask 0x%02X, appl mask 0x%08X

**Source   Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# %s failed DB-exchange, stack failed to form

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## %s failed DB-exchange, stack failed to form log

%s failed DB-exchange, stack failed to form

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# %s failed DB-exchange, stack formation delayed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## %s failed DB-exchange, stack formation delayed log

%s failed DB-exchange, stack formation delayed

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# %s failed to set its stack startup event: 0x%08X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## %s failed to set its stack startup event: 0x%08X log

%s failed to set its stack startup event: 0x%08X

### Source    Severity

SMGR

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP internal supply voltage is at high alarm level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP internal supply voltage is at high alarm level on %s log

SFP internal supply voltage is at high alarm level on %s

**Source**   **Severity**

GBIC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP internal supply voltage is at high alarm level on s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP internal supply voltage is at high alarm level on s log

SFP internal supply voltage is at high alarm level on s

The internal supply voltage of a transceiver inserted on a certain unit/port is at high alarm level.

Source	Severity
Port driver	Information

### Remedial action

Check pluggable part and replace if necessary.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP internal supply voltage is at high warning level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP internal supply voltage is at high warning level on %s log

SFP internal supply voltage is at high warning level on %s

The internal supply voltage of a transceiver inserted on a certain unit/port is at high warning level.

Source	Severity
Port driver	Information

### Remedial action

Check pluggable part and replace if necessary.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP internal supply voltage is at low alarm level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP internal supply voltage is at low alarm level on %s log

SFP internal supply voltage is at low alarm level on %s

The internal supply voltage of a transceiver inserted on a certain unit/port is at low alarm level.

Source	Severity
Port driver	Information

### Remedial action

Check pluggable part and replace if necessary.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP internal supply voltage is at low warning level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP internal supply voltage is at low warning level on %s log

SFP internal supply voltage is at low warning level on %s

The internal supply voltage of a transceiver inserted on a certain unit/port is at low warning level.

Source	Severity
Port driver	Information

### Remedial action

Check pluggable part and replace if necessary.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP internal supply voltage is no longer at the high alarm level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP internal supply voltage is no longer at the high alarm level log

SFP internal supply voltage is no longer at the high alarm level

Will be logged only after the actual value of the internal voltage has previously exceeded the alarm threshold, and at the current moment the value is below that threshold.

Source	Severity
Port Driver	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP internal supply voltage is no longer at the high alarm level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP internal supply voltage is no longer at the high alarm level on %s log

SFP internal supply voltage is no longer at the high alarm level on %s

Source	Severity
GBIC	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SFP internal supply voltage is no longer at the high warning level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP internal supply voltage is no longer at the high warning level log

SFP internal supply voltage is no longer at the high warning level

Will be logged only after the actual value of the internal voltage has previously exceeded the warning threshold, and at the current moment the value is below that threshold.

Source	Severity
Port Driver	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP internal supply voltage is no longer at the high warning level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP internal supply voltage is no longer at the high warning level on %s log

SFP internal supply voltage is no longer at the high warning level on %s

**Source**   **Severity**  
GBIC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP internal supply voltage is no longer at the low alarm level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP internal supply voltage is no longer at the low alarm level log

SFP internal supply voltage is no longer at the low alarm level

Will be logged only after the actual value of the internal voltage has previously exceeded the alarm threshold, and at the current moment the value is above that threshold.

Source	Severity
Port Driver	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP internal supply voltage is no longer at the low alarm level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP internal supply voltage is no longer at the low alarm level on %s log

SFP internal supply voltage is no longer at the low alarm level on %s

Source	Severity
GBIC	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP internal supply voltage is no longer at the low warning level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP internal supply voltage is no longer at the low warning level log

SFP internal supply voltage is no longer at the low warning level

Will be logged only after the actual value of the internal voltage has previously exceeded the warning threshold, and at the current moment the value is above that threshold.

Source	Severity
Port Driver	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP internal supply voltage is no longer at the low warning level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP internal supply voltage is no longer at the low warning level on %s log

SFP internal supply voltage is no longer at the low warning level on %s

Source	Severity
GBIC	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP internal temperature is at high alarm level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP internal temperature is at high alarm level on %s log

SFP internal temperature is at high alarm level on %s

The internal temperature of a transceiver inserted on a certain unit/port is at high alarm level.

Source	Severity
Port driver	Information

### Remedial action

Check pluggable part and replace if necessary.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP internal temperature is at high warning level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP internal temperature is at high warning level on %s log

SFP internal temperature is at high warning level on %s

The internal temperature of a transceiver inserted on a certain unit/port is at high warning level.

Source	Severity
Port driver	Information

### Remedial action

Check pluggable part and replace if necessary.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SFP internal temperature is at low alarm level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP internal temperature is at low alarm level on %s log

SFP internal temperature is at low alarm level on %s

The internal temperature of a transceiver inserted on a certain unit/port is at low alarm level.

Source	Severity
Port driver	Information

### Remedial action

Check pluggable part and replace if necessary.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP internal temperature is at low warning level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP internal temperature is at low warning level on %s log

SFP internal temperature is at low warning level on %s

The internal temperature of a transceiver inserted on a certain unit/port is at low warning level.

Source	Severity
Port driver	Information

### Remedial action

Check pluggable part and replace if necessary.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP internal temperature is no longer at the high alarm level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP internal temperature is no longer at the high alarm level log

SFP internal temperature is no longer at the high alarm level

Will be logged only after the actual value of the internal temperature has previously exceeded the high alarm threshold, and at the moment the value is below that threshold.

Source	Severity
Port Driver	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP internal temperature is no longer at the high alarm level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP internal temperature is no longer at the high alarm level on %s log

SFP internal temperature is no longer at the high alarm level on %s

Source	Severity
GBIC	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP internal temperature is no longer at the high warning level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP internal temperature is no longer at the high warning level log

SFP internal temperature is no longer at the high warning level

Will be logged only after the actual value of the internal temperature has previously exceeded the high warning threshold, and at the current moment the value is below that threshold.

Source	Severity
Port Driver	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP internal temperature is no longer at the high warning level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP internal temperature is no longer at the high warning level on %s log

SFP internal temperature is no longer at the high warning level on %s

Source	Severity
GBIC	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP internal temperature is no longer at the low alarm level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP internal temperature is no longer at the low alarm level log

SFP internal temperature is no longer at the low alarm level

Will be logged only after the actual value of the internal temperature has previously exceeded the low alarm threshold, and at the current moment the value is above that threshold.

Source	Severity
Port Driver	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP internal temperature is no longer at the low alarm level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP internal temperature is no longer at the low alarm level on %s log

SFP internal temperature is no longer at the low alarm level on %s

**Source**   **Severity**  
GBIC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SFP internal temperature is no longer at the low warning level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP internal temperature is no longer at the low warning level log

SFP internal temperature is no longer at the low warning level

Will be logged only after the actual value of the internal temperature has previously exceeded the low warning threshold, and at the current moment the value is above that threshold.

Source	Severity
Port Driver	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP internal temperature is no longer at the low warning level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP internal temperature is no longer at the low warning level on %s log

SFP internal temperature is no longer at the low warning level on %s

Source	Severity
GBIC	

Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP Received power is at high alarm level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP Received power is at high alarm level on %s log

SFP Received power is at high alarm level on %s

The received power of a transceiver inserted on a certain unit/port is at high alarm level.

Source	Severity
Port driver	Information

### Remedial action

Check pluggable part and replace if necessary.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP Received power is at high warning level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP Received power is at high warning level on %s log

SFP Received power is at high warning level on %s

The received power of a transceiver inserted on a certain unit/port is at high warning level.

Source	Severity
Port driver	Information

### Remedial action

Check pluggable part and replace if necessary.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP Received power is at low alarm level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP Received power is at low alarm level on %s log

SFP Received power is at low alarm level on %s

The received power of a transceiver inserted on a certain unit/port is at low alarm level.

Source	Severity
Port driver	Information

### Remedial action

Check pluggable part and replace if necessary.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP Received power is at low warning level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP Received power is at low warning level on %s log

SFP Received power is at low warning level on %s

The received power of a transceiver inserted on a certain unit/port is at low warning level.

Source	Severity
Port driver	Information

### Remedial action

Check pluggable part and replace if necessary.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP Received power is no longer at the high alarm level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP Received power is no longer at the high alarm level log

SFP Received power is no longer at the high alarm level

Will be logged only after the actual value of the RX power has previously exceeded the alarm threshold, and at the current moment the value is below that threshold.

Source	Severity
Port Driver	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP Received power is no longer at the high alarm level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP Received power is no longer at the high alarm level on %s log

SFP Received power is no longer at the high alarm level on %s

**Source**   **Severity**

GBIC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SFP Received power is no longer at the high warning level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP Received power is no longer at the high warning level log

SFP Received power is no longer at the high warning level

Will be logged only after the actual value of the RX power has previously exceeded the warning threshold, and at the current moment the value is below that threshold.

Source	Severity
Port Driver	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP Received power is no longer at the high warning level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP Received power is no longer at the high warning level on %s log

SFP Received power is no longer at the high warning level on %s

Source	Severity
GBIC	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP Received power is no longer at the low alarm level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP Received power is no longer at the low alarm level log

SFP Received power is no longer at the low alarm level

Will be logged only after the actual value of the RX power has previously exceeded the alarm threshold, and at the current moment the value is below that threshold.

Source	Severity
Port Driver	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP Received power is no longer at the low alarm level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP Received power is no longer at the low alarm level on %s log

SFP Received power is no longer at the low alarm level on %s

**Source**   **Severity**

GBIC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP Received power is no longer at the low warning level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP Received power is no longer at the low warning level log

SFP Received power is no longer at the low warning level

Will be logged only after the actual value of the RX power has previously exceeded the warning threshold, and at the current moment the value is below that threshold.

Source	Severity
Port Driver	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP Received power is no longer at the low warning level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP Received power is no longer at the low warning level on %s log

SFP Received power is no longer at the low warning level on %s

Source	Severity
GBIC	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP TX Bias current is at high alarm level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP TX Bias current is at high alarm level on %s log

SFP TX Bias current is at high alarm level on %s

The TX Bias current of a transceiver inserted on a certain unit/port is at high alarm level.

Source	Severity
Port driver	Information

### Remedial action

Check pluggable part and replace if necessary.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP TX Bias current is at high warning level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP TX Bias current is at high warning level on %s log

SFP TX Bias current is at high warning level on %s

The TX Bias current of a transceiver inserted on a certain unit/port is at high warning level.

Source	Severity
Port driver	Information

### Remedial action

Check pluggable part and replace if necessary.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SFP TX Bias current is at low alarm level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP TX Bias current is at low alarm level on %s log

SFP TX Bias current is at low alarm level on %s

The TX Bias current of a transceiver inserted on a certain unit/port is at low alarm level.

Source	Severity
Port driver	Information

### Remedial action

Check pluggable part and replace if necessary.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP TX Bias current is at low warning level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP TX Bias current is at low warning level on %s log

SFP TX Bias current is at low warning level on %s

The TX Bias current of a transceiver inserted on a certain unit/port is at low warning level.

Source	Severity
Port driver	Information

### Remedial action

Check pluggable part and replace if necessary.



# SFP TX Bias current is no longer at the high warning level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP TX Bias current is no longer at the high warning level on %s log

SFP TX Bias current is no longer at the high warning level on %s

**Source**   **Severity**  
GBIC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP TX Bias current is no longer at the low warning level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP TX Bias current is no longer at the low warning level on %s log

SFP TX Bias current is no longer at the low warning level on %s

**Source**   **Severity**

GBIC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP TX Bias is no longer at the high alarm level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP TX Bias is no longer at the high alarm level log

SFP TX Bias is no longer at the high alarm level

Will be logged only after the actual value of the bias has previously exceeded the alarm threshold, and at the current moment the value is below that threshold.

Source	Severity
Port Driver	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP TX Bias is no longer at the high alarm level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP TX Bias is no longer at the high alarm level on %s log

SFP TX Bias is no longer at the high alarm level on %s

**Source**   **Severity**

GBIC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP TX Bias is no longer at the high warning level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP TX Bias is no longer at the high warning level log

SFP TX Bias is no longer at the high warning level

Will be logged only after the actual value of the bias has previously exceeded the warning threshold, and at the current moment the value is below that threshold.

Source	Severity
Port Driver	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP TX Bias is no longer at the low alarm level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP TX Bias is no longer at the low alarm level log

SFP TX Bias is no longer at the low alarm level

Will be logged only after the actual value of the bias has previously exceeded the alarm threshold, and at the current moment the value is below that threshold.

Source	Severity
Port Driver	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SFP TX Bias is no longer at the low alarm level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP TX Bias is no longer at the low alarm level on %s log

SFP TX Bias is no longer at the low alarm level on %s

**Source**   **Severity**

GBIC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP TX Bias is no longer at the low warning level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP TX Bias is no longer at the low warning level log

SFP TX Bias is no longer at the low warning level

Will be logged only after the actual value of the bias has previously exceeded the warning threshold and at the current moment the value is above that threshold.

Source	Severity
Port Driver	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP TX output power is at high alarm level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP TX output power is at high alarm level on %s log

SFP TX output power is at high alarm level on %s

The TX output power of a transceiver inserted on a certain unit/port is at high alarm level.

Source	Severity
Port driver	Information

### Remedial action

Check pluggable part and replace if necessary.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP TX output power is at high warning level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP TX output power is at high warning level on %s log

SFP TX output power is at high warning level on %s

The TX output power of a transceiver inserted on a certain unit/port is at high warning level.

Source	Severity
Port driver	Information

### Remedial action

Check pluggable part and replace if necessary.



# SFP TX output power is at low alarm level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP TX output power is at low alarm level on %s log

SFP TX output power is at low alarm level on %s

The TX output power of a transceiver inserted on a certain unit/port is at low alarm level.

Source	Severity
Port driver	Information

### Remedial action

Check pluggable part and replace if necessary.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP TX output power is at low warning level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP TX output power is at low warning level on %s log

SFP TX output power is at low warning level on %s

The TX output power of a transceiver inserted on a certain unit/port is at low warning level.

Source	Severity
Port driver	Information

### Remedial action

Check pluggable part and replace if necessary.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP TX output power is no longer at the high alarm level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP TX output power is no longer at the high alarm level log

SFP TX output power is no longer at the high alarm level

Will be logged only after the actual value of the tx power has previously exceeded the alarm threshold, and at the current moment the value is below that threshold.

Source	Severity
Port Driver	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP TX output power is no longer at the high alarm level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP TX output power is no longer at the high alarm level on %s log

SFP TX output power is no longer at the high alarm level on %s

### Source   Severity

GBIC

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SFP TX output power is no longer at the high warning level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP TX output power is no longer at the high warning level log

SFP TX output power is no longer at the high warning level

Will be logged only after the actual value of the tx power has previously exceeded the warning threshold, and at the current moment the value is below that threshold.

Source	Severity
Port Driver	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP TX output power is no longer at the high warning level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP TX output power is no longer at the high warning level on %s log

SFP TX output power is no longer at the high warning level on %s

Source	Severity
GBIC	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP TX output power is no longer at the low alarm level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP TX output power is no longer at the low alarm level log

SFP TX output power is no longer at the low alarm level

Will be logged only after the actual value of the tx power has previously exceeded the alarm threshold, and at the current moment the value is below that threshold.

Source	Severity
Port Driver	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP TX output power is no longer at the low alarm level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP TX output power is no longer at the low alarm level on %s log

SFP TX output power is no longer at the low alarm level on %s

**Source**   **Severity**

GBIC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP TX output power is no longer at the low warning level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP TX output power is no longer at the low warning level log

SFP TX output power is no longer at the low warning level

Will be logged only after the actual value of the tx power has previously exceeded the warning threshold, and at the current moment the value is below that threshold.

Source	Severity
Port Driver	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SFP TX output power is no longer at the low warning level on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SFP TX output power is no longer at the low warning level on %s log

SFP TX output power is no longer at the low warning level on %s

**Source**   **Severity**  
GBIC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Simultaneous operations involving access asgn ifcs prohibited

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Simultaneous operations involving access asgn ifcs prohibited log

Simultaneous operations involving access asgn ifcs prohibited

Other similar operations involving the specified access assignment/interface(s) used by the policy are in progress.

Source	Severity
QoS	Information

### Remedial action

Try again later after all the pending operations are completed.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Simultaneous operations involving access asgn/ifcs prohibited

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Simultaneous operations involving access asgn/ifcs prohibited log

Simultaneous operations involving access asgn/ifcs prohibited

**Source   Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Simultaneous operations involving policies and blocks prohibited

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Simultaneous operations involving policies and blocks prohibited log

Simultaneous operations involving policies and blocks prohibited

Other similar operations involving the specified block used by the policy are in progress.

Source	Severity
QoS	Information

### Remedial action

Try again later after all the pending operations finished.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Simultaneous operations involving policies and ifcs prohibited

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Simultaneous operations involving policies and ifcs prohibited log

Simultaneous operations involving policies and ifcs prohibited

Interfaces directly associated with a policy must be stable (active, not being created/deleted).

Source	Severity
QoS	Information

### Remedial action

Try again later after all the pending operations finished.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Simultaneous operations involving policy blocks ifcs prohibited

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Simultaneous operations involving policy blocks ifcs prohibited log

Simultaneous operations involving policy blocks ifcs prohibited

Other similar operations involving the interface used by the block/policy are in progress.

Source	Severity
QoS	Information

### Remedial action

Try again later after all the pending operations are finished.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Simultaneous operations involving policy blocks/ifcs prohibited

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Simultaneous operations involving policy blocks/ifcs prohibited log

Simultaneous operations involving policy blocks/ifcs prohibited

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SLAMon Agent: agent IP address reset to default value

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SLAMon Agent: agent IP address reset to default value log

SLAMon Agent: agent IP address reset to default value

**Source**   **Severity**

SLAMon

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SLAMon Agent: CLI support not available

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SLAMon Agent: CLI support not available log

SLAMon Agent: CLI support not available

SLM CLI support not included in image - current N/A

Source	Severity
SLAMon	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SLAMon Agent: CLI timeout value out-of-range

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SLAMon Agent: CLI timeout value out-of-range log

SLAMon Agent: CLI timeout value out-of-range

The specified SLA Monitor agent CLI timeout value lies outside the acceptable range (60 seconds to 600 seconds).

Source	Severity
SLAMon	Information

### Remedial action

Specify an in-range value for the agent CLI timeout.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SLAMon Agent: disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SLAMon Agent: disabled log

SLAMon Agent: disabled

SLA Monitor agent state change detected — agent disabled.

Source	Severity
SLAMon	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SLAMon Agent: enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SLAMon Agent: enabled log

SLAMon Agent: enabled

SLA Monitor agent state change detected — agent enabled.

Source	Severity
SLAMon	Information

### Remedial action

No action required.



# SLAMon Agent: inconsistent IP address data specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SLAMon Agent: inconsistent IP address data specified log

SLAMon Agent: inconsistent IP address data specified

Source	Severity
SLAMon	Information

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SLAMon Agent: inconsistent UDP port data specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SLAMon Agent: inconsistent UDP port data specified log

SLAMon Agent: inconsistent UDP port data specified

Agent UDP (command) port and agent-to-agent communication UDP port values conflict with each other. The port values must be unique.

Source	Severity
SLAMon	Information

### Remedial action

Utilize defaults or specify unique agent UDP port values.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



SLAMon Agent: info: %d %d %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SLAMon Agent: info: %d %d %d log

SLAMon Agent: info: %d %d %d

General debug message — currently N/A

Source	Severity
SLAMon	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SLAMon Agent: invalid agent-to-agent port (must be even value)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SLAMon Agent: invalid agent-to-agent port (must be even value) log

SLAMon Agent: invalid agent-to-agent port (must be even value)

Agent-to-agent communication UDP port must be an even value.

Source	Severity
SLAMon	Information

### Remedial action

Specify an even value for port.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SLAMon Agent: message channel creation failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SLAMon Agent: message channel creation failure log

SLAMon Agent: message channel creation failure

Internal resource error - engineering log message.

Source	Severity
--------	----------

SLAMon	Critical
--------	----------

### Remedial action

Reset device

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SLAMon Agent: operation is restricted (CLI-only)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SLAMon Agent: operation is restricted (CLI-only) log

SLAMon Agent: operation is restricted (CLI-only)

The requested operation is only supported through the platform CLI.

Source	Severity
SLAMon	Information

### Remedial action

Utilize the platform CLI to perform the requested operation.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SLAMon Agent: platform CLI command interface initialization issue

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SLAMon Agent: platform CLI command interface initialization issue log

SLAMon Agent: platform CLI command interface initialization issue

Internal resource errore — engineering log message

Source	Severity
SLAMon	Critical

### Remedial action

Reset device.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SLAMon Agent: platform timer initialization issue

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SLAMon Agent: platform timer initialization issue log

SLAMon Agent: platform timer initialization issue

Internal resource error — engineering log message

Source	Severity
SLAMon	Critical

### Remedial action

Reset device.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SLAMon Agent: terminated

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SLAMon Agent: terminated log

SLAMon Agent: terminated

The agent task logic has been terminated.

Source	Severity
--------	----------

SLAMon	Critical
--------	----------

### Remedial action

System reset required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SLAMon Agent: terminated - command/frame processing issue detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SLAMon Agent: terminated - command/frame processing issue detected log

SLAMon Agent: terminated - command/frame processing issue detected

The agent command/packet receive logic detected an error, causing the agent operation to be terminated.

Source	Severity
--------	----------

SLAMon	Critical
--------	----------

### Remedial action

System reset required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SLAMon Agent: terminated - NTR test exception detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SLAMon Agent: terminated - NTR test exception detected log

SLAMon Agent: terminated - NTR test exception detected

The agent NTR test support detected a failure during test processing, causing agent operation to be terminated.

Source	Severity
--------	----------

SLAMon	Critical
--------	----------

### Remedial action

System reset required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SLAMon Agent: terminated - resources unavailable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SLAMon Agent: terminated - resources unavailable log

SLAMon Agent: terminated - resources unavailable

Resources required for agent initialization are not available, causing agent operation to be terminated. An invalid configuration, such as when the same port values are specified for agent-server and agent-agent communication, can also impact resource availability.

Source	Severity
--------	----------

SLAMon	Critical
--------	----------

### Remedial action

System reset required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SLAMon Agent: terminated - RTP test exception detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SLAMon Agent: terminated - RTP test exception detected log

SLAMon Agent: terminated - RTP test exception detected

The agent RTP test support detected a failure during test processing, causing agent operation to be terminated.

Source	Severity
SLAMon	Critical

### Remedial action

System reset required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



%s line %d: Dropping msg that originated from this unit (#%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## %s line %d: Dropping msg that originated from this unit (#%d) log

%s line %d: Dropping msg that originated from this unit (#%d)

**Source    Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



%s line %d: Logical unit #%d out of range

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## %s line %d: Logical unit #%d out of range log

%s line %d: Logical unit #%d out of range

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





%s line %d: Physical unit # %d out of range

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## %s line %d: Physical unit # %d out of range log

%s line %d: Physical unit # %d out of range

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



%s line %d: Stack links already down  
unit #%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## %s line %d: Stack links already down unit #%d log

%s line %d: Stack links already down unit #%d

**Source    Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



%s line %d: Unexpected stack link  
down msg from unit #%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## %s line %d: Unexpected stack link down msg from unit #%d log

%s line %d: Unexpected stack link down msg from unit #%d

### Source    Severity

SMGR

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SLPP: (Continued) - PDU was sent on Vlan %d.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SLPP: (Continued) - PDU was sent on Vlan %d. log

SLPP: (Continued) - PDU was sent on Vlan %d.

**Source    Severity**

SLPP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



SLPP-guard: hold-down timer has expired on port with SLPP-guard enabled. Port %s has been re-enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SLPP-guard: hold-down timer has expired on port with SLPP-guard enabled. Port %s has been re-enabled log

SLPP-guard: hold-down timer has expired on port with SLPP-guard enabled. Port %s has been re-enabled

The hold-down timer has expired and the port was re-enabled.

Source	Severity
SLPP Guard	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



SLPP-guard: SLPP-guard has not been enabled on port %s as no filters or filter precedences are available to setup an Ethertype filter

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SLPP-guard: SLPP-guard has not been enabled on port %s as no filters or filter precedences are available to setup an Ethertype filter log

SLPP-guard: SLPP-guard has not been enabled on port %s as no filters or filter precedences are available to setup an Ethertype filter

SLPP-guard filters error.

Source	Severity
SLPP Guard	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



SLPP-guard: SLPP packet received on port with SLPP-guard enabled. Port %s has been disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SLPP-guard: SLPP packet received on port with SLPP-guard enabled. Port %s has been disabled log

SLPP-guard: SLPP packet received on port with SLPP-guard enabled. Port %s has been disabled

A SLPP packet was received and SLPP-guard disabled the port.

Source	Severity
SLPP Guard	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SLPP: Warning - PDU was received on Unit %d, Port %d, Vlan %d.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SLPP: Warning - PDU was received on Unit %d, Port %d, Vlan %d. log

SLPP: Warning - PDU was received on Unit %d, Port %d, Vlan %d.

Source	Severity
SLPP	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SLPP Warning - PDU was received on Vlan VlanId Unit UnitNo Port PortNo .

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SLPP Warning - PDU was received on Vlan VlanId Unit UnitNo Port PortNo . log

SLPP Warning - PDU was received on Vlan VlanId Unit UnitNo Port PortNo .

The system detected an SLPP error when the SLPP packet sent is received back on a different VLAN.

Source	Severity
--------	----------

SMLT	Information
------	-------------

### Remedial action

Check for the correct port configuration



# SMLT IMC invalid cmd 1– StkCmd

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SMLT IMC invalid cmd 1– StkCmd log

SMLT IMC invalid cmd 1– StkCmd

An invalid SMLT Imc command received in the stack.

Source	Severity
SMLT	Information

### Remedial action

Restart the system.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SMLT IMC tx error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SMLT IMC tx error log

SMLT IMC tx error

The system failed to transmit the IMC message in the stack.

Source	Severity
SMLT	Information

### Remedial action

Restart the system.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SMLT input parameter error mlt port vlan

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SMLT input parameter error mlt port vlan log

SMLT input parameter error mlt port vlan

The system failed to enable the SMLT as the IST ports are not a part of the VLAN.

Source	Severity
SMLT	Information

### Remedial action

Check for the correct VLAN membership of the IST ports.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SMLT Stack db ex event num -0 – 0\*22221111

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SMLT Stack db ex event num -0 –0\*22221111 log

SMLT Stack db ex event num -0 –0\*22221111

Log SMLT db exchange events.

Source	Severity
SMLT	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SMLT stackEventNotify Invalid Msg Cmd - 0 – 0

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SMLT stackEventNotify Invalid Msg Cmd - 0 – 0 log

SMLT stackEventNotify Invalid Msg Cmd - 0 – 0

The system received an invalid stack related event.

Source	Severity
SMLT	Information

### Remedial action

Restart the system.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SMLT Stack inactive event 0-0-modMask

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SMLT Stack inactive event 0-0- modMask log

SMLT Stack inactive event 0-0- modMask

Log SMLT unit inactive events.

Source	Severity
SMLT	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SMLT Stack joined event num - 0 – 0\*33331111

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SMLT Stack joined event num - 0 – 0\*33331111 log

SMLT Stack joined event num - 0 – 0\*33331111

Log SMLT stack Join events.

Source	Severity
SMLT	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SMLT Stack leaved event 0 - 0 - modMask

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SMLT Stack leaved event 0 - 0 - modMask log

SMLT Stack leaved event 0 - 0 - modMask

Log SMLT stack leave events.

Source	Severity
SMLT	Information

### Remedial action

No action required.



# SMLT STP enabled on IST trunk trkNo stp group grp

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SMLT STP enabled on IST trunk trkNo stp group grp log

SMLT STP enabled on IST trunk trkNo stp group grp

STP enabled on the IST trunk error.

Source	Severity
SMLT	Information

### Remedial action

Disable the STP on IST trunk ports.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SMLT Warning - LAC SMLT with more than 8 links - key - count

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SMLT Warning - LAC SMLT with more than 8 links - key - count log

SMLT Warning - LAC SMLT with more than 8 links - key - count

LAC/SMLT with more than 8 links with specified key count.

Source	Severity
SMLT	Information

### Remedial action

Do not configure more than 8 links in the SMLT over the LAC configuration.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SMLT Warning - smltEnable Software License Error- 0 – 0

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SMLT Warning - smltEnable Software License Error- 0 – 0 log

SMLT Warning - smltEnable Software License Error- 0 – 0

This is a SMLT related warning indicating, software License error.

Source	Severity
SMLT	Information

### Remedial action

Check if a valid software license is available.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SMLT Warning - SMLT mismatched Lac\_Sys\_ID error shutdown all SMLT lac po

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SMLT Warning - SMLT mismatched Lac\_Sys\_ID error shutdown all SMLT lac po log

SMLT Warning - SMLT mismatched Lac\_Sys\_ID error shutdown all SMLT lac po

This is an SMLT related warning indicating, SMLT system ID mismatch.

Source	Severity
SMLT	Information

### Remedial action

The SMLT system ID did not match. Configure the correct system ID.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



%s neighbor is mis-configured, see  
neighboring unit for details

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## %s neighbor is mis-configured, see neighboring unit for details log

%s neighbor is mis-configured, see neighboring unit for details

**Source   Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SNMP-access is disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SNMP-access is disabled log

SNMP-access is disabled

SNMP access was disabled.

Source	Severity
SNMP	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SNMP-access is disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SNMP-access is disabled log

SNMP-access is disabled

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SNMP-access is enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SNMP-access is enabled log

SNMP-access is enabled

SNMP access was enabled.

Source	Severity
SNMP	Information

### Remedial action

None



# SNMP-access is enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SNMP-access is enabled log

SNMP-access is enabled

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SNTP Could not sync to NTP servers.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SNTP Could not sync to NTP servers. log

SNTP Could not sync to NTP servers.

The SNTP could not synchronize with any of the two NTP servers.

Source	Severity
--------	----------

SNTP	Critical
------	----------

### Remedial action

Try synchronizing to a valid NTP server. Make sure that the SNTP is connected to the NTP servers you are trying to synchronize with.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SNTP: Could not sync to SNTP servers.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SNTP: Could not sync to SNTP servers. log

SNTP: Could not sync to SNTP servers.

**Source**   **Severity**

SNTP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SNTP: First synchronization successful.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SNTP: First synchronization successful. log

SNTP: First synchronization successful.

The SNTP is synchronized with one of the NTP servers.

Source	Severity
SNTP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Source MAC address and mask values out-of-sync

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Source MAC address and mask values out-of-sync log

Source MAC address and mask values out-of-sync

The source MAC address and mask do not correspond (at least one address bit not included in mask is set).

Source	Severity
QoS	Serious

### Remedial action

Modify the source MAC address or mask.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SPBM adjacency with neighbor

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM adjacency with neighbor log

SPBM adjacency with neighbor

When IS-IS forms more than 1 adjacency with the same IS.

Source	Severity
ISIS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SPBM adjacency with neighbor

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM adjacency with neighbor log

SPBM adjacency with neighbor

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SPBM BVLAN is required but has not been configured

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM BVLAN is required but has not been configured log

SPBM BVLAN is required but has not been configured

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SPB-MC Dynamic i-sid range conflicts with existing i-sid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPB-MC Dynamic i-sid range conflicts with existing i-sid log

SPB-MC Dynamic i-sid range conflicts with existing i-sid

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



SPBM: Configuration on unit %d does not match BU configuration - SPBM local config discarded

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM: Configuration on unit %d does not match BU configuration - SPBM local config discarded log

SPBM: Configuration on unit %d does not match BU configuration - SPBM local config discarded

**Source**   **Severity**

SPB

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SPBM detect adj

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM detect adj log

SPBM detect adj

When the IS-IS adjacency state changes (down, init, up).

Source	Severity
ISIS	Information

### Remedial action

No action required.



# SPBM detect adj

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM detect adj log

SPBM detect adj

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SPBM: ERROR adding C-VLAN UNI for i-sid %d, vlan %d - no resources

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM: ERROR adding C-VLAN UNI for i-sid %d, vlan %d - no resources log

SPBM: ERROR adding C-VLAN UNI for i-sid %d, vlan %d - no resources

UNIs, NNIs and remote nodes use one or more Virtual Ports, depending on the configuration. The number of Virtual Ports that can be configured on the switch is limited.

Source	Severity
SPBM	Error

### Remedial action

See the "Limitations" section in the user manual. Remove unneeded UNIs.



# SPBM: ERROR adding i-sid %x to i-sid table - table full

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM: ERROR adding i-sid %x to i-sid table - table full log

SPBM: ERROR adding i-sid %x to i-sid table - table full

The number of I-SIDs that can be configured on the switch is limited.

Source	Severity
--------	----------

SPBM	Critical
------	----------

### Remedial action

See the "Limitations" section in the user manual. Remove unneeded I-SIDs.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SPBM: ERROR adding NNI on port %d vlan %d - no resources

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM: ERROR adding NNI on port %d vlan %d - no resources log

SPBM: ERROR adding NNI on port %d vlan %d - no resources

UNIs, NNIs and remote nodes use one or more Virtual Ports, depending on the configuration. The number of Virtual Ports that can be configured on the switch is limited.

Source	Severity
--------	----------

SPBM	Error
------	-------

### Remedial action

See the "Limitations" section in the user manual. Remove unneeded UNIs.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SPBM: ERROR adding peer %04x.%04x.%04x - no resources

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM: ERROR adding peer %04x.%04x.%04x - no resources log

SPBM: ERROR adding peer %04x.%04x.%04x - no resources

UNIs, NNIs and remote nodes use one or more Virtual Ports, depending on the configuration. The number of Virtual Ports that can be configured on the switch is limited. The remote system with the system-id listed in the text of the message will not receive.

Source	Severity
--------	----------

SPBM	Error
------	-------

### Remedial action

See the "Limitations" section in the user manual. Remove unneeded UNIs.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SPBM: ERROR adding switched UNI for i-sid %d, port %d, vlan %d - no resources

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM: ERROR adding switched UNI for i-sid %d, port %d, vlan %d - no resources log

SPBM: ERROR adding switched UNI for i-sid %d, port %d, vlan %d - no resources

When a trunk is disabled, the software automatically configures a UNI for each physical port in the trunk. UNIs, NNIs and remote nodes use one or more Virtual Ports, depending on the configuration.

Source	Severity
SPBM	Error

### Remedial action

See the "Limitations" section in the user manual. Remove unneeded UNIs.



# SPBM: ERROR adding Transparent UNI for i-sid %d, port %d - no resources

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM: ERROR adding Transparent UNI for i-sid %d, port %d - no resources log

SPBM: ERROR adding Transparent UNI for i-sid %d, port %d - no resources

Error adding Transparent UNI.

Source	Severity
SPB	Information

### Remedial action

No action required.



# SPBM: ERROR enabling SPBM due to Software License error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM: ERROR enabling SPBM due to Software License error log

SPBM: ERROR enabling SPBM due to Software License error

SPBM License missing or invalid; IS-IS protocol will not run.

Source	Severity
SPBM	Critical

### Remedial action

Run

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SPBM: ERROR same value for System ID and SMLT VIRTUAL BMAC - ISIS disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM: ERROR same value for System ID and SMLT VIRTUAL BMAC - ISIS disabled log

SPBM: ERROR same value for System ID and SMLT VIRTUAL BMAC - ISIS disabled

**Source**   **Severity**  
SPB

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SPBM: ERROR Trying to delete a non existing entry

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM: ERROR Trying to delete a non existing entry log

SPBM: ERROR Trying to delete a non existing entry

**Source**   **Severity**

SPB

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SPBM: ERROR updating UNI for port %d/%d - no resources

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM: ERROR updating UNI for port %d/%d - no resources log

SPBM: ERROR updating UNI for port %d/%d - no resources

UNIs, NNIs and remote nodes use one or more Virtual Ports, depending on the configuration. The number of Virtual Ports that can be configured on the switch is limited.

Source	Severity
--------	----------

SPBM	Error
------	-------

### Remedial action

See the "Limitations" section in the user manual. Remove unneeded UNIs.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SPBM: ERROR updating UNIs for trunk %d - no resources

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM: ERROR updating UNIs for trunk %d - no resources log

SPBM: ERROR updating UNIs for trunk %d - no resources

**Source**   **Severity**

SPB

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SPBM instance already exists

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM instance already exists log

SPBM instance already exists

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SPBM instance does not exist

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM instance does not exist log

SPBM instance does not exist

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SPBM instance is not enabled on this IS-IS interface

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM instance is not enabled on this IS-IS interface log

SPBM instance is not enabled on this IS-IS interface

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



SPBM: IPFIX over port %d/%d is disabled. IPFIX cannot be enabled over NNI

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM: IPFIX over port %d/%d is disabled. IPFIX cannot be enabled over NNI log

SPBM: IPFIX over port %d/%d is disabled. IPFIX cannot be enabled over NNI

**Source**   **Severity**

SPB

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



SPBM: IPFIX over port %d is disabled.  
IPFIX cannot be enabled over NNI

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM: IPFIX over port %d is disabled. IPFIX cannot be enabled over NNI log

SPBM: IPFIX over port %d is disabled. IPFIX cannot be enabled over NNI

Source	Severity
SPB	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SPBM ISIS

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM ISIS log

SPBM ISIS

An IS-IS trap indicating that a Hello packet with a duplicate system-id has been received.

Source	Severity
ISIS	Information

### Remedial action

Correct IS-IS system-id configuration.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SPBM ISIS

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM ISIS log

SPBM ISIS

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SPBM ISIS detect duplicate nick-name

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM ISIS detect duplicate nick-name log

SPBM ISIS detect duplicate nick-name

An IS-IS trap indicating that a LSP with a duplicate nickname has received.

Source	Severity
ISIS	Information

### Remedial action

Correct IS-IS SPBM nick-name configuration.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SPBM ISIS detect duplicate nick-name

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM ISIS detect duplicate nick-name log

SPBM ISIS detect duplicate nick-name

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SPBM ISIS node

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM ISIS node log

SPBM ISIS node

An IS-IS trap was sent indicating that a LSP with a different value of I1-metric has been received

Source	Severity
ISIS	Information

### Remedial action

Correct SPBM I1-metric configuration.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SPBM ISIS node

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM ISIS node log

SPBM ISIS node

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SPBM: Node already present on unit %d – will not add again

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM: Node already present on unit %d – will not add again log

SPBM: Node already present on unit %d – will not add again

The node that the agent spb logic is trying to add already exists on a different unit. Adding it again on the current unit would result in stack crash.

Source	Severity
SPB	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SPBM system ID cannot be same as IST peer system ID

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM system ID cannot be same as IST peer system ID log

SPBM system ID cannot be same as IST peer system ID

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SPBM system ID cannot be same as IST virtual bmac

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM system ID cannot be same as IST virtual bmac log

SPBM system ID cannot be same as IST virtual bmac

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SPBM system nickname is required but has not been configured

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM system nickname is required but has not been configured log

SPBM system nickname is required but has not been configured

Source	Severity
ISIS	

Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SPBM transparent UNI already configured on port

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SPBM transparent UNI already configured on port log

SPBM transparent UNI already configured on port

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Specified Destination Layer 4 min max range not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified Destination Layer 4 min max range not supported log

Specified Destination Layer 4 min max range not supported

The destination port range is not supported.

Source	Severity
QoS	Serious

### Remedial action

Check the documentation if necessary and adapt it to a supported port range.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Specified Destination Layer 4 min/max range not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified Destination Layer 4 min/max range not supported log

Specified Destination Layer 4 min/max range not supported

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Specified filter criteria contains conflicting data

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified filter criteria contains conflicting data log

Specified filter criteria contains conflicting data

**Source   Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Specified filter criteria is invalid inconsistent

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified filter criteria is invalid inconsistent log

Specified filter criteria is invalid inconsistent

Invalid/inconsistent filter criteria detected in classifier.

Source	Severity
QoS	Serious

### Remedial action

Identify and remove the inconsistent/invalid data.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Specified filter criteria is invalid/inconsistent

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified filter criteria is invalid/inconsistent log

Specified filter criteria is invalid/inconsistent

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Specified filter criteria too complex

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified filter criteria too complex log

Specified filter criteria too complex

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Specified filter information not found

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified filter information not found log

Specified filter information not found

Failed to find the corresponding classifier in the datapath filter manager table.

Source	Severity
QoS	Critical

### Remedial action

Check that the entry queried exists, if so try resetting the QoS agent or the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Specified filter manager resource invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified filter manager resource invalid log

Specified filter manager resource invalid

Filter manager detected an invalid unit.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Specified filter manager resource uninitialized

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified filter manager resource uninitialized log

Specified filter manager resource uninitialized

Unable to initialize the resource support.

Source	Severity
QoS	Critical

### Remedial action

Reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Specified inner VLAN ID min max range not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified inner VLAN ID min max range not supported log

Specified inner VLAN ID min max range not supported

Inner VLAN ID range not supported.

Source	Severity
QoS	Serious

### Remedial action

Check the documentation if necessary and adapt it to a supported port range.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Specified inner VLAN ID min/max range not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified inner VLAN ID min/max range not supported log

Specified inner VLAN ID min/max range not supported

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Specified IS-IS BVLAN does not currently exist

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified IS-IS BVLAN does not currently exist log

Specified IS-IS BVLAN does not currently exist

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Specified IS-IS BVLAN is not an SPBM VLAN

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified IS-IS BVLAN is not an SPBM VLAN log

Specified IS-IS BVLAN is not an SPBM VLAN

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Specified IS-IS system ID is invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified IS-IS system ID is invalid log

Specified IS-IS system ID is invalid

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Specified metering operation not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified metering operation not supported log

Specified metering operation not supported

The metering operation is not supported on the target hardware.

Source	Severity
QoS	Serious

### Remedial action

Create and use a compatible meter.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Specified metering statistics entry already in-use (by policy)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified metering statistics entry already in-use (by policy) log

Specified metering statistics entry already in-use (by policy)

Installing a meter with the same statistics entry already in use by a policy is not allowed, even though sharing a counter entry across meters is supported.

Source	Severity
QoS	Serious

### Remedial action

Enter a different statistics entry or remove the policy(s).

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Specified policy components (classifiers) conflicting

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified policy components (classifiers) conflicting log

Specified policy components (classifiers) conflicting

All the masks/filters must correspond.

Source	Severity
QoS	Serious

### Remedial action

Separate conflicting classifiers into multiple policies.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Specified policy criteria too complex

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified policy criteria too complex log

Specified policy criteria too complex

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Specified policy identifier (cookie) invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified policy identifier (cookie) invalid log

Specified policy identifier (cookie) invalid

Filter Manager was unable to find the corresponding cookie for the specified policy.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.



# Specified policy statistics entry already in-use (by meter)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified policy statistics entry already in-use (by meter) log

Specified policy statistics entry already in-use (by meter)

The same statistics entry is already associated with a meter. This is currently not allowed. Sharing a count entry across policies is supported.

Source	Severity
QoS	Serious

### Remedial action

Enter a different statistics entry or remove the meter.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Specified precedence mask reservation not found

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified precedence mask reservation not found log

Specified precedence mask reservation not found

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Specified precedence mask reservation parameter invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified precedence mask reservation parameter invalid log

Specified precedence mask reservation parameter invalid

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Specified queue set information invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified queue set information invalid log

Specified queue set information invalid

Invalid information regarding queue set (queue number must be in supported range and the egress flag must be set).

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Correct queue information and try again.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Specified rule/precedence mask reservation not found

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified rule/precedence mask reservation not found log

Specified rule/precedence mask reservation not found

**Source   Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Specified shaping bucket size out of supported range

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified shaping bucket size out of supported range log

Specified shaping bucket size out of supported range

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Specified shaping rate out of supported range

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified shaping rate out of supported range log

Specified shaping rate out of supported range

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Specified Source Layer 4 min max range not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified Source Layer 4 min max range not supported log

Specified Source Layer 4 min max range not supported

The source port range is not supported.

Source	Severity
QoS	Serious

### Remedial action

Check the documentation if necessary and adapt it to a supported port range.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Specified Source Layer 4 min/max range not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified Source Layer 4 min/max range not supported log

Specified Source Layer 4 min/max range not supported

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Specified statistics tracking operation not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified statistics tracking operation not supported log

Specified statistics tracking operation not supported

**Source   Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Specified token bucket criteria out of range

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified token bucket criteria out of range log

Specified token bucket criteria out of range

Unsupported meter rate range specified.

Source	Severity
QoS	Serious

### Remedial action

Enter a supported meter rate range.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Specified token bucket refresh interval not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified token bucket refresh interval not supported log

Specified token bucket refresh interval not supported

The refresh interval must be 8.

Source	Severity
QoS	Serious

### Remedial action

Enter the correct refresh interval.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Specified token bucket size (burst size) not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified token bucket size (burst size) not supported log

Specified token bucket size (burst size) not supported

The only supported token bucket sizes are  $2^n K$  where  $n$  must be between 2 and 14.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Enter one of the valid token bucket sizes.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Specified user policy interface currently QoS-disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified user policy interface currently QoS-disabled log

Specified user policy interface currently QoS-disabled

You cannot configure a user policy entry if the target interface is QoS disabled.

Source	Severity
QoS	Serious

### Remedial action

Choose a different interface.



# Specified VLAN ID min max range not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified VLAN ID min max range not supported log

Specified VLAN ID min max range not supported

VLAN ID range not supported.

Source	Severity
QoS	Serious

### Remedial action

Check the documentation if necessary and adapt it to a supported port range.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Specified VLAN ID min/max range not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Specified VLAN ID min/max range not supported log

Specified VLAN ID min/max range not supported

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Src Layer 4 port min max values invalid (max must be = to min)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Src Layer 4 port min max values invalid (max must be = to min) log

Src Layer 4 port min max values invalid (max must be = to min)

The maximum source port must be bigger than the minimum destination port.

Source	Severity
QoS	Serious

### Remedial action

Correct source port range limits.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Src Layer 4 port min/max values invalid (max must be $\geq$ to min)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Src Layer 4 port min/max values invalid (max must be $\geq$ to min) log

Src Layer 4 port min/max values invalid (max must be  $\geq$  to min)

Source	Severity
QoS	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# srTCM meter issue - CIR must be the same in both meters

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## srTCM meter issue - CIR must be the same in both meters log

srTCM meter issue - CIR must be the same in both meters

Different CIRs detected in the two meters.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Enter the same CIR for both meters.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# srTCM meter issue - EBS must be greater than CBS

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## srTCM meter issue - EBS must be greater than CBS log

srTCM meter issue - EBS must be greater than CBS

The burst size is not consistent.

Source	Severity
QoS	Serious

### Remedial action

Enter a EBS that is greater than CBS.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# srTCM trTCM meter issue - diff algorithms in associated meters

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## srTCM trTCM meter issue - diff algorithms in associated meters log

srTCM trTCM meter issue - diff algorithms in associated meters

Meter types and rate values are not synchronized .

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Associate a single algorithm for a meter.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# srTCM/trTCM meter issue - diff algorithms in associated meters

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## srTCM/trTCM meter issue - diff algorithms in associated meters log

srTCM/trTCM meter issue - diff algorithms in associated meters

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# srTCM trTCM meter issue - referenced meter incompatible unknown

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## srTCM trTCM meter issue - referenced meter incompatible unknown log

srTCM trTCM meter issue - referenced meter incompatible unknown

The referenced meter is compatible (srTCM/trTCM issue).

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Check for and remove any conflicts or incompatible data.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# srTCM/trTCM meter issue - referenced meter incompatible/unknown

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## srTCM/trTCM meter issue - referenced meter incompatible/unknown log

srTCM/trTCM meter issue - referenced meter incompatible/unknown

**Source**   **Severity**  
QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# srTCM trTCM meter issue - too many cascaded meters

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## srTCM trTCM meter issue - too many cascaded meters log

srTCM trTCM meter issue - too many cascaded meters

Meter cascade level is limited to two.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Enter only two meter cascade levels.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# srTCM/trTCM meter issue - too many cascaded meters

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## srTCM/trTCM meter issue - too many cascaded meters log

srTCM/trTCM meter issue - too many cascaded meters

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC ASCII CFG download SFTP failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC ASCII CFG download SFTP failure log

SSHC ASCII CFG download SFTP failure

SSHC Client failed to download the ASCII CFG file from SFTP.

Source	Severity
SSHC (SFTP and SSH Client)	Information

### Remedial action

Check IP address settings, host reachability, host key existence and username.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC: ASCII CFG download SFTP failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC: ASCII CFG download SFTP failure log

SSHC: ASCII CFG download SFTP failure

Download of ASCII config file to SFTP failed.

Source	Severity
SFTP	Information

### Remedial action

Check IP address settings, host reachability, host key existence and username.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC ASCII CFG upload SFTP failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC ASCII CFG upload SFTP failure log

SSHC ASCII CFG upload SFTP failure

SSHC Client failed to upload the ASCII CFG file to SFTP.

Source	Severity
SSHC (SFTP and SSH Client)	Information

### Remedial action

Check IP address settings, host reachability, host key existence and username.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SSHC: ASCII CFG upload SFTP failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC: ASCII CFG upload SFTP failure log

SSHC: ASCII CFG upload SFTP failure

Upload of ASCII config file to SFTP failed.

Source	Severity
SFTP	Information

### Remedial action

Check IP address settings, host reachability, host key existence and username.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC CFG download SFTP failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC CFG download SFTP failure log

SSHC CFG download SFTP failure

SSHC Client failed to download the CFG file from SFTP.

Source	Severity
SSHC (SFTP and SSH Client)	Information

### Remedial action

Check IP address settings, host reachability, host key existence and username.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC: CFG download SFTP failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC: CFG download SFTP failure log

SSHC: CFG download SFTP failure

Communication with server failed for some reason, therefore download failed.

Source	Severity
SSH Client	Information

### Remedial action

Check if ping works (if not dropped by firewall) for SFTP server. If full path is used verify if the path exists on the server. Check the server settings for sshd/sftp.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC CFG upload SFTP failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC CFG upload SFTP failure log

SSHC CFG upload SFTP failure

SSHC Client failed to upload the CFG file to SFTP.

Source	Severity
SSHC (SFTP and SSH Client)	Information

### Remedial action

Check IP address settings, host reachability, host key existence and username.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC: CFG upload SFTP failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC: CFG upload SFTP failure log

SSHC: CFG upload SFTP failure

Communication with server failed for some reason, therefore upload failed.

Source	Severity
SSH Client	Information

### Remedial action

Check if ping works (if not dropped by firewall) for SFTP server. If full path is used verify if the path exists on the server. Check the server settings for sshd/sftp.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC DSA Authentication failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC DSA Authentication failure log

SSHC DSA Authentication failure

Failed to authenticate to the SFTP server using the current DSA key as the current public DSA key of the switch/stack was not added to the SFTP server's "authorized keys" list..

Source	Severity
SFTP Client	Information

### Remedial action

Upload the key to TFTP/USB and add it to the server's "authorized keys" list.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC: DSA Authentication failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC: DSA Authentication failure log

SSHC: DSA Authentication failure

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC: DSA key deleted

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC: DSA key deleted log

SSHC: DSA key deleted

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SSHC: DSA key generation completed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC: DSA key generation completed log

SSHC: DSA key generation completed

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC DSA key generation failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC DSA key generation failure log

SSHC DSA key generation failure

SSHC Client failed to generate the DSA key.

Source	Severity
SSHC (SFTP and SSH Client)	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC: DSA key generation failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC: DSA key generation failure log

SSHC: DSA key generation failure

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC DSA key save failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC DSA key save failure log

SSHC DSA key save failure

SSHC Client failed to save the DSA key.

### Source

SSHC (SFTP and SSH Client)

### Severity

Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC: DSA key save failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC: DSA key save failure log

SSHC: DSA key save failure

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC DSA key upload TFTP failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC DSA key upload TFTP failure log

SSHC DSA key upload TFTP failure

SSHC Client failed to upload the DSA key to TFTP.

Source	Severity
SSHC (SFTP and SSH Client)	Information

### Remedial action

Check the TFTP server connection, and try again.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC: DSA key upload TFTP failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC: DSA key upload TFTP failure log

SSHC: DSA key upload TFTP failure

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC DSA key upload USB failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC DSA key upload USB failure log

SSHC DSA key upload USB failure

SSHC Client failed to upload the DSA key to the USB as, the memory stick is full or corrupted.

### Source

SSHC (SFTP and SSH Client)

### Severity

Information

### Remedial action

Create space on memory stick or replace the memory stick, and try again.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SSHC: DSA key upload USB failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC: DSA key upload USB failure log

SSHC: DSA key upload USB failure

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH\_CLIENT Key couldnt be saved for host ip address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH\_CLIENT Key couldnt be saved for host ip address log

SSH\_CLIENT Key couldnt be saved for host ip address

New host's key could not be saved as NVRAM is full or defective.

Source	Severity
SSH Client	Information

### Remedial action

Remove other host's keys to create space on NVRAM, and try again.



# SSH\_CLIENT: Key couldn't be saved for host %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH\_CLIENT: Key couldn't be saved for host %s log

SSH\_CLIENT: Key couldn't be saved for host %s

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH CLIENT SSH Connection to IP ip address was closed because parent console session console session ID was closed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH CLIENT SSH Connection to IP ip address was closed because parent console session console session ID was closed log

SSH CLIENT SSH Connection to IP ip address was closed because parent console session console session ID was closed

SSH Connection is closed as the console session, from which SSH Client was launched closed. (for example, ssh DUT, then ssh PC, then close ssh to DUT session)

Source	Severity
SSH Client	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



SSH CLIENT: SSH Connection to %s was closed because parent console session #%%d was closed.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH CLIENT: SSH Connection to %s was closed because parent console session #%%d was closed. log

SSH CLIENT: SSH Connection to %s was closed because parent console session #%%d was closed.

**Source**   **Severity**  
SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH CLIENT SSH Connection to %s was disconnected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH CLIENT SSH Connection to %s was disconnected log

SSH CLIENT SSH Connection to %s was disconnected

Successfully disconnected the SSH connection.

Source	Severity
SSH Client	Information

### Remedial action

No action required.



SSH CLIENT: SSH Connection to %s  
was disconnected by host. Connection  
time: %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH CLIENT: SSH Connection to %s was disconnected by host. Connection time: %s log

SSH CLIENT: SSH Connection to %s was disconnected by host. Connection time: %s

Host disconnected the SSH connection.

Source	Severity
SSH Client	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



SSH CLIENT: SSH Connection to %s  
was disconnected by host. Connection  
time: %s.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH CLIENT: SSH Connection to %s was disconnected by host. Connection time: %s. log

SSH CLIENT: SSH Connection to %s was disconnected by host. Connection time: %s.

**Source**   **Severity**  
SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





SSH CLIENT: SSH Connection to %s was disconnected by user. Connection time: %s.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH CLIENT: SSH Connection to %s was disconnected by user. Connection time: %s. log

SSH CLIENT: SSH Connection to %s was disconnected by user. Connection time: %s.

SSH user ended SSH connection.

Source	Severity
SSH Client	Information

### Remedial action

No action Required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH CLIENT Successful SSH Connection to %s using %s authentication

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH CLIENT Successful SSH Connection to %s using %s authentication log

SSH CLIENT Successful SSH Connection to %s using %s authentication

Successful SSH Connection.

Source	Severity
SSH Client	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH CLIENT: Successful SSH Connection to %s, using %s authentication

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH CLIENT: Successful SSH Connection to %s, using %s authentication log

SSH CLIENT: Successful SSH Connection to %s, using %s authentication

**Source**   **Severity**  
SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH: Client tried to authenticate with invalid certificate from address %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: Client tried to authenticate with invalid certificate from address %s log

SSH: Client tried to authenticate with invalid certificate from address %s

Source	Severity
SSH	Information

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH: Client tried to authenticate without principal name in certificate from address %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: Client tried to authenticate without principal name in certificate from address %s log

SSH: Client tried to authenticate without principal name in certificate from address %s

Source	Severity
SSH	Information

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH: Client tried to authenticate with revoked certificate from address %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: Client tried to authenticate with revoked certificate from address %s log

SSH: Client tried to authenticate with revoked certificate from address %s

Source	Severity
SSH	Information

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH: could not perform OCSP for the server certificate from address %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: could not perform OCSP for the server certificate from address %s log

SSH: could not perform OCSP for the server certificate from address %s

**Source    Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH: Couldn't create SSH Data Semaphore

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: Couldn't create SSH Data Semaphore log

SSH: Couldn't create SSH Data Semaphore

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SSHC Password Authentication failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC Password Authentication failure log

SSHC Password Authentication failure

SFTP download/upload operation failed due to incorrect password

Source	Severity
SFTP Client	Information

### Remedial action

Retry operation using the correct password.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC: Password Authentication failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC: Password Authentication failure log

SSHC: Password Authentication failure

Wrong username or password used, or password exceeded 30 characters.

Source	Severity
SSH Client	Information

### Remedial action

Check if user and password are correct and have 30 or less characters.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC RSA Authentication failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC RSA Authentication failure log

SSHC RSA Authentication failure

Failed to authenticate to the SFTP server using the current RSA key as it was not added to the SFTP server's "authorized keys" list..

Source	Severity
SFTP Client	Information

### Remedial action

Upload the key to TFTP/USB and add it to the server's "authorized keys" list.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC: RSA Authentication failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC: RSA Authentication failure log

SSHC: RSA Authentication failure

Mismatch or inconsistency between the generated key and the key uploaded on server.

Source	Severity
SSH Client	Information

### Remedial action

Check if the DSA/RSA key was handled correctly. If not sure regenerate the key and upload the new key using tftp server and then try again.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC: RSA key deleted

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC: RSA key deleted log

SSHC: RSA key deleted

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC: RSA key generation completed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC: RSA key generation completed log

SSHC: RSA key generation completed

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC RSA key generation failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC RSA key generation failure log

SSHC RSA key generation failure

SSHC Client failed to generate the RSA.

### Source

SSHC (SFTP and SSH Client)

### Severity

Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC RSA key save failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC RSA key save failure log

SSHC RSA key save failure

SSHC Client failed to save the RSA key.

### Source

SSHC (SFTP and SSH Client)

### Severity

Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SSHC RSA key upload TFTP failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC RSA key upload TFTP failure log

SSHC RSA key upload TFTP failure

SSHC Client failed to upload the RSA key to TFTP.

Source	Severity
SSHC (SFTP and SSH Client)	Information

### Remedial action

Check TFTP server connection, and try again.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC: RSA key upload TFTP failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC: RSA key upload TFTP failure log

SSHC: RSA key upload TFTP failure

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC RSA key upload USB failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC RSA key upload USB failure log

SSHC RSA key upload USB failure

SSHC Client failed to upload the RSA key to the USB as, the memory stick is full or corrupted.

### Source

SSHC (SFTP and SSH Client)

### Severity

Information

### Remedial action

Create space on memory stick or replace the memory stick, and try again.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC: RSA key upload USB failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC: RSA key upload USB failure log

SSHC: RSA key upload USB failure

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC server connection failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC server connection failure log

SSHC server connection failure

Failed to connect to SFTP server; following a command involving SFTP.

Source	Severity
SFTP Client	Information

### Remedial action

Check the connectivity to SFTP server. However, this error occurs when you attempt any authentication; it is not caused by authentication failures.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC: server connection failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC: server connection failure log

SSHC: server connection failure

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC: SSH Client session rekey failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC: SSH Client session rekey failure log

SSHC: SSH Client session rekey failure

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSHC: SSH Client session rekey success

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSHC: SSH Client session rekey success log

SSHC: SSH Client session rekey success

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SSH disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH disabled log

SSH disabled

The SSH is disabled

Source	Severity
SSH	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH: DSA Authentication failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: DSA Authentication failure log

SSH: DSA Authentication failure

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH: DSA auth key deleted

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: DSA auth key deleted log

SSH: DSA auth key deleted

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH DSA key deleted

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH DSA key deleted log

SSH DSA key deleted

The SSH DSA key deleted.

Source	Severity
SSH	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH DSA KEY generation completed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH DSA KEY generation completed log

SSH DSA KEY generation completed

The SSH DSA key generation completed.

Source	Severity
SSH	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH: DSA KEY generation completed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: DSA KEY generation completed log

SSH: DSA KEY generation completed

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH enabled in non-secure mode

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH enabled in non-secure mode log

SSH enabled in non-secure mode

The SSH is enabled in a non-secure mode.

Source	Severity
SSH	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH enabled in secure mode

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH enabled in secure mode log

SSH enabled in secure mode

The SSH is enabled in the secure mode.

Source	Severity
SSH	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SSH Maximum number of ssh sessions has been reached

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH Maximum number of ssh sessions has been reached log

SSH Maximum number of ssh sessions has been reached

The maximum number of SSH session is reached.

Source	Severity
SSH	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH: Maximum number of ssh sessions has been reached

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: Maximum number of ssh sessions has been reached log

SSH: Maximum number of ssh sessions has been reached

**Source   Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH: No response to OCSP query for client certificate from address %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: No response to OCSP query for client certificate from address %s log

SSH: No response to OCSP query for client certificate from address %s

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH: OCSP query verification passed for server certificate from address %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: OCSP query verification passed for server certificate from address %s log

SSH: OCSP query verification passed for server certificate from address %s

Source	Severity
SSH	Information

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH: OCSP test failed for client certificate from address %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: OCSP test failed for client certificate from address %s log

SSH: OCSP test failed for client certificate from address %s

**Source   Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH: OCSP test failed for server certificate from address %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: OCSP test failed for server certificate from address %s log

SSH: OCSP test failed for server certificate from address %s

**Source   Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH: Password Authentication failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: Password Authentication failure log

SSH: Password Authentication failure

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH: RADIUS server unreachable - client at address %s authenticated with local credentials

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: RADIUS server unreachable - client at address %s authenticated with local credentials

### Information log

SSH: RADIUS server unreachable - client at address %s authenticated with local credentials

When the RADIUS server is not reachable, the clients can still be authenticated using local credentials.

#### Source    Severity

SSH

#### Remedial action

Check RADIUS reachability.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>





# SSH: RSA Authentication failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: RSA Authentication failure log

SSH: RSA Authentication failure

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH: RSA auth key deleted

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: RSA auth key deleted log

SSH: RSA auth key deleted

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH RSA key deleted

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH RSA key deleted log

SSH RSA key deleted

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH RSA KEY generation completed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH RSA KEY generation completed log

SSH RSA KEY generation completed

The SSH RSA key is successfully generated.

Source	Severity
SSH	Information

### Remedial action

No action required.



# SSH: RSA KEY generation completed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: RSA KEY generation completed log

SSH: RSA KEY generation completed

**Source    Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH RSA key overwritten

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH RSA key overwritten log

SSH RSA key overwritten

The SSH RSA key is overwritten.

Source	Severity
SSH	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH: Server tried to authenticate with revoked certificate from address %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: Server tried to authenticate with revoked certificate from address %s log

SSH: Server tried to authenticate with revoked certificate from address %s

Source	Severity
SSH	Information

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH session closed by ip address remote host. Connection time h hours m minutes

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH session closed by ip address remote host. Connection time h hours m minutes log

SSH session closed by ip address remote host. Connection time h hours m minutes

Remote host closed the SSH session.

Source	Severity
SSH Client	Information

### Remedial action

No action required.





# SSH session login using port

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH session login using port log

SSH session login using port

Login session.

Source	Severity
SSH	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH session login using port:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH session login using port: log

SSH session login using port:

Source	Severity
--------	----------

SSH	
-----	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH: SSH session rekey failure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: SSH session rekey failure log

SSH: SSH session rekey failure

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH: SSH session rekey success

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: SSH session rekey success log

SSH: SSH session rekey success

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH: Succesfull response to OCSP query for client certificate from address %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: Succesfull response to OCSP query for client certificate from address %s log

SSH: Succesfull response to OCSP query for client certificate from address %s

Source	Severity
SSH	Information

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH System is generating DSA KEY wait ...

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH System is generating DSA KEY wait ... log

SSH System is generating DSA KEY wait ...

The system is generating the DSA key.

Source	Severity
SSH	Information

### Remedial action

No action required.



# SSH: System is generating DSA KEY, wait ...

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: System is generating DSA KEY, wait ... log

SSH: System is generating DSA KEY, wait ...

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH: System is generating RSA KEY, wait ...

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: System is generating RSA KEY, wait ... log

SSH: System is generating RSA KEY, wait ...

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SSH TFTP DSA key download complete

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH TFTP DSA key download complete log

SSH TFTP DSA key download complete

Download the SSH DSA key through the completed TFTP.

Source	Severity
SSH	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH TFTP RSA key download complete

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH TFTP RSA key download complete log

SSH TFTP RSA key download complete

SSH RSA key is successfully downloaded through TFTP.

Source	Severity
SSH	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH: The DSA key overwritten

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: The DSA key overwritten log

SSH: The DSA key overwritten

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH: The RSA key overwritten

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: The RSA key overwritten log

SSH: The RSA key overwritten

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH: Unknown response to OCSP query for client certificate from address %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: Unknown response to OCSP query for client certificate from address %s log

SSH: Unknown response to OCSP query for client certificate from address %s

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH: Unknown response to OCSP query for server certificate from address %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: Unknown response to OCSP query for server certificate from address %s log

SSH: Unknown response to OCSP query for server certificate from address %s

Source	Severity
SSH	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH USB DSA key download complete

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH USB DSA key download complete log

SSH USB DSA key download complete

The SSH DSA key downloading through the USB is completed.

Source	Severity
SSH	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH: USB DSA key download complete

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: USB DSA key download complete log

SSH: USB DSA key download complete

**Source    Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SSH USB RSA key download complete

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH USB RSA key download complete log

SSH USB RSA key download complete

The SSH RSA key is successfully downloaded through the USB.

Source	Severity
SSH	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSH: USB RSA key download complete

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH: USB RSA key download complete log

SSH: USB RSA key download complete

**Source**   **Severity**

SSH

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



%s %s in %s%s has expired

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## %s %s in %s%s has expired log

%s %s in %s%s has expired

Source	Severity
--------	----------

DIGICERT	
----------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



%s %s in %s%s will expire in %d days

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## %s %s in %s%s will expire in %d days log

%s %s in %s%s will expire in %d days

**Source**      **Severity**

DIGICERT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSL certificate creation completed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSL certificate creation completed log

SSL certificate creation completed

SSL certificate creation completed.

Source	Severity
SSL	Information

### Remedial action

No action required.



# SSL certificate creation failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSL certificate creation failed log

SSL certificate creation failed

SSL certificate creation failed.

Source	Severity
SSL	Information

### Remedial action

Retry.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSL certificate deleted

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSL certificate deleted log

SSL certificate deleted

SSL certificate deleted.

Source	Severity
SSL	Information

### Remedial action

No action required.



# SSL connection was closed from

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSL connection was closed from log

SSL connection was closed from

**Source**   **Severity**

SSL

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SSL disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSL disabled log

SSL disabled

SSL is disabled.

Source	Severity
SSL	Information

### Remedial action

No action required.



# SSL enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSL enabled log

SSL enabled

SSL is enabled.

Source	Severity
SSL	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSL negotiation failure from

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSL negotiation failure from log

SSL negotiation failure from

**Source**   **Severity**

SSL

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSL server reset

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSL server reset log

SSL server reset

SSL server reset.

Source	Severity
SSL	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SSL successful connection from

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSL successful connection from log

SSL successful connection from

**Source**   **Severity**

SSL

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack cable "Down 1" is misconfigured

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack cable "Down 1" is misconfigured log

Stack cable "Down 1" is misconfigured

Top cable of Downstream direction is misconfigured.

Source	Severity
HMOD	Information

### Remedial action

No action required.



# Stack cable "Down 2" is misconfigured

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack cable "Down 2" is misconfigured log

Stack cable "Down 2" is misconfigured

Bottom cable of Downstream direction is misconfigured.

Source	Severity
HMOD	Information

### Remedial action

No action required.



# Stack cable Down 1 is misconfigured

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack cable Down 1 is misconfigured log

Stack cable Down 1 is misconfigured

This message appears when the first downstream port is mis-configured.

Source	Severity
Hello Module	Error

### Remedial action

Connect the first downstream port to the first upstream port of the neighbor.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Stack cable Down 2 is misconfigured

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack cable Down 2 is misconfigured log

Stack cable Down 2 is misconfigured

This message appears when the second downstream port is mis-configured.

Source	Severity
Hello Module	Error

### Remedial action

Connect the second downstream port to the second upstream port of the neighbor.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack cable "Up 1" is misconfigured

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack cable "Up 1" is misconfigured log

Stack cable "Up 1" is misconfigured

Top cable of Upstream direction is misconfigured.

Source	Severity
HMOD	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack cable "Up 2" is misconfigured

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack cable "Up 2" is misconfigured log

Stack cable "Up 2" is misconfigured

Bottom cable of Upstream direction is misconfigured.

Source	Severity
HMOD	Information

### Remedial action

No action required.



# Stack cable Up 1 is misconfigured

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack cable Up 1 is misconfigured log

Stack cable Up 1 is misconfigured

This message appears when the first upstream port is mis-configured.

Source	Severity
Hello Module	Error

### Remedial action

Connect the first upstream port to the first downstream port of the neighbor.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack cable Up 2 is misconfigured

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack cable Up 2 is misconfigured log

Stack cable Up 2 is misconfigured

This message appears when the second upstream port is mis-configured.

Source	Severity
Hello Module	Error

### Remedial action

Connect the second upstream port to the second downstream port of the neighbor.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack IP changed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack IP changed log

Stack IP changed

This message indicates that the Stack IP has changed.

Source	Severity
IPT	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack link down, neighboring unit is not in stack

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack link down, neighboring unit is not in stack log

Stack link down, neighboring unit is not in stack

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack Manager config file ver. %d upgraded to ver. %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack Manager config file ver. %d upgraded to ver. %d log

Stack Manager config file ver. %d upgraded to ver. %d

**Source   Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Stack Manager unable to read from to configuration file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack Manager unable to read from to configuration file log

Stack Manager unable to read from to configuration file

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack Manager unable to write to configuration file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack Manager unable to write to configuration file log

Stack Manager unable to write to configuration file

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack Mgr: error: %s line %d %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack Mgr: error: %s line %d %d log

Stack Mgr: error: %s line %d %d

**Source    Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack Mgr: error: %s line %d 0x%X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack Mgr: error: %s line %d 0x%X log

Stack Mgr: error: %s line %d 0x%X

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack Mgr: event received msg\_src=0x%X num= 0x%X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack Mgr: event received msg\_src=0x%X num= 0x%X log

Stack Mgr: event received msg\_src=0x%X num= 0x%X

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack Mgr: ignored event %s for state %s, arg: %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack Mgr: ignored event %s for state %s, arg: %d log

Stack Mgr: ignored event %s for state %s, arg: %d

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack Mgr: IMC ack msg failed: status %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack Mgr: IMC ack msg failed: status %d log

Stack Mgr: IMC ack msg failed: status %d

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Stack Mgr: info: %s line %d %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack Mgr: info: %s line %d %d log

Stack Mgr: info: %s line %d %d

**Source    Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





Stack Mgr: initialized arg1= %d arg2 =  
%d arg3 = %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack Mgr: initialized arg1= %d arg2 = %d arg3 = %d log

Stack Mgr: initialized arg1= %d arg2 = %d arg3 = %d

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack Mgr: internal 5670 ports INACTIVE 0x%X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack Mgr: internal 5670 ports INACTIVE 0x%X log

Stack Mgr: internal 5670 ports INACTIVE 0x%X

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack Mgr: NAP error: MAC not found, stack size %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack Mgr: NAP error: MAC not found, stack size %d log

Stack Mgr: NAP error: MAC not found, stack size %d

### Source    Severity

SMGR

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack Mgr: queue creation failed %s line %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack Mgr: queue creation failed %s line %d log

Stack Mgr: queue creation failed %s line %d

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack Mgr: queue rec error qid= 0x%X errno=0x%X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack Mgr: queue rec error qid= 0x%X errno=0x%X log

Stack Mgr: queue rec error qid= 0x%X errno=0x%X

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack Mgr: queue send error qid= 0x%X errno=0x%X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack Mgr: queue send error qid= 0x%X errno=0x%X log

Stack Mgr: queue send error qid= 0x%X errno=0x%X

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack Mgr: semaphore creation failed %s line %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack Mgr: semaphore creation failed %s line %d log

Stack Mgr: semaphore creation failed %s line %d

### Source    Severity

SMGR

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack Mgr: %s msg send failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack Mgr: %s msg send failed log

Stack Mgr: %s msg send failed

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Stack Mgr: startup event failed type: 0x%08X option: %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack Mgr: startup event failed type: 0x%08X option: %d log

Stack Mgr: startup event failed type: 0x%08X option: %d

**Source    Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack Mgr: STEG\_GO event missed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack Mgr: STEG\_GO event missed log

Stack Mgr: STEG\_GO event missed

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack Mgr: 0x%X 0x%X 0x%X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack Mgr: 0x%X 0x%X 0x%X log

Stack Mgr: 0x%X 0x%X 0x%X

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack must have a configured base unit!

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack must have a configured base unit! log

Stack must have a configured base unit!

No Base Unit is configured in the stack.

Source	Severity
Stack Manager	Information

### Remedial action

Configure one Base Unit in the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack operation mode modified to Hybrid and unit reset

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack operation mode modified to Hybrid and unit reset log

Stack operation mode modified to Hybrid and unit reset

Operational Mode was automatically changed and unit was restarted.

Source	Severity
Stack Manager	Serious

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack operation mode modified to Pure and unit reset

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack operation mode modified to Pure and unit reset log

Stack operation mode modified to Pure and unit reset

Operational Mode was automatically changed and unit was restarted.

Source	Severity
Stack Manager	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack operation mode modified to %s and unit reset

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack operation mode modified to %s and unit reset log

Stack operation mode modified to %s and unit reset

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack Port %d: event %s causes state transition to %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack Port %d: event %s causes state transition to %s log

Stack Port %d: event %s causes state transition to %s

### Source   Severity

HMOD

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Stack Port %d: ignored event %s for state %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack Port %d: ignored event %s for state %s log

Stack Port %d: ignored event %s for state %s

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack RO password changed from IP add

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack RO password changed from IP add log

Stack RO password changed from IP add

Stack RO (Read Only) password changed from telnet or SSH session.

Source	Severity
Telnet Server	Serious

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack RO password changed from IP add:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack RO password changed from IP add: log

Stack RO password changed from IP add:

### Source    Severity

Telnet

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack RO password changed from IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack RO password changed from IP address log

Stack RO password changed from IP address

**Source**   **Severity**

WEB

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack RO password changed from serial conn

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack RO password changed from serial conn log

Stack RO password changed from serial conn

Stack RO (Read Only) password changed from the serial connection session.

Source	Severity
Console	Serious

### Remedial action

No action required.



# Stack RO password changed from serial connection

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack RO password changed from serial connection log

Stack RO password changed from serial connection

### Source   Severity

Telnet

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack RW password changed from IP add

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack RW password changed from IP add log

Stack RW password changed from IP add

Stack RW (Read Write) password changed from telnet or SSH session.

Source	Severity
Telnet Server	Serious

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack RW password changed from IP add:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack RW password changed from IP add: log

Stack RW password changed from IP add:

Source	Severity
--------	----------

Telnet	
--------	--

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Stack RW password changed from IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack RW password changed from IP address log

Stack RW password changed from IP address

**Source**   **Severity**

WEB

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack RW password changed from serial conn

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack RW password changed from serial conn log

Stack RW password changed from serial conn

Stack RW (Read Write) password changed from the serial connection session.

Source	Severity
Console	Serious

### Remedial action

No action required.



# Stack RW password changed from serial connection

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack RW password changed from serial connection log

Stack RW password changed from serial connection

### Source   Severity

Telnet

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Stack sync failed Exp: 0x%08X Act:  
0x%08X Missing: 0x%08X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack sync failed Exp: 0x%08X Act: 0x%08X Missing: 0x%08X log

Stack sync failed Exp: 0x%08X Act: 0x%08X Missing: 0x%08X

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack sync failed stack failed to form

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack sync failed stack failed to form log

Stack sync failed stack failed to form

The stack did not form as the stack synchronization failed.

Source	Severity
Stack Manager	Serious

### Remedial action

Reboot the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack sync failed, stack failed to form

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack sync failed, stack failed to form log

Stack sync failed, stack failed to form

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack sync failed, unit not in stack

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack sync failed, unit not in stack log

Stack sync failed, unit not in stack

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stack synchronization failed Exp value Act value Missing value

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack synchronization failed Exp value Act value Missing value log

Stack synchronization failed Exp value Act value Missing value

Stack synchronization failed on the unit. Missing value yields the application(s) that caused failure.

Source	Severity
Stack Manager	Serious

### Remedial action

Reboot the unit if it is unsuccessful in joining the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Stack synchronization failed stack formation delayed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stack synchronization failed stack formation delayed log

Stack synchronization failed stack formation delayed

The Stack Manager did not receive an acknowledgement after sending the Join message to all the Non Base units for three times in a row.

Source	Severity
Stack Monitor	Information

### Remedial action

No action required. The switch/stack reboots itself. The logs are saved to NVRAM for future reference.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



startDiscoveryMsg from unit #%%d (%s)  
will be processed now

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## startDiscoveryMsg from unit #%%d (%s) will be processed now log

startDiscoveryMsg from unit #%%d (%s) will be processed now

**Source    Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Static role association not found for ifc, default was used (%d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Static role association not found for ifc, default was used (%d/%d) log

Static role association not found for ifc, default was used (%d/%d)

The previous static role might have been deleted while the interface was in dynamic mode. Default role was used instead.

Source	Severity
--------	----------

QoS	Information
-----	-------------

### Remedial action

No action required.



# Stk config is "%s", %d units

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stk config is "%s", %d units log

Stk config is "%s", %d units

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STKMON: Could not get available buffer

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STKMON: Could not get available buffer log

STKMON: Could not get available buffer

**Source**                      **Severity**

Stack Monitor

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STKMON: End

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STKMON: End log

STKMON: End

Source	Severity
--------	----------

Stack Monitor	
---------------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STKMON: Failed to open config file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STKMON: Failed to open config file log

STKMON: Failed to open config file

**Source**                      **Severity**

Stack Monitor

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STKMON: Failed to write to config file

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STKMON: Failed to write to config file log

STKMON: Failed to write to config file

**Source**                      **Severity**

Stack Monitor

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# STKMON: Failed to xmit packet in stack

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STKMON: Failed to xmit packet in stack log

STKMON: Failed to xmit packet in stack

**Source**                      **Severity**

Stack Monitor

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STKMON: msgQReceive failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STKMON: msgQReceive failed log

STKMON: msgQReceive failed

**Source**                      **Severity**

Stack Monitor

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STKMON: Received unknown message into STKMON msg queue

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STKMON: Received unknown message into STKMON msg queue log

STKMON: Received unknown message into STKMON msg queue

Source	Severity
Stack Monitor	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STKMON: Start

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STKMON: Start log

STKMON: Start

**Source**                      **Severity**

Stack Monitor

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



stk startup event failed Exp: 0x%08X  
Act: 0x%08X Missing: 0x%08X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## stk startup event failed Exp: 0x%08X Act: 0x%08X Missing: 0x%08X log

stk startup event failed Exp: 0x%08X Act: 0x%08X Missing: 0x%08X

**Source**   **Severity**  
SMGR

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Stk startup event failed type: 0x%08X option: %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Stk startup event failed type: 0x%08X option: %d log

Stk startup event failed type: 0x%08X option: %d

**Source    Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP add Mlt link: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP add Mlt link: %d - %d - %d log

STP add Mlt link: %d - %d - %d

**Source**   **Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP CDT interface error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP CDT interface error log

STP CDT interface error

**Source**   **Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# STP Config Chk: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP Config Chk: %d - %d - %d log

STP Config Chk: %d - %d - %d

**Source    Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP dbrcv error: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP dbrcv error: %d - %d - %d log

STP dbrcv error: %d - %d - %d

**Source**   **Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



STP db\_record done: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP db\_record done: %d - %d - %d log

STP db\_record done: %d - %d - %d

**Source**   **Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP db\_remove: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP db\_remove: %d - %d - %d log

STP db\_remove: %d - %d - %d

**Source   Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



STP db\_remove done: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP db\_remove done: %d - %d - %d log

STP db\_remove done: %d - %d - %d

**Source**   **Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP dbxc error: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP dbxc error: %d - %d - %d log

STP dbxc error: %d - %d - %d

**Source**   **Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP db\_xchg: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP db\_xchg: %d - %d - %d log

STP db\_xchg: %d - %d - %d

**Source   Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP db\_xchg done: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP db\_xchg done: %d - %d - %d log

STP db\_xchg done: %d - %d - %d

**Source**   **Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# STP db\_xchg mask empty: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP db\_xchg mask empty: %d - %d - %d log

STP db\_xchg mask empty: %d - %d - %d

**Source    Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP db\_xchg rcv last pkt: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP db\_xchg rcv last pkt: %d - %d - %d log

STP db\_xchg rcv last pkt: %d - %d - %d

**Source    Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP different op mode remote-local-Module: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP different op mode remote-local-Module: %d - %d - %d log

STP different op mode remote-local-Module: %d - %d - %d

**Source**   **Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP Fatal Error: taskSupend(0) called %s line %d: %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP Fatal Error: taskSupend(0) called %s line %d: %d log

STP Fatal Error: taskSupend(0) called %s line %d: %d

### Source    Severity

STP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP get buffer fail: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP get buffer fail: %d - %d - %d log

STP get buffer fail: %d - %d - %d

**Source**   **Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP group %d disabled, empty vlans or no vlans %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP group %d disabled, empty vlans or no vlans %d - %d log

STP group %d disabled, empty vlans or no vlans %d - %d

**Source**   **Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP IMC error: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP IMC error: %d - %d - %d log

STP IMC error: %d - %d - %d

**Source**   **Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



STP join: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP join: %d - %d - %d log

STP join: %d - %d - %d

**Source**   **Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# STP join done: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP join done: %d - %d - %d log

STP join done: %d - %d - %d

**Source   Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP join timeout : %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP join timeout : %d - %d - %d log

STP join timeout : %d - %d - %d

**Source   Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP leave: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP leave: %d - %d - %d log

STP leave: %d - %d - %d

**Source    Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP leave done: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP leave done: %d - %d - %d log

STP leave done: %d - %d - %d

**Source    Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP Mlt create: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP Mlt create: %d - %d - %d log

STP Mlt create: %d - %d - %d

**Source   Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP Mlt remove: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP Mlt remove: %d - %d - %d log

STP Mlt remove: %d - %d - %d

**Source   Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP mod inactive: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP mod inactive: %d - %d - %d log

STP mod inactive: %d - %d - %d

**Source    Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



STP mod ina done: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP mod ina done: %d - %d - %d log

STP mod ina done: %d - %d - %d

**Source**   **Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# STP msgQ error: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP msgQ error: %d - %d - %d log

STP msgQ error: %d - %d - %d

**Source**   **Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP NV port clr: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP NV port clr: %d - %d - %d log

STP NV port clr: %d - %d - %d

**Source**   **Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP nvRam file error: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP nvRam file error: %d - %d - %d log

STP nvRam file error: %d - %d - %d

**Source    Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP parameter error: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP parameter error: %d - %d - %d log

STP parameter error: %d - %d - %d

**Source**   **Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP PDT interface error: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP PDT interface error: %d - %d - %d log

STP PDT interface error: %d - %d - %d

**Source**   **Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP port disable: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP port disable: %d - %d - %d log

STP port disable: %d - %d - %d

**Source**   **Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP STKM mask error: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP STKM mask error: %d - %d - %d log

STP STKM mask error: %d - %d - %d

**Source    Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP stpMlt create: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP stpMlt create: %d - %d - %d log

STP stpMlt create: %d - %d - %d

**Source**   **Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# STP Task Error: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP Task Error: %d - %d - %d log

STP Task Error: %d - %d - %d

**Source**   **Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP Timer 1st: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP Timer 1st: %d - %d - %d log

STP Timer 1st: %d - %d - %d

**Source**   **Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP Tx BPDU Alloc Fail: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP Tx BPDU Alloc Fail: %d - %d - %d log

STP Tx BPDU Alloc Fail: %d - %d - %d

**Source**   **Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP Tx BPDU IMC Fail: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP Tx BPDU IMC Fail: %d - %d - %d log

STP Tx BPDU IMC Fail: %d - %d - %d

**Source**   **Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP update cnfg: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP update cnfg: %d - %d - %d log

STP update cnfg: %d - %d - %d

**Source**   **Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP vlan clr cnfg: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP vlan clr cnfg: %d - %d - %d log

STP vlan clr cnfg: %d - %d - %d

**Source**   **Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# STP VLAN error: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## STP VLAN error: %d - %d - %d log

STP VLAN error: %d - %d - %d

**Source**   **Severity**

STP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Successful connection from IP address:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Successful connection from IP address: log

Successful connection from IP address:

The client is successfully connected to the telnet server.

Source	Severity
Telnet Server	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Successfully loaded backup configuration files

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Successfully loaded backup configuration files log

Successfully loaded backup configuration files

Successfully loaded backup configuration files.

Source	Severity
Multi Config	Serious

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Successfully loaded configuration files from block %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Successfully loaded configuration files from block %d log

Successfully loaded configuration files from block %d

Successfully loaded configuration files.

Source	Severity
Multi Config	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Successfully remapped config areas on unit %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Successfully remapped config areas on unit %d log

Successfully remapped config areas on unit %d

Successfully remapped the configuration areas on that unit.

Source	Severity
MCFG	Information

### Remedial action

No action required.



# Successful SSH connection to ip address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Successful SSH connection to ip address log

Successful SSH connection to ip address

SSH connection completed successfully.

Source	Severity
SSH Client	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Superfluous request from unit # %d to restart discovery

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Superfluous request from unit # %d to restart discovery log

Superfluous request from unit # %d to restart discovery

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Sw Exception

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Sw Exception log

Sw Exception

A task caused an exception and is suspended. The exception information is logged and can be accessed through the CLI.

Source	Severity
Exception	Critical

### Remedial action

The Exception information contains the problem task, the exception type, the register values, the exception stack trace and memory of the related DRAM area. With this information, you can find out the cause of the exception. (The most common method is to follow the stack trace).

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Sw Exception:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Sw Exception: log

Sw Exception:

Source	Severity
SWEXCEPTION	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Switched UNI already configured with same I-SID

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Switched UNI already configured with same I-SID log

Switched UNI already configured with same I-SID

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Switch IP changed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Switch IP changed log

Switch IP changed

This message indicates that the Switch IP has changed.

Source	Severity
IPT	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Switch RO password changed from IP add:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Switch RO password changed from IP add: log

Switch RO password changed from IP add:

Switch RO (Read Only) password changed from telnet or SSH session.

Source	Severity
Telnet Server	Serious

### Remedial action

No action required.



# Switch RO password changed from IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Switch RO password changed from IP address log

Switch RO password changed from IP address

**Source**   **Severity**

WEB

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Switch RO password changed from serial connection

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Switch RO password changed from serial connection log

Switch RO password changed from serial connection

Switch RO (read-only) password changed from the serial connection session.

Source	Severity
Console	Serious

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Switch RO password changed from serial connection

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Switch RO password changed from serial connection log

Switch RO password changed from serial connection

### Source   Severity

Telnet

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Switch RW password changed from IP add

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Switch RW password changed from IP add log

Switch RW password changed from IP add

Switch RW (Read Write) password changed from the telnet or the SSH session.

Source	Severity
Telnet Server	Serious

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Switch RW password changed from IP add:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Switch RW password changed from IP add: log

Switch RW password changed from IP add:

Source	Severity
--------	----------

Telnet	
--------	--

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Switch RW password changed from IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Switch RW password changed from IP address log

Switch RW password changed from IP address

**Source**   **Severity**

WEB

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Switch RW password changed from serial conn

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Switch RW password changed from serial conn log

Switch RW password changed from serial conn

Switch RW (Read Write) password changed from the serial connection session.

Source	Severity
Console	Serious

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Switch RW password changed from serial connection

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Switch RW password changed from serial connection log

Switch RW password changed from serial connection

**Source**   **Severity**

Telnet

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Syslog Stress Test customer message .

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Syslog Stress Test customer message . log

Syslog Stress Test customer message .

**Source**      **Severity**

ENGMENU

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Syslog Stress Test engineering message

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Syslog Stress Test engineering message . log

Syslog Stress Test engineering message .

**Source**      **Severity**

ENGMENU

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# System classifier modifications not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## System classifier modifications not supported log

System classifier modifications not supported

The system detected an internal error; The specified modifier option not supported.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# System classifier still referenced (deletion prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## System classifier still referenced (deletion prohibited) log

System classifier still referenced (deletion prohibited)

Cannot delete a system classifier element if it's referenced in a classifier.

Source	Severity
QoS	Serious

### Remedial action

Remove the classifier first.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# System filter distribution across stack failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## System filter distribution across stack failed log

System filter distribution across stack failed

Unable to commit changes across the stack.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# System memory on unit %d is under %d MBytes.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## System memory on unit %d is under %d MBytes. log

System memory on unit %d is under %d MBytes.

The system memory on the specified unit is under the specified size.

### Source

System Logging

### Severity

Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# System: Rear-Port Mode has been set to disable (reboot required to take effect)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## System: Rear-Port Mode has been set to disable (reboot required to take effect) log

System: Rear-Port Mode has been set to disable (reboot required to take effect)

System: Rear-Port Mode has been set to disable, reboot required to take effect.

Source	Severity
Rear-Port	Information

### Remedial action

Reboot.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



System: Rear-Port Mode has been set to disable (reboot required to take effect).

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## System: Rear-Port Mode has been set to disable (reboot required to take effect). log

System: Rear-Port Mode has been set to disable (reboot required to take effect).

Source	Severity
MCFG	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



System: Rear-Port Mode has been set to enable (reboot required to take effect).

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## System: Rear-Port Mode has been set to enable (reboot required to take effect). log

System: Rear-Port Mode has been set to enable (reboot required to take effect).

Rear-Port Mode has been set to enable. Reboot required to take effect.

Source	Severity
Rear-Port	Information

### Remedial action

Reboot.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Table is full

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Table is full log

Table is full

Source	Severity
--------	----------

L3Mgr	
-------	--

Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TACACS+ accounting disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS+ accounting disabled log

TACACS+ accounting disabled

Command logging (accounting) is disabled.

Source	Severity
TACACS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TACACS+ accounting enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS+ accounting enabled log

TACACS+ accounting enabled

Command logging (accounting) is enabled.

Source	Severity
TACACS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TACACS+ authenticated serial connection closed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS+ authenticated serial connection closed log

TACACS+ authenticated serial connection closed

TACACS authenticated serial console session was closed.

Source	Severity
TACACS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TACACS+ authenticated ssh session closed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS+ authenticated ssh session closed log

TACACS+ authenticated ssh session closed

**Source**   **Severity**

TACACS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# TACACS+ authenticated telnet session closed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS+ authenticated telnet session closed log

TACACS+ authenticated telnet session closed

Telnet session authenticated through TACACS closed.

Source	Severity
TACACS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TACACS+ authenticated telnet session max retries exceeded

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS+ authenticated telnet session max retries exceeded log

TACACS+ authenticated telnet session max retries exceeded

The maximum number of retries for a TACACS authenticated telnet session exceeded.

Source	Severity
TACACS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TACACS+ authentication on serial port disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS+ authentication on serial port disabled log

TACACS+ authentication on serial port disabled

**Source**   **Severity**

TACACS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TACACS+ authentication on serial port enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS+ authentication on serial port enabled log

TACACS+ authentication on serial port enabled

**Source**   **Severity**

TACACS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TACACS+ authentication on stack serial disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS+ authentication on stack serial disabled log

TACACS+ authentication on stack serial disabled

**Source**   **Severity**

TACACS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TACACS+ authentication on stack serial enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS+ authentication on stack serial enabled log

TACACS+ authentication on stack serial enabled

**Source**   **Severity**

TACACS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TACACS+ authentication on stack TELNET/WEB/SSH disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS+ authentication on stack TELNET/WEB/SSH disabled log

TACACS+ authentication on stack TELNET/WEB/SSH disabled

**Source**   **Severity**

TACACS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TACACS+ authentication on stack TELNET/WEB/SSH enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS+ authentication on stack TELNET/WEB/SSH enabled log

TACACS+ authentication on stack TELNET/WEB/SSH enabled

**Source**   **Severity**

TACACS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# TACACS+ authentication on switch serial disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS+ authentication on switch serial disabled log

TACACS+ authentication on switch serial disabled

**Source**   **Severity**

TACACS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TACACS+ authentication on switch serial enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS+ authentication on switch serial enabled log

TACACS+ authentication on switch serial enabled

**Source**   **Severity**

TACACS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TACACS+ authentication on switch serial port disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS+ authentication on switch serial port disabled log

TACACS+ authentication on switch serial port disabled

TACACS authentication disabled on the switch serial console.

Source	Severity
TACACS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TACACS+ authentication on switch serial port enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS+ authentication on switch serial port enabled log

TACACS+ authentication on switch serial port enabled

TACACS authentication enabled on switch serial console.

Source	Severity
TACACS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TACACS+ authentication on switch telnet disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS+ authentication on switch telnet disabled log

TACACS+ authentication on switch telnet disabled

TACACS authentication disabled on switch telnet.

Source	Severity
TACACS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TACACS+ authentication on switch telnet enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS+ authentication on switch telnet enabled log

TACACS+ authentication on switch telnet enabled

TACACS+ authentication is disabled on switch telnet.

Source	Severity
TACACS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TACACS+ authentication on switch telnet enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS+ authentication on switch telnet enabled log

TACACS+ authentication on switch telnet enabled

TACACS authentication enabled on switch telnet.

Source	Severity
TACACS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TACACS+ authentication on switch TELNET/WEB/SSH disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS+ authentication on switch TELNET/WEB/SSH disabled log

TACACS+ authentication on switch TELNET/WEB/SSH disabled

**Source**   **Severity**

TACACS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# TACACS+ authentication on switch TELNET/WEB/SSH enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS+ authentication on switch TELNET/WEB/SSH enabled log

TACACS+ authentication on switch TELNET/WEB/SSH enabled

**Source**   **Severity**

TACACS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TACACS+ authentication on TELNET/WEB/SSH disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS+ authentication on TELNET/WEB/SSH disabled log

TACACS+ authentication on TELNET/WEB/SSH disabled

**Source**   **Severity**

TACACS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TACACS+ authentication on TELNET/WEB/SSH enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS+ authentication on TELNET/WEB/SSH enabled log

TACACS+ authentication on TELNET/WEB/SSH enabled

**Source**   **Severity**

TACACS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TACACS+ authorization disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS+ authorization disabled log

TACACS+ authorization disabled

Command authorization is disabled.

Source	Severity
TACACS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TACACS+ authorization enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS+ authorization enabled log

TACACS+ authorization enabled

Command authorization is enabled.

Source	Severity
TACACS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TACACS+ successful authentication

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS+ successful authentication log

TACACS+ successful authentication

User authentication succeeded.

Source	Severity
TACACS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TACACS+ unsuccessful authentication

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS+ unsuccessful authentication log

TACACS+ unsuccessful authentication

User authentication failed.

Source	Severity
TACACS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TACACS authenticated SSH session closed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS authenticated SSH session closed log

TACACS authenticated SSH session closed

TACACS authenticated SSH session has closed.

Source	Severity
TACACS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# TACACS authentication on stack serial disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS authentication on stack serial disabled log

TACACS authentication on stack serial disabled

TACACS authentication disabled on stack serial console.

Source	Severity
TACACS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TACACS authentication on stack serial enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS authentication on stack serial enabled log

TACACS authentication on stack serial enabled

TACACS authentication enabled on stack serial console.

Source	Severity
TACACS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TACACS authentication on stack telnet disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS authentication on stack telnet disabled log

TACACS authentication on stack telnet disabled

TACACS authentication disabled on stack telnet.

Source	Severity
TACACS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TACACS authentication on stack telnet enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TACACS authentication on stack telnet enabled log

TACACS authentication on stack telnet enabled

TACACS authentication enabled on stack telnet.

Source	Severity
TACACS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Task priority changed for %s to %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Task priority changed for %s to %d log

Task priority changed for %s to %d

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Task %s is suspended

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Task %s is suspended log

Task %s is suspended

**Source**                      **Severity**

Stack Monitor

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Task task\_name is suspended

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Task task\_name is suspended log

Task task\_name is suspended

Stack Monitor detected that a task has been suspended for more than 5 minutes.

Source	Severity
Stack Monitor	Information

### Remedial action

No action required. The switch/stack reboots itself. The logs are saved to NVRAM for future reference.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Task task-name is suspended

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Task task-name is suspended log

Task task-name is suspended

One of the tasks running on the device encountered a critical error and was suspended.

Source	Severity
Stack Monitor	Critical

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Task whose index is %d,%d is suspended

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Task whose index is %d,%d is suspended log

Task whose index is %d,%d is suspended

Stack Monitor detected that one of the tasks running on the device encountered a critical error and has been suspended for more than 5 minutes.

Source	Severity
Stack Monitor	Critical

### Remedial action

No action required. The switch/stack reboots itself. The logs are saved to NVRAM for future reference.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# TCP Control Flag filter criteria requires TCP protocol

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TCP Control Flag filter criteria requires TCP protocol log

TCP Control Flag filter criteria requires TCP protocol

TCP Control Flag filter criteria must be used with TCP protocol filter criteria.

Source	Severity
QoS	Serious

### Remedial action

Add the TCP protocol option.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Telnet-access is disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Telnet-access is disabled log

Telnet-access is disabled

**Source**   **Severity**

Telnet

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Telnet-access is enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Telnet-access is enabled log

Telnet-access is enabled

**Source**   **Severity**

Telnet

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Temporary access assignment sync issue detected (ifc %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Temporary access assignment sync issue detected (ifc %d) log

Temporary access assignment sync issue detected (ifc %d)

**Source   Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Temporary base unit detected, becoming a non-base unit- %s line %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Temporary base unit detected, becoming a non-base unit- %s line %d log

Temporary base unit detected, becoming a non-base unit- %s line %d

Source	Severity
SMGR	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Temporary interface assignment sync issue detected (ifc %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Temporary interface assignment sync issue detected (ifc %d) log

Temporary interface assignment sync issue detected (ifc %d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Temporary QoS inter-module communication issue encountered

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Temporary QoS inter-module communication issue encountered log

Temporary QoS inter-module communication issue encountered

**Source**   **Severity**  
QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# TFTP Failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## TFTP Failed log

TFTP Failed

The system failed to get an image through the TFTP.

Source	Severity
Console	Serious

### Remedial action

Check the TFTP server.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



The account for user <%s> expires in  
%d days due to inactivity

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## The account for user <%s> expires in %d days due to inactivity log

The account for user <%s> expires in %d days due to inactivity

**Source   Severity**

AAA

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



The base (unit #%) has left the stack.  
Unit #% is now the base

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## The base (unit #%) has left the stack. Unit #% is now the base log

The base (unit #%) has left the stack. Unit #% is now the base

### Source   Severity

SMGR

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



The base (unit# number ) has left the stack. Unit# number is now the base

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## The base (unit# number ) has left the stack. Unit# number is now the base log

The base (unit# number ) has left the stack. Unit# number is now the base

The Base unit has left the stack, a new unit has replaced it.

Source	Severity
Stack Manager	Serious

### Remedial action

Examine the base unit that left the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# The BU switch is enabled. Cannot join existing stack

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## The BU switch is enabled. Cannot join existing stack log

The BU switch is enabled. Cannot join existing stack

The switch has BU switch set and is added to an existing stack.

Source	Severity
Stack Manager	Information

### Remedial action

Unset BU switch before adding it to a new stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# The IP phone PoE limit has been changed to x Watts due to the stack modules configuration

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## The IP phone PoE limit has been changed to x Watts due to the stack modules configuration log

The IP phone PoE limit has been changed to x Watts due to the stack modules configuration

As a global parameter, the IP phone PoE limit has dynamically changed to x Watts value in stack configuration, as being the maximum common value supported on all units from stack.

Source	Severity
PoE	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# The number of stack units is %d instead of expected %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## The number of stack units is %d instead of expected %d log

The number of stack units is %d instead of expected %d

**Source**                      **Severity**

Stack Monitor

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# The number of stack units is number instead of expected number

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## The number of stack units is number instead of expected number log

The number of stack units is number instead of expected number

The number of units in the stack differs from the one configured in Stack Monitor.

Source	Severity
Stack Monitor	Information

### Remedial action

Check if any units are down or unresponsive. Also check if the Stack Monitor is misconfigured ( that is the configured number of units is different from the real number of units in stack)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





The password for user <%s> expires in %d days due to password aging

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## The password for user <%s> expires in %d days due to password aging log

The password for user <%s> expires in %d days due to password aging

Source	Severity
AAA	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



The password for user <%s> has expired.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## The password for user <%s> has expired. log

The password for user <%s> has expired.

**Source   Severity**

AAA

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



The password for user <%s> was changed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## The password for user <%s> was changed log

The password for user <%s> was changed

**Source   Severity**

AAA

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



The password for user <%s> was not changed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## The password for user <%s> was not changed log

The password for user <%s> was not changed

**Source   Severity**

AAA

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



The role for user <%s> changed to %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## The role for user <%s> changed to %s log

The role for user <%s> changed to %s

**Source   Severity**

AAA

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



The static FDB entry MAC %02x-%02x-%02x-%02x-%02x-%02x VLAN %d trunk %d was deleted because LAG has disaggregated

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## The static FDB entry MAC %02x-%02x-%02x-%02x-%02x-%02x VLAN %d trunk %d was deleted because LAG has disaggregated log

The static FDB entry MAC %02x-%02x-%02x-%02x-%02x-%02x VLAN %d trunk %d was deleted because LAG has disaggregated

**Source**   **Severity**

CDT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



The static FDB entry MAC %02x-%02x-%02x-%02x-%02x-%02x VLAN %d was deleted because Port: %d has aggregated

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## The static FDB entry MAC %02x-%02x-%02x-%02x-%02x-%02x VLAN %d was deleted because Port: %d has aggregated log

The static FDB entry MAC %02x-%02x-%02x-%02x-%02x-%02x VLAN %d was deleted because Port: %d has aggregated

**Source**   **Severity**

CDT

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



The static FDB entry MAC %02x-%02x-%02x-%02x-%02x-%02x VLAN %d was deleted because Unit/Port: %d/%d has aggregated

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## The static FDB entry MAC %02x-%02x-%02x-%02x-%02x-%02x VLAN %d was deleted because Unit/Port: %d/%d has aggregated log

The static FDB entry MAC %02x-%02x-%02x-%02x-%02x-%02x VLAN %d was deleted because Unit/Port: %d/%d has aggregated

Source	Severity
CDT	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# The user <%s> was disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## The user <%s> was disabled log

The user <%s> was disabled

**Source    Severity**

AAA

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



The user <%s> was enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## The user <%s> was enabled log

The user <%s> was enabled

**Source    Severity**

AAA

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



The user <%s> was locked

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## The user <%s> was locked log

The user <%s> was locked

**Source    Severity**

AAA

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# The user <%s> was locked.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## The user <%s> was locked. log

The user <%s> was locked.

The message logs when an account is locked after the number of wrong logins exceeded the number of allowed retries.

Source	Severity
CONSOLE	Serious

### Remedial action

Wait until user account lockout time expires or unlock it with "username <user> unlock" command.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# The user <%s> was unlocked

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## The user <%s> was unlocked log

The user <%s> was unlocked

**Source   Severity**

AAA

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



The user <%s> with %s role has been created

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## The user <%s> with %s role has been created log

The user <%s> with %s role has been created

**Source    Severity**

AAA

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



The user <%s> with %s role has been deleted

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## The user <%s> with %s role has been deleted log

The user <%s> with %s role has been deleted

**Source   Severity**

AAA

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



This attribute is currently not configurable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## This attribute is currently not configurable log

This attribute is currently not configurable

**Source   Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





This log msg contains 3 encoded variables %x, %x, %x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## This log msg contains 3 encoded variables %x, %x, %x log

This log msg contains 3 encoded variables %x, %x, %x

**Source   Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# This unit has already been discovered

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## This unit has already been discovered log

This unit has already been discovered

**Source   Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# This unit has an incompatible stack operational mode setting

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## This unit has an incompatible stack operational mode setting log

This unit has an incompatible stack operational mode setting

### Source    Severity

SMGR

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



This unit has wrong F/W version,  
expected %s, actual %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## This unit has wrong F/W version, expected %s, actual %s log

This unit has wrong F/W version, expected %s, actual %s

**Source    Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# This unit has wrong F W version expected version actual version

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## This unit has wrong F W version expected version actual version log

This unit has wrong F W version expected version actual version

The unit did not join the stack because the F/W is different than base unit's F/W .

Source	Severity
Stack Manager	Information

### Remedial action

Download the correct F/W or configure the unit to automatically download it from the base unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



This unit has wrong S/W version,  
expected %s, actual %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## This unit has wrong S/W version, expected %s, actual %s log

This unit has wrong S/W version, expected %s, actual %s

**Source   Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# This unit has wrong S W version expected version actual version

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## This unit has wrong S W version expected version actual version log

This unit has wrong S W version expected version actual version

The unit did not join the stack because the S/W is different than the base unit's S/W .

Source	Severity
Stack Manager	Information

### Remedial action

You should download the correct S/W or configure the unit to automatically download it from base unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# This unit is operating as the Base unit

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## This unit is operating as the Base unit log

This unit is operating as the Base unit

**Source   Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Toggle the Agent Primary Image

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Toggle the Agent Primary Image log

Toggle the Agent Primary Image

The NVRAM block can be toggled between 1 and 2.

Source	Severity
config	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Token bucket algorithm identifier invalid

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Token bucket algorithm identifier invalid log

Token bucket algorithm identifier invalid

Invalid token bucket algorithm identifier.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Specify a valid token bucket identifier.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Token bucket algorithm identifier unknown unsupported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Token bucket algorithm identifier unknown unsupported log

Token bucket algorithm identifier unknown unsupported

Scheduling algorithm not found.

Source	Severity
QoS	Serious

### Remedial action

Specify an existing and valid algorithm identifier.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Token bucket algorithm identifier unknown/unsupported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Token bucket algorithm identifier unknown/unsupported log

Token bucket algorithm identifier unknown/unsupported

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Token bucket data distribution across stack failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Token bucket data distribution across stack failed log

Token bucket data distribution across stack failed

Unable to commit changes across the stack.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Token bucket entry referenced by meter (deletion prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Token bucket entry referenced by meter (deletion prohibited) log

Token bucket entry referenced by meter (deletion prohibited)

Cannot delete a token bucket entry if it's referenced in a meter.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Remove the meter first.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Token bucket entry referenced by shaper (deletion prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Token bucket entry referenced by shaper (deletion prohibited) log

Token bucket entry referenced by shaper (deletion prohibited)

Cannot delete a token bucket if it's referenced in a shaper.

Source	Severity
QoS	Serious

### Remedial action

Remove shaper first.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Token bucket minimum rate outside limits (64 - 10230000 Kbps)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Token bucket minimum rate outside limits (64 - 10230000 Kbps) log

Token bucket minimum rate outside limits (64 - 10230000 Kbps)

The minimum bucket rate must be in the range specified.

Source	Severity
QoS	Serious

### Remedial action

Enter a bucket rate bigger than 64Kbps and smaller than 10230000 Kbps.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Token bucket modifications not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Token bucket modifications not supported log

Token bucket modifications not supported

The system detected an internal error; The specified modifier option not supported.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Token bucket rate outside limits (64 - 10230000 Kbps)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Token bucket rate outside limits (64 - 10230000 Kbps) log

Token bucket rate outside limits (64 - 10230000 Kbps)

The token bucket rate must be between 0 and 32Gbps.

Source	Severity
QoS	Serious

### Remedial action

Enter a rate value within that range.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Token bucket size not compatible with committed fill rate

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Token bucket size not compatible with committed fill rate log

Token bucket size not compatible with committed fill rate

For cos/queue shaping only MinRate and Rate are set so BurstSize must be  $\geq$  Rate only when MinRate = 0.

Source	Severity
QoS	Serious

### Remedial action

Enter a valid token bucket size.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Too many manual area addresses

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Too many manual area addresses log

Too many manual area addresses

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Traffic Prof filter set delete operation failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Traffic Prof filter set delete operation failed log

Traffic Prof filter set delete operation failed

Unable to carry out the delete operation on the traffic profile filter set across the stack.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Traffic Prof filter set elem count exceeds available resources

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Traffic Prof filter set elem count exceeds available resources log

Traffic Prof filter set elem count exceeds available resources

Although the element count is within the documented limit, the actual resources necessary may not be available due to the runtime configuration.

Source	Severity
QoS	Serious

### Remedial action

Check for and remove the resources that are not needed.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Traffic Prof filter set install operation failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Traffic Prof filter set install operation failed log

Traffic Prof filter set install operation failed

Unable to carry out the installation on the traffic profile filter set across the stack.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Traffic Prof filter set policy count (%d) exceeds limit (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Traffic Prof filter set policy count (%d) exceeds limit (%d) log

Traffic Prof filter set policy count (%d) exceeds limit (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Traffic Prof filter set policy count ( policy count ) exceeds limit ( policy limit )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Traffic Prof filter set policy count ( policy count ) exceeds limit ( policy limit ) log

Traffic Prof filter set policy count ( policy count ) exceeds limit ( policy limit )

The traffic profile filter set policy limit depends on the target hardware platform.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Check the documentation for the maximum number of traffic profile filter set policies allowed.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Traffic Prof filter set rule count (%d) exceeds limit (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Traffic Prof filter set rule count (%d) exceeds limit (%d) log

Traffic Prof filter set rule count (%d) exceeds limit (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Traffic Prof filter set rule count ( rule count ) exceeds limit ( rule limit )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Traffic Prof filter set rule count ( rule count ) exceeds limit ( rule limit ) log

Traffic Prof filter set rule count ( rule count ) exceeds limit ( rule limit )

The maximum number of rules for a traffic profile filter set is 75.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Separate the excess into multiple traffic profile filter sets.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# Traffic Prof filter set update operation failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Traffic Prof filter set update operation failed log

Traffic Prof filter set update operation failed

Unable to carry out the update operation on the traffic profile filter set across the stack.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Traffic Prof installation conflict seen (ID %d Ifc %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Traffic Prof installation conflict seen (ID %d Ifc %d) log

Traffic Prof installation conflict seen (ID %d Ifc %d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Transparent UNI already configured with same I-SID

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Transparent UNI already configured with same I-SID log

Transparent UNI already configured with same I-SID

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: avFabricAttachDiscoveredElement - ifIndex %d element %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: avFabricAttachDiscoveredElement - ifIndex %d element %d log

Trap: avFabricAttachDiscoveredElement - ifIndex %d element %d

**Source**   **Severity**  
SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: avFabricAttachExpiredElement - ifIndex %d element %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: avFabricAttachExpiredElement - ifIndex %d element %d log

Trap: avFabricAttachExpiredElement - ifIndex %d element %d

### Source    Severity

SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Trap bsAdacPortConfigNotification

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap bsAdacPortConfigNotification log

Trap bsAdacPortConfigNotification

ADAC Port Configuration.

Source	Severity
ADAC	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsAdacPortConfigNotification

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsAdacPortConfigNotification log

Trap: bsAdacPortConfigNotification

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap bsAdacPortOperDisabledNotification

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap bsAdacPortOperDisabledNotification log

Trap bsAdacPortOperDisabledNotification

ADAC Port operation disabled.

Source	Severity
ADAC	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsAdacPortOperDisabledNotification

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsAdacPortOperDisabledNotification log

Trap: bsAdacPortOperDisabledNotification

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsDhcpSnoopingExtSaveSFTPRestoreFailure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsDhcpSnoopingExtSaveSFTPRestoreFailure log

Trap: bsDhcpSnoopingExtSaveSFTPRestoreFailure

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsDhcpSnoopingExtSaveSFTPRestoreFailure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsDhcpSnoopingExtSaveSFTPRestoreFailure log

Trap: bsDhcpSnoopingExtSaveSFTPRestoreFailure

This notification is generated after unsuccessfully restoring the DHCP snooping binding table from a SFTP server external file.

Source	Severity
DHCP Snoop	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsDhcpSnoopingExtSaveSFTPRestoreSuccess

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsDhcpSnoopingExtSaveSFTPRestoreSuccess log

Trap: bsDhcpSnoopingExtSaveSFTPRestoreSuccess

**Source   Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsDhcpSnoopingExtSaveSFTPRestoreSuccess

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsDhcpSnoopingExtSaveSFTPRestoreSuccess log

Trap: bsDhcpSnoopingExtSaveSFTPRestoreSuccess

This notification is generated after successfully restoring the DHCP snooping binding table from a SFTP server external file.

Source	Severity
DHCP Snoop	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Trap: bsDhcpSnoopingExtSaveSFTPSyncFailure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsDhcpSnoopingExtSaveSFTPSyncFailure log

Trap: bsDhcpSnoopingExtSaveSFTPSyncFailure

### Source    Severity

SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsDhcpSnoopingExtSaveSFTPSyncFailure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsDhcpSnoopingExtSaveSFTPSyncFailure log

Trap: bsDhcpSnoopingExtSaveSFTPSyncFailure

This notification is generated after unsuccessfully saving the DHCP Snooping binding table to a SFTP server external file.

Source	Severity
DHCP Snoop	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsDhcpSnoopingExtSaveSFTPSyncSuccess

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsDhcpSnoopingExtSaveSFTPSyncSuccess log

Trap: bsDhcpSnoopingExtSaveSFTPSyncSuccess

**Source   Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsDhcpSnoopingExtSaveSFTPSyncSuccess

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsDhcpSnoopingExtSaveSFTPSyncSuccess log

Trap: bsDhcpSnoopingExtSaveSFTPSyncSuccess

Maximum number of MAC addresses that can be learned on a trunk is reached.

Source	Severity
Bay Secure	Warning/Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsDhcpSnoopingExtSaveSFTPSyncSuccess

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsDhcpSnoopingExtSaveSFTPSyncSuccess log

Trap: bsDhcpSnoopingExtSaveSFTPSyncSuccess

This notification is generated after successfully saving the DHCP snooping binding table to a SFTP server external file.

Source	Severity
SNMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsifnInstallationFailure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsifnInstallationFailure log

Trap: bsifnInstallationFailure

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Trap: bsIpv6DHCPGNotif%s  
MAC: %02x: %02x: %02x: %02x: %02x: %02x  
Addr: %s Port: %hhu/%hhu

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsIpv6DHCPGNotif%s MAC:%02x:%02x:%02x:%02x:%02x:%02x Addr:%s Port:%hhu/%hhu log

Trap: bsIpv6DHCPGNotif%s MAC:%02x:%02x:%02x:%02x:%02x:%02x Addr:%s Port:%hhu/%hhu

DHCPv6 Guard Notification trap sent.

Source	Severity
IPv6 First Hop Security	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



Trap: bsIpv6NDNotificationSBTTableFull -  
MAC: %02x: %02x: %02x: %02x: %02x: %02x  
Addr: %s Port: %hhu/%hhu

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsIpv6NDNotificationSBTTableFull - MAC:%02x:%02x:%02x:%02x:%02x:%02x Addr:%s Port:%hhu/%hhu log

Trap: bsIpv6NDNotificationSBTTableFull - MAC:%02x:%02x:%02x:%02x:%02x:%02x Addr:%s Port:%hhu/%hhu

ND SBT Table Full Notification trap sent.

Source	Severity
IPv6 First Hop Security	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





Trap: bsIpv6NDNotificationsUntrustedPort -  
MAC: %02x: %02x: %02x: %02x: %02x: %02x  
Addr: %s Port: %hhu/%hhu

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsIpv6NDNotificationsUntrustedPort - MAC:%02x:%02x:%02x:%02x:%02x:%02x Addr:%s Port:%hhu/%hhu log

Trap: bsIpv6NDNotificationsUntrustedPort - MAC:%02x:%02x:%02x:%02x:%02x:%02x Addr:%s Port:%hhu/%hhu

Source	Severity
SNMP	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Trap: bsIpv6NDNotificationUntrustedPort -  
MAC: %02x: %02x: %02x: %02x: %02x: %02x  
Addr: %s Port: %hhu/%hhu

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsIpv6NDNotificationUntrustedPort - MAC:%02x:%02x:%02x:%02x:%02x:%02x Addr:%s Port:%hhu/%hhu log

Trap: bsIpv6NDNotificationUntrustedPort - MAC:%02x:%02x:%02x:%02x:%02x:%02x Addr:%s Port:%hhu/%hhu

ND Untrusted Port Notification trap sent.

Source	Severity
IPv6 First Hop Security	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



Trap: bsIpv6NDSBTTTableFull -  
MAC: %02x: %02x: %02x: %02x: %02x: %02x  
Addr: %s Port: %hhu/%hhu

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsIpv6NDSBTTTableFull - MAC:%02x:%02x:%02x:%02x:%02x:%02x Addr:%s Port:%hhu/%hhu log

Trap: bsIpv6NDSBTTTableFull - MAC:%02x:%02x:%02x:%02x:%02x:%02x Addr:%s Port:%hhu/%hhu

Source	Severity
SNMP	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Trap: bsIpv6RAGNotif%s  
MAC: %02x: %02x: %02x: %02x: %02x: %02x  
Addr: %s Port: %hhu/%hhu

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsIpv6RAGNotif%s MAC:%02x:%02x:%02x:%02x:%02x:%02x Addr:%s Port:%hhu/%hhu log

Trap: bsIpv6RAGNotif%s MAC:%02x:%02x:%02x:%02x:%02x:%02x Addr:%s Port:%hhu/%hhu

RA Guard Notification trap sent.

Source	Severity
IPv6 First Hop Security	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsLstGroupOperStateChanged

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsLstGroupOperStateChanged log

Trap: bsLstGroupOperStateChanged

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsLstGroupOperStateChanged

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsLstGroupOperStateChanged log

Trap: bsLstGroupOperStateChanged

This notification is generated when the operational status of a link-state tracking group changes due to an interface status change.

Source	Severity
LST	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsLstInterfaceStatusChanged

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsLstInterfaceStatusChanged log

Trap: bsLstInterfaceStatusChanged

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsLstInterfaceStatusChanged

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsLstInterfaceStatusChanged log

Trap: bsLstInterfaceStatusChanged

This notification is generated when a physical or logical interface changes its status in a particular link-state tracking group.

Source	Severity
LST	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Trap: bsnAaaAlreadyConnected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnAaaAlreadyConnected log

Trap: bsnAaaAlreadyConnected

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnAaaAlreadyConnected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnAaaAlreadyConnected log

Trap: bsnAaaAlreadyConnected

The message logs when a user connects more than one time.

Source	Severity
CONSOLE	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnAaaIncorrectLogOnThresholdExceeded

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnAaaIncorrectLogOnThresholdExceeded log

Trap: bsnAaaIncorrectLogOnThresholdExceeded

### Source    Severity

SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnAaaIncorrectLogOnThresholdExceeded

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnAaaIncorrectLogOnThresholdExceeded log

Trap: bsnAaaIncorrectLogOnThresholdExceeded

The message logs when an account is locked after the number of wrong logins exceeded the number of allowed retries.

Source	Severity
CONSOLE	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnAaaMaxNoOfSessionsExceeded

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnAaaMaxNoOfSessionsExceeded log

Trap: bsnAaaMaxNoOfSessionsExceeded

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnAaaMaxNoOfSessionsExceeded

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnAaaMaxNoOfSessionsExceeded log

Trap: bsnAaaMaxNoOfSessionsExceeded

The message logs when the maxim number of current sessions for a user account is exceeded. Informational.

Source	Severity
CONSOLE	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnAaaUserAccountInactivityTrap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnAaaUserAccountInactivityTrap log

Trap: bsnAaaUserAccountInactivityTrap

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnAaaUserAccountNotUsed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnAaaUserAccountNotUsed log

Trap: bsnAaaUserAccountNotUsed

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Trap: bsnAaaUserAccountNotUsed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnAaaUserAccountNotUsed log

Trap: bsnAaaUserAccountNotUsed

The message logs when a user account, represented by an username, has never been used during a time interval.

Source	Severity
CONSOLE	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnAaaUserPasswordAgingTrap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnAaaUserPasswordAgingTrap log

Trap: bsnAaaUserPasswordAgingTrap

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnAaaUserPasswordExpired

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnAaaUserPasswordExpired log

Trap: bsnAaaUserPasswordExpired

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnAuditRecordEventsFailure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnAuditRecordEventsFailure log

Trap: bsnAuditRecordEventsFailure

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnAuditShutDownTrap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnAuditShutDownTrap log

Trap: bsnAuditShutDownTrap

Audit logging has shut down. Available only in Enhanced Secure Mode.

Source	Severity
CLI Audit	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnAuditStartUpTrap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnAuditStartUpTrap log

Trap: bsnAuditStartUpTrap

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnAuditStorageAlarm

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnAuditStorageAlarm log

Trap: bsnAuditStorageAlarm

The audit storage log exceeded 75% of its capacity.

Source	Severity
CLI Audit	Information

### Remedial action

Save current log and activate the remote SYSLOG server in order to maintain a copy of the future audit recordings

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnAuditUnsentMessages

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnAuditUnsentMessages log

Trap: bsnAuditUnsentMessages

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Trap bsnConfigurationSavedToNvram

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap bsnConfigurationSavedToNvram log

Trap bsnConfigurationSavedToNvram

The configuration is saved to NVRAM.

Source	Severity
CONFIG DATA	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnConfigurationSavedToNvram

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnConfigurationSavedToNvram log

Trap: bsnConfigurationSavedToNvram

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap bsnEapAccessViolation

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap bsnEapAccessViolation log

Trap bsnEapAccessViolation

EAP access violation.

Source	Severity
EAP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnEapAccessViolation

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnEapAccessViolation log

Trap: bsnEapAccessViolation

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnEapAccessViolationExt

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnEapAccessViolationExt log

Trap: bsnEapAccessViolationExt

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnEapRAVError

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnEapRAVError log

Trap: bsnEapRAVError

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnEapRAVErrorExt

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnEapRAVErrorExt log

Trap: bsnEapRAVErrorExt

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap bsnEapUbpFailure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap bsnEapUbpFailure log

Trap bsnEapUbpFailure

EAP UBP failure.

Source	Severity
EAP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Trap: bsnEapUbpFailure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnEapUbpFailure log

Trap: bsnEapUbpFailure

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnesActivated

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnesActivated log

Trap: bsnesActivated

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnesDeactivated

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnesDeactivated log

Trap: bsnesDeactivated

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnesGloballyDisabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnesGloballyDisabled log

Trap: bsnesGloballyDisabled

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnesGloballyEnabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnesGloballyEnabled log

Trap: bsnesGloballyEnabled

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnesManuallyActivated

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnesManuallyActivated log

Trap: bsnesManuallyActivated

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnesManuallyDeactivated

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnesManuallyDeactivated log

Trap: bsnesManuallyDeactivated

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnesScheduleApplied

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnesScheduleApplied log

Trap: bsnesScheduleApplied

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Trap: bsnesScheduleNotApplied

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnesScheduleNotApplied log

Trap: bsnesScheduleNotApplied

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap bsnLacPortDisabledDueToLossOfVLACPDU

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap bsnLacPortDisabledDueToLossOfVLACPDU log

Trap bsnLacPortDisabledDueToLossOfVLACPDU

Lac Port Disabled Due To Loss Of VLACPDU

Source	Severity
LAC	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnLacPortDisabledDueToLossOfVLACPDU

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnLacPortDisabledDueToLossOfVLACPDU log

Trap: bsnLacPortDisabledDueToLossOfVLACPDU

### Source    Severity

SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap bsnLacPortEnabledDueToReceiptOfVLACPDU

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap bsnLacPortEnabledDueToReceiptOfVLACPDU log

Trap bsnLacPortEnabledDueToReceiptOfVLACPDU

LAC Port Enabled as the VLACPDU was received.

Source	Severity
LAC	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnLacPortEnabledDueToReceiptOfVLACPDU

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnLacPortEnabledDueToReceiptOfVLACPDU log

Trap: bsnLacPortEnabledDueToReceiptOfVLACPDU

### Source    Severity

SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnLacTrunkUnavailable

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnLacTrunkUnavailable log

Trap: bsnLacTrunkUnavailable

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnLoginFailure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnLoginFailure log

Trap: bsnLoginFailure

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnPortSpeedDuplexMismatch

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnPortSpeedDuplexMismatch log

Trap: bsnPortSpeedDuplexMismatch

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Trap: bsnROPasswordExpired: Read-only password expired

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnROPasswordExpired: Read-only password expired log

Trap: bsnROPasswordExpired: Read-only password expired

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnROPasswordExpired: Read-only password expired

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnROPasswordExpired: Read-only password expired log

Trap: bsnROPasswordExpired: Read-only password expired

Notify user that local read-only password has expired.

Source	Severity
Password Security	Information

### Remedial action

No action Required

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnRWPASSWORDExpired: Read-write password expired

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnRWPASSWORDExpired: Read-write password expired log

Trap: bsnRWPASSWORDExpired: Read-write password expired

### Source    Severity

SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnRWPASSWORDExpired: Read-write password expired

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnRWPASSWORDExpired: Read-write password expired log

Trap: bsnRWPASSWORDExpired: Read-write password expired

Notify user that local read-write password has expired.

Source	Severity
Password Security	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnSFPInsertion on port

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnSFPInsertion on port log

Trap: bsnSFPInsertion on port

**Source   Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnSFPInsertion on port

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnSFPInsertion on port log

Trap: bsnSFPInsertion on port

SFP was inserted.

Source	Severity
SNMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnSFPRemoval on port

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnSFPRemoval on port log

Trap: bsnSFPRemoval on port

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnSFPRemoval on port

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnSFPRemoval on port log

Trap: bsnSFPRemoval on port

SFP was removed.

Source	Severity
SNMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Trap: bsnSnmpMaxPktSizeChanged - Maximum SNMP packet size changed to %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnSnmpMaxPktSizeChanged - Maximum SNMP packet size changed to %d log

Trap: bsnSnmpMaxPktSizeChanged - Maximum SNMP packet size changed to %d

**Source**   **Severity**  
SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap bsnStackConfigurationError

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap bsnStackConfigurationError log

Trap bsnStackConfigurationError

Stack Configuration Error.

Source	Severity
Stack Monitor	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnStackConfigurationError

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnStackConfigurationError log

Trap: bsnStackConfigurationError

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap bsnStackManagerReconfiguration

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap bsnStackManagerReconfiguration log

Trap bsnStackManagerReconfiguration

Stack manager re-configuration.

Source	Severity
Stack Manager	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnStackManagerReconfiguration

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnStackManagerReconfiguration log

Trap: bsnStackManagerReconfiguration

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnStackProtection

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnStackProtection log

Trap: bsnStackProtection

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnSystemUp365Days sent from unit %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnSystemUp365Days sent from unit %d log

Trap: bsnSystemUp365Days sent from unit %d

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnSystemUp365Days sent from unit %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnSystemUp365Days sent from unit %d log

Trap: bsnSystemUp365Days sent from unit %d

The message is logged with the SNMP trap. The notification indicates the system has been up for 365 days.

Source	Severity
TOTAL SYS UPTIME (TSU)	Information

### Remedial action

No action required





Trap: bsnTrialLicenseExpiration: Trial license %d has expired. Disable licensed features to avoid network interruption

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnTrialLicenseExpiration: Trial license %d has expired. Disable licensed features to avoid network interruption log

Trap: bsnTrialLicenseExpiration: Trial license %d has expired. Disable licensed features to avoid network interruption

Source	Severity
SNMP	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Trap: bsnTrialLicenseExpiration: Trial license %d will expire in %d day(s)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnTrialLicenseExpiration: Trial license %d will expire in %d day(s) log

Trap: bsnTrialLicenseExpiration: Trial license %d will expire in %d day(s)

Source	Severity
SNMP	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap bsnTrialLicenseExpiration Trial license license# has expired. Disable licensed features to avoid network interruption

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap bsnTrialLicenseExpiration Trial license license# has expired. Disable licensed features to avoid network interruption log

Trap bsnTrialLicenseExpiration Trial license license# has expired. Disable licensed features to avoid network interruption

The trial license has expired.

Source	Severity
SOFTLIC	Information

### Remedial action

Disable the licensed features to avoid network interruption.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap bsnTrialLicenseExpiration Trial license license# will expire in # days day(s)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap bsnTrialLicenseExpiration Trial license license# will expire in # days day(s) log

Trap bsnTrialLicenseExpiration Trial license license# will expire in # days day(s)

This message indicates that the trial license will expire.

Source	Severity
SOFTLIC	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnTrunkPortDisabledToPreventBroadcastStorm

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnTrunkPortDisabledToPreventBroadcastStorm log

Trap: bsnTrunkPortDisabledToPreventBroadcastStorm

Source	Severity
SNMP	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnTrunkPortEnabledToPreventBroadcastStorm

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnTrunkPortEnabledToPreventBroadcastStorm log

Trap: bsnTrunkPortEnabledToPreventBroadcastStorm

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnUSBInsertion on unit

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnUSBInsertion on unit log

Trap: bsnUSBInsertion on unit

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnUSBInsertion on unit

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnUSBInsertion on unit log

Trap: bsnUSBInsertion on unit

USB was inserted.

Source	Severity
SNMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Trap: bsnUSBRemoval on unit

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnUSBRemoval on unit log

Trap: bsnUSBRemoval on unit

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsnUSBRemoval on unit

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsnUSBRemoval on unit log

Trap: bsnUSBRemoval on unit

USB was removed.

Source	Severity
SNMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bspelpPhonePowerLimitNotification

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bspelpPhonePowerLimitNotification log

Trap: bspelpPhonePowerLimitNotification

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bspelPhonePowerPriorityNotification

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bspelPhonePowerPriorityNotification log

Trap: bspelPhonePowerPriorityNotification

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap bspePethPsePortCurrentStatusNotification

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap bspePethPsePortCurrentStatusNotification log

Trap bspePethPsePortCurrentStatusNotification

Peth Pse Port Current Status.

Source	Severity
POL	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bspePethPsePortCurrentStatusNotification

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bspePethPsePortCurrentStatusNotification log

Trap: bspePethPsePortCurrentStatusNotification

**Source   Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsStormControlAboveHighWatermark

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsStormControlAboveHighWatermark log

Trap: bsStormControlAboveHighWatermark

**Source   Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsStormControlBelowLowWatermark

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsStormControlBelowLowWatermark log

Trap: bsStormControlBelowLowWatermark

**Source   Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Trap bsUnicastStormControlAboveHighWatermark

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap bsUnicastStormControlAboveHighWatermark log

Trap bsUnicastStormControlAboveHighWatermark

Unicast Storm Control reached the high watermark level.

Source	Severity
DRIVER	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsUnicastStormControlAboveHighWatermark

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsUnicastStormControlAboveHighWatermark log

Trap: bsUnicastStormControlAboveHighWatermark

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap bsUnicastStormControlBelowLowWatermark

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap bsUnicastStormControlBelowLowWatermark log

Trap bsUnicastStormControlBelowLowWatermark

Unicast Storm Control has gone below low watermark level.

Source	Severity
DRIVER	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsUnicastStormControlBelowLowWatermark

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsUnicastStormControlBelowLowWatermark log

Trap: bsUnicastStormControlBelowLowWatermark

**Source   Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap bsveVrrpTrapStateTransition

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap bsveVrrpTrapStateTransition log

Trap bsveVrrpTrapStateTransition

VRRP Trap State Transition.

Source	Severity
VRRP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: bsveVrrpTrapStateTransition

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: bsveVrrpTrapStateTransition log

Trap: bsveVrrpTrapStateTransition

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap DAPP - DoS Attack Detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap DAPP - DoS Attack Detected log

Trap DAPP - DoS Attack Detected

The system detected a DAPP - DoS attack.

Source	Severity
QPAV2	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: DAPP - DoS Attack Detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: DAPP - DoS Attack Detected log

Trap: DAPP - DoS Attack Detected

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Trap Device has entered Forced Stack Mode ( MAC Address )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap Device has entered Forced Stack Mode ( MAC Address ) log

Trap Device has entered Forced Stack Mode ( MAC Address )

Device has entered Forced Stack Mode.

Source	Severity
IPT	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Trap: Device has entered Forced Stack Mode  
(MAC: %02x: %02x: %02x: %02x: %02x: %02x  
IP: %s)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: Device has entered Forced Stack Mode (MAC:%02x:%02x:%02x:%02x:%02x:%02x IP:%s) log

Trap: Device has entered Forced Stack Mode (MAC:%02x:%02x:%02x:%02x:%02x:%02x IP:%s)

**Source**   **Severity**  
SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap entConfigChange

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap entConfigChange log

Trap entConfigChange

Ent Config Change.

Source	Severity
ENTMIB	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: entConfigChange

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: entConfigChange log

Trap: entConfigChange

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap fallingAlarm

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap fallingAlarm log

Trap fallingAlarm

Falling Alarm.

Source	Severity
RMON	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: fallingAlarm

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: fallingAlarm log

Trap: fallingAlarm

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: FCoE - Egress Issue Detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: FCoE - Egress Issue Detected log

Trap: FCoE - Egress Issue Detected

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: FCoE - Egress Issue Detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: FCoE - Egress Issue Detected log

Trap: FCoE - Egress Issue Detected

Issue detected with link/trunk used for FCoE Redirect.

Source	Severity
FCoE Redirect	Serious

### Remedial action

Check FCoE config/link status.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Trap IldpRemTableChange Ageouts = count

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap IldpRemTableChange Ageouts = count log

Trap IldpRemTableChange Ageouts = count

IldpRemTableChange Ageouts Number

Source	Severity
802.1AB	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: IldpRemTableChange Ageouts = %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: IldpRemTableChange Ageouts = %d log

Trap: IldpRemTableChange Ageouts = %d

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap IldpRemTableChange Deletes = count

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap IldpRemTableChange Deletes = count log

Trap IldpRemTableChange Deletes = count

IldpRemTableChange Deletes Number.

Source	Severity
802.1AB	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: IldpRemTableChange Deletes = %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: IldpRemTableChange Deletes = %d log

Trap: IldpRemTableChange Deletes = %d

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap IldpRemTableChange Drops = count

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap IldpRemTableChange Drops = count log

Trap IldpRemTableChange Drops = count

IldpRemTableChange Drops Number

Source	Severity
802.1AB	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: IldpRemTableChange Drops = %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: IldpRemTableChange Drops = %d log

Trap: IldpRemTableChange Drops = %d

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap IldpRemTableChange Inserts = count

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap IldpRemTableChange Inserts = count log

Trap IldpRemTableChange Inserts = count

IldpRemTableChange Inserts Number

Source	Severity
802.1AB	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: IldpRemTableChange Inserts = %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: IldpRemTableChange Inserts = %d log

Trap: IldpRemTableChange Inserts = %d

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





Trap:  
IldpXMedTopologyChangeDetected,  
Subtype = %d Class = %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: IldpXMedTopologyChangeDetected, Subtype = %d Class = %d log

Trap: IldpXMedTopologyChangeDetected, Subtype = %d Class = %d

Source	Severity
SNMP	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap IldpXMedTopologyChangeDetected Subtype = subtype Class = class

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap IldpXMedTopologyChangeDetected Subtype = subtype Class = class log

Trap IldpXMedTopologyChangeDetected Subtype = subtype Class = class

The system detected a IldpXMed Topology Change.

Source	Severity
802.1AB	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: MSTP Error Event

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: MSTP Error Event log

Trap: MSTP Error Event

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: MSTP General Event:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: MSTP General Event: log

Trap: MSTP General Event:

This message appears when a link comes up or goes down, or when a MSTP instance goes up or comes down.

Source	Severity
SNMP	Information

### Remedial action

None.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: MSTP General Event:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: MSTP General Event: log

Trap: MSTP General Event:

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: MSTP New Root

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: MSTP New Root log

Trap: MSTP New Root

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: MSTP Protocol Migration

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: MSTP Protocol Migration log

Trap: MSTP Protocol Migration

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: MSTP Region Config Change

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: MSTP Region Config Change log

Trap: MSTP Region Config Change

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Trap: MSTP Topology Change

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: MSTP Topology Change log

Trap: MSTP Topology Change

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap newRoot

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap newRoot log

Trap newRoot

New root.

Source	Severity
NNCLI	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: newRoot

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: newRoot log

Trap: newRoot

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap ntnQosPolicyEvolLocalUbpSessionFailure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap ntnQosPolicyEvolLocalUbpSessionFailure log

Trap ntnQosPolicyEvolLocalUbpSessionFailure

QoS Policy Evol Local UBP Session Failed.

Source	Severity
QPAV2	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: ntnQosPolicyEvolLocalUbpSessionFailure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: ntnQosPolicyEvolLocalUbpSessionFailure log

Trap: ntnQosPolicyEvolLocalUbpSessionFailure

**Source   Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap ospfIfAuthFailure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap ospfIfAuthFailure log

Trap ospfIfAuthFailure

The OSPF Interface Authentication failed.

Source	Severity
OSPF	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: ospfIfAuthFailure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: ospfIfAuthFailure log

Trap: ospfIfAuthFailure

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap ospfIfConfigError

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap ospfIfConfigError log

Trap ospfIfConfigError

OSPF Interface Configuration Error.

Source	Severity
OSPF	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Trap: ospfIfConfigError

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: ospfIfConfigError log

Trap: ospfIfConfigError

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap ospfIfStateChange

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap ospfIfStateChange log

Trap ospfIfStateChange

The OSPF Interface state changed.

Source	Severity
OSPF	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: ospfIfStateChange

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: ospfIfStateChange log

Trap: ospfIfStateChange

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap ospfNbrStateChange

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap ospfNbrStateChange log

Trap ospfNbrStateChange

OSPF Neighbor State Change.

Source	Severity
OSPF	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: ospfNbrStateChange

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: ospfNbrStateChange log

Trap: ospfNbrStateChange

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap ospfVirtIfAuthFailure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap ospfVirtIfAuthFailure log

Trap ospfVirtIfAuthFailure

The OSPF Virtual Interface Authentication failed.

Source	Severity
OSPF	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: ospfVirtIfAuthFailure

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: ospfVirtIfAuthFailure log

Trap: ospfVirtIfAuthFailure

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap ospfVirtIfConfigError

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap ospfVirtIfConfigError log

Trap ospfVirtIfConfigError

The system detected an OSPF Virtual Interface Configuration Error.

Source	Severity
OSPF	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Trap: ospfVirtIfConfigError

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: ospfVirtIfConfigError log

Trap: ospfVirtIfConfigError

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap ospfVirtIfStateChange

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap ospfVirtIfStateChange log

Trap ospfVirtIfStateChange

OSPF Virtual Interface State Change.

Source	Severity
OSPF	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: ospfVirtIfStateChange

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: ospfVirtIfStateChange log

Trap: ospfVirtIfStateChange

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap ospfVirtNbrStateChange

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap ospfVirtNbrStateChange log

Trap ospfVirtNbrStateChange

OSPF Virtual Neighbor State Change.

Source	Severity
OSPF	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: ospfVirtNbrStateChange

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: ospfVirtNbrStateChange log

Trap: ospfVirtNbrStateChange

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap pethMainPowerUsageOffNotification

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap pethMainPowerUsageOffNotification log

Trap pethMainPowerUsageOffNotification

Peth Main Power Usage Off.

Source	Severity
POL	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: pethMainPowerUsageOffNotification

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: pethMainPowerUsageOffNotification log

Trap: pethMainPowerUsageOffNotification

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap pethMainPowerUsageOnNotification

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap pethMainPowerUsageOnNotification log

Trap pethMainPowerUsageOnNotification

Peth Main Power Usage On.

Source	Severity
POL	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Trap: pethMainPowerUsageOnNotification

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: pethMainPowerUsageOnNotification log

Trap: pethMainPowerUsageOnNotification

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap pethPsePortOnOffNotification

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap pethPsePortOnOffNotification log

Trap pethPsePortOnOffNotification

Peth Pse Port On Off.

Source	Severity
POL	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: pethPsePortOnOffNotification

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: pethPsePortOnOffNotification log

Trap: pethPsePortOnOffNotification

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: rcIpBgpTmpAfBackwardTransitionNotification

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: rcIpBgpTmpAfBackwardTransitionNotification log

Trap: rcIpBgpTmpAfBackwardTransitionNotification

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: rcIpBgpTmpAfEstablishedNotification

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: rcIpBgpTmpAfEstablishedNotification log

Trap: rcIpBgpTmpAfEstablishedNotification

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: rcIIsisPlsbBvidMismatchTrap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: rclsisPlsbBvidMismatchTrap log

Trap: rcIIsisPlsbBvidMismatchTrap

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: rcIIsisPlsbBvidMismatchTrap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: rcIIsisPlsbBvidMismatchTrap log

Trap: rcIIsisPlsbBvidMismatchTrap

Trap was sent when the B-VID TLV from a neighbor node does not match the local configuration.

Source	Severity
ISIS	Information

### Remedial action

Correct SPBM B-VID configuration.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: rclsisPlsbLsdbUpdateTrap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: rclsisPlsbLsdbUpdateTrap log

Trap: rclsisPlsbLsdbUpdateTrap

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Trap: rcIIsisPlsbLsdbUpdateTrap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: rcIIsisPlsbLsdbUpdateTrap log

Trap: rcIIsisPlsbLsdbUpdateTrap

An IS-IS trap indicating that LSDB information has changed.

Source	Severity
ISIS	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: rcIIsisPlsbSmltPeerBmacMismatchTrap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: rcIIsisPlsbSmltPeerBmacMismatchTrap log

Trap: rcIIsisPlsbSmltPeerBmacMismatchTrap

### Source    Severity

SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: rcIIsisPlsbSmltPeerBmacMismatchTrap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: rcIIsisPlsbSmltPeerBmacMismatchTrap log

Trap: rcIIsisPlsbSmltPeerBmacMismatchTrap

A PLSB ISIS trap signifies that the Smlt Split-Beb configured in the local switch and IST peer are the same. Configure One IST switch as Split-Beb primary and configure IST peer as Split-Beb secondary.

Source	Severity
SPB	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: rcIIsisPlsbSmltSplitBebMismatchTrap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: rcIIsisPlsbSmltSplitBebMismatchTrap log

Trap: rcIIsisPlsbSmltSplitBebMismatchTrap

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: rcIsisPlsbSmltSplitBebMismatchTrap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: rcIsisPlsbSmltSplitBebMismatchTrap log

Trap: rcIsisPlsbSmltSplitBebMismatchTrap

A PLSB ISIS trap signifies that the Smlt Split-Beb configured in the local switch and IST peer are same. Configure One IST switch as Split-Beb primary and configure IST peer as Split-Beb secondary.

Source	Severity
SBR	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: rcIsisPlsbSmltVirtBmacMismatchTrap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: rcIsisPlsbSmltVirtBmacMismatchTrap log

Trap: rcIsisPlsbSmltVirtBmacMismatchTrap

### Source    Severity

SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: rcIsisPlsbSmltVirtBmacMismatchTrap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: rcIsisPlsbSmltVirtBmacMismatchTrap log

Trap: rcIsisPlsbSmltVirtBmacMismatchTrap

A PLSB ISIS trap signifies that the Virtual BMAC configured in the switch is different from virtual BMAC configured in the IST peer.

Source	Severity
SPB	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Trap: rcVrrpExtTrapStateTransitionTrap  
- master ipv6 address %s, ifindex %i,  
vrid %i

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: rcVrrpExtTrapStateTransitionTrap - master ipv6 address %s, ifindex %i, vrid %i log

Trap: rcVrrpExtTrapStateTransitionTrap - master ipv6 address %s, ifindex %i, vrid %i

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





Trap: rcVrrpTmpTrapNewMasterTrap -  
master ipv6 address %s, ifindex %d,  
vrid %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: rcVrrpTmpTrapNewMasterTrap - master ipv6 address %s, ifindex %d, vrid %d log

Trap: rcVrrpTmpTrapNewMasterTrap - master ipv6 address %s, ifindex %d, vrid %d

Source	Severity
SNMP	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap risingAlarm

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap risingAlarm log

Trap risingAlarm

Rising alarm.

Source	Severity
RMON	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: risingAlarm

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: risingAlarm log

Trap: risingAlarm

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap RSTP Error Event

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap RSTP Error Event log

Trap RSTP Error Event

RSTP Error Event.

Source	Severity
NNRST	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: RSTP Error Event

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: RSTP Error Event log

Trap: RSTP Error Event

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap RSTP General Event

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap RSTP General Event log

Trap RSTP General Event

RSTP General Event.

Source	Severity
NNRST	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: RSTP General Event:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: RSTP General Event: log

Trap: RSTP General Event:

This message appears when a link comes up or goes down.

Source	Severity
SNMP	Information

### Remedial action

None.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: RSTP General Event:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: RSTP General Event: log

Trap: RSTP General Event:

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Trap RSTP New Root

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap RSTP New Root log

Trap RSTP New Root

RSTP New Root.

Source	Severity
NNRST	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: RSTP New Root

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: RSTP New Root log

Trap: RSTP New Root

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap RSTP Protocol Migration

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap RSTP Protocol Migration log

Trap RSTP Protocol Migration

RSTP Protocol Migration.

Source	Severity
NNRST	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: RSTP Protocol Migration

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: RSTP Protocol Migration log

Trap: RSTP Protocol Migration

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap RSTP Topology Change

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap RSTP Topology Change log

Trap RSTP Topology Change

RSTP Topology Change.

Source	Severity
NNRST	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: RSTP Topology Change

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: RSTP Topology Change log

Trap: RSTP Topology Change

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: Run %s %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: Run %s %s log

Trap: Run %s %s

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: Run %s %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: Run %s %s log

Trap: Run %s %s

Script %s failed/was successfully executed.

Source	Severity
SNMP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Trap: s5CtrFanDirectionError

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: s5CtrFanDirectionError log

Trap: s5CtrFanDirectionError

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: s5CtrFanDirectionError

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: s5CtrFanDirectionError log

Trap: s5CtrFanDirectionError

The message is logged with the SNMP trap s5CtrFanDirectionError. This notification indicates that a fan component's direction is incorrect.

Source	Severity
DCE	Information

### Remedial action

Verify the fan component's direction.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: s5CtrHighTemperatureError

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: s5CtrHighTemperatureError log

Trap: s5CtrHighTemperatureError

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: s5CtrHighTemperatureError

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: s5CtrHighTemperatureError log

Trap: s5CtrHighTemperatureError

The message is logged with the SNMP trap s5CtrHighTemperatureError. This notification indicates that the system is overheated.

Source	Severity
DCE	Information

### Remedial action

Verify system temperature.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap s5CtrHotSwap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap s5CtrHotSwap log

Trap s5CtrHotSwap

Hot Swap.

Source	Severity
MCMGR, DRPMGR	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: s5CtrNewHotSwap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: s5CtrNewHotSwap log

Trap: s5CtrNewHotSwap

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: s5CtrNewProblem

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: s5CtrNewProblem log

Trap: s5CtrNewProblem

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: s5CtrNewUnitDown

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: s5CtrNewUnitDown log

Trap: s5CtrNewUnitDown

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Trap: s5CtrNewUnitUp

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: s5CtrNewUnitUp log

Trap: s5CtrNewUnitUp

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap s5CtrUnitDown

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap s5CtrUnitDown log

Trap s5CtrUnitDown

Unit down.

Source	Severity
L3, MLT	Serious

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap s5CtrUnitDown

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap s5CtrUnitDown log

Trap s5CtrUnitDown

Unit down.

Source	Severity
L3, MLT	Warning

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: s5EtrMacAddressTablesThresholdReached

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: s5EtrMacAddressTablesThresholdReached log

Trap: s5EtrMacAddressTablesThresholdReached

**Source   Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: s5EtrMacAddressTablesThresholdReached

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: s5EtrMacAddressTablesThresholdReached log

Trap: s5EtrMacAddressTablesThresholdReached

s5EtrMacAddressTablesThresholdReached trap signifies that the MAC address tables threshold is reached.

Source	Severity
CDT	Information

### Remedial action

Remove at least one MAC address.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: s5EtrNewSbsMacAccessViolation

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: s5EtrNewSbsMacAccessViolation log

Trap: s5EtrNewSbsMacAccessViolation

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap s5EtrSbsMacAccessViolation

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap s5EtrSbsMacAccessViolation log

Trap s5EtrSbsMacAccessViolation

MAC access violation.

**Source**

BAYSECURE, DCE

**Severity**

Information

**Remedial action**

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap s5EtrSbsMacAccessViolation

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap s5EtrSbsMacAccessViolation log

Trap s5EtrSbsMacAccessViolation

MAC access violation.

**Source**

BAYSECURE, DCE

**Severity**

Information

**Remedial action**

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Trap s5EtrSbsMacRemoved

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap s5EtrSbsMacRemoved log

Trap s5EtrSbsMacRemoved

MAC removed.

Source	Severity
NNCLI	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: s5EtrSbsMacRemoved

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: s5EtrSbsMacRemoved log

Trap: s5EtrSbsMacRemoved

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap s5EtrSbsMacTableCleared

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap s5EtrSbsMacTableCleared log

Trap s5EtrSbsMacTableCleared

MAC Table Cleared.

Source	Severity
NNCLI	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: s5EtrSbsMacTableCleared

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: s5EtrSbsMacTableCleared log

Trap: s5EtrSbsMacTableCleared

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap s5EtrSbsMacTableClearedForPort

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap s5EtrSbsMacTableClearedForPort log

Trap s5EtrSbsMacTableClearedForPort

The MAC table cleared for the Port.

Source	Severity
NNCLI	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: s5EtrSbsMacTableClearedForPort

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: s5EtrSbsMacTableClearedForPort log

Trap: s5EtrSbsMacTableClearedForPort

### Source    Severity

SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: s5EtrSbsMacTableFull

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: s5EtrSbsMacTableFull log

Trap: s5EtrSbsMacTableFull

**Source    Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: SFP Transceiver's Bias has reached an alarm level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: SFP Transceiver's Bias has reached an alarm level log

Trap: SFP Transceiver's Bias has reached an alarm level

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Trap: SFP Transceiver's Bias has reached a warning level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: SFP Transceiver's Bias has reached a warning level log

Trap: SFP Transceiver's Bias has reached a warning level

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: SFP Transceiver's Bias is no longer at warning/alarm level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: SFP Transceiver's Bias is no longer at warning/alarm level log

Trap: SFP Transceiver's Bias is no longer at warning/alarm level

**Source**   **Severity**  
SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: SFP Transceiver's Bias is no longer at warning/alarm level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: SFP Transceiver's Bias is no longer at warning/alarm level log

Trap: SFP Transceiver's Bias is no longer at warning/alarm level

Will be logged only after the specified bias trap was sent. The trap will be sent if the alarm/warning bits were set previously and at the current moment they are unset. The user will know how to distinguish between alarms and warnings because if there was recorded alarm ,an alarm trap will be sent. The same case for warnings.

Source	Severity
Port Driver	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: \$#160;SFP Transceiver's Bias is no longer at warning/alarm level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap:\$#160;SFP Transceiver's Bias is no longer at warning/alarm level log

Trap:\$#160;SFP Transceiver's Bias is no longer at warning/alarm level

Will be logged only after the specified bias trap was sent. The trap will be sent if the alarm/warning bits were set previously and at the current moment they are unset. The user will know how to distinguish between alarms and warnings because if there was recorded alarm ,an alarm trap will be sent. The same case for warnings.

Source	Severity
Port Driver	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: SFP Transceiver's Rx Power has reached an alarm level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: SFP Transceiver's Rx Power has reached an alarm level log

Trap: SFP Transceiver's Rx Power has reached an alarm level

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: SFP Transceiver's Rx Power has reached a warning level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: SFP Transceiver's Rx Power has reached a warning level log

Trap: SFP Transceiver's Rx Power has reached a warning level

**Source   Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: SFP Transceiver's Rx Power is no longer at warning/alarm level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: SFP Transceiver's Rx Power is no longer at warning/alarm level log

Trap: SFP Transceiver's Rx Power is no longer at warning/alarm level

**Source**   **Severity**  
SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: SFP Transceiver's Temperature has reached an alarm level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: SFP Transceiver's Temperature has reached an alarm level log

Trap: SFP Transceiver's Temperature has reached an alarm level

Source	Severity
SNMP	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Trap: SFP Transceiver's Temperature has reached a warning level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: SFP Transceiver's Temperature has reached a warning level log

Trap: SFP Transceiver's Temperature has reached a warning level

Source	Severity
SNMP	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: SFP Transceiver's Temperature is no longer at warning/alarm level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: SFP Transceiver's Temperature is no longer at warning/alarm level log

Trap: SFP Transceiver's Temperature is no longer at warning/alarm level

Source	Severity
SNMP	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: SFP Transceiver's Temperature is no longer at warning/alarm level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: SFP Transceiver's Temperature is no longer at warning/alarm level log

Trap: SFP Transceiver's Temperature is no longer at warning/alarm level

Will be logged only after the specified temperature trap was sent. The trap will be sent if the alarm/warning bits were set previously and at the current moment they are unset. The user will know how to distinguish between alarms and warnings because if there was recorded alarm ,an alarm trap will be sent. The same case for warnings.

Source	Severity
Port Driver	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: \$#160;SFP Transceiver's Temperature is no longer at warning/alarm level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap:\$#160;SFP Transceiver's Temperature is no longer at warning/alarm level log

Trap:\$#160;SFP Transceiver's Temperature is no longer at warning/alarm level

Will be logged only after the specified temperature trap was sent. The trap will be sent if the alarm/warning bits were set previously and at the current oment they are unset. The user will know how to distinguish between alarms and warnings because if there was recorded alarm ,an alarm trap will be sent. The same case for warnings.

Source	Severity
Port Driver	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: SFP Transceiver's Tx Power has reached an alarm level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: SFP Transceiver's Tx Power has reached an alarm level log

Trap: SFP Transceiver's Tx Power has reached an alarm level

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: SFP Transceiver's Tx Power has reached a warning level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: SFP Transceiver's Tx Power has reached a warning level log

Trap: SFP Transceiver's Tx Power has reached a warning level

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: SFP Transceiver's Tx Power is no longer at warning/alarm level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: SFP Transceiver's Tx Power is no longer at warning/alarm level log

Trap: SFP Transceiver's Tx Power is no longer at warning/alarm level

**Source**   **Severity**  
SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: SFP Transceiver's Tx Power is no longer at warning/alarm level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: SFP Transceiver's Tx Power is no longer at warning/alarm level log

Trap: SFP Transceiver's Tx Power is no longer at warning/alarm level

Will be logged only after the tx specified power trap was sent. The trap will be sent if the alarm/warning bits were set previously and at the current moment they are unset. The user will know how to distinguish between alarms and warnings because if there was recorded alarm ,an alarm trap will be sent. The same case for warnings.

Source	Severity
Port Driver	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>





# Trap: \$#160;SFP Transceiver's Tx Power is no longer at warning/alarm level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap:\$#160;SFP Transceiver's Tx Power is no longer at warning/alarm level log

Trap:\$#160;SFP Transceiver's Tx Power is no longer at warning/alarm level

Will be logged only after the tx specified power trap was sent. The trap will be sent if the alarm/warning bits were set previously and at the current moment they are unset. The user will know how to distinguish between alarms and warnings because if there was recorded alarm ,an alarm trap will be sent. The same case for warnings.

Source	Severity
Port Driver	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: SFP Transceiver's Voltage has reached an alarm level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: SFP Transceiver's Voltage has reached an alarm level log

Trap: SFP Transceiver's Voltage has reached an alarm level

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: SFP Transceiver's Voltage has reached a warning level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: SFP Transceiver's Voltage has reached a warning level log

Trap: SFP Transceiver's Voltage has reached a warning level

**Source   Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: SFP Transceiver's Voltage is no longer at warning/alarm level

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: SFP Transceiver's Voltage is no longer at warning/alarm level log

Trap: SFP Transceiver's Voltage is no longer at warning/alarm level

**Source**   **Severity**  
SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: slaMonitorAgentExceptionDetected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: slaMonitorAgentExceptionDetected log

Trap: slaMonitorAgentExceptionDetected

SLAMon agent operation terminated.

Source	Severity
SLAMon	Critical

### Remedial action

Reset device.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: SLPP Guard Hold Down Expired, %s. Port has been re-enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: SLPP Guard Hold Down Expired, %s. Port has been re-enabled log

Trap: SLPP Guard Hold Down Expired, %s. Port has been re-enabled

**Source**   **Severity**  
SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: SLPP Guard Packet Received, %s. Port has been disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: SLPP Guard Packet Received, %s. Port has been disabled log

Trap: SLPP Guard Packet Received, %s. Port has been disabled

### Source    Severity

SNMP

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap SLPP Port Down Event

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap SLPP Port Down Event log

Trap SLPP Port Down Event

SLPP Port Down Event.

Source	Severity
SMLT	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Trap: SLPP Port Down Event

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: SLPP Port Down Event log

Trap: SLPP Port Down Event

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap Smlt Ist Link Down

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap Smlt Ist Link Down log

Trap Smlt Ist Link Down

SMLT IST Link Down.

Source	Severity
SMLT	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: Smlt Ist Link Down

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: Smlt Ist Link Down log

Trap: Smlt Ist Link Down

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap Smlt Ist Link Up

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap Smlt Ist Link Up log

Trap Smlt Ist Link Up

SMLT IST Link Up

Source	Severity
SMLT	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: Smlt Ist Link Up

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: Smlt Ist Link Up log

Trap: Smlt Ist Link Up

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap Smlt Link Down

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap Smlt Link Down log

Trap Smlt Link Down

SMLT Link Down.

Source	Severity
SMLT	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: Smlt Link Down

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: Smlt Link Down log

Trap: Smlt Link Down

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap Smlt Link Up

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap Smlt Link Up log

Trap Smlt Link Up

SMLT Link Up.

Source	Severity
SMLT	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Trap: Smlt Link Up

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: Smlt Link Up log

Trap: Smlt Link Up

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap topologyChange

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap topologyChange log

Trap topologyChange

Topology Change.

Source	Severity
NNCLI	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: topologyChange

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: topologyChange log

Trap: topologyChange

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap ubpEAPSessionEnd

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap ubpEAPSessionEnd log

Trap ubpEAPSessionEnd

EAP Session end.

Source	Severity
QPAV2	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: ubpEAPSessionEnd

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: ubpEAPSessionEnd log

Trap: ubpEAPSessionEnd

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap ubpEAPSessionStart

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap ubpEAPSessionStart log

Trap ubpEAPSessionStart

EAP Session Start.

Source	Severity
QPAV2	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap: ubpEAPSessionStart

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: ubpEAPSessionStart log

Trap: ubpEAPSessionStart

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trap vrrpTrapNewMaster

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap vrrpTrapNewMaster log

Trap vrrpTrapNewMaster

VRRP Trap New Master.

Source	Severity
VRRP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Trap: vrrpTrapNewMaster

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trap: vrrpTrapNewMaster log

Trap: vrrpTrapNewMaster

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# trTCM meter issue - PBS must be greater than CBS

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## trTCM meter issue - PBS must be greater than CBS log

trTCM meter issue - PBS must be greater than CBS

PBS is not greater than CBS.

Source	Severity
QoS	Serious

### Remedial action

Modify options so that PIR is greater than CIR.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# trTCM meter issue - PIR must be greater than CIR

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## trTCM meter issue - PIR must be greater than CIR log

trTCM meter issue - PIR must be greater than CIR

PIR is not greater than CIR .

Source	Severity
QoS	Serious

### Remedial action

Modify options so that PIR is greater than CIR.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Trusted processing mode change rejected - inadequate resources

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Trusted processing mode change rejected - inadequate resources log

Trusted processing mode change rejected - inadequate resources

Unable to commit trusted processing mode transition form partial to full. Not enough resources available.

Source	Severity
QoS	Serious

### Remedial action

Check for and remove unneeded resources.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



tx db cat=%d cnt=%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## tx db cat=%d cnt=%d log

tx db cat=%d cnt=%d

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# UBP CoA cannot proceed, dynamic UBP not enabled either for EAP or Non-EAP clients

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## UBP CoA cannot proceed, dynamic UBP not enabled either for EAP or Non-EAP clients log

UBP CoA cannot proceed, dynamic UBP not enabled either for EAP or Non-EAP clients

CoA cannot run if dynamic UBP is not enabled either for EAP or for non-EAP clients.

Source	Severity
--------	----------

EAP	Warning
-----	---------

### Remedial action

Enable dynamic UBP either for EAP or for non-EAP clients.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to add block member ( block elem# component set id ) to existing policy

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to add block member ( block elem# component set id ) to existing policy log

Unable to add block member ( block elem# component set id ) to existing policy

Failed to install the specified classifier-block.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Check for available resources, interface capabilities or possible conflicts.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to add block member (%d/%d) to existing policy

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to add block member (%d/%d) to existing policy log

Unable to add block member (%d/%d) to existing policy

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Unable to apply existing policy data to interface (%d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to apply existing policy data to interface (%d/%d) log

Unable to apply existing policy data to interface (%d/%d)

**Source   Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to apply existing policy data to interface ( unit# port# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to apply existing policy data to interface ( unit# port# ) log

Unable to apply existing policy data to interface ( unit# port# )

The interface assignment change needs to add the port to an existing policy.

Source	Severity
QoS	Serious

### Remedial action

Check the available/not needed resources.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to apply existing user-based policy data to new user

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to apply existing user-based policy data to new user log

Unable to apply existing user-based policy data to new user

The system failed to clone the policy and the meter data that is associated with the current user.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, or reset the stack

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to apply filter set to ports (unsupported capabilities)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to apply filter set to ports (unsupported capabilities) log

Unable to apply filter set to ports (unsupported capabilities)

The filter set cannot be applied to the specified ports as the required interface capabilities are not compatible with all the interfaces.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Check the interface capabilities, and adapt the port mask for the operation to succeed.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to apply newly-defined UBP filter set to existing user

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to apply newly-defined UBP filter set to existing user log

Unable to apply newly-defined UBP filter set to existing user

The system failed to apply the defined user based policy filter set to the existing user.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, or reset the stack.



# Unable to apply pre-defined UBP filter set to new user

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to apply pre-defined UBP filter set to new user log

Unable to apply pre-defined UBP filter set to new user

Unable to install/update a UBP filter set for a new user.

Source	Severity
QoS	Serious

### Remedial action

Free resources/update UBP filter set

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to apply pre-defined UBP filter set to new user (port %d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to apply pre-defined UBP filter set to new user (port %d/%d) log

Unable to apply pre-defined UBP filter set to new user (port %d/%d)

The agent failed to install the corresponding UBP filter.

Source	Severity
--------	----------

QoS	Information
-----	-------------

### Remedial action

Check the log for a previous more detailed message or the current available hardware resources.



# Unable to complete requested access asgn system operation (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to complete requested access asgn system operation (%d) log

Unable to complete requested access asgn system operation (%d)

**Source**   **Severity**  
QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Unable to complete requested access asgn system operation ( oper type )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to complete requested access asgn system operation ( oper type ) log

Unable to complete requested access asgn system operation ( oper type )

The system failed to enable or disable the access assignment on the base or non-base unit (in the stack).

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, or reset the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to complete requested policy system operation (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to complete requested policy system operation (%d) log

Unable to complete requested policy system operation (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to complete requested policy system operation ( operation type )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to complete requested policy system operation ( operation type ) log

Unable to complete requested policy system operation ( operation type )

The operation failed either on base or on non-base unit.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent, reset the unit or check stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to compress classification criteria in set adequately

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to compress classification criteria in set adequately log

Unable to compress classification criteria in set adequately

Failed to compress the combination of classification data elements from the individual classifiers.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Separate the conflicting elements into multiple classifier sets.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to compress specified policy criteria

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to compress specified policy criteria log

Unable to compress specified policy criteria

Unable to compress the rule and/or mask for the specified filter. Filter Manager internal error.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to create action for access element

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to create action for access element log

Unable to create action for access element

Creation of action for the specified access element failed.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to create classifier block entry for access element

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to create classifier block entry for access element log

Unable to create classifier block entry for access element

Creation of the classifier block entry failed.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to create classifier component entry for access element

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to create classifier component entry for access element log

Unable to create classifier component entry for access element

Creation of the classifier component entry failed.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Unable to create count action (meter) for access assignment

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to create count action (meter) for access assignment log

Unable to create count action (meter) for access assignment

Failed to count action (from meter) for access assignment on base or non-base unit (if the stack is preset).

Source	Severity
QoS	Serious

### Remedial action

Check log for the related details on the issue. Try again later, reset the QoS agent or reset the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to create count action (policy) for access assignment

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to create count action (policy) for access assignment log

Unable to create count action (policy) for access assignment

Failed to count action (from policy) for access assignment on base or non-base unit.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, or reset the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to create count action (secondary meter) for access asgn

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to create count action (secondary meter) for access asgn log

Unable to create count action (secondary meter) for access asgn

Failed to create the count action component for ACL.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, or reset the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to create DS MF classifier for access element

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to create DS MF classifier for access element log

Unable to create DS MF classifier for access element

DS(IP) MF Classifier creation failed.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to create L2 MF classifier for access element

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to create L2 MF classifier for access element log

Unable to create L2 MF classifier for access element

Creation of the L2 MF classifier failed.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to create metering data for access assignment

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to create metering data for access assignment log

Unable to create metering data for access assignment

Failed to create metering data for access assignment on base or non-base unit.

Source	Severity
QoS	Serious

### Remedial action

Check log for the related details on the issue. Try again later, reset the QoS agent or reset the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to create non-match components for ACL

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to create non-match components for ACL log

Unable to create non-match components for ACL

Failed to create a non-match action component for ACL.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, or reset the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to create out-of-profile action for access assignment

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to create out-of-profile action for access assignment log

Unable to create out-of-profile action for access assignment

Failed to create out-of-profile action for access assignment on base or non-base unit.

Source	Severity
QoS	Serious

### Remedial action

Check the log for the related details on the issue. Try again later, reset the QoS agent or reset the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Unable to create policy data for access assignment

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to create policy data for access assignment log

Unable to create policy data for access assignment

Failed to create policy data for access assignment on base or non-base unit.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, or reset the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to create secondary metering data for access assignment

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to create secondary metering data for access assignment log

Unable to create secondary metering data for access assignment

Failed to create secondary metering data for ACL.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, or reset the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to create secondary token bucket data for access asgn

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to create secondary token bucket data for access asgn log

Unable to create secondary token bucket data for access asgn

The system failed to create a secondary token bucket component for ACL.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, or reset the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to create token bucket data for access assignment

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to create token bucket data for access assignment log

Unable to create token bucket data for access assignment

Failed to create the token bucket data for the access assignment on base or non-base unit.

Source	Severity
QoS	Serious

### Remedial action

Check log for the related details on the issue. Try again later, reset the QoS agent or reset the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to create yellow action for access assignment

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to create yellow action for access assignment log

Unable to create yellow action for access assignment

Failed to create yellow action component for ACL.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, or reset the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to deactivate policy associated with interface

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to deactivate policy associated with interface log

Unable to deactivate policy associated with interface

The resource policy deallocation failed.

Source	Severity
QoS	Serious

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to delete block member ( block element# component set id ) from existing policy

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to delete block member ( block element# component set id ) from existing policy log

Unable to delete block member ( block element# component set id ) from existing policy

Failed to remove the specified classifier-block .

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Check for existing references, possible conflicts or try again later.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# Unable to delete block member (%d/%d) from existing policy

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to delete block member (%d/%d) from existing policy log

Unable to delete block member (%d/%d) from existing policy

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Unable to delete UBP filter set on interface %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to delete UBP filter set on interface %d log

Unable to delete UBP filter set on interface %d

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to delete UBP filter set on interface ifc#

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to delete UBP filter set on interface ifc# log

Unable to delete UBP filter set on interface ifc#

Failed to remove the user based policy filter set on the specified interface.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, or reset the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to derive suitable filter set element eval precedence

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to derive suitable filter set element eval precedence log

Unable to derive suitable filter set element eval precedence

A precedence must be assigned to a filter set; else it cannot be installed on the interface.

Source	Severity
QoS	Serious

### Remedial action

Check the available un-needed resources, try again later, reset the QoS agent or reset the unit.



# Unable to determine clfr interface(s) compatibility

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to determine clfr interface(s) compatibility log

Unable to determine clfr interface(s) compatibility

Unable to make changes because the system failed to determine classifier/interface(s) compatibility version.

Source	Severity
QoS	Serious

### Remedial action

Enter a different classifier/interface, try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to determine clfr/interface(s) compatibility

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to determine clfr/interface(s) compatibility log

Unable to determine clfr/interface(s) compatibility

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to determine meter/interface(s) compatibility

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to determine meter/interface(s) compatibility log

Unable to determine meter/interface(s) compatibility

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to disable ARP Spoofing support on interface (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to disable ARP Spoofing support on interface (%d) log

Unable to disable ARP Spoofing support on interface (%d)

**Source   Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to disable ARP Spoofing support on interface ( ifc# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to disable ARP Spoofing support on interface ( ifc# ) log

Unable to disable ARP Spoofing support on interface ( ifc# )

The system failed to disable the ARP Spoofing support on the specified interface.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, or reset the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Unable to disable BPDUBlkr support on interface (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to disable BPDUBlkr support on interface (%d) log

Unable to disable BPDUBlkr support on interface (%d)

**Source   Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to disable BPDUBlkr support on interface ( ifc# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to disable BPDUBlkr support on interface ( ifc# ) log

Unable to disable BPDUBlkr support on interface ( ifc# )

Failed to disable BPDUBlkr policy data on the specified interface.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent or reset the stack.



# Unable to disable DHCP Snooping support on interface (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to disable DHCP Snooping support on interface (%d) log

Unable to disable DHCP Snooping support on interface (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to disable DHCP Snooping support on interface ( ifc# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to disable DHCP Snooping support on interface ( ifc# ) log

Unable to disable DHCP Snooping support on interface ( ifc# )

The system failed to disable the DHCP Snooping support on the specified interface.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent or reset the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to disable DHCP Spoofing support on interface (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to disable DHCP Spoofing support on interface (%d) log

Unable to disable DHCP Spoofing support on interface (%d)

**Source   Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to disable DHCP Spoofing support on interface ( ifc# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to disable DHCP Spoofing support on interface ( ifc# ) log

Unable to disable DHCP Spoofing support on interface ( ifc# )

The system failed to disable the DHCP Spoofing support on the specified interface.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, or reset the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to disable DNSPort support on interface (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to disable DNSPort support on interface (%d) log

Unable to disable DNSPort support on interface (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to disable DNSPort support on interface ( ifc# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to disable DNSPort support on interface ( ifc# ) log

Unable to disable DNSPort support on interface ( ifc# )

The system failed to disable the DNSPort policy data on the specified interface.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, or reset the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Unable to disable existing policy data on interface (%d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to disable existing policy data on interface (%d/%d) log

Unable to disable existing policy data on interface (%d/%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to disable existing policy data on interface ( unit# port# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to disable existing policy data on interface ( unit# port# ) log

Unable to disable existing policy data on interface ( unit# port# )

The interface assignment change needs to remove the port form an existing policy. This operation failed.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Check for and remove any conflicts regarding the interface.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to disable FTPPort support on interface (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to disable FTPPort support on interface (%d) log

Unable to disable FTPPort support on interface (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to disable FTPPort support on interface ( ifc# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to disable FTPPort support on interface ( ifc# ) log

Unable to disable FTPPort support on interface ( ifc# )

The system failed to disable the FTPPort policy data on the specified interface.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, or reset the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to disable Nachia support on interface (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to disable Nachia support on interface (%d) log

Unable to disable Nachia support on interface (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to disable Nachia support on interface ( ifc# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to disable Nachia support on interface ( ifc# ) log

Unable to disable Nachia support on interface ( ifc# )

The system failed to disable the Nachia policy data on the specified interface.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, or reset the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to disable policy data for access assignment

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to disable policy data for access assignment log

Unable to disable policy data for access assignment

Failed to disable the policy data.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, or reset the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to disable SQLSlam support on interface (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to disable SQLSlam support on interface (%d) log

Unable to disable SQLSlam support on interface (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Unable to disable SQLSlam support on interface ( ifc# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to disable SQLSlam support on interface ( ifc# ) log

Unable to disable SQLSlam support on interface ( ifc# )

The system failed to disable the SQLSlam policy data on the specified interface.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, or reset the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to disable SynFinScan support on interface (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to disable SynFinScan support on interface (%d) log

Unable to disable SynFinScan support on interface (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to disable SynFinScan support on interface ( ifc# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to disable SynFinScan support on interface ( ifc# ) log

Unable to disable SynFinScan support on interface ( ifc# )

The system failed to disable the SynFinScan policy data on the specified interface.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, or reset the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to disable Xmas support on interface (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to disable Xmas support on interface (%d) log

Unable to disable Xmas support on interface (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to disable Xmas support on interface ( ifc# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to disable Xmas support on interface ( ifc# ) log

Unable to disable Xmas support on interface ( ifc# )

The system failed to disable the Xmas policy data on the specified interface.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, or reset the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to enable ARP Spoofing support on interface (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to enable ARP Spoofing support on interface (%d) log

Unable to enable ARP Spoofing support on interface (%d)

**Source   Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to enable ARP Spoofing support on interface ( ifc# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to enable ARP Spoofing support on interface ( ifc# ) log

Unable to enable ARP Spoofing support on interface ( ifc# )

The system failed to enable the ARP Spoofing support on the specified interface.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, reset the stack, or use a different interface.



# Unable to enable BPDUBlkr support on interface (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to enable BPDUBlkr support on interface (%d) log

Unable to enable BPDUBlkr support on interface (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Unable to enable BPDUBlkr support on interface ( ifc# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to enable BPDUBlkr support on interface ( ifc# ) log

Unable to enable BPDUBlkr support on interface ( ifc# )

The system failed to enable the BDUBlkr policy data on the specified interface.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, reset the stack, or use a different interface.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to enable BPDUBlkr support on multiple interfaces

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to enable BPDUBlkr support on multiple interfaces log

Unable to enable BPDUBlkr support on multiple interfaces

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to enable DHCP Snooping support on interface (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to enable DHCP Snooping support on interface (%d) log

Unable to enable DHCP Snooping support on interface (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to enable DHCP Snooping support on interface ( ifc# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to enable DHCP Snooping support on interface ( ifc# ) log

Unable to enable DHCP Snooping support on interface ( ifc# )

The system failed to enable the DHCP Snooping support on the specified interface.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, reset the stack, or use a different interface.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to enable DHCP Spoofing support on interface (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to enable DHCP Spoofing support on interface (%d) log

Unable to enable DHCP Spoofing support on interface (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to enable DHCP Spoofing support on interface ( ifc# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to enable DHCP Spoofing support on interface ( ifc# ) log

Unable to enable DHCP Spoofing support on interface ( ifc# )

The system failed to enable the DHCP Spoofing support on the specified interface.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, reset the stack, or use a different interface.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to enable DNSPort support on interface (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to enable DNSPort support on interface (%d) log

Unable to enable DNSPort support on interface (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to enable DNSPort support on interface ( ifc# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to enable DNSPort support on interface ( ifc# ) log

Unable to enable DNSPort support on interface ( ifc# )

The system failed to enable the DNSPort policy data on the specified interface.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, reset the stack, or use a different interface.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Unable to enable FTPPort support on interface (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to enable FTPPort support on interface (%d) log

Unable to enable FTPPort support on interface (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to enable FTPPort support on interface ( ifc# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to enable FTPPort support on interface ( ifc# ) log

Unable to enable FTPPort support on interface ( ifc# )

The system failed to enable the FTPPort policy data on the specified interface.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, reset the stack, or use a different interface.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to enable Nachia support on interface (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to enable Nachia support on interface (%d) log

Unable to enable Nachia support on interface (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to enable Nachia support on interface ( ifc# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to enable Nachia support on interface ( ifc# ) log

Unable to enable Nachia support on interface ( ifc# )

The system failed to enable the Nachia policy data on the specified interface.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, reset the stack, or use a different interface.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to enable policy data for access assignment

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to enable policy data for access assignment log

Unable to enable policy data for access assignment

Failed to enable the policy data.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, or reset the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to enable SQLSlam support on interface (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to enable SQLSlam support on interface (%d) log

Unable to enable SQLSlam support on interface (%d)

**Source   Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to enable SQLSlam support on interface ( ifc# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to enable SQLSlam support on interface ( ifc# ) log

Unable to enable SQLSlam support on interface ( ifc# )

The system failed to enable the SQLSlam policy data on the specified interface.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, reset the stack, or use a different interface.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to enable SynFinScan support on interface (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to enable SynFinScan support on interface (%d) log

Unable to enable SynFinScan support on interface (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Unable to enable SynFinScan support on interface ( ifc# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to enable SynFinScan support on interface ( ifc# ) log

Unable to enable SynFinScan support on interface ( ifc# )

The system failed to enable the SynFinScan policy data on the specified interface.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, reset the stack, or use a different interface.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to enable Xmas support on interface (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to enable Xmas support on interface (%d) log

Unable to enable Xmas support on interface (%d)

The system failed to enable the Xmas policy data on the specified interface.

Source	Severity
QoS	Serious

### Remedial action

Check log for related details on the issue. Try again later, reset the QoS agent, reset the stack, or use a different interface.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to inform SPB of ifc assignment change (%d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to inform SPB of ifc assignment change (%d/%d) log

Unable to inform SPB of ifc assignment change (%d/%d)

SPB might not be aware of the current QoS interface type class of the specified interface.

Source	Severity
QoS	Critical

### Remedial action

Force a transition on the specified interface.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to inform SPB of ifc assignment change (%d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to inform SPB of ifc assignment change (%d/%d) log

Unable to inform SPB of ifc assignment change (%d/%d)

The information regarding an interface type class assigned to the identified port, failed to reach SPB.

Source	Severity
QoS Agent	Information

### Remedial action

If you are seeing this because of a QoS interface class modification and SPB is not used, the message can be ignored. Otherwise, a QoS class transition for the specified port forces the creation of a new message.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to install access assignment - component creation issue

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to install access assignment - component creation issue log

Unable to install access assignment - component creation issue

Unable to create many of the access assignment components like: base action, token bucket entry, count action, meter, policy.

Source	Severity
QoS	Serious

### Remedial action

Check for the available or not needed resources.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to install access element - component creation issue

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to install access element - component creation issue log

Unable to install access element - component creation issue

The Access element installation failed.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to locate corresponding DS L2 access elements

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to locate corresponding DS L2 access elements log

Unable to locate corresponding DS L2 access elements

The corresponding DS(IP)/L2 classifier(s) does not exist.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to locate corresponding DS/L2 access elements

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to locate corresponding DS/L2 access elements log

Unable to locate corresponding DS/L2 access elements

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Unable to manipulate DAPP support (no applicable interfaces)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to manipulate DAPP support (no applicable interfaces) log

Unable to manipulate DAPP support (no applicable interfaces)

The target interfaces data does not exist.

Source	Severity
QoS	Serious

### Remedial action

Enter an existing interface data.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to modify access assignment - component modify issue

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to modify access assignment - component modify issue log

Unable to modify access assignment - component modify issue

Unable to make changes as one of the modifications required for an access assignment component failed.

Source	Severity
QoS	Serious

### Remedial action

Check the log for a more detailed information on the issue. Try again later, reset the QoS agent, or reset the stack.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to relinquish FCoE resource reservations

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to relinquish FCoE resource reservations log

Unable to relinquish FCoE resource reservations

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to restore dynamic ifc to default role association (%d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to restore dynamic ifc to default role association (%d/%d) log

Unable to restore dynamic ifc to default role association (%d/%d)

The system failed to restore the interface to its pre-dynamic settings. Default was used because the original role does not exist any more.

Source	Severity
QoS	Warning

### Remedial action

Check the log for possible precedence conflict messages. Resolve conflicts and apply it manually.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to restore dynamic ifc to static role association (%d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to restore dynamic ifc to static role association (%d/%d) log

Unable to restore dynamic ifc to static role association (%d/%d)

The system failed to restore the interface to its pre-dynamic settings.

Source	Severity
QoS	Warning

### Remedial action

Check the log for possible precedence conflict messages. Resolve conflicts and apply it manually.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to update config in NVRAM - %s line %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to update config in NVRAM - %s line %d log

Unable to update config in NVRAM - %s line %d

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to validate metering data - request denied

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to validate metering data - request denied log

Unable to validate metering data - request denied

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unable to verify required filter criteria

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unable to verify required filter criteria log

Unable to verify required filter criteria

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Unauthorized connection attempt from IP address:

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unauthorized connection attempt from IP address: log

Unauthorized connection attempt from IP address:

**Source    Severity**

IPMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unexpected DB Ack, got %s from unit # %d, expected %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unexpected DB Ack, got %s from unit # %d, expected %s log

Unexpected DB Ack, got %s from unit # %d, expected %s

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# UNI already exists on the specified port and VLAN

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## UNI already exists on the specified port and VLAN log

UNI already exists on the specified port and VLAN

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unicast block unit/port %d/%d level %u watermark %u

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unicast block unit/port %d/%d level %u watermark %u log

Unicast block unit/port %d/%d level %u watermark %u

**Source**   **Severity**

SC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unicast block unit port unit\_port level level watermark watermark

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unicast block unit port unit\_port level level watermark watermark log

Unicast block unit port unit\_port level level watermark watermark

Unicast blocking is enabled on the indicated port as it reached the high water mark level.

Source	Severity
port driver	Information

### Remedial action

Investigate the cause of the unicast storm to ensure optimal network performance.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unicast (%d) and Non-Unicast (%d) interfaces in conflict

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unicast (%d) and Non-Unicast (%d) interfaces in conflict log

Unicast (%d) and Non-Unicast (%d) interfaces in conflict

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unicast ( Interface# ) and Non-Unicast ( interface# ) interfaces in conflict

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unicast ( Interface# ) and Non-Unicast ( interface# ) interfaces in conflict log

Unicast ( Interface# ) and Non-Unicast ( interface# ) interfaces in conflict

The interface number for unicast and non-unicast does not correspond.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Enter the same interface/port number.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unicast over high watermark unit/port %d/%d level %u watermark %u

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unicast over high watermark unit/port %d/%d level %u watermark %u log

Unicast over high watermark unit/port %d/%d level %u watermark %u

**Source**   **Severity**

SC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Unicast still blocked unit/port %d/%d level %u watermark %u

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unicast still blocked unit/port %d/%d level %u watermark %u log

Unicast still blocked unit/port %d/%d level %u watermark %u

**Source   Severity**

SC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unicast still over low watermark unit/port %d/%d level %u watermark %u

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unicast still over low watermark unit/port %d/%d level %u watermark %u log

Unicast still over low watermark unit/port %d/%d level %u watermark %u

**Source**   **Severity**  
SC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unicast unblock unit/port %d/%d level %u watermark %u

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unicast unblock unit/port %d/%d level %u watermark %u log

Unicast unblock unit/port %d/%d level %u watermark %u

**Source**   **Severity**

SC

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unicast unblock unit port unit\_port level level watermark watermark

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unicast unblock unit port unit\_port level level watermark watermark log

Unicast unblock unit port unit\_port level level watermark watermark

Unicast blocking is disabled on the indicated port as it reached below the high water mark level.

Source	Severity
port driver	Information

### Remedial action

No action required.



# Unicast under low watermark unit/port %d/%d level %u watermark %u

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unicast under low watermark unit/port %d/%d level %u watermark %u log

Unicast under low watermark unit/port %d/%d level %u watermark %u

Source	Severity
SC	

Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unit # %d already deleted from this unit's database

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unit # %d already deleted from this unit's database log

Unit # %d already deleted from this unit's database

**Source    Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unit # %d link down on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unit # %d link down on %s log

Unit # %d link down on %s

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unit # %d link up on %s

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unit # %d link up on %s log

Unit # %d link up on %s

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Unknown access assignment entry specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown access assignment entry specified (%d) log

Unknown access assignment entry specified (%d)

Internal QPA error, the access assignment entry does not exist.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent, or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown access element entry specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown access element entry specified (%d) log

Unknown access element entry specified (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown access element entry specified ( entry# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown access element entry specified ( entry# ) log

Unknown access element entry specified ( entry# )

The system detected an internal QPA error; The count action entry does not exist.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent, or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown action entry specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown action entry specified (%d) log

Unknown action entry specified (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown action entry specified ( entry# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown action entry specified ( entry# ) log

Unknown action entry specified ( entry# )

The system detected an internal QPA error; the action entry does not exist.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent, or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown classifier block entry specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown classifier block entry specified (%d) log

Unknown classifier block entry specified (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown classifier block entry specified ( entry# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown classifier block entry specified ( entry# ) log

Unknown classifier block entry specified ( entry# )

The system detected an internal QPA error; The classifier component entry does not exist.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent, or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown classifier component entry specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown classifier component entry specified (%d) log

Unknown classifier component entry specified (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Unknown classifier component entry specified ( entry# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown classifier component entry specified ( entry# ) log

Unknown classifier component entry specified ( entry# )

The system detected an internal QPA error; The classifier component entry does not exist.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent, or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown CoS shaping entry specified (%d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown CoS shaping entry specified (%d/%d) log

Unknown CoS shaping entry specified (%d/%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown CoS shaping entry specified ( entry# CoS )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown CoS shaping entry specified ( entry# CoS ) log

Unknown CoS shaping entry specified ( entry# CoS )

The system detected an Internal QPA error; The interface shaping entry does not exist.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent, or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown count action entry specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown count action entry specified (%d) log

Unknown count action entry specified (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown count action entry specified ( entry# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown count action entry specified ( entry# ) log

Unknown count action entry specified ( entry# )

The system detected an internal QPA error; The count action entry does not exist.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent, or reset the unit.



# Unknown DSCP mapping entry specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown DSCP mapping entry specified (%d) log

Unknown DSCP mapping entry specified (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown DSCP mapping entry specified ( entry# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown DSCP mapping entry specified ( entry# ) log

Unknown DSCP mapping entry specified ( entry# )

The system detected an internal QPA error; The DSCP mapping entry does not exist.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent, or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown entry (class class# ) specified ( entry# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown entry (class class# ) specified ( entry# ) log

Unknown entry (class class# ) specified ( entry# )

The system detected an internal QPA error; The specified entry does not exist.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent, or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Unknown entry (class %d) specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown entry (class %d) specified (%d) log

Unknown entry (class %d) specified (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown FCoE redirection entry specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown FCoE redirection entry specified (%d) log

Unknown FCoE redirection entry specified (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown incompatible access element specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown incompatible access element specified log

Unknown incompatible access element specified

The access element specified does not exist or the storage type is not compatible.

Source	Severity
QoS	Serious

### Remedial action

Specify a compatible access element.



# Unknown/incompatible access element specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown/incompatible access element specified log

Unknown/incompatible access element specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown incompatible action component specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown incompatible action component specified log

Unknown incompatible action component specified

Specified action doesn't exist or it's system/agent entry.

Source	Severity
QoS	Serious

### Remedial action

Enter an existing action or create a new one.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown/incompatible action component specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown/incompatible action component specified log

Unknown/incompatible action component specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown incompatible classifier block specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown incompatible classifier block specified log

Unknown incompatible classifier block specified

The classifier block does not exist.

Source	Severity
QoS	Serious

### Remedial action

Enter an existing classifier block or create a new one.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown/incompatible classifier block specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown/incompatible classifier block specified log

Unknown/incompatible classifier block specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Unknown incompatible classifier set specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown incompatible classifier set specified log

Unknown incompatible classifier set specified

The specified classifier set does not exist.

Source	Severity
QoS	Serious

### Remedial action

Enter an existing classifier set or create a new one.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown/incompatible classifier set specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown/incompatible classifier set specified log

Unknown/incompatible classifier set specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown incompatible in-profile action specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown incompatible in-profile action specified log

Unknown incompatible in-profile action specified

The in-profile action specified is unknown or incompatible.

Source	Severity
QoS	Serious

### Remedial action

Check log for other possible details on the issue. Verify that the in-profile action exists and is compatible with the entry.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown/incompatible in-profile action specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown/incompatible in-profile action specified log

Unknown/incompatible in-profile action specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown incompatible in-profile (green) action specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown incompatible in-profile (green) action specified log

Unknown incompatible in-profile (green) action specified

Action criteria or storage type is not compatible with the action criteria type specified (in-profile green).

Source	Severity
QoS	Serious

### Remedial action

Enter a compatible in-profile action.



# Unknown/incompatible in-profile (green) action specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown/incompatible in-profile (green) action specified log

Unknown/incompatible in-profile (green) action specified

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown incompatible match action specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown incompatible match action specified log

Unknown incompatible match action specified

The specified action does not exist.

Source	Severity
QoS	Serious

### Remedial action

Enter an existing action or create a new one.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown/incompatible match action specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown/incompatible match action specified log

Unknown/incompatible match action specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Unknown incompatible metering component specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown incompatible metering component specified log

Unknown incompatible metering component specified

The metering component is unknown or not compatible.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Verify that the metering component exists and also that the storage types of the entries are compatible.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown/incompatible metering component specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown/incompatible metering component specified log

Unknown/incompatible metering component specified

**Source   Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown incompatible metering statistics entry specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown incompatible metering statistics entry specified log

Unknown incompatible metering statistics entry specified

Unknown or incompatible statistics with policy storage type.

Source	Severity
QoS	Serious

### Remedial action

Enter different statistics type.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown/incompatible metering statistics entry specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown/incompatible metering statistics entry specified log

Unknown/incompatible metering statistics entry specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown incompatible out-of-profile action specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown incompatible out-of-profile action specified log

Unknown incompatible out-of-profile action specified

The out-of-profile action specified is unknown or incompatible.

Source	Severity
QoS	Serious

### Remedial action

Check log for other possible details on the issue. Verify that the out-of-profile action exists and is compatible with the entry.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown/incompatible out-of-profile action specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown/incompatible out-of-profile action specified log

Unknown/incompatible out-of-profile action specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown incompatible out-of-profile (red) action specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown incompatible out-of-profile (red) action specified log

Unknown incompatible out-of-profile (red) action specified

Action criteria or storage type is not compatible with the action criteria type specified (out-of-profile red).

Source	Severity
QoS	Serious

### Remedial action

Enter a compatible out-of-profile action.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown/incompatible out-of-profile (red) action specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown/incompatible out-of-profile (red) action specified log

Unknown/incompatible out-of-profile (red) action specified

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Unknown incompatible out-of-profile (yellow) action specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown incompatible out-of-profile (yellow) action specified log

Unknown incompatible out-of-profile (yellow) action specified

Action criteria or storage type is not compatible with the action criteria type specified (out-of-profile yellow).

Source	Severity
QoS	Serious

### Remedial action

Enter a compatible out-of-profile action.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown/incompatible out-of-profile (yellow) action specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown/incompatible out-of-profile (yellow) action specified log

Unknown/incompatible out-of-profile (yellow) action specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown incompatible policy non-match action specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown incompatible policy non-match action specified log

Unknown incompatible policy non-match action specified

The specified non-match action does not exist.

Source	Severity
QoS	Serious

### Remedial action

Enter an existing non-match action or create a new one.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown/incompatible policy non-match action specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown/incompatible policy non-match action specified log

Unknown/incompatible policy non-match action specified

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown incompatible policy statistics entry specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown incompatible policy statistics entry specified log

Unknown incompatible policy statistics entry specified

Unknown or incompatible statistics with policy storage type.

Source	Severity
QoS	Serious

### Remedial action

Enter different statistics type.



# Unknown/incompatible policy statistics entry specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown/incompatible policy statistics entry specified log

Unknown/incompatible policy statistics entry specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown incompatible queue set specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown incompatible queue set specified log

Unknown incompatible queue set specified

The queue set specified is unknown.

Source	Severity
QoS	Serious

### Remedial action

Use an existing queue set.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown/incompatible queue set specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown/incompatible queue set specified log

Unknown/incompatible queue set specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Unknown incompatible role combination specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown incompatible role combination specified log

Unknown incompatible role combination specified

Referenced role must exist/be stable prior to entry creation/modification.

Source	Severity
QoS	Serious

### Remedial action

Make sure the role combination exists or create a new one.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown/incompatible role combination specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown/incompatible role combination specified log

Unknown/incompatible role combination specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown incompatible token bucket reference specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown incompatible token bucket reference specified log

Unknown incompatible token bucket reference specified

Referenced token bucket not found.

Source	Severity
QoS	Critical

### Remedial action

Enter an existing/compatible token bucket.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown incompatible token bucket reference specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown incompatible token bucket reference specified log

Unknown incompatible token bucket reference specified

The token bucket specified is not valid.

Source	Severity
QoS	Serious

### Remedial action

Check the documentation and use a valid token bucket.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown/incompatible token bucket reference specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown/incompatible token bucket reference specified log

Unknown/incompatible token bucket reference specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown interface application entry specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown interface application entry specified (%d) log

Unknown interface application entry specified (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown interface application entry specified ( entry# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown interface application entry specified ( entry# ) log

Unknown interface application entry specified ( entry# )

The system detected an internal QPA error; The interface application entry does not exist.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent, or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown interface assignment entry specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown interface assignment entry specified (%d) log

Unknown interface assignment entry specified (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Unknown interface assignment entry specified ( entry# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown interface assignment entry specified ( entry# ) log

Unknown interface assignment entry specified ( entry# )

The system detected an internal QPA error; The interface assignment entry does not exist.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown interface queue entry specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown interface queue entry specified (%d) log

Unknown interface queue entry specified (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown interface queue entry specified ( ifc queue id )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown interface queue entry specified ( ifc queue id ) log

Unknown interface queue entry specified ( ifc queue id )

The system detected an internal QPA error; The interface queue entry does not exist.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown interface shaping entry specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown interface shaping entry specified (%d) log

Unknown interface shaping entry specified (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown interface shaping entry specified ( entry# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown interface shaping entry specified ( entry# ) log

Unknown interface shaping entry specified ( entry# )

The system detected an internal QPA error; The interface shaping entry does not exist.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.



# Unknown IP classifier entry specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown IP classifier entry specified (%d) log

Unknown IP classifier entry specified (%d)

The system detected an internal QPA error; The IP classifier does not exist.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.



# Unknown Layer 2 classifier entry specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown Layer 2 classifier entry specified (%d) log

Unknown Layer 2 classifier entry specified (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown Layer 2 classifier entry specified ( entry# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown Layer 2 classifier entry specified ( entry# ) log

Unknown Layer 2 classifier entry specified ( entry# )

The system detected an internal QPA error; The I2 classifier does not exist.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Unknown meter entry specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown meter entry specified (%d) log

Unknown meter entry specified (%d)

The system detected an internal QPA error; The meter component entry does not exist.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown/out-of-range interface index value (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown/out-of-range interface index value (%d) log

Unknown/out-of-range interface index value (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown out-of-range interface index value ( ifc# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown out-of-range interface index value ( ifc# ) log

Unknown out-of-range interface index value ( ifc# )

The interface index does not exist.

Source	Severity
QoS	Serious

### Remedial action

Check the platform's/stack's port range and use a valid interface index.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown out-of-range interface index value ( ifc index )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown out-of-range interface index value ( ifc index ) log

Unknown out-of-range interface index value ( ifc index )

The interface index does not exist.

Source	Severity
QoS	Serious

### Remedial action

Check the port range of the platform or the stack, and use a valid interface index.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown policy entry specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown policy entry specified (%d) log

Unknown policy entry specified (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown policy entry specified ( entry# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown policy entry specified ( entry# ) log

Unknown policy entry specified ( entry# )

The system detected an internal QPA error; The classifier component entry does not exist.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown 802.1p user priority mapping entry specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown 802.1p user priority mapping entry specified (%d) log

Unknown 802.1p user priority mapping entry specified (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown 802.1p user priority mapping entry specified ( entry# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown 802.1p user priority mapping entry specified ( entry# ) log

Unknown 802.1p user priority mapping entry specified ( entry# )

The system detected an internal QPA error; The 802.1p user priority mapping entry does not exist.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent, or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Unknown queue set assignment entry specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown queue set assignment entry specified (%d) log

Unknown queue set assignment entry specified (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown queue set assignment entry specified ( entry# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown queue set assignment entry specified ( entry# ) log

Unknown queue set assignment entry specified ( entry# )

The system detected an internal QPA error; The queue set does not exist.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown queue set queue reference detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown queue set queue reference detected log

Unknown queue set queue reference detected

The specified queue (set) does not exist.

Source	Severity
QoS	Serious

### Remedial action

Enter an existing queue/queue set.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown queue set/queue reference detected

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown queue set/queue reference detected log

Unknown queue set/queue reference detected

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown queue shaping entry specified (%d/%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown queue shaping entry specified (%d/%d) log

Unknown queue shaping entry specified (%d/%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown queue shaping entry specified ( entry# queue )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown queue shaping entry specified ( entry# queue ) log

Unknown queue shaping entry specified ( entry# queue )

The system detected an internal QPA error; The count action entry does not exist.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown role combination entry specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown role combination entry specified (%d) log

Unknown role combination entry specified (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown role combination entry specified ( role comb id )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown role combination entry specified ( role comb id ) log

Unknown role combination entry specified ( role comb id )

The system detected an internal QPA error; The role combination entry does not exist.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Unknown System classifier entry specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown System classifier entry specified (%d) log

Unknown System classifier entry specified (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown System classifier entry specified ( entry# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown System classifier entry specified ( entry# ) log

Unknown System classifier entry specified ( entry# )

The system detected an Internal QPA error; the system classifier does not exist.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown token bucket entry specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown token bucket entry specified (%d) log

Unknown token bucket entry specified (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown token bucket entry specified ( entry# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown token bucket entry specified ( entry# ) log

Unknown token bucket entry specified ( entry# )

The system detected an internal QPA error; The token bucket does not exist.

Source	Severity
--------	----------

QoS	Critical
-----	----------

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown unsupported attribute specified ( attribute )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown unsupported attribute specified ( attribute ) log

Unknown unsupported attribute specified ( attribute )

The specified attribute is not supported or unknown for the class you are trying to configure an entry

Source	Severity
QoS	Information

### Remedial action

Check the documentation if necessary and use a supported attribute for that QoS class.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown/unsupported attribute specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown/unsupported attribute specified (%d) log

Unknown/unsupported attribute specified (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown unsupported interface application type specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown unsupported interface application type specified log

Unknown unsupported interface application type specified

The interface application type provided is unknown or unsupported.

Source	Severity
QoS	Serious

### Remedial action

Check documentation and use a valid interface application type.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown/unsupported interface application type specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown/unsupported interface application type specified log

Unknown/unsupported interface application type specified

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Unknown/unsupported interface class specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown/unsupported interface class specified (%d) log

Unknown/unsupported interface class specified (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown unsupported interface class specified ( ifc class )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown unsupported interface class specified ( ifc class ) log

Unknown unsupported interface class specified ( ifc class )

The valid interface classes are trusted, untrusted and unrestricted.

Source	Severity
QoS	Serious

### Remedial action

Enter a valid/supported interface class.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown unsupported IP Flag specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown unsupported IP Flag specified log

Unknown unsupported IP Flag specified

The specified IP Flag is not supported.

Source	Severity
QoS	Serious

### Remedial action

Check documentation if necessary and enter a valid IP Flag.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown/unsupported IP Flag specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown/unsupported IP Flag specified log

Unknown/unsupported IP Flag specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown unsupported RowStatus specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown unsupported RowStatus specified log

Unknown unsupported RowStatus specified

The status is unknown or unsupported for the current entry. Valid statuses are (the supported ones depend on the QoS component): active, create and go, create and wait, destroy, not in service, not ready.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown/unsupported RowStatus specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown/unsupported RowStatus specified log

Unknown/unsupported RowStatus specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown unsupported StorageType specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown unsupported StorageType specified log

Unknown unsupported StorageType specified

The supported storage types are: volatile, non-volatile, permanent, read-only and other. Also, take into account that certain actions/entries require certain storage types.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Check the documentation if necessary and use a compatible/valid storage type.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown/unsupported StorageType specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown/unsupported StorageType specified log

Unknown/unsupported StorageType specified

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Unknown unsupported TCP Control Flag specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown unsupported TCP Control Flag specified log

Unknown unsupported TCP Control Flag specified

The specified TCP Control Flag is not supported.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Check documentation if necessary and enter a valid TCP Control Flag.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown/unsupported TCP Control Flag specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown/unsupported TCP Control Flag specified log

Unknown/unsupported TCP Control Flag specified

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown user policy entry specified (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown user policy entry specified (%d) log

Unknown user policy entry specified (%d)

**Source    Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unknown user policy entry specified ( entry# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unknown user policy entry specified ( entry# ) log

Unknown user policy entry specified ( entry# )

The system detected an internal QPA error; The user policy entry does not exist.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent, or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unsupported field for ACL in dynamic CoA UBP

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unsupported field for ACL in dynamic CoA UBP log

Unsupported field for ACL in dynamic CoA UBP

An unsupported field for dynamic UBP creation came in a RADIUS provided ACL for CoA, or the field contains a wrong or unsupported value.

Source	Severity
EAP	Warning

### Remedial action

Check the settings on the RADIUS server.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Unsupported field for ACL in dynamic  
UBP, port %s, MAC  
%02x:%02x:%02x:%02x:%02x:%02x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unsupported field for ACL in dynamic UBP, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x log

Unsupported field for ACL in dynamic UBP, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x

RADIUS provided ACL contains an unsupported or wrongfully set field for the dynamic creation of a UBP.

Source	Severity
EAP	Warning

### Remedial action

Check the settings on the RADIUS server.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unsupported field for SET in dynamic CoA UBP

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unsupported field for SET in dynamic CoA UBP log

Unsupported field for SET in dynamic CoA UBP

An unsupported field for dynamic UBP creation came in a RADIUS provided SET for CoA.

Source	Severity
EAP	Warning

### Remedial action

Check the settings on the RADIUS server.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Unsupported field for SET in dynamic  
UBP, port %s, MAC  
%02x:%02x:%02x:%02x:%02x:%02x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unsupported field for SET in dynamic UBP, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x log

Unsupported field for SET in dynamic UBP, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x

An unsupported field for dynamic UBP creation came in a RADIUS provided SET.

Source	Severity
EAP	Warning

### Remedial action

Check the settings on the RADIUS server.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Unsupported IP address type specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unsupported IP address type specified log

Unsupported IP address type specified

Unsupported address type provided. (It should not get here) Internal error.

Source	Severity
QoS	Serious

### Remedial action

Enter a ipv4 or ipv6 address.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unsupported IPv4 Options value specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unsupported IPv4 Options value specified log

Unsupported IPv4 Options value specified

Invalid IPv4 option detected.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unsupported pattern offset data specified

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unsupported pattern offset data specified log

Unsupported pattern offset data specified

Position data and pattern data cannot be processed correctly into an appropriate mask.

Source	Severity
QoS	Serious

### Remedial action

Change or separate the pattern data into multiple system classifiers.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unsupported unknown QoS agent configuration attribute ( attribute# )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unsupported unknown QoS agent configuration attribute ( attribute# ) log

Unsupported unknown QoS agent configuration attribute ( attribute# )

The attribute you are trying to configure is not supported/recognized by the QoS agent.

Source	Severity
QoS	Serious

### Remedial action

Remove the attribute.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unsupported/unknown QoS agent configuration attribute (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unsupported/unknown QoS agent configuration attribute (%d) log

Unsupported/unknown QoS agent configuration attribute (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unsupported value for ACL field in dynamic CoA UBP

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unsupported value for ACL field in dynamic CoA UBP log

Unsupported value for ACL field in dynamic CoA UBP

A supported field for dynamic UBP creation that came in a RADIUS provided ACL for CoA contains a wrong or unsupported value.

Source	Severity
--------	----------

EAP	Warning
-----	---------

### Remedial action

Check the settings on the RADIUS server.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Unsupported value for ACL field in  
dynamic UBP, port %s, MAC  
%02x:%02x:%02x:%02x:%02x:%02x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unsupported value for ACL field in dynamic UBP, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x log

Unsupported value for ACL field in dynamic UBP, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x

A supported field for dynamic UBP creation that came in a RADIUS provided ACL contains a wrong or unsupported value.

Source	Severity
EAP	Warning

### Remedial action

Check the settings on the RADIUS server.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Unsupported value for SET field in dynamic CoA UBP

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unsupported value for SET field in dynamic CoA UBP log

Unsupported value for SET field in dynamic CoA UBP

A supported field for dynamic UBP creation that came in a RADIUS provided SET for CoA contains a wrong or unsupported value.

Source	Severity
--------	----------

EAP	Warning
-----	---------

### Remedial action

Check the settings on the RADIUS server.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





Unsupported value for SET field in  
dynamic UBP, port %s, MAC  
%02x:%02x:%02x:%02x:%02x:%02x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Unsupported value for SET field in dynamic UBP, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x log

Unsupported value for SET field in dynamic UBP, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x

A supported field for dynamic UBP creation that came in a RADIUS provided SET contains a wrong or unsupported value.

Source	Severity
EAP	Warning

### Remedial action

Check the settings on the RADIUS server.



# Update priority value and update DSCP value out-of-sync

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Update priority value and update DSCP value out-of-sync log

Update priority value and update DSCP value out-of-sync

If the priority update is set to be done based on DSCP-to-user priority map (egressmap) the DSCP value must be specified.

Source	Severity
QoS	Serious

### Remedial action

Change the update priority type or specify a DSCP value.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Update priority value per ingress DSCP currently not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Update priority value per ingress DSCP currently not supported log

Update priority value per ingress DSCP currently not supported

Priority update based on 802.1p priority-to-DSCP map (ingressmap) is not currently supported.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Change the update priority type.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Upstream direction is logically down

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Upstream direction is logically down log

Upstream direction is logically down

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Upstream direction is logically up

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Upstream direction is logically up log

Upstream direction is logically up

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Upstream Port #%u is unexpectedly logically up

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Upstream Port #%u is unexpectedly logically up log

Upstream Port #%u is unexpectedly logically up

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Upstream stack direction is down cable removed or neighbor powered off

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Upstream stack direction is down cable removed or neighbor powered off log

Upstream stack direction is down cable removed or neighbor powered off

The upstream stack direction is down, cable removed or neighbor powered off.

Source	Severity
Hello Module	Information

### Remedial action

Connect the upstream port to the downstream port of the neighbor. Also check if the neighbor is powered on.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Upstream stack direction is down, cable removed or neighbor powered off

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Upstream stack direction is down, cable removed or neighbor powered off log

Upstream stack direction is down, cable removed or neighbor powered off

Source	Severity
HMOD	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Upstream stack direction is misconfigured

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Upstream stack direction is misconfigured log

Upstream stack direction is misconfigured

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Upstream stack direction is mis-configured

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Upstream stack direction is mis-configured log

Upstream stack direction is mis-configured

This message appears when an upstream port is mis-configured.

Source	Severity
Hello Module	Information

### Remedial action

Connect the upstream port to the downstream port of the neighbor.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Upstream stack direction is up, cable inserted or neighbor powered on

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Upstream stack direction is up, cable inserted or neighbor powered on log

Upstream stack direction is up, cable inserted or neighbor powered on

Source	Severity
HMOD	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Upstream stack ports down, wait for stack ports before processing

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Upstream stack ports down, wait for stack ports before processing log

Upstream stack ports down, wait for stack ports before processing

**Source**   **Severity**  
SMGR

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Upstream Stack Port #%u is logically down

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Upstream Stack Port #%u is logically down log

Upstream Stack Port #%u is logically down

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Upstream Stack Port # %u is logically up

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Upstream Stack Port # %u is logically up log

Upstream Stack Port # %u is logically up

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Upstream stack port %u is misconfigured

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Upstream stack port %u is misconfigured log

Upstream stack port %u is misconfigured

**Source**   **Severity**

HMOD

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# USB device inserted

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## USB device inserted log

USB device inserted

A USB memory stick has been inserted in the unit.

Source	Severity
USB	Information

### Remedial action

No action required.





# USB device removed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## USB device removed log

USB device removed

A USB memory stick has been removed from the unit.

Source	Severity
USB	Information

### Remedial action

No action required.



# USB nvRam file error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## USB nvRam file error log

USB nvRam file error

**Source**   **Severity**

USB

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# USB unsupported file system

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## USB unsupported file system log

USB unsupported file system

**Source**   **Severity**

USB

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# USC Install SET fail unit port unit\_port status = status

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## USC Install SET fail unit port unit\_port status = status log

USC Install SET fail unit port unit\_port status = status

Installation of the Unicast Storm Control filter during set phase failed for the indicated port.

Source	Severity
port driver	Information

### Remedial action

Verify that the hardware filter resources are available for the indicated port. Current hardware filter resource usage can be displayed through the 'show qos diag' command. You may need to disable other applications currently using hardware filter resources in order to free them up for the Unicast Storm Control application.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# USC Install TEST fail unit port unit\_port status = status

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## USC Install TEST fail unit port unit\_port status = status log

USC Install TEST fail unit port unit\_port status = status

Installation of the Unicast Storm Control filter during test phase failed for the indicated port.

Source	Severity
port driver	Information

### Remedial action

Verify the hardware filter resources are available for the indicated port. Current hardware filter resource usage can be displayed through the 'show qos diag' command. You may need to disable other applications currently using hardware filter resources in order to free them up for the Unicast Storm Control application.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# USC UnInst SET failed for port port status = status

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## USC UnInst SET failed for port port status = status log

USC UnInst SET failed for port port status = status

The Unicast Storm Control filter could not be uninstalled during the set phase for the indicated port.

Source	Severity
port driver	Information

### Remedial action

Verify the hardware filter resources have been un-installed for the Unicast Storm Control application. If not, reboot it to successfully remove any hardware filter resources that are still attached to the Unicast Storm Control application.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Used stack size of task %s is (%d%%).

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Used stack size of task %s is (%d%%). log

Used stack size of task %s is (%d%%).

The used stack size of the specified task has the specified value.

### Source

System Logging

### Severity

Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# User allowed (fallback authentication) to log in from Web from Src IP

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## User allowed (fallback authentication) to log in from Web from Src IP log

User allowed (fallback authentication) to log in from Web from Src IP

Source	Severity
WEB	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# User allowed (radius authentication pass) to log in from Web from Src IP

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## User allowed (radius authentication pass) to log in from Web from Src IP log

User allowed (radius authentication pass) to log in from Web from Src IP

Client from the indicated IP address has been authenticated successfully through the Radius server.

Source	Severity
WEB	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# User allowed (radius authentication pass) to log in from Web from Src IP

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## User allowed (radius authentication pass) to log in from Web from Src IP log

User allowed (radius authentication pass) to log in from Web from Src IP

Source	Severity
WEB	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# User disallowed (radius authentication fail) to log in from Web from Src IP

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## User disallowed (radius authentication fail) to log in from Web from Src IP log

User disallowed (radius authentication fail) to log in from Web from Src IP

Client from the indicated IP address has failed authentication through the Radius server.

Source	Severity
WEB	Information

### Remedial action

Provide the correct username and password to gain access.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# User Policy data referencing interface (operation prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## User Policy data referencing interface (operation prohibited) log

User Policy data referencing interface (operation prohibited)

There are non-QoS applications that have created entries that reference this interface.

Source	Severity
QoS	Serious

### Remedial action

Remove all references before performing other operations.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# User policy distribution across stack failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## User policy distribution across stack failed log

User policy distribution across stack failed

Unable to commit user policy distribution across the stack.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# User policy filter set count (%d) exceeds limit (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## User policy filter set count (%d) exceeds limit (%d) log

User policy filter set count (%d) exceeds limit (%d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# User policy filter set count (<set count>) exceeds limit (<set limit>)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## User policy filter set count (<set count>) exceeds limit (<set limit>) log

User policy filter set count (<set count>) exceeds limit (<set limit>)

The user policy filter set limit depends on the target hardware platform.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Check documentation for the maximum number of user policy filter sets allowed.



# User policy filter set delete operation failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## User policy filter set delete operation failed log

User policy filter set delete operation failed

Unable to carry out the update operation on the policy filter set across the stack.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# User policy filter set element count exceeds available resources

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## User policy filter set element count exceeds available resources log

User policy filter set element count exceeds available resources

The policy filter set element count limit depends on the target hardware platform.

Source	Severity
QoS	Serious

### Remedial action

Check the documentation for the maximum number of policy filter set elements allowed.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# User policy filter set install operation failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## User policy filter set install operation failed log

User policy filter set install operation failed

Unable to carry out the update operation on the policy filter set across the stack.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# User policy filter set update operation failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## User policy filter set update operation failed log

User policy filter set update operation failed

Unable to carry out the update operation on the policy filter set across the stack.

Source	Severity
QoS	Information

### Remedial action

Try later or check the stack health.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# User policy group contains invalid unacceptable characters

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## User policy group contains invalid unacceptable characters log

User policy group contains invalid unacceptable characters

Only printable characters are allowed.

Source	Severity
QoS	Serious

### Remedial action

Enter valid characters for the policy group.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# User policy group contains invalid/unacceptable characters

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## User policy group contains invalid/unacceptable characters log

User policy group contains invalid/unacceptable characters

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# User policy group length outside of acceptable limits

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## User policy group length outside of acceptable limits log

User policy group length outside of acceptable limits

The maximum user policy group length is 64.

Source	Severity
QoS	Serious

### Remedial action

Separate the entries into multiple policy groups.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# User policy modifications not supported

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## User policy modifications not supported log

User policy modifications not supported

The system detected an internal error; The specified modifier option not supported.

Source	Severity
QoS	Critical

### Remedial action

Try again later, reset the QoS agent, or reset the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# User policy name contains invalid unacceptable characters

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## User policy name contains invalid unacceptable characters log

User policy name contains invalid unacceptable characters

Only printable characters are allowed.

Source	Severity
QoS	Serious

### Remedial action

Enter valid characters for the policy label.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# User policy name contains invalid/unacceptable characters

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## User policy name contains invalid/unacceptable characters log

User policy name contains invalid/unacceptable characters

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# User policy name length outside of acceptable limits

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## User policy name length outside of acceptable limits log

User policy name length outside of acceptable limits

The maximum length for a policy name is 64.

Source	Severity
QoS	Serious

### Remedial action

Enter a policy name within the specified limit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# User Policy (UBP) filter set in use (QoS disable prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## User Policy (UBP) filter set in use (QoS disable prohibited) log

User Policy (UBP) filter set in use (QoS disable prohibited)

Cannot disable the QoS system if there still are user policies in use.

Source	Severity
QoS	Serious

### Remedial action

Remove the user policies first.



# User Policy (UBP) filter set in use (QoS reset prohibited)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## User Policy (UBP) filter set in use (QoS reset prohibited) log

User Policy (UBP) filter set in use (QoS reset prohibited)

Cannot reset the QoS engine if the user policy filter sets are still in use.

Source	Severity
QoS	Serious

### Remedial action

Remove or disable the user policy filter sets before re-setting the QoS engine.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# User priority specified with untagged frames (invalid)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## User priority specified with untagged frames (invalid) log

User priority specified with untagged frames (invalid)

User priority appears in tagged frames.

Source	Severity
QoS	Serious

### Remedial action

Drop either priority or untagged option.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLACP: API error: %d-%d-%d.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLACP: API error: %d-%d-%d. log

VLACP: API error: %d-%d-%d.

**Source    Severity**

VLACP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLACP: input parameter error: %d-%d-%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLACP: input parameter error: %d-%d-%d log

VLACP: input parameter error: %d-%d-%d

**Source**   **Severity**

VLACP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLACP: msgQ error: %d-%d-%d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLACP: msgQ error: %d-%d-%d log

VLACP: msgQ error: %d-%d-%d

**Source**   **Severity**

VLACP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# VLACP: nvRam file error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLACP: nvRam file error log

VLACP: nvRam file error

**Source**   **Severity**

VLACP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLACP: RX event: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLACP: RX event: %d - %d - %d log

VLACP: RX event: %d - %d - %d

**Source**   **Severity**

VLACP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLACP: Stack event: %d - %d - 0x%x

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLACP: Stack event: %d - %d - 0x%x log

VLACP: Stack event: %d - %d - 0x%x

**Source    Severity**

VLACP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLACP: Start

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLACP: Start log

VLACP: Start

**Source**   **Severity**

VLACP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLACP: TMR event: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLACP: TMR event: %d - %d - %d log

VLACP: TMR event: %d - %d - %d

**Source**   **Severity**

VLACP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLACP: TX event: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLACP: TX event: %d - %d - %d log

VLACP: TX event: %d - %d - %d

**Source**   **Severity**

VLACP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLACP: vlacp\_log\_link\_change: %d - %d - %d

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLACP: vlacp\_log\_link\_change: %d - %d - %d log

VLACP: vlacp\_log\_link\_change: %d - %d - %d

**Source**   **Severity**

VLACP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLAN cannot re-assign

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN cannot re-assign log

VLAN cannot re-assign

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# VLAN configuration does not match BU VLAN configuration.DIFF\_MASK=

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN configuration does not match BU VLAN configuration.DIFF\_MASK= log

VLAN configuration does not match BU VLAN configuration.DIFF\_MASK=

**Source**   **Severity**

VLAN

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



VLAN configuration does not match BU  
VLAN configuration. VLAN config  
defaulted

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN configuration does not match BU VLAN configuration. VLAN config defaulted log

VLAN configuration does not match BU VLAN configuration. VLAN config defaulted

VLAN configuration was defaulted because the current VLAN configuration does not match the Base Unit VLAN configuration.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



VLAN configuration does not match BU  
VLAN configuration. VLAN config  
defaulted

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN configuration does not match BU VLAN configuration. VLAN config defaulted log

VLAN configuration does not match BU VLAN configuration. VLAN config defaulted

This Non-Base Unit has the same number of VLANs as the Base Unit, but it has a different VLAN configuration than the Base Unit at dbexchange point.

Source	Severity
VLAN	Information

### Remedial action

Reconfigure the port settings for this Non-Base Unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLAN does not exist

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN does not exist log

VLAN does not exist

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLAN ID min/max values invalid (%d !< %d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN ID min/max values invalid (%d !< %d) log

VLAN ID min/max values invalid (%d !< %d)

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLAN ID min max values invalid ( min VLAN ID ! max VLAN ID )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN ID min max values invalid ( min VLAN ID ! max VLAN ID ) log

VLAN ID min max values invalid ( min VLAN ID ! max VLAN ID )

Max VLAN ID value must be bigger than min value.

Source	Severity
--------	----------

QoS	Serious
-----	---------

### Remedial action

Correct the VLAN ID range limits.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLAN IMC callback failed

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN IMC callback failed log

VLAN IMC callback failed

There was an error when sending VLAN configuration to stack.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLAN IMC was not sent

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN IMC was not sent log

VLAN IMC was not sent

There was an error when sending VLAN configuration to stack.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Vlan is already a RSPAN vlan

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Vlan is already a RSPAN vlan log

Vlan is already a RSPAN vlan

If a VLAN is of type RSPAN it cannot be a C-VLAN.

Source	Severity
SPB	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLAN is configured as C-VLAN

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN is configured as C-VLAN log

VLAN is configured as C-VLAN

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLAN is configured as switched UNI

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN is configured as switched UNI log

VLAN is configured as switched UNI

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLAN is not switched UNI

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN is not switched UNI log

VLAN is not switched UNI

Source	Severity
ISIS	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLAN NVRAM read error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN NVRAM read error log

VLAN NVRAM read error

There was an error when reading the VLAN configuration from NVRAM.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLAN NVRAM read error

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN NVRAM read error log

VLAN NVRAM read error

Error at NVRAM restore.

Source	Severity
VLAN	Information

### Remedial action

Reconfigure VLAN settings and/or port configuration on this unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLAN queue messages discarded

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN queue messages discarded log

VLAN queue messages discarded

Internal VLAN messages were discarded.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLAN queue messages discarded

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN queue messages discarded log

VLAN queue messages discarded

Logged for each message that was not successfully sent to the VLAN queue.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# VLAN range could not be reduced sufficiently

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN range could not be reduced sufficiently log

VLAN range could not be reduced sufficiently

The VLAN range could not be reduce sufficiently for it's installation to be supported.

Source	Severity
QoS	Serious

### Remedial action

Modify the VLAN range.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLAN range support with FCoE redirection not available

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN range support with FCoE redirection not available log

VLAN range support with FCoE redirection not available

**Source**   **Severity**

QoS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLAN set error from IMC

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN set error from IMC log

VLAN set error from IMC

BU sends IMC to all NBUs and an error occurs when applying Vlan configuration on a NBU.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLAN set error from RPC

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN set error from RPC log

VLAN set error from RPC

NBU sends RPC to BU and an error occurs when applying Vlan configuration on BU.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLAN to VRF Mapping Message Sent Failure.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN to VRF Mapping Message Sent Failure. log

VLAN to VRF Mapping Message Sent Failure.

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Voice VLAN ID and Data VLAN ID cannot have the same value

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Voice VLAN ID and Data VLAN ID cannot have the same value log

Voice VLAN ID and Data VLAN ID cannot have the same value

Voice VLAN and Data VLAN must have different VLAN IDs.

### Source

Run scripts: IP Office, LLDP, ADAC

### Severity

Information

### Remedial action

Check existing settings that could be in conflict with the script parameters. Undo settings or boot default the switch, then re-run the script, entering proper data input.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VRF Already Exist.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VRF Already Exist. log

VRF Already Exist.

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VRF Constructor failed to create.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VRF Constructor failed to create. log

VRF Constructor failed to create.

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# VRF feature disabled due to inadequate license.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VRF feature disabled due to inadequate license. log

VRF feature disabled due to inadequate license.

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VRF IP Forwarding is Enable while changing the Maxroutes.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VRF IP Forwarding is Enable while changing the Maxroutes. log

VRF IP Forwarding is Enable while changing the Maxroutes.

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VRF Not Exist.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VRF Not Exist. log

VRF Not Exist.

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VRF NvRAM Open Error .

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VRF NvRAM Open Error . log

VRF NvRAM Open Error .

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VRF NvRAM Read Error.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VRF NvRAM Read Error. log

VRF NvRAM Read Error.

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VRRP Feature globally disabled due to missing license

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VRRP Feature globally disabled due to missing license log

VRRP Feature globally disabled due to missing license

Disable the Global VRRP because the license is missing or expired. VRRP will be disabled till the license is installed.

Source	Severity
VRRP	Information

### Remedial action

Install a valid Layer3/VRRP license.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VRRP: Feature globally disabled due to missing license

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VRRP: Feature globally disabled due to missing license log

VRRP: Feature globally disabled due to missing license

**Source**   **Severity**

VRRP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



VRRP: IP address is changed to (0x%08X), different than Phy IP Address. Decreasing automatically priority from 255 to 254.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VRRP: IP address is changed to (0x%08X), different than Phy IP Address. Decreasing automatically priority from 255 to 254. log

VRRP: IP address is changed to (0x%08X), different than Phy IP Address. Decreasing automatically priority from 255 to 254.

**Source**   **Severity**

VRRP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# VRRPv3 filters have NOT been installed.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VRRPv3 filters have NOT been installed. log

VRRPv3 filters have NOT been installed.

**Source    Severity**

VRRPv3

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VRRPv3 filters successfully installed.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VRRPv3 filters successfully installed. log

VRRPv3 filters successfully installed.

Source	Severity
--------	----------

VRRPv3	
--------	--

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VRRP: VR %d/%d: Received mismatching advertisement interval (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VRRP: VR %d/%d: Received mismatching advertisement interval (%d) log

VRRP: VR %d/%d: Received mismatching advertisement interval (%d)

**Source    Severity**

VRRP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VRRP: VR %d/%d: Received mismatching advertisement type (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VRRP: VR %d/%d: Received mismatching advertisement type (%d) log

VRRP: VR %d/%d: Received mismatching advertisement type (%d)

**Source    Severity**

VRRP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VRRP: VR %d/%d: Received mismatching fast advertisement interval (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VRRP: VR %d/%d: Received mismatching fast advertisement interval (%d) log

VRRP: VR %d/%d: Received mismatching fast advertisement interval (%d)

**Source    Severity**

VRRP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VRRP: VR %d/%d: Received mismatching virtual IP address (0x%08X)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VRRP: VR %d/%d: Received mismatching virtual IP address (0x%08X) log

VRRP: VR %d/%d: Received mismatching virtual IP address (0x%08X)

**Source    Severity**

VRRP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VRRP: VR %d/%d: Received unknown VRRP packet type (%d)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VRRP: VR %d/%d: Received unknown VRRP packet type (%d) log

VRRP: VR %d/%d: Received unknown VRRP packet type (%d)

**Source    Severity**

VRRP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VRRP: vrrpAdvtQueue is FULL. RX advertisement dropped in vlan %d!

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VRRP: vrrpAdvtQueue is FULL. RX advertisement dropped in vlan %d! log

VRRP: vrrpAdvtQueue is FULL. RX advertisement dropped in vlan %d!

vrrpAdvtQueue is FULL for the identified VLAN.

Source	Severity
--------	----------

VRRP	Information
------	-------------

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# VRRP: vrrpQueue is FULL. Message dropped.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VRRP: vrrpQueue is FULL. Message dropped. log

VRRP: vrrpQueue is FULL. Message dropped.

vrrpQueue is FULL.

Source	Severity
VRRP	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VRRP VR VR Id VLAN Id Received mismatching advertisement interval ( advertisement interval)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VRRP VR VR Id VLAN Id Received mismatching advertisement interval ( advertisement interval) log

VRRP VR VR Id VLAN Id Received mismatching advertisement interval ( advertisement interval)

The system Received a VRRP packet with different advertisement interval. VRRP advertisements from VRRP routers with different advertisement interval will be dropped until problem is solved.

Source	Severity
VRRP	Information

### Remedial action

Use or set the same advertisement interval for the VRRP routers.



# VRRP VR VR Id VLAN Id Received mismatching advertisement type ( advertisement type )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VRRP VR VR Id VLAN Id Received mismatching advertisement type ( advertisement type ) log

VRRP VR VR Id VLAN Id Received mismatching advertisement type ( advertisement type )

The system received a VRRP packet with different advertisement type. VRRP advertisements from VRRP routers with different advertisement type will be dropped till the problem is solved.

Source	Severity
VRRP	Information

### Remedial action

Use or set the same advertisement type for VRRP routers. Fast advertisement should be either enabled or disabled on all VRRP routers.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VRRP VR VR Id VLAN Id Received mismatching fast advertisement interval ( fast advertisement interval)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VRRP VR VR Id VLAN Id Received mismatching fast advertisement interval ( fast advertisement interval) log

VRRP VR VR Id VLAN Id Received mismatching fast advertisement interval ( fast advertisement interval)

The system received a VRRP packet with different fast advertisement interval. VRRP advertisements from VRRP routers with different fast advertisement interval will be dropped till the problem is solved.

Source	Severity
--------	----------

VRRP	Information
------	-------------

### Remedial action

Use or set the same fast advertisement interval for all VRRP routers.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# VRRP VR VR Id VLAN Id Received mismatching virtual IP address ( received virtual ip address )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VRRP VR VR Id VLAN Id Received mismatching virtual IP address ( received virtual ip address ) log

VRRP VR VR Id VLAN Id Received mismatching virtual IP address ( received virtual ip address )

The system received a VRRP packet with different virtual IP address VRRP advertisements from VRRP routers with different virtual IP address will be dropped until problem is solved.

Source	Severity
VRRP	Information

### Remedial action

Use or set the same virtual IP address for all VRRP routers.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VRRP VR VR Id VLAN Id Received unknown VRRP packet type ( vrrp packet type )

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VRRP VR VR Id VLAN Id Received unknown VRRP packet type ( vrrp packet type ) log

VRRP VR VR Id VLAN Id Received unknown VRRP packet type ( vrrp packet type )

Received unknown or wrong VRRP packet type. VRRP advertisements from VRRP routers with different VRRP type will be dropped till the problem is solved.

Source	Severity
VRRP	Information

### Remedial action

Use or set the same VRRP type for all VRRP routers.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Warm Start Trap

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Warm Start Trap log

Warm Start Trap

**Source**   **Severity**

SNMP

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Warning

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Warning log

Warning

Source	Severity
--------	----------

L3Mgr	
-------	--

Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Warning failed to connect to %s card (in unit %s)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Warning failed to connect to %s card (in unit %s) log

Warning failed to connect to %s card (in unit %s)

This message appears when the system detects MDA card physical connection issues for the identified MDA model.

Source	Severity
MDA	Information

### Remedial action

Check the MDA card physical connection.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Warning: non-supported qsfps inserted on %s. Port will be disabled.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Warning: non-supported qsfps inserted on %s. Port will be disabled. log

Warning: non-supported qsfps inserted on %s. Port will be disabled.

Informs the user that an unsupported GBIC was inserted into a port and the port is disabled.

Source	Severity
--------	----------

MDA	Information
-----	-------------

### Remedial action

Insert a supported GBIC into the specified port.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Warning: non-supported qsfps inserted on %s. Port will not link up.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Warning: non-supported qsfps inserted on %s. Port will not link up. log

Warning: non-supported qsfps inserted on %s. Port will not link up.

Source	Severity
GBIC	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



Warning: non-supported stack cable inserted on %s. Stacking port will be admin disabled.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Warning: non-supported stack cable inserted on %s. Stacking port will be admin disabled. log

Warning: non-supported stack cable inserted on %s. Stacking port will be admin disabled.

Source	Severity
GBIC	

### Remedial action

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Warning:non-supported transceiver on %s has been detected.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Warning:non-supported transceiver on %s has been detected. log

Warning:non-supported transceiver on %s has been detected.

Informs the user that the transceiver is unsupported on a certain port.

Source	Severity
PDT	Information

### Remedial action

Replace with supported transceiver.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Warning %s card unsafely removed (from unit %s)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Warning %s card unsafely removed (from unit %s) log

Warning %s card unsafely removed (from unit %s)

This message appears when the identified MDA card is removed without first being disabled.

Source	Severity
MDA	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# WEB-access is disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## WEB-access is disabled log

WEB-access is disabled

HTTP access was disabled.

Source	Severity
WEB	Information

### Remedial action

None

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# WEB-access is disabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## WEB-access is disabled log

WEB-access is disabled

**Source**   **Severity**

WEB

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# WEB-access is enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## WEB-access is enabled log

WEB-access is enabled

HTTP access was enabled.

Source	Severity
WEB	Information

### Remedial action

None



# WEB-access is enabled

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## WEB-access is enabled log

WEB-access is enabled

**Source**   **Severity**

WEB

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Web authentication fail from IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Web authentication fail from IP address log

Web authentication fail from IP address

Client from the indicated IP address has failed authentication.

Source	Severity
WEB	Information

### Remedial action

Provide the correct username and password to gain access to the web server.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Web authentication fail from IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Web authentication fail from IP address log

Web authentication fail from IP address

**Source**   **Severity**

WEB

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Web authentication from IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Web authentication from IP address log

Web authentication from IP address

Client from the indicated IP address has been successfully authenticated.

Source	Severity
WEB	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Web authentication from IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Web authentication from IP address log

Web authentication from IP address

**Source**   **Severity**

WEB

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Web authentication (RADIUS auth) from IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Web authentication (RADIUS auth) from IP address log

Web authentication (RADIUS auth) from IP address

**Source**   **Severity**

WEB

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Web connection from IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Web connection from IP address log

Web connection from IP address

New client from the indicated IP address is connected to the web server.

Source	Severity
WEB	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Web connection from IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Web connection from IP address log

Web connection from IP address

**Source**   **Severity**

WEB

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# WebControl server running.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## WebControl server running. log

WebControl server running.

**Source**   **Severity**

WEB

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Web disconnect from IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Web disconnect from IP address log

Web disconnect from IP address

Client from the indicated IP address is disconnected from the web server.

Source	Severity
WEB	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Web disconnect from IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Web disconnect from IP address log

Web disconnect from IP address

**Source**   **Severity**

WEB

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Web server attempting to open socket for port %d.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Web server attempting to open socket for port %d. log

Web server attempting to open socket for port %d.

**Source   Severity**

WEB

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Web server attempting to open socket for port HTTP port

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Web server attempting to open socket for port HTTP port log

Web server attempting to open socket for port HTTP port

Web server is attempting to change communication to the new HTTP port indicated.

Source	Severity
WEB	Information

### Remedial action

No action required.



# Web server starts service on port %d.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Web server starts service on port %d. log

Web server starts service on port %d.

**Source   Severity**

WEB

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Web server starts service on port HTTP port

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Web server starts service on port HTTP port log

Web server starts service on port HTTP port

Web server is up and running, communicating through the indicated HTTP port.

Source	Severity
WEB	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





Web server starts service on ports: %d for HTTP and %d for HTTPS.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Web server starts service on ports: %d for HTTP and %d for HTTPS. log

Web server starts service on ports: %d for HTTP and %d for HTTPS.

Source	Severity
WEB	

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Web timeout from IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Web timeout from IP address log

Web timeout from IP address

Client from the indicated IP address has timed out from the web server due to inactivity.

Source	Severity
WEB	Information

### Remedial action

Client may need to login again to gain access to the web server.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Web timeout from IP address

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Web timeout from IP address log

Web timeout from IP address

**Source**   **Severity**

WEB

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# When enable IST must configure SMLT peer BMAC

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## When enable IST must configure SMLT peer BMAC log

When enable IST must configure SMLT peer BMAC

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# When setting Virtual BMAC to zero, Peer BMAC must be zero

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## When setting Virtual BMAC to zero, Peer BMAC must be zero log

When setting Virtual BMAC to zero, Peer BMAC must be zero

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Wrong QoS Agent buffer setting, expected %s, actual %s, unit cannot join stack

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Wrong QoS Agent buffer setting, expected %s, actual %s, unit cannot join stack log

Wrong QoS Agent buffer setting, expected %s, actual %s, unit cannot join stack

**Source**   **Severity**  
SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Wrong QoS Agent buffer setting, expected %s, actual %s, unit reconfigured and reboot

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Wrong QoS Agent buffer setting, expected %s, actual %s, unit reconfigured and reboot log

Wrong QoS Agent buffer setting, expected %s, actual %s, unit reconfigured and reboot

**Source**   **Severity**  
SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Wrong QoS Agent buffer setting, expected %s, actual %s, unit re-configured and reboot

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Wrong QoS Agent buffer setting, expected %s, actual %s, unit re-configured and reboot log

Wrong QoS Agent buffer setting, expected %s, actual %s, unit re-configured and reboot

QoS agent buffer allocation is different that the one of the BU's.

Source	Severity
Stack Manager	Serious

### Remedial action

Wait for re-configuration and reboot cycle.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Wrong QoS Agent buffer setting, expected %s, actual %s, unit re-configured and reboot

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Wrong QoS Agent buffer setting, expected %s, actual %s, unit re-configured and reboot log

Wrong QoS Agent buffer setting, expected %s, actual %s, unit re-configured and reboot

QoS agent buffer allocation is different that the one of the BU's.

Source	Severity
Stack Manager	Serious

### Remedial action

Wait for re-configuration and reboot cycle.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Wrong QOS Agent buffer setting expected value actual value unit cannot join stack.

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Wrong QOS Agent buffer setting expected value actual value unit cannot join stack. log

Wrong QOS Agent buffer setting expected value actual value unit cannot join stack.

The QOS buffer setting on this unit is different than that of the base unit's setting.

Source	Severity
Stack Manager	Information

### Remedial action

Modify the QOS buffer setting on the unit.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Wrong QoS Agent queue setting, expected %u, actual %u, unit cannot join stack

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Wrong QoS Agent queue setting, expected %u, actual %u, unit cannot join stack log

Wrong QoS Agent queue setting, expected %u, actual %u, unit cannot join stack

**Source**   **Severity**  
SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Wrong QoS Agent queue setting, expected %u, actual %u, unit cannot join stack

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Wrong QoS Agent queue setting, expected %u, actual %u, unit cannot join stack log

Wrong QoS Agent queue setting, expected %u, actual %u, unit cannot join stack

**Source**   **Severity**

SMGR

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Wrong QoS Agent queue setting, expected %u, actual %u, unit reconfigured and reboot

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Wrong QoS Agent queue setting, expected %u, actual %u, unit reconfigured and reboot log

Wrong QoS Agent queue setting, expected %u, actual %u, unit reconfigured and reboot

Non Bu QoS queue set size is checked at discovery against BU's QoS que set, changed if needed, unit is rebooted if value is changed.

Source	Severity
Stack Manager	Serious

### Remedial action

Assure that QoS queue set size on Non Base Units is the same as the BU QoS queue set size.



# Wrong QoS Agent queue setting, expected %u, actual %u, unit re-configured and reboot

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Wrong QoS Agent queue setting, expected %u, actual %u, unit re-configured and reboot log

Wrong QoS Agent queue setting, expected %u, actual %u, unit re-configured and reboot

QoS agent queue setting is different that the one of the BU's.

Source	Severity
Stack Manager	Serious

### Remedial action

Wait for re-configuration and reboot cycle.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Wrong QoS Agent queue setting, expected %u, actual %u, unit reconfigured and reboot

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Wrong QoS Agent queue setting, expected %u, actual %u, unit reconfigured and reboot log

Wrong QoS Agent queue setting, expected %u, actual %u, unit reconfigured and reboot

Non Bu QoS queue set size is checked at discovery against BU's QoS que set, changed if needed, unit is rebooted if value is changed.

Source	Severity
Stack Manager	Serious

### Remedial action

Assure that QoS queue set size on Non Base Units is the same as the BU QoS queue set size.



# Wrong QoS Agent queue setting, expected %u, actual %u, unit re-configured and reboot

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Wrong QoS Agent queue setting, expected %u, actual %u, unit re-configured and reboot log

Wrong QoS Agent queue setting, expected %u, actual %u, unit re-configured and reboot

QoS agent queue setting is different that the one of the BU's.

Source	Severity
Stack Manager	Serious

### Remedial action

Wait for re-configuration and reboot cycle.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Wrong value

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Wrong value log

Wrong value

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Wrong value

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Wrong value log

Wrong value

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Wrong VLANs nvq\_RecDescr actRecs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Wrong VLANs nvq\_RecDescr actRecs log

Wrong VLANs nvq\_RecDescr actRecs

There was an error when reading the VLAN configuration from NVRAM.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Wrong VLANs nvq\_RecDescr actRecs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Wrong VLANs nvq\_RecDescr actRecs log

Wrong VLANs nvq\_RecDescr actRecs

There was an error when reading the VLAN configuration from NVRAM.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Wrong VMACs nvq\_RecDescr actRecs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Wrong VMACs nvq\_RecDescr actRecs log

Wrong VMACs nvq\_RecDescr actRecs

There was an error when reading the VLAN configuration from NVRAM.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Wrong VMACs nvq\_RecDescr actRecs

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Wrong VMACs nvq\_RecDescr actRecs log

Wrong VMACs nvq\_RecDescr actRecs

There was an error when reading the VLAN configuration from NVRAM.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Wrong vrec field

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Wrong vrec field log

Wrong vrec field

There was an error when reading the VLAN configuration from NVRAM.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Wrong vrec field

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Wrong vrec field log

Wrong vrec field

There was an error when reading the VLAN configuration from NVRAM.

Source	Severity
VLAN	Information

### Remedial action

No action required.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





0x%X 0x%X 0x%X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## 0x%X 0x%X 0x%X log

0x%X 0x%X 0x%X

**Source**   **Severity**

L3Mgr

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Zero SMLT peer BMAC must have primary split BEB

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Zero SMLT peer BMAC must have primary split BEB log

Zero SMLT peer BMAC must have primary split BEB

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Zero SMLT peer BMAC must have primary split BEB

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Zero SMLT peer BMAC must have primary split BEB log

Zero SMLT peer BMAC must have primary split BEB

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Zero SMLT peer BMAC must have zero virtual BMAC

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Zero SMLT peer BMAC must have zero virtual BMAC log

Zero SMLT peer BMAC must have zero virtual BMAC

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Zero SMLT peer BMAC must have zero virtual BMAC

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Zero SMLT peer BMAC must have zero virtual BMAC log

Zero SMLT peer BMAC must have zero virtual BMAC

**Source**   **Severity**

ISIS

**Remedial action**

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ZTP+: failed to connect to the XMC server

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ZTP+: failed to connect to the XMC server log

ZTP+: failed to connect to the XMC server

Could not connect to the ZTP+ server.

Source	Severity
ZTP	Inform

### Remedial action

No action.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ZTP+: failed to start the auto-provisioning process

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ZTP+: failed to start the auto-provisioning process log

ZTP+: failed to start the auto-provisioning process

Local error. Could not start the ZTP+ process.

Source	Severity
--------	----------

ZTP	Inform
-----	--------

### Remedial action

No action.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ZTP+: failed to upgrade the firmware

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ZTP+: failed to upgrade the firmware log

ZTP+: failed to upgrade the firmware

Firmware upgrade could not be performed.

Source	Severity
--------	----------

ZTP	Inform
-----	--------

### Remedial action

No action.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# ZTP+: successfully connected to the XMC server

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ZTP+: successfully connected to the XMC server log

ZTP+: successfully connected to the XMC server

Successful connection to the ZTP+ server.

Source	Severity
ZTP	Inform

### Remedial action

No action.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ZTP+: successfully upgraded the firmware

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ZTP+: successfully upgraded the firmware log

ZTP+: successfully upgraded the firmware

Firmware upgrade finished successfully.

Source	Severity
ZTP	Inform

### Remedial action

No action.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ZTP+: the auto-provisioning process has started

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ZTP+: the auto-provisioning process has started log

ZTP+: the auto-provisioning process has started

ZTP+ process started.

Source	Severity
ZTP	Inform

### Remedial action

No action.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ZTP+: the firmware upgrade has started

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ZTP+: the firmware upgrade has started log

ZTP+: the firmware upgrade has started

Firmware upgrade started.

Source	Severity
ZTP	Inform

### Remedial action

No action.

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QoS logs starting with A

This page lists all the logs starting with the letter A that are generated by the QoS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

- [Access assignment distribution across stack failed](#)
- [Access assignment modifications not supported](#)
- [Access assignment modification support limited](#)
- [Access assignment name contains unacceptable characters](#)
- [Access assignment name length outside of acceptable limits](#)
- [Access assignment name not acceptable - reserved](#)
- [Access assignment template still in use \(siblings active\)](#)
- [Access element block label contains unacceptable characters](#)
- [Access element block label length outside of acceptable limits](#)
- [Access element cluster count \( cluster count \) exceeds limit \( cluster limit \)](#)
- [Access element cluster count \(%d\) exceeds limit \(%d\)](#)
- [Access element cluster is referenced \(addition prohibited\)](#)
- [Access element cluster is referenced \(deletion prohibited\)](#)
- [Access element distribution across stack failed](#)
- [Access element modifications not supported](#)
- [Access element name contains unacceptable characters](#)
- [Access element name length outside of acceptable limits](#)
- [Access element name not acceptable - reserved](#)
- [Additional metering data needed for specified metering mode](#)
- [Agent configuration distribution across stack failed](#)
- [Attempt to create an element that already exists \(prohibited\)](#)
- [Attempt to delete modify non-existing element \(prohibited\)](#)
- [Attempt to delete/modify non-existing element \(prohibited\)](#)
- [Attempt to delete referenced NSNA filter set \(prohibited\)](#)
- [Attempt to delete referenced UBP filter set \(prohibited\)](#)
- [Attempt to manipulate system-owned interface \(prohibited\)](#)
- [Attempt to manipulate user policy data rejected \(disabled\)](#)
- [AutoQoS mode enable failure - inadequate resources](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)



# QoS logs starting with B

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QoS logs starting with B

This page lists all the logs starting with the letter B that are generated by the QoS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

- [Base action distribution across stack failed](#)
- [Base action entry referenced by clfr block \(deletion prohibited\)](#)
- [Base action entry referenced by meter \(deletion prohibited\)](#)
- [Base action entry referenced by policy \(deletion prohibited\)](#)
- [Base action extension identifier invalid](#)
- [Base action modification prohibited due to action usage](#)
- [Base action modifications not supported](#)
- [Buffer configuration inconsistency detected \(local buffer conf stack buffer conf.\)](#)
- [Buffer configuration inconsistency detected \(local %d, stack %d\)](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QoS logs starting with C

This page lists all the logs starting with the letter C that are generated by the QoS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

- [Capabilities determined by agent \(not-writable\)](#)
- [Capabilities value invalid](#)
- [Classifier block component set ID out-of-range \( clfr comp set ID \)](#)
- [Classifier block component set ID out-of-range \(%d\)](#)
- [Classifier block distribution across stack failed](#)
- [Classifier block modifications not supported](#)
- [Classifier block number out-of-range \( block# \)](#)
- [Classifier block number out-of-range \(%d\)](#)
- [Classifier block precedence value not supported](#)
- [Classifier component distribution across stack failed](#)
- [Classifier component modifications not supported](#)
- [Classifier component set ID out-of-range \( clfsr comp set ID \)](#)
- [Classifier component set ID out-of-range \(%d\)](#)
- [Classifier conflict \(duplicate clfr data in block\) detected](#)
- [Classifier content incompatible with target interface\(s\)](#)
- [Classifier inconsistency detected \(conflicting allocation modes\)](#)
- [Classifier set block reference out-of-range \( clfr setblock# \)](#)
- [Classifier set/block reference out-of-range \(%d\)](#)
- [Classifier type unknown](#)
- [Clfr content \(system\) incompatible with target interface\(s\)](#)
- [Composite filter set addition failure comp filter set unknown](#)
- [Composite filter set addition failure: comp filter set unknown](#)
- [Composite filter set addition failure data consistency issue](#)
- [Composite filter set addition failure: data consistency issue](#)
- [Composite filter set addition failure data invalid](#)
- [Composite filter set addition failure: data invalid](#)
- [Composite filter set addition failure replication failure](#)
- [Composite filter set addition failure: replication failure](#)
- [Composite filter set addition failure resources unavailable](#)
- [Composite filter set addition failure: resources unavailable](#)
- [Composite filter set addition failure seed filter set unknown](#)
- [Composite filter set addition failure: seed filter set unknown](#)
- [Composite filter set creation failure data invalid](#)
- [Composite filter set creation failure: data invalid](#)
- [Composite filter set creation failure MAC data not allowed](#)
- [Composite filter set creation failure: MAC data not allowed](#)
- [Composite filter set creation failure replication failure](#)
- [Composite filter set creation failure: replication failure](#)
- [Composite filter set creation failure seed filter set unknown](#)
- [Composite filter set creation failure: seed filter set unknown](#)
- [Composite filter set creation failure: set already exists](#)
- [Composite filter set deletion failure base set target invalid](#)
- [Composite filter set deletion failure: base set target invalid](#)
- [Composite filter set deletion failure comp filter set unknown](#)
- [Composite filter set deletion failure: comp filter set unknown](#)

[Composite filter set deletion failure data invalid](#)

- [Composite filter set deletion failure: data invalid](#)
- [Composite filter set deletion failure seed filter set unknown](#)
- [Composite filter set deletion failure: seed filter set unknown](#)
- [Composite filter set destruction failure data invalid](#)
- [Composite filter set destruction failure: data invalid](#)
- [Composite filter set membership limits exceeded](#)
- [Conflicting action sources detected](#)
- [Conflicting master block member information detected](#)
- [Conflicting policy role policy interface index data detected](#)
- [Conflicting policy role/policy interface index data detected](#)
- [COS mapping distribution across stack failed](#)
- [CoS shaping distribution across stack failed](#)
- [CoS shaping modifications not supported](#)
- [CoS shaping not supported with specified interface](#)
- [Count action distribution across stack failed](#)
- [Count action entry referenced by meter \(deletion prohibited\)](#)
- [Count action entry referenced by policy \(deletion prohibited\)](#)
- [Count action modifications not supported](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QoS logs starting with D

This page lists all the logs starting with the letter D that are generated by the QoS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

- [DAPP-detected DoS attack blocked: unit %d \(many ports\)](#)
- [DAPP-detected DoS attack blocked: unit %d port %d](#)
- [DAPP-detected DoS attack blocked unit unit# \(many ports\)](#)
- [DAPP-detected DoS attack blocked unit unit# port port#](#)
- [DAPP resources not available \(unit %d\)](#)
- [DAPP resources not available \(unit unit# \)](#)
- [DAPP support disable failure](#)
- [DAPP support enable failure](#)
- [DAPP with statistics tracking in use \(QoS disable prohibited\)](#)
- [Data distribution class class# across stack failed](#)
- [Data distribution \(class %d\) across stack failed](#)
- [Data model version attribute value not supported](#)
- [Default ifc assignment failure \[%d port\(s\)\]: ifc QoS-disabled](#)
- [Default ifc assignment failure port# port\(s\) ifc QoS-disabled](#)
- [Delayed filter set installation completed \(time %d\)](#)
- [Delayed filter set installation started \(time %d\)](#)
- [Destination MAC address and mask values out-of-sync](#)
- [Different classifier component masks keys in block detected](#)
- [Different classifier component masks/keys in block detected](#)
- [DSCP mapping distribution across stack failed](#)
- [DSCP mapping modifications not supported](#)
- [DSCP remarking not supported for IPv6 \(green action\)](#)
- [DSCP remarking not supported for IPv6 \(in-profile action\)](#)
- [DSCP remarking not supported for IPv6 \(match action\)](#)
- [DSCP remarking not supported for IPv6 \(non-match action\)](#)
- [DSCP remarking not supported for IPv6 \(out-of-profile action\)](#)
- [DSCP remarking not supported for IPv6 \(red action\)](#)
- [DSCP remarking not supported for IPv6 \(yellow action\)](#)
- [DSCP value modification prohibited](#)
- [DS/L2 entry mismatch detected \(NSNA filter set data\)](#)
- [DS/L2 entry mismatch detected \(UBP filter set data\)](#)
- [Dst IP addr matching not supported with IP addr type data](#)
- [Dst Layer 4 port min max values invalid \(max must be = to min\)](#)
- [Dst Layer 4 port min/max values invalid \(max must be >= to min\)](#)
- [Dst MAC addr matching not supported with address type data](#)
- [Duplicate access asgn name type index detected \(prohibited\)](#)
- [Duplicate access asgn name/type/index detected \(prohibited\)](#)
- [Duplicate classifier class values in set detected](#)
- [Duplicate entry detected \(prohibited\)](#)
- [Duplicate FCoE redirection entry detected](#)
- [Duplicate FCoE redirection entry detected \(prohibited\)](#)
- [Duplicate set values in block detected](#)
- [Duplicate users \(different port, same user name\) prohibited](#)
- [Dynamic interface assignment failure \(%d/%d\)](#)
- [Dynamic role combination cannot be used in explicit assignment](#)





# QoS logs starting with E

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QoS logs starting with E

This page lists all the logs starting with the letter E that are generated by the QoS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

- [EAP Failed qpa-RoleAssociation unitPort 0x%x mac %08x%04x](#)
- [Egress interface and egress mask are mutually exclusive](#)
- [Element deletion prohibited \(permanent read-only system entry\)](#)
- [Element deletion prohibited \(permanent/read-only/system entry\)](#)
- [Element enable prohibited. Please delete and re-enter data](#)
- [Element label contains unacceptable characters](#)
- [Element label length outside of acceptable limits \(max 16 chars\)](#)
- [Element label not acceptable - reserved](#)
- [Element may only be modified not created or deleted](#)
- [Element modification prohibited \(read-only or system entry\)](#)
- [Evaluation precedence conflict detected \(NSNA filter set data\)](#)
- [Evaluation precedence conflict detected \(UBP filter set data\)](#)
- [Evaluation precedence conflict \(Traffic Prof filter set data\)](#)
- [Evaluation precedence value required but not specified](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QoS logs starting with F

This page lists all the logs starting with the letter F that are generated by the QoS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

- [Failed to restore dynamic role combination post QoS reset](#)
- [FCoE controller MAC not set - FCoE redirection enable prohibited](#)
- [FCoE FNC access disabled](#)
- [FCoE FNC access enabled](#)
- [FCoE ingress interface list content issue - ifIndex %d invalid](#)
- [FCoE redirection controller filter deletion failure detected](#)
- [FCoE redirection controller filter installation failure detected](#)
- [FCoE redirection disable issue - incomplete FCoE entry deletion](#)
- [FCoE redirection element manipulation blocked \(operation mode is disabled\)](#)
- [FCoE redirection element name contains unacceptable characters](#)
- [FCoE redirection element name length outside of acceptable limits](#)
- [FCoE redirection element name not acceptable - reserved](#)
- [FCoE redirection enable issue - incomplete FCoE entry installation](#)
- [FCoE redirection entry modification not supported](#)
- [FCoE redirection traffic filter deletion failure detected](#)
- [FCoE redirection traffic filter installation failure detected](#)
- [FCoE traffic redirection disabled](#)
- [FCoE traffic redirection enabled](#)
- [Filter control block resources exhausted](#)
- [Filter creation issue detected - in-profile action component](#)
- [Filter creation issue detected - match action component](#)
- [Filter creation issue detected - metering component](#)
- [Filter creation issue detected - non-match action component](#)
- [Filter creation issue detected - out-of-profile action component](#)
- [Filter manager internal error encountered](#)
- [Filter manager memory resources exhausted](#)
- [Filter manager metering or policy rule space exhausted](#)
- [Filter manager metering resources exhausted](#)
- [Filter manager policy rule space potentially exhausted](#)
- [Filter manager request parameter invalid](#)
- [Filter manager statistics tracking resources exhausted](#)
- [Filter set data inconsistent \(conflicting IP/non-IP data\)](#)
- [Filter set installation timeout detected \(ID %d\)](#)
- [Filter set \(NSNA\) was not restored/installed](#)
- [Filter set requirements incompatible with target interface](#)
- [Filter set \(Traffic Profile\) was not restored/installed](#)
- [Filter set \(User Based Policy\) was not restored/installed](#)
- [First TrTCM Meter Index must be in range 1-5000](#)
- [Flow ID filtering not supported for IPv4](#)
- [Flow ID out-of-range \(%d\)](#)
- [Flow ID out-of-range \( Flow ID \)](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QoS logs starting with G

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QoS logs starting with G

This page lists all the logs starting with the letter G that are generated by the QoS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

- [Got UserPolicy from Radius but UBP disabled - unitPort 0x%x mac %08x%04x](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QoS logs starting with I

This page lists all the logs starting with the letter I that are generated by the QoS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

- [Ifc app modification issue \(inconsistent default gateway data\)](#)
- [Ifc app modification issue \(inconsistent DHCP server data\)](#)
- [Ifc app modification issue \(inconsistent ifType data\)](#)
- [Ifc app support not currently available on interface \(%d\)](#)
- [Ifc app support not currently available on interface \( ifc# \)](#)
- [Ifc assignment issue - prec conflict \(policy %d disabled\)](#)
- [Ifc assignment issue - prec conflict \(policy policy# disabled\)](#)
- [Inadequate resources available for application policy criteria](#)
- [Inappropriate status transition specified](#)
- [Incompatible base action extension specified](#)
- [Incompatible classifier reference \(agent-defined clfr\)](#)
- [Incompatible data model version values \(referenced clfr data\)](#)
- [Incompatible data model version values \(referenced meter data\)](#)
- [Incompatible in-profile action \(trusted ifc\)](#)
- [Incompatible in-profile action \(unrestricted ifc\)](#)
- [Incompatible in-profile action \(untrusted ifc\)](#)
- [Incompatible in-profile action \(untrustedv4v6 ifc\)](#)
- [Incompatible match action \(trusted ifc\)](#)
- [Incompatible match action \(unrestricted ifc\)](#)
- [Incompatible match action \(untrusted ifc\)](#)
- [Incompatible match action \(untrustedv4v6 ifc\)](#)
- [Incompatible non-match action \(trusted ifc\)](#)
- [Incompatible non-match action \(unrestricted ifc\)](#)
- [Incompatible non-match action \(untrusted ifc\)](#)
- [Incompatible non-match action \(untrustedv4v6 ifc\)](#)
- [Incompatible out-of-profile action \(trusted ifc\)](#)
- [Incompatible out-of-profile action \(unrestricted ifc\)](#)
- [Incompatible out-of-profile action \(untrusted ifc\)](#)
- [Incompatible out-of-profile action \(untrustedv4v6 ifc\)](#)
- [Incompatible range requirements detected](#)
- [Incompatible StorageType specified \(re classifier\)](#)
- [Incompatible StorageType specified \(re: classifier\)](#)
- [Inconsistent action criteria detected across block members](#)
- [Inconsistent classifier component \( clfr comp# \) state detected](#)
- [Inconsistent classifier component \(%d\) state detected](#)
- [Inconsistent labels detected for members of same block](#)
- [Inconsistent labels detected for members of same set](#)
- [Inconsistent MAC data detected across filter set members](#)
- [Inconsistent metering criteria detected across block members](#)
- [Index value out-of-range](#)
- [Index value out-of-range or permanent/read-only/system entry](#)
- [Inner VLAN ID filtering requires double tag](#)
- [Inner VLAN ID min/max values invalid \(%d !< %d\)](#)
- [Inner VLAN ID min max values invalid \( min VLAN ID ! max VLAN ID \)](#)
- [In-profile action contains conflicting data](#)

[Insufficient HW resources to support port role association](#)

- [Insufficient HW resources to support port/role association](#)
- [Insufficient policy space available to support access assignment](#)
- [Insufficient resources available to support policy installation](#)
- [Interface action distribution across stack failed](#)
- [Interface action entry referenced by base action](#)
- [Interface action extension identifier invalid](#)
- [Interface action modifications not supported](#)
- [Interface Application data in use \(QoS disable prohibited\)](#)
- [Interface application distribution across stack failed](#)
- [Interface application modifications not supported](#)
- [Interface application Undo failure \(app app# \)](#)
- [Interface application Undo failure \(app %d\)](#)
- [Interface assignment distribution across stack failed](#)
- [Interface assignment failure - precedence conflict detected](#)
- [Interface assignment modifications not supported](#)
- [Interface capabilities incompatible with policy data](#)
- [Interface data out-of-sync in Policy and User Policy entries](#)
- [Interface queue modifications not supported](#)
- [Interface resources inadequate to support application enable](#)
- [Interface shaping and CoS shaping conflict \(same ifc specified\)](#)
- [Interface shaping and queue shaping conflict \(same ifc specified\)](#)
- [Interface shaping distribution across stack failed](#)
- [Interface shaping modifications not supported](#)
- [Interface shaping not supported with specified interface](#)
- [Interfaces QoS-disabled \(%d on unit %d\) - restoration issue](#)
- [Interfaces QoS-disabled \( port# on unit# \) - restoration issue](#)
- [Invalid access assignment type option specified](#)
- [Invalid access element type option specified](#)
- [Invalid classifier ID specified](#)
- [Invalid classifier reference](#)
- [Invalid classifier reference \(unknown class\)](#)
- [Invalid classifier reference \(unknown incompatible set\)](#)
- [Invalid classifier reference \(unknown/incompatible set\)](#)
- [Invalid classifier reference \(unknown instance\)](#)
- [Invalid clear QoS statistics value specified](#)
- [Invalid DAPP state transition detected \(prohibited\)](#)
- [Invalid datapath identifier specified](#)
- [Invalid default DSCP value specified](#)
- [Invalid default packet format value specified](#)
- [Invalid destination MAC address length specified](#)
- [Invalid destination MAC address mask length specified](#)
- [Invalid drop action option specified](#)
- [Invalid drop action option specifiedInvalid drop action option specified](#)
- [Invalid drop precedence value specified \(%d\)](#)
- [Invalid drop precedence value specified \( precedence \)](#)
- [Invalid DSCP value specified \(%d\)](#)
- [Invalid DSCP value specified \( DSCP value \)](#)
- [Invalid egress interface specified \(%d\)](#)
- [Invalid egress interface specified \( ifc# \)](#)
- [Invalid egress interface tag option specified](#)
- [Invalid egress interface type specified \(%d\)](#)
- [Invalid egress interface type specified \(<ifc type>\)](#)
- [Invalid egress mask value specified](#)
- [Invalid entry creation attempted \(index %d\)](#)
- [Invalid entry creation attempted \(index index# \)](#)
- [Invalid EtherType value specified \( Ether Type 0xFFFF \)](#)
- [Invalid EtherType value specified \(%04x\)](#)
- [Invalid expired session data specified](#)
- [Invalid/expired session data specified](#)
- [Invalid FCoE controller MAC address specified](#)
- [Invalid FCoE D ID data specified](#)
- [Invalid FCoE redirection destination MAC address specified](#)
- [Invalid FCoE redirection source MAC address specified](#)
- [Invalid FCoE S ID data specified](#)



- [Invalid filter set priority value detected](#)
- [Invalid/incompatible queue reference detected](#)
- [Invalid interface found in egress mask \(%d\)](#)
- [Invalid interface found in egress mask \( egress mask bit# \)](#)
- [Invalid interface index data specified \(%d\)](#)
- [Invalid interface index data specified \( ifc index \)](#)
- [Invalid interface index data \(system-owned\) specified](#)
- [Invalid IP destination address prefix detected](#)
- [Invalid IP source address prefix detected](#)
- [Invalid master block member value specified](#)
- [Invalid maximum inner VLAN ID value specified \(%d\)](#)
- [Invalid maximum inner VLAN ID value specified \( VLAN ID \)](#)
- [Invalid maximum VLAN ID value specified \(%d\)](#)
- [Invalid maximum VLAN ID value specified \( VLAN ID \)](#)
- [Invalid metering data \(bucket size\) specified for interface\(s\)](#)
- [Invalid metering data \(granularity\) specified for interface\(s\)](#)
- [Invalid metering data \(rate\) specified for interface\(s\)](#)
- [Invalid metering data \(srTCM trTCM\) specified for interface\(s\)](#)
- [Invalid metering data \(srTCM/trTCM\) specified for interface\(s\)](#)
- [Invalid minimum inner VLAN ID value specified \(%d\)](#)
- [Invalid minimum inner VLAN ID value specified \( VLAN ID \)](#)
- [Invalid minimum VLAN ID value specified \(%d\)](#)
- [Invalid minimum VLAN ID value specified \( VLAN ID \)](#)
- [Invalid mix of classifiers \(IPv4&IPv6\) in block detected](#)
- [Invalid mix of IP address data \(Dst IP type\) in set detected](#)
- [Invalid mix of IP address data \(Dst IP/type\) in set detected](#)
- [Invalid mix of IP and non-IP data in set detected](#)
- [Invalid mix of IP data \(IPv4 IPv6\) in set detected](#)
- [Invalid mix of IP data \(IPv4/IPv6\) in set detected](#)
- [Invalid mix of IP type data \(options/non-IP\) in set detected](#)
- [Invalid option specified for BcastFrames attribute](#)
- [Invalid option specified for KnownIpMcast attribute](#)
- [Invalid option specified for KnownMcastFrames attribute](#)
- [Invalid option specified for KnownNonIpMcast attribute](#)
- [Invalid option specified for KnownUcastFrames attribute](#)
- [Invalid option specified for NonIpPkt attribute](#)
- [Invalid option specified for PatternIpVersion attribute](#)
- [Invalid option specified for PatternL2Format attribute](#)
- [Invalid option specified for UnknownIpMcast attribute](#)
- [Invalid option specified for UnknownMcastFrames attribute](#)
- [Invalid option specified for UnknownNonIpMcast attribute](#)
- [Invalid option specified for UnknownUcastFrames attribute](#)
- [Invalid parameters on egress stage \(not currently supported\)](#)
- [Invalid pattern data length \(untagged format\) specified](#)
- [Invalid pattern data string length specified](#)
- [Invalid pattern format data specified](#)
- [Invalid pattern position string length specified](#)
- [Invalid port detected in specified port mask](#)
- [Invalid 802.1p user priority value specified \(%d\)](#)
- [Invalid 802.1p user priority value specified \( priority value \)](#)
- [Invalid resetToDefaults value specified](#)
- [Invalid set drop precedence value specified](#)
- [Invalid shaping data \(bucket size\) specified for interface\(s\)](#)
- [Invalid shaping data \(granularity\) specified for interface\(s\)](#)
- [Invalid shaping data \(minimum rate granularity\) specified](#)
- [Invalid shaping data \(minimum rate > maximum rate\) specified](#)
- [Invalid shaping data \(minimum rate maximum rate\) specified](#)
- [Invalid shaping data \(minimum rate\) specified](#)
- [Invalid shaping data \(rate\) specified for interface\(s\)](#)
- [Invalid source MAC address length specified](#)
- [Invalid source MAC address mask length specified](#)
- [Invalid statistics counter identification specified](#)
- [Invalid statistics tracking value](#)
- [Invalid statistics type value](#)
- [Invalid track statistics value specified](#)

- [Invalid/unknown access assignment entry state encountered \(%d\)](#)
- [Invalid unknown access assignment entry state encountered \( entry state \)](#)
- [Invalid/unknown access element entry state encountered \(%d\)](#)
- [Invalid unknown access element entry state encountered \( entry state \)](#)
- [Invalid/unknown action entry state encountered \(%d\)](#)
- [Invalid unknown action entry state encountered \( entry state \)](#)
- [Invalid unknown bandwidth type specified](#)
- [Invalid/unknown bandwidth type specified](#)
- [Invalid/unknown classifier block entry state encountered \(%d\)](#)
- [Invalid unknown classifier block entry state encountered \( entry state \)](#)
- [Invalid/unknown CoS shaping entry state encountered \(%d\)](#)
- [Invalid unknown CoS shaping entry state encountered \( entry state \)](#)
- [Invalid/unknown count action entry state encountered \(%d\)](#)
- [Invalid/unknown DSCP mapping entry state encountered \(%d\)](#)
- [Invalid unknown DSCP mapping entry state encountered \( entry state \)](#)
- [Invalid unknown entry state \(class class# \) encountered \( entry state \)](#)
- [Invalid/unknown entry state \(class %d\) encountered \(%d\)](#)
- [Invalid/unknown FCoE redirection entry state encountered \(%d\)](#)
- [Invalid/unknown interface action entry state encountered \(%d\)](#)
- [Invalid unknown interface action entry state encountered \( entry state \)](#)
- [Invalid/unknown interface app entry state encountered \(%d\)](#)
- [Invalid/unknown interface app entry state encountered \(<entry state>\)](#)
- [Invalid/unknown interface assignment entry state encountered \(%d\)](#)
- [Invalid unknown interface assignment entry state encountered \( entry state \)](#)
- [Invalid/unknown interface queue entry state encountered \(%d\)](#)
- [Invalid unknown interface queue entry state encountered \( entry state \)](#)
- [Invalid/unknown interface shaping entry state encountered \(%d\)](#)
- [Invalid unknown interface shaping entry state encountered \( entry# \)](#)
- [Invalid/unknown IP filter entry state encountered \(%d\)](#)
- [Invalid unknown IP filter entry state encountered \( entry state \)](#)
- [Invalid/unknown Layer 2 filter entry state encountered \(%d\)](#)
- [Invalid unknown Layer 2 filter entry state encountered \( entry state \)](#)
- [Invalid/unknown meter entry state encountered \(%d\)](#)
- [Invalid unknown meter entry state encountered \( entry state \)](#)
- [Invalid/unknown policy entry state encountered \(%d\)](#)
- [Invalid unknown policy entry state encountered \( entry state \)](#)
- [Invalid/unknown 802.1p user priority mapping entry state \(%d\)](#)
- [Invalid unknown 802.1p user priority mapping entry state \( entry state \)](#)
- [Invalid/unknown queue set assignment entry state encountered \(%d\)](#)
- [Invalid unknown queue set assignment entry state encountered \( entry state \)](#)
- [Invalid/unknown queue shaping entry state encountered \(%d\)](#)
- [Invalid unknown queue shaping entry state encountered \( entry state \)](#)
- [Invalid/unknown queuing discipline enum specified \(%d\)](#)
- [Invalid unknown queuing discipline enum specified \( queuing discipline \)](#)
- [Invalid/unknown role combination entry state encountered \(%d\)](#)
- [Invalid unknown role combination entry state encountered \( entry state \)](#)
- [Invalid/unknown System filter entry state encountered \(%d\)](#)
- [Invalid unknown System filter entry state encountered \( entry state \)](#)
- [Invalid/unknown token bucket entry state encountered \(%d\)](#)
- [Invalid unknown token bucket entry state encountered \( entry state \)](#)
- [Invalid/unknown user policy entry state encountered \(%d\)](#)
- [Invalid unknown user policy entry state encountered \( entry state \)](#)
- [Invalid/unsupported AutoOoS mode value specified](#)
- [Invalid unsupported buffering capabilities value specified](#)
- [Invalid/unsupported buffering capabilities value specified](#)
- [Invalid/unsupported classifier allocation mode specified](#)
- [Invalid/unsupported classifier meter type specified](#)
- [Invalid unsupported copy-to-cpu option specified](#)
- [Invalid/unsupported copy-to-cpu option specified](#)
- [Invalid unsupported DAPP enable value specified](#)
- [Invalid/unsupported DAPP enable value specified](#)
- [Invalid unsupported DAPP maximum IPv4 ICMP length specified](#)
- [Invalid unsupported DAPP maximum IPv6 ICMP length specified](#)
- [Invalid/unsupported DAPP maximum IPv4 ICMP length specified](#)
- [Invalid/unsupported DAPP maximum IPv6 ICMP length specified](#)

- [Invalid unsupported DAPP minimum TCP header length specified](#)
- [Invalid/unsupported DAPP minimum TCP header length specified](#)
- [Invalid unsupported default gateway address length specified](#)
- [Invalid/unsupported default gateway address length specified](#)
- [Invalid unsupported default gateway address specified](#)
- [Invalid/unsupported default gateway address specified](#)
- [Invalid unsupported destination IP address length specified](#)
- [Invalid/unsupported destination IP address length specified](#)
- [Invalid unsupported DHCP server address length specified](#)
- [Invalid/unsupported DHCP server address length specified](#)
- [Invalid unsupported DHCP server address specified](#)
- [Invalid/unsupported DHCP server address specified](#)
- [Invalid/unsupported FCoE accessibility mode value specified](#)
- [Invalid/unsupported FCoE ingress interface list specified](#)
- [Invalid/unsupported FCoE redirection egress interface specified](#)
- [Invalid/unsupported FCoE redirection etherType detected](#)
- [Invalid/unsupported FCoE redirection mode value specified](#)
- [Invalid unsupported interface type specified](#)
- [Invalid/unsupported interface type specified](#)
- [Invalid/unsupported IP address/mask length specified](#)
- [Invalid/unsupported metering mode value specified](#)
- [Invalid unsupported mirror frame option specified](#)
- [Invalid/unsupported mirror frame option specified](#)
- [Invalid unsupported NT application mode value specified](#)
- [Invalid unsupported packet type value specified](#)
- [Invalid/unsupported packet type value specified](#)
- [Invalid unsupported QoS system operational mode value specified](#)
- [Invalid/unsupported QoS system operational mode value specified](#)
- [Invalid unsupported queue configuration value specified](#)
- [Invalid/unsupported queue configuration value specified](#)
- [Invalid unsupported role assoc compatibility specified](#)
- [Invalid/unsupported role assoc compatibility specified](#)
- [Invalid unsupported source IP address length specified](#)
- [Invalid/unsupported source IP address length specified](#)
- [Invalid/unsupported stage specified](#)
- [Invalid unsupported Trusted processing mode value specified](#)
- [Invalid/unsupported Trusted processing mode value specified](#)
- [Invalid unsupported UBP support level value specified](#)
- [Invalid/unsupported UBP support level value specified](#)
- [Invalid/unsupported VLAN tag value specified \(%d\)](#)
- [Invalid unsupported VLAN tag value specified \( VLAN tag \)](#)
- [Invalid update DSCP value specified \(%d\)](#)
- [Invalid update DSCP value specified \( DSCP value \)](#)
- [Invalid update DSCP value specified \(not currently supported\)](#)
- [Invalid update priority value specified](#)
- [Invalid update VLAN Id specified \(%d\)](#)
- [Invalid update VLAN Id specified \( VLAN Id \)](#)
- [Invalid user priority match selection specified \(%d\)](#)
- [Invalid user priority match selection specified \( priority value \)](#)
- [IP classifier distribution across stack failed](#)
- [IP classifier entry still referenced \(deletion prohibited\)](#)
- [IP classifier modifications not supported](#)
- [IP destination address and mask values out-of-sync](#)
- [IP destination Layer 4 port maximum value out-of-range \(%d\)](#)
- [IP destination Layer 4 port maximum value out-of-range \( dest port#](#)
- [IP destination Layer 4 port minimum value out-of-range \(%d\)](#)
- [IP destination Layer 4 port minimum value out-of-range \( dest port# \)](#)
- [IP protocol value out-of-range \(%d\)](#)
- [IP protocol value out-of-range \( IP protocol# \)](#)
- [IP protocol value TCP or UDP needed with Layer 4 port filtering](#)
- [IP source address and mask values out-of-sync](#)
- [IP source Layer 4 port maximum value out-of-range \(%d\)](#)
- [IP source Layer 4 port minimum value out-of-range \(%d\)](#)
- [IP source Layer 4 port minimum value out-of-range \( src port# \)](#)
- [IPv4-only filter criteria mixed with IPv6 criteria](#)

- [Issue detected during QoS stack synchronization](#)
- [Issue detected enabling disabling DSCP table usage \(port#\)](#)
- [Issue detected restoring QPA data from NV \(class class# \)](#)
- [Issue detected restoring QPA data from NV \(class %d\)](#)
- [Issue detected setting native DSCP table values](#)
- [Issues detected with QoS operational mode disable \(%d ifcs\)](#)
- [Issues detected with QoS operational mode disable \( ifcs# ifcs\)](#)
- [Issues detected with QoS operational mode enable \(%d ifcs\)](#)
- [Issues detected with QoS operational mode enable \( ifcs# ifcs\)](#)
- [Issue with classifier component mask detected](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QoS logs starting with L

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QoS logs starting with L

This page lists all the logs starting with the letter L that are generated by the QoS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

- [Layer 2 classifier modifications not supported](#)
- [Layer 2 classifier still referenced \(deletion prohibited\)](#)
- [Layer 2 filter distribution across stack failed](#)
- [Layer 4 port filtering with IPv6 requires UDP TCP Next Header](#)
- [Layer 4 port filtering with IPv6 requires UDP/TCP Next Header](#)
- [Layer 4 port range could not be reduced sufficiently](#)
- [Lossless and Lossless-PFC modes are only supported in queue set 2](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# QoS logs starting with M

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QoS logs starting with M

This page lists all the logs starting with the letter M that are generated by the QoS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

- [Martian packet detected with destination address mask %s on port %d/%d](#)
- [Martian packet detected with source address mask %s and destination address mask %s on port %d](#)
- [Martian packet detected with source address mask %s on port %d/%d](#)
- [Martian packet logging does not support metering](#)
- [Martian packet logging requires individual tracking statistics](#)
- [Maximum users-per-interface limit \(%d\) reached](#)
- [Meter distribution across stack failed](#)
- [Meter entry referenced by clfr block \(deletion prohibited\)](#)
- [Meter entry referenced by meter \(deletion prohibited\)](#)
- [Meter entry referenced by policy \(deletion prohibited\)](#)
- [Meter \(from clfr block\) usage in multiple policies prohibited](#)
- [Meter \(from policy\) usage in multiple policies prohibited](#)
- [Meter identifier out-of-range \(%d\)](#)
- [Meter identifier out-of-range \( meter id \)](#)
- [Metering not supported with DS L2 access control lists](#)
- [Metering not supported with DS/L2 access control lists](#)
- [Meter modifications not supported](#)
- [Mirroring \(requested via action\) not configured correctly](#)
- [Modification of action \(non-match usage\) prohibited](#)
- [Modify the pattern data or use the correct data format](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QoS logs starting with N

This page lists all the logs starting with the letter N that are generated by the QoS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

- [Network access to FCoE Redirect functionality is currently disabled](#)
- [Non-match action contains conflicting data](#)
- [Non-match action not available for use with filter sets](#)
- [Non-match action support not available on certain interfaces](#)
- [Non-QoS interfaces may not be assigned to a role combination](#)
- [Non-supported action option \(green action\) specified](#)
- [Non-supported action option \(in-profile action\) specified](#)
- [Non-supported action option \(match action\) specified](#)
- [Non-supported action option \(out-of-profile action\) specified](#)
- [Non-supported action option \(policy non-match action\) specified](#)
- [Non-supported action option \(red action\) specified](#)
- [Non-supported action option \(yellow action\) specified](#)
- [Non-unique element label detected \(prohibited\)](#)
- [Non-unique FCoE redirection entry name detected \(prohibited\)](#)
- [Non-unique precedence order value detected \(prohibited\)](#)
- [Non-volatile QoS data discarded during restoration](#)
- [Non-volatile storage commit delay too large](#)
- [Non-zero pattern data detected in masked position](#)
- [No resources available for classifier port range checking](#)
- [No resources available for classifier range checking](#)
- [NSNA filter set assignment failed](#)
- [NSNA filter set count \(%d\) exceeds limit \(%d\)](#)
- [NSNA filter set data in use \(QoS disable prohibited\)](#)
- [NSNA filter set data in use \(QoS reset prohibited\)](#)
- [NSNA filter set delete operation failed](#)
- [NSNA filter set element count exceeds available resources](#)
- [NSNA filter set install operation failed](#)
- [NSNA filter set template does not exist](#)
- [NSNA filter set update operation failed](#)
- [NSNA system port transition failed](#)
- [NT application mode enable failure - inadequate resources](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)



# QoS logs starting with O

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QoS logs starting with O

This page lists all the logs starting with the letter O that are generated by the QoS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

- [Only one frame type supported per classifier](#)
- [Out-of-profile action contains conflicting data](#)
- [Out-of-range CoS index value \( COS index value \)](#)
- [Out-of-range CoS index value \(%d\)](#)
- [Out-of-range queue index value \(%d\) for in-use queue set](#)
- [Out-of-range queue index value \(%d\) for pending queue set](#)
- [Out-of-range queue index value \(%d\) specified](#)
- [Out-of-range queue index value \( queue index \) for in-use queue set](#)
- [Out-of-range queue index value \( queue index \) for pending queue set](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QoS logs starting with P

This page lists all the logs starting with the letter P that are generated by the QoS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

- [Packet redirection support limited by target interfaces](#)
- [Packet reordering detected \(re: new mappings\)](#)
- [Pattern matching data in excess of bytes# bytes specified](#)
- [Pattern matching data in excess of %d bytes specified](#)
- [Pattern matching \(Dst IP\) not supported with IP addr type data](#)
- [Pattern matching \(Dst MAC\) not supported with address type data](#)
- [Pattern matching \(IP\) not supported with non-IP addr type data](#)
- [Pattern matching not supported with other classification data](#)
- [Pattern modifier data specified without actual pattern data](#)
- [Pattern position and data strings must be same length](#)
- [Pending filter control block already defined](#)
- [Policies with session data must be port-based](#)
- [Policy action out-of-range \( action# \)](#)
- [Policy action out-of-range \(%d\)](#)
- [Policy content incompatible with precedence allocation mode](#)
- [Policy content incompatible with target interface\(s\)](#)
- [Policy distribution across stack failed](#)
- [Policy mask availability issue \(space exhausted\)](#)
- [Policy mask issue \(space exhausted/precedence conflict\)](#)
- [Policy modifications not supported](#)
- [Policy modification support limited](#)
- [Policy non-match action out-of-range \(%d\)](#)
- [Policy non-match action out-of-range \( non-match action# \)](#)
- [Policy precedence conflict detected with non-QoS application](#)
- [Policy precedence value out-of-range for target interface\(s\)](#)
- [Policy requirements exceed available resources \(slot %d\)](#)
- [Policy requirements exceed available resources \(slot slot# \)](#)
- [Policy statistics index out-of-range \(%d\)](#)
- [Policy statistics index out-of-range \( stats index \)](#)
- [Policy with this filtering values is already installed on this precedence](#)
- [Post-join ACL installation issue detected \(ifc %d\)](#)
- [Post-join ACL installation issue detected \(ifc ifc# \)](#)
- [Post-join filter set installation issue detected \(ifc %d\)](#)
- [Post-join filter set installation issue detected \(ifc ifc# \)](#)
- [Post-join policy installation issue detected \(ifc %d\)](#)
- [Post-join traffic-profile installation issue detected \(ifc %d\)](#)
- [Post-join traffic-profile installation issue detected \(ifc ifc# \)](#)
- [Potential inconsistent access asgn state \(Undo fail\) detected](#)
- [Potential inconsistent access asgn state \(Undo fail - unit %d\)](#)
- [Potential inconsistent access elem state \(Undo fail\) detected](#)
- [Potential inconsistent access elem state \(Undo fail - unit %d\)](#)
- [Potential inconsistent block state \(Undo fail\) detected](#)
- [Potential inconsistent ifc assignment state \(Undo fail\) detected](#)
- [Potential inconsistent ifc assignment state \(Undo fail - unit %d\)](#)
- [Potential inconsistent policy state \(Undo fail\) detected](#)

[Potential inconsistent policy state \(Undo fail - unit %d\)](#)

- [Precedence value out-of-range](#)
- [Provided metering information incomplete](#)
- [802.1p user priority mapping modifications not supported](#)
- [802.1p user priority value modification prohibited](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# QoS logs starting with Q

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QoS logs starting with Q

This page lists all the logs starting with the letter Q that are generated by the QoS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

- [QoS inter-module communication failure: class %d phase %d](#)
- [QoS inter-module communication issue detected](#)
- [QoS policies may not be applied to uplink or daisy chain ports \(%d\)](#)
- [QoS policies may not be applied to uplink or daisy chain ports \( port# \)](#)
- [Queue configuration inconsistency detected \(local %d, stack %d\)](#)
- [Queue configuration inconsistency detected \(local queue conf stack queue conf \)](#)
- [Queue data distribution across stack failed](#)
- [Queue set assignment distribution across stack failed](#)
- [Queue set assignment modifications not supported](#)
- [Queue set unacceptable - pending range excludes in-use queues](#)
- [Queue set value modification prohibited](#)
- [Queue set value modification prohibited](#)
- [Queue shaping distribution across stack failed](#)
- [Queue shaping modifications not supported](#)
- [Queue shaping not supported with specified interface](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QoS logs starting with R

This page lists all the logs starting with the letter R that are generated by the QoS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

- [Rate granularity limited to increments of 1 Mbps or 64 Kbps](#)
- [Rate \(min\) granularity limited \(increments of 1 Mbps or 64 Kbps\)](#)
- [Referenced block \(by policy\) deletion prohibited](#)
- [Referenced set \(by block\) modifications prohibited](#)
- [Referenced set \(by policy\) modifications prohibited](#)
- [Referenced token bucket data invalid \(burst size\)](#)
- [Remote QoS-disable request failure \(%d on unit %d\)](#)
- [Remote QoS-disable request failure \( port# on unit unit# \)](#)
- [Requested attribute usage is currently not supported](#)
- [Requested filter manager support unavailable](#)
- [Requested precedence mask reservation not available](#)
- [Requested reserve data invalid](#)
- [Request invalid - QoS interface apps enabled on interface\(s\)](#)
- [Request invalid - specified interface currently QoS-disabled](#)
- [Request temporarily denied - QoS support is currently disabled](#)
- [Required application data not provided](#)
- [Required bandwidth information not specified](#)
- [Required FCoE filter resources unavailable - enable request denied](#)
- [Required FCoE resources currently unavailable \(unit %d\)](#)
- [Required range check resources are not currently available](#)
- [Resource alloc event timeout \(tgt all apps except QoS Agent rcv event \)](#)
- [Resource alloc event timeout \(tgt %08x rcv %08x\)](#)
- [Resources exhausted \(maximum class entries reached\)](#)
- [Resources exhausted \(maximum dynamic class entries reached\)](#)
- [Resources exhausted \(out-of-memory\)](#)
- [Role combination associated with interface \(deletion prohibited\)](#)
- [Role combination contains unacceptable characters](#)
- [Role combination distribution across stack failed](#)
- [Role combination length outside of acceptable limits](#)
- [Role combination modifications not supported](#)
- [Role combination referenced by policy \(deletion prohibited\)](#)
- [Role \(interface\) capabilities incompatible with policy data](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QoS logs starting with S

This page lists all the logs starting with the letter S that are generated by the QoS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

- [Set drop precedence value and update DSCP value out-of-sync](#)
- [Simultaneous operations involving access asgn ifcs prohibited](#)
- [Simultaneous operations involving access asgn/ifcs prohibited](#)
- [Simultaneous operations involving policies and blocks prohibited](#)
- [Simultaneous operations involving policies and ifcs prohibited](#)
- [Simultaneous operations involving policy blocks ifcs prohibited](#)
- [Simultaneous operations involving policy blocks/ifcs prohibited](#)
- [Source MAC address and mask values out-of-sync](#)
- [Specified Destination Layer 4 min max range not supported](#)
- [Specified Destination Layer 4 min/max range not supported](#)
- [Specified filter criteria contains conflicting data](#)
- [Specified filter criteria is invalid inconsistent](#)
- [Specified filter criteria is invalid/inconsistent](#)
- [Specified filter criteria too complex](#)
- [Specified filter information not found](#)
- [Specified filter manager resource invalid](#)
- [Specified filter manager resource uninitialized](#)
- [Specified inner VLAN ID min max range not supported](#)
- [Specified inner VLAN ID min/max range not supported](#)
- [Specified metering operation not supported](#)
- [Specified metering statistics entry already in-use \(by policy\)](#)
- [Specified policy components \(classifiers\) conflicting](#)
- [Specified policy criteria too complex](#)
- [Specified policy identifier \(cookie\) invalid](#)
- [Specified policy statistics entry already in-use \(by meter\)](#)
- [Specified precedence mask reservation not found](#)
- [Specified precedence mask reservation parameter invalid](#)
- [Specified queue set information invalid](#)
- [Specified rule/precedence mask reservation not found](#)
- [Specified shaping bucket size out of supported range](#)
- [Specified shaping rate out of supported range](#)
- [Specified Source Layer 4 min max range not supported](#)
- [Specified Source Layer 4 min/max range not supported](#)
- [Specified statistics tracking operation not supported](#)
- [Specified token bucket criteria out of range](#)
- [Specified token bucket refresh interval not supported](#)
- [Specified token bucket size \(burst size\) not supported](#)
- [Specified user policy interface currently QoS-disabled](#)
- [Specified VLAN ID min max range not supported](#)
- [Specified VLAN ID min/max range not supported](#)
- [Src Layer 4 port min max values invalid \(max must be = to min\)](#)
- [Src Layer 4 port min/max values invalid \(max must be >= to min\)](#)
- [srTCM meter issue - CIR must be the same in both meters](#)
- [srTCM meter issue - EBS must be greater than CBS](#)
- [srTCM trTCM meter issue - diff algorithms in associated meters](#)

[srTCM/trTCM meter issue - diff algorithms in associated meters](#)

- [srTCM trTCM meter issue - referenced meter incompatible unknown](#)
- [srTCM/trTCM meter issue - referenced meter incompatible/unknown](#)
- [srTCM trTCM meter issue - too many cascaded meters](#)
- [srTCM/trTCM meter issue - too many cascaded meters](#)
- [Static role association not found for ifc, default was used \(%d/%d\)](#)
- [System classifier modifications not supported](#)
- [System classifier still referenced \(deletion prohibited\)](#)
- [System filter distribution across stack failed](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QoS logs starting with T

This page lists all the logs starting with the letter T that are generated by the QoS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

- [TCP Control Flag filter criteria requires TCP protocol](#)
- [Temporary access assignment sync issue detected \(lfc %d\)](#)
- [Temporary interface assignment sync issue detected \(lfc %d\)](#)
- [Temporary QoS inter-module communication issue encountered](#)
- [Token bucket algorithm identifier invalid](#)
- [Token bucket algorithm identifier unknown unsupported](#)
- [Token bucket algorithm identifier unknown/unsupported](#)
- [Token bucket data distribution across stack failed](#)
- [Token bucket entry referenced by meter \(deletion prohibited\)](#)
- [Token bucket entry referenced by shaper \(deletion prohibited\)](#)
- [Token bucket minimum rate outside limits \(64 - 10230000 Kbps\)](#)
- [Token bucket modifications not supported](#)
- [Token bucket rate outside limits \(64 - 10230000 Kbps\)](#)
- [Token bucket size not compatible with committed fill rate](#)
- [Traffic Prof filter set delete operation failed](#)
- [Traffic Prof filter set elem count exceeds available resources](#)
- [Traffic Prof filter set install operation failed](#)
- [Traffic Prof filter set policy count \(%d\) exceeds limit \(%d\)](#)
- [Traffic Prof filter set policy count \( policy count \) exceeds limit \( policy limit \)](#)
- [Traffic Prof filter set rule count \(%d\) exceeds limit \(%d\)](#)
- [Traffic Prof filter set rule count \( rule count \) exceeds limit \( rule limit \)](#)
- [Traffic Prof filter set update operation failed](#)
- [Traffic Prof installation conflict seen \(ID %d lfc %d\)](#)
- [trTCM meter issue - PBS must be greater than CBS](#)
- [trTCM meter issue - PIR must be greater than CIR](#)
- [Trusted processing mode change rejected - inadequate resources](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QoS logs starting with U

This page lists all the logs starting with the letter U that are generated by the QoS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

- [Unable to add block member \( block elem# component set id \) to existing policy](#)
- [Unable to add block member \(%d/%d\) to existing policy](#)
- [Unable to apply existing policy data to interface \(%d/%d\)](#)
- [Unable to apply existing policy data to interface \( unit# port# \)](#)
- [Unable to apply existing user-based policy data to new user](#)
- [Unable to apply filter set to ports \(unsupported capabilities\)](#)
- [Unable to apply newly-defined UBP filter set to existing user](#)
- [Unable to apply pre-defined UBP filter set to new user](#)
- [Unable to apply pre-defined UBP filter set to new user \(port %d/%d\)](#)
- [Unable to complete requested access asgn system operation \(%d\)](#)
- [Unable to complete requested access asgn system operation \( oper type \)](#)
- [Unable to complete requested policy system operation \(%d\)](#)
- [Unable to complete requested policy system operation \( operation type \)](#)
- [Unable to compress classification criteria in set adequately](#)
- [Unable to compress specified policy criteria](#)
- [Unable to create action for access element](#)
- [Unable to create classifier block entry for access element](#)
- [Unable to create classifier component entry for access element](#)
- [Unable to create count action \(meter\) for access assignment](#)
- [Unable to create count action \(policy\) for access assignment](#)
- [Unable to create count action \(secondary meter\) for access asgn](#)
- [Unable to create DS MF classifier for access element](#)
- [Unable to create L2 MF classifier for access element](#)
- [Unable to create metering data for access assignment](#)
- [Unable to create non-match components for ACL](#)
- [Unable to create out-of-profile action for access assignment](#)
- [Unable to create policy data for access assignment](#)
- [Unable to create secondary metering data for access assignment](#)
- [Unable to create secondary token bucket data for access asgn](#)
- [Unable to create token bucket data for access assignment](#)
- [Unable to create yellow action for access assignment](#)
- [Unable to deactivate policy associated with interface](#)
- [Unable to delete block member \( block element# component set id \) from existing policy](#)
- [Unable to delete block member \(%d/%d\) from existing policy](#)
- [Unable to delete UBP filter set on interface %d](#)
- [Unable to delete UBP filter set on interface ifc#](#)
- [Unable to derive suitable filter set element eval precedence](#)
- [Unable to determine clfr interface\(s\) compatibility](#)
- [Unable to determine clfr/interface\(s\) compatibility](#)
- [Unable to determine meter/interface\(s\) compatibility](#)
- [Unable to disable ARP Spoofing support on interface \(%d\)](#)
- [Unable to disable ARP Spoofing support on interface \( ifc# \)](#)
- [Unable to disable BPDUBIkr support on interface \(%d\)](#)
- [Unable to disable BPDUBIkr support on interface \( ifc# \)](#)
- [Unable to disable DHCP Snooping support on interface \(%d\)](#)



- [Unable to disable DHCP Snooping support on interface \( ifc# \)](#)
- [Unable to disable DHCP Spoofing support on interface \(%d\)](#)
- [Unable to disable DHCP Spoofing support on interface \( ifc# \)](#)
- [Unable to disable DNSPort support on interface \(%d\)](#)
- [Unable to disable DNSPort support on interface \( ifc# \)](#)
- [Unable to disable existing policy data on interface \(%d/%d\)](#)
- [Unable to disable existing policy data on interface \( unit# port# \)](#)
- [Unable to disable FTPPort support on interface \(%d\)](#)
- [Unable to disable FTPPort support on interface \( ifc# \)](#)
- [Unable to disable Nachia support on interface \(%d\)](#)
- [Unable to disable Nachia support on interface \( ifc# \)](#)
- [Unable to disable policy data for access assignment](#)
- [Unable to disable SQLSlam support on interface \(%d\)](#)
- [Unable to disable SQLSlam support on interface \( ifc# \)](#)
- [Unable to disable SynFinScan support on interface \(%d\)](#)
- [Unable to disable SynFinScan support on interface \( ifc# \)](#)
- [Unable to disable Xmas support on interface \(%d\)](#)
- [Unable to disable Xmas support on interface \( ifc# \)](#)
- [Unable to enable ARP Spoofing support on interface \(%d\)](#)
- [Unable to enable ARP Spoofing support on interface \( ifc# \)](#)
- [Unable to enable BPDUBIkr support on interface \(%d\)](#)
- [Unable to enable BPDUBIkr support on interface \( ifc# \)](#)
- [Unable to enable BPDUBIkr support on multiple interfaces](#)
- [Unable to enable DHCP Snooping support on interface \(%d\)](#)
- [Unable to enable DHCP Snooping support on interface \( ifc# \)](#)
- [Unable to enable DHCP Spoofing support on interface \(%d\)](#)
- [Unable to enable DHCP Spoofing support on interface \( ifc# \)](#)
- [Unable to enable DNSPort support on interface \(%d\)](#)
- [Unable to enable DNSPort support on interface \( ifc# \)](#)
- [Unable to enable FTPPort support on interface \(%d\)](#)
- [Unable to enable FTPPort support on interface \( ifc# \)](#)
- [Unable to enable Nachia support on interface \(%d\)](#)
- [Unable to enable Nachia support on interface \( ifc# \)](#)
- [Unable to enable policy data for access assignment](#)
- [Unable to enable SQLSlam support on interface \(%d\)](#)
- [Unable to enable SQLSlam support on interface \( ifc# \)](#)
- [Unable to enable SynFinScan support on interface \(%d\)](#)
- [Unable to enable SynFinScan support on interface \( ifc# \)](#)
- [Unable to enable Xmas support on interface \(%d\)](#)
- [Unable to inform SPB of ifc assignment change \(%d/%d\)](#)
- [Unable to install access assignment - component creation issue](#)
- [Unable to install access element - component creation issue](#)
- [Unable to locate corresponding DS L2 access elements](#)
- [Unable to locate corresponding DS/L2 access elements](#)
- [Unable to manipulate DAPP support \(no applicable interfaces\)](#)
- [Unable to modify access assignment - component modify issue](#)
- [Unable to relinquish FCoE resource reservations](#)
- [Unable to restore dynamic ifc to default role association \(%d/%d\)](#)
- [Unable to restore dynamic ifc to static role association \(%d/%d\)](#)
- [Unable to validate metering data - request denied](#)
- [Unable to verify required filter criteria](#)
- [Unicast \(%d\) and Non-Unicast \(%d\) interfaces in conflict](#)
- [Unicast \( Interface# \) and Non-Unicast \( interface# \) interfaces in conflict](#)
- [Unknown access assignment entry specified \(%d\)](#)
- [Unknown access element entry specified \(%d\)](#)
- [Unknown access element entry specified \( entry# \)](#)
- [Unknown action entry specified \(%d\)](#)
- [Unknown action entry specified \( entry# \)](#)
- [Unknown classifier block entry specified \(%d\)](#)
- [Unknown classifier block entry specified \( entry# \)](#)
- [Unknown classifier component entry specified \(%d\)](#)
- [Unknown classifier component entry specified \( entry# \)](#)
- [Unknown CoS shaping entry specified \(%d/%d\)](#)
- [Unknown CoS shaping entry specified \( entry# CoS \)](#)
- [Unknown count action entry specified \(%d\)](#)

- [Unknown count action entry specified \( entry# \)](#)
- [Unknown DSCP mapping entry specified \(%d\)](#)
- [Unknown DSCP mapping entry specified \( entry# \)](#)
- [Unknown entry \(class class# \) specified \( entry# \)](#)
- [Unknown entry \(class %d\) specified \(%d\)](#)
- [Unknown FCoE redirection entry specified \(%d\)](#)
- [Unknown incompatible access element specified](#)
- [Unknown/incompatible access element specified](#)
- [Unknown incompatible action component specified](#)
- [Unknown/incompatible action component specified](#)
- [Unknown incompatible classifier block specified](#)
- [Unknown/incompatible classifier block specified](#)
- [Unknown incompatible classifier set specified](#)
- [Unknown/incompatible classifier set specified](#)
- [Unknown incompatible in-profile action specified](#)
- [Unknown/incompatible in-profile action specified](#)
- [Unknown incompatible in-profile \(green\) action specified](#)
- [Unknown/incompatible in-profile \(green\) action specified](#)
- [Unknown incompatible match action specified](#)
- [Unknown/incompatible match action specified](#)
- [Unknown incompatible metering component specified](#)
- [Unknown/incompatible metering component specified](#)
- [Unknown incompatible metering statistics entry specified](#)
- [Unknown/incompatible metering statistics entry specified](#)
- [Unknown incompatible out-of-profile action specified](#)
- [Unknown/incompatible out-of-profile action specified](#)
- [Unknown incompatible out-of-profile \(red\) action specified](#)
- [Unknown/incompatible out-of-profile \(red\) action specified](#)
- [Unknown incompatible out-of-profile \(yellow\) action specified](#)
- [Unknown/incompatible out-of-profile \(yellow\) action specified](#)
- [Unknown incompatible policy non-match action specified](#)
- [Unknown/incompatible policy non-match action specified](#)
- [Unknown incompatible policy statistics entry specified](#)
- [Unknown/incompatible policy statistics entry specified](#)
- [Unknown incompatible queue set specified](#)
- [Unknown/incompatible queue set specified](#)
- [Unknown incompatible role combination specified](#)
- [Unknown/incompatible role combination specified](#)
- [Unknown incompatible token bucket reference specified](#)
- [Unknown incompatible token bucket reference specified](#)
- [Unknown/incompatible token bucket reference specified](#)
- [Unknown interface application entry specified \(%d\)](#)
- [Unknown interface application entry specified \( entry# \)](#)
- [Unknown interface assignment entry specified \(%d\)](#)
- [Unknown interface assignment entry specified \( entry# \)](#)
- [Unknown interface queue entry specified \(%d\)](#)
- [Unknown interface queue entry specified \( ifc queue id \)](#)
- [Unknown interface shaping entry specified \(%d\)](#)
- [Unknown interface shaping entry specified \( entry# \)](#)
- [Unknown IP classifier entry specified \(%d\)](#)
- [Unknown Layer 2 classifier entry specified \(%d\)](#)
- [Unknown Layer 2 classifier entry specified \( entry# \)](#)
- [Unknown meter entry specified \(%d\)](#)
- [Unknown/out-of-range interface index value \(%d\)](#)
- [Unknown out-of-range interface index value \( ifc# \)](#)
- [Unknown out-of-range interface index value \( ifc index \)](#)
- [Unknown policy entry specified \(%d\)](#)
- [Unknown policy entry specified \( entry# \)](#)
- [Unknown 802.1p user priority mapping entry specified \(%d\)](#)
- [Unknown 802.1p user priority mapping entry specified \( entry# \)](#)
- [Unknown queue set assignment entry specified \(%d\)](#)
- [Unknown queue set assignment entry specified \( entry# \)](#)
- [Unknown queue set queue reference detected](#)
- [Unknown queue set/queue reference detected](#)
- [Unknown queue shaping entry specified \(%d/%d\)](#)

- [Unknown queue shaping entry specified \( entry# queue \)](#)
- [Unknown role combination entry specified \(%d\)](#)
- [Unknown role combination entry specified \( role comb id \)](#)
- [Unknown System classifier entry specified \(%d\)](#)
- [Unknown System classifier entry specified \( entry# \)](#)
- [Unknown token bucket entry specified \(%d\)](#)
- [Unknown token bucket entry specified \( entry# \)](#)
- [Unknown unsupported attribute specified \( attribute \)](#)
- [Unknown/unsupported attribute specified \(%d\)](#)
- [Unknown unsupported interface application type specified](#)
- [Unknown/unsupported interface application type specified](#)
- [Unknown/unsupported interface class specified \(%d\)](#)
- [Unknown unsupported interface class specified \( ifc class \)](#)
- [Unknown unsupported IP Flag specified](#)
- [Unknown/unsupported IP Flag specified](#)
- [Unknown unsupported RowStatus specified](#)
- [Unknown/unsupported RowStatus specified](#)
- [Unknown unsupported StorageType specified](#)
- [Unknown/unsupported StorageType specified](#)
- [Unknown unsupported TCP Control Flag specified](#)
- [Unknown/unsupported TCP Control Flag specified](#)
- [Unknown user policy entry specified \(%d\)](#)
- [Unknown user policy entry specified \( entry# \)](#)
- [Unsupported IP address type specified](#)
- [Unsupported IPv4 Options value specified](#)
- [Unsupported pattern offset data specified](#)
- [Unsupported unknown QoS agent configuration attribute \( attribute# \)](#)
- [Unsupported/unknown QoS agent configuration attribute \(%d\)](#)
- [Update priority value and update DSCP value out-of-sync](#)
- [Update priority value per ingress DSCP currently not supported](#)
- [User Policy data referencing interface \(operation prohibited\)](#)
- [User policy distribution across stack failed](#)
- [User policy filter set count \(%d\) exceeds limit \(%d\)](#)
- [User policy filter set count \(<set count>\) exceeds limit \(<set limit>\)](#)
- [User policy filter set delete operation failed](#)
- [User policy filter set element count exceeds available resources](#)
- [User policy filter set install operation failed](#)
- [User policy filter set update operation failed](#)
- [User policy group contains invalid unacceptable characters](#)
- [User policy group contains invalid/unacceptable characters](#)
- [User policy group length outside of acceptable limits](#)
- [User policy modifications not supported](#)
- [User policy name contains invalid unacceptable characters](#)
- [User policy name contains invalid/unacceptable characters](#)
- [User policy name length outside of acceptable limits](#)
- [User Policy \(UBP\) filter set in use \(QoS disable prohibited\)](#)
- [User Policy \(UBP\) filter set in use \(QoS reset prohibited\)](#)
- [User priority specified with untagged frames \(invalid\)](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)



# QoS logs starting with V

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## QoS logs starting with V

This page lists all the logs starting with the letter V that are generated by the QoS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

- [VLAN ID min/max values invalid \(%d !< %d\)](#)
- [VLAN ID min max values invalid \( min VLAN ID ! max VLAN ID \)](#)
- [VLAN range could not be reduced sufficiently](#)
- [VLAN range support with FCoE redirection not available](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Fabric Attach logs starting with F

This page lists all the logs starting with the letter F that are generated by the Fabric Attach source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[E](#)

- [Fabric Attach: agent settings reset incomplete](#)
- [Fabric Attach: application discovery notification \(event %d\)](#)
- [Fabric Attach: application state notification \(event %d\)](#)
- [Fabric Attach: asgn activation failure \(port tagging\)](#)
- [Fabric Attach: asgn activation failure \(PVID update\)](#)
- [Fabric Attach: asgn activation failure \(switched UNI creation\)](#)
- [Fabric Attach: asgn activation failure \(VLAN creation\)](#)
- [Fabric Attach: asgn activation failure \(VLAN membership\)](#)
- [Fabric Attach: asgn rejection failure \(port PVID update\)](#)
- [Fabric Attach: asgn rejection failure \(switched UNI deletion\)](#)
- [Fabric Attach: asgn rejection failure \(VLAN deletion\)](#)
- [Fabric Attach: asgn rejection failure \(VLAN membership\)](#)
- [Fabric Attach: asgn reset issues \(%d asgns\)](#)
- [Fabric Attach: Auto Attach capabilities disabled](#)
- [Fabric Attach: Auto Attach capabilities enabled](#)
- [Fabric Attach: auto attach operations not completed \(VLAN <VID>\)](#)
- [Fabric Attach: auto provision setting not supported by platform](#)
- [Fabric Attach: binding acceptance failure \(ifc %d %d/%d\)](#)
- [Fabric Attach: binding acceptance failure \(port %d %d/%d\)](#)
- [Fabric Attach: binding acceptance failure \(port %d/%d %d/%d\)](#)
- [Fabric Attach: binding accepted \(ifc %d %d/%d\)](#)
- [Fabric Attach: binding accepted \(port %d %d/%d\)](#)
- [Fabric Attach: binding accepted \(port %d/%d %d/%d\)](#)
- [Fabric Attach: binding activation failure \(%d/%d\)](#)
- [Fabric Attach: binding activation success \(ifc %d %d/%d\)](#)
- [Fabric Attach: binding activation success \(port %d %d/%d\)](#)
- [Fabric Attach: binding activation success \(port %d/%d %d/%d\)](#)
- [Fabric Attach: binding activation success \(trunk %d %d/%d\)](#)
- [Fabric Attach: binding deactivation failure \(ifc %d %d/%d\)](#)
- [Fabric Attach: binding deactivation failure \(port %d %d/%d\)](#)
- [Fabric Attach: binding deactivation failure \(port %d/%d %d/%d\)](#)
- [Fabric Attach: binding deactivation failure \(trunk %d %d/%d\)](#)
- [Fabric Attach: binding deactivation success \(ifc %d %d/%d\)](#)
- [Fabric Attach: binding deactivation success \(port %d %d/%d\)](#)
- [Fabric Attach: binding deactivation success \(port %d/%d %d/%d\)](#)
- [Fabric Attach: binding deactivation success \(trunk %d %d/%d\)](#)
- [Fabric Attach: binding deleted \(ifc %d %d/%d\)](#)
- [Fabric Attach: binding expiration \(ifc %d %d/%d\)](#)
- [Fabric Attach: binding expiration \(port %d %d/%d\)](#)
- [Fabric Attach: binding expiration \(port %d/%d %d/%d\)](#)
- [Fabric Attach: binding updated \(ifc %d %d/%d\)](#)
- [Fabric Attach: can't transition to server from standalone mode](#)
- [Fabric Attach: can't update standalone mode setting in server mode](#)
- [Fabric Attach: client attach delete failure - Type %d \(VLAN deletion\)](#)
- [Fabric Attach: client attach delete failure - Type %d \(VLAN membership\)](#)

- [Fabric Attach: client attach install failure - Type %d \(I-SID/VLAN binding install\)](#)
- [Fabric Attach: client attach install failure - Type %d \(priority update\)](#)
- [Fabric Attach: client attach install failure - Type %d \(PVID update\)](#)
- [Fabric Attach: client attach install failure - Type %d \(tagging mode update\)](#)
- [Fabric Attach: client attach install failure - Type %d \(VLAN creation\)](#)
- [Fabric Attach: client attach install failure - Type %d \(VLAN membership\)](#)
- [Fabric Attach: client binding accepted \(%d/%d/%d\)](#)
- [Fabric Attach: client binding conflict detected \(%d/%d/%d\)](#)
- [Fabric Attach: client binding deleted \(%d/%d/%d\)](#)
- [Fabric Attach: client detection settings update failed \(type %d\)](#)
- [Fabric Attach: client settings update failed \(type %d\)](#)
- [Fabric Attach: client update requires global zero touch option be enabled](#)
- [Fabric Attach: conflicting uplink data detected](#)
- [Fabric Attach: device deleted \(port %d\)](#)
- [Fabric Attach: device deleted \(port %d/%d\)](#)
- [Fabric Attach: device deleted \(stack operations\)](#)
- [Fabric Attach: device deleted \(trunk %d port %d\)](#)
- [Fabric Attach: device deleted \(trunk %d port %d/%d\)](#)
- [Fabric Attach: device discovered \(Auth Fail - element %d port %d\)](#)
- [Fabric Attach: device discovered \(Auth Fail - element %d port %d/%d\)](#)
- [Fabric Attach: device discovered \(Auth Fail - element %d trunk %d port %d\)](#)
- [Fabric Attach: device discovered \(Auth Fail - element %d trunk %d port %d/%d\)](#)
- [Fabric Attach: device discovered \(Auth Pass - element %d port %d\)](#)
- [Fabric Attach: device discovered \(Auth Pass - element %d port %d/%d\)](#)
- [Fabric Attach: device discovered \(Auth Pass - element %d trunk %d port %d\)](#)
- [Fabric Attach: device discovered \(Auth Pass - element %d trunk %d port %d/%d\)](#)
- [Fabric Attach: device discovered \(Not Auth - element %d port %d\)](#)
- [Fabric Attach: device discovered \(Not Auth - element %d port %d/%d\)](#)
- [Fabric Attach: device discovered \(Not Auth - element %d trunk %d port %d\)](#)
- [Fabric Attach: device discovered \(Not Auth - element %d trunk %d port %d/%d\)](#)
- [Fabric Attach: device expired \(port %d\)](#)
- [Fabric Attach: device expired \(port %d/%d\)](#)
- [Fabric Attach: device expired \(trunk %d port %d\)](#)
- [Fabric Attach: device expired \(trunk %d port %d/%d\)](#)
- [Fabric Attach: EAP notification - discovery \(ifc %d type %d\)](#)
- [Fabric Attach: EAP notification - expiration \(ifc %d type %d\)](#)
- [Fabric Attach: element type updated](#)
- [Fabric Attach: expiration cleanup issue detected \(%d secs\)](#)
- [Fabric Attach: incompatible device advertisement \(port %d\)](#)
- [Fabric Attach: incompatible device advertisement \(port %d/%d\)](#)
- [Fabric Attach: incompatible \(non-EAP\) zero touch options cleared during restore](#)
- [Fabric Attach: interface-specific I-SID/VLAN assignments not allowed](#)
- [Fabric Attach: internal client \(%d/%d/%d\) creation failure](#)
- [Fabric Attach: internal client \(%d/%d/%d\) creation success](#)
- [Fabric Attach: internal client \(%d/%d/%d\) deletion failure](#)
- [Fabric Attach: internal client \(%d/%d/%d\) deletion success](#)
- [Fabric Attach: invalid client detection data \(type %d\)](#)
- [Fabric Attach: invalid client detection element type \(type %d\)](#)
- [Fabric Attach: invalid MAC address range data \(type %d\)](#)
- [Fabric Attach: invalid VLAN data \(unknown or incompatible type\)](#)
- [Fabric Attach: invalid zero touch client custom ID \(type %d\)](#)
- [Fabric Attach: invalid zero touch client description \(type %d\)](#)
- [Fabric Attach: invalid zero touch client name \(type %d\)](#)
- [Fabric Attach: invalid zero touch client options \(type %d\)](#)
- [Fabric Attach: I-SID/VLAN assignment creation failure \(unexpected\)](#)
- [Fabric Attach: I-SID/VLAN assignment deletion failure \(unexpected\)](#)
- [Fabric Attach: LLDP sync issue - add \(%d/%d/%d\)](#)
- [Fabric Attach: LLDP sync issue - delete \(%d/%d/%d\)](#)
- [Fabric Attach: LLDP sync issue - update \(%d/%d/%d\)](#)
- [Fabric Attach: local asgn - created \(%d/%d\)](#)
- [Fabric Attach: local asgn - deleted \(%d/%d\)](#)
- [Fabric Attach: management VLAN updated \(was %d, now %d\) by zero touch auto-attach](#)
- [Fabric Attach: management VLAN updated \(was <VID>, now <VID>\) by Auto Attach](#)
- [Fabric Attach: message authentication support not available](#)
- [Fabric Attach: message processing \(msgid %d\)](#)



- [Fabric Attach: multiple FA Servers detected](#)
- [Fabric Attach: non-deterministic client detection data \(type %d\)](#)
- [Fabric Attach: non-MLT trunk uplink requires MLT ID/LACP key binding \(missing\)](#)
- [Fabric Attach: NVRAM port data restore failure detected](#)
- [Fabric Attach: NVRAM port data save failure detected](#)
- [Fabric Attach: NVRAM restore failure detected](#)
- [Fabric Attach: NVRAM save failure detected](#)
- [Fabric Attach: NVRAM save success \(%d local %d remote\)](#)
- [Fabric Attach: NVRAM save success \(port-specific data\)](#)
- [Fabric Attach: operation failure detected](#)
- [Fabric Attach: operation not supported \(server-only operation\)](#)
- [Fabric Attach: operation not supported \(switch-only operation\)](#)
- [Fabric Attach: operation rejected - client-owned entry](#)
- [Fabric Attach: operation rejected - CVLAN already exists](#)
- [Fabric Attach: operation rejected - entry does not exist](#)
- [Fabric Attach: operation rejected - not supported by element type](#)
- [Fabric Attach: operation rejected - service not enabled](#)
- [Fabric Attach: operation rejected - table entry limits reached](#)
- [Fabric Attach: option incompatible with other options \(type %d\)](#)
- [Fabric Attach: port authentication update - data flushed \(MLT %d\)](#)
- [Fabric Attach: port authentication update - data flushed \(port %d\)](#)
- [Fabric Attach: port authentication update - data flushed \(port %d/%d\)](#)
- [Fabric Attach: potential incomplete binding cleanup](#)
- [Fabric Attach: primary FA Server lost](#)
- [Fabric Attach: primary FA server selected \(port %d\)](#)
- [Fabric Attach: primary FA server selected \(port %d/%d\)](#)
- [Fabric Attach: primary FA server selected \(trunk %d\)](#)
- [Fabric Attach: proxy not supported by element type](#)
- [Fabric Attach: proxy sync issue - update \(%d/%d - %d\)](#)
- [Fabric Attach: rcvd invalid I-SID/VLAN asgn state \(%d - %d/%d\)](#)
- [Fabric Attach: remote asgn - switch removal \(%d/%d/%d\)](#)
- [Fabric Attach: remote smlt peer asgn - acceptance failure \(%d/%d/%d\)](#)
- [Fabric Attach: remote smlt peer asgn - accepted \(%d/%d/%d\)](#)
- [Fabric Attach: remote smlt peer asgn - deleted \(%d/%d/%d\)](#)
- [Fabric Attach: remote smlt peer asgn - updated \(%d/%d/%d\)](#)
- [Fabric Attach: remote smlt peer removal \(%d/%d/%d\)](#)
- [Fabric Attach: remote smlt peer removal issue detected](#)
- [Fabric Attach: server asgn \(%d/%d\) rejection](#)
- [Fabric Attach: server asgn \(%d/%d\) rejection - application interactions](#)
- [Fabric Attach: server asgn \(%d/%d\) rejection - invalid binding with SPBM provisioning](#)
- [Fabric Attach: server asgn \(%d/%d\) rejection - invalid VLAN](#)
- [Fabric Attach: server asgn \(%d/%d\) rejection - no FA resources](#)
- [Fabric Attach: server asgn \(%d/%d\) rejection - no VLAN resources](#)
- [Fabric Attach: server asgn \(%d/%d\) rejection - peer acceptance](#)
- [Fabric Attach: server asgn \(<ISID>/<VID>\) rejection](#)
- [Fabric Attach: server asgn \(<ISID>/<VID>\) rejection - application interactions](#)
- [Fabric Attach: server asgn \(<ISID>/<VID>\) rejection - invalid VLAN](#)
- [Fabric Attach: server asgn \(<ISID>/<VID>\) rejection - no FA resources](#)
- [Fabric Attach: server asgn \(<ISID>/<VID>\) rejection - no VLAN resources](#)
- [Fabric Attach: server connection type change](#)
- [Fabric Attach: server connection type change \(different ports\)](#)
- [Fabric Attach: server connection type change \(different trunks\)](#)
- [Fabric Attach: server connection type change \(non-trunk to trunk\)](#)
- [Fabric Attach: server connection type change \(trunk to non-trunk\)](#)
- [Fabric Attach: service disabled](#)
- [Fabric Attach: service enabled](#)
- [Fabric Attach: specified element type not supported](#)
- [Fabric Attach: specified uplink currently a trunk member](#)
- [Fabric Attach: specified uplink currently invalid](#)
- [Fabric Attach: standalone/non-standalone proxy transition \(service reset\)](#)
- [Fabric Attach: standalone proxy unavailable when SPBM is enabled](#)
- [Fabric Attach: static uplink addition failure](#)
- [Fabric Attach: static uplink deletion failure](#)
- [Fabric Attach: switch removal issue detected \(switch %d/%d\)](#)
- [Fabric Attach: temporary I-SID/VLAN binding deletion failure](#)

- [Fabric Attach: timer-related services unavailable](#)
- [Fabric Attach: trunk link automatically enabled \(MLT %d port %d/%d\)](#)
- [Fabric Attach: trusted client bindings \(%d\) exceed limit \(%d\)](#)
- [Fabric Attach: Trusted interface update - clear \(ifc %d\)](#)
- [Fabric Attach: Trusted interface update failure - clear \(ifc %d\)](#)
- [Fabric Attach: Trusted interface update failure - set \(ifc %d\)](#)
- [Fabric Attach: Trusted interface update - set \(ifc %d\)](#)
- [Fabric Attach: unknown I-SID/VLAN asgn \(update %d/%d\)](#)
- [Fabric Attach: unknown message rcvd \(msgId %d\)](#)
- [Fabric Attach: uplink operation only supported by FA Proxy](#)
- [Fabric Attach: zero touch auto-attach capabilities disabled](#)
- [Fabric Attach: zero touch auto-attach capabilities enabled](#)
- [Fabric Attach: zero touch auto-attach failure \(DHCP initiation\)](#)
- [Fabric Attach: zero touch auto-attach failure \(mgmt VLAN update\)](#)
- [Fabric Attach: zero touch auto-attach failure \(port tagging\)](#)
- [Fabric Attach: zero touch auto-attach failure \(PVID update\)](#)
- [Fabric Attach: zero touch auto-attach failure \(VLAN creation\)](#)
- [Fabric Attach: zero touch auto-attach failure \(VLAN membership\)](#)
- [Fabric Attach: zero touch auto-attach operations not completed \(mgmt VLAN %d\)](#)
- [Fabric Attach: zero touch client already exists \(type %d\)](#)
- [Fabric Attach: zero touch client attach creation \(Type %d\) failure](#)
- [Fabric Attach: zero touch client attach creation \(Type %d\) success](#)
- [Fabric Attach: zero touch client attach deletion \(Type %d\) failure](#)
- [Fabric Attach: zero touch client attach deletion \(Type %d\) success](#)
- [Fabric Attach: zero touch client attach failure - operation not supported](#)
- [Fabric Attach: zero touch client attach failure - Type %d Port %d](#)
- [Fabric Attach: zero touch client attach failure - Type %d Port %d/%d](#)
- [Fabric Attach: zero touch client attach success - Type %d Port %d](#)
- [Fabric Attach: zero touch client attach success - Type %d Port %d/%d](#)
- [Fabric Attach: zero touch client unknown \(type %d\)](#)
- [Fabric Attach: zero touch custom client deletion rejected \(type %d referenced\)](#)
- [Fabric Attach: zero touch failure \(trusted connection\)](#)
- [Fabric Attach: zero touch option failure \(PVID update ifc %d\)](#)
- [Fabric Attach: zero touch option processing failure detected](#)
- [Fabric Attach: zero touch setting read-only for FA element type](#)

E





# SNMP logs starting with A

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SNMP logs starting with A

This page lists all the logs starting with the letter A that are generated by the SNMP source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [C](#) | [D](#) | [E](#) | [I](#) | [L](#) | [P](#) | [R](#) | [S](#) | [I](#) | [W](#)

- [Authentication Failure Trap](#)

[A](#) | [C](#) | [D](#) | [E](#) | [I](#) | [L](#) | [P](#) | [R](#) | [S](#) | [I](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SNMP logs starting with C

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SNMP logs starting with C

This page lists all the logs starting with the letter C that are generated by the SNMP source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [C](#) | [D](#) | [E](#) | [I](#) | [L](#) | [P](#) | [R](#) | [S](#) | [I](#) | [W](#)

- [Cold Start Trap](#)

[A](#) | [C](#) | [D](#) | [E](#) | [I](#) | [L](#) | [P](#) | [R](#) | [S](#) | [I](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SNMP logs starting with D

This page lists all the logs starting with the letter D that are generated by the SNMP source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [C](#) | [D](#) | [E](#) | [I](#) | [L](#) | [P](#) | [R](#) | [S](#) | [T](#) | [W](#)

- [DAI: ARP packet with invalid IP/MAC binding dropped on untrusted port %d/%d. ARP packet has MAC source %02x-%02x-%02x-%02x-%02x-%02x](#)
- [DHCP Option 82 information could not be added to the DHCP packet because the resulting packet would be too long](#)
- [DHCP Snoop: DHCP ACK dropped on untrusted port %d/%d \(not allowed on untrusted port\)](#)
- [DHCP Snoop: DHCP binding table is full on unit %d, additional DHCP clients will not be added on this unit](#)
- [DHCP Snoop: DHCP DISCOVER dropped on port %d/%d \(source MAC %02x-%02x-%02x-%02x-%02x-%02x not matching client MAC %02x-%02x-%02x-%02x-%02x-%02x\)](#)
- [DHCP Snoop: DHCP INFORM dropped on port %d/%d \(source MAC %02x-%02x-%02x-%02x-%02x-%02x not matching client MAC %02x-%02x-%02x-%02x-%02x-%02x\)](#)
- [DHCP Snoop: DHCP LEASEACTIVE dropped on untrusted port %d/%d \(not allowed on untrusted port\)](#)
- [DHCP Snoop: DHCP LEASEQUERY dropped on untrusted port %d/%d \(not allowed on untrusted port\)](#)
- [DHCP Snoop: DHCP LEASEUNASSIGNED dropped on untrusted port %d/%d \(not allowed on untrusted port\)](#)
- [DHCP Snoop: DHCP LEASEUNKNOWN dropped on untrusted port %d/%d \(not allowed on untrusted port\)](#)
- [DHCP Snoop: DHCP NAK dropped on untrusted port %d/%d \(not allowed on untrusted port\)](#)
- [DHCP Snoop: DHCP OFFER dropped on untrusted port %d/%d \(not allowed on untrusted port\)](#)
- [DHCP Snoop: DHCP packet dropped on port %d/%d - static entry with the same MAC %02x-%02x-%02x-%02x-%02x-%02x in binding table](#)
- [DHCP Snoop: DHCP RELEASE/DECLINE dropped on port %d/%d \(MAC %02x-%02x-%02x-%02x-%02x-%02x does not exist in binding table\)](#)
- [DHCP Snoop: DHCP RELEASE/DECLINE dropped on port %d/%d \(MAC %02x-%02x-%02x-%02x-%02x-%02x is associated to port %d/%d\)](#)
- [DHCP Snoop: DHCP REPLY with MAC %02x-%02x-%02x-%02x-%02x-%02x and IP Lease %d.%d.%d.%d dropped \(no DHCP REQUEST was received\)](#)
- [DHCP Snoop: DHCP REQUEST dropped on port %d/%d \(source MAC %02x-%02x-%02x-%02x-%02x-%02x not matching client MAC %02x-%02x-%02x-%02x-%02x-%02x\)](#)
- [DHCP Snoop: DHCP snooping binding table restored successfully from TFTP address](#)
- [DHCP Snoop: DHCP snooping binding table restored successfully from USB unit %d](#)
- [DHCP Snoop: DHCP snooping binding table restore from TFTP address](#)
- [DHCP Snoop: DHCP snooping binding table restore from USB unit %d, failed](#)
- [DHCP Snoop: DHCP snooping binding table saved successfully to TFTP address](#)
- [DHCP Snoop: DHCP snooping binding table saved successfully to USB unit %d](#)
- [DHCP Snoop: DHCP snooping binding table save to TFTP address](#)
- [DHCP Snoop: DHCP snooping binding table save to USB unit %d, failed](#)
- [DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored \(expired lease\)](#)
- [DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored \(invalid interface %d/%d\)](#)
- [DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored \(MAC conflict\)](#)
- [DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored \(parsing failure\)](#)
- [DHCP Snoop: NTP is not synchronized; external save/restore of DHCP snooping entries not possible](#)

[A](#) | [C](#) | [D](#) | [E](#) | [I](#) | [L](#) | [P](#) | [R](#) | [S](#) | [T](#) | [W](#)





# SNMP logs starting with E

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SNMP logs starting with E

This page lists all the logs starting with the letter E that are generated by the SNMP source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [C](#) | [D](#) | [E](#) | [I](#) | [L](#) | [P](#) | [R](#) | [S](#) | [T](#) | [W](#)

- [Egp Neighbor Loss Trap](#)
- [Egp Neighbor Loss Trap](#)
- [Enterprise Specific Trap](#)
- [Enterprise Specific Trap](#)

[A](#) | [C](#) | [D](#) | [E](#) | [I](#) | [L](#) | [P](#) | [R](#) | [S](#) | [T](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SNMP logs starting with I

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SNMP logs starting with I

This page lists all the logs starting with the letter I that are generated by the SNMP source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [C](#) | [D](#) | [E](#) | [I](#) | [L](#) | [P](#) | [R](#) | [S](#) | [T](#) | [W](#)

- [IPSG: Insufficient resources available to enable IPSG on port %d/%d](#)
- [IPSG: Maximum IP entries on port %d/%d has been reached](#)

[A](#) | [C](#) | [D](#) | [E](#) | [I](#) | [L](#) | [P](#) | [R](#) | [S](#) | [T](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SNMP logs starting with L

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SNMP logs starting with L

This page lists all the logs starting with the letter L that are generated by the SNMP source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [C](#) | [D](#) | [E](#) | [I](#) | [L](#) | [P](#) | [R](#) | [S](#) | [T](#) | [W](#)

- [Link Down Trap](#)
- [Link Up Trap](#)

[A](#) | [C](#) | [D](#) | [E](#) | [I](#) | [L](#) | [P](#) | [R](#) | [S](#) | [T](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SNMP logs starting with P

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SNMP logs starting with P

This page lists all the logs starting with the letter P that are generated by the SNMP source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [C](#) | [D](#) | [E](#) | [I](#) | [L](#) | [P](#) | [R](#) | [S](#) | [T](#) | [W](#)

- [PIM: Neighbor status change](#)

[A](#) | [C](#) | [D](#) | [E](#) | [I](#) | [L](#) | [P](#) | [R](#) | [S](#) | [T](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SNMP logs starting with R

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SNMP logs starting with R

This page lists all the logs starting with the letter R that are generated by the SNMP source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [C](#) | [D](#) | [E](#) | [I](#) | [L](#) | [P](#) | [R](#) | [S](#) | [T](#) | [W](#)

- [Reset initiated through snmp](#)

[A](#) | [C](#) | [D](#) | [E](#) | [I](#) | [L](#) | [P](#) | [R](#) | [S](#) | [T](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SNMP logs starting with S

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SNMP logs starting with S

This page lists all the logs starting with the letter S that are generated by the SNMP source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [C](#) | [D](#) | [E](#) | [I](#) | [L](#) | [P](#) | [R](#) | [S](#) | [T](#) | [W](#)

- [SNMP-access is disabled](#)
- [SNMP-access is disabled](#)
- [SNMP-access is enabled](#)
- [SNMP-access is enabled](#)
- [SPBM adjacency with neighbor](#)
- [SPBM detect adj](#)
- [SPBM ISIS](#)
- [SPBM ISIS detect duplicate nick-name](#)
- [SPBM ISIS node](#)

[A](#) | [C](#) | [D](#) | [E](#) | [I](#) | [L](#) | [P](#) | [R](#) | [S](#) | [T](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SNMP logs starting with T

This page lists all the logs starting with the letter T that are generated by the SNMP source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [C](#) | [D](#) | [E](#) | [I](#) | [L](#) | [P](#) | [R](#) | [S](#) | [T](#) | [W](#)

- [Trap: avFabricAttachDiscoveredElement - ifIndex %d element %d](#)
- [Trap: avFabricAttachExpiredElement - ifIndex %d element %d](#)
- [Trap: bsAdacPortConfigNotification](#)
- [Trap: bsAdacPortOperDisabledNotification](#)
- [Trap: bsDhcpSnoopingExtSaveSFTPRestoreFailure](#)
- [Trap: bsDhcpSnoopingExtSaveSFTPRestoreSuccess](#)
- [Trap: bsDhcpSnoopingExtSaveSFTPSyncFailure](#)
- [Trap: bsDhcpSnoopingExtSaveSFTPSyncSuccess](#)
- [Trap: bsDhcpSnoopingExtSaveSFTPSyncSuccess](#)
- [Trap: bsInfnInstallationFailure](#)
- [Trap: bsIpv6NDNotificationsUntrustedPort - MAC:%02x:%02x:%02x:%02x:%02x:%02x Addr:%s Port:%hhu/%hhu](#)
- [Trap: bsIpv6NDSBTTableFull - MAC:%02x:%02x:%02x:%02x:%02x:%02x Addr:%s Port:%hhu/%hhu](#)
- [Trap: bsLstGroupOperStateChanged](#)
- [Trap: bsLstInterfaceStatusChanged](#)
- [Trap: bsnAaaAlreadyConnected](#)
- [Trap: bsnAaaIncorrectLogOnThresholdExceeded](#)
- [Trap: bsnAaaMaxNoOfSessionsExceeded](#)
- [Trap: bsnAaaUserAccountInactivityTrap](#)
- [Trap: bsnAaaUserAccountNotUsed](#)
- [Trap: bsnAaaUserPasswordAgingTrap](#)
- [Trap: bsnAaaUserPasswordExpired](#)
- [Trap: bsnAuditRecordEventsFailure](#)
- [Trap: bsnAuditStartUpTrap](#)
- [Trap: bsnAuditUnsentMessages](#)
- [Trap: bsnConfigurationSavedToNvram](#)
- [Trap: bsnEapAccessViolation](#)
- [Trap: bsnEapAccessViolationExt](#)
- [Trap: bsnEapRAVErrors](#)
- [Trap: bsnEapRAVErrorsExt](#)
- [Trap: bsnEapUbpFailure](#)
- [Trap: bsnesActivated](#)
- [Trap: bsnesDeactivated](#)
- [Trap: bsnesGloballyDisabled](#)
- [Trap: bsnesGloballyEnabled](#)
- [Trap: bsnesManuallyActivated](#)
- [Trap: bsnesManuallyDeactivated](#)
- [Trap: bsnesScheduleApplied](#)
- [Trap: bsnesScheduleNotApplied](#)
- [Trap: bsnLacPortDisabledDueToLossOfVLANPDU](#)
- [Trap: bsnLacPortEnabledDueToReceiptOfVLANPDU](#)
- [Trap: bsnLacTrunkUnavailable](#)
- [Trap: bsnLoginFailure](#)
- [Trap: bsnPortSpeedDuplexMismatch](#)
- [Trap: bsnROPasswordExpired: Read-only password expired](#)
- [Trap: bsnRWPasswordExpired: Read-write password expired](#)

- [Trap: bsnSFPIInsertion on port](#)
- [Trap: bsnSFPIInsertion on port](#)
- [Trap: bsnSFPRemoval on port](#)
- [Trap: bsnSFPRemoval on port](#)
- [Trap: bsnSnmpMaxPktSizeChanged - Maximum SNMP packet size changed to %d](#)
- [Trap: bsnStackConfigurationError](#)
- [Trap: bsnStackManagerReconfiguration](#)
- [Trap: bsnStackProtection](#)
- [Trap: bsnSystemUp365Days sent from unit %d](#)
- [Trap: bsnTrialLicenseExpiration: Trial license %d has expired. Disable licensed features to avoid network interruption](#)
- [Trap: bsnTrialLicenseExpiration: Trial license %d will expire in %d day\(s\)](#)
- [Trap: bsnTrunkPortDisabledToPreventBroadcastStorm](#)
- [Trap: bsnTrunkPortEnabledToPreventBroadcastStorm](#)
- [Trap: bsnUSBInsertion on unit](#)
- [Trap: bsnUSBInsertion on unit](#)
- [Trap: bsnUSBRemoval on unit](#)
- [Trap: bsnUSBRemoval on unit](#)
- [Trap: bspelpPhonePowerLimitNotification](#)
- [Trap: bspelpPhonePowerPriorityNotification](#)
- [Trap: bspePethPsePortCurrentStatusNotification](#)
- [Trap: bsStormControlAboveHighWatermark](#)
- [Trap: bsStormControlBelowLowWatermark](#)
- [Trap: bsUnicastStormControlAboveHighWatermark](#)
- [Trap: bsUnicastStormControlBelowLowWatermark](#)
- [Trap: bsveVrrpTrapStateTransition](#)
- [Trap: DAPP - DoS Attack Detected](#)
- [Trap: Device has entered Forced Stack Mode \(MAC:%02x:%02x:%02x:%02x:%02x:%02x IP:%s\)](#)
- [Trap: entConfigChange](#)
- [Trap: fallingAlarm](#)
- [Trap: FCoE - Egress Issue Detected](#)
- [Trap: IldpRemTableChange Ageouts = %d](#)
- [Trap: IldpRemTableChange Deletes = %d](#)
- [Trap: IldpRemTableChange Drops = %d](#)
- [Trap: IldpRemTableChange Inserts = %d](#)
- [Trap: IldpXMedTopologyChangeDetected, Subtype = %d Class = %d](#)
- [Trap: MSTP Error Event](#)
- [Trap: MSTP General Event:](#)
- [Trap: MSTP General Event:](#)
- [Trap: MSTP New Root](#)
- [Trap: MSTP Protocol Migration](#)
- [Trap: MSTP Region Config Change](#)
- [Trap: MSTP Topology Change](#)
- [Trap: newRoot](#)
- [Trap: ntnQosPolicyEvolLocalUbpSessionFailure](#)
- [Trap: ospfIfAuthFailure](#)
- [Trap: ospfIfConfigError](#)
- [Trap: ospfIfStateChange](#)
- [Trap: ospfNbrStateChange](#)
- [Trap: ospfVirtIfAuthFailure](#)
- [Trap: ospfVirtIfConfigError](#)
- [Trap: ospfVirtIfStateChange](#)
- [Trap: ospfVirtNbrStateChange](#)
- [Trap: pethMainPowerUsageOffNotification](#)
- [Trap: pethMainPowerUsageOnNotification](#)
- [Trap: pethPsePortOnOffNotification](#)
- [Trap: rclpBgpTmpAfBackwardTransitionNotification](#)
- [Trap: rclpBgpTmpAfEstablishedNotification](#)
- [Trap: rclsisPlsbBvidMismatchTrap](#)
- [Trap: rclsisPlsbLsdbUpdateTrap](#)
- [Trap: rclsisPlsbSmltPeerBmacMismatchTrap](#)
- [Trap: rclsisPlsbSmltSplitBebMismatchTrap](#)
- [Trap: rclsisPlsbSmltVirtBmacMismatchTrap](#)
- [Trap: rcVrrpExtTrapStateTransitionTrap - master ipv6 address %s, ifindex %i, vrid %i](#)
- [Trap: rcVrrpTmpTrapNewMasterTrap - master ipv6 address %s, ifindex %d, vrid %d](#)
- [Trap: risingAlarm](#)

- [Trap: RSTP Error Event](#)
- [Trap: RSTP General Event:](#)
- [Trap: RSTP General Event:](#)
- [Trap: RSTP New Root](#)
- [Trap: RSTP Protocol Migration](#)
- [Trap: RSTP Topology Change](#)
- [Trap: Run %s %s](#)
- [Trap: Run %s %s](#)
- [Trap: s5CtrFanDirectionError](#)
- [Trap: s5CtrHighTemperatureError](#)
- [Trap: s5CtrNewHotSwap](#)
- [Trap: s5CtrNewProblem](#)
- [Trap: s5CtrNewUnitDown](#)
- [Trap: s5CtrNewUnitUp](#)
- [Trap: s5EtrMacAddressTablesThresholdReached](#)
- [Trap: s5EtrNewSbsMacAccessViolation](#)
- [Trap: s5EtrSbsMacRemoved](#)
- [Trap: s5EtrSbsMacTableCleared](#)
- [Trap: s5EtrSbsMacTableClearedForPort](#)
- [Trap: s5EtrSbsMacTableFull](#)
- [Trap: SFP Transceiver's Bias has reached an alarm level](#)
- [Trap: SFP Transceiver's Bias has reached a warning level](#)
- [Trap: SFP Transceiver's Bias is no longer at warning/alarm level](#)
- [Trap: SFP Transceiver's Rx Power has reached an alarm level](#)
- [Trap: SFP Transceiver's Rx Power has reached a warning level](#)
- [Trap: SFP Transceiver's Rx Power is no longer at warning/alarm level](#)
- [Trap: SFP Transceiver's Temperature has reached an alarm level](#)
- [Trap: SFP Transceiver's Temperature has reached a warning level](#)
- [Trap: SFP Transceiver's Temperature is no longer at warning/alarm level](#)
- [Trap: SFP Transceiver's Tx Power has reached an alarm level](#)
- [Trap: SFP Transceiver's Tx Power has reached a warning level](#)
- [Trap: SFP Transceiver's Tx Power is no longer at warning/alarm level](#)
- [Trap: SFP Transceiver's Voltage has reached an alarm level](#)
- [Trap: SFP Transceiver's Voltage has reached a warning level](#)
- [Trap: SFP Transceiver's Voltage is no longer at warning/alarm level](#)
- [Trap: SLPP Guard Hold Down Expired. %s. Port has been re-enabled](#)
- [Trap: SLPP Guard Packet Received. %s. Port has been disabled](#)
- [Trap: SLPP Port Down Event](#)
- [Trap: Smlt 1st Link Down](#)
- [Trap: Smlt 1st Link Up](#)
- [Trap: Smlt Link Down](#)
- [Trap: Smlt Link Up](#)
- [Trap: topologyChange](#)
- [Trap: ubpEAPSessionEnd](#)
- [Trap: ubpEAPSessionStart](#)
- [Trap: vrrpTrapNewMaster](#)

[A](#) | [C](#) | [D](#) | [E](#) | [I](#) | [L](#) | [P](#) | [R](#) | [S](#) | [T](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# SNMP logs starting with W

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SNMP logs starting with W

This page lists all the logs starting with the letter W that are generated by the SNMP source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [C](#) | [D](#) | [E](#) | [I](#) | [L](#) | [P](#) | [R](#) | [S](#) | [I](#) | [W](#)

- [Warm Start Trap](#)

[A](#) | [C](#) | [D](#) | [E](#) | [I](#) | [L](#) | [P](#) | [R](#) | [S](#) | [I](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP logs starting with E

This page lists all the logs starting with the letter E that are generated by the EAP source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[E](#) | [G](#) | [I](#) | [M](#) | [N](#) | [I](#) | [U](#)

- [EAP: AdminfMgr Install Set Failed on port:](#)
- [EAP: AdminfMgr Install Test Failed on port:](#)
- [EAP Bad pkt id](#)
- [EAP Bad pkt len](#)
- [EAP: Bad pkt len](#)
- [EAP: cannot add Isolated %s to multiple VLANs. Port already assigned to one Private VLAN.](#)
- [EAP: cannot add Isolated %s to non-Private VLAN %d.](#)
- [EAP: cannot add non-Isolated %s to private VLAN %d.](#)
- [EAP: cannot apply contradictory Egress Vid %d on port %d.](#)
- [EAP: cannot apply contradictory Egress Vid %d on port %d.](#)
- [EAP: cannot apply Egress Vids on ADAC port %d.](#)
- [EAP: cannot apply Egress Vids on ADAC port %d.](#)
- [EAP: cannot apply inexistent Egress Vid %d on port %d.](#)
- [EAP: cannot apply inexistent Egress Vid %d on port %d.](#)
- [EAP: cannot apply inexistent Egress VLAN Name on port %d.](#)
- [EAP: cannot apply inexistent Egress VLAN Name on port %d.](#)
- [EAP: Cannot assign PVID %d. on port %d it is in another STP group](#)
- [EAP: cannot autocreate a Non-Private VLAN for Isolated %s.](#)
- [EAP: Cannot auto-create VLAN %d. it is mapped to another STP group](#)
- [EAP: Cannot enable IP source guard on port %s: DHCP snooping is not enabled globally](#)
- [EAP: Cannot enable IP source guard on port %s: the port is not a member of a DHCP Snooping enabled VLAN](#)
- [EAP: Cannot enable IP source guard on port %s: the port is not a member of an ARP Inspection enabled VLAN](#)
- [EAP: Cannot enable IP source guard on port %s: unable to apply the new setting](#)
- [EAP: Cannot set DHCP Snooping on non-autocreated VLAN %d](#)
- [EAP: Cannot set DHCP Snooping option82 on non-autocreated VLAN %d](#)
- [EAP: Cannot set Dynamic ARP Inspection on non-autocreated VLAN %d](#)
- [EAP: Cannot set IGMP Snooping on non-autocreated VLAN %d](#)
- [EAP: Cannot set IGMP Snooping on Switched UNI VLAN %d](#)
- [EAP: Cannot set option 82 subscriber ID longer than %d characters on port %d](#)
- [EAP: cannot set PVID %d to %s. VLAN is Private and port is not Isolated.](#)
- [EAP: Cannot set speed/duplex on port %s: cannot retrieve current configuration](#)
- [EAP: Cannot set speed/duplex on port %s: memory allocation error](#)
- [EAP: Cannot set speed/duplex on port %s: speed or duplex value missing](#)
- [EAP: Cannot set speed/duplex on port %s: unable to apply the new port configuration](#)
- [EAP: Cannot set speed/duplex on port %s: unsupported values](#)
- [EAP: CDT Error](#)
- [EAP Client blocked \(Block Subsequent MAC Authentication\): Different VID than expected](#)
- [EAP Client blocked \(Block Subsequent MAC Authentication\): Invalid VID](#)
- [EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. All bindings have been rejected](#)
- [EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. All RAVs or Bindings from RADIUS are invalid](#)
- [EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Cannot use FA bindings in Legacy networks](#)
- [EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. EAP FA context unknown network](#)
- [EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Maximum number of VLANs reached](#)
- [EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Only MHSA mode supports multiple RAVs](#)
- [EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Receiving unconfigured VLAN from Radius without](#)

## Autocreate

- EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid bindings exceeded the maximum threshold of 16
- EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid bindings exceeded the maximum threshold of 94
- EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid not supported in MHMA and SHSA
- EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with different Isid from the configured one is invalid
- EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with Isid equal to 0 not supported in FA SPB networks
- EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with Isid <> 0 not supported in Standalone Proxy or Autoproxy
- EAP Client %02x:%02x:%02x:%02x:%02x:%02x: Vlan %d not created. Maximum number of VLANs reached
- EAP Could not process pkt
- EAP: Could not process pkt
- EAP: Done Read From NVRAM - readVer %d in %s: cfgVer %d
- EAP Error - Default
- EAP Error - Failed to free mac info memory
- EAP: Error initializing dynamic settings semaphore
- EAP: Error initializing semaphore
- EAP: Error Radius - ifIndex not found
- EAP Error: Reached maximum number of messages in the queue
- EAP Error while sending Access Violation Trap
- EAP: Error while sending Access Violation Trap
- EAP Error while sending RAV Error Trap
- EAP: Error while sending RAV Error Trap
- EAP: FA bind conflict between
- EAP Failed initialize global arrays
- EAP: Failed initialize global arrays
- EAP: Failed installing FOV UBP.
- EAP: Failed qpa-RoleAssociation on port: %s. MAC %02x:%02x:%02x:%02x:%02x:%02x
- EAP Failed to add host, max number of clients reached
- EAP: Failed to add host, max number of clients reached
- EAP Failed to add host, memory allocation error
- EAP: Failed to add host, memory allocation error
- EAP Failed to create dyna global arrays
- EAP: Failed to create dyna global arrays
- EAP: GVlan Deleted
- EAP: GVlan Disabled for
- EAP: IMC Failed to send message
- EAP: IMC Memory allocation error
- EAP: Invalid NRAV ID
- EAP: Invalid RAV ID
- EAP: Invalid Vlan ID %d configured for port %d
- EAP Invalid Vlan ID vid configured for port num
- EAP: Mac Authenticated - port %d mac %08x%04x
- EAP: Mac AuthFail -
- EAP Mac AuthFail - unitPort <unit-portnum> macHi <xx-xx> macLo <xx-xx-xx-xx>
- EAP: Mac Deleted - Aborted - port %d mac %08x%04x
- EAP: Mac Deleted - Bkend Timeout - port %d mac %08x%04x
- EAP: Mac Deleted - Disconnected - port %d mac %08x%04x
- EAP: Mac Intruder -
- EAP: Maximum number of FA Table entries reached
- EAP Memory allocation error
- EAP: Memory allocation error
- EAP Message queue error
- EAP: Message queue error
- EAP: NEAP port %s not member of any VLAN. Added to VLAN %d for NEAP authentication
- EAP Neap port was not member of any vlan
- EAP NULL pkt to send on Success
- EAP: NULL pkt to send on Success
- EAP NVRAM open error
- EAP: NVRAM open error
- EAP NVRAM read port admin state error
- EAP: NVRAM read port admin state error
- EAP NVRAM read system admin state error
- EAP: NVRAM read system admin state error
- EAP NVRAM read system ubp state error



- [EAP: NVRAM read system ubp state error](#)
- [EAP NVRAM write error](#)
- [EAP: NVRAM write error](#)
- [EAP: Pvid attribute from RADIUS ignored.](#)
- [EAP: Pvid attribute from RADIUS ignored.](#)
- [EAP: RAV not configured on switch for MHSA and Isolated %s.](#)
- [EAP Reached Mac Intruder Count](#)
- [EAP: Reached MAC intruder count on %s](#)
- [EAP: Reached maximum number of VLAN ranges for ARP inspection](#)
- [EAP: Reached maximum number of VLAN ranges for DHCP snooping](#)
- [EAP: Reached maximum number of VLAN ranges for DHCP snooping option 82](#)
- [EAP: Reached maximum number of VLAN ranges for IGMP snooping](#)
- [EAP: Receiving unsupported Auto-Create-VLAN VSA in SHSA or MHMA](#)
- [EAP Task spawn error](#)
- [EAP: Task spawn error](#)
- [EAP: Timer error](#)
- [EAP: Unable to Reserve EapAdmin Filter Resources](#)
- [EAP: Unable to UnReserve EapAdmin Filter Resources](#)
- [EAP: Vlan Change Aborted, it is in another STP Group](#)
- [EAP: Vlan Change Aborted on brouter.](#)
- [EAP: Warning, trying to set DHCP Snooping on VLAN %d not from client's attributes](#)
- [EAP: Warning, trying to set DHCP Snooping option82 on VLAN %d not from client's attributes](#)
- [EAP: Warning, trying to set Dynamic ARP Inspection on VLAN %d not from client's attributes](#)
- [EAP: Warning, trying to set IGMP Snooping on VLAN %d not from client's attributes](#)
- [Error/Warning - Eap File Read: readVer %d in %s:cfgVer %d](#)
- [Error/Warning - Eap File signals a software downgrade:%d \(%s:%d\), default all eap settings](#)
- [Error/Warning - Eap File Version Mismatch:%d \(%s:%d\)](#)
- [Error/Warning - Eap File Write:%d \(%s:%d\)](#)
- [Error/Warning - Param:%d \(%s:%d\)](#)

[E](#) | [G](#) | [I](#) | [M](#) | [N](#) | [I](#) | [U](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP logs starting with G

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP logs starting with G

This page lists all the logs starting with the letter G that are generated by the EAP source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[E](#) | [G](#) | [I](#) | [M](#) | [N](#) | [I](#) | [U](#)

- [Got dynamic UBP but it's not enabled for EAP clients, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x](#)
- [Got dynamic UBP but it's not enabled for Non-EAP clients, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x](#)
- [Got UserPolicy from Radius but QosOperMode disabled - unitPort %08x%04x](#)
- [Got UserPolicy from Radius but UBP disabled - unitPort 0x%x mac %08x%04x](#)

[E](#) | [G](#) | [I](#) | [M](#) | [N](#) | [I](#) | [U](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP logs starting with I

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP logs starting with I

This page lists all the logs starting with the letter I that are generated by the EAP source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[E](#) | [G](#) | [I](#) | [M](#) | [N](#) | [T](#) | [U](#)

- [Insufficient dynamic UBP attributes in CoA, need ACL, UROL and SET](#)
- [Insufficient dynamic UBP attributes, need ACL, UROL and SET, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x](#)
- [Invalid NRAV id %d, on port %d, cannot be B-VLAN](#)
- [Invalid NRAV id %d, on port %d, it isn't a SPBM VLAN](#)
- [Invalid RAV id %d, on port %d, cannot be B-VLAN](#)
- [Invalid RAV id %d, on port %d, it isn't a SPBM VLAN](#)

[E](#) | [G](#) | [I](#) | [M](#) | [N](#) | [T](#) | [U](#)



# EAP logs starting with M

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP logs starting with M

This page lists all the logs starting with the letter M that are generated by the EAP source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[E](#) | [G](#) | [I](#) | [M](#) | [N](#) | [I](#) | [U](#)

- [MAC %02x:%02x:%02x:%02x:%02x:%02x not authenticated: only one client is allowed in MHSA mode](#)
- [MHSA Auto-Configuration completed on port %s.](#)
- [MHSA Auto-Configuration failed on port %s - eap status is unauthorized.](#)
- [MHSA Auto-Configuration failed on port %s - port is RSPAN destination.](#)
- [MHSA Auto-Configuration failed on port %s - port mirroring is enabled.](#)

[E](#) | [G](#) | [I](#) | [M](#) | [N](#) | [I](#) | [U](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP logs starting with N

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP logs starting with N

This page lists all the logs starting with the letter N that are generated by the EAP source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[E](#) | [G](#) | [I](#) | [M](#) | [N](#) | [I](#) | [U](#)

- [NEAP Accounting - Memory allocation failure](#)
- [NEAP Accounting: Memory allocation failure](#)
- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. All bindings have been rejected](#)
- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. All NRAVs or Bindings from RADIUS are invalid](#)
- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Already authenticated by other method.](#)
- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Cannot use FA bindings in Legacy networks](#)
- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. EAP FA context unknown network](#)
- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Maximum number of VLANs reached](#)
- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Only MHSA mode supports multiple NRAVs](#)
- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Receiving unconfigured VLAN from Radius without Autocreate](#)
- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid bindings exceeded the maximum threshold of 16](#)
- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid bindings exceeded the maximum threshold of 94](#)
- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid not supported in MHMA and SHSA](#)
- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with different Isid from the configured one is invalid](#)
- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with Isid equal to 0 not supported in FA SPB networks](#)
- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with Isid <> 0 not supported in Standalone Proxy or Autopro](#)
- [NEAP Client %02x:%02x:%02x:%02x:%02x:%02x: Vlan %d not created. Maximum number of VLANs reached](#)
- [NEAP: MAC - %02x:%02x:%02x:%02x:%02x:%02x. Binding already set for client. pushed trusted bindings will be ingored.](#)
- [NEAP: MAC - %02x:%02x:%02x:%02x:%02x:%02x. Invalid Fabric-Attach-Client-Trust value](#)
- [NEAP: MAC - %02x:%02x:%02x:%02x:%02x:%02x. Multiple trusted bindings supported only in MHSA](#)
- [NEAP: MAC - %02x:%02x:%02x:%02x:%02x:%02x. Number of ranges exceeded the maximum threshold of 10](#)
- [NEAP: MAC - %02x:%02x:%02x:%02x:%02x:%02x. Ranges are ignored](#)
- [NEAP Phone %02x:%02x:%02x:%02x:%02x:%02x migrated from port %d/%d.](#)
- [NEAP: Pvid attribute from RADIUS ignored.](#)
- [NEAP: Receiving unsupported Auto-Create-VLAN VSA in SHSA or MHMA](#)
- [Non-EAP Client blocked \(Block Subsequent MAC Authentication\): Different VID than expected](#)
- [Non-EAP Client blocked \(Block Subsequent MAC Authentication\): EAP Use Rav Not enabled](#)

[E](#) | [G](#) | [I](#) | [M](#) | [N](#) | [I](#) | [U](#)



# EAP logs starting with T

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP logs starting with T

This page lists all the logs starting with the letter T that are generated by the EAP source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[E](#) | [G](#) | [I](#) | [M](#) | [N](#) | [T](#) | [U](#)

- [Trap\\_bsnEapAccessViolation](#)
- [Trap\\_bsnEapUbpFailure](#)

[E](#) | [G](#) | [I](#) | [M](#) | [N](#) | [T](#) | [U](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# EAP logs starting with U

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## EAP logs starting with U

This page lists all the logs starting with the letter U that are generated by the EAP source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[E](#) | [G](#) | [I](#) | [M](#) | [N](#) | [I](#) | [U](#)

- [UBP CoA cannot proceed, dynamic UBP not enabled either for EAP or Non-EAP clients](#)
- [Unsupported field for ACL in dynamic CoA UBP](#)
- [Unsupported field for ACL in dynamic UBP, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x](#)
- [Unsupported field for SET in dynamic CoA UBP](#)
- [Unsupported field for SET in dynamic UBP, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x](#)
- [Unsupported value for ACL field in dynamic CoA UBP](#)
- [Unsupported value for ACL field in dynamic UBP, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x](#)
- [Unsupported value for SET field in dynamic CoA UBP](#)
- [Unsupported value for SET field in dynamic UBP, port %s, MAC %02x:%02x:%02x:%02x:%02x:%02x](#)

[E](#) | [G](#) | [I](#) | [M](#) | [N](#) | [I](#) | [U](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ISIS logs starting with A

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ISIS logs starting with A

This page lists all the logs starting with the letter A that are generated by the ISIS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [Z](#)

- [Access not granted. Contact www.extremenetworks.com to update Software license.](#)
- [An SPBM instance must be configured before the requested operation can proceed](#)

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ISIS logs starting with C

This page lists all the logs starting with the letter C that are generated by the ISIS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [Z](#)

- [Cannot add C-VLAN to ETREE](#)
- [Cannot add C-VLAN to ISID. IGMP Snooping is enabled on C-VLAN from I-SID](#)
- [Cannot add C-VLAN with IGMP Snooping to ISID with multiple VLANs configured](#)
- [Cannot add ETREE to ISID with multiple VLANs configured](#)
- [Cannot add SWITCHED UNI to ISID. IGMP Snooping is enabled on C-VLAN from I-SID](#)
- [Cannot change metric type from wide to narrow](#)
- [Cannot change system ID with nodal MEP MIP association](#)
- [Cannot config i-sid for spbm vlan](#)
- [Cannot configure ethertype without SPBM globally enabled](#)
- [Cannot configure SPBM in non SPBM mode](#)
- [Cannot configure without loopback port available](#)
- [Cannot configure without SPBM globally enabled](#)
- [Cannot create an SPBM VLAN from a regular VLAN that has static MAC addresses](#)
- [Cannot create circuit interface on eap port](#)
- [Cannot create circuit interface on port %i. Maximum circ number exceded](#)
- [Cannot create circuit interface on unit %i port %i. Maximum circ number exceded](#)
- [Cannot create CVLAN if the indicated VLAN contains NNI](#)
- [Cannot create CVLAN on L3 VLAN](#)
- [Cannot create CVLAN on vlan: IGMP Snooping enabled and SPBM Mcast disabled](#)
- [Cannot create CVLAN on VLAN that is part of SMLT](#)
- [Cannot create IS-IS interface on IST interface](#)
- [Cannot create IS-IS interface on MLT which has port member with IS-IS interface](#)
- [Cannot create IS-IS interface on port which is member of MLT with IS-IS interface](#)
- [Cannot create IS-IS interface on port with IPFIX enabled](#)
- [Cannot create IS-IS interface on private vlan isolated/promiscuous port](#)
- [Cannot create IS-IS interface on SMLT interface](#)
- [Cannot create switched UNI on NNI interface](#)
- [Cannot create transparent UNI as port belongs to at least one VLAN](#)
- [Cannot create UNI on VLAN with IGMP SNOOP enabled](#)
- [Cannot create UNI on VLAN with IPV6 VRRPV3 configured](#)
- [Cannot create UNI on VLAN with MLD SNOOP configured](#)
- [Cannot delete SPBM instance. IS-IS interface is configured](#)
- [Cannot delete SPBM instance. system ID is configured](#)
- [Cannot disable IP Shortcut without first disabling IP routing](#)
- [Cannot disable SPBM globally while i-sid and UNI configuration exists](#)
- [Cannot disable SPBM multicast - IGMP Snooping is enabled on C-VLANs](#)
- [Cannot enable IS-IS interface on port with mac-security settings](#)
- [Cannot enable IS-IS interface without SPBM instance](#)
- [Cannot enable SPBM globally if next STP operation mode is RSTP](#)
- [Cannot enable SPBM globally on RSTP mode](#)
- [Cannot enable SPBM globally on stack mode](#)
- [Cannot enable SPBM globally while L3 is enabled](#)
- [Cannot enable SPBM multicast: feature unsupported](#)
- [Cannot enable SPBM multicast while unknown-mcast-no-flood is enabled](#)
- [Cannot enable SPBM while PIM is enabled](#)

[Cannot enable the SPBM instance on a IS-IS interface configured 'UntagAll'](#)

- [Cannot set SPBM instance on adac call server port](#)
- [Cannot set SPBM instance on adac phone port](#)
- [Cannot set SPBM instance on adac uplink port](#)
- [Cannot set SPBM instance on a monitor port with allow traffic disabled](#)
- [Cannot set SPBM instance on MLT which is in a CVLAN](#)
- [Cannot set SPBM instance on port of CVLAN](#)
- [Cannot set SPBM instance on transparent UNI port](#)
- [Cannot update settings with the same data](#)
- [Cannot use multicast address](#)
- [Change rear-port mode before setting SPBM globally](#)
- [Configuration does not exist](#)
- [Control VLAN does not exist](#)
- [CVLAN already exists](#)
- [C-VLAN UNI already configured with same I-SID](#)

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [I](#) | [U](#) | [V](#) | [W](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ISIS logs starting with D

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ISIS logs starting with D

This page lists all the logs starting with the letter D that are generated by the ISIS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [Z](#)

- [Delete all interfaces before set SPBM globally](#)
- [Delete manual area before set SPBM globally](#)
- [Delete SPBM instance before set SPBM globally](#)
- [Delete SPBM VLAN before set SPBM globally](#)
- [Delete summary address before set SPBM globally](#)
- [Disable IS-IS before set SPBM globally](#)
- [Do not configure more than two VLANs per SPBM instance](#)

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ISIS logs starting with I

This page lists all the logs starting with the letter I that are generated by the ISIS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [Z](#)

- [Inconsistency detected between SPBM instance VLAN data and primary SPBM BVLAN](#)
- [Invalid authentication type](#)
- [Invalid CSNP interval](#)
- [Invalid Ethertype](#)
- [Invalid interface index](#)
- [Invalid IP address](#)
- [Invalid IP address type](#)
- [Invalid IP source address](#)
- [Invalid IS-IS circuit ID](#)
- [Invalid IS-IS circuit type](#)
- [Invalid key ID](#)
- [Invalid manual area address length](#)
- [Invalid or inconsistent value](#)
- [Invalid password](#)
- [Invalid port](#)
- [Invalid RXMT LSP interval](#)
- [Invalid SPF delay, should be multiple of hundred](#)
- [Invalid VLAN ID](#)
- [IP source address must be configured before enable IP SC](#)
- [IS-IS cannot be enabled when SPBM is globally disabled](#)
- [IS-IS circuit already exists](#)
- [IS-IS circuit does not exist](#)
- [IS-IS circuit level hello timer should be in seconds](#)
- [IS-IS interface is enabled](#)
- [IS-IS interface type cannot be changed: point-to-point interface type only](#)
- [IS-IS is enabled on this interface](#)
- [IS-IS is enabled, runtime change not allowed](#)
- [IS-IS Level-2 circuits defined \(Level-1 only operation request rejected\)](#)
- [IS-IS Level-1 only operation supported](#)
- [IS-IS Level-1 operation is required for SPBM](#)
- [IS-IS manual area must be configured before the requested operation can proceed](#)
- [IS-IS max LSP generation interval must be >= to the min LSP interval](#)
- [IS-IS system ID cannot be a multicast address](#)
- [IS-IS system ID must be configured before the requested operation can proceed](#)

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [Z](#)



# ISIS logs starting with L

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ISIS logs starting with L

This page lists all the logs starting with the letter L that are generated by the ISIS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [Z](#)

- [Level router does not support](#)

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ISIS logs starting with M

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ISIS logs starting with M

This page lists all the logs starting with the letter M that are generated by the ISIS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [Z](#)

- [Manual area entry exists](#)
- [Manual area error](#)
- [Metric value is invalid for narrow type](#)
- [Min LSP interval should not be >= max LSP](#)
- [Must change node nickname after updating the system ID](#)

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ISIS logs starting with N

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ISIS logs starting with N

This page lists all the logs starting with the letter N that are generated by the ISIS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [Z](#)

- [Narrow metric is not supported in SPBM mode](#)
- [NNI is not supported over SMLT ports](#)

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ISIS logs starting with O

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ISIS logs starting with O

This page lists all the logs starting with the letter O that are generated by the ISIS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [Z](#)

- [Only one SPBM instance allowed](#)
- [Overload cannot be disabled](#)
- [Overload on startup is out of range](#)

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# ISIS logs starting with P

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ISIS logs starting with P

This page lists all the logs starting with the letter P that are generated by the ISIS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [Z](#)

- [Password exists](#)
- [Port is not member of VLAN](#)
- [Primary VLAN does not match for the specified SPBM instance](#)
- [Primary VLAN is not added for the specified SPBM instance](#)
- [Priority is only for broadcast type](#)

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ISIS logs starting with R

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ISIS logs starting with R

This page lists all the logs starting with the letter R that are generated by the ISIS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [Z](#)

- [RC SNMP CANNOT CONFIG PLSB ISIS INTF ON IST PORT](#)
- [RC SNMP CANNOT CONFIG PLSB ISIS INTF ON SMLT](#)
- [RC SNMP ISIS BCAST NOT SUPPORT OVER MLT](#)
- [Requested operation succeeded](#)

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ISIS logs starting with S

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ISIS logs starting with S

This page lists all the logs starting with the letter S that are generated by the ISIS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [Z](#)

- [SPBM adjacency with neighbor](#)
- [SPBM BVLAN is required but has not been configured](#)
- [SPB-MC Dynamic i-sid range conflicts with existing i-sid](#)
- [SPBM detect adj](#)
- [SPBM instance already exists](#)
- [SPBM instance does not exist](#)
- [SPBM instance is not enabled on this IS-IS interface](#)
- [SPBM ISIS](#)
- [SPBM ISIS detect duplicate nick-name](#)
- [SPBM ISIS node](#)
- [SPBM system ID cannot be same as IST peer system ID](#)
- [SPBM system ID cannot be same as IST virtual bmac](#)
- [SPBM system nickname is required but has not been configured](#)
- [SPBM transparent UNI already configured on port](#)
- [Specified IS-IS BVLAN does not currently exist](#)
- [Specified IS-IS BVLAN is not an SPBM VLAN](#)
- [Specified IS-IS system ID is invalid](#)
- [Switched UNI already configured with same I-SID](#)

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ISIS logs starting with T

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ISIS logs starting with T

This page lists all the logs starting with the letter T that are generated by the ISIS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [Z](#)

- [This attribute is currently not configurable](#)
- [Too many manual area addresses](#)
- [Transparent UNI already configured with same I-SID](#)
- [Trap: rclsisPlsbBvidMismatchTrap](#)
- [Trap: rclsisPlsbLsdbUpdateTrap](#)

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ISIS logs starting with U

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ISIS logs starting with U

This page lists all the logs starting with the letter U that are generated by the ISIS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [I](#) | [U](#) | [V](#) | [W](#) | [Z](#)

- [UNI already exists on the specified port and VLAN](#)

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [I](#) | [U](#) | [V](#) | [W](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ISIS logs starting with V

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ISIS logs starting with V

This page lists all the logs starting with the letter V that are generated by the ISIS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [Z](#)

- [VLAN cannot re-assign](#)
- [VLAN does not exist](#)
- [VLAN is configured as C-VLAN](#)
- [VLAN is configured as switched UNI](#)
- [VLAN is not switched UNI](#)

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ISIS logs starting with W

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ISIS logs starting with W

This page lists all the logs starting with the letter W that are generated by the ISIS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [Z](#)

- [When enable IST must configure SMLT peer BMAC](#)
- [When setting Virtual BMAC to zero, Peer BMAC must be zero](#)

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# ISIS logs starting with Z

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## ISIS logs starting with Z

This page lists all the logs starting with the letter Z that are generated by the ISIS source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [Z](#)

- [Zero SMLT peer BMAC must have primary split BEB](#)
- [Zero SMLT peer BMAC must have primary split BEB](#)
- [Zero SMLT peer BMAC must have zero virtual BMAC](#)
- [Zero SMLT peer BMAC must have zero virtual BMAC](#)

[A](#) | [C](#) | [D](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#) | [Z](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SMGR logs starting with B

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SMGR logs starting with B

This page lists all the logs starting with the letter B that are generated by the SMGR source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)

- [Base requesting re-discovery, this unit becoming base](#)

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SMGR logs starting with C

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SMGR logs starting with C

This page lists all the logs starting with the letter C that are generated by the SMGR source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)

- [Change of active config block failed %d](#)
- [Clearing MC unicast IMC entries, unit %d, end\\_type %s, stk\\_type %s](#)
- [Clearing VLAN entries, end\\_type %s, stk\\_type %s](#)
- [Configured base unit detected, drop its discovery msg - %s line %d](#)

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SMGR logs starting with D

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SMGR logs starting with D

This page lists all the logs starting with the letter D that are generated by the SMGR source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)

- [DB Ack from %s for unit #%d, mask 0x%X](#)
- [%d event sent, unit mask 0x%02X, appl mask 0x%08X](#)
- [Different SPBM operating mode than BU. Unit reconfigured and rebooted %s](#)
- [Discovery delayed due to NSNA configuration in progress](#)
- [Discovery ignored due to agent image download in progress](#)
- [Discovery message not received](#)
- [Discovery Msg dropped, expiry time exceeded %d ticks, actual %d](#)
- [Downstream stack ports down, wait for stack ports before processing](#)
- [Duplicate DB Ack for %s\(%d\) detected](#)

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SMGR logs starting with E

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SMGR logs starting with E

This page lists all the logs starting with the letter E that are generated by the SMGR source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)

- [Event %s\(%d\) causes state transition to %s](#)

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SMGR logs starting with F

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SMGR logs starting with F

This page lists all the logs starting with the letter F that are generated by the SMGR source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)

- [Filter limiting mode not supported on 5510-XX, unit cannot join stack](#)
- [Found MAC in NAP entry %d of %d stkCfg is "%s"](#)
- [Front-panel UI requested stack reset](#)
- [Front-panel UI selected Base unit](#)
- [Front-panel UI selected non-Base unit](#)
- [Front-panel UI selected use rear-panel base/non-base switch](#)

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)



# SMGR logs starting with H

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SMGR logs starting with H

This page lists all the logs starting with the letter H that are generated by the SMGR source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)

- [Hello module detected %s stack direction %s](#)

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SMGR logs starting with J

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SMGR logs starting with J

This page lists all the logs starting with the letter J that are generated by the SMGR source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)

- [Join event sent, unit mask 0x%02X, appl mask 0x%08X 0x%08X](#)

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SMGR logs starting with L

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SMGR logs starting with L

This page lists all the logs starting with the letter L that are generated by the SMGR source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)

- [Leave event sent, unit mask 0x%02X, appl mask 0x%08X 0x%08X](#)

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# SMGR logs starting with M

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SMGR logs starting with M

This page lists all the logs starting with the letter M that are generated by the SMGR source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)

- [More than %d units discovered](#)
- [Msg not sent. "numUnits" to big - %s line %d](#)

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SMGR logs starting with N

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SMGR logs starting with N

This page lists all the logs starting with the letter N that are generated by the SMGR source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)

- [numberAssignment ack received from unit # %d](#)
- [Number assignment message not received](#)

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SMGR logs starting with R

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SMGR logs starting with R

This page lists all the logs starting with the letter R that are generated by the SMGR source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)

- [Remove Data Ack from unit # %d, mask 0x%X](#)
- [Remove event sent, unit mask 0x%02X, appl mask 0x%08X 0x%08X](#)
- [Restart discovery msg rcvd from unit # %d, "%s"](#)
- [Restarting discovery due to local stack port](#)

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SMGR logs starting with S

This page lists all the logs starting with the letter S that are generated by the SMGR source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)

- [%s Appl. unexpectedly set bit in DB exch. recv mask. bit 0x%08X](#)
- [%s DB exchange succeeded for this unit. bit 0x%08X](#)
- [Sending restart discovery msg to base unit](#)
- [Setting MC broadcast IMC entry. ports %X. end type %s. stk type %s](#)
- [Setting MC non-IMC entries. end type %s. stk type %s](#)
- [Setting MC unicast IMC entries. unit %d. end type %s. stk type %s](#)
- [Setting VLAN entries. end type %s. stk type %s](#)
- [%s event NOT sent to %s](#)
- [%s event sent to %s. unit mask 0x%02X](#)
- [%s event sent. unit mask 0x%02X. appl mask 0x%08X](#)
- [%s failed DB-exchange. stack failed to form](#)
- [%s failed DB-exchange. stack formation delayed](#)
- [%s failed to set its stack startup event: 0x%08X](#)
- [%s line %d: Dropping msg that originated from this unit \(%d\)](#)
- [%s line %d: Logical unit %d out of range](#)
- [%s line %d: Physical unit %d out of range](#)
- [%s line %d: Stack links already down unit %d](#)
- [%s line %d: Unexpected stack link down msg from unit %d](#)
- [%s neighbor is mis-configured. see neighboring unit for details](#)
- [Stack link down. neighboring unit is not in stack](#)
- [Stack Manager config file ver. %d upgraded to ver. %d](#)
- [Stack Manager unable to read from to configuration file](#)
- [Stack Manager unable to write to configuration file](#)
- [Stack Mgr: error: %s line %d %d](#)
- [Stack Mgr: error: %s line %d 0x%X](#)
- [Stack Mgr: event received msg\\_src=0x%X num= 0x%X](#)
- [Stack Mgr: ignored event %s for state %s. arg: %d](#)
- [Stack Mgr: IMC ack msg failed: status %d](#)
- [Stack Mgr: info: %s line %d %d](#)
- [Stack Mgr: initialized arg1= %d arg2 = %d arg3 = %d](#)
- [Stack Mgr: internal 5670 ports INACTIVE 0x%X](#)
- [Stack Mgr: NAP error: MAC not found. stack size %d](#)
- [Stack Mgr: queue creation failed %s line %d](#)
- [Stack Mgr: queue rec error qid= 0x%X errno=0x%X](#)
- [Stack Mgr: queue send error qid= 0x%X errno=0x%X](#)
- [Stack Mgr: semaphore creation failed %s line %d](#)
- [Stack Mgr: %s msg send failed](#)
- [Stack Mgr: startup event failed type: 0x%08X option: %d](#)
- [Stack Mgr: STEG GO event missed](#)
- [Stack Mgr: 0x%X 0x%X 0x%X](#)
- [Stack operation mode modified to %s and unit reset](#)
- [Stack sync failed Exp: 0x%08X Act: 0x%08X Missing: 0x%08X](#)
- [Stack sync failed. stack failed to form](#)
- [Stack sync failed. unit not in stack](#)
- [startDiscoveryMsg from unit %d \(%s\) will be processed now](#)

[Stk config is "%s", %d units](#)

- [stk startup event failed Exp: 0x%08X Act: 0x%08X Missing: 0x%08X](#)
- [Stk startup event failed type: 0x%08X option: %d](#)
- [Superfluous request from unit #%d to restart discovery](#)

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SMGR logs starting with T

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SMGR logs starting with T

This page lists all the logs starting with the letter T that are generated by the SMGR source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)

- [Task priority changed for %s to %d](#)
- [Temporary base unit detected, becoming a non-base unit- %s line %d](#)
- [The base \(unit #%d\) has left the stack. Unit #%d is now the base](#)
- [This log msg contains 3 encoded variables %x, %x, %x](#)
- [This unit has already been discovered](#)
- [This unit has an incompatible stack operational mode setting](#)
- [This unit has wrong F/W version, expected %s, actual %s](#)
- [This unit has wrong S/W version, expected %s, actual %s](#)
- [This unit is operating as the Base unit](#)

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# SMGR logs starting with U

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SMGR logs starting with U

This page lists all the logs starting with the letter U that are generated by the SMGR source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)

- [Unable to update config in NVRAM - %s line %d](#)
- [Unexpected DB Ack, got %s from unit #%%d, expected %s](#)
- [Unit #%%d already deleted from this unit's database](#)
- [Unit #%%d link down on %s](#)
- [Unit #%%d link up on %s](#)
- [Upstream stack ports down, wait for stack ports before processing](#)

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)



# SMGR logs starting with W

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SMGR logs starting with W

This page lists all the logs starting with the letter W that are generated by the SMGR source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)

- [Wrong QoS Agent buffer setting, expected %s, actual %s, unit cannot join stack](#)
- [Wrong QoS Agent buffer setting, expected %s, actual %s, unit reconfigured and reboot](#)
- [Wrong QoS Agent queue setting, expected %u, actual %u, unit cannot join stack](#)
- [Wrong QoS Agent queue setting, expected %u, actual %u, unit cannot join stack](#)

[B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [J](#) | [L](#) | [M](#) | [N](#) | [R](#) | [S](#) | [I](#) | [U](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR logs starting with A

This page lists all the logs starting with the letter A that are generated by the AUR source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [D](#)

- [AAUR - Info: AAUR default](#)
- [AAUR-Info AAUR default](#)
- [AAUR - Info: AAUR disable](#)
- [AAUR-Info AAUR disable](#)
- [AAUR - Info: AAUR enable](#)
- [AAUR-Info AAUR enable](#)
- [AAUR - Info: Agent transfer finished](#)
- [AAUR-Info Agent transfer finished](#)
- [AAUR - Info: Receive request for agent image, start transfer](#)
- [AAUR-Info Receive request for agent image start transfer](#)
- [AAUR - Info: Receive request for agent image, Unable to start transfer](#)
- [AAUR-Info Receive request for agent image, Unable to start transfer](#)
- [AAUR-Info Send request for new agent image](#)
- [AAUR - Info: Slave refuse transfer](#)
- [AAUR-Info Slave refuse transfer](#)
- [AAUR - Info: Start receive image](#)
- [AAUR-Info The hardware is not compatible with the image version number version](#)
- [AAUR - The hardware is not compatible with the %s version](#)
- [AAUR - Warning Agent image check sum ERROR](#)
- [AAUR - Warning: Agent image check sum ERROR](#)
- [AAUR - Warning: Agent image hash ERROR](#)
- [AAUR - Warning: Cannot get FLASH resource](#)
- [AAUR-Warning Cannot get FLASH resource](#)
- [AAUR - Warning Slave agent image check sum ERROR](#)
- [AAUR - Warning: Slave agent image check sum ERROR](#)
- [AAUR - Warning: Slave agent image hash ERROR](#)
- [AUR - Error: Checksum Error, Could not restore the old config. Using the default cfg](#)
- [AUR - Error: Failed process MAC](#)
- [AUR - Error: Failed to cancel delay watchdog timer](#)
- [AUR - Error: Failed to cancel process watchdog timer](#)
- [AUR - Error: Failed to cancel watchdog timer](#)
- [AUR - Error: Failed to create a new MAC record](#)
- [AUR - Error: Failed to create message queue](#)
- [AUR - Error: Failed to create watchdog timer](#)
- [AUR - Error: Failed to disable AUR](#)
- [AUR - Error: Failed to enable AUR](#)
- [AUR - Error: Failed to get an imc buffer](#)
- [AUR - Error: Failed to save data to NBU](#)
- [AUR - Error: Failed to send msg to IMC](#)
- [AUR - Error: Failed to spawn cfgso task](#)
- [AUR - Error: Failed to start delay watchdog timer](#)
- [AUR - Error: Failed to start process watchdog timer](#)
- [AUR - Error: Failed to start watchdog timer](#)
- [AUR - Error: file not close](#)
- [AUR - Error: File not open](#)

- [AUR - Error: File not read](#)
- [AUR - Error: File not write](#)
- [AUR - Error: Invalid value](#)
- [AUR - Error: Next BU ID is 0](#)
- [AUR-Info AUR disable](#)
- [AUR-Info AUR enable](#)
- [AUR - Info: AUR Restored to default](#)
- [AUR-Info AUR Restored to default](#)
- [AUR - Info: Base Unit refused configuration transfer](#)
- [AUR - Info: Busy - Wait for the next sync](#)
- [AUR - Info: Configuration transfer finished](#)
- [AUR - Info: Configuration transfer from Unit %d finished](#)
- [AUR - Info: Configuration transfer to Base Unit finished](#)
- [AUR - Info: Configuration transfer to Unit %d finished](#)
- [AUR - Info: Do MIRROR](#)
- [AUR - Info: Do Restore](#)
- [AUR - Info: New unit has different HW config. Using cfg from the new unit](#)
- [AUR-Info New unit has different HW config Using cfg from the new unit](#)
- [AUR - Info: No VALID INACTIVE - do MIRROR](#)
- [AUR - Info: process flash sync](#)
- [AUR - Info: Receive request for configuration transfer. Start transfer](#)
- [AUR - Info: Receive request for configuration transfer. Unable to start transfer](#)
- [AUR - Info: same MAC - do MIRROR](#)
- [AUR - Info: Send configuration request to restore Base Unit](#)
- [AUR - Info: Send configuration to restore Unit %d](#)
- [AUR - Info: sending MAC to slave](#)
- [AUR - Info: Slave Unit %d refused configuration transfer](#)
- [AUR - Warning: Cannot get FLASH resource](#)
- [AUR - Warning: Configuration check sum ERROR](#)
- [AUR - Warning: Delay Watchdog timer expire](#)
- [AUR - Warning: Invalid Msg.Id](#)
- [AUR - Warning: No matched MAC](#)
- [AUR - Warning: Process Watchdog timer expire](#)
- [AUR - Warning: Watchdog timer expire](#)

[A](#) | [D](#)



# AUR logs starting with D

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## AUR logs starting with D

This page lists all the logs starting with the letter D that are generated by the AUR source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [D](#)

- [DAUR - Info Diag transfer finished](#)
- [DAUR - Info: Diag transfer finished](#)
- [DAUR - Info Receive request for diag image start transfer](#)
- [DAUR - Info: Receive request for diag image. start transfer](#)
- [DAUR - Info: Receive request for diag image. Unable to start transfer](#)
- [DAUR - Info Receive request for diag image. Unable to transfer](#)
- [DAUR - Info Send request for new diag image](#)
- [DAUR - Info: Send request for new diag image](#)
- [DAUR - Info Slave refuse transfer](#)
- [DAUR - Info: Slave refuse transfer](#)
- [DAUR - Info Start receive image](#)
- [DAUR - Info: Start receive image](#)
- [DAUR - The hardware is not compatible with the image version number version](#)
- [DAUR - The hardware is not compatible with the %s version](#)
- [DAUR - Warning: Cannot get FLASH resource](#)
- [DAUR - Warning Diag image check sum ERROR](#)
- [DAUR - Warning: Diag image check sum ERROR](#)
- [DAUR - Warning Slave diag image check sum ERROR](#)
- [DAUR - Warning: Slave diag image check sum ERROR](#)

[A](#) | [D](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# VLAN logs starting with B

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN logs starting with B

This page lists all the logs starting with the letter B that are generated by the VLAN source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[B](#) | [C](#) | [E](#) | [F](#) | [N](#) | [S](#) | [V](#) | [W](#)

- [BU was unable to send IMC for NBUs VLAN/Port configuration](#)

[B](#) | [C](#) | [E](#) | [F](#) | [N](#) | [S](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLAN logs starting with C

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN logs starting with C

This page lists all the logs starting with the letter C that are generated by the VLAN source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[B](#) | [C](#) | [E](#) | [F](#) | [N](#) | [S](#) | [V](#) | [W](#)

- [Cli add vlan vlan id members port mask](#)
- [Cli create vlan vlan id type port](#)
- [Cli delete vlan vlan id members port mask](#)
- [Cli delete vlan vlan id type port](#)
- [Cli set autopvid disable](#)
- [Cli set autopvid enable](#)
- [Cli set management vlan vlan id](#)
- [Cli set ports port mask tagging disable](#)
- [Cli set ports port mask tagging enable](#)
- [Cli set pvid vlan id ports port mask](#)
- [Cli set vlan vlan id members port mask](#)
- [Cons activate vlan vlan id](#)
- [Cons add vlan vlan id port unit port](#)
- [Cons create vlan vlan id type port](#)
- [Cons delete vlan vlan id port unit port](#)
- [Cons delete vlan vlan id type port](#)
- [Cons set autopvid disable](#)
- [Cons set autopvid enable](#)
- [Cons set management vlan vlan id](#)
- [Cons set port unit port pvid vlan id](#)
- [Cons set port unit port tagging disable](#)
- [Cons set port unit port tagging enable](#)

[B](#) | [C](#) | [E](#) | [F](#) | [N](#) | [S](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLAN logs starting with E

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN logs starting with E

This page lists all the logs starting with the letter E that are generated by the VLAN source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[B](#) | [C](#) | [E](#) | [F](#) | [N](#) | [S](#) | [V](#) | [W](#)

- [Error getting VLAN info for Port's pvid](#)
- [Error in q\\_smgr.c - line %d, p1 = %d, p2 = %d](#)
- [Error reading nvq\\_ObjDescr from VLAN file](#)
- [Error reading prec from VLAN file](#)
- [Error reading vmrec from VLAN file](#)
- [Error reading vrec from VLAN file](#)
- [Error restoring from VLAN file](#)
- [Error restoring from VLAN file. Wrong nvq.Descr.devVer](#)
- [Error restoring from VLAN file. Wrong nvq.Descr.notBlank](#)
- [Error restoring nvq.Descr from VLAN file](#)
- [Error restoring object from VLAN file - bad file pointer or mode](#)
- [Error restoring object from VLAN file - bad file pointer or mode.](#)
- [Error restoring object from VLAN NVRAM file](#)
- [Error restoring Port from VLAN NVRAM file](#)
- [Error restoring Ports from VLAN file](#)
- [Error restoring VLANs from VLAN file](#)
- [Error restoring VMACs from VLAN file](#)
- [Error seeking object in VLAN file](#)
- [Error seeking Ports in VLAN file](#)
- [Error seeking VLANs in VLAN file](#)
- [Error seeking VMACs in VLAN file](#)
- [Error updating Private VLAN configuration when transitioning from](#)
- [Error updating Private VLAN configuration when trying to](#)

[B](#) | [C](#) | [E](#) | [F](#) | [N](#) | [S](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLAN logs starting with F

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN logs starting with F

This page lists all the logs starting with the letter F that are generated by the VLAN source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[B](#) | [C](#) | [E](#) | [F](#) | [N](#) | [S](#) | [V](#) | [W](#)

- [Fatal in %s at line %d](#)
- [FMGR: CoSQ Init - CoS Mapping: unit\(%d\)](#)
- [FMGR: CoSQ Init - CoS Queues: unit\(%d\)](#)
- [FMGR: CoSQ Init - CoS Schedule: unit\(%d\) port\(%d\)](#)
- [FMGR: CoSQ Init - end](#)
- [FMGR: CoSQ Init - HOL Cell Limit: unit\(%d\) port\(%d\)](#)
- [FMGR: CoSQ Init - HOL Packet Limit: unit\(%d\) port\(%d\)](#)
- [FMGR: CoSQ Init - IBP Cell Limit: unit\(%d\) port\(%d\)](#)
- [FMGR: CoSQ Init - IBP Discard Limit: unit\(%d\) port\(%d\)](#)
- [FMGR: CoSQ Init - IBP Packet Limit: unit\(%d\) port\(%d\)](#)
- [FMGR: CoSQ Init - Packet Maximum: unit\(%d\) port\(%d\)](#)
- [FMGR: CoSQ Init - start](#)

[B](#) | [C](#) | [E](#) | [F](#) | [N](#) | [S](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLAN logs starting with N

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN logs starting with N

This page lists all the logs starting with the letter N that are generated by the VLAN source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[B](#) | [C](#) | [E](#) | [F](#) | [N](#) | [S](#) | [V](#) | [W](#)

- [Number of VLANs does not match BU number of VLANs. VLAN config defaulted](#)
- [Number of VLANs does not match BU number of VLANs. VLAN config defaulted](#)

[B](#) | [C](#) | [E](#) | [F](#) | [N](#) | [S](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# VLAN logs starting with S

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN logs starting with S

This page lists all the logs starting with the letter S that are generated by the VLAN source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[B](#) | [C](#) | [E](#) | [F](#) | [N](#) | [S](#) | [V](#) | [W](#)

- [Set port to default](#)

[B](#) | [C](#) | [E](#) | [F](#) | [N](#) | [S](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLAN logs starting with V

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN logs starting with V

This page lists all the logs starting with the letter V that are generated by the VLAN source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[B](#) | [C](#) | [E](#) | [F](#) | [N](#) | [S](#) | [V](#) | [W](#)

- [VLAN configuration does not match BU VLAN configuration.DIFF\\_MASK=](#)
- [VLAN configuration does not match BU VLAN configuration. VLAN config defaulted](#)
- [VLAN configuration does not match BU VLAN configuration. VLAN config defaulted](#)
- [VLAN IMC callback failed](#)
- [VLAN IMC was not sent](#)
- [VLAN NVRAM read error](#)
- [VLAN NVRAM read error](#)
- [VLAN queue messages discarded](#)
- [VLAN queue messages discarded](#)
- [VLAN set error from IMC](#)
- [VLAN set error from RPC](#)

[B](#) | [C](#) | [E](#) | [F](#) | [N](#) | [S](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# VLAN logs starting with W

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## VLAN logs starting with W

This page lists all the logs starting with the letter W that are generated by the VLAN source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[B](#) | [C](#) | [E](#) | [F](#) | [N](#) | [S](#) | [V](#) | [W](#)

- [Wrong VLANs nvq RecDescr actRecs](#)
- [Wrong VLANs nvq RecDescr actRecs](#)
- [Wrong VMACs nvq RecDescr actRecs](#)
- [Wrong VMACs nvq RecDescr actRecs](#)
- [Wrong vrec field](#)
- [Wrong vrec field](#)

[B](#) | [C](#) | [E](#) | [F](#) | [N](#) | [S](#) | [V](#) | [W](#)



# L3Mgr logs starting with A

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## L3Mgr logs starting with A

This page lists all the logs starting with the letter A that are generated by the L3Mgr source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

- [Action not supported](#)
- [!Alert! file=%s line=%d msg=%s](#)

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# L3Mgr logs starting with B

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## L3Mgr logs starting with B

This page lists all the logs starting with the letter B that are generated by the L3Mgr source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

- [Bad Param %d](#)

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# L3Mgr logs starting with D

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## L3Mgr logs starting with D

This page lists all the logs starting with the letter D that are generated by the L3Mgr source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

- [Default VRF Name can not be changed.](#)
- [Destination unit not found](#)
- [Dynamic ARP could not be learned. maximum dynamic ARP limit is reached.](#)
- [Dynamic route could not be learned. maximum dynamic route is reached.](#)

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# L3Mgr logs starting with E

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## L3Mgr logs starting with E

This page lists all the logs starting with the letter E that are generated by the L3Mgr source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

- [ECMP features disabled due to inadequate license](#)
- [ECMP features disabled due to inadequate license.](#)
- [Entry already exists](#)
- [Entry does not exist](#)
- [Entry is not active](#)
- [Error](#)
- [Exception tid=%p vec=%#x esf=%#x](#)

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# L3Mgr logs starting with F

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## L3Mgr logs starting with F

This page lists all the logs starting with the letter F that are generated by the L3Mgr source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

- [Failed ARP add ip addr 0xFFFFFFFF to HW hw error code](#)
- [Failed ARP add %#x/%#x to HW \(%d\).](#)
- [Failed MVLAN\(%d\) L3 %d.%d.%d.%d](#)
- [Failed MVLAN\( vid \) L3 ip addr ip mask](#)
- [Failed route add <ip addr/ip mask> to HW <hw error code>](#)
- [Failed route add %#x/%#x nh %#x, vlan %d, port %#x to HW \(%d\).](#)
- [Failed to create IP intf %d:%#x in HW \(%d\).](#)
- [Failed to create IP intf vid ip addr in HW hw error code](#)
- [File=%s line=%d val=0x%X](#)

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# L3Mgr logs starting with G

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## L3Mgr logs starting with G

This page lists all the logs starting with the letter G that are generated by the L3Mgr source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

- [Gateway=%#x cost=%d line=%d](#)
- [General Error](#)
- [GWL3 failed at %d, IP %#x, vid %d unit %d \(%d\).](#)
- [GWL3 failed at %d, MAC %08x%04x, vid %d unit %d \(%d\).](#)
- [GWL3 failed at %d, NET %#x/%#x, vid %d unit %d \(%d\).](#)

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020  
©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# L3Mgr logs starting with I

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## L3Mgr logs starting with I

This page lists all the logs starting with the letter I that are generated by the L3Mgr source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

- [IMC Error \(mem or send\)](#)
- [Inconsistent value](#)
- [Internal Error](#)
- [Invalid source interface id](#)
- [Invalid source interface type](#)
- [IP blocking now %d \(1=ON,2=OFF\).](#)
- [IP blocking now 1 2 \(1=ON 2=OFF\)](#)

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# L3Mgr logs starting with L

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## L3Mgr logs starting with L

This page lists all the logs starting with the letter L that are generated by the L3Mgr source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

- [Limit reached for static routes.](#)
- [L3MGR is %s %s %#x](#)
- [l3m\\_smgr exp db %s 0x%X](#)
- [l3m\\_smgr rep db cat=%d cnt=%d](#)
- [l3m\\_smgr rx db cat=%d cnt=%d rxdb=0x%X](#)
- [l3m\\_smgr stkev %d %x %s](#)
- [L3S event=%s state=%s new=%s](#)
- [L3S unexpected event=%s state=%s enabled=%d](#)
- [L3 %s %#x %#x](#)

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# L3Mgr logs starting with M

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## L3Mgr logs starting with M

This page lists all the logs starting with the letter M that are generated by the L3Mgr source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

- [Maximum number of dynamic routes reached](#)
- [Maximum number of dynamic routes reached.](#)
- [Max-local is smaller than local configured interfaces number.](#)
- [Max number of dynamic routes increased.](#)
- [Max-static is smaller than local configured static routes number.](#)
- [MVLAN vid=%d ip=%#x msk=%#x](#)

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)



# L3Mgr logs starting with N

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## L3Mgr logs starting with N

This page lists all the logs starting with the letter N that are generated by the L3Mgr source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

- [New IP Route Partitioning becomes effective on next L3/L2 mode change.](#)

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# L3Mgr logs starting with O

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## L3Mgr logs starting with O

This page lists all the logs starting with the letter O that are generated by the L3Mgr source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

- [Ok](#)

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# L3Mgr logs starting with R

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## L3Mgr logs starting with R

This page lists all the logs starting with the letter R that are generated by the L3Mgr source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

- [Radius use-mgmt-ip must be disabled first](#)
- [Resource not available](#)
- [RPC Error \(mem or send\)](#)

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# L3Mgr logs starting with S

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## L3Mgr logs starting with S

This page lists all the logs starting with the letter S that are generated by the L3Mgr source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

- [Save/restore line=%d msg=%s val=0x%X](#)

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# L3Mgr logs starting with T

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## L3Mgr logs starting with T

This page lists all the logs starting with the letter T that are generated by the L3Mgr source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

- [Table is full](#)
- [tx db cat=%d cnt=%d](#)

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# L3Mgr logs starting with V

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## L3Mgr logs starting with V

This page lists all the logs starting with the letter V that are generated by the L3Mgr source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [I](#) | [V](#) | [W](#) | [X](#)

- [VLAN to VRF Mapping Message Sent Failure.](#)
- [VRF Already Exist.](#)
- [VRF Constructor failed to create.](#)
- [VRF feature disabled due to inadequate license.](#)
- [VRF IP Forwarding is Enable while changing the Maxroutes.](#)
- [VRF Not Exist.](#)
- [VRF NvRAM Open Error.](#)
- [VRF NvRAM Read Error.](#)

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [I](#) | [V](#) | [W](#) | [X](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# L3Mgr logs starting with W

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## L3Mgr logs starting with W

This page lists all the logs starting with the letter W that are generated by the L3Mgr source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

- [Warning](#)
- [Wrong value](#)
- [Wrong value](#)

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# L3Mgr logs starting with X

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## L3Mgr logs starting with X

This page lists all the logs starting with the letter X that are generated by the L3Mgr source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

- [0x%X 0x%X 0x%X](#)

[A](#) | [B](#) | [D](#) | [E](#) | [F](#) | [G](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [R](#) | [S](#) | [T](#) | [V](#) | [W](#) | [X](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## IGMP logs starting with I

This page lists all the logs starting with the letter I that are generated by the IGMP source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

I

- [IGAP : Acct started - Group = 0x%x, UsrIP = 0x%x, port = %d](#)
- [IGAP : Acct stopped - Group = 0x%x, UsrIP = 0x%x, port = %d](#)
- [IGAP : Enabled\(1\)/Disabled\(0\) - %d](#)
- [IGAP : Join Failed. Same m/c MAC-vlan=%d.OldGrp=0x%x.NewGrp=0x%x](#)
- [IGAP : Set Router Port - vlan = %d, port = %d](#)
- [IGAP : Stacking is not supported but detected stack!](#)
- [IGAP : User Join - Group = 0x%x, UsrIP = 0x%x, port = %d](#)
- [IGAP : User Leave - Group = 0x%x, UsrIP = 0x%x, port = %d](#)
- [IGAP : User Timeout - Group = 0x%x, UsrIP = 0x%x, port = %d](#)
- [IGMP Added reserved multicast address](#)
- [IGMP: Added reserved multicast address](#)
- [IGMP: Config. database exchanged between all units of the stack](#)
- [IGMP: Config. database received on unit %d from %d](#)
- [IGMP: Config. database sent by unit %d](#)
- [IGMP: Config. failed. Loaded to factory default](#)
- [IGMP: Config. loaded successfully](#)
- [IGMP: Dynamic router port %d added](#)
- [IGMP: Dynamic router port %d removed](#)
- [IGMP: Error sending database from unit %d](#)
- [IGMP Error sending database from unit unit#](#)
- [IGMP: Error sending group database from unit %d](#)
- [IGMP Error sending group database from unit unit#](#)
- [IGMP: Exceeded reserved multicast address range: #Addr %d \\* #VLANs %d > %d](#)
- [IGMP Exceeded reserved multicast address range #Addr numResAddrEntries+1 \\* #VLANs numActiveVLANs maxReservedRange](#)
- [IGMP: Group database received from all non-base units](#)
- [IGMP: Group database received on unit %d from %d](#)
- [IGMP: Group database sent by unit %d](#)
- [IGMP: Initialization failed: Error code %d](#)
- [IGMP Initialization failed Error code errCode](#)
- [IGMP: Initialization success](#)
- [IGMP: Join stack completed. Database synchronized](#)
- [IGMP: LEAVE received for Group 0x%x on VLAN %d and port %d](#)
- [IGMP: Mirror port %d set](#)
- [IGMP: Multicast table full, dropping streams](#)
- [IGMP: new Querier IP learned on port %d](#)
- [IGMP: Not able to join stack: Error code %d](#)
- [IGMP: Policy initialization failed](#)
- [IGMP: Policy initialization success](#)
- [IGMP: Port %d added to VLAN %d](#)
- [IGMP: Port %d removed from VLAN %d](#)
- [IGMP: Proxy disabled on VLAN %d](#)
- [IGMP Proxy disabled on VLAN vlan#](#)
- [IGMP: Proxy enabled on VLAN %d](#)
- [IGMP Proxy enabled on VLAN vlan#](#)

- [IGMP: QUERY received for Group 0x%x on VLAN %d and port %d](#)
- [IGMP: Query Time set to %d on VLAN %d](#)
- [IGMP Query Time set to num on VLAN vlan#](#)
- [IGMP Removed reserved multicast address](#)
- [IGMP: Removed reserved multicast address](#)
- [IGMP: REPORT received for Group 0x%x on VLAN %d and port %d](#)
- [IGMP: Robust Value set to %d on VLAN %d](#)
- [IGMP Robust Value set to num on VLAN vlan#](#)
- [IGMP: Snooping disabled on VLAN %d](#)
- [IGMP Snooping disabled on VLAN vlan#](#)
- [IGMP: Snooping enabled on VLAN %d](#)
- [IGMP Snooping enabled on VLAN vlan#](#)
- [IGMP SSM Range changed](#)
- [IGMP: Trunk %d created. IGMP groups added on all trunk ports](#)
- [IGMP: Trunk %d removed. IGMP groups removed on all trunk ports](#)
- [IGMP Unable to add reserved multicast address](#)
- [IGMP: Unable to add reserved multicast address](#)
- [IGMP Unknown Multicast Filter disabled](#)
- [IGMP: Unknown Multicast Filter disabled](#)
- [IGMP Unknown Multicast Filter enabled](#)
- [IGMP: Unknown Multicast Filter enabled](#)
- [IGMP V1 router ports mask](#)
- [IGMP V2 router ports mask](#)
- [IGMP: V1 router ports mask](#)
- [IGMP: V2 router ports mask](#)

1



# MLT logs starting with D

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT logs starting with D

This page lists all the logs starting with the letter D that are generated by the MLT source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[D](#) | [E](#) | [L](#) | [M](#) | [P](#)

- [Disabling trunk ports for loop prevention:](#)
- [DMLT:%d disabled due stack failure keep unit:%d port:%d enabled](#)

[D](#) | [E](#) | [L](#) | [M](#) | [P](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT logs starting with E

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT logs starting with E

This page lists all the logs starting with the letter E that are generated by the MLT source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[D](#) | [E](#) | [L](#) | [M](#) | [P](#)

- [Enabling trunk ports:](#)

[D](#) | [E](#) | [L](#) | [M](#) | [P](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# MLT logs starting with L

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT logs starting with L

This page lists all the logs starting with the letter L that are generated by the MLT source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[D](#) | [E](#) | [L](#) | [M](#) | [P](#)

- [Last MLT trunk was allocated by LAC. No more free trunk groups.](#)
- [Last MLT trunk was allocated by MLT. No more free trunk groups.](#)

[D](#) | [E](#) | [L](#) | [M](#) | [P](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT logs starting with M

This page lists all the logs starting with the letter M that are generated by the MLT source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[D](#) | [E](#) | [L](#) | [M](#) | [P](#)

- [MLT %d disabled due to: %s](#)
- [MLT debug: %d, %d, %x](#)
- [MLT %d failed configuration verification.](#)
- [MLT %d failed configuration verification. Bad ARP INSPECTION configuration.](#)
- [MLT %d failed configuration verification. Bad DHCP-SNOOPING configuration.](#)
- [MLT %d failed configuration verification. Bad IGMP configuration.](#)
- [MLT %d failed configuration verification. Bad IPSG CLASS configuration.](#)
- [MLT %d failed configuration verification. Bad ISPG CLASS configuration.](#)
- [MLT %d failed configuration verification. Bad MAC learning configuration.](#)
- [MLT %d failed configuration verification. Bad rate-limiting configuration.](#)
- [MLT %d failed configuration verification. Bad SLPP-guard configuration.](#)
- [MLT %d failed configuration verification. Bad SPBM configuration.](#)
- [MLT %d failed configuration verification. Bad STORM CONTROL configuration.](#)
- [MLT %d failed configuration verification. Bad VLACP configuration.](#)
- [MLT %d failed configuration verification. Bad VLAN configuration.](#)
- [MLT %d failed configuration verification. Error #: %d-%d](#)
- [MLT %d failed configuration verification. Ports are in different static VLANs.](#)
- [MLT %d failed configuration verification. Ports are in different VLANs.](#)
- [MLT %d failed configuration verification. Ports have different private-vlan port type.](#)
- [MLT %d failed configuration verification. Ports have different static vlan PVIDs.](#)
- [MLT %d failed configuration verification. Ports have different static vlan tagging.](#)
- [MLT %d failed configuration verification. Ports have different VLACP admin enable state.](#)
- [MLT %d failed configuration verification. Ports have different VLACP ethertype.](#)
- [MLT %d failed configuration verification. Ports have different VLACP fast periodic time value.](#)
- [MLT %d failed configuration verification. Ports have different VLACP mac address.](#)
- [MLT %d failed configuration verification. Ports have different VLACP slow periodic time value.](#)
- [MLT %d failed configuration verification. Ports have different VLACP timeout scale.](#)
- [MLT %d failed configuration verification. Ports have different VLACP timeout type.](#)
- [MLT %d failed configuration verification. Ports have different vlan priorities.](#)
- [MLT %d failed configuration verification. Ports have different vlan PVIDs.](#)
- [MLT %d failed configuration verification. Ports have different vlan tag frames filter settings.](#)
- [MLT %d failed configuration verification. Ports have different vlan tagging.](#)
- [MLT %d failed configuration verification. Ports have different vlan unreg frames filter settings.](#)
- [MLT %d failed configuration verification. Ports have different vlan untag frames filter settings.](#)
- [MLT Distribute DB fail](#)
- [MLT failed to get STP sync semaphore.](#)
- [MLT get buffer failed](#)
- [MLT get module info fail](#)
- [MLT get msgQ RX fail](#)
- [MLT get msgQ unknown cmd](#)
- [MLT get stack event invalid](#)
- [MLT ID# failed configuration verification. Error # error num](#)
- [MLT IMC acknowledge error](#)
- [MLT IMC get buffer fail](#)
- [MLT IMC invalid cmd](#)

- [MLT IMC set link fail](#)
- [MLT IMC set name fail](#)
- [MLT IMC set state fail](#)
- [MLT IMC set STP fail](#)
- [MLT IMC set trunk with bad parameters](#)
- [MLT IMC subType invalid](#)
- [MLT IMC tx error](#)
- [MLT Join module DB fail](#)
- [MLT misconfiguration may be on Trunk #1.](#)
- [MLT misconfiguration may be on Trunk #2.](#)
- [MLT misconfiguration may be on Trunk #3.](#)
- [MLT misconfiguration may be on Trunk #4.](#)
- [MLT misconfiguration may be on Trunk #5.](#)
- [MLT misconfiguration may be on Trunk #6.](#)
- [MLT NV File error](#)
- [MLT NV File reset](#)

[D](#) | [E](#) | [L](#) | [M](#) | [P](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# MLT logs starting with P

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## MLT logs starting with P

This page lists all the logs starting with the letter P that are generated by the MLT source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[D](#) | [E](#) | [L](#) | [M](#) | [P](#)

- [Port %d/%d of MLT %d is disabled because it has wrong configuration](#)

[D](#) | [E](#) | [L](#) | [M](#) | [P](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## SSH logs starting with S

This page lists all the logs starting with the letter S that are generated by the SSH source.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

### S

- [SSHC: DSA Authentication failure](#)
- [SSHC: DSA key deleted](#)
- [SSHC: DSA key generation completed](#)
- [SSHC: DSA key generation failure](#)
- [SSHC: DSA key save failure](#)
- [SSHC: DSA key upload TFTP failure](#)
- [SSHC: DSA key upload USB failure](#)
- [SSH CLIENT: Key couldn't be saved for host %s](#)
- [SSH CLIENT: SSH Connection to %s was closed because parent console session #%d was closed.](#)
- [SSH CLIENT: SSH Connection to %s was disconnected by host. Connection time: %s.](#)
- [SSH CLIENT: Successful SSH Connection to %s, using %s authentication](#)
- [SSH: Client tried to authenticate with invalid certificate from address %s](#)
- [SSH: Client tried to authenticate without principal name in certificate from address %s](#)
- [SSH: Client tried to authenticate with revoked certificate from address %s](#)
- [SSH: could not perform OCSP for the server certificate from address %s](#)
- [SSH: Couldn't create SSH Data Semaphore](#)
- [SSHC: RSA key deleted](#)
- [SSHC: RSA key generation completed](#)
- [SSHC: RSA key upload TFTP failure](#)
- [SSHC: RSA key upload USB failure](#)
- [SSHC: server connection failure](#)
- [SSHC: SSH Client session rekey failure](#)
- [SSHC: SSH Client session rekey success](#)
- [SSH disabled](#)
- [SSH: DSA Authentication failure](#)
- [SSH: DSA auth key deleted](#)
- [SSH DSA key deleted](#)
- [SSH DSA KEY generation completed](#)
- [SSH: DSA KEY generation completed](#)
- [SSH enabled in non-secure mode](#)
- [SSH enabled in secure mode](#)
- [SSH Maximum number of ssh sessions has been reached](#)
- [SSH: Maximum number of ssh sessions has been reached](#)
- [SSH: No response to OCSP query for client certificate from address %s](#)
- [SSH: OCSP query verification passed for server certificate from address %s](#)
- [SSH: OCSP test failed for client certificate from address %s](#)
- [SSH: OCSP test failed for server certificate from address %s](#)
- [SSH: Password Authentication failure](#)
- [SSH: RADIUS server unreachable - client at address %s authenticated with local credentialsInformation](#)
- [SSH: RSA Authentication failure](#)
- [SSH: RSA auth key deleted](#)
- [SSH RSA key deleted](#)
- [SSH RSA KEY generation completed](#)
- [SSH: RSA KEY generation completed](#)
- [SSH RSA key overwritten](#)

SSH: Server tried to authenticate with revoked certificate from address %s

- SSH session login using port
- SSH session login using port:
- SSH: SSH session rekey failure
- SSH: SSH session rekey success
- SSH: Succesfull response to OCSP query for client certificate from address %s
- SSH System is generating DSA KEY wait ...
- SSH: System is generating DSA KEY, wait ...
- SSH: System is generating RSA KEY, wait ...
- SSH TFTP DSA key download complete
- SSH TFTP RSA key download complete
- SSH: The DSA key overwritten
- SSH: The RSA key overwritten
- SSH: Unknown response to OCSP query for client certificate from address %s
- SSH: Unknown response to OCSP query for server certificate from address %s
- SSH USB DSA key download complete
- SSH: USB DSA key download complete
- SSH USB RSA key download complete
- SSH: USB RSA key download complete

S

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Information logs starting with A

This page lists all the logs starting with the letter A that are generated with a severity of Information.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [AAUR-Info AAUR default](#)
- [AAUR-Info AAUR disable](#)
- [AAUR-Info AAUR enable](#)
- [AAUR-Info Agent transfer finished](#)
- [AAUR - Info: Receive request for agent image. start transfer](#)
- [AAUR-Info Receive request for agent image start transfer](#)
- [AAUR-Info Receive request for agent image. Unable to start transfer](#)
- [AAUR-Info Send request for new agent image](#)
- [AAUR-Info Slave refuse transfer](#)
- [AAUR-Info The hardware is not compatible with the image version number version](#)
- [AAUR-Warning Cannot get FLASH resource](#)
- [Access assignment distribution across stack failed](#)
- [Access element distribution across stack failed](#)
- [ADAC Error applying main VLAN QoS configuration](#)
- [ADAC Error applying VLAN QoS configuration for unit port unit# port#](#)
- [ADAC Error forcing administrative state to disable enable](#)
- [ADAC Error removing main VLAN QoS configuration](#)
- [ADAC Error removing VLAN QoS configuration for unit port unit# port#](#)
- [ADAC Forced administrative state to disable enable](#)
- [ADAC System operationally disable enable](#)
- [Agent configuration distribution across stack failed](#)
- [Allowed connection attempt from user :](#)
- [Another BU tried to join the stack. Unit ignored](#)
- [application\\_name failed DB-exchange stack formation delayed](#)
- [App-Telemetry: User configuration file loaded](#)
- [ASCFG - Error: Failed to get file from TFTP](#)
- [ASCFG - Error: Failed to get file from USB](#)
- [ASCFG - Error: Failed to get script buffer](#)
- [ASCFG - Error: Failed to get the flash resource](#)
- [ASCFG - Error: Failed to give sem semBAutoSaveAscDone](#)
- [ASCFG - Error: Failed to init ascii file system](#)
- [ASCFG - Error: Failed to malloc memory for ram drive](#)
- [ASCFG - Error: Failed to open ascii file system](#)
- [ASCFG - Error: Failed to open record file](#)
- [ASCFG - Error: Failed to open script file](#)
- [ASCFG - Error: Failed to read record file](#)
- [ASCFG - Error: Failed to read script file](#)
- [ASCFG - Error: Failed to release the flash resource](#)
- [ASCFG - Error: Failed to run script file](#)
- [ASCFG - Error: Failed to save ascii file system](#)
- [ASCFG - Error: Failed to send msg to ascfg queue](#)
- [ASCFG - Error: Failed to send notice to NBU](#)
- [ASCFG - Error: Failed to take sem semBAutoSaveAscDone](#)
- [ASCFG - Error: Failed to update the status](#)
- [ASCFG - Error: Failed to write record file](#)

- [ASCFG - Error: Failed to write script file](#)
- [ASCFG - Error: File larger max file size](#)
- [ASCFG - Error: Invalid file system. Init](#)
- [ASCFG - Error: Invalid script entry 0](#)
- [ASCFG - Error: Invalid script entry 1](#)
- [ASCFG - Info: Run Boot Script Successfully](#)
- [ASCII failed](#)
- [ASCII finished successfully](#)
- [ASCII finished successfully at load on boot](#)
- [ASCII transfer failed](#)
- [ASCII transfer failed at load on boot](#)
- [ASCII transfer OK](#)
- [ASCII transfer OK at load on boot](#)
- [AUR-Info AUR disable](#)
- [AUR-Info AUR enable](#)
- [AUR-Info AUR Restored to default](#)
- [AUR-Info New unit has different HW config Using cfg from the new unit](#)
- [Authentication Failure Trap](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Information logs starting with B

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Information logs starting with B

This page lists all the logs starting with the letter B that are generated with a severity of Information.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [Backup configuration block %d in use](#)
- [Backup configuration restored from primary configuration block %d](#)
- [Backup configuration updated for next active configuration block %d](#)
- [Backup Configuration Version is updated](#)
- [Base action distribution across stack failed](#)
- [BaySec Exceeded number MAC addresses on unit# port#](#)
- [Bay Secure Exceeded number per-port MAC addresses on port unit# port#](#)
- [Bay Secure intruder](#)
- [Bay Secure intruder MAC](#)
- [Bay Secure per-port addresses deleted](#)
- [BECOME\\_TEMP\\_BU event sent unit mask value appl mask value](#)
- [Boot: system boot status 0x%x](#)
- [BPDU received on port with BPDU-Filtering enabled.](#)
- [BU was unable to send IMC for NBUs VLAN/Port configuration](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Information logs starting with C

This page lists all the logs starting with the letter C that are generated with a severity of Information.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [cam driver initialized](#)
- [Cannot delete ISID used by EAP Fail Open VLAN](#)
- [Cannot delete ISID used by EAP Guest VLAN](#)
- [Cannot delete ISID used by EAP VoIP VLAN](#)
- [Cannot disable IP Source Guard on Unit unit# Port port#](#)
- [Cannot enable SPBM: EAP Guest, FailOpen or Voice VLANs are not default](#)
- [Cannot enable SPBM while MVR is enabled](#)
- [Cannot set IP source address to zero when IP Shortcut is enabled](#)
- [Capabilities determined by agent \(not-writable\)](#)
- [CDT MAC address mac\\_address was removed because LAG trunk trunked has disaggregated.](#)
- [CDT MAC address mac\\_address was removed because port port\\_no has aggregated in LAG](#)
- [CDT The static FDB entry MAC mac\\_address VLAN vlan\\_id trunk trunkId was deleted because LAG has disaggregated](#)
- [CDT The static FDB entry MAC mac\\_address VLAN vlan\\_id was deleted because Unit Port unit port has aggregated](#)
- [CFG - Could not acquire FLASH sem](#)
- [CFGSO - Error: Failed to create watchdog timer](#)
- [CFGSO - Error: Failed to get an imc buffer](#)
- [CFGSO - Error: Failed to save data to NBU](#)
- [CFGSO - Error: Failed to start watchdog timer](#)
- [CFGSO - Error: File not read](#)
- [CFGSO - Error: File not write](#)
- [CFM: ERROR adding port filters for VLAN %d - no resources](#)
- [Change of active config block and or reset failed block-number](#)
- [Classifier block distribution across stack failed](#)
- [Classifier component distribution across stack failed](#)
- [Classifier inconsistency detected \(conflicting allocation modes\)](#)
- [Cli add vlan vlan\\_id members port mask](#)
- [Cli create vlan vlan\\_id type port](#)
- [Cli delete vlan vlan\\_id members port mask](#)
- [Cli delete vlan vlan\\_id type port](#)
- [CLI pswd: Stack authentication parameter is obsolete: unified changes have been applied to both stack and switch](#)
- [CLI pswd: Stack auth type RADIUS/TACACS+ won't apply partially \(stack IP addr not set\). Local user/pass used](#)
- [CLI pswd: Stack auth type RADIUS/TACACS+ won't apply partially \(switch IP addr not set\). Local user/pass used](#)
- [CLI pswd: Switch authentication parameter is obsolete: changes have not been applied](#)
- [Cli set autopvid disable](#)
- [Cli set autopvid enable](#)
- [Cli set management vlan vlan\\_id](#)
- [Cli set ports port mask tagging disable](#)
- [Cli set ports port mask tagging enable](#)
- [Cli set pvid vlan\\_id ports port mask](#)
- [Cli set vlan vlan\\_id members port mask](#)
- [Cold Start Trap](#)
- [Config areas already remapped on unit %d](#)
- [Configuration block %d is now in use](#)
- [Configuration saved to nv block # block\\_number](#)
- [Conflicting egress interface and egress trunk data specified](#)

- [Connection closed \(failed login\) IP address:](#)
- [Connection closed \(inactivity logout\) IP address](#)
- [Connection closed \(login timeout\) IP address:](#)
- [Connection closed \(lost connection\) IP address](#)
- [Connection closed. Maximum number of sessions reached. IP address:](#)
- [Connection closed. Maximum number of sessions reached. IP address:](#)
- [Connection closed \(user logout\). IP address:](#)
- [Cons activate vlan vlan id](#)
- [Cons add vlan vlan id port unit port](#)
- [Cons create vlan vlan id type port](#)
- [Cons delete vlan vlan id port unit port](#)
- [Cons delete vlan vlan id type port](#)
- [Cons set autopvid disable](#)
- [Cons set autopvid enable](#)
- [Cons set management vlan vlan id](#)
- [Cons set port unit port pvid vlan id](#)
- [Cons set port unit port tagging disable](#)
- [Cons set port unit port tagging enable](#)
- [COS mapping distribution across stack failed](#)
- [CoS shaping distribution across stack failed](#)
- [Count action distribution across stack failed](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Information logs starting with D

This page lists all the logs starting with the letter D that are generated with a severity of Information.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [DAI: ARP packet with invalid IP/MAC binding dropped on untrusted port %d/%d. ARP packet has MAC source %02x-%02x-%02x-%02x-%02x-%02x.](#)
- [DAI ARP packet with invalid IP MAC binding dropped on untrusted port unit# port#](#)
- [DAPP-detected DoS attack blocked unit unit# \(many ports\)](#)
- [DAPP-detected DoS attack blocked unit unit# port port#](#)
- [DAPP support disable failure](#)
- [DAPP support enable failure](#)
- [Data distribution class class# across stack failed](#)
- [DAUR - Info Diag transfer finished](#)
- [DAUR - Info Receive request for diag image start transfer](#)
- [DAUR - Info Receive request for diag image. Unable to transfer](#)
- [DAUR - Info Send request for new diag image](#)
- [DAUR - Info Slave refuse transfer](#)
- [DAUR - Info Start receive image](#)
- [DAUR - The hardware is not compatible with the image version number version](#)
- [DAUR - Warning: Cannot get FLASH resource](#)
- [DHCP packet with mismatch MAC address dropped on un-trusted port unit# port# mac\(MAC ADDRESS\)](#)
- [DHCP Snoop DHCP ACK dropped on untrusted port unit# port# \(not allowed on untrusted port\)](#)
- [DHCP Snoop DHCP binding table is full additional DHCP clients will not be added to the binding table](#)
- [DHCP Snoop: DHCP DISCOVER dropped on port %d/%d \(source MAC not matching client MAC\)](#)
- [DHCP Snoop DHCP NAK dropped on untrusted port unit# port# \(not allowed on untrusted port\)](#)
- [DHCP Snoop DHCP OFFER dropped on untrusted port unit# port# \(not allowed on untrusted port\)](#)
- [DHCP Snoop: DHCP packet dropped on port %d/%d - static entry with the same MAC %02x-%02x-%02x-%02x-%02x-%02x in binding table](#)
- [DHCP Snoop: DHCP packet dropped on port %d/%d - static entry with the same MAC %02x-%02x-%02x-%02x-%02x-%02x in binding table](#)
- [DHCP Snoop DHCP RELEASE DECLINE dropped on untrusted port unit# port# because MAC Addr\( MACaddress \) is associated to port unit# port#](#)
- [DHCP Snoop DHCP RELEASE DECLINE dropped on untrusted port unit# port# \(MAC Addr\(MACaddress \) does not exist in binding table\)](#)
- [DHCP Snoop DHCP REQUEST dropped on un-trusted port unit# port# due to source MAC address\(MAC ADDRESS\) not matching DHCP client](#)
- [DHCP Snoop DHCP snooping binding table restored successfully from TFTP address](#)
- [DHCP Snoop DHCP snooping binding table restored successfully from USB unit unit#](#)
- [DHCP Snoop: DHCP snooping binding table restore from SFTP address](#)
- [DHCP Snoop DHCP snooping binding table restore from TFTP address A.B.C.D IPv6 address failed](#)
- [DHCP Snoop DHCP snooping binding table restore from USB unit unit# failed](#)
- [DHCP Snoop: DHCP snooping binding table saved successfully to SFTP address](#)
- [DHCP Snoop DHCP snooping binding table saved successfully to TFTP address](#)
- [DHCP Snoop DHCP snooping binding table saved successfully to USB unit unit#](#)
- [DHCP Snoop: DHCP snooping binding table save to SFTP address](#)
- [DHCP Snoop DHCP snooping binding table save to TFTP address A.B.C.D IPv6 address failed](#)
- [DHCP Snoop: DHCP snooping binding table save to TFTP address, failed](#)
- [DHCP Snoop DHCP snooping binding table save to USB unit unit# failed](#)
- [DHCP Snoop: DHCP snooping binding table succesfully restored from SFTP address](#)

- [DHCP Snoop DHCP snooping entry entry number not restored due to expired lease](#)
- [DHCP Snoop DHCP snooping entry entry number not restored due to MAC conflict](#)
- [DHCP Snoop DHCP snooping entry entry number not restored due to parsing failure](#)
- [DHCP Snoop DHCP snooping entry with MAC MacAddress not restored on invalid interface unit# port#](#)
- [DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored \(invalid Vlan %d\)](#)
- [DHCP Snoop: DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored on trusted interface %d/%d](#)
- [DHCP Snoop: DHCP snooping entry 0x%08x not restored on trusted interface %d/%d](#)
- [DHCP snooping entry with MAC %02x-%02x-%02x-%02x-%02x-%02x not restored \(invalid Vlan %d\)](#)
- [DHCP Snoop NTP is not synchronized: external save restore of DHCP snooping entries not possible](#)
- [Disallowed connection Access Reject for user :](#)
- [Disallowed connection attempt from IP address:](#)
- [Disallowed connection attempt - too many telnet sessions](#)
- [Disallowed connection Invalid SvcType for user :](#)
- [DISTRIBUTE DB event sent unit mask value appl mask value](#)
- [DosFs - Error File not closed](#)
- [Downstream stack direction is down cable removed or neighbor powered off](#)
- [Downstream stack direction is mis-configured](#)
- [Downstream stack direction is up cable inserted or neighbor powered on](#)
- [DSCP mapping distribution across stack failed](#)
- [DSCP value modification prohibited](#)
- [Duplicate address deletion failed ipv6 address](#)
- [Duplicate address detection succeeded ipv6 address](#)
- [Duplicate entry detected \(prohibited\)](#)
- [Duplicate FCoE redirection entry detected](#)
- [Dynamic role combination cannot be used in explicit assignment](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Information logs starting with E

This page lists all the logs starting with the letter E that are generated with a severity of Information.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [EAP Bad pkt id](#)
- [EAP Bad pkt len](#)
- [EAP: cannot apply contradictory Egress Vid %d on port %d.](#)
- [EAP: cannot apply Egress Vids on ADAC port %d.](#)
- [EAP: cannot apply inexistent Egress Vid %d on port %d.](#)
- [EAP: cannot apply inexistent Egress VLAN Name on port %d.](#)
- [EAP: Cannot enable IP source guard on port %s: DHCP snooping is not enabled globally](#)
- [EAP: Cannot enable IP source guard on port %s: the port is not a member of a DHCP Snooping enabled VLAN](#)
- [EAP: Cannot enable IP source guard on port %s: the port is not a member of an ARP Inspection enabled VLAN](#)
- [EAP: Cannot enable IP source guard on port %s: unable to apply the new setting](#)
- [EAP: Cannot set DHCP Snooping on non-autocreated VLAN %d](#)
- [EAP: Cannot set DHCP Snooping option82 on non-autocreated VLAN %d](#)
- [EAP: Cannot set Dynamic ARP Inspection on non-autocreated VLAN %d](#)
- [EAP: Cannot set IGMP Snooping on non-autocreated VLAN %d](#)
- [EAP: Cannot set IGMP Snooping on Switched UNI VLAN %d](#)
- [EAP: Cannot set option 82 subscriber ID longer than %d characters on port %d](#)
- [EAP: Cannot set speed/duplex on port %s: cannot retrieve current configuration](#)
- [EAP: Cannot set speed/duplex on port %s: memory allocation error](#)
- [EAP: Cannot set speed/duplex on port %s: speed or duplex value missing](#)
- [EAP: Cannot set speed/duplex on port %s: unable to apply the new port configuration](#)
- [EAP: Cannot set speed/duplex on port %s: unsupported values](#)
- [EAP CDT Error](#)
- [EAP Client blocked \(Block Subsequent MAC Authentication\): Different VID than expected](#)
- [EAP Client blocked \(Block Subsequent MAC Authentication\): Invalid VID](#)
- [EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid bindings exceeded the maximum threshold of 94](#)
- [EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with different Isid from the configured one is invalid](#)
- [EAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:Isid with Isid <> 0 not supported in Standalone Proxy or Autopro](#)
- [EAP Could not process pkt](#)
- [EAP Error - Default](#)
- [EAP Error - Failed to free mac info memory](#)
- [EAP Error Radius - ifIndex not found](#)
- [EAP Error while sending Access Violation Trap](#)
- [EAP Error while sending RAV Error Trap](#)
- [EAP: Failed installing FOV UBP.](#)
- [EAP Failed gpa-RoleAssociation unitPort ifIndex macHi xx-xx macLo xx-xx-xx-xx](#)
- [EAP Failed gpa-RoleAssociation unitPort 0x%x mac %08x%04x](#)
- [EAP Failed to add host, max number of clients reached](#)
- [EAP Failed to add host, memory allocation error](#)
- [EAP GVlan Disabled for unitPort ifIndex - GVlan\( vid \) in different stg\( id \)](#)
- [EAP IMC Failed to send message](#)
- [EAP IMC Memory allocation error](#)
- [EAP Invalid RAV ID](#)
- [EAP Invalid Vlan ID vid configured for port num](#)
- [EAP Mac AuthFail - unitPort <unit-portnum> macHi <xx-xx> macLo <xx-xx-xx-xx>](#)

- [EAP Neap port was not member of any vlan](#)
- [EAP NULL pkt to send on Success](#)
- [EAP: Pvid attribute from RADIUS ignored.](#)
- [EAP Reached Mac Intruder Count](#)
- [EAP: Reached MAC intruder count on %s](#)
- [EAP: Reached maximum number of VLAN ranges for ARP inspection](#)
- [EAP: Reached maximum number of VLAN ranges for DHCP snooping](#)
- [EAP: Reached maximum number of VLAN ranges for DHCP snooping option 82](#)
- [EAP: Reached maximum number of VLAN ranges for IGMP snooping](#)
- [EAP Unable to Reserve EapAdmin Filter Resources rc retCode unitPort ifIndex](#)
- [EAP Unable to Reserve Filter Resources rc retCode unitPort ifIndex Force- Unauthorised](#)
- [EAP Unable to UnReserve EapAdmin Filter Resources rc retCode unitPort ifIndex](#)
- [EAP Unable to UnReserve Filter Resources rc retCode unitPort unit-portnum](#)
- [EAP Vlan Change Aborted](#)
- [EAP: Warning. trying to set DHCP Snooping on VLAN %d not from client's attributes](#)
- [EAP: Warning. trying to set DHCP Snooping option82 on VLAN %d not from client's attributes](#)
- [EAP: Warning. trying to set Dynamic ARP Inspection on VLAN %d not from client's attributes](#)
- [EAP: Warning. trying to set IGMP Snooping on VLAN %d not from client's attributes](#)
- [ECMP features disabled due to inadequate license](#)
- [Egp Neighbor Loss Trap](#)
- [Egress interface or trunk data is required - data missing](#)
- [Element deletion prohibited \(permanent read-only system entry\)](#)
- [Element label not acceptable - reserved](#)
- [Element may only be modified not created or deleted](#)
- [Element modification prohibited \(read-only or system entry\)](#)
- [Energy Server activated by schedule](#)
- [Energy Server deactivated by schedule](#)
- [Energy Server globally disabled](#)
- [Energy Server globally enabled](#)
- [Energy Server manually activated](#)
- [Energy Server manually deactivated](#)
- [Energy Server not applying schedule because SNTP not synchronized](#)
- [Energy Server time is synchronized applying schedule](#)
- [Enterprise Specific Trap](#)
- [Error clearing the configuration counters from flash history on unit %d](#)
- [Error configuring 802.1AB](#)
- [Error configuring LLDP MED policies](#)
- [Error configuring Management IP Address](#)
- [Error configuring port names](#)
- [Error copying the configuration to new flash areas on unit %d](#)
- [Error creating Data VLAN](#)
- [Error creating MLT](#)
- [Error creating Voice VLAN](#)
- [Error deleting previously created cost 1 default route](#)
- [Error deleting previously created Voice and Data VLANs](#)
- [Error disabling global DHCP relay errCode](#)
- [Error enabling ADAC](#)
- [Error enabling ADAC on ports](#)
- [Error enabling global DHCP relay errCode](#)
- [Error enabling IP Routing](#)
- [Error enabling mstp learning on all ports](#)
- [Error enabling rstp learning on all ports](#)
- [Error executing script](#)
- [Error getting VLAN info for Port's pvid](#)
- [Error loading backup configuration block %d](#)
- [Error loading configuration block %d](#)
- [Error loading primary configuration block # block\\_number](#)
- [Error reading nvq\\_ObjDescr from VLAN file](#)
- [Error reading prec from VLAN file](#)
- [Error reading vmrec from VLAN file](#)
- [Error reading vrec from VLAN file](#)
- [Error restoring from VLAN file](#)
- [Error restoring from VLAN file. Wrong nvq.Descr.devVer](#)
- [Error restoring from VLAN file. Wrong nvq.Descr.notBlank](#)
- [Error restoring management vlan to 1 or disabling ip routing](#)

- [Error restoring nvq.Descr from VLAN file](#)
- [Error restoring object from VLAN file - bad file pointer or mode](#)
- [Error restoring object from VLAN NVRAM file](#)
- [Error restoring Port from VLAN NVRAM file](#)
- [Error restoring Ports from VLAN file](#)
- [Error restoring VLANs from VLAN file](#)
- [Error restoring VMACs from VLAN file](#)
- [Error saving configuration](#)
- [Error saving configuration to block # block\\_number](#)
- [Error seeking object in VLAN file](#)
- [Error seeking Ports in VLAN file](#)
- [Error seeking VLANs in VLAN file](#)
- [Error seeking VMACs in VLAN file](#)
- [Error setting ADAC operating mode](#)
- [Error setting call server ports](#)
- [Error setting Data VLAN Gateway IP address and network mask](#)
- [Error setting default IP Route](#)
- [Error setting IP Office Call-Server IP address](#)
- [Error setting IP Office File-Server IP address](#)
- [Error setting Management VLAN](#)
- [Error setting poe-priority high on ports](#)
- [Error setting QoS](#)
- [Error setting spanning-tree learning to fast on all ports](#)
- [Error setting the remap flag in flash on unit %d](#)
- [Error setting uplink ports](#)
- [Error setting VLAN attributes](#)
- [Error setting VLAN Gateway IP address and network mask](#)
- [Error setting Voice VLAN Gateway IP address and network mask](#)
- [Error/Warning - Eap File signals a software downgrade:%d \(%s:%d\), default all eap settings](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Information logs starting with F

This page lists all the logs starting with the letter F that are generated with a severity of Information.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [Fabric Attach: Auto Attach capabilities disabled](#)
- [Fabric Attach: Auto Attach capabilities enabled](#)
- [Fabric Attach: binding acceptance failure \(port %d %d/%d\)](#)
- [Fabric Attach: binding acceptance failure \(port %d/%d %d/%d\)](#)
- [Fabric Attach: binding accepted \(port %d %d/%d\)](#)
- [Fabric Attach: binding accepted \(port %d/%d %d/%d\)](#)
- [Fabric Attach: binding activation success \(port %d %d/%d\)](#)
- [Fabric Attach: binding activation success \(port %d/%d %d/%d\)](#)
- [Fabric Attach: binding deactivation failure \(port %d %d/%d\)](#)
- [Fabric Attach: binding deactivation failure \(port %d/%d %d/%d\)](#)
- [Fabric Attach: binding deactivation success \(port %d %d/%d\)](#)
- [Fabric Attach: binding deactivation success \(port %d/%d %d/%d\)](#)
- [Fabric Attach: binding expiration \(port %d %d/%d\)](#)
- [Fabric Attach: binding expiration \(port %d/%d %d/%d\)](#)
- [Fabric Attach: element type updated](#)
- [Fabric Attach: management VLAN updated \(was <VID>, now <VID>\) by Auto Attach](#)
- [Fabric Attach: multiple FA Servers detected](#)
- [Fabric Attach: primary FA Server lost](#)
- [Fabric Attach: proxy not supported by element type](#)
- [Fabric Attach: service disabled](#)
- [Fabric Attach: service enabled](#)
- [Fabric Attach: specified element type not supported](#)
- [Fabric Attach: zero touch mgmt VLAN distribution disabled](#)
- [Fabric Attach: zero touch mgmt VLAN distribution enabled](#)
- [Failed ARP add ip addr 0xFFFFFFFF to HW hw error code](#)
- [Failed login from IP address](#)
- [Failed login from serial connection](#)
- [Failed login \(local auth\) from IP address:](#)
- [Failed login \(local auth\) from serial connection](#)
- [Failed login\(radius auth\) from IP add](#)
- [Failed MVLAN\( vid \) L3 ip addr ip mask](#)
- [Failed to create IP intf vid ip addr in HW hw error code](#)
- [FCoE controller ifIndex not set - FCoE redirection enable prohibited](#)
- [FCoE controller VLAN not set - FCoE redirection enable prohibited](#)
- [Filter limiting mode not supported on 5510-XX unit cannot join stack](#)
- [Flash Erase Failed Sector %d Address 0x%x](#)
- [Flash Erase Warning Sector %d Address 0x%x Erase time %d ms](#)
- [FSH - File not closed :](#)
- [FSH - Some files are not closed. MsgType # %d](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)





# Information logs starting with G

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Information logs starting with G

This page lists all the logs starting with the letter G that are generated with a severity of Information.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [Gateway IP changed](#)
- [Got UserPolicy from Radius but UBP disabled - unitPort 0x%x mac %08x%04x](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Information logs starting with H

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Information logs starting with H

This page lists all the logs starting with the letter H that are generated with a severity of Information.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [Hello Module unable to communicate with neighbor\(s\) unit reset](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series

9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Information logs starting with I

This page lists all the logs starting with the letter I that are generated with a severity of Information.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [IGMP Added reserved multicast address](#)
- [IGMP Exceeded reserved multicast address range #Addr numResAddrEntries+1 \\* #VLANs numActiveVLANs maxReservedRange](#)
- [IGMP: Multicast table full, dropping streams](#)
- [IGMP No hardware resource available](#)
- [IGMP Proxy disabled on VLAN vlan#](#)
- [IGMP Proxy enabled on VLAN vlan#](#)
- [IGMP Query Time set to num on VLAN vlan#](#)
- [IGMP Removed reserved multicast address](#)
- [IGMP Robust Value set to num on VLAN vlan#](#)
- [IGMP Snooping disabled on VLAN vlan#](#)
- [IGMP Snooping enabled on VLAN vlan#](#)
- [IGMP SSM Range changed](#)
- [IGMP SSM Range changed](#)
- [IGMP Unable to add reserved multicast address](#)
- [IGMP Unknown Multicast Filter disabled](#)
- [IGMP Unknown Multicast Filter enabled](#)
- [IGMP: V2 report drop on reserved GA](#)
- [IGMP: V3 report group skip on invalid GA](#)
- [IGMP: V3 report group skip on reserved GA](#)
- [IGMP V1 router ports mask](#)
- [IGMP V2 router ports mask](#)
- [IMC ack pool alloc failed %s line %d](#)
- [IMC ack timeout msgType= %d imcSeq= %d ackExpected= 0x%02X](#)
- [IMC app rcv routine error, type= %s\(%d\)](#)
- [IMC buffers of size size have been exhausted buffer pool size size](#)
- [IMC buffers of size %u have been exhausted, buffer pool size %u](#)
- [Index value out-of-range](#)
- [Info: Transceiver inserted on %s](#)
- [Info: Transceiver removed from %s](#)
- [Interface action distribution across stack failed](#)
- [Interface application distribution across stack failed](#)
- [Interface assignment distribution across stack failed](#)
- [Invalid Configuration Block Number %d](#)
- [Invalid Configuration Magic Number](#)
- [Invalid Configuration Version Number](#)
- [Invalid drop action option specifiedInvalid drop action option specified](#)
- [Invalid entry creation attempted \(index index# \)](#)
- [Invalid FCoE controller ingress interface specified](#)
- [Invalid FCoE controller VLAN specified](#)
- [Invalid RAV id %d, on port %d, cannot be B-VLAN](#)
- [Invalid/unknown FCoE redirection egress trunk ID specified](#)
- [Invalid update DSCP value specified \( DSCP value.\)](#)
- [IP blocking now 1 2 \(1=ON 2=OFF\)](#)
- [IP classifier distribution across stack failed](#)

## [IPFIX enable failure](#)

- [IpFwdNhop Err Filter Install mod\\_inst=0x%08x vid=%d rv=%d](#)
- [IpFwdNhop Err Filter Modify mod\\_inst=0x%08x vid=%d rv=%d](#)
- [IpFwdNhop Err Filter UnInstall mod\\_inst=0x%08x vid=%d rv=%d](#)
- [IpFwdNhop Err Save DB to NVRAM General File myMod=%d isBU=%d rw=%d](#)
- [IpFwdNhop Err Save DB to NVRAM Instance File myMod=%d isBU=%d rw=%d](#)
- [IpFwdNhop Err Save DB to NVRAM Policy File myMod=%d isBU=%d rw=%d](#)
- [IpFwdNhop: Feature enable temporarily blocked - resources unavailable](#)
- [IpFwdNhop: Filter installation issue - resources unavailable](#)
- [IpFwdNhop: Issue detected during data restore \(interface entry %d\)](#)
- [IpFwdNhop: Issue detected during enable retry \(interface entry %d\)](#)
- [IpFwdNhop: Issue detected during feature enable \(interface entry %d\)](#)
- [IpFwdNhop: Issue detected during interface creation \(interface entry %d\)](#)
- [IpFwdNhop: Issue detected during VLAN %d routing status update](#)
- [IpFwdNhop: Issue detected during VLAN membership addition \(VID %d\)](#)
- [IpFwdNhop: Issue detected during VLAN membership deletion \(VID %d\)](#)
- [IpFwdNhop: Issue detected during VLAN policy association \(entry %d\)](#)
- [IpFwdNhop: Requested precedence and/or filter resources unavailable](#)
- [IpFwdNhop: Requested range checking resources unavailable](#)
- [IpFwdNhop: VLAN membership update \(VID %d\) issue - resources unavailable](#)
- [IP protocol value TCP or UDP needed with Layer 4 port filtering](#)
- [IPSG Insufficient resources available to enable IPSG on port unit# port#](#)
- [IPSG Maximum IP entries on port unit# port# has been reached](#)
- [IPSG nvRam file error param1 param2 param3](#)
- [IPSG Reached Max. IP entries supported on this port port#](#)
- [IPSG Reached Max. IP entries supported on this port unit# port#](#)
- [IPSG Resource allocated for Ports unit# port#](#)
- [IP Source Guard disabled on Unit unit# Port port#](#)
- [IP Source Guard enabled on Unit unit# Port port#](#)
- [IPT BootP Disabled \(response not received from server\)](#)
- [IPT IP Address changed by BOOTP Server](#)
- [IPT: IP Address not in use \(duplicate detected\)](#)
- [IPT: Using the last BOOTP/DHCP assigned IP address \(BOOTP server not reachable\)](#)
- [IPv6 DST MAC filters could NOT be installed.](#)
- [IPv6 DST MAC filters successfully installed.](#)
- [IPv6 enabled with hardware support and FMGR filters](#)
- [IPv6 enabled with hardware support only](#)
- [IPv6 FHS filters could NOT be installed](#)
- [IPv6 FHS filters successfully installed](#)
- [IPv6 Forwarding disabled due to inadequate license](#)
- [IPv6 malloc failure](#)
- [IPv6 SG filters could NOT be installed](#)
- [IPv6 SG filters successfully installed](#)
- [Issue detected during QoS stack synchronization](#)
- [Issue detected enabling/disabling DSCP table usage \(port#\)](#)
- [Issue detected setting native DSCP table values](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# Information logs starting with J

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Information logs starting with J

This page lists all the logs starting with the letter J that are generated with a severity of Information.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [JOIN event sent unit mask value appl mask value](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Information logs starting with L

This page lists all the logs starting with the letter L that are generated with a severity of Information.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [LAC: Allocated trunk with id %d for aggregator %d](#)
- [LAC: Deallocated trunk with id %d for aggregator %d](#)
- [LAC: MLT %d error on far end.](#)
- [LAC: MLT %d error, partner aggregation bit not set.](#)
- [LAC: MLT %d error, partner expired bit set.](#)
- [LAC: MLT %d error, partner synchronization bit not set.](#)
- [LAC MLT error on far end. 0 - 0 - 0](#)
- [LAC: MLT error, partner aggregation bit not set](#)
- [LAC: MLT error, partner expired bit set.](#)
- [LAC: MLT error, partner synchronization bit not set.](#)
- [LAC No more trunk group available for LAC. 0 - 0 - 0](#)
- [LAC: Trunk %d is disabled](#)
- [LAC: Trunk %d is enabled](#)
- [LAC with admin key %d failed configuration verification. Bad ARP INSPECTION configuration.](#)
- [LAC with admin key %d failed configuration verification. Bad DHCP-SNOOPING configuration.](#)
- [LAC with admin key %d failed configuration verification. Bad IGMP configuration.](#)
- [LAC with admin key %d failed configuration verification. Bad MAC Security configuration.](#)
- [LAC with admin key %d failed configuration verification. Bad qos status.](#)
- [LAC with admin key %d failed configuration verification. Bad rate-limiting configuration.](#)
- [LAC with admin key %d failed configuration verification. Bad VLAN configuration.](#)
- [LAC with admin key %d failed configuration verification. Cannot set admin key to the value used by ADAC Uplink.](#)
- [LAC with admin key %d failed configuration verification. Error #: %d-%d](#)
- [LAC with admin key %d failed configuration verification. Ports have different IPSG configurations.](#)
- [LAC with admin key %d failed configuration verification. Ports have different MAC learning status.](#)
- [LAC with admin key %d failed configuration verification. Ports have different mac security learning status.](#)
- [LAC with admin key %d failed configuration verification. Ports have different mac security settings.](#)
- [LAC with admin key %d failed configuration verification. Ports have different mac security status.](#)
- [LAC with admin key %d failed configuration verification. Ports have different private-vlan port type.](#)
- [LAC with admin key %d failed configuration verification. Ports have different qos config.](#)
- [LAC with admin key %d failed configuration verification. Ports have different SLPP-guard configurations.](#)
- [LAC with admin key %d failed configuration verification. Ports have different SPBM configurations.](#)
- [LAC with admin key %d failed configuration verification. Ports have different VLACP admin enable state.](#)
- [LAC with admin key %d failed configuration verification. Ports have different VLACP ethertype.](#)
- [LAC with admin key %d failed configuration verification. Ports have different VLACP fast periodic time value.](#)
- [LAC with admin key %d failed configuration verification. Ports have different VLACP mac address.](#)
- [LAC with admin key %d failed configuration verification. Ports have different VLACP slow periodic time value.](#)
- [LAC with admin key %d failed configuration verification. Ports have different VLACP timeout scale.](#)
- [LAC with admin key %d failed configuration verification. Ports have different VLACP timeout type.](#)
- [LAC with admin key %d failed configuration verification. Ports have different vlan filter tag frames settings.](#)
- [LAC with admin key %d failed configuration verification. Ports have different vlan filter untag frames settings.](#)
- [LAC with admin key %d failed configuration verification. Ports have different vlan filter untag frames settings.](#)
- [LAC with admin key %d failed configuration verification. Ports have different vlan priorities.](#)
- [LAC with admin key %d failed configuration verification. Ports have different vlan PVIDs.](#)
- [LAC with admin key %d failed configuration verification. Ports have different vlan tagging.](#)
- [LAC with admin key %d failed configuration verification. Same key is used by ports belonging to different VLAN.](#)



- [Last MLT trunk was allocated by LAC. No more free trunk groups.](#)
- [Last MLT trunk was allocated by MLT. No more free trunk groups.](#)
- [Layer 2 filter distribution across stack failed](#)
- [LEAVE event sent unit mask value appl mask value](#)
- [Link Down Trap](#)
- [LinkStateTracking: First interface %d/d went up in link state group %d, enabling downstream ports](#)
- [LinkStateTracking: First interface mlt %d went up in link state group %d, enabling downstream interfaces](#)
- [LinkStateTracking: First interface %s went up in link state group %d, enabling downstream interfaces](#)
- [LinkStateTracking: Interface %d/d went down in link state group %d](#)
- [LinkStateTracking: Interface %d/d went up in link state group %d](#)
- [LinkStateTracking: Interface mlt %d went down in link state group %d](#)
- [LinkStateTracking: Interface mlt %d went up in link state group %d](#)
- [LinkStateTracking: Interface %s went down in link state group %d](#)
- [LinkStateTracking: Interface %s went up in link state group %d](#)
- [LinkStateTracking: Last interface %d/d went down in link state group %d, disabling downstream interfaces](#)
- [LinkStateTracking: Last interface mlt %d went down in link state group %d, disabling downstream interfaces](#)
- [LinkStateTracking: Last interface %s went down in link state group %d, disabling downstream interfaces](#)
- [Link Up Trap](#)
- [Loading configuration block # block\\_number](#)
- [Local authentication disabled on serial](#)
- [Local authentication disabled on telnet](#)
- [Local authentication enabled on serial](#)
- [Local authentication enabled on telnet](#)
- [Login timeout serial connection](#)
- [Lossless and Lossless-PFC modes are only supported in queue set 2](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Information logs starting with M

This page lists all the logs starting with the letter M that are generated with a severity of Information.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [MAC security table full](#)
- [Management IP: OOB port%s](#)
- [Management IP: OOB port%s](#)
- [Maximum number of dynamic routes reached](#)
- [Meter distribution across stack failed](#)
- [MHSA Auto-Configuration completed on port %s.](#)
- [MHSA Auto-Configuration failed on port %s - eap status is unauthorized.](#)
- [MHSA Auto-Configuration failed on port %s - port is RSPAN destination.](#)
- [MHSA Auto-Configuration failed on port %s - port mirroring is enabled.](#)
- [MLD: Filters could NOT be installed.](#)
- [MLD: Filters successfully installed.](#)
- [MLD: Maximum number of mld enabled interfaces reached](#)
- [MLD: The maximum number of available hardware MLD entries has been reached](#)
- [MLD: The maximum number of available hardware MLD entries has been reached](#)
- [MLT %d failed configuration verification. Bad ARP INSPECTION configuration.](#)
- [MLT %d failed configuration verification. Bad DHCP-SNOOPING configuration.](#)
- [MLT %d failed configuration verification. Bad IGMP configuration.](#)
- [MLT %d failed configuration verification. Bad IPSG CLASS configuration.](#)
- [MLT %d failed configuration verification. Bad MAC learning configuration.](#)
- [MLT %d failed configuration verification. Bad rate-limiting configuration.](#)
- [MLT %d failed configuration verification. Bad SLPP-guard configuration.](#)
- [MLT %d failed configuration verification. Bad SPBM configuration.](#)
- [MLT %d failed configuration verification. Bad VLACP configuration](#)
- [MLT %d failed configuration verification. Bad VLAN configuration.](#)
- [MLT %d failed configuration verification. Ports are in different static VLANs.](#)
- [MLT %d failed configuration verification. Ports are in different VLANs.](#)
- [MLT %d failed configuration verification. Ports have different private-vlan port type.](#)
- [MLT %d failed configuration verification. Ports have different static vlan PVIDs.](#)
- [MLT %d failed configuration verification. Ports have different static vlan tagging.](#)
- [MLT %d failed configuration verification. Ports have different VLACP admin enable state.](#)
- [MLT %d failed configuration verification. Ports have different VLACP ethertype.](#)
- [MLT %d failed configuration verification. Ports have different VLACP fast periodic time value.](#)
- [MLT %d failed configuration verification. Ports have different VLACP mac address.](#)
- [MLT %d failed configuration verification. Ports have different VLACP slow periodic time value.](#)
- [MLT %d failed configuration verification. Ports have different VLACP timeout scale.](#)
- [MLT %d failed configuration verification. Ports have different VLACP timeout type.](#)
- [MLT %d failed configuration verification. Ports have different vlan priorities.](#)
- [MLT %d failed configuration verification. Ports have different vlan PVIDs.](#)
- [MLT %d failed configuration verification. Ports have different vlan tag frames filter settings.](#)
- [MLT %d failed configuration verification. Ports have different vlan tagging.](#)
- [MLT %d failed configuration verification. Ports have different vlan unreg frames filter settings.](#)
- [MLT %d failed configuration verification. Ports have different vlan untag frames filter settings.](#)
- [MLT ID# failed configuration verification. Error # error num](#)
- [MLT NV File error](#)
- [MODULE\\_INACTIVE event sent unit mask value appl mask value](#)

[More than value units discovered](#)

- [Multiple base units detected](#)
- [Multiple Waverunner units detected when base is a Flagship](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Information logs starting with N

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Information logs starting with N

This page lists all the logs starting with the letter N that are generated with a severity of Information.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Already authenticated by other method.](#)
- [NEAP Client blocked - MAC %02x:%02x:%02x:%02x:%02x:%02x. Vlan:lsid bindings exceeded the maximum threshold of 94](#)
- [NEAP Phone %02x:%02x:%02x:%02x:%02x:%02x migrated from port %d/%d.](#)
- [Network access settings for FCoE Redirect must be modified locally](#)
- [Nickname range 3.33.xx is reserved: coresponding mac used by IPv6 multicast](#)
- [Non-EAP Client blocked \(Block Subsequent MAC Authentication\): Different VID than expected](#)
- [Non-EAP Client blocked \(Block Subsequent MAC Authentication\): EAP Use Rav Not enabled](#)
- [Non-unique element label detected \(prohibited\)](#)
- [No Response from RADIUS Server](#)
- [Notice: DAC Cable on %s is below HW rev "H" and may cause link issues with a small number of PHYs](#)
- [Number of VLANs does not match BU number of VLANs. VLAN config defaulted](#)
- [Number of VLANs does not match BU number of VLANs. VLAN config defaulted](#)
- [NUOC - Disabled](#)
- [NUOC - Enabled](#)
- [NUOC - Execution of the cli template failed](#)
- [NUOC - Execution of the cli template succeded](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Information logs starting with O

This page lists all the logs starting with the letter O that are generated with a severity of Information.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [Ospf Area Mismatch RxArea ra.rb.rc.rd IntfArea ia.ib.ic.id](#)
- [Ospf Auth Failed IpAddr ia.ib.ic.id](#)
- [Ospf Auth Type Mismatch in Hello](#)
- [Ospf Auto Virt Link Failed area a1.a2.a3.a4 rtid r1.r2.r3.r4](#)
- [Ospf Bad Version](#)
- [OSPF Callback function of timer is NULL](#)
- [Ospf Cost Exceeds Limit Skip route Lsid l1.l2.l3.l4 Adv-rtr a1.a2.a3.a4](#)
- [OspfDbg Done Filter Init](#)
- [OspfDbg Done Global Init](#)
- [OspfDbg Done NV-Restore](#)
- [OspfDbg Done ReDist Init](#)
- [OspfDbg Init Instance vrfId=%d nodeP=0x%0x](#)
- [OspfDbg PostInit Done vrfId=%d nodeP=0x%0x](#)
- [OspfDbg PostInit EnableOspf vrfId=%d nodeP=0x%0x](#)
- [OspfDbg Started ospfTxHelloTimerTask](#)
- [Ospf Dead Int Mismatch in Hello](#)
- [Ospf Enable Failed as Resource Unavailable](#)
- [Ospf Hello Int Mismatch in Hello](#)
- [Ospf Hello: RId Same as Neighbor: rtid <r1.r2.r3.r4>, IpAddr <i1.i2.i3.i4>](#)
- [Ospf HW Mode Change:](#)
- [Ospf Invalid packet received: Pkt type <ospfPacketType>](#)
- [Ospf License Is Missing, Disable OSPF](#)
- [Ospf Nbr State Change: rtid <ra.rb.rc.rd> ipa <ia.ib.ic.id> state <neighborState>](#)
- [Ospf Netmask Mismatch in Hello IpAddr ia.ib.ic.id](#)
- [Ospf Option Mismatch in Hello IpAddr ia.ib.ic.id RxOption optionVal IntfOption optionVal](#)
- [OSPF Timer Link Error](#)
- [OSPF Timer List is corrupted](#)
- [OSPF Timer Unlink Error](#)
- [Ospf Virt Nbr State Change: rtid <r1.r2.r3.r4>, virtAreaId <v1.v2.v3.v4>, state <neighborState>](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Information logs starting with P

This page lists all the logs starting with the letter P that are generated with a severity of Information.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [Pim E-BSR change](#)
- [Pim Invalid packet received](#)
- [Pim License Is Missing Disable PIM](#)
- [Pim Mode Change](#)
- [Pim Nbr State Change Up](#)
- [PIM Neighbor status change Down](#)
- [PIM Neighbor status change Up](#)
- [Pim RP type state](#)
- [Pim Unicast route change](#)
- [Pim Virt Nbr State Change Down](#)
- [Pim Virt Nbr State Change Up](#)
- [PM in port mirroring the old data were modified - feature Allow Traffic in mirror port was added.](#)
- [PM in port mirroring the old data were modified - feature Many to Many was added.](#)
- [PM in port mirroring the old data were modified - feature Many to One was added.](#)
- [PM in port mirroring the old data were modified - feature Many to One with 128bits was added.](#)
- [PM: in port mirroring the old data were modified - feature RSPAN was added](#)
- [PM in port mirroring the old data were modified - mode type was out of range.](#)
- [PM in port mirroring the old data were modified - monitored portA was out of range.](#)
- [PM in port mirroring the old data were modified - monitored portB was out of range.](#)
- [PM in port mirroring the old data were modified - NVRAM file structure was changed.](#)
- [PM in port mirroring the old data were modified - probe port was out of range.](#)
- [PM some port mirroring messages were stored to be displayd with delay.](#)
- [PM unable to create mirror for instance instance number due to lack of available filter resources](#)
- [PoE Main Power Usage Off](#)
- [PoE Main Power Usage On](#)
- [PoE Module Reset](#)
- [PoE Port Detection Status port# Status powerStatus](#)
- [PoE The PoE power limit for port unit port has been changed to x Watts based on IP phone discovery settings](#)
- [PoE The PoE power limit for port unit port has been restored to previous value x Watts](#)
- [PoE The PoE priority for port unit port has been changed to x based on IP phone discovery settings](#)
- [PoE The PoE priority for port unit port has been restored to previous value x](#)
- [Policy content incompatible with precedence allocation mode](#)
- [Policy distribution across stack failed](#)
- [Port %d blocked by VLACP until end-partner connection reestablished](#)
- [Port %d reenabled by VLACP](#)
- [Port %s of LAC with key %d is disabled because it has wrong configuration](#)
- [Port unit# port# blocked by VLACP until end-partner connection reestablished](#)
- [Port unit# port# reenabled by VLACP](#)
- [Primary Configuration files are corrupted. Restored to default](#)
- [Primary Configuration Version is updated](#)
- [802.1p user priority value modification prohibited](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Information logs starting with Q

This page lists all the logs starting with the letter Q that are generated with a severity of Information.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [QoS inter-module communication issue detected](#)
- [Queue data distribution across stack failed](#)
- [Queue shaping distribution across stack failed](#)
- [QuickInstall console configuration error.](#)
- [QuickInstall:console configuration success.](#)
- [QuickInstall: Error! Unable to locate agent software file](#)
- [QuickInstall: Error! Unable to locate ASCII configuration file](#)
- [QuickInstall: Error! Unable to locate diagnostics software file.](#)
- [QuickInstall: Processing of USB config file has commenced.](#)
- [QuickInstall: Processing of USB config file is complete](#)
- [QuickInstall USB config file not found.](#)
- [QuickInstall USB file config error at line line#](#)
- [QuickInstall USB file config error - file exceed 4096 bytes](#)
- [QuickInstall USB file config error - file exceed 200 lines.](#)
- [QuickInstall:USB file config success.](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)





# Information logs starting with R

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Information logs starting with R

This page lists all the logs starting with the letter R that are generated with a severity of Information.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [RADIUS authentication on stack serial disabled](#)
- [RADIUS authentication on stack serial enabled](#)
- [RADIUS authentication on stack telnet disabled](#)
- [RADIUS authentication on stack telnet enabled](#)
- [RADIUS authentication on switch serial disabled](#)
- [RADIUS authentication on switch serial enabled](#)
- [RADIUS authentication on switch telnet disabled](#)
- [RADIUS authentication on switch telnet enabled](#)
- [RADIUS: ERROR - Couldn't create RADIUS Acct semaphore. errno %d](#)
- [RADIUS: ERROR - Couldn't create RADIUS semaphore. errno %d](#)
- [RADIUS: ERROR - Couldn't start RADIUS AcctClient\(\) task. errno %d](#)
- [RADIUS: ERROR - Couldn't start RADIUS client\(\) task. errno %d](#)
- [RADIUS: ERROR - Couldn't start radius recv\(\) task. errno %d](#)
- [RADIUS: ERROR - Couldn't start RADIUS ServerCheck\(\) task. errno %d](#)
- [Radius: Server with index %d is down](#)
- [Radius: Server with index %d is up](#)
- [REMOVE\\_DATA event sent unit mask value appl mask value](#)
- [Replaced "Wrong OoS Agent buffer setting. expected %u. actual %u. unit cannot join stack" with "Wrong OoS Agent buffer setting. expected %s. actual %s. unit cannot join stack"](#)
- [Resources exhausted \(maximum dynamic class entries reached\)](#)
- [Restore Backup Configuration to Manufacture Default](#)
- [Restore Primary Configuration to Manufacture Default](#)
- [Role combination distribution across stack failed](#)
- [Role combination length outside of acceptable limits](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Information logs starting with S

This page lists all the logs starting with the letter S that are generated with a severity of Information.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [%s card inserted \(in unit %s\)](#)
- [%s card removed \(from unit %s\)](#)
- [Script was successfully executed](#)
- [Session closed \(inactivity logout\) IP address](#)
- [Session closed \(lost connection\) IP address](#)
- [Session closed \(user logout\) IP address](#)
- [Session closed \(user logout\) serial connection](#)
- [Session opened from IP address](#)
- [Session opened from serial connection](#)
- [Session opened \(local auth\) from IP address:](#)
- [Session opened \(local auth\) from serial connection](#)
- [Session opened\(radius auth\) from IP add](#)
- [Session opened\(radius auth\) from serial conn](#)
- [Set port to default](#)
- [SFP internal supply voltage is at high alarm level on s](#)
- [SFP internal supply voltage is at high warning level on %s](#)
- [SFP internal supply voltage is at low alarm level on %s](#)
- [SFP internal supply voltage is at low warning level on %s](#)
- [SFP internal supply voltage is no longer at the high alarm level](#)
- [SFP internal supply voltage is no longer at the high warning level](#)
- [SFP internal supply voltage is no longer at the low alarm level](#)
- [SFP internal supply voltage is no longer at the low warning level](#)
- [SFP internal temperature is at high alarm level on %s](#)
- [SFP internal temperature is at high warning level on %s](#)
- [SFP internal temperature is at low alarm level on %s](#)
- [SFP internal temperature is at low warning level on %s](#)
- [SFP internal temperature is no longer at the high alarm level](#)
- [SFP internal temperature is no longer at the high warning level](#)
- [SFP internal temperature is no longer at the low alarm level](#)
- [SFP internal temperature is no longer at the low warning level](#)
- [SFP Received power is at high alarm level on %s](#)
- [SFP Received power is at high warning level on %s](#)
- [SFP Received power is at low alarm level on %s](#)
- [SFP Received power is at low warning level on %s](#)
- [SFP Received power is no longer at the high alarm level](#)
- [SFP Received power is no longer at the high warning level](#)
- [SFP Received power is no longer at the low alarm level](#)
- [SFP Received power is no longer at the low warning level](#)
- [SFP TX Bias current is at high alarm level on %s](#)
- [SFP TX Bias current is at high warning level on %s](#)
- [SFP TX Bias current is at low alarm level on %s](#)
- [SFP TX Bias current is at low warning level on %s](#)
- [SFP TX Bias is no longer at the high alarm level](#)
- [SFP TX Bias is no longer at the high warning level](#)
- [SFP TX Bias is no longer at the low alarm level](#)

- [SFP TX Bias is no longer at the low warning level](#)
- [SFP TX output power is at high alarm level on %s](#)
- [SFP TX output power is at high warning level on %s](#)
- [SFP TX output power is at low alarm level on %s](#)
- [SFP TX output power is at low warning level on %s](#)
- [SFP TX output power is no longer at the high alarm level](#)
- [SFP TX output power is no longer at the high warning level](#)
- [SFP TX output power is no longer at the low alarm level](#)
- [SFP TX output power is no longer at the low warning level](#)
- [Simultaneous operations involving access asgn ifcs prohibited](#)
- [Simultaneous operations involving policies and blocks prohibited](#)
- [Simultaneous operations involving policies and ifcs prohibited](#)
- [Simultaneous operations involving policy blocks ifcs prohibited](#)
- [SLAMon Agent: CLI support not available](#)
- [SLAMon Agent: CLI timeout value out-of-range](#)
- [SLAMon Agent: disabled](#)
- [SLAMon Agent: enabled](#)
- [SLAMon Agent: inconsistent IP address data specified](#)
- [SLAMon Agent: inconsistent UDP port data specified](#)
- [SLAMon Agent: info: %d %d %d](#)
- [SLAMon Agent: invalid agent-to-agent port \(must be even value\)](#)
- [SLAMon Agent: operation is restricted \(CLI-only\)](#)
- [SLPP-guard: hold-down timer has expired on port with SLPP-guard enabled. Port %s has been re-enabled](#)
- [SLPP-guard: SLPP-guard has not been enabled on port %s as no filters or filter precedences are available to setup an Ethertype filter](#)
- [SLPP-guard: SLPP packet received on port with SLPP-guard enabled. Port %s has been disabled](#)
- [SLPP Warning - PDU was received on Vlan VlanId Unit UnitNo Port PortNo .](#)
- [SMLT IMC invalid cmd 1- StkCmd](#)
- [SMLT IMC tx error](#)
- [SMLT input parameter error mlt port vlan](#)
- [SMLT Stack db ex event num -0 -0\\*22221111](#)
- [SMLT stackEventNotify Invalid Msg Cmd - 0 - 0](#)
- [SMLT Stack inactive event 0-0- modMask](#)
- [SMLT Stack joined event num - 0 - 0\\*33331111](#)
- [SMLT Stack leaved event 0 - 0 - modMask](#)
- [SMLT STP enabled on IST trunk trkNo stp group grp](#)
- [SMLT Warning - LAC SMLT with more than 8 links - key - count](#)
- [SMLT Warning - smltEnable Software License Error- 0 - 0](#)
- [SMLT Warning - SMLT mismatched Lac Sys ID error shutdown all SMLT lac po](#)
- [SNMP-access is disabled](#)
- [SNMP-access is enabled](#)
- [SNTP: First synchronization successful.](#)
- [SPBM adjacency with neighbor](#)
- [SPBM detect adj](#)
- [SPBM: ERROR adding Transparent UNI for i-sid %d. port %d - no resources](#)
- [SPBM ISIS](#)
- [SPBM ISIS detect duplicate nick-name](#)
- [SPBM ISIS node](#)
- [SPBM: Node already present on unit %d - will not add again](#)
- [SSHC ASCII CFG download SFTP failure](#)
- [SSHC: ASCII CFG download SFTP failure](#)
- [SSHC ASCII CFG upload SFTP failure](#)
- [SSHC: ASCII CFG upload SFTP failure](#)
- [SSHC CFG download SFTP failure](#)
- [SSHC: CFG download SFTP failure](#)
- [SSHC CFG upload SFTP failure](#)
- [SSHC: CFG upload SFTP failure](#)
- [SSHC DSA Authentication failure](#)
- [SSHC DSA key generation failure](#)
- [SSHC DSA key save failure](#)
- [SSHC DSA key upload TFTP failure](#)
- [SSHC DSA key upload USB failure](#)
- [SSH CLIENT Key couldnt be saved for host ip address](#)
- [SSH CLIENT SSH Connection to IP ip address was closed because parent console session console session ID was closed](#)
- [SSH CLIENT SSH Connection to %s was disconnected](#)

- [SSH CLIENT: SSH Connection to %s was disconnected by host. Connection time: %s](#)
- [SSH CLIENT: SSH Connection to %s was disconnected by user. Connection time: %s.](#)
- [SSH CLIENT Successful SSH Connection to %s using %s authentication](#)
- [SSH: Client tried to authenticate with invalid certificate from address %s](#)
- [SSH: Client tried to authenticate without principal name in certificate from address %s](#)
- [SSH: Client tried to authenticate with revoked certificate from address %s](#)
- [SSHC Password Authentication failure](#)
- [SSHC: Password Authentication failure](#)
- [SSHC RSA Authentication failure](#)
- [SSHC: RSA Authentication failure](#)
- [SSHC RSA key generation failure](#)
- [SSHC RSA key save failure](#)
- [SSHC RSA key upload TFTP failure](#)
- [SSHC RSA key upload USB failure](#)
- [SSHC server connection failure](#)
- [SSH disabled](#)
- [SSH DSA key deleted](#)
- [SSH DSA KEY generation completed](#)
- [SSH enabled in non-secure mode](#)
- [SSH enabled in secure mode](#)
- [SSH Maximum number of ssh sessions has been reached](#)
- [SSH: OCSP query verification passed for server certificate from address %s](#)
- [SSH RSA KEY generation completed](#)
- [SSH RSA key overwritten](#)
- [SSH: Server tried to authenticate with revoked certificate from address %s](#)
- [SSH session closed by ip address remote host. Connection time h hours m minutes](#)
- [SSH session login using port](#)
- [SSH: Succesfull response to OCSP query for client certificate from address %s](#)
- [SSH System is generating DSA KEY wait ...](#)
- [SSH TFTP DSA key download complete](#)
- [SSH TFTP RSA key download complete](#)
- [SSH USB DSA key download complete](#)
- [SSH USB RSA key download complete](#)
- [SSL certificate creation completed](#)
- [SSL certificate creation failed](#)
- [SSL certificate deleted](#)
- [SSL disabled](#)
- [SSL enabled](#)
- [SSL server reset](#)
- [Stack cable "Down 1" is misconfigured](#)
- [Stack cable "Down 2" is misconfigured](#)
- [Stack cable "Up 1" is misconfigured](#)
- [Stack cable "Up 2" is misconfigured](#)
- [Stack IP changed](#)
- [Stack must have a configured base unit!](#)
- [Stack operation mode modified to Pure and unit reset](#)
- [Stack synchronization failed stack formation delayed](#)
- [Static role association not found for ifc, default was used \(%d/%d\)](#)
- [Successful connection from IP address:](#)
- [Successfully loaded configuration files from block %d](#)
- [Successfully remapped config areas on unit %d](#)
- [Successful SSH connection to ip address](#)
- [Switch IP changed](#)
- [System filter distribution across stack failed](#)
- [System memory on unit %d is under %d MBytes.](#)
- [System: Rear-Port Mode has been set to disable \(reboot required to take effect\)](#)
- [System: Rear-Port Mode has been set to enable \(reboot required to take effect\).](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)



[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Information logs starting with T

This page lists all the logs starting with the letter T that are generated with a severity of Information.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [TACACS+ accounting disabled](#)
- [TACACS+ accounting enabled](#)
- [TACACS+ authenticated serial connection closed](#)
- [TACACS+ authenticated telnet session closed](#)
- [TACACS+ authenticated telnet session max retries exceeded](#)
- [TACACS+ authentication on switch serial port disabled](#)
- [TACACS+ authentication on switch serial port enabled](#)
- [TACACS+ authentication on switch telnet disabled](#)
- [TACACS+ authentication on switch telnet enabled](#)
- [TACACS+ authentication on switch telnet enabled](#)
- [TACACS+ authorization disabled](#)
- [TACACS+ authorization enabled](#)
- [TACACS+ successful authentication](#)
- [TACACS+ unsuccessful authentication](#)
- [TACACS authenticated SSH session closed](#)
- [TACACS authentication on stack serial disabled](#)
- [TACACS authentication on stack serial enabled](#)
- [TACACS authentication on stack telnet disabled](#)
- [TACACS authentication on stack telnet enabled](#)
- [Task task\\_name is suspended](#)
- [The BU switch is enabled. Cannot join existing stack](#)
- [The IP phone PoE limit has been changed to x Watts due to the stack modules configuration](#)
- [The number of stack units is number instead of expected number](#)
- [This unit has wrong F W version expected version actual version](#)
- [This unit has wrong S W version expected version actual version](#)
- [Toggle the Agent Primary Image](#)
- [Token bucket data distribution across stack failed](#)
- [Traffic Prof filter set delete operation failed](#)
- [Traffic Prof filter set install operation failed](#)
- [Traffic Prof filter set update operation failed](#)
- [Trap bsAdacPortConfigNotification](#)
- [Trap bsAdacPortOperDisabledNotification](#)
- [Trap: bsDhcpSnoopingExtSaveSFTPRestoreFailure](#)
- [Trap: bsDhcpSnoopingExtSaveSFTPRestoreSuccess](#)
- [Trap: bsDhcpSnoopingExtSaveSFTPSyncFailure](#)
- [Trap: bsDhcpSnoopingExtSaveSFTPSyncSuccess](#)
- [Trap: bsIpv6DHCPGNotif%\\$ MAC:%02x:%02x:%02x:%02x:%02x Addr:%s Port:%hhu/%hhu](#)
- [Trap: bsIpv6NDNotificationSBTTableFull - MAC:%02x:%02x:%02x:%02x:%02x Addr:%s Port:%hhu/%hhu](#)
- [Trap: bsIpv6NDNotificationUntrustedPort - MAC:%02x:%02x:%02x:%02x:%02x Addr:%s Port:%hhu/%hhu](#)
- [Trap: bsIpv6RAGNotif%\\$ MAC:%02x:%02x:%02x:%02x:%02x Addr:%s Port:%hhu/%hhu](#)
- [Trap: bsLstGroupOperStateChanged](#)
- [Trap: bsLstInterfaceStatusChanged](#)
- [Trap: bsnAaaAlreadyConnected](#)
- [Trap: bsnAaaIncorrectLogOnThresholdExceeded](#)
- [Trap: bsnAaaMaxNoOfSessionsExceeded](#)

- [Trap: bsnAaaUserAccountNotUsed](#)
- [Trap: bsnAuditShutDownTrap](#)
- [Trap: bsnAuditStorageAlarm](#)
- [Trap: bsnConfigurationSavedToNvram](#)
- [Trap: bsnEapAccessViolation](#)
- [Trap: bsnEapUbpFailure](#)
- [Trap: bsnLacPortDisabledDueToLossOfVLACPDU](#)
- [Trap: bsnLacPortEnabledDueToReceiptOfVLACPDU](#)
- [Trap: bsnROPasswordExpired: Read-only password expired](#)
- [Trap: bsnRWPasswordExpired: Read-write password expired](#)
- [Trap: bsnSFPIinsertion on port](#)
- [Trap: bsnSFPRemoval on port](#)
- [Trap: bsnStackConfigurationError](#)
- [Trap: bsnStackManagerReconfiguration](#)
- [Trap: bsnSystemUp365Days sent from unit %d](#)
- [Trap: bsnTrialLicenseExpiration Trial license license# has expired. Disable licensed features to avoid network interruption](#)
- [Trap: bsnTrialLicenseExpiration Trial license license# will expire in # days day\(s\)](#)
- [Trap: bsnUSBInsertion on unit](#)
- [Trap: bsnUSBRemoval on unit](#)
- [Trap: bspePethPsePortCurrentStatusNotification](#)
- [Trap: bsUnicastStormControlAboveHighWatermark](#)
- [Trap: bsUnicastStormControlBelowLowWatermark](#)
- [Trap: bsveVrrpTrapStateTransition](#)
- [Trap: DAPP - DoS Attack Detected](#)
- [Trap: Device has entered Forced Stack Mode \( MAC Address \)](#)
- [Trap: entConfigChange](#)
- [Trap: fallingAlarm](#)
- [Trap: lldpRemTableChange Ageouts = count](#)
- [Trap: lldpRemTableChange Deletes = count](#)
- [Trap: lldpRemTableChange Drops = count](#)
- [Trap: lldpRemTableChange Inserts = count](#)
- [Trap: lldpXMedTopologyChangeDetected Subtype = subtype Class = class](#)
- [Trap: MSTP General Event:](#)
- [Trap: newRoot](#)
- [Trap: ntnQosPolicyEvolLocalUbpSessionFailure](#)
- [Trap: ospfIfAuthFailure](#)
- [Trap: ospfIfConfigError](#)
- [Trap: ospfIfStateChange](#)
- [Trap: ospfNbrStateChange](#)
- [Trap: ospfVirtIfAuthFailure](#)
- [Trap: ospfVirtIfConfigError](#)
- [Trap: ospfVirtIfStateChange](#)
- [Trap: ospfVirtNbrStateChange](#)
- [Trap: pethMainPowerUsageOffNotification](#)
- [Trap: pethMainPowerUsageOnNotification](#)
- [Trap: pethPsePortOnOffNotification](#)
- [Trap: rclsisPlsbBvidMismatchTrap](#)
- [Trap: rclsisPlsbLsdbUpdateTrap](#)
- [Trap: rclsisPlsbSmltPeerBmacMismatchTrap](#)
- [Trap: rclsisPlsbSmltSplitBebMismatchTrap](#)
- [Trap: rclsisPlsbSmltVirtBmacMismatchTrap](#)
- [Trap: risingAlarm](#)
- [Trap: RSTP Error Event](#)
- [Trap: RSTP General Event](#)
- [Trap: RSTP General Event:](#)
- [Trap: RSTP New Root](#)
- [Trap: RSTP Protocol Migration](#)
- [Trap: RSTP Topology Change](#)
- [Trap: Run %s %s](#)
- [Trap: s5CtrFanDirectionError](#)
- [Trap: s5CtrHighTemperatureError](#)
- [Trap: s5CtrHotSwap](#)
- [Trap: s5EtrMacAddressTablesThresholdReached](#)
- [Trap: s5EtrSbsMacAccessViolation](#)
- [Trap: s5EtrSbsMacAccessViolation](#)

- [Trap s5EtrSbsMacRemoved](#)
- [Trap s5EtrSbsMacTableCleared](#)
- [Trap s5EtrSbsMacTableClearedForPort](#)
- [Trap: SFP Transceiver's Bias is no longer at warning/alarm level](#)
- [Trap:\\$#160:SFP Transceiver's Bias is no longer at warning/alarm level](#)
- [Trap: SFP Transceiver's Temperature is no longer at warning/alarm level](#)
- [Trap:\\$#160:SFP Transceiver's Temperature is no longer at warning/alarm level](#)
- [Trap: SFP Transceiver's Tx Power is no longer at warning/alarm level](#)
- [Trap:\\$#160:SFP Transceiver's Tx Power is no longer at warning/alarm level](#)
- [Trap SLPP Port Down Event](#)
- [Trap Smlt Ist Link Down](#)
- [Trap Smlt Ist Link Up](#)
- [Trap Smlt Link Down](#)
- [Trap Smlt Link Up](#)
- [Trap topologyChange](#)
- [Trap ubpEAPSessionEnd](#)
- [Trap ubpEAPSessionStart](#)
- [Trap vrrpTrapNewMaster](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Information logs starting with U

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Information logs starting with U

This page lists all the logs starting with the letter U that are generated with a severity of Information.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [Unable to apply pre-defined UBP filter set to new user \(port %d/%d\)](#)
- [Unable to inform SPB of ifc assignment change \(%d/%d\)](#)
- [Unicast block unit port unit\\_port level level watermark watermark](#)
- [Unicast unblock unit port unit\\_port level level watermark watermark](#)
- [Unknown unsupported attribute specified \( attribute \)](#)
- [Upstream stack direction is down cable removed or neighbor powered off](#)
- [Upstream stack direction is mis-configured](#)
- [USB device inserted](#)
- [USB device removed](#)
- [USC Install SET fail unit port unit\\_port status = status](#)
- [USC Install TEST fail unit port unit\\_port status = status](#)
- [USC UnInst SET failed for port port status = status](#)
- [Used stack size of task %s is \(%d%%\).](#)
- [User allowed \(radius authentication pass\) to log in from Web from Src IP](#)
- [User disallowed \(radius authentication fail\) to log in from Web from Src IP](#)
- [User policy distribution across stack failed](#)
- [User policy filter set delete operation failed](#)
- [User policy filter set install operation failed](#)
- [User policy filter set update operation failed](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Information logs starting with V

This page lists all the logs starting with the letter V that are generated with a severity of Information.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [VLAN configuration does not match BU VLAN configuration. VLAN config defaulted](#)
- [VLAN configuration does not match BU VLAN configuration. VLAN config defaulted](#)
- [VLAN IMC callback failed](#)
- [VLAN IMC was not sent](#)
- [Vlan is already a RSPAN vlan](#)
- [VLAN NVRAM read error](#)
- [VLAN NVRAM read error](#)
- [VLAN queue messages discarded](#)
- [VLAN queue messages discarded](#)
- [VLAN set error from IMC](#)
- [VLAN set error from RPC](#)
- [Voice VLAN ID and Data VLAN ID cannot have the same value](#)
- [VRRP Feature globally disabled due to missing license](#)
- [VRRP: vrrpAdvQueue is FULL. RX advertisement dropped in vlan %d!](#)
- [VRRP: vrrpQueue is FULL. Message dropped.](#)
- [VRRP VR VR Id VLAN Id Received mismatching advertisement interval \( advertisement interval\)](#)
- [VRRP VR VR Id VLAN Id Received mismatching advertisement type \( advertisement type \)](#)
- [VRRP VR VR Id VLAN Id Received mismatching fast advertisement interval \( fast advertisement interval\)](#)
- [VRRP VR VR Id VLAN Id Received mismatching virtual IP address \( received virtual ip address \)](#)
- [VRRP VR VR Id VLAN Id Received unknown VRRP packet type \( vrrp packet type \)](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)



# Information logs starting with W

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Information logs starting with W

This page lists all the logs starting with the letter W that are generated with a severity of Information.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [Warning failed to connect to %s card \(in unit %s\)](#)
- [Warning: non-supported qsfps inserted on %s. Port will be disabled.](#)
- [Warning:non-supported transceiver on %s has been detected.](#)
- [Warning %s card unsafely removed \(from unit %s\)](#)
- [WEB-access is disabled](#)
- [WEB-access is enabled](#)
- [Web authentication fail from IP address](#)
- [Web authentication from IP address](#)
- [Web connection from IP address](#)
- [Web disconnect from IP address](#)
- [Web server attempting to open socket for port HTTP port](#)
- [Web server starts service on port HTTP port](#)
- [Web timeout from IP address](#)
- [Wrong OOS Agent buffer setting expected value actual value unit cannot join stack.](#)
- [Wrong VLANs nvq RecDescr actRecs](#)
- [Wrong VLANs nvq RecDescr actRecs](#)
- [Wrong VMACs nvq RecDescr actRecs](#)
- [Wrong VMACs nvq RecDescr actRecs](#)
- [Wrong vrec field](#)
- [Wrong vrec field](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [G](#) | [H](#) | [I](#) | [J](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Serious logs starting with A

This page lists all the logs starting with the letter A that are generated with a severity of Serious.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [AAUR - Info: Receive request for agent image. Unable to start transfer](#)
- [AAUR - Warning Agent image check sum ERROR](#)
- [AAUR - Warning Slave agent image check sum ERROR](#)
- [Access assignment modification support limited](#)
- [Access assignment name contains unacceptable characters](#)
- [Access assignment name length outside of acceptable limits](#)
- [Access assignment name not acceptable - reserved](#)
- [Access assignment template still in use \(siblings active\)](#)
- [Access element block label contains unacceptable characters](#)
- [Access element block label length outside of acceptable limits](#)
- [Access element cluster count \( cluster count \) exceeds limit \( cluster limit \)](#)
- [Access element cluster is referenced \(addition prohibited\)](#)
- [Access element cluster is referenced \(deletion prohibited\)](#)
- [Access element name contains unacceptable characters](#)
- [Access element name length outside of acceptable limits](#)
- [Access element name not acceptable - reserved](#)
- [ADAC: ADAC of Nortel IP Phones not functional](#)
- [ADAC: Error registering CDT handlers](#)
- [application-name failed DB-exchange stack formation delayed](#)
- [App-Telemetry: Default configuration file loaded](#)
- [App-Telemetry: Policy file is empty](#)
- [Assertion Failure in bcm\\_l3\\_hit\\_check- l3sw ip=%#x.l3hw ip=%#x](#)
- [Attempt to create an element that already exists \(prohibited\)](#)
- [Attempt to delete modify non-existing element \(prohibited\)](#)
- [Attempt to manipulate system-owned interface \(prohibited\)](#)
- [Attempt to manipulate user policy data rejected \(disabled\)](#)
- [Audit data initialized \(bad checksum\)](#)
- [Audit data initialized \(bad magic number\)](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)



# Serious logs starting with B

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Serious logs starting with B

This page lists all the logs starting with the letter B that are generated with a severity of Serious.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [Base action entry referenced by clfr block \(deletion prohibited\)](#)
- [Base action entry referenced by meter \(deletion prohibited\)](#)
- [Base action entry referenced by policy \(deletion prohibited\)](#)
- [Base action extension identifier invalid](#)
- [Base action modification prohibited due to action usage](#)
- [Base unit has loopback port mode %s and the current unit %s. Unit reconfigured and rebooted](#)
- [BaySec Not enough resource on port port# . Check QOS cfg](#)
- [Bay Secure error line line# # of octets read from NVRAM](#)
- [Bay Secure MAC DA filtering not enough resources](#)
- [Bay Secure Policy Error error type line line# 0](#)
- [Buffer configuration inconsistency detected \(local buffer conf stack buffer conf \)](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Serious logs starting with C

This page lists all the logs starting with the letter C that are generated with a severity of Serious.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [call to cdt api function failed due to lock timeout \(code=%d, total failures=%d, task=%s\)](#)
- [CFGSO - Warning Invalid Msg Id](#)
- [Classifier block component set ID out-of-range \( clfr comp set ID \)](#)
- [Classifier block number out-of-range \( block# \)](#)
- [Classifier block precedence value not supported](#)
- [Classifier component set ID out-of-range \( clfr comp set ID \)](#)
- [Classifier conflict \(duplicate clfr data in block\) detected](#)
- [Classifier content incompatible with target interface\(s\)](#)
- [Classifier set block reference out-of-range \( clfr setblock# \)](#)
- [Classifier type unknown](#)
- [Clfr content \(system\) incompatible with target interface\(s\)](#)
- [Composite filter set addition failure data consistency issue](#)
- [Composite filter set addition failure data invalid](#)
- [Composite filter set addition failure resources unavailable](#)
- [Composite filter set creation failure data invalid](#)
- [Composite filter set creation failure MAC data not allowed](#)
- [Composite filter set deletion failure base set target invalid](#)
- [Composite filter set deletion failure data invalid](#)
- [Composite filter set destruction failure data invalid](#)
- [Composite filter set membership limits exceeded](#)
- [Conflicting action sources detected](#)
- [Conflicting master block member information detected](#)
- [Conflicting policy role policy interface index data detected](#)
- [CoS shaping not supported with specified interface](#)
- [Count action entry referenced by meter \(deletion prohibited\)](#)
- [Count action entry referenced by policy \(deletion prohibited\)](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)



# Serious logs starting with D

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Serious logs starting with D

This page lists all the logs starting with the letter D that are generated with a severity of Serious.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [DAPP resources not available \(unit unit# \)](#)
- [DAPP with statistics tracking in use \(QoS disable prohibited\)](#)
- [DAUR - Warning Diag image check sum ERROR](#)
- [DAUR - Warning Slave diag image check sum ERROR](#)
- [Default ifc assignment failure port# port\(s\) ifc QoS-disabled](#)
- [Destination MAC address and mask values out-of-sync](#)
- [Different classifier component masks keys in block detected](#)
- [Different enhanced secure mode settings than BU. Unit reconfigured and rebooted.](#)
- [Different spanning-tree mode configured than BU. Unit re-configured and rebooted](#)
- [Different spanning-tree mode configured than BU. Unit reconfigured and rebooted.](#)
- [Download – Error: Failed to get FLASH sem](#)
- [Download - %s image %sprogrammed successfully](#)
- [DSCP remarking not supported for IPv6 \(green action\)](#)
- [DSCP remarking not supported for IPv6 \(in-profile action\)](#)
- [DSCP remarking not supported for IPv6 \(match action\)](#)
- [DSCP remarking not supported for IPv6 \(non-match action\)](#)
- [DSCP remarking not supported for IPv6 \(out-of-profile action\)](#)
- [DSCP remarking not supported for IPv6 \(red action\)](#)
- [DSCP remarking not supported for IPv6 \(yellow action\)](#)
- [Dst IP addr matching not supported with IP addr type data](#)
- [Dst Layer 4 port min max values invalid \(max must be = to min\)](#)
- [Dst MAC addr matching not supported with address type data](#)
- [Duplicate access asgn name type index detected \(prohibited\)](#)
- [Duplicate classifier class values in set detected](#)
- [Duplicate set values in block detected](#)
- [Dynamic interface assignment failure \(%d/%d\)](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Serious logs starting with E

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Serious logs starting with E

This page lists all the logs starting with the letter E that are generated with a severity of Serious.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [EAP Error: Reached maximum number of messages in the queue](#)
- [EAP Failed initialize global arrays](#)
- [EAP Failed to create dyna global arrays](#)
- [EAP Memory allocation error](#)
- [EAP Message queue error](#)
- [EAP NVRAM open error](#)
- [EAP NVRAM read port admin state error](#)
- [EAP NVRAM read system admin state error](#)
- [EAP NVRAM read system ubp state error](#)
- [EAP NVRAM write error](#)
- [EAP Task spawn error](#)
- [Egress interface and egress mask are mutually exclusive](#)
- [Element enable prohibited. Please delete and re-enter data](#)
- [Element label contains unacceptable characters](#)
- [Element label length outside of acceptable limits \(max 16 chars\)](#)
- [Error accessing Image File](#)
- [Error Bad Image Checksum](#)
- [Error in XGS3 memory DMA transfer](#)
- [Error reading Image File](#)
- [Evaluation precedence conflict detected \(UBP filter set data\)](#)
- [Evaluation precedence conflict \(Traffic Prof filter set data\)](#)
- [Evaluation precedence value required but not specified](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>





# Serious logs starting with F

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Serious logs starting with F

This page lists all the logs starting with the letter F that are generated with a severity of Serious.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [Failed to Create a Watchdog](#)
- [Failed to Read Image from Memory](#)
- [FCoE redirection default frame filter deletion failure detected](#)
- [FCoE redirection default frame filter installation failure detected](#)
- [FCoE redirection - egress interface issue detected \(ifIndex %d\)](#)
- [FCoE redirection - egress trunk issue detected \(trunk ID %d\)](#)
- [Filter control block resources exhausted](#)
- [Filter creation issue detected - in-profile action component](#)
- [Filter creation issue detected - match action component](#)
- [Filter creation issue detected - metering component](#)
- [Filter creation issue detected - non-match action component](#)
- [Filter creation issue detected - out-of-profile action component](#)
- [Filter manager memory resources exhausted](#)
- [Filter manager metering or policy rule space exhausted](#)
- [Filter manager metering resources exhausted](#)
- [Filter manager statistics tracking resources exhausted](#)
- [Filter set requirements incompatible with target interface](#)
- [First TrTCM Meter Index must be in range 1-5000](#)
- [Flow ID filtering not supported for IPv4](#)
- [Flow ID out-of-range \( Flow ID \)](#)
- [Front-panel UI selected use rear-panel base non-base switch](#)
- [FSH - NULL version for next reboot \(could not get semaphore\)](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Serious logs starting with I

This page lists all the logs starting with the letter I that are generated with a severity of Serious.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [Ifc app modification issue \(inconsistent default gateway data\)](#)
- [Ifc app modification issue \(inconsistent DHCP server data\)](#)
- [Ifc app modification issue \(inconsistent ifType data\)](#)
- [Ifc app support not currently available on interface \( ifc# \)](#)
- [Ifc assignment issue - prec conflict \(policy policy# disabled\)](#)
- [IGMP Error sending database from unit unit#](#)
- [IGMP Error sending group database from unit unit#](#)
- [IGMP Maximum number of igmp enabled interfaces reached](#)
- [Inadequate resources available for application policy criteria](#)
- [Incompatible base action extension specified](#)
- [Incompatible classifier reference \(agent-defined clfr\)](#)
- [Incompatible in-profile action \(trusted ifc\)](#)
- [Incompatible in-profile action \(unrestricted ifc\)](#)
- [Incompatible in-profile action \(untrusted ifc\)](#)
- [Incompatible in-profile action \(untrustedv4v6 ifc\)](#)
- [Incompatible match action \(unrestricted ifc\)](#)
- [Incompatible match action \(untrusted ifc\)](#)
- [Incompatible match action \(untrustedv4v6 ifc\)](#)
- [Incompatible non-match action \(trusted ifc\)](#)
- [Incompatible non-match action \(unrestricted ifc\)](#)
- [Incompatible non-match action \(untrusted ifc\)](#)
- [Incompatible out-of-profile action \(trusted ifc\)](#)
- [Incompatible out-of-profile action \(unrestricted ifc\)](#)
- [Incompatible out-of-profile action \(untrusted ifc\)](#)
- [Incompatible out-of-profile action \(untrustedv4v6 ifc\)](#)
- [Incompatible StorageType specified \(re classifier\)](#)
- [Inconsistent action criteria detected across block members](#)
- [Inconsistent labels detected for members of same block](#)
- [Inconsistent labels detected for members of same set](#)
- [Inconsistent MAC data detected across filter set members](#)
- [Inconsistent metering criteria detected across block members](#)
- [Inner VLAN ID filtering requires double tag](#)
- [Inner VLAN ID min max values invalid \( min VLAN ID ! max VLAN ID \)](#)
- [In-profile action contains conflicting data](#)
- [Insufficient HW resources to support port role association](#)
- [Insufficient policy space available to support access assignment](#)
- [Insufficient resources available to support policy installation](#)
- [Interface action entry referenced by base action](#)
- [Interface Application data in use \(OoS disable prohibited\)](#)
- [Interface application Undo failure \(app app# \)](#)
- [Interface assignment failure - precedence conflict detected](#)
- [Interface capabilities incompatible with policy data](#)
- [Interface data out-of-sync in Policy and User Policy entries](#)
- [Interface resources inadequate to support application enable](#)
- [Interface shaping and CoS shaping conflict \(same ifc specified\)](#)

[Interface shaping and queue shaping conflict \(same ifc specified\)](#)

- [Interface shaping not supported with specified interface](#)
- [Interfaces QoS-disabled \( port# on unit# \) - restoration issue](#)
- [Invalid access assignment type option specified](#)
- [Invalid access element type option specified](#)
- [Invalid classifier reference](#)
- [Invalid classifier reference \(unknown incompatible set\)](#)
- [Invalid classifier reference \(unknown instance\)](#)
- [Invalid DAPP state transition detected \(prohibited\)](#)
- [Invalid destination MAC address length specified](#)
- [Invalid destination MAC address mask length specified](#)
- [Invalid drop precedence value specified \( precedence \)](#)
- [Invalid DSCP value specified \( DSCP value \)](#)
- [Invalid egress interface specified \( ifc# \)](#)
- [Invalid egress interface type specified \(<ifc type>\)](#)
- [Invalid egress mask value specified](#)
- [Invalid EtherType value specified \( Ether Type 0xXXXX \)](#)
- [Invalid expired session data specified](#)
- [Invalid filter set priority value detected](#)
- [Invalid interface found in egress mask \( egress mask bit# \)](#)
- [Invalid interface index data specified \(%d\)](#)
- [Invalid interface index data specified \( ifc index \)](#)
- [Invalid interface index data \(system-owned\) specified](#)
- [Invalid IP destination address prefix detected](#)
- [Invalid IP source address prefix detected](#)
- [Invalid maximum inner VLAN ID value specified \( VLAN ID \)](#)
- [Invalid maximum VLAN ID value specified \( VLAN ID \)](#)
- [Invalid metering data \(bucket size\) specified for interface\(s\)](#)
- [Invalid metering data \(granularity\) specified for interface\(s\)](#)
- [Invalid metering data \(rate\) specified for interface\(s\)](#)
- [Invalid metering data \(srTCM trTCM\) specified for interface\(s\)](#)
- [Invalid minimum inner VLAN ID value specified \( VLAN ID \)](#)
- [Invalid minimum VLAN ID value specified \( VLAN ID \)](#)
- [Invalid mix of IP address data \(Dst IP type\) in set detected](#)
- [Invalid mix of IP and non-IP data in set detected](#)
- [Invalid mix of IP data \(IPv4 IPv6\) in set detected](#)
- [Invalid option specified for PatternIpVersion attribute](#)
- [Invalid pattern data length \(untagged format\) specified](#)
- [Invalid pattern data string length specified](#)
- [Invalid pattern format data specified](#)
- [Invalid pattern position string length specified](#)
- [Invalid port detected in specified port mask](#)
- [Invalid 802.1p user priority value specified \( priority value \)](#)
- [Invalid set drop precedence value specified](#)
- [Invalid shaping data \(bucket size\) specified for interface\(s\)](#)
- [Invalid shaping data \(granularity\) specified for interface\(s\)](#)
- [Invalid shaping data \(minimum rate granularity\) specified](#)
- [Invalid shaping data \(minimum rate maximum rate\) specified](#)
- [Invalid shaping data \(minimum rate\) specified](#)
- [Invalid shaping data \(rate\) specified for interface\(s\)](#)
- [Invalid source MAC address length specified](#)
- [Invalid source MAC address mask length specified](#)
- [Invalid statistics counter identification specified](#)
- [Invalid statistics tracking value](#)
- [Invalid statistics type value](#)
- [Invalid track statistics value specified](#)
- [Invalid unknown bandwidth type specified](#)
- [Invalid unsupported buffering capabilities value specified](#)
- [Invalid/unsupported classifier allocation mode specified](#)
- [Invalid unsupported copy-to-cpu option specified](#)
- [Invalid unsupported DAPP enable value specified](#)
- [Invalid unsupported DAPP maximum IPv4 ICMP length specified](#)
- [Invalid unsupported DAPP maximum IPv6 ICMP length specified](#)
- [Invalid unsupported DAPP minimum TCP header length specified](#)
- [Invalid unsupported default gateway address length specified](#)

- [Invalid unsupported default gateway address specified](#)
- [Invalid unsupported destination IP address length specified](#)
- [Invalid unsupported DHCP server address length specified](#)
- [Invalid unsupported DHCP server address specified](#)
- [Invalid unsupported interface type specified](#)
- [Invalid unsupported mirror frame option specified](#)
- [Invalid unsupported NT application mode value specified](#)
- [Invalid unsupported packet type value specified](#)
- [Invalid unsupported QoS system operational mode value specified](#)
- [Invalid unsupported queue configuration value specified](#)
- [Invalid unsupported role assoc compatibility specified](#)
- [Invalid unsupported source IP address length specified](#)
- [Invalid unsupported Trusted processing mode value specified](#)
- [Invalid unsupported UBP support level value specified](#)
- [Invalid unsupported VLAN tag value specified \( VLAN tag \)](#)
- [Invalid update DSCP value specified \(not currently supported\)](#)
- [Invalid update priority value specified](#)
- [Invalid update VLAN Id specified \( VLAN Id \)](#)
- [Invalid user priority match selection specified \( priority value \)](#)
- [IP classifier entry still referenced \(deletion prohibited\)](#)
- [IP destination address and mask values out-of-sync](#)
- [IP destination Layer 4 port maximum value out-of-range \( dest port#](#)
- [IP destination Layer 4 port minimum value out-of-range \( dest port# \)](#)
- [IP protocol value out-of-range \( IP protocol# \)](#)
- [IP source address and mask values out-of-sync](#)
- [IP source Layer 4 port minimum value out-of-range \( src port# \)](#)
- [IPv6 in IPV4 tunnel SIP mismatch](#)
- [IPv4-only filter criteria mixed with IPv6 criteria](#)
- [Issue detected enabling/disabling DSCP Mapping Table usage \(port %d\)](#)
- [Issue detected setting native DSCP Mapping Table values](#)
- [Issue with classifier component mask detected](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# Serious logs starting with L

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Serious logs starting with L

This page lists all the logs starting with the letter L that are generated with a severity of Serious.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [Layer 2 classifier still referenced \(deletion prohibited\)](#)
- [Layer 4 port filtering with IPv6 requires UDP TCP Next Header](#)
- [Layer 4 port range could not be reduced sufficiently](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Serious logs starting with M

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Serious logs starting with M

This page lists all the logs starting with the letter M that are generated with a severity of Serious.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [Management IP: excess traffic received on Management port%s](#)
- [Memory Allocation Error](#)
- [Meter entry referenced by clfr block \(deletion prohibited\)](#)
- [Meter entry referenced by meter \(deletion prohibited\)](#)
- [Meter entry referenced by policy \(deletion prohibited\)](#)
- [Meter \(from clfr block\) usage in multiple policies prohibited](#)
- [Meter \(from policy\) usage in multiple policies prohibited](#)
- [Meter identifier out-of-range \( meter id \)](#)
- [Metering not supported with DS L2 access control lists](#)
- [Mirroring \(requested via action\) not configured correctly](#)
- [Modification of action \(non-match usage\) prohibited](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Serious logs starting with N

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Serious logs starting with N

This page lists all the logs starting with the letter N that are generated with a severity of Serious.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [NEAP Accounting - Memory allocation failure](#)
- [Non-match action contains conflicting data](#)
- [Non-match action not available for use with filter sets](#)
- [Non-match action support not available on certain interfaces](#)
- [Non-QoS interfaces may not be assigned to a role combination](#)
- [Non-supported action option \(green action\) specified](#)
- [Non-supported action option \(in-profile action\) specified](#)
- [Non-supported action option \(match action\) specified](#)
- [Non-supported action option \(out-of-profile action\) specified](#)
- [Non-supported action option \(policy non-match action\) specified](#)
- [Non-supported action option \(red action\) specified](#)
- [Non-supported action option \(yellow action\) specified](#)
- [Non-unique precedence order value detected \(prohibited\)](#)
- [Non-volatile QoS data discarded during restoration](#)
- [Non-volatile storage commit delay too large](#)
- [No resources available for classifier port range checking](#)
- [Not Enough Memory](#)
- [NT application mode enable failure - inadequate resources](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Serious logs starting with O

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Serious logs starting with O

This page lists all the logs starting with the letter O that are generated with a severity of Serious.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [Only one frame type supported per classifier](#)
- [Out-of-profile action contains conflicting data](#)
- [Out-of-range CoS index value \( COS index value \)](#)
- [Out-of-range queue index value \( queue index \) for in-use queue set](#)
- [Out-of-range queue index value \( queue index \) for pending queue set](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Serious logs starting with P

This page lists all the logs starting with the letter P that are generated with a severity of Serious.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [Packet redirection support limited by target interfaces](#)
- [Pattern matching data in excess of bytes# bytes specified](#)
- [Pattern matching \(Dst IP\) not supported with IP addr type data](#)
- [Pattern matching \(Dst MAC\) not supported with address type data](#)
- [Pattern matching \(IP\) not supported with non-IP addr type data](#)
- [Pattern matching not supported with other classification data](#)
- [Pattern modifier data specified without actual pattern data](#)
- [Pattern position and data strings must be same length](#)
- [Policies with session data must be port-based](#)
- [Policy action out-of-range \( action# \)](#)
- [Policy content incompatible with target interface\(s\)](#)
- [Policy mask availability issue \(space exhausted\)](#)
- [Policy modification support limited](#)
- [Policy non-match action out-of-range \( non-match action# \)](#)
- [Policy precedence conflict detected with non-QoS application](#)
- [Policy precedence value out-of-range for target interface\(s\)](#)
- [Policy requirements exceed available resources \(slot slot# \)](#)
- [Policy statistics index out-of-range \( stats index \)](#)
- [Policy with this filtering values is already installed on this precedence](#)
- [Post-join ACL installation issue detected \(ifc ifc# \)](#)
- [Post-join filter set installation issue detected \(ifc ifc# \)](#)
- [Post-join traffic-profile installation issue detected \(ifc ifc# \)](#)
- [Potential inconsistent access asgn state \(Undo fail\) detected](#)
- [Potential inconsistent ifc assignment state \(Undo fail\) detected](#)
- [Potential inconsistent policy state \(Undo fail\) detected](#)
- [Precedence value out-of-range](#)
- [Provided metering information incomplete](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)



# Serious logs starting with Q

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Serious logs starting with Q

This page lists all the logs starting with the letter Q that are generated with a severity of Serious.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [Q](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [I](#) | [U](#) | [V](#) | [W](#)

- [QoS filter-limiting mode modified and unit reset](#)
- [QoS policies may not be applied to uplink or daisy chain ports \( port# \)](#)
- [Queue configuration inconsistency detected \(local queue conf stack queue conf \)](#)
- [Queue set assignment distribution across stack failed](#)
- [Queue set unacceptable - pending range excludes in-use queues](#)
- [Queue set value modification prohibited](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [Q](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [I](#) | [U](#) | [V](#) | [W](#)



# Serious logs starting with R

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Serious logs starting with R

This page lists all the logs starting with the letter R that are generated with a severity of Serious.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [Rate granularity limited to increments of 1 Mbps or 64 Kbps](#)
- [Rate \(min\) granularity limited \(increments of 1 Mbps or 64 Kbps\)](#)
- [Referenced block \(by policy\) deletion prohibited](#)
- [Referenced set \(by block\) modifications prohibited](#)
- [Referenced set \(by policy\) modifications prohibited](#)
- [Remote QoS-disable request failure \( port# on unit unit# \)](#)
- [Requested attribute usage is currently not supported](#)
- [Requested filter manager support unavailable](#)
- [Requested reserve data invalid](#)
- [Request invalid - QoS interface apps enabled on interface\(s\)](#)
- [Request invalid - specified interface currently QoS-disabled](#)
- [Request temporarily denied - QoS support is currently disabled](#)
- [Required bandwidth information not specified](#)
- [Reset initiated by console](#)
- [Reset initiated through SSH by IP address](#)
- [Reset initiated through telnet by IP address](#)
- [Reset to default initiated by console](#)
- [Reset to default initiated through telnet by IP address](#)
- [Resources exhausted \(maximum class entries reached\)](#)
- [Resources exhausted \(out-of-memory\)](#)
- [Role combination associated with interface \(deletion prohibited\)](#)
- [Role combination contains unacceptable characters](#)
- [Role combination referenced by policy \(deletion prohibited\)](#)
- [Role \(interface\) capabilities incompatible with policy data](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Serious logs starting with S

This page lists all the logs starting with the letter S that are generated with a severity of Serious.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [Source MAC address and mask values out-of-sync](#)
- [Specified Destination Layer 4 min max range not supported](#)
- [Specified filter criteria is invalid inconsistent](#)
- [Specified inner VLAN ID min max range not supported](#)
- [Specified metering operation not supported](#)
- [Specified metering statistics entry already in-use \(by policy\)](#)
- [Specified policy components \(classifiers\) conflicting](#)
- [Specified policy statistics entry already in-use \(by meter\)](#)
- [Specified queue set information invalid](#)
- [Specified Source Layer 4 min max range not supported](#)
- [Specified token bucket criteria out of range](#)
- [Specified token bucket refresh interval not supported](#)
- [Specified token bucket size \(burst size\) not supported](#)
- [Specified user policy interface currently QoS-disabled](#)
- [Specified VLAN ID min max range not supported](#)
- [Src Layer 4 port min max values invalid \(max must be = to min\)](#)
- [srTCM meter issue - CIR must be the same in both meters](#)
- [srTCM meter issue - EBS must be greater than CBS](#)
- [srTCM trTCM meter issue - diff algorithms in associated meters](#)
- [srTCM trTCM meter issue - referenced meter incompatible unknown](#)
- [srTCM trTCM meter issue - too many cascaded meters](#)
- [Stack operation mode modified to Hybrid and unit reset](#)
- [Stack RO password changed from IP add](#)
- [Stack RO password changed from serial conn](#)
- [Stack RW password changed from IP add](#)
- [Stack RW password changed from serial conn](#)
- [Stack sync failed stack failed to form](#)
- [Stack synchronization failed Exp value Act value Missing value](#)
- [Successfully loaded backup configuration files](#)
- [Switch RO password changed from IP add:](#)
- [Switch RO password changed from serial connection](#)
- [Switch RW password changed from IP add](#)
- [Switch RW password changed from serial conn](#)
- [System classifier still referenced \(deletion prohibited\)](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)



# Serious logs starting with T

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Serious logs starting with T

This page lists all the logs starting with the letter T that are generated with a severity of Serious.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [TCP Control Flag filter criteria requires TCP protocol](#)
- [TFTP Failed](#)
- [The base \(unit# number \) has left the stack. Unit# number is now the base](#)
- [The user <%s> was locked.](#)
- [Token bucket algorithm identifier invalid](#)
- [Token bucket algorithm identifier unknown unsupported](#)
- [Token bucket entry referenced by meter \(deletion prohibited\)](#)
- [Token bucket entry referenced by shaper \(deletion prohibited\)](#)
- [Token bucket minimum rate outside limits \(64 - 10230000 Kbps\)](#)
- [Token bucket rate outside limits \(64 - 10230000 Kbps\)](#)
- [Token bucket size not compatible with committed fill rate](#)
- [Traffic Prof filter set elem count exceeds available resources](#)
- [Traffic Prof filter set policy count \( policy count \) exceeds limit \( policy limit \)](#)
- [Traffic Prof filter set rule count \( rule count \) exceeds limit \( rule limit \)](#)
- [Trap: FCoE - Egress Issue Detected](#)
- [Trap s5CtrUnitDown](#)
- [trTCM meter issue - PBS must be greater than CBS](#)
- [trTCM meter issue - PIR must be greater than CIR](#)
- [Trusted processing mode change rejected - inadequate resources](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Serious logs starting with U

This page lists all the logs starting with the letter U that are generated with a severity of Serious.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [I](#) | [U](#) | [V](#) | [W](#)

- [Unable to add block member \( block elem# component set id \) to existing policy](#)
- [Unable to apply existing policy data to interface \( unit# port# \)](#)
- [Unable to apply existing user-based policy data to new user](#)
- [Unable to apply filter set to ports \(unsupported capabilities\)](#)
- [Unable to apply newly-defined UBP filter set to existing user](#)
- [Unable to apply pre-defined UBP filter set to new user](#)
- [Unable to compress classification criteria in set adequately](#)
- [Unable to create count action \(meter\) for access assignment](#)
- [Unable to create count action \(policy\) for access assignment](#)
- [Unable to create count action \(secondary meter\) for access asgn](#)
- [Unable to create metering data for access assignment](#)
- [Unable to create non-match components for ACL](#)
- [Unable to create out-of-profile action for access assignment](#)
- [Unable to create policy data for access assignment](#)
- [Unable to create secondary metering data for access assignment](#)
- [Unable to create secondary token bucket data for access asgn](#)
- [Unable to create token bucket data for access assignment](#)
- [Unable to create yellow action for access assignment](#)
- [Unable to deactivate policy associated with interface](#)
- [Unable to delete block member \( block element# component set id \) from existing policy](#)
- [Unable to delete UBP filter set on interface ifc#](#)
- [Unable to derive suitable filter set element eval precedence](#)
- [Unable to determine clfr interface\(s\) compatibility](#)
- [Unable to disable ARP Spoofing support on interface \( ifc# \)](#)
- [Unable to disable BPDUBlkr support on interface \( ifc# \)](#)
- [Unable to disable DHCP Snooping support on interface \( ifc# \)](#)
- [Unable to disable DHCP Spoofing support on interface \( ifc# \)](#)
- [Unable to disable DNSPort support on interface \( ifc# \)](#)
- [Unable to disable existing policy data on interface \( unit# port# \)](#)
- [Unable to disable FTPPort support on interface \( ifc# \)](#)
- [Unable to disable Nachia support on interface \( ifc# \)](#)
- [Unable to disable policy data for access assignment](#)
- [Unable to disable SQLSlam support on interface \( ifc# \)](#)
- [Unable to disable SynFinScan support on interface \( ifc# \)](#)
- [Unable to disable Xmas support on interface \( ifc# \)](#)
- [Unable to enable ARP Spoofing support on interface \( ifc# \)](#)
- [Unable to enable BPDUBlkr support on interface \( ifc# \)](#)
- [Unable to enable DHCP Snooping support on interface \( ifc# \)](#)
- [Unable to enable DHCP Spoofing support on interface \( ifc# \)](#)
- [Unable to enable DNSPort support on interface \( ifc# \)](#)
- [Unable to enable FTPPort support on interface \( ifc# \)](#)
- [Unable to enable Nachia support on interface \( ifc# \)](#)
- [Unable to enable policy data for access assignment](#)
- [Unable to enable SQLSlam support on interface \( ifc# \)](#)
- [Unable to enable SynFinScan support on interface \( ifc# \)](#)

[Unable to enable Xmas support on interface \(%d\)](#)

- [Unable to install access assignment - component creation issue](#)
- [Unable to manipulate DAPP support \(no applicable interfaces\)](#)
- [Unable to modify access assignment - component modify issue](#)
- [Unicast \( Interface# \) and Non-Unicast \( interface# \) interfaces in conflict](#)
- [Unknown incompatible access element specified](#)
- [Unknown incompatible action component specified](#)
- [Unknown incompatible classifier block specified](#)
- [Unknown incompatible classifier set specified](#)
- [Unknown incompatible in-profile action specified](#)
- [Unknown incompatible in-profile \(green\) action specified](#)
- [Unknown incompatible match action specified](#)
- [Unknown incompatible metering component specified](#)
- [Unknown incompatible metering statistics entry specified](#)
- [Unknown incompatible out-of-profile action specified](#)
- [Unknown incompatible out-of-profile \(red\) action specified](#)
- [Unknown incompatible out-of-profile \(yellow\) action specified](#)
- [Unknown incompatible policy non-match action specified](#)
- [Unknown incompatible policy statistics entry specified](#)
- [Unknown incompatible queue set specified](#)
- [Unknown incompatible role combination specified](#)
- [Unknown incompatible token bucket reference specified](#)
- [Unknown out-of-range interface index value \( ifc# \)](#)
- [Unknown out-of-range interface index value \( ifc index \)](#)
- [Unknown queue set queue reference detected](#)
- [Unknown unsupported interface application type specified](#)
- [Unknown unsupported interface class specified \( ifc class \)](#)
- [Unknown unsupported IP Flag specified](#)
- [Unknown unsupported StorageType specified](#)
- [Unknown unsupported TCP Control Flag specified](#)
- [Unsupported IP address type specified](#)
- [Unsupported pattern offset data specified](#)
- [Unsupported unknown QoS agent configuration attribute \( attribute# \)](#)
- [Update priority value and update DSCP value out-of-sync](#)
- [Update priority value per ingress DSCP currently not supported](#)
- [User Policy data referencing interface \(operation prohibited\)](#)
- [User policy filter set count \(<set count>\) exceeds limit \(<set limit>\)](#)
- [User policy filter set element count exceeds available resources](#)
- [User policy group contains invalid unacceptable characters](#)
- [User policy group length outside of acceptable limits](#)
- [User policy name contains invalid unacceptable characters](#)
- [User policy name length outside of acceptable limits](#)
- [User Policy \(UBP\) filter set in use \(QoS disable prohibited\)](#)
- [User Policy \(UBP\) filter set in use \(QoS reset prohibited\)](#)
- [User priority specified with untagged frames \(invalid\)](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# Serious logs starting with V

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Serious logs starting with V

This page lists all the logs starting with the letter V that are generated with a severity of Serious.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [VLAN ID min max values invalid \( min VLAN ID ! max VLAN ID \)](#)
- [VLAN range could not be reduced sufficiently](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Serious logs starting with W

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Serious logs starting with W

This page lists all the logs starting with the letter W that are generated with a severity of Serious.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)

- [Wrong QoS Agent buffer setting, expected %s, actual %s, unit re-configured and reboot](#)
- [Wrong QoS Agent buffer setting, expected %s, actual %s, unit re-configured and reboot](#)
- [Wrong QoS Agent queue setting, expected %u, actual %u, unit reconfigured and reboot](#)
- [Wrong QoS Agent queue setting, expected %u, actual %u, unit re-configured and reboot](#)
- [Wrong QoS Agent queue setting, expected %u, actual %u, unit reconfigured and reboot](#)
- [Wrong QoS Agent queue setting, expected %u, actual %u, unit re-configured and reboot](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [I](#) | [L](#) | [M](#) | [N](#) | [O](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#) | [V](#) | [W](#)



# Critical logs starting with A

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Critical logs starting with A

This page lists all the logs starting with the letter A that are generated with a severity of Critical.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)

- [Access assignment modifications not supported](#)
- [Access element modifications not supported](#)
- [application-name failed DB-exchange stack failed to form](#)
- [App-Telemetry: Configuration file missing or cannot be read. No config file will be used](#)
- [App-Telemetry: Default configuration file is missing](#)
- [App-Telemetry: Maximum number of entries has been reached](#)
- [App-Telemetry: Parse error detected in policy file at line](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Critical logs starting with B

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Critical logs starting with B

This page lists all the logs starting with the letter B that are generated with a severity of Critical.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)

- [Base action modifications not supported](#)
- [Bay Secure Resource Error error# line line# resource ID](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Critical logs starting with C

This page lists all the logs starting with the letter C that are generated with a severity of Critical.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)

- [cam driver initialization failed \(code= error type argument= line# \)](#)
- [cam processing aborted \(code= error type argument= line# \)](#)
- [Classifier block modifications not supported](#)
- [Classifier component modifications not supported](#)
- [Composite filter set addition failure comp filter set unknown](#)
- [Composite filter set addition failure replication failure](#)
- [Composite filter set creation failure replication failure](#)
- [Composite filter set creation failure seed filter set unknown](#)
- [Composite filter set deletion failure comp filter set unknown](#)
- [Composite filter set deletion failure seed filter set unknown](#)
- [CoS shaping modifications not supported](#)
- [Count action modifications not supported](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Critical logs starting with D

This page lists all the logs starting with the letter D that are generated with a severity of Critical.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)

- [Data model version attribute value not supported](#)
- [Download - DL\\_CKSUM\\_ACK\\_ERROR](#)
- [Download - DL\\_HASH\\_ACK\\_ERROR](#)
- [Download - DL\\_PROGRAM\\_STATUS\\_ACK\\_ERROR](#)
- [Download - DL\\_START\\_PROGRAM\\_FLASH\\_ACK\\_ERROR](#)
- [Download - Error: Failed to get the dl resource.](#)
- [Download - Error: Failed to get the Reset sem](#)
- [Download - Error: Failed to send message to dlQueue](#)
- [Download - Error: Image is invalid](#)
- [Download - Error: Watchdog expire: No Ack from NBUs, download MSG # %d](#)
- [Download - Failed to get buffer](#)
- [Download - Failed to malloc for buffer](#)
- [Download - Failed to start a watchdog](#)
- [Download - Image Checksum Error](#)
- [Download - Image Hash Error](#)
- [Download - Largest mem blk < DL\\_SYSMEM\\_RESERVED](#)
- [Download - NBU: Block Checksum Error](#)
- [Download - NBU: DL\\_PROGRAM\\_STATUS: ERROR](#)
- [Download - TFTP timeout OR image file not found](#)
- [Download - tftpXfer failed](#)
- [DSCP mapping modifications not supported](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)



# Critical logs starting with E

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Critical logs starting with E

This page lists all the logs starting with the letter E that are generated with a severity of Critical.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)

- [EAP: Error initializing dynamic settings semaphore](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Critical logs starting with F

This page lists all the logs starting with the letter F that are generated with a severity of Critical.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)

- [Filter manager internal error encountered](#)
- [Filter manager request parameter invalid](#)
- [FSH – Error: Calling taskLock\(\) returns Error](#)
- [FSH - Error: Failed to erase flash address %x located in the %s](#)
- [FSH – Error: Failed to erase flash sector](#)
- [FSH – Error: Failed to lock flash sector](#)
- [FSH – Error: Failed to program flash](#)
- [FSH – Error: Failed to unlock flash sector](#)
- [FSH – Error: Failed to write to flash address](#)
- [FSH - Error: Failed to write to %s, at address:%x](#)
- [FSH - Time to Download the Image: %d seconds](#)
- [FSH - Time to Program the Image to flash: %d seconds](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)



# Critical logs starting with H

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Critical logs starting with H

This page lists all the logs starting with the letter H that are generated with a severity of Critical.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)

- [Hello Module unable to communicate with neighbor\(s\) unit reset](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Critical logs starting with I

This page lists all the logs starting with the letter I that are generated with a severity of Critical.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)

- [IGMP Initialization failed Error code errCode](#)
- [IMC buffers of size buffer size have been exhausted buffer pool size pool size](#)
- [Incompatible data model version values \(referenced clfr data\)](#)
- [Incompatible data model version values \(referenced meter data\)](#)
- [Inconsistent classifier component \( clfr comp# \) state detected](#)
- [Interface action extension identifier invalid](#)
- [Interface action modifications not supported](#)
- [Interface application modifications not supported](#)
- [Interface assignment modifications not supported](#)
- [Interface queue modifications not supported](#)
- [Interface shaping modifications not supported](#)
- [Invalid classifier ID specified](#)
- [Invalid classifier reference \(unknown class\)](#)
- [Invalid datapath identifier specified](#)
- [Invalid master block member value specified](#)
- [Invalid option specified for BcastFrames attribute](#)
- [Invalid option specified for KnownIpMcast attribute](#)
- [Invalid option specified for KnownMcastFrames attribute](#)
- [Invalid option specified for KnownNonIpMcast attribute](#)
- [Invalid option specified for KnownUcastFrames attribute](#)
- [Invalid option specified for NonIpPkt attribute](#)
- [Invalid option specified for UnknownMcastFrames attribute](#)
- [Invalid option specified for UnknownNonIpMcast attribute](#)
- [Invalid option specified for UnknownUcastFrames attribute](#)
- [Invalid resetToDefaults value specified](#)
- [Invalid unknown access assignment entry state encountered \( entry state \)](#)
- [Invalid unknown access element entry state encountered \( entry state \)](#)
- [Invalid unknown action entry state encountered \( entry state \)](#)
- [Invalid unknown classifier block entry state encountered \( entry state \)](#)
- [Invalid unknown CoS shaping entry state encountered \( entry state \)](#)
- [Invalid unknown DSCP mapping entry state encountered \( entry state \)](#)
- [Invalid unknown entry state \(class class# \) encountered \( entry state \)](#)
- [Invalid unknown interface action entry state encountered \( entry state \)](#)
- [Invalid/unknown interface app entry state encountered \(<entry state>\)](#)
- [Invalid unknown interface assignment entry state encountered \( entry state \)](#)
- [Invalid unknown interface queue entry state encountered \( entry state \)](#)
- [Invalid unknown interface shaping entry state encountered \( entry# \)](#)
- [Invalid unknown IP filter entry state encountered \( entry state \)](#)
- [Invalid unknown Layer 2 filter entry state encountered \( entry state \)](#)
- [Invalid unknown meter entry state encountered \( entry state \)](#)
- [Invalid unknown policy entry state encountered \( entry state \)](#)
- [Invalid unknown 802.1p user priority mapping entry state \( entry state \)](#)
- [Invalid unknown queue set assignment entry state encountered \( entry state \)](#)
- [Invalid unknown queue shaping entry state encountered \( entry state \)](#)
- [Invalid unknown queuing discipline enum specified \( queuing discipline \)](#)

- [Invalid unknown role combination entry state encountered \( entry state \)](#)
- [Invalid unknown System filter entry state encountered \( entry state \)](#)
- [Invalid unknown token bucket entry state encountered \( entry state \)](#)
- [Invalid unknown user policy entry state encountered \( entry state \)](#)
- [IP classifier modifications not supported](#)
- [Issue detected restoring QPA data from NV \(class class# \)](#)
- [Issues detected with OoS operational mode disable \( ifcs# ifcs\)](#)
- [Issues detected with OoS operational mode enable \( ifcs# ifcs\)](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Critical logs starting with L

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Critical logs starting with L

This page lists all the logs starting with the letter L that are generated with a severity of Critical.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)

- [Layer 2 classifier modifications not supported](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Critical logs starting with M

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Critical logs starting with M

This page lists all the logs starting with the letter M that are generated with a severity of Critical.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)

- [MCM group node corrupted:](#)
- [Memory on unit %d is under %d MBytes.](#)
- [Meter modifications not supported](#)
- [Modify the pattern data or use the correct data format](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Critical logs starting with P

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Critical logs starting with P

This page lists all the logs starting with the letter P that are generated with a severity of Critical.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)

- [Policy modifications not supported](#)
- [Post-join policy installation issue detected \(ifc %d\)](#)
- [Potential inconsistent access elem state \(Undo fail\) detected](#)
- [Potential inconsistent block state \(Undo fail\) detected](#)
- [802.1p user priority mapping modifications not supported](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference

February 2020

©Extreme Networks 2020 All Rights Reserved.

<http://extremenetworks.com/support>



# Critical logs starting with Q

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Critical logs starting with Q

This page lists all the logs starting with the letter Q that are generated with a severity of Critical.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)

- [Queue set assignment modifications not supported](#)
- [Queue shaping modifications not supported](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Critical logs starting with R

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Critical logs starting with R

This page lists all the logs starting with the letter R that are generated with a severity of Critical.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)

- [Reset - Error Failed to get the Reset sem](#)
- [Resource alloc event timeout \(tgt all apps except OoS Agent rcv event \)](#)
- [Role combination modifications not supported](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>



# Critical logs starting with S

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Critical logs starting with S

This page lists all the logs starting with the letter S that are generated with a severity of Critical.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)

- [SLAMon Agent: message channel creation failure](#)
- [SLAMon Agent: platform CLI command interface initialization issue](#)
- [SLAMon Agent: platform timer initialization issue](#)
- [SLAMon Agent: terminated](#)
- [SLAMon Agent: terminated - command/frame processing issue detected](#)
- [SLAMon Agent: terminated - NTR test exception detected](#)
- [SLAMon Agent: terminated - resources unavailable](#)
- [SLAMon Agent: terminated - RTP test exception detected](#)
- [SNTP Could not sync to NTP servers.](#)
- [SPBM: ERROR adding i-sid %x to i-sid table - table full](#)
- [SPBM: ERROR enabling SPBM due to Software License error](#)
- [Specified filter information not found](#)
- [Specified filter manager resource invalid](#)
- [Specified filter manager resource uninitialized](#)
- [Specified policy identifier \(cookie\) invalid](#)
- [Sw Exception](#)
- [System classifier modifications not supported](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>





# Critical logs starting with T

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Critical logs starting with T

This page lists all the logs starting with the letter T that are generated with a severity of Critical.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)

- [Task task-name is suspended](#)
- [Task whose index is %d.%d is suspended](#)
- [Token bucket modifications not supported](#)
- [Trap: slaMonitorAgentExceptionDetected](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [T](#) | [U](#)

Ethernet Routing Switch 3500, 3600, 4800, 4900, 5900 and Virtual Services Platform 7000 Series  
9036480-00 Rev AA Logs Reference  
February 2020

©Extreme Networks 2020 All Rights Reserved.  
<http://extremenetworks.com/support>

[Home](#) | [Alphabetical listing](#) | [Source listing](#) | [Severity listing](#)

## Critical logs starting with U

This page lists all the logs starting with the letter U that are generated with a severity of Critical.

Navigate to the description of each log by clicking the log name, or select a different letter for the logs that start with that letter.

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [I](#) | [U](#)

- [Unable to complete requested access asgn system operation \( oper type \)](#)
- [Unable to complete requested policy system operation \( operation type \)](#)
- [Unable to compress specified policy criteria](#)
- [Unable to create action for access element](#)
- [Unable to create classifier block entry for access element](#)
- [Unable to create classifier component entry for access element](#)
- [Unable to create DS MF classifier for access element](#)
- [Unable to create L2 MF classifier for access element](#)
- [Unable to inform SPB of ifc assignment change \(%d/%d\)](#)
- [Unable to install access element - component creation issue](#)
- [Unable to locate corresponding DS L2 access elements](#)
- [Unknown access assignment entry specified \(%d\)](#)
- [Unknown access element entry specified \( entry# \)](#)
- [Unknown action entry specified \( entry# \)](#)
- [Unknown classifier block entry specified \( entry# \)](#)
- [Unknown classifier component entry specified \( entry# \)](#)
- [Unknown CoS shaping entry specified \( entry# CoS \)](#)
- [Unknown count action entry specified \( entry# \)](#)
- [Unknown DSCP mapping entry specified \( entry# \)](#)
- [Unknown entry \( class class# \) specified \( entry# \)](#)
- [Unknown incompatible token bucket reference specified](#)
- [Unknown interface application entry specified \( entry# \)](#)
- [Unknown interface assignment entry specified \( entry# \)](#)
- [Unknown interface queue entry specified \( ifc queue id \)](#)
- [Unknown interface shaping entry specified \( entry# \)](#)
- [Unknown IP classifier entry specified \(%d\)](#)
- [Unknown Layer 2 classifier entry specified \( entry# \)](#)
- [Unknown meter entry specified \(%d\)](#)
- [Unknown policy entry specified \( entry# \)](#)
- [Unknown 802.1p user priority mapping entry specified \( entry# \)](#)
- [Unknown queue set assignment entry specified \( entry# \)](#)
- [Unknown queue shaping entry specified \( entry# queue \)](#)
- [Unknown role combination entry specified \( role comb id \)](#)
- [Unknown System classifier entry specified \( entry# \)](#)
- [Unknown token bucket entry specified \( entry# \)](#)
- [Unknown unsupported RowStatus specified](#)
- [Unknown user policy entry specified \( entry# \)](#)
- [Unsupported IPv4 Options value specified](#)
- [User policy modifications not supported](#)

[A](#) | [B](#) | [C](#) | [D](#) | [E](#) | [F](#) | [H](#) | [I](#) | [L](#) | [M](#) | [P](#) | [Q](#) | [R](#) | [S](#) | [I](#) | [U](#)

