

# **Customer Release Notes**

# Ethernet Routing Switch 4900 and 5900 Series

Software Release 7.7.2 May 2020

#### **INTRODUCTION:**

This document provides specific information for version 7.7.2 of agent software for the Ethernet Routing Switch 4900 and 5900 Series (All models).

The purpose of this version is to address customer and internally found software issues.

Extreme Networks recommends that you thoroughly review this document prior to installing or upgrading this product.

For the latest firmware versions, visit the download site at: www.extremenetworks.com/support/

# **IMPORTANT NOTES BEFORE UPGRADING TO THIS RELEASE**

If diagnostic upgrade is needed, extract the diagnostic image radiag\_xxxx.bin file from the Diag\_xxxx.zip archive.

#### PLATFORMS SUPPORTED

Ethernet Routing Switch 4900 and 5900 Series (All models)

#### **NOTES FOR UPGRADE**

Please see "Release Notes for Ethernet Routing Switch 4900 and 5900 Series, Release 7.7", available at <u>https://www.extremenetworks.com/documentation</u> for details on how to upgrade your Switch.

#### FILE NAMES FOR THIS RELEASE

#### Ethernet Routing Switch 4900 Series

| File Name                                     | Module or File Type          | File Size (bytes) |
|---|------------------------------|-------------------|
| 4900_772017s.img                              | Secure runtime image         | 19783636          |
| Diag_7504.zip                                 | Diagnostic software          | 7470411           |
| Ethernet_Routing_Switch_Ranger_MIBs_7.7.0.zip | MIB Definition File archive  | 3607574           |
| ers5000v770_HELP_EDM.zip                      | EDM Help file zip            | 2074419           |
| ers5900v7.7.0.0.zip                           | EDM plug-in for COM file zip | 3814285           |
| 5900_poe_v15011.bin                           | POE firmware                 | 40960             |

05/12/2020 P/N: 9036714-00 Rev. AA

#### Ethernet Routing Switch 5900 Series

| File Name                                     | Module or File Type          | File Size (bytes) |
|---|------------------------------|-------------------|
| 5900_772017s.img                              | Secure runtime image         | 20402788          |
| Diag_7504.zip                                 | Diagnostic software          | 7470411           |
| Ethernet_Routing_Switch_Ranger_MIBs_7.7.0.zip | MIB Definition File archive  | 3607574           |
| ers5000v770_HELP_EDM.zip                      | EDM Help file zip            | 2074419           |
| ers5900v7.7.0.0.zip                           | EDM plug-in for COM file zip | 3814285           |
| 5900_poe_v15011.bin                           | POE firmware                 | 40960             |

# **VERSION OF PREVIOUS RELEASE**

#### Software Version 7.7.1

#### COMPATIBILITY

This software release is managed with Enterprise Device Manager (EDM), which is integrated into the agent software.

# **CHANGES IN THIS RELEASE**

#### **New Features in This Release**

None.

## **Old Features Removed from This Release**

None.

| Problems Resolved in This Release |  |  |
|-----------------------------------|--|--|
| ERS495900-5502                    | On a stack in highly intensive logging environments (5+ logs /sec for a long period of time) some CLI commands could become non responsive if remote logging is enabled and a SNMP or CLI query requires an internal transfer of logs through the stack. |  |
| ERS495900-5561,<br>ERS495900-5672 | Backing up the binary configuration file through TFTP when the SNMP notify is configured could result in the failure of establishing connections through SSH/Telnet/HTTP or in some cases frozen CLI   |  |
| ERS495900-5633                    | On a specific scenario when adding 2 units at once in a stack, ISIS configuration and fabric traffic can be impacted.  |  |
| ERS495900-5646                    | A NEAP client using an RAV, in an FA-enabled switch which automatically configures VLAN/I-SID bindings through FA on the uplink towards the switch, fails to do so after a two-unit stack reverts to a standalone unit.                                  |  |
| ERS495900-5688                    | IPFIX reporting incorrect amount of traffic  |  |

### **KNOWN LIMITATIONS:**

None.

For other previously known issues, please refer to the product release notes and technical documentation available from the Extreme Networks Support web site at: <u>www.extremenetworks.com/support/</u>.

#### **DOCUMENTATION CORRECTIONS**

None.

#### TROUBLESHOOTING

As good practices of help for troubleshooting various issues, we recommend:

- configuring the device to use the Simple Network Time Protocol to synchronize the device clock;
- setting a remote logging server to capture all level logs, including informational ones. (#logging remote level informational).

#### **GLOBAL SUPPORT:**

By Phone: +1 800-998-2408 (toll-free in U.S. and Canada)

For the toll-free support number in your country: <a href="http://www.extremenetworks.com/support/">www.extremenetworks.com/support/</a>

- By Email: <u>support@extremenetworks.com</u>
- By Web: <u>www.extremenetworks.com/support/</u>
- By Mail: Extreme Networks, Inc. 6480 Via Del Oro San Jose, CA 95119

For information regarding the latest software available, recent release note revisions, or if you require additional assistance, please visit the Extreme Networks Support website.

Copyright © 2020 Extreme Networks, Inc. - All Rights Reserved.

#### Legal Notice

Extreme Networks, Inc. reserves the right to make changes in specifications and other information contained in this document and its website without prior notice. The reader should in all cases consult representatives of Extreme Networks to determine whether any such changes have been made.

The hardware, firmware, software or any specifications described or referred to in this document are subject to change without notice. Trademarks

Extreme Networks and the Extreme Networks logo are trademarks or registered trademarks of Extreme Networks, Inc. in the United States and/or other countries. All other names (including any product names) mentioned in this document are the property of their respective owners and may be trademarks or registered trademarks of their respective companies/owners.

For additional information on Extreme Networks trademarks, please see:

www.extremenetworks.com/company/legal/trademarks