

Virtual Services Platform 8200 Software Release 4.0.1.4

1. Release Summary

Release Date: March 2015

Purpose: Software release to address customer found software issues.

2. Important Notes before Upgrading to This Release

None.

3. Platforms Supported

Virtual Services Platform 8200

4. Special Instructions for Upgrade from previous releases

None.

5. Notes for Upgrade

Please see “Release Notes for Avaya Virtual Services Platform 8284XSQ” for software release 4.0.1.0 (NN47227-401, 02.04) available at <http://www.avaya.com/support> for details on how to upgrade your Switch.

File Names For This Release

File Name	Module or File Type	File Size (bytes)
VSP8200.4.0.1.4.tgz	Release 4.0.1.4 archived software distribution	44208899
VSP8200.4.0.1.4_modules.tgz	Release 4.0.1.4 Encryption Modules	41826
VSP8200.4.0.1.4_mib.zip	Archive of all MIB files	798496
VSP8200.4.0.1.4_mib.txt	MIB file	5163355
VSP8200.4.0.1.4_mib_sup.txt	MIB file	630059
VSP8200v401_HELP_EDM_gzip.zip	EDM Help file	2275488
VSP8200v4.0.1.0.zip	EDM plug-in for v401/vsp8200	3517565
VSP8200.4.0.1.4.md5	MD5 Checksums	602

Note about image download:

Ensure images are downloaded using the binary file transfer. Perform MD5 checksum check on downloaded files to ensure file integrity.

Check that the file type suffix is “.tgz” and the image names after download to device match those shown in the above table. Some download utilities have been observed to append “.tar” to the file name or change the filename extension from “.tgz” to “.tar”. If file type suffix is “.tar” or file name does not exactly match the names shown in above table, rename the downloaded file to the name shown in the table above so that the activation procedures will operate properly.

Load activation procedure:

```
software add VSP8200.4.0.1.4.tgz
software add-modules VSP8200.4.0.1.4.GA VSP8200.4.0.1.4_modules.tgz
software activate VSP8200.4.0.1.4.GA
```

6. Version of Previous Release

Software Version 4.0.0.0, 4.0.1.0, 4.0.1.1, 4.0.1.2, 4.0.1.3

7. Compatibility

8. Changes in 4.0.1.4

New Features in This Release

Old Features Removed From This Release

Problems Resolved in This Release

ID	Description
wi01206138	SSH clone session option is not supported and not handled gracefully. Using the clone session option in SSH clients like SecureCRT may cause a system reset.
wi01210072	CP may reset when SNMP community string is too long.

9. Outstanding Issues

Please see “Release Notes for Avaya Virtual Services Platform 8284XSQ” for software release 4.0.1.0 (NN47227-401, 02.04) available at <http://www.avaya.com/support> for details regarding Known Issues.

In addition, the following issues have been identified:

<u>ID</u>	<u>Problem Description</u>	<u>Workaround</u>
wi01203911	High latency observed in processing ICMP Request and DHCP Relay packets when large number of IP-netbios broadcast packets are received.	Workaround is to use ACL filter to capture and drop the unwanted broadcast packets.
wi01186535	Simplified VIST configuration cannot be managed correctly using EDM.	Use ACLI to configure/modify/delete Simplified VIST related commands and parameters.
wi01192436	MLT up/down trap is not sent when first port of the MLT transitions up or last port of the MLT transitions down.	Log messages of the MLT up and down events are written and sent to syslog servers if configured.

10. Known Limitations

Please see “Release Notes for Avaya Virtual Services Platform 8284XSQ” for software release 4.0.1.0 (NN47227-401, 02.04) available at <http://www.avaya.com/support> for details regarding Known Limitations.

The VSP8284XSQ platform may experience a watchdog timeout induced reset when a momentary power loss to the system occurs. In this situation the datapath has been reinitialized even though there is enough power left in the system for the Control Plane to generate a coredump. The reset is needed for the system to be fully functional again. Using a UPS is recommended to mitigate momentary power interruption.

11. Documentation Corrections

For other known issues, please refer to the product release notes and technical documentation available from the Avaya Technical Support web site at: <http://www.avaya.com/support> .

Copyright © 2015 Avaya Inc - All Rights Reserved.

The information in this document is subject to change without notice. The statements, configurations, technical data, and recommendations in this document are believed to be accurate and reliable, but are presented without express or implied warranty. Users must take full responsibility for their applications of any products specified in this document. The information in this document is proprietary to Avaya.

To access more technical documentation, search our knowledge base, or open a service request online, please visit Avaya Technical Support on the web at: <http://www.avaya.com/support>