

Customer Release Notes

G-Series

Firmware Version 6.61.16.0002

April 2016

INTRODUCTION:

This document provides specific information for version 6.61.16.0002 of firmware for the following G3 products:

G3G124-24	G3G124-24P	G3G170-24
-----------	------------	-----------

Extreme Networks recommends that you thoroughly review this document prior to installing or upgrading this product.

For the latest firmware versions, visit the download site at:
<http://support.extremenetworks.com/>

FIRMWARE SPECIFICATION:

Status	Version No.	Type	Release Date
Current Version	6.61.16.0002	Maintenance Release	April 2016
Previous Version	6.61.15.0003	Maintenance Release	September 2015
Previous Version	6.61.14.0006	Maintenance Release	May 2015
Previous Version	6.61.13.0006	Maintenance Release	November 2014
Previous Version	6.61.12.0005	Maintenance Release	April 2014
Previous Version	6.61.11.0006	Maintenance Release	December 2013
Previous Version	6.61.10.0008	Maintenance Release	September 2013
Previous Version	6.61.09.0012	Maintenance Release	August 2013
Previous Version	6.61.08.0013	Maintenance Release	April 2013
Previous Version	6.61.07.0010	Maintenance Release	October 2012
Previous Version	6.61.06.0009	Maintenance Release	August 2012
Previous Version	6.61.05.0009	Maintenance Release	July 2012
Previous Version	6.61.03.0004	Maintenance Release	April 2012
Previous Version	6.61.02.0007	Feature Release	March 2012
Previous Version	6.42.11.0006	Maintenance Release	February 2012
Previous Version	6.42.10.0016	Maintenance Release	December 2011
Previous Version	6.42.09.0005	Maintenance Release	August 2011
Previous Version	6.42.08.0007	Maintenance Release	July 2011
Previous Version	6.42.07.0010	Maintenance Release	May 2011

Status	Version No.	Type	Release Date
Previous Version	6.42.06.0008	Maintenance Release	April 2011
Previous Version	6.42.05.0001	Maintenance Release	March 2011
Previous Version	6.42.03.0004	Maintenance Release	January 2011
Previous Version	6.42.02.0006	Maintenance Release	December 2010
Previous Version	6.42.01.0046	Maintenance Release	November 2010
Previous Version	6.03.08.0012	Maintenance Release	October 2010
Previous Version	6.03.06.0008	Maintenance Release	August 2010
Previous Version	6.03.05.0004	Maintenance Release	June 2010
Previous Version	6.03.04.0004	Maintenance Release	April 2010
Previous Version	6.03.03.0008	Maintenance Release	February 2010
Previous Version	6.03.02.0006	Maintenance Release	November 2009
Previous Version	6.03.01.0008	Maintenance Release	September 2009
Previous Version	6.03.00.0022	Feature Release	June 2009
Previous Version	1.02.06.0004	Maintenance Release	June 2009
Previous Version	1.02.05.0004	Maintenance Release	April 2009
Previous Version	1.02.04.0005	Maintenance Release	March 2009
Previous Version	1.02.03.0010	Maintenance Release	January 2009
Previous Version	1.02.02.0009	Maintenance Release	November 2008
Previous Version	1.02.00.0043	Feature Release	October 2008
Previous Version	1.00.03.0002	Maintenance Release	July 2008
Previous Version	1.00.02.0001	Maintenance Release	May 2008
Previous Version	1.00.01.0058	Maintenance Release	May 2008
Previous Version	1.00.00.0054	Initial Release	March 2008

BOOTPROM COMPATIBILITY:

This version of firmware is compatible with all boot code versions.

NETWORK MANAGEMENT SOFTWARE SUPPORT:

Network Management Suite (NMS)	Version No.
NMS Automated Security Manager	6.2
NMS Console	6.2
NMS Inventory Manager	6.2
NMS Policy Manager	6.2
NMS NAC Manager	6.2

If you install this image, you may not have control of all the latest features of this product until the next version(s) of network management software. Please review the software release notes for your specific network management platform for details.

PLUGGABLE PORTS SUPPORTED:

MGBICs	Description
MGBIC-LC01	1000Base-SX, IEEE 802.3 MM, 850 nm Short Wave Length, 220/550M, LC SFP
MGBIC-LC03	1000Base-SX-LX/LH, MM, 1310 nm Long Wave Length, 2 KM, LC SFP
MGBIC-LC07	Extended 1000Base-LX, IEEE 802.3 SM, 1550 nm Long Wave Length, 110KM, LC SFP.
MGBIC-LC09	1000Base-LX, IEEE 802.3 SM, 1310 nm Long Wave Length, 10 KM, LC SFP
MGBIC-MT01	1000Base-SX, IEEE 802.3 MM, 850 nm Short Wave Length, 220/550 M, MTRJ SFP
MGBIC-02	1000Base-T, IEEE 802.3 Cat5, Copper Twisted Pair, 100 M, RJ45 SFP
MGBIC-08	1000Base-LX/LH, IEEE 802.3 SM, 1550 nm Long Wave Length, 80 KM, LC SFP
MGBIC-LC04	100Base-FX, IEEE 802.3 MM, 1310 nm Long Wave Length, 2 KM, LC SFP
MGBIC-LC05	100Base-FX, IEEE 802.3 SM, 1310 nm Long Wave Length, 10 KM, LC SFP
MGBIC-BX10-D	1000Base-BX10-D Single Fiber SM, Bidirectional, 1490nm Tx / 1310nm Rx, 10 km, Simplex LC SFP (must be paired with MGBIC-BX10-U)
MGBIC-BX10-U	1000Base-BX10-U, 1 Gb, Single Fiber SM, Bidirectional 1310nm Tx / 1490nm Rx, 10 km, Simplex LC SFP (must be paired with MGBIC-BX10-D)
MGBIC-BX40-U	1 Gb, 1000Base-BX40-U Single Fiber SM, Bidirectional, 1310nm Tx / 1490nm Rx, 40 Km, Simplex LC SFP (must be paired with MGBIC-BX40-D)
MGBIC-BX40-D	1 Gb, 1000Base-BX40-D Single Fiber SM, Bidirectional, 1490nm Tx / 1310nm Rx, 40 Km, Simplex LC SFP (must be paired with MGBIC-BX40-U)
MGBIC-BX120-D	1 Gb, 1000Base-BX120-D Single Fiber SM, Bidirectional, 1590nm Tx / 1490nm Rx, 120 Km, Simplex LC SFP (must be paired with MGBIC-BX120-U)
MGBIC-BX120-U	1 Gb, 1000Base-BX120-U Single Fiber SM, Bidirectional, 1490nm Tx / 1590nm Rx, 120 Km, Simplex LC SFP (must be paired with MGBIC-BX120-D)

XFPs	Description
10GBASE-ER-XFP	10GBASE-ER, IEEE 802.3 SM, 1550 nm Long Wave Length, 40 KM, LC XFP
10GBASE-LR-XFP	10GBASE-LR, IEEE 802.3 SM, 1310 nm Long Wave Length, 10 KM, LC XFP
10GB-LRM-SFP+	10 Gb, 10GBASE-LRM, IEEE 802.3 MM, 1310 nm Long Wave Length, 220 m, LC SFP+
10GBASE-SR-XFP	10GBASE-SR, IEEE 802.3 MM, 850 nm Short Wave Length, 33/82 M, LC XFP
10GBASE-CX4-XFP	10GBASE-CX4, IEEE 802.3 Twin Axial, Copper SFF-8470, 15 M, LC XFP
10GBASE-ZR-XFP	10GBASE-ZR, SM, 1550 nm Long Wave Length, 80 KM, LC XFP
10GBASE-LW-XFP	10GBASE-LW, Laserwire® XFP adapter for use with Laserwire cable assembly*

*The Laserwire® mark is a registered trademark and is the property of Finisar Corporation.

NOTE: Installing third party or unknown pluggable ports may cause the device to malfunction and will void your warranty.

PRODUCT FEATURES:**What's New in 6.61**

Spanning Tree Diagnostic MIB - Support for the Enterasys Spanning Tree Diagnostic MIB.
MSTP Multisource Detection - Checks for a change in the source MAC address of received BPDUs. Once detected this information is used to change the Spanning Tree point-to-point status of LAN on the given port.
OSPF Passive Interface - Define an interface that disables both reception and transmission of OSPF PDUs.
VRRP master-icmp-reply - Support for the ability to ping the backup VRRP IP address.
MAC Locking clearonlinkchange – Support for the optional ability to maintain first arrival MAC addresses on a port with a change in link status.
MAC Locking Threshold Notification – Support for notification when the MAC address tables threshold is reached.
Time Based Reset – Support for the ability to add time and date to the reset command.
Flexible Link Aggregation Groups – Support for configurable group limits.
Service Access Control Lists (SACL) - Provide security for switch management features, by ensuring that only known and trusted devices are allowed to remotely manage the switch via TCP/IP. A Service ACL may be applied to a specific host service (i.e. Telnet, SNMP, SSH, HTTP).
Access Control Lists – Added support for IPv6 and MAC based ACLs. Added queue assignment action to ACLs Note: ACLs are not supported simultaneously with Policy.
Increased Password Security – Supports new password options including: complexity, history, aging. Passwords can be encrypted using a FIPS 1402 approved algorithm.
Login Banner – Added support for a login banner with required user acceptance, in addition to the post login Message of the Day banner.
Warning: Configuration files containing login banners should not be used on pre-6.61 images
VLAN Classification – Added support for standalone “VLAN Association” application, for subnet, protocol and MAC based VLAN classification.
Password Reset Button Enhancements – Now supports ability to disable/enable the password reset button. The default admin login account will now be restored, as well as the default password.
OpenSSL FIPS Object Cryptographic Module – This module replaces previous software libraries used for encryption. This module is FIPS 140-2 validated when run in the C2 security profile.
IPsec for RADIUS transactions – Secures RADIUS transactions, including encryption of passwords passed via RADIUS.
Command Logging – Support for command logging added.
SNTP Server-Client Authentication - Authentication ensures that any response received from an SNTP time server has come from the intended reference.
Console Disconnect – Support added for Console disconnect through the use of VT100 terminal emulation.
Mixed Strict and WRR Port Transmit Queue settings – Extended the “port txq” command to support mixing one or more queues in strict priority with queues running in WRR.
Security Log – Added support for an undeletable security log that can only be read by the administrator.
Secure directory – Created a secure directory that can only be accessed by a super-user. This directory contains no files by default but may be used to load and store configuration files.
VLAN 4094 – VLAN 4094 is no longer reserved.

Existing Product Features	
Manual Mode POE	Class Based POE
DHCP Spoof Protection	Hot Insertion of IOMs
ARP Spoof Protection	IP Forward Protocol

Existing Product Features	
High-Temperature Alerts	Multiport LAG to single port LAG automatic failover
Show support CLI command	32K MAC Address Table
802.1D	Auto-Negotiation
802.1Q -VLAN Tagging	8 Priority Queues per Port
802.1p -Traffic Management / Mapping to 6 Queues	MGBIC Support: MGBIC-LC01, MGBIC-LC03, MGBIC-LC09, MGBIC-02, MGBIC-08, MGBIC-MT01, MGBIC-LC04, MGBIC-LC05, MGBIC-LC07
802.3x Flow Control	Session-Timeout and Termination-Action RADIUS Attributes Support
Base chassis: 24 Gbps Full Duplex (48 Gbps bidirectional) Base chassis with three 24 port cards: 96 Gbps Full Duplex (192 Gbps bidirectional) Base chassis with three quad 10Gb cards: 144Gbps Full Duplex (288 Gbps bidirectional)	Ability to Set Port Advertised Ability via CLI
802.3ad – Dynamic and Static Creation for Link Aggregation	Multi-method Authentication
802.1s – Multiple Spanning Tree Protocol (up to 4 instances)	Multiple RFC3580 Users per port (up to 8)
802.1w – Rapid Spanning Tree	Multi-User Authentication (up to 8 per port)
RFC-3580 dynamic VLAN assignment based on 802.1X, PWA or MAC Authentication	L2 Policy Rules
Spanning Tree Backup Root	COS based Inbound Rate Limiter per Policy User
Spanning Tree Loop Protect	DHCP Server
LLDP/LLDP-MED	Web Authentication (PWA)
Legacy Path Cost	Web Redirect – PWA+ and URL redirection
Spanning Tree Pass Through	802.1X Authentication
SpanGuard	Non-Strict 802.1X Default RFC 3580 With Auth Failure
Link Flap Detection	RADIUS Client
Per Port Broadcast Suppression	Turn Off RADIUS Authentication (RADIUS Realm)
Port Mirroring (Single instance)	Queuing Control Strict and Weighted Round Robin
Private Port (Private VLAN)	MAC Authentication / MAC Authentication Masking
Cabletron Discovery Protocol (CDP)	MAC Authentication Retained After Age Out
Cisco Discovery Protocol (CDP) v1/2	RADIUS Accounting for MAC Authentication
Cisco IP Phone Discovery	EAP pass-through
GVRP	VLAN marking of mirrored traffic – Edge only
IGMP v1/v2/v3 and IGMP Snooping	Dynamic and Static MAC Locking
IPV6 Tunneling	New Mac Trap
Syslog	Dynamic Egress
Text-based Configuration Upload/Download	SSHv2 Support
CLI Management	WebView
Telnet Support	SSL Interface to WebView

Existing Product Features	
IPv4/IPv6 Dual Host Management Support (SNMP, Telnet, SFTP, SCP, SSH, RADIUS)	RMON (4 groups)
Discard VLAN Tagged Frames	RMON View in the CLI With Persistent Sets
Policy – Multi User	RMON Packet Capture/Filtering Sampling
Priority Classification L3-L4	SNMPv1, SNMPv2c, SNMPv3
VLAN-to-Policy Mapping on a per Port Basis	Simple Network Time Protocol (SNTP)
Node/Alias Table	Alias Port Naming
ToS Rewrite	Ability to Set Time and Date via the MIB
IPv4/IPv6 Routing	Jumbo Frame (up to 9K)
Multiple IP Helpers per Interface (up to 6)	Configurable Login Banner
ACLs	CPU/Memory utilization monitoring via SNMP
Standard: IPv4 Routing Protocols: RIP, IRDP, Static routes License required: IPv6, OSPFv3, OSPF, VRRP, DVMRP, PIM-SM	CoS MIB based Flood Control (broadcast, multicast, and unknown unicast)
Hybrid Policy Mode*	sFlow
VLAN-to-Policy Mapping*	ACLs per VLAN
LLDP-MED Network-Policy TLV	Host Protect (permanently enabled)
TACACS+	AES-128 support with SNMPv3
Extended ACLs	Selectable management interfaces
Secure Copy / Secure FTP	Copy & Paste
Power Supply & Fan Monitoring via SNMPv3	RFC3580 dynamic VLAN assignment based on PWA
PC + Phone	IOM Push Button Disconnect Delay
TDR-based cable status check detects cable breaks and disconnections	Display 802.3 pause counters
New per-role policy limits	Serviceability enhancements
Tx Queue Monitoring	

INSTALLATION AND CONFIGURATION NOTES:

WARNING:

- Direct firmware upgrades to 6.61 from 6.03 (and previous) images may result in the loss of some configuration. It is recommended to upgrade to 6.42 prior to loading 6.61. Alternatively the configuration may be saved to a file and reloaded after upgrade.
- 6.61.05.009 contains new boot PROM code that will be programmed into the PROM the first time the image is booted. This process should take less than 3 minutes and the switch will reboot itself once PROM programming is complete. Do not remove power during this process. If the process of programming is interrupted it may leave the switch in an unrecoverable state.

Note:

If VLAN 4094 is provisioned in firmware 6.61, it must be removed prior to backrevving to firmware 6.42 as VLAN 4094 is not supported in release 6.42. Failure to remove VLAN 4094 could potentially cause issues loading certain Layer 3 parameters.

As a best practice, Extreme Networks recommends that prior to upgrading or downgrading the firmware on your switch, you save the existing working configuration of the system by using the show config outfile <filename> command. Please note that you will need a copy of your previous configuration if you need to back-rev from 6.42.xx.xxxx to the previous firmware version.

The G3 most likely will not be shipped to you pre-configured with the latest version of software. It is strongly recommended that you upgrade to the latest firmware version BEFORE deploying any new switches. Please refer to <http://support.extremenetworks.com/> for the latest firmware updates to the G-Series and follow the TFTP download instructions that are included in your *G-Series CLI Reference* and the *Fixed Switch Configuration Guide*.

Soft copies of the *G-Series CLI Reference* and the *Fixed Switch Configuration Guide* are available at no cost on the Enterasys Networks web site, <http://support.extremenetworks.com/>

Please refer to <http://support.extremenetworks.com/> under the “Firmware” tab to view information on changes previous to the release information listed in this document.

Policy Capacities

Policy roles (profiles) per system	31
Number of users per port	Tunnel Mode = 8, Policy Mode = 8, Hybrid Mode = 8
Number of unique rules per system	1536
L3/L4 rules	1024
EtherType rules	256
MAC rules	256
Number of rules per single role	250
Number of masks	No Limit
COS rate limiting (IRL)	Yes
Role-based rate limiting	Yes
Rule-based rate limiting	No
Priority-based rate limiting	No
Fixed rule precedence	Yes
VLAN to policy mapping**	Assign VLAN traffic to use a specific policy
Rule Types	
EtherType*	VLAN/cos/drop/forward***
MAC dest / MAC source	Cos/drop/forward
IP Protocol	Cos/drop/forward
IP dest socket / IP source socket	Cos/drop/forward
IP TOS	Cos/drop/forward
TCP dest port / TCP source port	Cos/drop/forward
UDP dest port / UDP source port	Cos/drop/forward
ICMP Type	No

* The EtherType to VLAN mapping rule is supported only when ‘numusers’ (number of users allowed to authenticate on a port) is set to 1.

** The VLAN to policy mapping rule is supported only when ‘numusers’ (number of users allowed to authenticate on a port) is set to 2 or greater.

*** When configuring EtherType to VLAN rules, there is a maximum of 7 VLAN rules per profile.

Router Capacities

Feature	Capacity
ARP Dynamic	4072
ARP Static	512 (shared with Dynamic)
Route Table	2500
OSPF Areas	4
OSPF Neighbors	400 – 128 per interface
Total OSPF LSA Type	2500
OSPF LSA Type 1 – Router Links	No restriction can equal 2500
OSPF LSA Type 2 – Networks Links	No restriction can equal 2500
OSPF LSA Type 3 – Summary Networks	No restriction can equal 2500
OSPF LSA Type 4 – Summary ASBRs	No restriction can equal 2500
OSPF LSA Type 5 – AS External Links	No restriction can equal 2500
OSPF LSA Type 7 – NSSA External Links	No restriction can equal 2500
OSPF LSA Type 9 – Opaque Subnet-only	Not Supported
OSPF LSA Type 10 – Opaque Area	Not Supported
OSPF LSA Type 11 – Opaque AS	Not Supported
OSPF ECMP Paths	4
Static Routes	64
RIP Routes	2500
IP Interfaces	24
Secondary IP addresses per Interface	31
VRRP Interfaces	20
IP Helper Address	6 per interface
Access Rules (inbound only)	100
Access Rules – Per ACL	20 per list – 60 total per interface
IGMP Groups	256
DVMRP Routes	256

sFlow Capacities

Feature	Capacity
Number of sFlow pollers	unlimited
Number of sFlow samplers	32

FIRMWARE CHANGES AND ENHANCEMENTS:**Changes and Enhancements in 6.61.16.0002**

19644 Corrected an issue in port mac locking that could result in a ""nim_events.c(213)" reset event
19511 Corrected a potential loss of management and eventual reset condition seen when monitoring the etsysResourceUtilizationMIB.
19608 Corrected a potential reset condition when attempting to save a prompt ("set prompt"), of 50 or more characters.
19568 The previous resolution to this issue was not complete if Cisco CDP is being used.
19650 Corrected a reset issue that can occur when an IP helper address is configured for the same subnet as the interface it is added to.
19649 Corrected an issue in the display of radius server configuration that could erroneously be detected as a configuration change.
19656 Corrected a memory utilization issue with RW user accounts that resulted in the message "System memory is too low to complete new cli tree operation".
19652 Corrected an issue with processing LLDP packets that could result in a reset with the message " Last switch reset was caused by buff.c(546):"
19643 Corrected a reset condition resulting in the message "dot1s_task(0xac24038) + broad_l3_mcast.(2766):Error 0xFFFFFFFF".
19320 Corrected an issue where the SNMP server table is restored in reverse order from entry Configuration.

Changes and Enhancements in 6.61.15.0003

19568 Extreme Summit and BlackDiamond platforms may use a single source MAC address for protocol and host generated packets. Previously, If redundant connections were made to these devices without the use of a link aggregation, the MAC address might be learned on a port in a blocking state. This would result in the loss of connectivity to their host IP address.
19553 Corrected a potential reset condition when processing jumbo 802.1x and 802.1s control frames
19484 Corrected a logic error with handling of an apostrophe as the second character of a system login. This error previously resulted in the incorrect storage of the password.
19588 Corrected a reset issue in the LLDP application, which produced the log entry, "reset caused by buff.c(546)"
19557 Corrected an issue where LC-04 and LC-05 MGBICs are recognized properly but will not provide link.
18590 Addressed an issue in the IGMP snooping application that could result in a reset with the error message, "nim_events.c(213): Error code 0x0000BADD"
19528 Corrected an issue in the TFTP application that may have resulted in corrupted file transfers.
19450 Corrected an issue in the output of the "show vlan portinfo vlan" command, where some egress ports may not be displayed.
19581 Addressed an issue in host packet processing that could result in a reset with the error message, "edb_bxs.c(1314) 286 %% Last switch reset caused by Fault(0x00000E00) SRR0(0x01554000)"
19583 Corrected a memory loss issue in SNMP trap processing that could result in a reset.
19579 Corrected an issue where the "set length" command was not persistent.

Changes and Enhancements in 6.61.15.0003

19565 Added support for the Accelink-WTD RTX226-440-C71 XFP-ER

19586 Corrected an issue where the snmpEngineTime (1.3.6.1.6.3.10.2.1.3) MIB value rolled over after 497 days of system uptime instead of the maximum allowed 24855 days.

Changes and Enhancements in 6.61.14.0006

Modified Spanning Tree loop protect behavior to disable a protected port when in a state where multiple BPDU sources have been detected.

19379 Corrected an issue where the G3 would erroneously report power supply temperature exceeded ("Power Supply 1 temperature has exceeded the upper threshold").

19440 Updated MIB to support new 10G ifMauTypes found in RFC 3636.

19534 Corrected an SNMP issue within the ctChasPowerTable where power supply redundancy may be incorrectly returned.

19267 Corrected an issue that could prevent SFPs from linking on bootup if auto-negotiation is disabled.

19276 Corrected an issue where ports could erroneously be removed from link aggregations. This could result in users MAC addresses being learned on incorrect ports.

19332 Corrected a reset issue in the SNMP Task that resulted in the message "edb_bxs.c(1314) 73 %% Last switch reset caused by Fault(0x00000300) SRR0(0x01104270) ESR(0x00800000) MSR(0x00000200) DEAR(0x0000000C) IMISS(0x01104270)".

19377 Corrected an issue that prevented the disabling of an admin login account from being persistent.

19334 Corrected a potential reset condition that resulted in the message "Task IGMP(0xc73a978) is suspended with error 2"

19241 Corrected an issue where erroneous POE traps "etsysPseChassisPowerNonRedundant" and "etsysPseChassisPowerRedundant" were transmitted.

19318 Corrected an issue where the "set length" command was not persistent.

19366 Corrected an issue where the output of "show lldp port remote-info" was missing remote-info POE Device-Type information.

19372 Added support for the ability to separately configure RADIUS and RADIUS accounting parameters.

19282 Corrected an issue that could cause the CLI to lock.

19437 Corrected a reset issue concerning the LLDP POE tx-tlv option which resulted in the message "NIM G3 reset 0x0000BADD caused by nim_t:Task ID:0x0a6dcd20".

19434 Corrected a reset issue which resulted in the message "Nim_T reset due to TASK 0x0a758ec0"

19383 Corrected a potential method of corrupting the startup configuration file. This may previously have resulted in the continuous rebooting of the system on power up.

Changes and Enhancements in 6.61.13.0006

18907 Corrected an issue that prevented clearing SNMP community name public, using the NetSight Configuration Template.

19300 Corrected a message queuing issue with the resulting log entry, "RADIUS: Msg Queue is full! Event".

19305 Corrected an issue where the LLDP protocol was not processed on unauthenticated ports.

Changes and Enhancements in 6.61.13.0006
18777 Corrected an issue with internal packet priority of that caused delayed or missed user authentication.
19196 Addressed an issue which allowed corrupted DHCP packets, to be looped back on dhcpsnooping trusted ports.
18907 Corrected an issue that prevented clearing the SNMP community name public using NetSight.
18587 Corrected an issue where SSH sessions were misidentified as Telnet sessions, in syslog messages.
19288 Corrected an issue that prevented Cisco Voice Gateway dot1x authentication.
19271 Corrected a potential reset "Fault(0x0000D00)", caused by a memory leak in SNMP processing.
19287 Corrected a reset condition generated when an invalid index was used in the CTRON chassis MIB.
18095 Corrected a message queuing issue that may have caused loss of management or loss of ospf adjacency, with the resulting log entry, "timer.c(995) 4278 %% XX_Call() failure in _checkTimers".
19257 Corrected an issue with Policy CoS rate limiter implementation that could cause loss of Spanning Tree BPDUs.
18943 Corrected an issue with MGBIC-LC04 support, that may have resulted in the failure to link on system boot.
18499 Corrected an issue that prevented identification of Avago MGBIC-LC04s.
18870 Corrected a potential reset condition in the "snoopTask" task, which produced the log entry, "sal.c(1197): Error code 0x00000000".
18880 Corrected an issue where Initiating a Secure Copy (SCP) file transfer could result in loss of management.
18990 Corrected an issue where the Spanguard application will lock a port on receiving an LLDP packet with a destination MAC of 01:80:C2:00:00:00.
19249 Modified the logging behavior of SNTP to prevent excessive changed system time messages, "sntp_client.c(2109) 62 %% SNTP has changed system time".
16086 Attempt to recover from a L2 table DMA error that previously resulted in a reset with a log entry of: "soc_l2x_thread DMA failed too many times". On an L2 Table DMA failure we will now walk the table to find the corrupted entry and remove it. The expected warning message is: "warning soc_l2x_thread: Bad L2 table entry found. Recovering".
19163 Corrected a potential reset condition in the "ipMapForwardingTask" task, which produced the log entry, "sal.c(1184): Error code 0x00000000".

Changes and Enhancements in 6.61.12.0005
19033 Corrected an issue in TACACS command accounting, where the receipt of an unknown TACAC reply packet caused the CLI to become unresponsive.
19076 Modified the SNTP protocol to insure that the UDP source port will not be equal to the UDP destination port.
18793 Patched updates to SSH to address the following Common Vulnerabilities and Exposures (CVEs): CVE-2006-4925, CVE-2012-0814, and CVE-2008-1657. Note: Scan tools that report potential vulnerabilities based on SSH version may still report these CVEs.
18789 Corrected an issue with recognition of 10GB-SR-SFP transceivers.
18455 Addressed an issue in the SSH application that could result in a reset with the error message, "Fault (0x00000E00) Task EDB BXS".

Changes and Enhancements in 6.61.12.0005

18490 Corrected an issue in Spanning Tree Loop Protection on aggregated ports, which could cause the port to inadvertently become locked.

18711 Addressed an issue in the IGMP application that could result in a reset with the error message, "nim_events.c(216) 593 %% NIM: Timeout event(UP) on unit(1) slot(0) port(46)(intIfNum(46)) for components(IGMP_SNOOPING)"

18861 Added support for the ctAliasEntryClearAll object of the Ctron Alias MIB.

18864 Corrected an issue with timed resets, where the current configuration would be saved automatically even if the SNMP persistmode was set to manual.

18891 Corrected an issue in the output of "Show spantree stats active", which displayed the incorrect role for the physical ports that are currently a member of an aggregation.

18928 Corrected an issue that prevented more than 1024 ARP cache entries from being displayed in the CLI when paginating.

18931 Syslog messages will now be generated on SNMP user authentication failure.

Changes and Enhancements in 6.61.11.0006

18676 Corrected potential continuous reboot condition when supporting 8 XFPs simultaneously.

18691 Corrected an issue in the implementation of the Enterasys Resource Utilization MIB, where setting etsysResource1minThreshold to zero, did not prevent etsysResourceLoad1minThresholdExceeded notifications.

18761 Corrected an issue where etsysMACLockingMACViolation traps could erroneously be generated.

18747 Corrected an issue with support for MGBIC-LC04 which could cause failure to link on boot up.

18466 Corrected one potential cause of a reset that would result in the error message "reset caused by prefix.c(1941): Error code 0x00000000 IGMP".

Changes and Enhancements in 6.61.10.0008

18584 Addressed an issue in MAC Locking application that could result in a reset with the error message, "nim_events.c(213): Error code 0x0000BADD"

18569 Corrected an issue with the interaction of MAC Locking and 802.1x, which could prevent client network access.

17978 Corrected an issue with TACACS+ management authentication, where local authentication was not allowed when TACACS+ server was unreachable.

18383 Addressed a reset memory corruption issue that could result in a system reset.

18468 Modified the IP helper application to allow forwarding of packets with a TTL=1. This previously prevented one IP Phone vendor's bootp requests from being forwarded.

18483 Corrected an issue with the "show reset" command which prevented the display of scheduled resets.

18494 Corrected an issue with the MIB object etsysConfigMgmtChangeDelayTime that prevented the use of scheduled resets.

18550 Added password support for the "!" character. Previously its use would result in an additional space being added to the end of the password string on reset.

Changes and Enhancements in 6.61.10.0008

18596 The "clear snmp community <name>" command will now remove the community name when using the encrypted community name. The command will not work without specifying one or the other.

18629 Corrected a potential reset condition in the creation of a VRRP VRID, that would result in the error message, "Task VRRPdaemon(0xba4c860) is suspended with error 1, creating file sysDmp8J".

18648 Addressed Cert Vulnerability Note VU#229804, where an invalid Open Shortest Path First (OSPF) LSA erases neighboring route tables.

18421 Corrected an issue where the Policy application allowed 802.1x supplicant EAP packets to be leaked to other ports.

Changes and Enhancements in 6.61.09.0012

16073 Adjusted the priority of packets destined to the IPv4 address of loopback interface 1 (if configured), to increase the ability to maintain management when there is large volumes for traffic trapped to the host CPU.

16911 Corrected the output of the "show logging default" command to display the correct severity value.

18449 Corrected the timestamp of Radius Accounting packets to account for daylight savings.

17297 Addressed a potential SSH session lockup when attempting to perform a "show support" command.

18000 Addressed high CPU utilization resulting from shutting down a routed SNTP interface.

18009 Corrected an issue where IGMP query packets were not processed by IGMP unless IGMP Snooping was also configured.

17263 Corrected the format of lldpStatsRemTablesInserts in the LLDP MIB.

17116 Corrected the inability to append to a configuration file that has flow control disabled.

17957 Addressed an issue where a port could stop learning MAC addresses if the policy mactable response set to both (i.e. Hybrid authentication mode).

18012 Added support for the etsysRadiusAcctClientMIB

18103 Corrected an issue where removing an IP Helper address from one interface prevented its use globally.

18194 Corrected the inability to access the network from a port in "force-auth", with multiauth mode set to strict, and maclocking firstarrival set to 1.

18231 Corrected an issue where the VLAN returned by RADIUS as a result of an RFC 3580 VLAN Authorization, fails to be applied to the user, when the MultiAuth mode is strict.

18275 Packets with an invalid destination mac address (All zero's) are now dropped.

18281 Corrected an issue where "sys-des" option was not persistent in LLDP commands.

18330 Corrected an issue that could result in the message "sysnet_util.c(802) 153 %% Out of system buffers", when running with VRRP enabled.

18369 Corrected an issue where Dynamic ARP Inspection (DAI) was not functioning on VLAN authenticated ports.

18378 Corrected an issue with the Spanning Tree Diagnostic MIB, which prevented operation with NetSight flexviews.

18396 Corrected an issue with 10G ports configured with auto-negotiation disabled, which prevented forwarding after system reset.

18432 Corrected an issue that resulted in the message "Policy_dist: Mac-vlan error adding macAuth user", and prevented adding the authenticating users VLAN attribute from being applied correctly to hardware.

Changes and Enhancements in 6.61.09.0012

18458 Corrected an issue where enabling MSCHAPv2 for management authentication, prevented user authentication via RADIUS.

18461 Corrected a display issue where “show multiauth session”, still showed MAC authenticated users, when the port was down.

Changes and Enhancements in 6.61.08.0013

16442 Corrected an issue with DHCP relay agent that could prevent completion of the DHCP process.

16911 Corrected incorrect values displayed in the output of the “show logging default” command.

17038 Corrected an issue with failing to timeout TACACS+ transactions. Loss of contact with the TACACS server could have resulted in loss of switch management.

17046 Addressed potential loss of configuration when upgrading image from 6.03.xx

17081 Adapted disputed BPDU algorithm to support Cisco 2950 MSTP/RSTP behavior, which previously prevented spanning tree convergence.

17175 Corrected an issue where “set pause disable” would disable a 10Gb (tg) port.

17497 The timing of a reset configured by the "reset at" command now takes into account the offset configured through the “set summertime enable” command.

17874 Host generated OSPF PDUs are now tagged to priority 6 when egressing tagged. Previously priority 0 was used. These packets may have been dropped at the lower priority.

18021 Corrected an issue with enabling VLAN authenticated, Wake-On-LAN devices.

17949 Corrected a display issue with the “show mac port” command being case sensitive.

17884 The output of the "show port status" command displayed the an MGBIC-08 as 1000-lx. It is now displayed as 1000-lx/lh.

17137 The output of the "show port status" command displayed an MGBIC-LC03 as 1000-sx. It is now displayed as 1000-lx/lhmm.

17875 Addressed a VLAN egress issue where a port’s statically applied egress could be cleared by removal of policy applied egress.

17797 Addressed a display issue with output of “show spantree nonforwardingreason” so it accurately reports the non-forwarding reason.

17717 Corrected an issue where “show config outfile” would display corrupted file names, when TACACS was used to authenticate the command.

17673 Corrected an issue with calculating policy profile use counts. Previously the output of “show policy profile all”, could incorrectly display an applied profile as not as being in use.

17498 Corrected an issue with the processing of large LLDP PDUs that previously resulted in a system reset.

17485 Corrected an issue in TACACS+ authentication that could hang SSH and Telnet sessions.

17482 Added SNMP support for ifdescr (1.3.6.1.2.1.2.2.1.2) for SFP ports. Previously Netsight shows installed MGBIC-BX## as not installed.

17479 Resolved an issue with link up/down messages not displaying on the local console.

17478 Corrected an issue with memory utilization associated with saving configuration files. This issue could cause memory exhaustion and result in a reset.

Changes and Enhancements in 6.61.08.0013

17286 Corrected an issue with VLAN Authorization (RFC 3580), where RADIUS VLANID tunnel attributes greater than 999 were not accepted.

18129 Corrected an issue with archiving configurations using NetSight Inventory Manager

18198 With the introduction of IPv6 ACLs, Policy and ACLs were prevented from being configured simultaneously. Policy configuration is now prevented only in "ipv6mode". These features use the same hardware resources and administrators are not guaranteed to reach published resource limits.

Changes and Enhancements in 6.61.07.0010

15668/16748/17266 Addressed an issue with IGMP snooping which resulted in loss of management with error "MRT: assertion (0) failed at line 1893 file ../../../../src/application/ip_mcast/vendor/igmp2/prefix.c error at an aprox rate of 10 entries/s" or "edb_bxs.c(1226) 110 %% Last switch reset caused by prefix.c(1941): Error code 0x00000000, after xx second".

16602 Addressed a RADIUS authentication issue which could cause a reset with error "edb_bxs.c(1226) 204 %% Last switch reset caused by Fault(0x00000e00) SRR0(0x00e9d490) ESR(0x00000000) MSR(0x00001200) DEAR(0x31303203) IMISS(0x00e9d490)" while processing a RADIUS response packet.

16742 Fixed a semaphore deadlock in POE with the following error "broad_poe.c(5001) 182 % PoE timeout while in reset and recovery mode".

16864 Resolved an issue associated with SNMP configuration with error at boot up "The following commands in "startup-config.cfg" failed:".

16974 The "show ip ospf interface" command output now includes information for OSPF loopback interfaces.

17017/17027 Resolved a code exception in SNMP task with reset "BOOT[141143864]: edb_bxs.c(1226) 108 %% Last switch reset caused by Fault(0x00001100) SRR0(0x01162ae8) SRR1(0x4000b030) MSR(0x00001030) DMISS(0xc914d6d0) IMISS(0x00000000)".

17035 Addressed an issue with Service ACLs which could cause the switch to block SNTP packets. This fix will allow users to configure the SNTP service type and define PERMIT/DENY rules for SNTP traffic.

17124 Addressed an issue whereby setting a lengthy login banner when TACACS+ was enabled caused an exception and reset "Fault(0x00000300) SRR0(0x00e6e83c) SRR1(0x2000b032) MSR(0x00001030) DMISS(0x2000b032) IMISS(0x00000000)".

17134 Device config no longer displays "passive-interface vlan" for each configured interface when "passive-interface default" command was entered.

17203 The "show port status" output now displays correct SFP type for Avago AFBR-5715PZ transceivers.

17215 Addressed a platform related issue which prevented the switch to generate syslog entry and SNMP trap messages for temperature changes.

17256 Addressed a reset associated with issuing the "clear snmp community" command when the switch security mode was set to c2.

17362 & 17619 Addressed an issue which prevented DHCP to function properly on trusted ports when DHCP snooping was enabled.

17530 & 17773 Addressed an issue in LLDP with reset and error similar to "Last switch reset caused by Fault(0x00001100) SRR0(0x0126BB0C) SRR1(0x4002B030) DMISS(0x19DFE888) IMISS(0x00000000) DAR(0x00000000) DSISR(0x00000000)".

Changes and Enhancements in 6.61.06.0009
To increase the ability to detect memory corruption, protected code space has been created. Any attempt to overwrite operation code space results in an exception that logs the location of the offending operation and resets the switch.
A hardware based watchdog timer has been enabled to increase error recoverability. If the switch enters a hung state where it no longer services the timer, the watchdog will reset the switch without manual interaction.
4616 With this release we have added support for the Interface Name and System Description optional data tuples to CDP.
9783 Added the "all <port#>" option to the "clear maclock" command to clear static maclock entries on a single or range of ports.
14359 Corrected an issue whereby the "show rmon stats" command output displayed incorrect value for oversized packet counters.
14938 Corrected an issue whereby under certain circumstances the SNMP client could stop processing requests.
15192 Resolved an issue whereby the ifTableLastChange MIB object (1.3.6.1.4.1.9.9.27) returned incorrect data.
15997/17051/17117 Addressed an issue whereby IGMP group membership reports were erroneously flooded across the associated VLAN. This could potentially interrupt multicast traffic such as FOG to some clients.
16330 Resolved a CLI issue which caused mdi and mdix strings to be interchanged in "show port mdix all" and "show config port" output. This resulted in the wrong cable type connection to be displayed.
16354 When authenticating a user on an auth-opt port and using RFC3580 dynamic VLAN assignment, the port may get into a state where users are no longer able to authenticate on the port. This has been resolved.
16376 DHCP discovery packets are now serviced at a higher priority COS queue. Previously DHCP requests were dropped when L2 multicast traffic was switched at high rate to the host.
16411 Corrected the OID value for chHotTemp object (. 1.3.6.1.4.1.52.11004) in the xtraps MIB group. This issue only affected SNMPv2 and v3.
16421 Power LEDs now correctly display the switch's power mode if a second power supply is inserted during the boot sequence.
16488 Addressed an issue with configuring Ether type policy rules via Netsight Policy Manager. Out of range values were accepted and the resulting classification rules could not be removed via the CLI.
16521 Addressed an issue with Syslog message format by removing extra spaces between timestamp and host's IP address.
16591 Addressed a policy issue whereby deny actions were assigned higher precedence over permit rules. This caused a deny-all policy at the role level to disregard subsequent permit rules and drop all inbound traffic to the port.
16630 Resolved an issue whereby continuous SSH sessions to the switch caused the session to hang. Telnet, console and SNMP management were unaffected.
16639 Addressed an issue which could remove static DHCP binding for a client's MAC address when the client renewed its DHCP lease.
16647 Corrected an issue with IGMP snooping which caused multicast traffic to flood out ports once the IGMP group membership interval time expired.
16750 Resolved an issue with the "set policy rule < profile-index > ipdestsocket "command whereby policy was applied to traffic which did not match the specified destination IP address. This resulted in packet loss due to erroneous traffic classification.

Changes and Enhancements in 6.61.06.0009

16778 Addressed an issue where user defined passwords with embedded spaces revert to default settings upon reboot. As best practice, password strings containing spaces should be enclosed in quotes.

16997 Addressed an issue which prevented users to define password strings starting with "!".

17009 Addressed an issue associated with the command line parsing buffer which prevented service-ACLs to be displayed in certain show command outputs. This issue was seen when screen length was set to a non-zero value.

17032 The MGBIC-LC05 will now link-up when auto-negotiation is enabled.

17048 Resolved a code exception in SNMPTask with reset "BOOT[141143864]: edb_bxs.c(1226) 108 %% Last switch reset caused by Fault(0x00001100) SRR0(0x01162ae8) SRR1(0x4000b030) MSR(0x00001030) DMISS(0xc914d6d0) IMISS(0x00000000)".

17083 Addressed an issue whereby logging to the switch via webview could cause a reset with a message similar to "edb_bxs_api.c(786) 202 %% Last switch reset caused by Fault(0x00000300) SRR0(0x01113A40) SRR1(0x0000B030) DMISS(0x13350104) IMISS(0x00000000) DAR(0x00000000) DSISR(0x0A000000)".

17120 Removed informational debug messages similar to "SIM[88867688]: broad_hpc_drv.c(2686) 19017 % bcm_port_update: u=0 p=20 link=1 rv=-15" from the CLI output.

17130 The MGBIC-BX120 SFP transceiver modules are now supported in CLI display output.

17149 If a login banner is configured on the switch and a console cable is attached, no response is sent to the screen when the <enter> key is hit. This has been addressed.

Changes and Enhancements in 6.61.05.0009

17069 Resolved an issue which could prevent PoE delivery to some ports following an upgrade to firmware 6.61.02 or 6.61.03.

17073 The bootrom is now upgraded ONLY on a system reboot following a firmware upgrade. This addressed an issue which could prevent units from booting up after upgrade to firmware 6.61.02 or 6.61.03.

Changes and Enhancements in 6.61.03.0004

16951 Addressed an issue with hybrid policy authentication in which the authenticated user's MAC address was not learned.

16958 Addressed an issue with the TCP MIB in which a continuous GetNext on the tcpListenerProcess OID would loop.

16982 Addressed an issue with high CPU utilization when setting an SNTP interface to an interface that is not up.

16993 Addressed a reset condition when large numbers of VLAN egress rules are pushed from policy manager.

Changes and Enhancements in 6.61.02.0007

13946 Addressed an issue which prevented GVRP from automatically propagating VLANs assigned to ports via vlan authentication.

15007 Corrected a port MAC layer communication issue that resulted in the logging of a "bcm_port_update failed: Operation failed" message.

Changes and Enhancements in 6.61.02.0007

15974 Resolved a buffer allocation issue which could cause the switch to stop generating console and syslog messages.
16041 Addressed an issue associated with transmit queue monitoring whereby an oversubscribed front-panel port could potentially cause spanning tree topology change and reconvergence when flow control was enabled.
16155 Addressed a flow control issue where packet based backpressure limits were reached with packets sent to the host. This could inadvertently activate flow control on an undersubscribed uplink port.
16288 Corrected an issue where the wrong port speed was displayed for 100BASE-FX SPF ports.
16294 Addressed an issue which prevented forbidden precedence in policy to override 802.1Q VLAN egress on a port when default role and dot1q applied to the same VLAN. Additionally, the precedence order was corrected to "Forbidden", "Untagged" and "Tagged".
16343 Addressed an issue where the EEPROM value was not properly read for the combo SFP slots in a G3G170 switch.
16486 Addressed a CLI display issue with Transmit Queue Monitoring which could cause oversubscribed ports to appear stalled when flow control was engaged.
16815 Resolved a multiauth issue which prevented a user to authenticate via multiple authentication methods using the same vlan assignment.
16826 Corrected an issue which prevented Service ACLs to work over routed interfaces.

Changes and Enhancements in 6.42.11.0006

14077 & 16236 Addressed an issue which resulted in high CPU utilization when the switch received Kiss-o'-death packets from an SNTP server.
16067 Addressed an issue whereby the following CLI messages were scrolled continuously on the console "SIM[149535472]: timer.c(995) 1001 %% XX_Call() failure in _checkTimers for queue 0 thread 0xfc8ad00. A timer has fired but the message queue that holds the event has filled".
16135 Addressed a buffer management issue which limited the number of LLDP-MED endpoint connections to the switch. Previously only 6 connections were allowed.
16157 Addressed an issue which caused LAG ports to enter Ingress Back Pressure (IBP). This issue could cause LACP and STP BPDU control packets to be dropped when oversubscribing a LAG with Flow Control (FC) disabled.
16253 Addressed an issue associated with OSPF which could cause the default route to be removed from the routing table. In some cases issuing the "clear ip ospf process" command could result in a reset with the following error "Assertion failed: er == E_OK, file ../src/application/routing/protocol/ospf/sprdx.c, line 797".
16291 Corrected an issue with the LLDP service routine which prevented LLDP-MED endpoints to register with the switch after a warm boot. This issue was not seen when the switch was cold started.

Changes and Enhancements in 6.42.10.0016

15593 Addressed an issue associated with LLDP and LLDP-MED which resulted in a reset with an exception message in the lldpXMedRemCapCurrentGet task.
15599 Addressed an issue where an extra line was inserted in the CLI output display. This was seen when screen length was set to non-default and ENTER was pressed to advance the output one line at a time.
15874 The "clear dhcp conflict logging" CLI command now disables DHCP conflict logging.
15876 Addressed an issue where login authentication failed to switch from SSH to local when the RADIUS server was unreachable.

Changes and Enhancements in 6.42.10.0016

15893 Resolved an issue whereby the member of a single-port LAG was not properly added to the egress list of the LAG's VLAN if the port was down while the LAG was being configured.
15916 Resolved an issue whereby RMON failed to capture packets when capture type in the channel entry was set to "failed".
15933 Corrected an issue in CDP which could result in an error "NIM[164832176]: nim_intf_map_api.c(420) 1083 % internal interface number 21021 out of range" when the "show neighbors" command was executed.
15983 Addressed an issue with unlocking MAC addresses in a MAC locked port after a link down. This issue prevented locking the first MAC arriving on a port after a link up when the first arrival value was set to 1.
16039 Addressed an issue whereby sFlow datagrams were transmitted with invalid packet type when selectable management was configured.
16077 Addressed a system hang and reset which was accompanied by messages similar to "broad_hpc_drv.c(2689) 30 %% _soc_xgs3_mem_dma: L2_ENTRY.ipipe0 failed(NAK), unit 1" and "hwutils.c(4178) 39 %% MPC85xx DMA/PCI register dump".
16089 Addressed an issue whereby client RADIUS requests were sent to all configured RADIUS servers even when the primary server was reachable.
16107 Addressed an issue where DAI was silently dropping ARP packets which exceeded 64 bytes in size. This resulted in loss of contact with some devices such as Cisco Analog Telephone Adaptor (ATA) products when DAI was enabled.

Changes and Enhancements in 6.42.09.0005

6672 The "clear spantree adminpathcost" CLI command now works when using wildcards for the port-string option field.
13573 Corrected a memory access issue associated with SSH which could potentially result in a device reset. This issue was previously seen when using SFTP to transfer files to an OpenSSH 3.8p1 server.
14359 Corrected an issue whereby the "show rmon stats" command output displayed incorrect value for oversized packet counters.
14494 Corrected an issue associated with RSTP which prevented the alternate port from failing over to the root bridge when the root port failed.
14796 Addressed an issue where setting the CLI screen length to a non-zero value could cause the "clear snmp" command to not appear in the "show config" output.
14910 Addressed an issue where the "set port advertise" command was removed from the config following an upgrade to firmware 6.42.
14989 Addressed a CLI issue which could potentially cause a reset when the output of the "show config" command exceeded 9K lines.
15052 Resolved an issue whereby the "show lldp port remote-info" command would not display the correct POE Power source of remote devices.
15054 Resolved an issue whereby the switch would flood unicast DHCP release packets across the VLAN when the path to the network DHCP server was known.
15177 Corrected an issue where uploading a file to a Secure Copy (SCP) server could potentially cause a CLI session lockup and reset with the following errors "0x8798140 (TransferTask): task 0x8798140 has had a failure and has been stopped" and "0x8798140 (TransferTask): fatal kernel task-level exception!".
15189 With this release UDP ports 7700 and 7800 are no longer used during the TFTP image download operation.
15196 Users are no longer required to enable IPv6 administrative mode to configure an IPv6 gateway address for the host interface.

Changes and Enhancements in 6.42.09.0005

15224 Resolved a display issue associated with the “show neighbors” command where the device ID in the Cisco DP neighbor discovery field was truncated.

15246 Addressed an issue with the “set snmp group” command where group names delimited by spaces were not saved in config correctly.

15297 Addressed an issue associated with the switch port state machine which could potentially cause device ports to lockup.

15308 Resolved an issue which could prevent Spanning Tree from failing over to the alternate port after multiple failovers when automatic edge port detection was disabled on edge ports.

15315 Resolved a problem where the “show vlan portinfo vlan” command displayed port information for all configured VLANs not just the one specified in the command.

15400 Addressed a persistency issue associated with the “set radius server” command when the specified server secret password started with the exclamation mark (!).

15550 Addressed an issue where the etsysMACLocking traps were generated with incorrect MIB object name causing them to appear as Enterprise Specific traps.

15584 Resolved an issue where the etsysResourceProcessName (1.3.6.1.4.1.5624.1.2.49.1.2.1.1.2) MIB in etsysResourceUtilizationMIB module returned an incorrect process name.

15596 Addressed an issue where the Multiauth numusers value was set to default if the policy mactable response type was changed; consequently all instances of “set multiauth port numusers” command were removed from the config.

15841 Addressed an issue where the user defined MDI/MDIX mode was reversed when issuing the "Set port mdix" command.

15848 Corrected an issue whereby users could potentially fail to send a DHCP request after being assigned a new profile. This issue was caused by a small delay in moving users to the new authenticated VLAN.

15859 Corrected an issue with the premature closure of the RADIUS UDP socket. This issue could have prevented user authentication when the server response was routed through the unit and was not received from the RADIUS server within 1 second.

Changes and Enhancements in 6.42.08.0007

14716/15019/15350/15357 Addressed a DHCP snooping issue whereby DHCP packets forwarded over LAG ports to the CPU were sent back to the source causing a loop and high CPU utilization.

15711 Resolved an issue whereby connecting a Redundant Power Supply (RPS) to an operational switch could cause loss of PoE power delivery to attached devices.

Changes and Enhancements in 6.42.07.0010

15348 Addressed a user connectivity issue where a user could internally be learned on a Spanning Tree discarding port, if an IGMP message sourced by the user is seen on that port.

15452 Corrected an issue which could potentially prevent MAC address notification traps from being generated and cause a CLI lockup.

Changes and Enhancements in 6.42.06.0008

13100 Resolved an issue whereby executing the “show config outfile” command followed by “show support” could cause a device reset.

14582 Corrected a formatting issue associated with the "show dhcpsnooping port" command output display.

Changes and Enhancements in 6.42.06.0008

14639	The "movemanagement" command is now supported over SSH sessions.
14733	When upgrading from firmware 1.02.05 to higher revisions, the port inlinepower admin state will now persist when preceded by the "set port inlinepower admin off" command in the config file.
14776	Corrected an issue whereby read-write and read-only SSH users were unable to log back onto the switch once locked out.
14817	Resolved an issue whereby SNMPv3 inform requests were not sent when the device was in router mode.
14903	Corrected an issue whereby the egress ports on GVRP-generated VLANs were removed after LACP was disabled on the associated LAG port.
14954 & 15182	Addressed an issue which could affect re-learning the ARP table on a switched interface after issuing the "clear arp-cache" command.
15013	Addressed a potential TCP vulnerability identified in US-CERT VU#723308.
15060	Cisco discovery protocol announcements now contain the IP address of the routed interface on which the PDUs are sent.
15084	With this release the output of "show txqmonitor" and "show txqmonitor flowcontrol" commands are now gathered in the "show support" CLI command.

Changes and Enhancements in 6.42.05.0001

15171	Corrected an issue with the premature closure of the RADIUS UDP socket. This issue could have prevented user authentication in cases where a response was not received from the RADIUS server within 1 second.
-------	--

Changes and Enhancements in 6.42.03.0004

13278	Resolved an SSH issue which prevented users from logging onto the switch using the Ponderosa SSH Client application.
13979	Resolved a Multiauth issue whereby the switch continued to send MAC authentication requests after the supplicant successfully authenticated via 802.1X, which could potentially cause a reset.
14224	Authenticated users that remained quiet for periods of time after authenticating failed to reauthenticate once the session timed out. This has been corrected.
14447	Monitoring SSH sessions to the switch via the Xymon Monitor (aka hobbitmon) bbtest-net program will no longer cause the sessions to hang.
14487	Resolved an OSPF issue whereby changing the interface path cost caused the system to generate incorrect route table entry and next hop address.
14567	The "show vlan portinfo" command output now displays the correct egress list. This was only a display issue on dynamic VLANs.
14739	The LLDP auto-negotiation TLV definition now advertises correct port capability.
14740	Resolved a problem whereby accessing the system via SSH failed with the following message "Connection refused". This issue was only seen when a device config was loaded via TFTP or NetSight Inventory Manager.
14757	sFlow Receivers are no longer persistent and will not be displayed in the running-config. Receivers can be viewed using the "show sflow receivers" command. This will prevent receiver timers from making configurations appear to change in Inventory Manager.
14921	Routed interfaces will not be enabled without egress. Policy applied egress was previously not considered in the calculation.

Changes and Enhancements in 6.42.03.0004

14926 Corrected an issue with 802.1x where a client table entry was lost with each authentication. This would eventually result in clients being unable to authenticate.

Changes and Enhancements in 6.42.02.0006

14485 Resolved an issue with loop protect whereby breaking links on a LAG could potentially stop traffic across its member ports shortly after connection was re-established.

14846 The host protect feature now properly rate limits the traffic.

14882 Upgrading from firmware 1.02 to 6.42.01 without an interim upgrade to 6.03.08 caused PoE power-delivery failures. Upgrading from firmware 1.02 to 6.42.02 does not require any interim upgrade.

14895 Corrected a reset condition when the "set system hostprotect enable" command was applied via NetSight onto a system with host protect disabled.

14900 Corrected a potential reset condition with a message similar to "edb_bxs_api.c(779) 22 %% Last switch reset caused by nim_events.c(213): Error code 0x0000badd, after 328456 second".

Changes and Enhancements in 6.42.01.0046

When upgrading PoE switches from firmware 01.02 to 6.42.01, you must first upgrade to firmware 6.03.08 then to 6.42.01.

12480 Customers are now able to see the serial number of the switch via NetSight Flexview.

12796 Resolved an issue whereby some MGBIC-LC03 LX SFP modules would display as type SX in the "show port status" command output.

12989 Resolved an issue whereby the SNTP client running in broadcast mode could potentially fail if the server was unavailable at the time client went operational.

13113 When restoring a saved configuration file, Spanning Tree settings are now loaded in correct order.

13153 Corrected an issue where loss of management could ensue when a Telnet session with an active TFTP transfer is terminated.

13367 Resolved an issue whereby login authentication via TACACS+ failed to switch over according to authentication precedence rules when the TACACS+ server was unavailable.

13392 Resolved an issue whereby static ARP entries were displayed in the configuration file after being administratively removed.

13674 Resolved an issue with IGMP snooping filters whereby the device could drop some SMB packets in transit, causing the file transfer to fail.

13792 Corrected an issue which resulted in the daylight savings times function to fail when the dates to start and stop DST spanned over a year.

13843 All configured static routes are now properly redistributed in OSPF update messages and displayed in the routing table.

13844 Resolved an issue whereby the switch could potentially respond with NAS-Port-Type RADIUS attribute of Virtual instead of Async when users attempted to login to console.

13850 The "set cdp state" command failed with the following error "Invalid range specified", when issued for a range of 10-Gigabit ports. This has been resolved.

13851 The "set length" command is now persistent after a reset.

13941 The daylight savings time function (Summer Time) now works properly when SNTP is enabled.

Changes and Enhancements in 6.42.01.0046

13943/14091/14096/14186/14199/14223 Resolved a potential memory leak associated with IP multicast which could cause a reset with a message similar to "osapi.c(1381) and broad_cpu_intf.(3086)" or "CRASH - broad_cpu_intf and hapiBroadPruneTxPorts" or "Fault(0x00001100) SRR0(0x00074ce8) SRR1(0x4002b030) MSR(0x00001030) DMISS(0x9990693a) IMISS(0x00000000)".

13980 The value of port utilization percentage is now calculated and displayed correctly in the "show rmon history" command output.

14003 Resolved an issue whereby Syslog messages were not generated for SSH login events.

14022 Corrected an issue whereby processing CDP packets which contained malformed type-length-value (TLV) tuples could potentially cause a device reset.

14034 Resolved an issue whereby configuring an IP helper address on the 24th router interface failed with the following message, "Error: VlanId is not matching with any of router interface".

14035 & 14774 802.1x supplicants now properly failover to specified backup RADIUS servers when the primary server is unavailable.

14109 Corrected an issue whereby changing the authentication precedence to an erroneous value via SNMP could disable 802.1X authentication.

14121 Resolved an issue whereby 802.1x client authentication packets were flooded out ports blocked by Spanning Tree. This resulted in supplicant authentication failures and high CPU utilization.

14136 Resolved a CLI display issue whereby the "show lldp port remote-info" and "show lldp port local-info" commands displayed incorrect device type for 1000BaseT ports.

14137 The snmpEngineTime (1.3.6.1.6.3.10.2.1.3) MIB value rolled over after 497 days of system uptime instead of the maximum allowed 24855 days. This has been fixed.

14170 Resolved an issue where the RADIUS Medium-Type Attribute failed to validate. This could potentially result in "maca_radius.c(378) 104065 %% macaRadiusAcceptProcess: invalid mediumType length 10" messages and a reset.

14258 The "clear snmp group" command is now persistent across reboots.

14260 Using the VLAN Elements Editor from the NetSight Policy Manager application to configure an access or trunk port caused the uplink to be removed from the egress list, this has been resolved. Previously this issue was reported on firmware 6.41.03.0018 and above.

14289 With this release the SNMP IF-MIB.ifHCInOctets (1.3.6.1.2.1.31.1.1.1.6) counters for LAGs have been changed from 32-bits to 64-bits.

14295 Resolved an issue which prevented accessing the device via SNMP when the management IP address was in the 172.16.0.0/16 network address range.

14342 Resolved an issue whereby 802.1x authenticated users could no longer authenticate after the port mode was changed from auto to forced authorized and back.

14469 Resolved an issue whereby DHCP relay agent stopped forwarding client's requests to the DHCP server.

14637 The SNMP group CLI commands now persist across device resets.

14665 Resolved an issue whereby disabling MAC locking globally or on any port, would terminate all authenticated sessions (MAC authentication, 802.1X, PWA) on the MAC locked port.

Changes and Enhancements in 6.03.08.0012

14629 & 14690 Resolved an issue whereby applying policy to a port with existing policy would block traffic from egressing the port.

Changes and Enhancements in 6.03.06.0008

12697	The router interface state is only affected by the EAPOL status when in strict 802.1X mode. All other times it will be based only on the VLAN egress list.
12796	Resolved an issue whereby some MGBIC-LC03 LX SFP modules would display as type SX in the "show port status" command output.
13113	When restoring a saved configuration file, Spanning Tree settings are now loaded in correct order.
13153	Corrected an issue where loss of management could ensue when a telnet session with an active TFTP transfer is terminated.
13392	Resolved an issue whereby static ARP entries were displayed in the configuration file after being administratively removed.
13422	The value of the MIB object snmpEnableAuthenTraps (1.3.6.1.2.1.11.30) is now persistent across device resets.
13674	Resolved an issue with IGMP snooping filters whereby the device could drop some SMB packets in transit, causing the file transfer to fail.
13867	Resolved an issue whereby applying a new policy role to a port caused the port's egress status to change from untagged to tagged.
13943 & 14096	Resolved a potential memory leak associated with IP multicast which could cause a reset with a message similar to "osapi.c(1381) and broad_cpu_intf.(3086)" or "CRASH - broad_cpu_intf and hapiBroadPruneTxPorts".
13980	The value of port utilization percentage is now calculated and displayed correctly in the "show rmon history" command output.
14003	Resolved an issue whereby Syslog messages were not generated for SSH login events.
14022	Corrected an issue whereby processing CDP packets which contained malformed type-length-value (TLV) tuples could potentially cause a device reset.
14034	Resolved an issue whereby configuring an IP helper address on the 24th router interface failed with the following message, "Error: VlanId is not matching with any of router interface".
14121	Resolved an issue whereby 802.1x client authentication packets were flooded out ports blocked by Spanning Tree. This resulted in supplicant authentication failures and high CPU utilization.
14295	Resolved an issue which prevented accessing the device via SNMP when the management IP address was in the 172.16.0.0/16 network address range.

Changes and Enhancements in 6.03.05.0004

12472	Resolved an issue where the switch could send duplicate ICMP response packets when the source/destination IP addresses of the ICMP request were on the same routing interface and ICMP redirect was enabled.
12606	The "show multiauth session" command now properly displays the session timeout value. Previously the CLI returned a zero for this field when the Termination-Action RADIUS attribute was set to RADIUS-Request.
12767	The Spanning Tree path cost value for LAG ports is now properly calculated.
12870	The ICMP unreachable packets generated by the switch will now be transmitted in the order in which received.
13059	Resolved an issue which could cause loss of telnet and SSH management while the console continuously displayed "ewsStringCopyIn: no net buffers available". Traffic forwarding and SNMP management were unaffected.
13157	The "clear port advertise" command now returns port settings to default values.

Changes and Enhancements in 6.03.05.0004

13224 Resolved an SNMPv3 issue which under rare conditions could cause the CLI to overwrite the “set snmp group” settings.

13238 Corrected an issue where the switch would not forward the IP helper client packets when only one DHCP relay agent was configured on the interface.

13261 Resolved an issue with the “show port egress” command where the egress information for some ports were not displayed.

13340 The SNMP Target IP address mask is now properly displayed in the “show config snmp” or “show snmp targetaddr” command outputs.

13376 All super user accounts will now be re-enabled after the system lockout timer expires. Previously only the default admin super user account was re-enabled and all other super users would remain locked out after the maximum login attempts was reached.

13470 Corrected an issue where the NAS-Port-Type RADIUS attribute for an authorized console session would change from Async to Virtual after a Telnet user successfully logged into the device.

13485 Resolved an issue where, in some rare cases, SSH users attempting to login to the switch could cause a reset if the RADIUS server returned incorrect attributes.

13540 Resolved an issue where using SCP to transfer files from a Telnet session could cause both the local console and telnet to hang. There was no issue transferring files with SCP from the console.

13620 The TACACS+ client session authorization settings will now be persistent across reboots.

13662 Resolved an issue with the TACACS+ session authorization where using non-default attributes for service level exec would not grant admin privileges to the user.

13860 Resolved an issue where the switch would not respond to SNMP management requests when the least significant digit of the NetSight server IP address was set to zero. Previously using the NetSight server address of x.x.x.0/255.255.252.0 would not work.

13892 Resolved an issue where enabling DHCP snooping on the switch could cause DHCP offer packets to be transmitted out the LAG member interfaces. This caused a packet loop leading to high CPU utilization.

14162 The WebView management application copyright date has been updated to 2010.

Changes and Enhancements in 6.03.04.0004

10874 Corrected an issue when under certain circumstances the SNTP client stopped processing requests.

11306 Resolved a CLI issue associated with save and restore of a config file which contained the “set DHCP exclude” command.

12357 Resolved an issue where multi-user-authentication failed when only one user was allowed to authenticate on a port. Previously policy was applied when the “set multiauth port numusers 2” command was issued.

12480 Customers are now able to see both the device model and serial number via Netsight Flexview.

12549 Corrected an issue where the “ip igmp enable” command was not included in the configuration without an active routing license key.

12702 Resolved an issue with the “set system login” command where the CLI accepted a password preceded with an “!” but errored out when restoring it from a saved config. Previously restoring the password caused the following message, “Error: Missing value for “password” and the user was unable to login.

12813 The switch now sends a small TFTP acknowledge packet at the completion of a successful download. Previously a 512 Byte ACK was transmitted which could potentially slow down the file transfer.

12848 Resolved an issue where link aggregation could potentially fail sometime after a LAG was formed. Previously the failure occurred when a network loop caused a participant switch to receive its own LACP PDUs.

Changes and Enhancements in 6.03.04.0004

12869 Resolved an issue where the switch could take up to 5 seconds to generate an ICMP host unreachable message when the remote host failed to reply.
12871 DHCP snooping now works on LAGs and their underlying physical ports when configured as trusted ports.
12893 Resolved an issue with sFlow where the actual packet sampling rate did not match the user defined value.
12909 Corrected an issue with the "set length" command that could prevent the display of default routes in running config. Default routes could be displayed via the "show ip route" command.
12910 Corrected an issue where multiauth users which had successfully authenticated via dot1x and macauth lost network connectivity after their static egress was administratively removed.
12951 Resolved an LACP buffering issue which could prevent traffic flow across LAGs after some time.
12960 Resolved an issue with the "show vlan portinfo" command where the VLAN egress for dot1x clients would not appear in the output.
13111 Spanning Tree settings are now restored in proper order when loaded from a saved configuration file.
13150 Static arp entries are now preserved across device resets or when interfaces change state.
13151 Resolved a display issue with the "show lldp port remote-info" command where the "Operational Speed/Duplex/Type" field reported an incorrect value.
13176 The ifMIB module now supports the ifName object (1.3.6.1.2.1.31.1.1.1.1). Previously port link up/down traps did not include the interface name.

Changes and Enhancements in 6.03.03.0008

12552 Corrected a potential memory leak associated with OSPF type-4 LSAs which could cause loss of management access via telnet, SNMP or CLI.
12635 Users can now change the TACACS+ session authorization attribute name by issuing the "set session authorization" command. Previously the default name "priv-lvl" could not be changed.
12884 Resolved a loss of management issue when using Cisco ACS version 3.3 to secure access switches using TACACS+. Previously CLI or console sessions could lock up once user name and password credentials were provided.
12897 Static route entries are now displayed in the "show running-config" command output.
12905 Resolved a RADIUS buffering issue where the switch stopped sending RADIUS request packets and reported the following error message "RADIUS: Msg Queue is full! Event: 19".
12984 & 13252 Resolved an issue where traffic forwarding through the switch either stopped or would be routed through the slow path after a VRRP failover.
13062 Added support for the TAG field of the VLAN ID string in the "Tunnel-Private-Group-ID" RADIUS tunnel authentication attribute. Previously using the TAG field caused dot1x, MAC and PWA authentication to fail with the following error message: "maca_radius.c(365) 62 %% macaRadiusAcceptProcess: TunnelPrivateGroupID0 length is greater than 4!".
13170 SSH client sessions are now consistently terminated after 3 failed attempts. Previously in some 6.03 releases when a user reached max login retries, all subsequent invalid logins were disconnected after first try.
13264 Corrected an issue which resulted in momentary loss of data shortly after users MAC authenticated. This issue did not affect dot1x clients and only occurred when a user's MAC address appeared in multiple FID entries.

Changes and Enhancements in 6.03.02.0006

12261 Resolved an issue where the switch could stop forwarding multicast streams across DVMRP enabled interfaces.
12793 Corrected an issue with the "show vlan static" command where the output would not display untagged egress ports.
12812 & 12941 Resolved an SSH issue where the client sent multiple access requests to the RADIUS server after the first request was already granted.
12823 Resolved a buffering issue which could cause loss of telnet and SSH management while the console continuously displayed "ewsStringCopyIn: no net buffers available". Traffic forwarding and SNMP management were unaffected.
12896 Corrected an issue where the host may stop responding to ARP requests causing loss of management (SNMP, telnet and SSH).

Changes and Enhancements in 6.03.01.0008

<p>Added support for the following OIDs to the CTRON-CHASSIS-MIB ctChas object:</p> <ul style="list-style-type: none"> • ctChasFNB.0 denotes the presence or absence of the FNB. • ctChasAlarmEna.0 allows an audible alarm to be either enabled or disabled. Setting this object to disable(1) will prevent an audible alarm from being heard and will also stop the sound from a current audible alarm. Setting this object to enable(2) will allow an audible alarm to be heard and will also enable the sound from a current audible alarm, if it has previously been disabled. • chassisAlarmState.0 denotes the current condition of the power supply fault detection circuit. The object value will read chassisNoFaultCondition(1) when the chassis is operating with no power faults detected and will read chassisFaultCondition(2) when the chassis is in a power fault condition.
12661 Corrected an issue with the MAU-MIB etsysMultiAuthStationClearUsers object (1.3.6.1.4.1.5624.1.2.46.1.3.1.1.3) which could prevent users from reauthenticating after they were unauthenticated.
12646 Corrected an issue where executing the "clear snmp view all 1" command followed by a "show config" could result in a reset.
12640 Corrected a dot1x issue that could result in the inability to apply policy to ports where authentication was not configured.
12585 Resolved a DMA issue which caused the following extraneous console error messages: "soc_l2x_thread: DMA failed too many times".
11683 & 12561 The "show vlan" and "show port egress" command outputs now show the VLAN egress information assigned via dynamic policy.
12560 Resolved an issue with the NMS Inventory Manager Timed Reset function which could cause devices to reset some time after the scheduled reset time.
12517 Resolved an issue whereby the switch failed to forward DHCP client messages when DHCP snooping was disabled on the associated VLAN. .
12513 The SNMP agent now uses the source IP address of the selected management interface (if specified) when generating traps.
12506 Corrected an issue with the "show support" command output when the screen length was set to greater than zero.
12499 Resolved a CLI issue associated with "show port egress" whereby the mirror source port failed to show in the command output.
12480 Customers are now able to see the serial number of the switch via Netsight Flexview.
12449 Resolved a potential memory leak associated with the "show config" CLI command.

Changes and Enhancements in 6.03.01.0008

12444 Corrected an issue whereby the sFlow SysUptime field of the sFlow packet was not properly initialized on bootup.
12445 Resolved an issue whereby the "set sflow interface" command would go into effect even if the specified interface was down.
12439 The switch now includes the NAS-identifier value in the RADIUS access-accept packet sent to the RADIUS server.
12438 Corrected an Issue where the port inlinepower admin state was not persistent when it was preceded by a "set port inlinepower admin off" in the config file.
12430 Corrected a CLI issue where the "show config all" command could result in loss of management or high CPU utilization when screen length was greater than zero.
12427 Users are now able to access the web when PWA guest networking is enabled with no authentication method.
12407 Resolved an issue whereby the static Rendezvous Point IP addresses could not be removed by executing the "no ip pimsm staticrp" command.
12295 Corrected a potential buffer allocation issue associated with OSPF which could cause the unit to stop forwarding traffic.
12289 Wake-on-LAN UDP packets destined to ports 0, 7 and 9 are now forwarded when configured via the "ip forwarding-protocol udp" command.
12223 Corrected an issue where the MAC addresses of devices connected to the switch front panel failed to appear in the port MAC address table.
11784 Resolved an issue whereby moving a port to the VLAN specified by policy was delayed when DHCP snooping was enabled.
11613 SNMP packets are now forwarded across the switch using the IP address of the selectable management port (if configured).
11551 The Entity MIB module now includes the serial number of the switch's power supply.

Changes and Enhancements in 6.03.00.0022

All new features added in this release are documented under the What's New in 6.03 section above.
12345 Corrected an issue with the LLDP application that prevented the switch from correctly displaying LLDP neighbor information advertised by a Siemens OpenStage 40 SIP phone.
9714 Corrected an issue that prevented the "clear nodealias config <port>" command from clearing non-default maxentries values.
9427 An RMON alarm now triggers correctly for a rising threshold when the startup parameter is configured for "either".
9637 An RMON alarm configured for both a rising threshold and falling threshold will not continuously be triggered for the falling threshold if the traffic rates do not exceed the falling threshold.
10411 Corrected an issue that prevented the configuration and enforcement of the system lockout feature after X number of SSH attempts failed.
9941 Corrected an issue causing an ACL to be applied to every virtual interface on a port if it was applied to a single VLAN. The issue is resolved via new support for VLAN-based ACLs.
12293 Resolved an issue where idle management sessions failed to disconnect after the maximum idle time was reached.
12254 Resolved an issue where expired SSH sessions failed to disconnect after 60 seconds.

KNOWN RESTRICTIONS AND LIMITATIONS:**Known Issues in 6.61.16.0002**

There are no new known restrictions or limitations associated with this release.

Known Issues from Previous Releases

Direct firmware upgrades to 6.61 from 6.03 (and previous) images may result in the loss of some configuration. (notably VRRP and SNTP) One workaround is to upgrade to 6.42 prior to loading 6.61. Alternatively the configuration may be saved to a file and reloaded after upgrade.

Switching**COS / TOS**

2371 If the CoS state is disabled, but a CoS priority has been configured, the switch will continue to forward packets with the CoS priority. However, the ToS field will not be modified.

6660 Configuring the last two bits of the ToS field is not supported. For example, when a CoS Index is configured to set a ToS value of 255, it will result in only the value 0xFC being set in the matching packets.

Dynamic Egress

Egress assignments made to ports by using Dynamic Egress are only supported on VLANs which have been statically created.

GVRP

3532 GVRP frames are not forwarded when GVRP is disabled.

2031 The G3 switch will propagate GVRP packets containing any known VLANs. All VLANs learned via GVRP will appear in the GVRP MIBs, regardless of whether or not there are local users attached to those VLANs.

VLAN Tagging

3410 The "set port vlan" command requires that the VLAN(s) specified when executing the command must already be preconfigured statically on the device.

A VLAN cannot be disabled via CLI and/or WebView. SNMP must be used.

Policy / Authentication

TACACS+ using single connect is configurable through the CLI but it is not supported in this release.

The G3 supports CoS-based Inbound Rate Limits for Policy Roles (profiles). Rule-based Inbound Rate Limits (IRLs) are not supported and will be ignored if configured.

Setting an extensive number of policy rules via the CLI can cause momentary loss of CLI and SNMP management.

Policies can only be assigned to ports on VLANs which have been statically created.

A role with CoS and/or PVID configured counts as an L2 rule and a mask. Multiple Roles with CoS and PVID configured counts only as one rule and one mask globally.

For policy roles that are set to "Deny Traffic" (e.g., Quarantine Role), ARP frames are dropped unless a policy rule explicitly permits forwarding of ARP frames.

2175 ARP packets are not classified based on policy IP source/destination rules.

3094 If a policy profile has cos-status enabled, only 99 rules can be supported per policy profile.

Policy roles and rules cannot be applied to ports that are members of a link aggregation group (LAG).

13421 Upgrading from firmware 6.03.02 to 6.03.03 from a TACACS+ account causes a console lockup. Workaround: Upgrade from a non TACACS+ user account.

Known Issues from Previous Releases	
VLAN Authorization	
When a VLAN tunnel is applied, traffic is egressed untagged as expected. "Show vlanauthorization" will display the correct VLAN and MAC address; however "show vlan" and "show port egress" will not display tunnel ports.	
MAC Locking	
Static MAC locking a user on multiple ports is not supported.	
It is possible under extenuating circumstances that a violating MACLock user can dot1x authenticate on the port but all other traffic from that user will be dropped.	
Statically MACLocked addresses in the Filtering Database show as "other" in the "show mac" response.	
The MACLock table may show multiple entries for the same user depending upon the VLAN assignment.	
RADIUS	
By design, the switch does not allow the Primary and Secondary RADIUS servers to be using the same IP address.	
MAC Authentication	
10893 On rare occasions with authentication, there is a potential for the MAC address of a user who fails to authenticate to remain unlearned for a period of time.	
In some rare cases, the command "set macauthentication portinitialize <port-string>" does not terminate mac-authenticated user sessions.	
PWA	
On switches that support multiauth, only one PWA authenticated user is supported per port	
Spanning Tree	
The "show spantree stats active" command may erroneously display some ports as active. If a port was once active and later goes down, the system will still show the port on the "active" list.	
VLAN marking of mirrored traffic – Edge only	
MAC addresses will be learned for packets tagged with the mirror VLAN ID. This will prevent the ability to snoop traffic across multiple hops.	
Warning: Traffic mirrored to a VLAN may contain control traffic. This may be interpreted by the downstream neighbor as legal control frames. Users should disable any protocols on inter-switch connections that might be affected (i.e., Spanning Tree).	
Routing	
16569 If VLAN 4094 is provisioned in firmware 6.61, it must be removed prior to backrevving to firmware 6.42 as VLAN 4094 is not supported in release 6.42. Failure to remove VLAN 4094 could potentially cause issues loading certain Layer 3 parameters	
A user cannot overwrite the IP address of a configured interface if the new IP address is in the same subnet as the original. They must first delete the existing interface IP address and then add the new IP address.	
The G3 will not add a dynamic host route to its routing table for a subnet it already knows about.	
The G3 does not support the ability for a user to configure the host's gateway to be a local routed interface IP. The host's gateway must exist on a different device in the network, if one is configured.	
The G3 only supports one default route. If a default route is configured on the router, it will take precedence over the default route configured for the host IP.	
ACLs	
Access Control Lists (ACLs) use the same hardware resources as Policy rules and should not be used simultaneously with Policy.	
IPv6	

Known Issues from Previous Releases
Servers for PWA cannot be configured with an IPv6 address.
OSPFv3 virtual links are not displayed in the OSPF adjacency table.
RIP
RIP stops calculating cost properly if cost ever equaled 16. If route cost is reduced below 16, the cost will not be propagated downstream properly.
OSPFv2
OSPF area 0 is always configured by default on the G3.
The OSPF ABR doesn't insert the default route into the NSSA when using the command "area <area_id> nssa". The default does get inserted when using the command "area <area_id> nssa default-information-originate".
The G3 only redistributes inter-area and intra-area OSPF routes via RIP. The redistribution of external type 1, external type 2, NSSA, and stub routes into RIP is not supported.
Area default-cost parameter isn't used when the ABR router is configured for an NSSA.
The G3 does not redistribute the default route via OSPF redistribution.
When creating a stub or NSSA area, in order to remove the existing summary or external LSAs before they age out naturally, all of the stub/NSSA area routers can either be reset, or the user can stop and restart the OSPF process. Otherwise, after 3600 seconds have passed, the MaxAged Summary or External LSAs will be removed automatically.
Multicast Routing
The output of "show ip mroute" will display the source mask address as 0.0.0.0.
The mroute table source network field displays the host IP address, not the host network.
Management
The switch can support up to two concurrent SSH client sessions.
An SNMPv3 configuration file created in an X.2 release will fail when loading into a switch running 6.03 or above. Workaround: After a switch has been upgraded, a previously created SNMPv3 configuration file MUST be re-generated (saved) using the new code in order for SNMPv3 to function correctly.
9328 If the host IP address or the router IP interface used for management is in a zero subnet (i.e., 10.0.x.x/16), ARPs will resolve, and the host will be unable to ping devices within the subnet.
9367 ICMP packets containing the record route or timestamp options will not be forwarded by the device.
10997 When auto-negotiation is disabled on an SFP port in a G3 that has a 100Base-FX connection, the CLI will display the incorrect speed for the port and a link may not be established. Workaround: After auto-negotiation has been disabled, manually configure the port for 100M via the "set port speed ge.1.2.xx 100" command to establish a 100M link using 100Base-FX MGBICs.
11539 It is highly recommended that DAI be configured on edge ports only due to the potential for the DHCP snooping database to become out of sync during a system reset.
11567 When upgrading from 1.02.02 firmware or earlier to 6.03 firmware, the CPU LED may blink red as the PoE driver is being updated. This only happens during the initial upgrade and will not appear in subsequent reboots.
11593 Setting the SNMP community context to default via the "set snmp community xxx context default" command could cause loss of SNMP management contact. In order to set a configured context back to the default (NULL) context, enter a hyphen as the value of the context parameter. For example, use the following command: "set snmp community abcde context -".
12329 User is unable to set port advertise speeds 10t, 10tfd, 100tx, and 100txfd on combo ports.
12737 When initiating a telnet session from the console of the device to another device, the telnet session will occasionally fail with the following error message: "telnet: Unable to connect to remote host: Connection timed out". Executing the command a second time will succeed.

Known Issues from Previous Releases
WebView (Web-based Management)
Configuration information for LAGs configured via WebView will not be reflected correctly when viewed via the CLI.
RMON
When packets are transmitted outbound they are counted under packet sizes 64-1518 in RMON stats but not total Packets or Octets.
Enabling RMON capture on an interface will cause packets to be duplicated on the interface while the functionality is enabled.
Only RMON offset values of 1-1518 are supported.
RMON automatically creates entries for stats using indexes associated with each port. If any of the automatically created indexes are cleared and then associated with a new entry with an index less than 450, the new entries will not be persistent. Upon resetting the device, RMON will automatically create entries for each port using the initial default indexes. To avoid this situation, always use an index of 450 or greater when creating new entries.
Port counters and RMON counter may display differing values.
Packets greater than 1518 will not be counted by the IfInErrors MIB.
<p>The switch now has support for RMON Capture Packet/Filter Sampling through both the CLI and MIBs, but with the following constraints:</p> <ul style="list-style-type: none"> • RMON Capture Packet/Filter Sampling and Port Mirroring cannot be enabled on the same interface concurrently. • The user can capture a total of 100 packets on an interface, no more and no less. <ul style="list-style-type: none"> ○ The captured frames will be as close to sequential as the hardware will allow. ○ Only one interface can be configured for capturing at a time. ○ Once 100 frames have been captured by the hardware the application will stop without manual intervention. • As described in the MIB, the filter is only applied after the frame is captured, thus only a subset of the frames captured will be available for display. • There is only one Buffer Control Entry supported. • Due to the limitations of the hardware, the Buffer Control Entry table will have limits on a few of its elements: <ul style="list-style-type: none"> ○ MaxOctetsRequested can only be set to the value -1 which indicates the application will capture as many packets as possible given its restrictions. ○ CaptureSliceSize can only be set to 1518. ○ The Full Action element can only be set to —lockll since the device does not support wrapping the capture buffer. • Due to hardware limitations, the only frame error counted is oversized frames. • The application does not support Events, therefore the following elements of the Channel Entry Table are not supported: TurnOnEventIndex, TurnOffEventIndex, EventIndex, and EventStatus. • There is only one Channel Entry available at a time. <ul style="list-style-type: none"> ○ There are only three Filter Entries available, and a user can associate all three Filter Entries with the Channel Entry. <p>Configured channel, filter, and buffer information will be saved across resets, but not frames within the capture buffer.</p>
sFlow
14061 sFlow can create varying degrees of CPU utilization depending on the number of samplers, sampling rate, pollers, and sampling interval. High CPU utilization can be mitigated by reducing samplers and pollers, or increasing sampling rate and interval. Since traffic is switched in hardware, CPU utilization should not affect switch performance. However, it may slow management response.
12004 sFlow does not sample with frame rates < 1024fps.

For the most up-to-date information concerning known issues, go to the **Global Knowledgebase** section at <http://support.extremenetworks.com/>.

For the latest copy of this release note, go to <http://support.extremenetworks.com/>.

To report an issue not listed in this document or in the **Global Knowledgebase**, contact our Technical Support Staff.

IETF STANDARDS MIB SUPPORT:

RFC No.	Title
RFC 1213	MIBII
RFC 1493	Bridge MIB
RFC 2613	SMON MIB (portCopyConfig)
RFC 2819	RMON MIB
RFC 2668	MAU-MIB
RFC 2233	IfMIB
RFC 2863	IfMIB
RFC 2620	Radius Accounting MIB
RFC 2618	Radius Authentication MIB
RFC 3621	Power Ethernet MIB
IEEE 802.1X MIB	802.1-PAE-MIB
IEEE 802.3ad MIB	IEEE 8023-LAG-MIB
RFC 2674	802.1p/Q BridgeMIB
RFC 2737	Entity MIB (physical branch only)
RFC 2933	IGMP MIB
RFC 2271	SNMP Framework MIB
RFC 3413	SNMP Applications MIB
RFC 3414	SNMP Usm MIB
RFC 3415	SNMP Vacm MIB
RFC 3584	SNMP Community MIB
RFC 1248	OSPF Version 2 MIB
RFC 2740	OSPF Version 3 MIB
RFC 1724	RIP Version 2 MIB
RFC 2787	VRRP MIB
RFC 1981	Path MTU for IPv6
RFC 2465	IPv6 MIB
RFC 2466	ICMPv6 MIB
RFC 2460	IPv6 Protocol Specification
RFC 2461	Neighbor Discovery
RFC 2462	Stateless Autoconfiguration
RFC 2463	ICMPv6
RFC 4291	IP Version 6 Addressing Architecture

RFC No.	Title
RFC 3587	IPv6 Global Unicast Address Format
RFC 4007	IPv6 Scoped Address Architecture

PRIVATE ENTERPRISE MIB SUPPORT:

Title
ctbroadcast mib
ctenvironment mib
ctRatePolicing mib
ctQBridgeMIBExt mib
ctCDP mib
ctAliasMib
ctTxQArb mib
ctDownLoad mib
etsysRadiusAuthClientMIB
etsysRadiusAuthClientEncryptMIB
etsysPolicyProfileMIB
etsysPwaMIB
etsysSyslogClientMIB
etsysConfigurationManagementMIB
etsysMACLockingMIB
etsysSnmpPersistenceMIB
etsysMstpMIB
etsysMACAuthenticationMIB
etsysletfBridgeMibExtMIB
etsysMultiAuthMIB
etsysSntpClientMIB
etsysleee8023LagMibExtMIB
etsysVlanAuthorizationMIB
etsysCosMIB
etsysResourceUtilizationMIB
etsysMultiUser8021xMIB
etsysTacacsClientMIB
etsysSpanningTreeDiagnosticMIB

Private Enterprise MIBs are available in ASN.1 format from the Extreme Networks web site at: www.extremenetworks.com/support/policies/mibs/. Indexed MIB documentation is also available.

SNMP TRAP SUPPORT:

Traps	Description
Authentication Failure	User has failed network authentication
ColdStart (RFC 1213)	System has initialized due to power-up
CPU Utilization	CPU utilization exceeds configured threshold
etsysPsePowerNotification	Power system failure
Fan failure	Fan state transitioned from "normal to failing" or from "failing to normal"
Link Up (RFC 1213)	User port transitioned to an up state
Link Down (RFC 1213)	User port transitioned to an up state
Link Flap	Link pattern has exceeded threshold parameters
LLDP	Remote system change detected
LLDP-MED	Topology change detected on the port (that is remote device has been attached or removed from the port)
newaddrtrap	New MAC address detected on non-CDP port
Maclock violation	Detected source MAC address not permitted
Overtemperature	Transitioned to thermal alarm state
PoE inlinpower	Port status change or power threshold exceeded
Policy Inbound Rate Limit	Rate limit violation
RMON FallingAlarm (RFC 1757)	A monitored MIB decreased to a trigger value
RMON RisingAlarm (RFC 1757)	A monitored MIB increased to a trigger value
RPS Power status	Redundant Power Supply status change
STP Disputed BPDU	Disputed BPDU events exceeded threshold
STP Loop Protect	Inconsistent BPDU receipt on ISL port
STP New Root (RFC 1493)	Root bridge role transition has occurred
STP Spanguard	Incoming BPDU detected on edge port
STP Topology Change (RFC 1493)	Spanning Tree topology has changed

RADIUS ATTRIBUTES SUPPORT:

Attribute	RFC Source
Calling-Station-Id	RFC 2865, RFC 3580
Class	RFC 2865
EAP-Message	RFC 3579
Filter-ID	RFC 2865, RFC 3580
Framed-MTU	RFC 2865, RFC 3580
Message-Authenticator	RFC 3579
NAS-Identifier	RFC 2865, RFC 3580
NAS-IP-Address	RFC 2865, RFC 3580
NAS-Port	RFC 2865, RFC 3580
NAS-Port-Id	RFC 2865, RFC 3580

Attribute	RFC Source
NAS-Port-Type	RFC 2865, RFC 3580
Session-Timeout	RFC 2865
State	RFC 2865
Termination-Action	RFC 2865, RFC 3580
Tunnel Attributes	RFC 2867, RFC 2868, RFC 3580
User-Name	RFC 2865, RFC 3580

RADIUS Accounting Attributes

Attribute	RFC Source
Acct-Session-Id	RFC 2866
Acct-Terminate-Cause	RFC 2866

GLOBAL SUPPORT:

By Phone: +1 877-801-7082 (toll-free in U.S. and Canada)

For the toll-free support number in your country:
www.extremenetworks.com/support/

By Email: support@extremenetworks.com

By Web: www.extremenetworks.com/support/

By Mail: Extreme Networks, Inc.
 145 Rio Robles
 San Jose, CA 95134

For information regarding the latest software available, recent release note revisions, or if you require additional assistance, please visit the Extreme Networks Support website.

APPENDIX A: CHANGES AND ENHANCEMENT HISTORY FROM PREVIOUS RELEASES**Changes and Enhancements in 1.02.06.0004**

11876 & 12073 Resolved an issue with LLDP which could potentially prevent users from authenticating successfully when attached to the switch via an IP phone.

11890 Corrected a CLI issue where the “show config all” command erroneously displayed the STP Loop Protect status on ports as “enable” for disabled ports.

11942 Resolved an issue whereby the bufferControlTurnOnTime RMON-MIB (1.3.6.1.2.1.16.8.1.1.11) returned an incorrect value causing the wrong date and time to be displayed.

11959 Resolved an issue associated with SSH end users whereby the switch would send a challenge request to the RADIUS server after the initial request was successfully granted.

11960 Corrected an issue associated with pasting CLI commands into the console via SSH or Telnet connections whereby pasted-in carriage return characters were ignored.

12121 Corrected an issue whereby configuring separate RADIUS authentication and RADIUS accounting servers caused the switch to send multiple accounting request packets per authenticating user. This could cause excessive CPU loads.

12132 Resolved an issue whereby a default policy rule could prevent admin policy from being applied.

12134 Corrected a potential issue with orphaned SSH sessions which prevented the switch from properly cleaning up the connections.

12202 The output of the CLI command “show lldp port” will now display the port Id information received in the LLDP PDU from the remote device.

12209 Resolved an issue with the STP Loop Protect feature which could potentially slow down the Spanning Tree (RSTP) failover time.

12236 The “show snmp” command now displays correct values for the latest snmp request and update times. Previously the “Last snmp Request” and “Last snmp Status” outputs were out of sync with the current time.

12244 Resolved an issue with the “show dot1x auth-diag” command output whereby the “Backend Auth Fails” field was missing for some ports.

Changes and Enhancements in 1.02.05.0004

11540 Resolved a potential snmp issue which could cause the switch to stop processing snmp requests. Previously the state of a server which had become unavailable would show as "Not in service" after the server became available.

11588 Corrected an issue where monitoring RMON MIB statistics via an SNMP management station could potentially cause a device reset.

11668 Resolved an issue where clients on a switch failed to obtain DHCP IP addresses when DHCP snooping was set on their VLAN interfaces but not globally enabled.

11681 Corrected an issue whereby applying a new policy on ports could potentially cause existing policies to be removed.

11830 802.1x authenticated users' MAC addresses will now be learned on ports where multiauth mode is set to strict and firstarrival is 1. Previously unauthorized devices could prevent dot1x users from connecting to the network.

11949 Corrected an issue whereby setting an IP helper address on the switch could cause the DHCP server application to fail.

12047 Resolved a potential loss of port configuration which could occur when upgrading from firmware 1.01.01.0040 and above to 1.02.04.0005.

Changes and Enhancements in 1.02.04.0005

Implemented the ability for a user to set the port mdi / mdix settings via the CLI to allow support for a variety of media converters. This feature is not supported on RJ45 Combo ports that can be used in an either/or configuration with SFP MGBICs. The commands added are:

show port mdix { all | auto | forced-auto | mdi | mdix } [port-string]

set port mdix { auto | forced-auto | mdi | mdix } [port-string]

By default, Enterasys Networks switch devices are configured to automatically detect the cable type connection, straight through (MDI) or cross-over (MDIX), required by the cable connected to the port.

10981 Corrected an issue whereby terminating user sessions from Policy Manager could potentially fail for multiauth users which were authenticated via dot1x then macauth, or vice versa.

11133 Corrected an issue whereby policy applied to a GVRP enabled switch could result in the loss of management or high CPU utilization.

11338 Corrected an issue whereby the daylight savings times function would fail if the start and end times spanned across a year.

11401 Corrected a potential indexing issue with the etsysMulti1xSupplicantAddressTable MIB (1.3.6.1.4.1.5624.1.2.53.1.2.5) which was added in firmware revision 1.02.03.0010.

11437 Corrected a VRRP issue where a switch would respond to a traceroute with the wrong interface when multiple interfaces used the same VRID.

11444 Corrected an issue which prevented users from configuring VLAN membership for ports belonging to dynamic VLANs.

11466 The IP helper function now uses the originating routers IP address when forwarding DHCP request packets. Previously the switch replaced the source IP address of the DHCP request with its own address.

11522 Resolved an issue whereby upgrading from firmware revision 1.0.x to 1.2.x could potentially cause the LACP configuration to be lost.

11566 Corrected an issue with igmpsnooping whereby if a user authenticated with dot1x and a dynamic policy was assigned, multicast traffic could cease to transmit to the authenticated port.

11584 Corrected an issue with the "show support" command which prevented the switch configuration from being displayed in its entirety.

11586 Corrected an issue with ciscoCdpMIB MIB where the cdpCacheEntry Table (1.3.6.1.4.1.9.9.23.1.2.1.1) could potentially fail to return a value.

11597 Corrected an issue with the "show config outfile" command which could prevent the backed up configuration file from being restored properly.

11675 Corrected a CLI display issue associated with the "set port txq" command. Previously the first 2 queue values would not be displayed when 100% of the traffic was assigned to the highest transmit queue.

11865 Corrected a potential connectivity issue whereby after a device reset, auto-MIDX was not enabled on ports with auto negotiation disabled.

Changes and Enhancements in 1.02.03.0010

Added a new feature that allows you to troubleshoot and locate faults in copper cable connections on a port basis. A new CLI command, **show port cablestatus** <port-string>, allows you to diagnose cabling problems in realtime. The command returns the following:

normal = normal
open = no cable attached to port
short = detection of an inter-pair short
fail = unknown error or crosstalk
detach = for ports on stack units no longer present, but were previously connected
unsupported = ports other than 1GE RJ45 ports

The “Detach” designation is applicable to stacking products only.

This command is only supported on RJ45 copper connections running at 1GE speeds.

9260 Added support for the ctAliasProtocolTable, ctAliasMacAddressTable and ctAliasClearAll objects to the ctAliasMib MIB. Previously multiple entries with the same MAC address on the same port could potentially cause the IP Resolution for that MAC address to fail.

11204 Corrected an issue whereby removing an existing DHCP Relay Agent followed by adding a DHCP server on the switch could cause the server to fail.

11324 Resolved an issue where UDP helper function would not forward packets destined to UDP port 4011.

11335 Corrected an issue with extended ACLs that prevented rules containing both masked IP hosts and TCP or UDP destination ports from being applied.

11338 Corrected an issue whereby daylight savings times settings would not work if the start and end times spanned across a year.

11342 A change has been made which eliminates the second attempt to authenticate through a RADIUS server when the first attempt (using the specific client MAC address) is rejected and the mask to be used for the second attempt is set to all “F”s.

11377 Corrected an LLDP issue where the “show neighbor” command failed to display the neighbors' host IP addresses.

11392 Corrected an OSPF issue whereby after a firmware upgrade from revision X.1 to X.2 the default path cost value could change from 10 to 1.

11401 & 11402 Added support for the etsysMulti1xSupplicantAddressTable (1.3.6.1.4.1.5624.1.2.53.1.2.5) from the Multi User 802.x MIB. This table gives a list of current dot1x users and indicates whether they are active (authenticated) and the user name associated with that user.

11420 The DHCP snooping function has been changed to only rate limit untrusted ports when a rate limit is configured. Previously the rate limit was applied to all trusted and untrusted ports.

11477 Corrected an issue where the system LED on G3s could erroneously blink red during boot up indicating a device failure.

11487 Corrected an issue where active links on MGBIC-LC04 and MGBIC-LC05 ports could potentially fail to re-establish link after a device reset.

Changes and Enhancements in 1.02.02.0009

10597 & 11408 Resolved an issue in multiuserauth mode whereby an inactive user was dropped from the egress VLAN list and could no longer transmit packets out the egress VLAN.

10827 Corrected an issue where the “show system” command failed to display maximum temperature threshold settings.

10889 Resolved an issue where a 2-port LAG would not failover to a single port LAG when a member port was removed.

10973 Corrected an issue where oversized SSH packets potentially caused a switch reboot.

Changes and Enhancements in 1.02.02.0009
11070 Corrected an issue where VLAN egress settings via NetSight would not persist after a reboot.
11065 Resolved an issue where rebooting the VRRP master switch could potentially stop traffic from being forwarded to clients across a LAG port.
11106 IPV6 proxy-routing now supports static MAC addresses. Previously configuring static MAC addresses while ipv6 proxy-routing was enabled would cause the following error: proxy_routing.c 489: In hapiBroadRoutingRouteProxyConfig call to "hapiBroadSystemMacAddrAdd" - FAILED : 1.
11125 The fan number designators are now consistent between the CLI and Syslog messages.
11131 The RADIUS Filter-ID attribute is no longer case sensitive for management users.
11156 & 11322 Corrected an issue where the "show mac type self" command displayed an incorrect MAC address and could potentially lockup the CLI.
11157 Corrected an issue where manually configured port speed settings were not saved in the config file. System restoration using a newly saved config file properly restored configured port speeds.
11205 & 11206 Corrected an issue where the "show vlan portinfo vlan" command failed to display member LAGs and associated port details.
11215 Resolved an issue where enabling maclock agefirstarrival would fail to remove aged-out firstarrival maclock entries.
11230 Corrected an issue where OSPF routes would fail to advertise for the secondary IP address on an interface.
11234 Corrected an issue where user-configured CDP hold time values would not be applied. The default hold time value would be used instead.
11237 Corrected an issue with multiauth strict mode where the second user on a port would not appear in the forwarding database.
11240 Resolved an issue where "clear multiauth mode" did not restore default settings.
11267 Corrected an issue where the entPhysicalSerialNum MIB (1.3.6.1.2.1.47.1.1.1.11) could potentially return the wrong Serial Number.
11275 Corrected an issue where only the first IGMP group join message would be processed by the switch. All additional requests would potentially be ignored.

Changes and Enhancements in 1.02.00.0043
Added DHCP spoofing protection via DHCP snooping. Previously you could use Enterasys Policy to protect your DHCP services, but now DHCP protection can be done independently of ETS Policy.
Added protection from man-in-the-middle ARP spoofing attacks. This feature works in conjunction with the DHCP snooping database to ensure that ARP requests match the IP/MAC/Port binding relationship dynamically created during DHCP client/server exchanges.
Added support for the etsysResourcesScalarsGroup attribute from the etsysResourceUtilizationMIB to enable the ability to set threshold levels for CPU utilization notification traps.
Added the ability for multiport LAGs to continue operating in multiport mode as long as there is at least one active port in the LAG. Previously administrators needed to create backup single-port LAGs to ensure that a multi-port LAG would not change its behavior if all but one port dropped out of the LAG. This redundant configuration effectively reduced the number of LAGs that could be configured in the switch by half. Alternatively, you had to configure egress tagging at the port level to match the LAG configuration ensuring that traffic would be marked appropriately when only a single port remained active.
Added support for forwarding broadcast IP traffic to a unicast IP address via "ip forward protocol".
11160 Corrected an issue where manually configured port speed settings were not saved in the config file. System restoration using a newly saved config file will properly restore configured port speeds.

Changes and Enhancements in 1.02.00.0043

10395 Added support for disabling ICMP redirects on routing interfaces to reduce CPU loads in certain configurations.

Added support for protecting the health of the switch based on predetermined safe operating temperature limits. The administrator can change the maximum temperature threshold where a trap and syslog message is generated warning them of high-temperature conditions before service is affected.

Modified the "set boot system" command to prompt the administrator before resetting the switch. If the administrator elects not to reset the switch, the new firmware is copied into the active partition but only takes effect after the switch is reset/rebooted.

Modified the newmac trap to include the MAC address of the client in the SNMP trap.

10274 & 10183 Corrected an issue where the first packet through the switch is dropped with policy applied, subsequent packet transmissions are successful.

10194 Corrected a potential VRRP issue resulting in a CLI lock up while the following error message was displayed: SIM[213497528]: timer.c(995) 5048 %XX_Call() failure in _checkTimers for thread 0xcba85c0.

10993 & 11071 Corrected an issue where the "show config" command would not display port speeds configured via CLI or WebView.

10995 Corrected an issue that prevented the "switch description" field from being permanently stored in the configuration.

10592 Corrected an issue that occurred when processing an invalid policy role received from RADIUS. The switch now applies the default port role, where previously the existing role was unchanged.

11085 Corrected an issue where management packets destined to the switch host IP address received on a routed interface, were replied to using the IP address of the routed interface

10795 Addressed a potential SNMP vulnerability identified in US-CERT VU#878004.

Added support for MD5 authentication over OSPF virtual links.

9842 Resolved an issue with Cisco DP where the "show neighbor" command displayed an incorrect port ID value.

Changes and Enhancements in 1.00.03.0002

Resolved an issue which prevented multicast control packets from being forwarded properly through LAG ports.

Corrected an issue where ASM was not able to apply actions to ports.

Corrected an issue in the Policy MIB where the etsysPortPolicyProfileSummaryTable (1.3.6.1.4.1.5624.1.2.6.3.3) failed to return a value for etsysPortPolicyProfileSummaryOperID.

Corrected an issue where the MIB2 ipForwarding=1.3.6.1.2.1.4.1 returned the wrong value for a switch.

Corrected an issue where CLI buffer sizes exceeding 1024 lines would cause errors in the output display.

Corrected an issue with RMON where packet capture over non-default VLANs only worked in one direction.

Changes and Enhancements in 1.00.02.0001

Corrected a potential issue with loss of link on 10GBE ports.

Changes and Enhancements in 1.00.01.0058

Corrected an issue with the RADIUS reauthentication timer. During an unrecognized overflow condition which occurred approximately once every 49 days, the switch would constantly attempt to authenticate all RADIUS supplicants. This would last for a period equal to the authentication time.

Corrected an issue where existing COS based Inbound Rate Limiters (IRLs) were not disabled by "set cos state disable" command

Corrected a potential memory corruption and reset associated with MAC Authentication.

Changes and Enhancements in 1.00.01.0058

Corrected an issue where IGMP Snooping failed on a user port that had been authenticated to a new VLAN other than the PVID of the port.
Corrected a CLI display issue where clearing a default role on a port on a port or device resulted in the "show multiauth session" command incorrectly displaying that the user's authenticated roles were also cleared.
Corrected an issue where Dynamic Egress would fail on ports configured to discard VLAN tagged packets
Corrected an issue where the switch would no longer send EAP requests once a single user was authenticated. This could have been an issue for some supplicants in a multi-user configuration.
Corrected an issue where port speed (ifSpeed and ifHighSpeed) were incorrectly reported for 10 Gig interfaces.
Corrected the inability to set dot3MauType to dot3MauType1000BaseTFD in MAU-MIB
Corrected a potential SNMP loop in the processing of the LLDP management requests
Corrected an issue where ACLs were not automatically applied to a new interface that joined a VLAN with existing ACLs.
Corrected an issue in DVMRP where the stream associated with a new group was dropped if the session is stopped and a new channel is selected to the same multicast server
Corrected an issue where permanent licenses were incorrectly detected as having expired.
Corrected a small memory leak associated with license verification.
Corrected an issue that could result in the inability to apply previously acceptable policies to ports after a system reboot.
Corrected an issue where the switch would not process BPDUs containing information on more than the supported number of Spanning Tree instances.
Corrected an issue where setting a port that is configured for macauthentication to a "multiauth port mode" of "forced-auth" caused the port to no longer learn MACs after a reset.
Corrected an issue where session idle timeout was kicking in for active 802.1x clients.
Corrected an issue where the RADIUS VLAN tunnel attribute was ignored if a Filter ID was also sent by the RADIUS server when configured for VLAN authentication.
Corrected an issue where a VLAN authenticated user did not lose membership in the original VLAN on reauthentication to a new VLAN.
Corrected an issue where the number of authenticated users on a port could be miscalculated preventing new users from authenticating.
Corrected an issue where a received gratuitous ARP with an IP address of zero caused the system to reset.
Corrected an issue where the switch incorrectly advertised support for 1000T Half Duplex.
Corrected an issue in Policy that could prevent the application of a profile after a system reboot. Previously a hardware error was given indicating a failure to set a profile on a port.

Changes and Enhancements in 1.00.00.0054

Initial customer release.
