

VSP Operating System Software Release

6.1.2.1

1. Release Summary

Release Date: Jan 2018

Purpose: Software release to address customer found software issues.

2. Important Notes before Upgrading to This Release

If upgrading systems from either release 4.2.1.0 or release 4.2.1.1 that have ISIS enabled link(s) configured with HMAC-MD5 authentication, then you need to perform the procedure described in section (4) below in order to avoid potential network connectivity loss.

If upgrading systems running 4.1.X releases which also have TACACS+ enabled, refer to section 4 for upgrade instructions.

3. Platforms Supported

Virtual Services Platform 4000 Series

- Virtual Services Platform VSP 4850GTS
- Virtual Services Platform VSP 4850GTS-PWR+
- Virtual Services Platform VSP 4450GSX-PWR+
- Virtual Services Platform VSP 4450GSX-DC
- Virtual Services Platform VSP 4450GTS-DC
- Virtual Services Platform VSP 4450GTX-HT-PWR+

Virtual Services Platform 7200 Series

- Virtual Services Platform VSP 7254XSQ
- Virtual Services Platform VSP 7254XTQ

Virtual Services Platform 8000 Series

- Virtual Services Platform 8200
- Virtual Services Platform 8400

4. Special Instructions for Upgrade from previous releases

1. The following procedure should be followed when upgrading systems running one of the following two releases, 4.2.1.0 or 4.2.1.1 which also have ISIS enabled links with HMAC-MD5 authentication on:

Disable ISIS authentication throughout the network a system at a time, a link at a time by disabling it on either side of each link, ensuring the link is stable before moving to the next. When a system has been reconfigured free of ISIS HMAC-MD5 authentication in all of its links, save the configuration file and perform the upgrade to release 4.2.3.0 or greater. After all these systems have been upgraded to release 4.2.3.0 or greater, you may re-enable authentication a system at a time, a link at a time and save the configuration file in each of the involved systems.

Example:

```
VSP:1(config)#interface gigabitethernet x/y
```

```
VSP:1(config-if)#no isis hello-auth
```

```
VSP:1(config-if)#save config
```

```
VSP:1(config-if)# PERFORM THE UPGRADE
```

```
VSP:1(config)#interface gigabitethernet x/y
```

```
VSP:1(config-if)# isis hello-auth type hmac-md5 key <keyname> [key-id <keyed>]
```

```
VSP:1(config-if)#save config
```

2. The following procedure should be followed when upgrading systems running 4.1.X releases which also have TACACS+ enabled on:

When you upgrade from VOSS 4.1.X to VOSS 4.2 or a higher release, the TACACS+ host configurations will be lost. After the upgrade, the TACACS+ host configurations will not take effect so you must reconfigure them. After you make the configurations, you must save the changes on the device. You should also save the configuration to a file to retain the configuration settings.

3. Upgrading DVR configurations from releases 6.0.1.1 and earlier to 6.0.1.2 and beyond.
 - a. All DVR nodes must be upgraded to the same release.
 - b. All DVR leaves should be upgraded first.

5. Notes for Upgrade

Please see “Release Notes for VSP Operating System” for software release 6.1.0 (NN47227-401, 15.05) available at <http://www.avaya.com/support> for details on how to upgrade your Switch.

File Names For This Release

Virtual Services Platform 4000 Series

File Name	Module or File Type	File Size (bytes)
VOSS4K.6.1.2.1.tgz	Release 6.1.2.1 archived software distribution	104437642
VOSS4K.6.1.2.1_mib.zip	Archive of all MIB files	1083041
VOSS4K.6.1.2.1_mib.txt	MIB file	7180195
VOSS4K.6.1.2.1_mib_sup.txt	MIB file	1182904
VSP4000v612_HELP_EDM_gzip.zip	EDM Help file	3282973
VSP4000v6.1.2.1.zip	EDM plug-in for COM	4869205
VOSS4K.6.1.2.1.md5	MD5 Checksums	578
VOSS4K.6.1.2.1.sha512	SHA512 Checksums	1538

Virtual Services Platform 7200 Series

File Name	Module or File Type	File Size (bytes)
VOSS7K.6.1.2.1.tgz	Release 6.1.2.1 archived software distribution	66442836
VOSS7K.6.1.2.1_mib.zip	Archive of all MIB files	1083041
VOSS7K.6.1.2.1_mib.txt	MIB file	7180195
VOSS7K.6.1.2.1_mib_sup.txt	MIB file	1186371
VOSSv612_HELP_EDM_gzip.zip	EDM Help file	3288186
VOSSv6.1.2.1.zip	EDM plug-in for COM	5176832
VSP7K.6.1.2.1.md5	MD5 Checksums	572
VOSS7K.6.1.2.1.sha512	SHA512 Checksums	1532

Virtual Services Platform 8000 Series

File Name	Module or File Type	File Size (bytes)
VOSS8K.6.1.2.1.tgz	Release 6.1.2.1 archived software distribution	120473180
VOSS8K.6.1.2.1_mib.zip	Archive of all MIB files	1083041
VOSS8K_6.1.2.1_mib.txt	MIB file	7180195
VOSS8K.6.1.2.1_mib_sup.txt	MIB file	1182253
VOSSv612_HELP_EDM_gzip.zip	EDM Help file	3288186
VOSSv6.1.2.1.zip	EDM plug-in for COM	5176832
VSP8K.6.1.2.1.md5	MD5 Checksums	764
VOSS8K.6.1.2.1.sha512	SHA512 Checksums	2012

Note about image download:

Ensure images are downloaded using the binary file transfer. Perform MD5 checksum check on downloaded files to ensure file integrity.

Check that the file type suffix is “.tgz” and the image names after download to device match those shown in the above table. Some download utilities have been observed to append “.tar” to the file name or change the filename extension from “.tgz” to “.tar”. If file type suffix is “.tar” or file name does not exactly match the names shown in above table, rename the downloaded file to the name shown in the table above so that the activation procedures will operate properly.

Load activation procedures:

```
software add VOSS4K.6.1.2.1.tgz
software activate VOSS4K.6.1.2.1.GA
```

or

```
software add VOSS7K.6.1.2.1.tgz
software activate VOSS7K.6.1.2.1.GA
```

or

```
software add VOSS8K.6.1.2.1.tgz
software activate VOSS8K.6.1.2.1.GA
```

6. Version of Previous Release

Virtual Services Platform 4000 Series

Software Version 3.0.0.0, 3.0.1.0, 3.1.0.0, 3.1.0.2, 3.1.0.3, 4.0.0.0, 4.0.0.1, 4.0.0.2, 4.0.0.3, 4.1.0.0, 4.1.0.1, 4.2.0.0, 4.2.0.1, 4.2.1.0, 4.2.1.1, 4.2.2.0, 4.2.3.0, 5.0.0.0, 5.0.1.0, 5.1.0.0, 5.1.1.0, 5.1.1.1, 5.1.1.2, 5.1.1.3, 5.1.1.4, 6.0.0.0, 6.0.1.0, 6.0.1.1, 6.0.1.2, 6.1.0.0, 6.1.1.0 and 6.1.2.0 for VSP 4850GTS platforms

Software version 4.0.0.0, 4.0.0.1, 4.0.0.2, 4.0.0.3, 4.1.0.0, 4.1.0.1, 4.2.0.0, 4.2.0.1, 4.2.1.0, 4.2.1.1, 4.2.2.0, 4.2.3.0, 5.0.0.0, 5.0.1.0, 5.1.0.0, 5.1.1.0, 5.1.1.1, 5.1.1.2, 5.1.1.3, 5.1.1.4, 6.0.0.0, 6.0.1.0, 6.0.1.1, 6.0.1.2, 6.1.0.0, 6.1.1.0 and 6.1.2.0 for VSP 4450GSX platform

Software Version 4.0.50.0 4.2.1.1, 4.2.2.0, 4.2.3.0, 5.0.0.0, 5.0.1.0, 5.1.0.0, 5.1.1.0, 5.1.1.1, 5.1.1.2, 5.1.1.3, 5.1.1.4, 6.0.0.0, 6.0.1.0, 6.0.1.1, 6.0.1.2, 6.1.0.0, 6.1.1.0 and 6.1.2.0 for VSP 4450GSX DC and VSP 4450GTS DC platforms

Software Version 4.0.40.0, 4.1.0.0, 4.1.0.1, 4.2.0.0, 4.2.0.1, 4.2.1.0 4.2.1.1, 4.2.2.0, 4.2.3.0, 5.0.0.0, 5.0.1.0, 5.1.0.0, 5.1.1.0, 5.1.1.1, 5.1.1.2, 5.1.1.3, 5.1.1.4, 6.0.0.0, 6.0.1.0 , 6.0.1.1, 6.0.1.2, 6.1.0.0, 6.1.1.0 and 6.1.2.0 for VSP 4450GTX-HT-PWR+ platform

Virtual Services Platform 7200 Series

Software Version 4.2.1.0, 4.2.1.1, 4.2.2.0, 4.2.3.0, 5.0.0.0, 5.0.1.0, 5.1.0.0, 5.1.1.0, 5.1.1.1, 5.1.1.2, 5.1.1.3, 5.1.1.4, 6.0.0.0, 6.0.1.0 , 6.0.1.1, 6.0.1.2, 6.1.0.0, 6.1.1.0 and 6.1.2.0

Virtual Services Platform 8000 Series

Software Version 4.0.0.0, 4.0.1.0, 4.0.1.1, 4.0.1.2, 4.0.1.3, 4.0.1.4, 4.1.0.0, 4.1.0.1, 4.2.0.0, 4.2.0.1, 4.2.1.0, 4.2.1.1, 4.2.2.0, 4.2.3.0, 5.0.0.0, 5.0.1.0, 5.1.0.0, 5.1.1.0, 5.1.1.1, 5.1.1.2, 5.1.1.3, 5.1.1.4, 6.0.0.0, 6.0.1.0 , 6.0.1.1, 6.0.1.2, 6.1.0.0, 6.1.1.0 and 6.1.2.0 for VSP8200 platform

Software Version, 4.2.0.0, 4.2.0.1, 4.2.1.0, 4.2.1.1, 4.2.2.0, 4.2.3.0, 5.0.0.0, 5.0.1.0, 5.1.0.0, 5.1.1.0, 5.1.1.1, 5.1.1.2, 5.1.1.3, 5.1.1.4, 6.0.0.0, 6.0.1.0, 6.0.1.1, 6.0.1.2, 6.1.0.0, 6.1.1.0 and 6.1.2.0 for VSP8404 platform

Software Version, 5.3.0.0, 6.1.0.0, 6.1.1.0 and 6.1.2.0 for VSP8404c platform

7. Compatibility

8. Changes in 6.1.2.1

Problems Resolved in This Release

ID	Description
VSP4000-197	Fixed issue in the Common Name (CN) when installing certificates.

9. Outstanding Issues

Please see “Release Notes for VSP Operating System” for software release 6.1.0 (NN47227-401, 15.05) available at <http://www.avaya.com/support> for details regarding Known Issues.

10. Known Limitations

Please see “Release Notes for VSP Operating System” for software release 6.1.0 (NN47227-401, 15.05) available at <http://www.avaya.com/support> for details regarding Known Limitations.

VSP8200 and VSP8400 platforms may experience a watchdog timeout induced reset when a momentary power loss to the system occurs. In this situation, the datapath has been reinitialized even though there is enough power left in the system for the Control Plane to generate a coredump. The reset is needed for the system to be fully functional again. Using a UPS is recommended to mitigate momentary power interruption.

Regular cleanup of unneeded files on USB drives is recommended to minimize possibility of USB corruption when a system is reset, shutdown or power is lost.

11. Documentation Corrections

For other known issues, please refer to the product release notes and technical documentation available from the Avaya Technical Support web site at: <http://www.avaya.com/support> .

Copyright © 2018 Extreme Networks, Inc. - All Rights Reserved.

The information in this document is subject to change without notice. The statements, configurations, technical data, and recommendations in this document are believed to be accurate and reliable, but are presented without express or implied warranty. Users must take full responsibility for their applications of any products specified in this document. The information in this document is proprietary to Extreme Networks, Inc.

To access more technical documentation, search our knowledge base, or open a service request online, please visit Avaya Technical Support on the web at: <http://www.avaya.com/support>