

# Virtual Services Platform 9000 Software Release 4.2.1.4

## 1. Release Summary

Release Date: August 2018

Purpose: Software release to address customer found software issues.

#### 2. Important Notes before Upgrading to This Release

None.

### 3. Platforms Supported

Virtual Services Platform 9000 (all models)

#### 4. Special Instructions for Upgrade from previous releases

None.

#### 5. Notes for Upgrade

Please see "Virtual Services Platform 9000, Release Notes" for software release 4.1.0.0 available at <a href="https://www.extremenetworks.com/support/documentation">https://www.extremenetworks.com/support/documentation</a> for details on how to upgrade your switch.

#### **File Names For This Release**

File Name	Module or File Type	File Size (bytes)
VSP9K.4.2.1.4.tgz	Release 4.2.1.4 archived distribution	177268831
VSP9K.4.2.1.4_modules.tgz	Encryption modules	41909
VSP9K.4.2.1.4_mib.zip	Archive of all MIB files	826414
VSP9K.4.2.1.4_mib.txt	MIB file	5497380
VSP9K.4.2.1.4_mib_sup.txt	MIB file	959378
VSP9000v410_HELP_EDM_gzip.zip	EDM Help file	3882169
VSP9K.4.2.1.4.md5	MD5 Checksums	741
VSP9K.4.2.1.4.sha512	SHA encryption	1989
VSP9000v4.2.0.0.zip	EDM WAR plugin for COM	5657179



## Note about image download:

Ensure images are downloaded using the binary file transfer. Perform MD5 checksum check on downloaded files to ensure file integrity.

Check that the file type suffix is ".tgz" and the image names after download to device match those shown in the above table. Some download utilities have been observed to append ".tar" to the file name or change the filename extension from ".tgz" to ".tar". If file type suffix is ".tar" or file name does not exactly match the names shown in above table, rename the downloaded file to the name shown in the table above so that the activation procedures will operate properly.

## Load activation procedure:

software add VSP9K.4.2.1.4.tgz software add-modules 4.2.1.4.GA VSP9K.4.2.1.4\_modules.tgz software activate 4.2.1.4.GA

#### 6. Version of Previous Release

Software Version 3.4.x.x, 4.0.0.0, 4.0.1.0, 4.0.1.1, 4.0.1.2, 4.1.0.0, 4.1.1.0, 4.1.2.0, 4.1.3.0, 4.1.4.0, 4.1.5.0, 4.2.0.0, 4.2.1.0, 4.2.1.1, 4.2.1.2 and 4.2.1.3.

#### 7. Compatibility

#### 8. Changes in 4.2.1.4

August 2018 PN: 9035662

**New Features in This Release** 

#### **Old Features Removed From This Release**

None



#### **Problems Resolved in This Release**

ID	Description
VSP9000-864	Any new L3VSN routes learned via SPBM are now installed correctly in the routing table when the administrator changes the ISIS route preference from a default value of 7 to another value dynamically.
VSP9000-875	An Alarm log message is generated when the switch encounters "VPE_CMD ERROR cmd_sync_send: IPC sync send failed: ND_IPC_TIMEOUT". Administrator needs to reset the slot to recover from both the error condition and clearing the message from alarm log.
VSP9000-883	A full throughput value of 10Gbps is now achieved using the 10gigSFP+ end of AA1404035-E6 DAC cable on a 9048-XS2 card.

#### 10. Outstanding Issues

Please see "Virtual Services Platform 9000, Release Notes" for software release 4.1.0.0, 4.1.1.0, 4.1.2.0, 4.1.3.0, 4.1.4.0, 4.1.5.0, 4.2.0.0, 4.2.1.0, 4.2.1.1, 4.2.1.2 and 4.2.1.3 available at <a href="https://www.extremenetworks.com/support/release-notes">https://www.extremenetworks.com/support/release-notes</a> for details regarding Known Issues.

ID	Description
VSP9000-874	Oversubscribed unicast traffic across 10G port prevents sending of local sourced High Priority VRRP Hello and OSPF Hello Multicast traffic in a timely manner and causes VRRP state and OSPF adjacencies flaps.

## 11. Known Limitations

Please see "Virtual Services Platform 9000, Release Notes" for software release 4.1.0.0, 4.1.1.0, 4.1.2.0, 4.1.3.0, 4.1.4.0, 4.1.5.0, 4.2.0.0, 4.2.1.0, 4.2.1.1, 4.2.1.2 and 4.2.1.3 available at <a href="https://www.extremenetworks.com/support/release-notes">https://www.extremenetworks.com/support/release-notes</a> for more details regarding Known Limitations.

# 12. Software Scaling Capabilities

Please see "Virtual Services Platform 9000, Release Notes" for software release 4.1.0.0 available at <a href="https://www.extremenetworks.com/support/release-notes">https://www.extremenetworks.com/support/release-notes</a> for more details regarding scaling capabilities.

#### 13. Documentation Corrections

August 2018 PN: 9035662

For other known issues, please refer to the product release notes and technical documentation available at: <a href="https://www.extremenetworks.com/support/documentation">https://www.extremenetworks.com/support/documentation</a>.



Copyright © 2018 Extreme Networks, Inc. - All Rights Reserved.

## **Legal Notice**

Extreme Networks, Inc. reserves the right to make changes in specifications and other information contained in this document and its website without prior notice. The reader should in all cases consult representatives of Extreme Networks to determine whether any such changes have been made.

The hardware, firmware, software or any specifications described or referred to in this document are subject to change without notice.

#### **Trademarks**

Extreme Networks and the Extreme Networks logo are trademarks or registered trademarks of Extreme Networks, Inc. in the United States and/or other countries. All other names (including any product names) mentioned in this document are the property of their respective owners and may be trademarks or registered trademarks of their respective companies/owners.

For additional information on Extreme Networks trademarks, please see: www.extremenetworks.com/company/legal/trademarks