



## WiNG 5.8.3.0-041R Release Notes

<b>Overview .....</b>	<b>1</b>
<b>1. Platforms Supported .....</b>	<b>1</b>
<b>2. New Features in WiNG 5.8.3 .....</b>	<b>2</b>
<b>3. Firmware Upgrade / Downgrade – Controllers and Dependent APs .....</b>	<b>6</b>
3.1 Important Notes on Upgrade / Downgrade .....	6
3.2 Upgrade/Downgrade Matrix .....	8
3.3 Upgrade/Downgrade Procedure for WLAN Controllers.....	10
3.4 Upgrade/Downgrade Procedure for dependent APs connected to RFS controllers – AP 650 ..	10
3.5 Device Upgrade Options.....	11
3.6 Auto Upgrade.....	11
3.7 AutoInstall .....	12
<b>4. Firmware Upgrade/Downgrade – Independent APs.....</b>	<b>12</b>
4.1 Important Notes on Upgrade / Downgrade .....	12
4.2 Upgrade/Downgrade Matrix .....	13
4.3 AP Upgrade/Downgrade Procedure .....	14
4.4 AutoInstall .....	14
<b>5. Upgrade / Downgrade - NSight and Captive-Portal .....</b>	<b>15</b>
5.1 Important Notes on Upgrade – Nsight and Captive Portal .....	15
5.2 Important Notes on Downgrade – NSight and Captive Portal .....	16
<b>6. Important Notes .....</b>	<b>17</b>
<b>7. DFS Tables, Sensor and Radio Share .....</b>	<b>28</b>
<b>8. Vulnerability updates .....</b>	<b>30</b>
<b>9. Issues Fixed .....</b>	<b>31</b>
<b>10. Known Issues .....</b>	<b>34</b>

### Overview

WiNG 5.8.3 is a maintenance release that continues to build on the innovative WiNG 5 architecture across the Zebra Technologies 802.11n and 802.11ac Enterprise WLAN portfolio. WiNG 5.8.3 adds support for new platforms, introduces several feature enhancements and provides critical customer fixes.

### 1. Platforms Supported

WiNG 5.8.3 supports the following platforms with the corresponding firmware images.

Note: RFS 4011 and NX 9000 platforms are end of life. No new images will be released or supported for those platforms.

Controller Platform	Firmware Image
RFS 4000	RFS4000-5.8.3.0-041R.img, RFS4000-LEAN-5.8.3.0-041R.img
RFS 6000	RFS6000-5.8.3.0-041R.img, RFS6000-LEAN-5.8.3.0-041R.img
RFS 7000	RFS7000-5.8.3.0-041R.img, RFS7000-LEAN-5.8.3.0-041R.img
NX 9500/ NX9510	NX9000-5.8.3.0-041R.img
NX 9600 / NX 9610	NX9600-5.8.3.0-041R.img, NX9600-LEAN-5.8.3.0-041R.img
NX 75XX	NX7500-5.8.3.0-041R.img, NX75XX-LEAN-5.8.3.0-041R.img
NX 5500	NX5500-5.8.3.0-041R.img, NX5500-LEAN-5.8.3.0-041R.img
NX 45XX/NX 65XX	NX65XX-5.8.3.0-041R.img



Virtual Platform	Firmware Image
VX 9000 <sup>1</sup> —production iso/img image	VX9000-INSTALL-5.8.3.0-041R.iso, VX9000--5.8.3.0-041R.img, VX9000-LEAN-5.8.3.0-041R
VX 9000 – demo iso image	VX9000-DEMO-INSTALL-5.8.3.0-041R.iso <sup>2</sup>

<sup>1</sup>VX 9000 image has default 64 AP license starting WiNG 5.8.3.

<sup>2</sup>The VX demo image is a 60-day trial image of the VX 9000 software VM that can be used for demos and in the lab environments. This image does not need any additional licenses; it comes with 16 AAP licenses built-in. There is no migration from the demo image to the production image.

WiNG Express Manager	Firmware Image
NX 5500E	NX5500E-5.8.3.0-041R.img
NX 7510E	NX7500E-5.8.3.0-041R.img
VX 9000E	VX9000E-INSTALL-5.8.3.0-041R.iso

AP Platforms	Firmware Image
Dependent APs	
AP 621	AP621-5.8.3.0-041R.img (included in all Controller images)
AP 622	AP622-5.8.3.0-041R (included in all Controller images)
AP 650	AP650-5.8.3.0-041R.img AP650-LEAN-5.8.3.0-041R.img <sup>3</sup> (included in all Controller images)
Independent /Adaptive APs	
AP 6511 / AP 6511E	AP6511-5.8.3.0-041R.img (included in NX controller images)
AP 6521 / AP 6521E	AP6521-5.8.3.0-041R.img (included in all Controller images)
AP 6522 / AP 6522E	AP6522-5.8.3.0-041R.img (included in all Controller images)
AP 6532	AP6532-5.8.3.0-041R.img AP6532-LEAN-5.8.3.0-041R.img <sup>3</sup> (included in all Controller images)
AP 6562 / AP 6562E	AP6562-5.8.3.0-041R.img (included in all Controller images)
AP 7131 / AP7161 / AP 7181	AP71XX-5.8.3.0-041R.img (included in NX controller images)
AP 7532	AP7532-5.8.3.0-041R.img (included in the NX controller images)
AP 7522	AP7522-5.8.3.0-041R.img (included in the NX controller images)
AP 7522E	AP7522E-5.8.3.0-041R.img (included in the express controller images)
AP 7562	AP7562-5.8.3.0-041R.img (included in the NX controller images)
AP 7502 / AP 7502E	AP7502-5.8.3.0-041R.img (included in the NX controller images)
AP 8132 / AP 8122 / AP 8163	AP81XX-5.8.3.0-041R.img (included in NX controller images)
AP 8222 / AP 8232	AP82XX-5.8.3.0-041R.img (included in NX controller images)
AP 8533	AP8533-5.8.3.0-041R.img (included in NX controller images)
AP 8432	AP8432-5.8.3.0-041R.img (included in NX controller images)
Independent /Adaptive Wall Switch	
ES 6510	AP6511-5.8.3.0-041R.img (ES 6510 uses AP 6511 image)

<sup>3</sup>AP6532-LEAN-5.8.3.0-041R.img / AP650-LEAN-5.8.3.0-041R.img built **without GUI component**.

## 2. New Features in WiNG 5.8.3

WiNG 5.8.3 introduces support for following new features/enhancements:

### **New AP Support – AP 8533 and AP 8432**

WiNG 5.8.3 introduces support for 802.11 Wave2 Access Points: AP 8533 and AP 8432.

The AP 8533 tri radio external antenna and internal antenna Access Points are high-tier Access Point's for dependable and efficient network performance.

The AP 8533 is a Wave2 802.11ac Access Point utilizing one 5GHz 802.11ac radio, one 2.4GHz 802.11n radio and a dual-band unlock 2.4GHz/5GHz 802.11ac radio for sensor functionality and a Bluetooth/BLE radio.



Following SKUs will be supported for the AP 8533 platform:

Internal - AP 8533	Description
AP-8533-68SB30-US	AP-8533 TRI RADIO 802.11AC WAVE2 ACCESS POINT, DEDICATED SENSOR, BLE, INTERNAL ANTENNA 2XGE, US
AP-8533-68SB30-WR	AP-8533 TRI RADIO 802.11AC WAVE2 ACCESS POINT, DEDICATED SENSOR, BLE, INTERNAL ANTENNA 2XGE, WR
AP-8533-68SB30-EU	AP-8533 TRI RADIO 802.11AC WAVE2 ACCESS POINT, DEDICATED SENSOR, BLE, INTERNAL ANTENNA 2XGE, EU
External - AP 8533	Description
AP-8533-68SB40-US	AP-8533 TRI RADIO 802.11AC WAVE2 ACCESS POINT, DEDICATED SENSOR, BLE, EXTERNAL ANTENNA 2XGE, US
AP-8533-68SB40-WR	AP-8533 TRI RADIO 802.11AC WAVE2 ACCESS POINT, DEDICATED SENSOR, BLE, EXTERNAL ANTENNA 2XGE, WR
AP-8533-68SB40-EU	AP-8533 TRI RADIO 802.11AC WAVE2 ACCESS POINT, DEDICATED SENSOR, BLE, EXTERNAL ANTENNA 2XGE, EU

The AP 8432 dual radio internal antenna Access Points are high-tier Access Point's for dependable and efficient network performance and IOT applications. The AP 8432 is a Wave2 802.11ac Access Point utilizing one 5GHz 802.11ac radio, one dual-band unlock 2.4GHz/5 GHz 802.11ac radio for sensor functionality and a Bluetooth/BLE radio, POE out and USB port.

Following SKUs will be supported for the AP 8432 platform:

Internal AP 8432	Description
AP-8432-680B30-US	AP-8432 DUAL RADIO 802.11AC WAVE2 ACCESS POINT, BAND UNLOCKED, BLE, INTERNAL ANTENNA, POE OUT, USB, 2XGE, US
AP-8432-680B30-WR	AP-8432 DUAL RADIO 802.11AC WAVE2 ACCESS POINT, BAND UNLOCKED, BLE, INTERNAL ANTENNA, POE OUT, USB, 2XGE, WR
AP-8432-680B30-EU	AP-8432 DUAL RADIO 802.11AC WAVE2 ACCESS POINT, BAND UNLOCKED, BLE, INTERNAL ANTENNA, POE OUT, USB, 2XGE, EU

Note: MU-MIMO, 160 Mhz support, MCX and MCX dependant features, LLDP on GE2, adaptivity recovery, MSTP, controller assisted mobility, AP test, Spectrum Analysis are not support in this release. AP 8432 will not support sensor radio share functionality in this software release.

Following tables represent AP 8533 and AP 8432 power management:

AP 8533	3af	3at	AP 8432	3af	3at
Radio 1	2x4	4x4	Radio 1	3x3	3x3
Radio 2	2x4	4x4	Radio 2	4x4	4x4
Radio 3	1x1	3x3	POE out	OFF	ON if configured <sup>1</sup>
BLE	ON	ON	BLE	ON	ON
GE1	ON	ON	GE1	ON	ON
GE2	ON	ON	GE2	ON	ON

<sup>1</sup>AP 8432 – to enable POE out on ge2 – use “service power-config 3af-out”.

## **New SKU Support**

WiNG 5.8.3 introduces support for outdoor rated access points for different marketing verticals.

### AP-7562-670042

The AP-7562-670042 is a new sku for the AP 7562 with a factory installed IP67 outdoor integrated antenna. The AP 7562 is designed as a 3x3:3 802.11ac AP with integrated factory installed antenna for easy installation.



AP-7562-670042 comes to simplify the outdoor installation and lower the cost to deploy outdoor access points for parking lots, and warehouse yards and warehouse freezers. Simply mount on the building wall or mount in the ceiling of a warehouse and the AP 7562 becomes part of your WiFi network.

AP-7562-670042	Description
AP-7562-670042-US	AP 7562 DUAL RADIO 802.11AC 3X3:3 MIMO OUTDOOR ACCESS POINT ANTENNA INSTALLED AT FACTORY, US
AP-7562-670042-WR	AP 7562 DUAL RADIO 802.11AC 3X3:3 MIMO OUTDOOR ACCESS POINT ANTENNA INSTALLED AT FACTORY, WR
AP-7562-670042-EU	AP 7562 DUAL RADIO 802.11AC 3X3:3 MIMO OUTDOOR ACCESS POINT ANTENNA INSTALLED AT FACTORY, EU
AP-7562-670042-IL	AP 7562 DUAL RADIO 802.11AC 3X3:3 MIMO OUTDOOR ACCESS POINT ANTENNA INSTALLED AT FACTORY, IL

AP-7562-6704M

The AP-7562-6704M is a new sku for the AP 7562 for industrial applications. The AP-7562-6704M is a version of AP-7562 with the two RJ45 connectors replaced with M12 connectors. M12 connectors are locking connectors primarily used for railway applications and other industrial applications. The AP-7562-6704M is an M12 version of the AP 7562 ruggedized IP 67 Access Point specifically designed for harsh environments requiring locking connectors for industrial applications. M12 connectors provide a reliable sturdy connection when subjected to shock and vibration.

AP-7562-6704M	Description
AP-7562-6704M-US	AP-7562 ACCESS POINT DUAL RADIO 3X3:3 MIMO 802.11AC OUTDOOR ACCESS POINT EXTERNAL ANTENNA M12 CONNECTOR, US
AP-7562-6704M-WR	AP-7562 ACCESS POINT DUAL RADIO 3X3:3 MIMO 802.11AC OUTDOOR ACCESS POINT EXTERNAL ANTENNA M12 CONNECTOR, WR
AP-7562-6704M-EU	AP-7562 ACCESS POINT DUAL RADIO 3X3:3 MIMO 802.11AC OUTDOOR ACCESS POINT EXTERNAL ANTENNA M12 CONNECTOR, EU

**SWiFT UI Enhancements**

- WiNG Assist – configuration assistance for Swift UI. Applies to WiNG Express Access Points and selected WiNG Enterprise Access Points that run the Swift UI
- DHCP Server: adds ability to provide DHCP IP exclude range
- Adds ability to enable/disable band-steering
- WiNG Express Manager - Adds ability to configure country code when creating a new site
- Support for MeshConnex (MCX) on WiNG Express Manager  
Note: In WiNG 5.8.3 – user can't configure MCX and WLAN on the same radio.
- Adds ability to configure short preamble
- WiNG Express SSID now includes last four octets of AP MAC address.
- Adds ability to set a static IP for VLAN 1
- Provides 802.11r support
- WiNG Express Manager adds provision for IP address configuration option on AP

**Critical Resource Monitoring (CRM) Enhancements**

WiNG 5.8.3 adds ability to configure unique critical resources for monitoring status on a per WLAN basis. Previous implementation only allowed one CRM to be used across all the WLANs and could not handle deployment scenarios which required CRM monitoring for guest as well as corporate WLANs as the CRM resources are going to be different for both.



## **UI Changes For AP 7532/7522/7562**

AP 7532/7522/7562 – SWiFT UI will be the default UI but user will now have an option to load the Enterprise UI on the Access Point Page of the swift UI. Device configuration will be persistent when converting from SWiFT to Enterprise UI. The return to SWiFT UI will require reset the AP to factory defaults.

AP 7522E SKU will have a separate image, and will not have an option to load Flex UI.

## **“Inter-tunnel bridging” Option For Mint Level 2 Tunnels**

WiNG 5.8.3 adds the support for a configurable option to enable “inter-tunnel bridging” when mint level 2 tunnels are used just like we support for l2tpv3 tunnels.

## **Captive Portal: Bypass Detection Support For Android Mobile Devices**

Android and iOS devices have a mechanism to detect a captive portal upon connecting to a Wi-Fi network, which displays a notification and brings up a web sheet which will display the redirected web pages for the captive portal (login/welcome pages). There are certain use-cases which require the welcome page to be displayed on a browser page vs. the web sheet and other use-cases which require certain applications to be allowed prior to the user starting a browser interaction. This feature allows a WiNG Captive Portal enabled Wi-Fi network to bypass the captive portal detection feature present in these smartphone/tablet devices thereby requiring the user to open a browser and/or allowing certain applications to go through without prompting for captive portal sign on.

Existing implementation only supported this feature for iOS devices, WiNG 5.8.3 extends the same feature to support Android devices as well.

## **Enhanced Purge Functionality For Guest Management Registered Users**

WiNG guest management allows to purge the registered users from the database based on user profile fields, 5.8.3 extends the functionality to include the following additional filter options:

1. users who haven't accessed the network for x number of days.
2. users record belongs to a particular user group.
3. user's registered through non-social/social authentication(facebook/google)
4. incomplete registration documents(one that are not used the One-Time-Password)

## **Guest Management - Support Notification via SMTP Relay Server**

WiNG 5.8.3 adds support to send the Email/SMS-Over-Email using the SMTP relay server that doesn't require any authentication or encryption mechanism for communication.

## **IGMP Leave**

AP 7502 will now support IGMP Fast Leave processing for wired clients. When enabled for IGMP Snooping with Fast Leave support, AP will process Leave requests from a connected IGMP Host and remove the multicast address from the Ethernet interface immediately. When enabled for IGMP Snooping without Fast Leave support, AP will process Leave requests according to the published recommendations in RFC 4541. This feature is specifically targeted for IPTV kind of deployment on AP7502, where on each FE port on AP7502 there is as separate STB connected.



### **Automatic creation of RF-Domain entries in controller configuration:**

Ability for automatically creating RF-Domain configuration entries in the controller configuration when an AP adopts with an auto-provisioning rule that uses wildcards and no matching RF-Domain entry is found. The configuration for all such rf-domains created will follow a default rf-domain template that is referenced in the auto-provisioning policy. This functionality is off by default, i.e. if matching rf-domain entries are not found in the controller configuration, devices will remain in “Adoption Pending” state.

### **Ekahau Support for AP 7532/7522/7562**

WiNG 5.8.3 adds support for Ekahau Blink mode for AP 7532, AP 7522 and AP 7562.

### **VX 9000 Default License**

VX 9000 will be pre-loaded with 64 AP adoption license.

## **3. Firmware Upgrade / Downgrade – Controllers and Dependent APs**

### ***3.1 Important Notes on Upgrade / Downgrade***

1. WiNG 5.8.2 and above - Upgrading AP 6532 / AP 650
  - o WiNG 5.8.2 and above mitigates AP 6532 image size issue by introducing 2 different images:
    - o *AP6532-LEAN-5.8.3.0-041R.img*: built without the GUI component and is included in the controller images
    - o *AP6532-5.8.3.0-041R.img*: standard image, however without the GUI help files, for independent APs that require GUI support.
  - o Controller based deployment:
    - o Upgrade the AP with *AP6532-LEAN-5.8.3.0-041R.img* image (included in the controller images).
    - o Once upgraded, if the non-active (Secondary) flash partition has image version prior to WiNG 5.7.2, load *AP6532-LEAN-5.8.3.0-041R.img* image to the partition.
2. WiNG 5.8.1 changes default RAID configuration for NX 9600 from RAID 5 to RAID 10 to improve performance. Note: RAID configuration cannot be changed upon upgrade or downgrade.  
NX 9600 controllers manufactured with v5.8.1 or above will have RAID 10 configured. NX 9600 controllers manufactured with v5.5.6 will have RAID 5 configured. RAID configuration can only be changed by authorized Zebra personnel.
3. DHCP Vendor Class changes  
DHCP Vendor Class Identifier has been changed in WiNG 5.7.1 and later to use “Wing” instead of Motorola (5.7)/Zebra (5.5.6) to be consistent with rest of re-branding changes, e.g. WingAP.AP7532, WingAP8132, WingRFS.RFS4000 and etc.  
Note: DHCP vendor class should be modified on DHCP servers prior to upgrading APs.
4. When downgrading from WiNG 5.7.2 (or newer) to WiNG 5.7.1 (or older), the SNMP trap host configuration will need to be re-applied due to the newly introduced encrypted community string option.
  - v5.7.2 (or newer):

```
(config-management-policy-default)#snmp-server host 1.1.1.1 v2c community ?  
0 Enter a clear text trap community name  
2 Enter an encrypted trap community name  
WORD Enter Trap Community Name
```
  - v5.7.1 (or older):

```
(config-management-policy-default)#snmp-server host 1.1.1.1 v2c community ?
```

*WORD Enter Trap Community Name*

5. When downgrading an RFS 4000 from WiNG 5.8 to WiNG 5.7, the user first needs to downgrade the RFS 4000 to WiNG 5.7.2 before moving to WiNG 5.7.
6. Prior to upgrading to WiNG 5.7.1 or above if you have Onboard-Radius Server with LDAP Authentication configured, please note the following:  
  
"(sAMAccountName=%{Stripped-User-Name:-%{User-Name}})" – is not supported.  
"(sAMAccountName=%{Stripped-User-Name})" – is supported.  
  
Configurations using "(sAMAccountName=%{Stripped-User-Name:-%{User-Name}})" need to be updated to "(sAMAccountName=%{Stripped-User-Name})" prior to performing the upgrade process.
7. When downgrading from WiNG 5.8 to WiNG 5.5.5 or WiNG 5.5.4 on AP 7532/7522, the user needs to apply patch **AP75XX-CPU-Bringup-1.0.patch**.  
AP 7532/7522 running wing 5.5.6/5.7.x has an updated kernel version and the patch is required when the AP downgrades to a firmware with a prior kernel version.  
Steps to apply the patch:
  - Load the kernel patch for AP 7532/7522 device models on controller using device-upgrade load-image option:
    - "device-upgrade load-image ap7522 tftp://<server ip address >/AP75XX-CPU-Bringup-1.0.patch"
  - Execute "device-upgrade all force no-reboot" from the controller to upgrade the APs with the patch.
  - Use "boot system primary" or "boot system secondary" based on the WiNG 5.5.5/5.5.4 image location on the APs and reload the APs from the controller.
8. When downgrading from WiNG 5.8.x to a version prior to WING 5.4.x through rf-domain, the user needs to downgrade without reloading APs and then do a manual reload on the rf-domain. The following are the CLI commands for this procedure:  
device-upgrade rf-domain <RF domain name> all no-reboot ... this downgrades all APs (including the RF domain manager) without rebooting them  
reload on <RF domain name> ... this reboots the entire RF domain.  
Staggered reboot option is not supported in this downgrade scenario.
9. Firmware upgrades can take several minutes; aborting an update by removing power may damage the AP or controller. Please allow time for devices to complete the upgrade. Where APs are powered through PoE connections to WLAN controllers, the controller needs to stay up during the upgrade process.
10. Both the controller and the AP should be upgraded to the same versions – a firmware mismatch can cause network disruptions and should be avoided. When upgrading, the controllers should be upgraded first and then the APs. When downgrading, the APs should be downgraded first, and then the controller.
11. In Virtual Controller deployments, APs running version 5.4.x will not adopt to a virtual controller running WiNG v5.8. First upgrade APs to WiNG v5.8 (manually) and then upgrade the Virtual Controller. New APs need to be upgraded to 5.5.x manually before connecting to a WiNG 5.8 Virtual Controller network.
12. Downgrade to WiNG 4 is not recommended in countries following ETSI regulations as WiNG 4 is not compliant with current ETSI DFS regulations.

### 3.2 Upgrade/Downgrade Matrix

This section documents allowed upgrade/ downgrade combinations. Please ensure that the controller and AP are on the same WiNG version after the upgrade is complete.

Dependent/Adaptive with the RFS controller	Upgrade from	Downgrade to	Notes
RFS + AP 650	v4.3.x onwards on the controller	v4.3.x onwards on the controller	AP 650 image is contained within the controller image
RFS + AP 7131/AP 7131N	v4.1.1 onwards on the AP v4.3.x onwards on the controller	v4.1.1 onwards on the AP v4.3.x onwards on the controller	AP 7131/AP 7131N v5.x image is not within the controller image
RFS + AP 6532	v5.1 onwards	v5.1 onwards	AP 6532 image is contained within the controller image
RFS + AP 6511	v5.1 onwards	v5.1 onwards	AP 6511 image is not contained within the controller image
RFS + ES 6510	v5.4 and higher	v5.4 and higher	ES 6510 uses the same image file as the AP 6511. The image is not contained within the controller image
RFS 4011 with AP 650	v5.1 onwards	v5.1 onwards	
RFS/NX 9XXX + AP 7181 Controllers need to be on 5.4 to be able to adopt AP 7181.	v5.4 onwards	v5.4 onwards	Controller assistance is not available for upgrade from 3.2.2 to 5.4. This can be performed standalone or with Wireless Manager.
RFS/NX 9XXX + AP 7161	v5.1.1, v5.1.4, v5.2 onwards	v5.1.1, v5.1.4, v5.2 onwards	
RFS/NX 9XXX + AP 6521/AP 621	v5.2 onwards	v5.2 onwards	AP 6521 image is contained within the controller image
RFS/NX 9XXX + AP 6522	v5.4 onwards	v5.4 onwards	AP 6522 image is contained within the controller image
RFS/NX 9XXX + AP 6562	v5.4.4 onwards	v5.4.4 onwards	AP 6562 image is contained within the controller image
RFS/NX 9XXX + AP 622	v5.2.3, v5.2.13 or 5.4 and higher.	v5.2.3, v5.2.13 or 5.4 and higher.	AP 622 image is contained within the controller image. WiNG 5.3.x does not support AP 622





Dependent/Adaptive with the RFS controller	Upgrade from	Downgrade to	Notes
NX 45XX/NX 65XX + AP 7131, AP 6532, AP 650, AP 6511, AP 6521, AP 621	v5.2.4, 5.4.2 and higher	v5.2.4	AP images are contained within the controller image
NX 45XX/NX 65XX + AP 7181, AP 7161, AP 6522, AP 622, AP 6562, AP 8132	v5.4.4 and higher	v5.4.4	AP images are contained within the controller image
RFS/ NX + AP 8132	v5.2.6, 5.4.2 and higher	v5.2.6, 5.4.2 and higher	AP 8132 image is not within the RFS controller image, but is contained within NX controller image
RFS/ NX + AP 82XX	v5.5.3 and higher	v5.5.3 and higher	AP 82XX image is not within the RFS controller image, but is contained within NX controller image
RFS/ NX + AP 8122	v5.5.2 and higher	v5.5.2 and higher	AP 8122 image is not within the RFS controller image, but is contained within NX controller image
NX7500	v5.5.2 and higher	v5.5.2 and higher	Note: WiNG 5.6 doesn't support NX 7500.
RFS/NX + AP 7532/AP 7522	v5.5.3.1 and higher, excluding v5.6.x	v5.5.3.1 and higher, excluding v5.6.x	AP image is contained within the NX controller image in v5.5.4
RFS/NX + AP 7562	v5.7.1 and higher	v5.7.1 and higher	AP image is contained within the NX controller image in v5.7.1
RFS/NX + AP 7502	v5.5.4.1 and higher, excluding v5.6.x	v5.5.4.1 and higher, excluding v5.6.x	AP image is contained within the NX controller image in v5.5.5
RFS/ NX + AP 8163	v5.6 and higher	v5.6 and higher	AP 8163 images are not within the controller image
VX + all supported APs	v5.6 and higher	v5.6 and higher	
NX 7510E/VX 9000E/NX 5500E + AP 6511E / AP 6521E / AP 6522E / AP 6562E / AP 7502E / AP 7522E	v5.5.3 and higher	-	NX 7510E and VX 9000E are supported starting with v5.7 NX 5500E is supported starting with v5.8
NX 96XX	v5.5.6 and higher	v5.5.6	NX 96XX is not supported with v5.6.x and v5.7.x

Dependent/Adaptive with the RFS controller	Upgrade from	Downgrade to	Notes
NX 5500	v5.8	v5.8	NX 5500 is supported starting with 5.8
RFS/NX + AP 8533	v5.8.3 and higher	v5.8.3 and higher	AP image is contained within the NX controller image in v5.8.3
RFS/NX + AP 8432	v5.8.3 and higher	v5.8.3 and higher	AP image is contained within the NX controller image in v5.8.3

### 3.3 Upgrade/Downgrade Procedure for WLAN Controllers

Customers upgrading from an earlier WiNG 5 release not requiring ONEVIEW, the procedure is the same as before.

Customers using ONEVIEW in WiNG 5.5, please see the WiNG 5.5 training for details of upgrade/downgrade. **Note in particular the use of the “Lean Controller image” which does not include AP images** – since the controller image size is now significantly larger than WiNG 5.4.x release.

The method described in this section uses the Command Line Interface (CLI) procedures. To log into the CLI, either SSH, Telnet or serial access can be used.

**IMPORTANT:** Always create config back-up before upgrade.

1. Copy the RFSX000-5.8.X.X-0XXR.img or NXXX00-5.8.X.X-0XXR.img to your tftp/ftp server.
2. Use the `—upgrade ftp://<username>:<password>@<ip address of server>/<name of file>`, or `—upgrade tftp://<ip address of server>/<name of file>` command from CLI or `Switch->Firmware->Update Firmware` option from the GUI. You may need to specify the username and password for your ftp server.
3. Restart the controller. From CLI the command is `—reload`.

### 3.4 Upgrade/Downgrade Procedure for dependent APs connected to RFS controllers – AP 650

Note: If upgrading from any of the following releases 4.x, 5.0.x, 5.1.x, 5.2.0.x, 5.2.1.x, 5.2.3.x, 5.2.4.x, 5.2.6.x, 5.2.11.x, 5.2.12.x, 5.2.21.x or 5.3.x, you need to upgrade to 5.2.13 or 5.4.x before upgrading to 5.8.

A WiNG 5.x controller can upgrade an AP 650 running 4.x code to 5.x using the WISPe upgrade. This capability is enabled using "legacy-auto-update" command for the controller, either under the device or profile. The controller will first adopt the access point using the standard WISPE protocol messages (just as a 4.x controller would adopt it) and then download the new image to it, which would convert the AP to WiNG 5.x version of code.

**Legacy-auto-update is enabled by default.** If legacy-auto-update is disabled, use the following CLI instructions to enable the Legacy-auto-update feature:

```
rfs4000-22A136#configure terminal
Enter configuration commands, one per line. End with CNTL/Z.
rfs4000-22A136(config)#profile rfs4000 default-rfs4000
rfs4000-22A136(config-profile-default-rfs4000)#legacy-auto-update
rfs4000-22A136(config-profile-default-rfs4000)#commit
rfs4000-22A136(config-profile-default-rfs4000)#
```

**Important:** In WiNG 5.4.x – please enable FTP server on the controller for legacy-auto-update to work.

### 3.5 Device Upgrade Options

WiNG 5.x supports device firmware upgrade from the controller. For firmware upgrade through controller, firmware image needs to be loaded onto a controller and the same can be used for the upgrade of all the corresponding devices.

Available firmware on the controller can be checked using the below command:

```
nx9500-6C8647#show device-upgrade versions
```

If device firmware is not part of controller image, a new image can be uploaded using following command:

```
nx9500-6C8647# device-upgrade load-image
```

Once device firmware is loaded on the controller, below are the different options that are available for device firmware upgrade:

- **Manual Upgrade**

Firmware upgrade can be initiated on a single or a list of Aps using the below command.

```
nx9500-6C8647# device-upgrade ap71xx-16C7B4 ?  
no-reboot      No reboot (manually reboot after the upgrade)  
reboot-time    Schedule a reboot time  
upgrade-time   Schedule an upgrade time
```

```
nx9500-6C8647# device-upgrade ap71xx all ?  
force          Force upgrade on all devices  
no-reboot      No reboot (manually reboot after the upgrade)  
reboot-time    Schedule a reboot time  
staggered-reboot Reboot one at a time without network being hit  
upgrade-time   Schedule an upgrade time
```

- **Scheduling Firmware upgrade**

Firmware upgrade can be scheduled on a controller, that is upgrade time and reboot time can be configured. Firmware upgrade on the Aps follows the configured upgrade time.

```
nx9500-6C8647# device-upgrade all ?  
no-reboot      No reboot (manually reboot after the upgrade)  
reboot-time    Schedule a reboot time  
staggered-reboot Reboot one at a time without network being hit  
upgrade-time   Schedule an upgrade time
```

- **Upgrade through RF Domain manager**

Manual Firmware upgrade can be initiated through a domain manager

```
nx9500-6C8647# #device-upgrade rf-domain ?  
DOMAIN-NAME   RF-Domain name  
all            Upgrade all RF Domains  
containing     Specify domains that contain a sub-string in the domain name  
filter         Specify additional selection filter
```

### 3.6 Auto Upgrade

Auto firmware upgrade can be enabled on the controller using the below command. When enabled, any AP with a firmware version different than the controller will be upgraded to the controller's version on adoption.

```
rfs4000-22A1B8(config-device-XXX)# device-upgrade auto
```

The number of concurrent firmware upgrades can be configured using the below command based on the bandwidth available between the controller and the Aps.

```
rfs4000-22A1B8(config-device-XXX)# device-upgrade count ?  
<1-20> Number of concurrent AP upgrades
```

**Note: Auto upgrade on the APs always happens through the controller.**



### 3.7 AutoInstall

AutoInstall in WiNG 5 works via the DHCP server. This requires the definition of Vendor Class and three sub-options that can be either sent separately, or under option 43:

Option 186 - defines the tftp/ftp server and ftp username, password information (IP address and protocol need to enter as a string: —ftp://admin:admin123@192.168.1.10|)

Option 187 - defines the firmware path and file name

Option 188 - defines the config path and file name

Autoinstall of firmware and autoinstall of configuration can be enabled or disabled. Ensure to enable “ip dhcp client request options all” on the VLAN interface which is being used to perform the above autoinstall.

DHCP vendor class for platforms is noted below:

- WingRFS.RFS4000
- WingRFS.RFS6000
- WingRFS.RFS7000
- WingNX.NX4500
- WingNX.NX4524
- WingNX.NX6500
- WingNX.NX6524
- WingNX.NX7500
- WingNX.NX9000
- WingNX.VX
- WingNX.NX5500

## 4. Firmware Upgrade/Downgrade – Independent APs

### 4.1 Important Notes on Upgrade / Downgrade

1. WiNG 5.8.2 and above - Upgrading AP 6532
  - WiNG 5.8.2 and above mitigates AP 6532 image size issue by introducing 2 different images:
    - *AP6532-LEAN-5.8.3.0-041R.img*: built without the GUI component and is included in the controller images
    - *AP6532-5.8.3.0-041R.img*: standard image, however without the GUI help files, for independent APs that require GUI support.
  - Standalone/Independent AP deployment:
    - AP can be upgraded using *AP6532-5.8.3.0-041R.img* image. However, AP must be upgraded to a version WiNG 5.5.4 or above prior to upgrading to WiNG 5.8.2
    - Once upgraded, if the non-active (Secondary) flash partition has image version prior to WiNG 5.7.2, load *AP6532-5.8.3.0-041R.img* image to the partition
2. WiNG 5.8.1 added support for new NAND chipset for AP 8122, AP 8132, AP 8163, AP 8222 and AP 8232. APs manufactured with new NAND cannot be downgraded to prior version.
3. When downgrading from WiNG 5.7.2 (or newer) to WiNG 5.7.1 (or older), the SNMP trap host configuration will need to be re-applied due to the newly introduced encrypted community string option.
  - v5.7.2 (or newer):

```
(config-management-policy-default)#snmp-server host 1.1.1.1 v2c community ?  
0 Enter a clear text trap community name  
2 Enter an encrypted trap community name  
WORD Enter Trap Community Name
```
  - v5.7.1 (or older):

```
(config-management-policy-default)#snmp-server host 1.1.1.1 v2c community ?  
WORD Enter Trap Community Name
```
4. When downgrading from WiNG 5.8 to WiNG 5.5.5 or WiNG 5.5.4 on AP 7532/7522, the user needs to apply kernel patch **AP75XX-CPU-Bringup-1.0.patch**.



AP7532/AP7522 running wing 5.5.6/5.7.x has an updated kernel version and the patch is required when the AP downgrades to a firmware with a prior kernel version.

Steps to apply the patch:

- Copy AP75XX-CPU-Bringup-1.0.patch to your tftp server.
- Apply the patch using upgrade command:
  - “upgrade tftp://<server ip address >/AP75XX-CPU-Bringup-1.0.patch”
- Use “boot system primary” or “boot system secondary” based on the WiNG 5.5.5/5.5.4 image location on the AP and reload.

5. When downgrading from WiNG 5.5.x to a lower WiNG 5.x version through rf-domain, the user needs to downgrade without reloading APs and then do a manual reload on the rf-domain. The following are the CLI commands for this procedure:

*device-upgrade rf-domain <RF domain name> all no-reboot ...* this downgrades all APs (including the RF domain manager) without rebooting them

*reload on <RF domain name> ...* this reboots the entire RF domain.

Staggered reboot option is not supported in this downgrade scenario.

6. Firmware upgrades can take several minutes; aborting an update by removing power may damage the AP. Please allow time for devices to complete the upgrade.
7. Upgrade for AP 6532 from release prior to v5.2.13 directly to v5.4.x or later is NOT seamless and requires additional steps. AP should first be updated to WiNG 5.2.13 image.
8. Downgrade to WiNG 4 is not recommended in countries following ETSI regulations as WiNG 4 is not compliant with current ETSI DFS regulations.

## 4.2 Upgrade/Downgrade Matrix

Independent/Adaptive Access Point	Upgrade from	Downgrade to	Notes
AP 6511	v5.1 onwards	v5.1 onwards	
ES 6510	v5.4 onwards	v5.4 onwards	
AP 6521	v5.2.x onwards	v5.2.x onwards	
AP 6522	v5.4 onwards	v5.4 onwards	
AP 6532	v5.1 onwards	v5.1 onwards	See Note 2
AP 6562	v5.4.4 onwards	v5.4.4 onwards	
AP 7131	v4.1.1 onwards	v4.1.1 onwards	
AP 7161	v5.1.1 (adaptive) v5.1.4 (adaptive) v5.2 onwards	v5.1.1 (adaptive) v5.1.4 (adaptive) v5.2 onwards	
AP 7181	v5.4 onwards	v5.4 onwards	See Note 1.
AP 7502	v5.5.5 onwards	v5.5.5 onwards	No support in v5.6.x
AP 7532/ AP 7522	v5.5.3.1 onwards	v5.5.3.1 onwards	No support in v5.6.x
AP 7562	v5.7.1 onwards	v5.7.1 onwards	
AP 8132	v5.2.6, 5.4.2 onwards	v5.2.6	
AP 8122	v5.5.2 onwards	v5.5.2 onwards	
AP 8222/AP 8232	v5.5.3 onwards	v5.5.3 onwards	
AP 8163	v5.6 onwards	v5.6 onwards	



Independent/Adaptive Access Point	Upgrade from	Downgrade to	Notes
AP 6511E / AP 6521E / AP 6522E / AP 6562E / AP 7502E / AP 7522E	v5.5.3 onwards	v5.5.3 onwards	
AP 8533	v5.8.3 onwards	v5.8.3 onwards	
AP 8432	v5.8.3 onwards	v5.8.3 onwards	

Notes:

1. AP 7181 - WLAN Controller assistance is not available for upgrade from 3.2.3 to 5.4.x. This upgrade can be performed standalone or with Wireless Manager. The migration process will convert the necessary settings/configuration to maintain mesh connectivity. Please refer to section 4.3.3.
2. If upgrading from any of the following releases 5.0.x, 5.1.x, 5.2.0.x, 5.2.1.x, 5.2.3.x, 5.2.4.x, 5.2.6.x, 5.2.11.x, 5.2.12.x, 5.2.21.x or 5.3.x, you need to upgrade to 5.2.13 or 5.4.x before upgrading to 5.5.x.

### 4.3 AP Upgrade/Downgrade Procedure

The method described in this section uses the Command Line Interface (CLI) procedures. To log into the CLI, either SSH, Telnet or serial access can be used.

1. Copy the APXXXX-5.8.X.X-0XXR.img to your tftp/ftp server.
2. Use the **—upgrade ftp://<username>:<password>@<ip address of server>/<name of file>**, or **—upgrade tftp://<ip address of server>/<name of file>** command from CLI or **AccessPoint->Firmware->Update Firmware** option from the GUI. You may need to specify the username and password for your ftp server.
3. Restart the Access Point. From CLI the command is **—reload**.

Note: WiNG 5.1.3 added support for the new NAND for AP 7131N. WiNG 5.1.4 added support for the new NAND for AP 7161. Hardware revs with the new NAND will be unable to downgrade below these versions or version 4.1.5 – as these support the new NAND, but previous versions do not.

Note: WiNG 5.5.2 added support for new NAND for AP 8XXX platforms. Downgrade to prior releases on hardware with new NAND will be prevented.

### 4.4 AutoInstall

AutoInstall in WiNG 5 works via DHCP. This requires the definition of Vendor Class and three sub-options that can be either sent separately, or under option 43:

Option 186 - defines the tftp/ftp server and ftp username, password information (IP address and protocol need to be entered as a string: **—ftp://admin:admin123@192.168.1.10||**)

Option 187 - defines the firmware path and file name

Option 188 - defines the config path and file name

Autoinstall of firmware and autoinstall of configuration can be enabled or disabled. Ensure to enable “ip dhcp client request options all” on the vlan interface which is being used to perform the above autoinstall.

DHCP vendor class for platforms is noted below:

- WingAP.AP6511
- WingAP.AP6521
- WingAP.AP6522
- WingAP.AP6562
- WingAP.AP6532
- WingAP.AP7131
- WingAP.AP7161
- WingAP.AP7181
- WingAP.AP7502
- WingAP.AP7522
- WingAP.AP7532
- WingAP.AP7562
- WingAP.AP8122
- WingAP.AP8132
- WingAP.AP8222
- WingAP.AP8232
- WingAP.AP8163
- WingAP.AP8533
- WingAP.AP8432

## 5. Upgrade / Downgrade - NSight and Captive-Portal

### 5.1 Important Notes on Upgrade – Nsight and Captive Portal

1. Upgrading from WiNG 5.8.2 to WiNG 5.8.3 - NSight
  - Upgrade all devices to new firmware using the upgrade command. DO NOT reboot the devices.
  - Disable NSight-server on both primary and secondary replica-set members:

*Primary #self*

*Enter configuration commands, one per line. End with CNTL/Z.*

*Primary (config-device-00-0C-29-35-AE-F6)#no use nsight-policy*

*Primary (config-device-00-0C-29-35-AE-F6)#comm wr*

*Primary (config-device-00-0C-29-35-AE-F6)#end*

*Secondary #self*

*Enter configuration commands, one per line. End with CNTL/Z.*

*Secondary (config-device-00-0C-29-35-AE-F7)#no use nsight-policy*

*Secondary (config-device-00-0C-29-35-AE-F7)#comm wr*

*Secondary (config-device-00-0C-29-35-AE-F7)#end*

- Reboot the primary replica-set member and wait for the device to come up and join the replica-set. Make sure that the replica-set is up before rebooting the secondary replica-set member. Use the below mentioned command to verify:

*Primary#sh database status*

<i>MEMBER</i>	<i>STATE</i>	<i>ONLINE TIME</i>
<i>192.168.210.200*</i>	<i>PRIMARY</i>	<i>0 hours 2 min 17 sec</i>
<i>192.168.210.201</i>	<i>SECONDARY</i>	<i>15 hours 15 min 53 sec</i>
<i>192.168.210.203</i>	<i>ARBITER</i>	<i>15 hours 47 min 16 sec</i>

*[\*] indicates this device.*

*Secondary#sh database status*

<i>MEMBER</i>	<i>STATE</i>	<i>ONLINE TIME</i>
<i>192.168.210.200</i>	<i>PRIMARY</i>	<i>0 hours 2 min 17 sec</i>
<i>192.168.210.201 *</i>	<i>SECONDARY</i>	<i>15 hours 15 min 53 sec</i>
<i>192.168.210.203</i>	<i>ARBITER</i>	<i>15 hours 47 min 16 sec</i>

*[\*] indicates this device.*

- Reboot the secondary and wait for the device to come up and join the replica-set. As mentioned in in the previous step, verify that the replica-set is up using 'sh database status' command.
- Reboot the Arbiter and wait for the device to come up and join the replica-set.
- Enable nsight-server on both primary and secondary:

*Primary #self*

*Enter configuration commands, one per line. End with CNTL/Z.*

*Primary (config-device-00-0C-29-35-AE-F6)# use nsight-policy <nsight-policy>*

*Primary (config-device-00-0C-29-35-AE-F6)#comm wr*

*Primary (config-device-00-0C-29-35-AE-F6)#end*

*Secondary #self*



```
Enter configuration commands, one per line. End with CNTL/Z.
Secondary (config-device-00-0C-29-35-AE-F7)#use nsight-policy <nsight-policy>
Secondary (config-device-00-0C-29-35-AE-F7)#comm wr
Secondary (config-device-00-0C-29-35-AE-F7)#end
```

## 2. Upgrading from 5.8.0/5.8.1 to WiNG 5.8.2 or later

The database file definitions for NSight and Captive Portal in WiNG 5.8.2 have been changed:

- There is no portability of NSight data from the earlier versions (WiNG 5.8.0 and WiNG 5.8.1). In the case of needing to downgrade to WiNG 5.8.0 or WiNG 5.8.1, user must do a database backup before upgrading to WiNG 5.8.2 or later.
- For Captive Portal data, user must do a database backup (export using JSON format) from the earlier versions (WiNG 5.8.0 and WiNG 5.8.1) before upgrading to WiNG 5.8.2, and can be imported after the upgrade.

The following are upgrade steps for NX 7500, NX 9500 and NX 9600 (please refer WiNG 5.8.1 notes and ensure NX 9600 is configured for RAID10):

- Load WiNG 5.8.2 or later image on to the device using upgrade and reload commands:  
*Upgrade tftp://<server-ip-address>/NX9XXX-5.8.2.0-030R.img*
- After the device reloaded and prompt appears, execute the following commands. The device will reload after the last command:  
*service database server stop*  
*service database remove-all-files*  
*All database files will be removed, do you want to continue? (y/n): y*

VX 9000 requires re-install using the VX9000-INSTALL-5.8.3.0-041R.ISO image due to changes to the flash partition (25% of the allocated disk size – 4GBMin, 128GB Max) to take effect:

- Export configuration before reinstalling the VX.
- To preserve the same MAC address (and therefore the serial number for licensing)
  - Delete current hard disk from the VM
  - Add new virtual hard disk
  - Connect ISO file as virtual CD
  - Boot into CD to start installation process
  - After installation is complete, restore configuration from backup

## 5.2 Important Notes on Downgrade – NSight and Captive Portal

When downgrading from WiNG 5.8.2 to a lower versions of WiNG, following are the downgrade steps needed for NX 7500 (for Captive Portal), NX 9500, NX 9600 and VX 9000, if NSight or Captive portal are enabled

- Backup the database for any future use
- Load the required image version on to the device using upgrade and additional commands listed below:  
*upgrade tftp://<server-ip-address>/<filename>*  
*no use nsight-policy (Needed only if Nsight was enabled)*  
*commit write*  
*service database server stop*  
*service database remove-all-files*  
*All database files will be removed, do you want to continue? (y/n): y*
- After the device reload, restore the captive portal database, and the device is ready for deployment.



## 6. Important Notes

### New in v5.8.3

1. HTTPS connections will use TLS 1.2 ciphers by default. To allow backward compatibility for non TLS 1.2 capable devices to connect– configure in management policy, “no https use-secure-ciphers-only”.
2. Added an event log message to report an error condition when an ACL using alias (network, network-group etc) definitions results in expanding to more than 500 rules per ACL. The ACL will not get applied and the following log message is generated (event history/syslog) – “ACL rules exceeded the maximum limit; reduce the rules for ACL to get installed”.
3. EX 3500 and T5 adoption running non TLS1.2 compatible version will need to have “no https use-secure-ciphers-only” configured to get adopted.
4. NSight: In addition to being able to search for a mac-address in the global search box using 11-22-33-44-55-66/11:22:33:44:55:66/112233445566 formats, now a user can search using the Cisco MAC Address format 1122.3344.5566 as well.
5. Added a CLI command in mint global policy to enable/disable the checksum validation for certain mint control packets such as LSP .  
To ensure the integrity of the LSP packets received checksum is added as an optional field.  
[no] lsp checksum
6. The ftp server throttles simultaneous connection from same host to a limit and it is implementation specific. The new CLI can be used to configure the simultaneous connection to a FTP server.  
  
remote-debug max-ftp-sessions <1-400>  
  
[no] remote-debug max-ftp-sessions  
  
device-override remote-debug max-ftp-sessions
7. SSH diffie-hellman-group1-sha1 key exchange algorithm was removed due to this older SSH applications might not work with WiNG 5.8.3 and customer will need to update to use newer more secure versions of SSH clients.

### New in v5.8.2

1. Zebra NSight – please refer to “Zebra NSight Deployment guide” posted on Support site under product manuals.
2. Application Visibility
  - In bridge-mode tunnel setup where Application Visibility is enabled on the controller, APs will also have to be enabled for application visibility (DPI engine support on the platform is required) for Wireless Client statistics
  - Number of clients and top client information may be missing from certain entries on all application list. This may happen when the application is detected on the wired side or in the case where the usage for this application is very minimal.
3. VX-9000
  - Not supported on Amazon instance type C4 due to kernel limitation
  - Secondary storage: VX 9000 has disk size limitation on the default disk of 2TB. However, when a secondary virtual disk is used, VX 9000 can support disks size larger than 2TB
    - Enabling secondary storage does not copy data files to the new location
    - It is recommended immediately after provisioning the guest instance, before enabling NSight or Captive-Portal

- If the secondary storage needs to be enabled after NSight/Captive-portal, it is recommended to backup the database, and restore the database after secondary storage is enabled.
  - If the VX 9000 instance is not a primary (replica-set member), the database server will perform full data sync after it is restarted with the new secondary storage disk
  - VX 9000 requires re-install using the VX9000-INSTALL-5.8.3.0-041R.ISO image, if the user intends to configure NSight / Captive portal functionality. This is due to the changes to the flash partition (25% of the allocated disk size – 4GBMin, 128GB Max) to take effect:
    - Export configuration before reinstalling the VX.
    - To preserve the same MAC address (and therefore the serial number for licensing)
      - Delete current hard disk from the VM
      - Add new virtual hard disk
      - Connect ISO file as virtual CD
      - Boot into CD to start installation processAfter installation is complete, restore configuration.
4. Multi-byte (Chinese Character) SSID
    - Max limit of 64 character length for multi-byte SSID
    - Known limitation with Windows 7 Clients: Available Networks UI display unexpected characters for multi-byte SSID
  5. SWIFT UI
    - Adoption mode under basic settings will take effect with pressing commit button twice.
  6. Import running configuration function is supported only through the CLI.

#### **New in v5.8.1**

1. Some mobile devices (Apple) that use LDAP EAP-TLS as primary means of authentication can fail authenticating to WiNG controller. Work around would be configure authentication type as PEAP-MSCHAPv2 on the controller when using LDAP.
2. AP7522, AP7532, AP7562, AP8232, AP 8222 and AP7502 do not support multiple SSIDs per BSSID due to restrictions enforced by the chipset/driver.  
WiNG 5.8.1 adds commit time validation for multiple SSIDs per BSS for AP 7522, AP 7532, AP 7562, AP 82xx and AP 7502 and will throw an error if misconfiguration is detected.
3. Adaptivity recovery on/off command gives the user ability to configure adaptivity recovery. When adaptivity recovery is turned off, if radio enters adaptivity mode then it will not switch channels. By default – this feature is enabled..
4. WiNG 5.8.1 adds GUI support for psk key overrides per rf-domain.
5. LDAP chase referral has been disabled by default in all platforms to address memory and authentication related issues. It can be enabled if necessary under radius server policy.
6. If the CLI command - "upgrade <URL> on <device-name>" is being used then please note it has been changed to "upgrade <URL> <device-name ...>".
7. Added additional filters to be used on rf-domain when remote-debug is done on rf-domain. Additional filters include area, floor, and containing field which takes a substring of hostname and selects devices matching that hostname string to run remote-debug.

#### **New in v5.8**

1. Zebra NSight
  - Zebra NSight is supported on the NX 9500, NX 9600 and VX 9000 platforms with the following scale limits:
    - VX 9000 : Supports up to 10,000 APs (@ 500 RF domains) / 5,000 (@ 1000 RF domains)
    - NX 9500 : Supports up to 6,000 APs (@ 200 RF domains)
    - NX 9600 : Supports up to 3,000 APs (@ 200 RF domains)***[Note: NSight scale numbers are relatively lower in NX 9600 than NX 9500 due to IOPS limits in RAID5 disk configuration. Future WiNG releases will change RAID configuration in NX 9600 to RAID1+0 for improved IOPS]***

- Zebra NSight license is preloaded in WiNG 5.8 (platforms: NX 9500, NX 9600, VX 9000) for immediate use, limited to 120 days from the date of install. The user is expected to purchase and install required number of Zebra NSight subscription license for continued operation.
  - New dashboard created via one browser session will not be visible/available on a different, already open session. It will be available for any new session logins.
  - The filters, for instance – selecting a specific WLAN, on the Dashboard widgets will apply even when the user moves across sites/levels on the left-side navigation tree.
  - *Top/bottom 10 grid tables in the summary page (and in the widgets) will not show any data if the table entries values are zero.*
  - For Zebra NSight system running for a limited amount of time (few hours), 'Top App by usage' may not show details for larger aggregate statistic duration (1 month, 3 months).
  - 'location' command in the rf-domain configuration will be used to store geo-coordinates of the site-location for MAPVIEW functionality.
  - *While using 'Heatmap' on the MapView/Floormap, user must select one channel at a time for correct heatmap view*
  - *In Hierarchical Mode, an offline AP may show up as online status under local controller details. The correct AP status shown on the Key Metric Strip or the device list/details.*
  - *In MapView/Floormap the user defined custom columns in show table option may not be retained after page refresh.*
  - *The top X charts in the summary page may show incorrect client count when the clients are roaming*
2. Captive-Portal
- Captive portal user database storage is supported on the NX 95XX/ NX 96XX/ VX 9000 and NX 75XX platforms with the following scale limits:
    - NX 95XX/ NX 96XX / VX 9000 - 2 Million user identities
    - NX 75XX - 1 Million user identities
  - If client device roams (to a nearby AP) between the initial connection redirect and the registration action, the registration may not work and user needs to close/open the browser to connect/register to the captive portal.
  - Upgrade to 5.8 (from 5.5.x and above) will do a one-time import on the existing (SQLite) user database into the newer MongoDB database.
  - Configure "bypass captive-portal-detection" in the captive-portal-policy to ensure the OAUTH functionality works properly on the iPhones and Windows mobile phones.
  - While uploading logo/images for captive portal using sftp in CLI, the user will not be prompted for password and is expected to supply along with the username in the command line.
  - With over 1.5 million user entries in the Captive-Portal database, the controller may respond with a delay for the CLI command "show guest-registration user trends time all" when issued after restart/reboot.
  - User trend data graphs and charts are shown in UTC timezone
3. Application Visibility & Control
- The Blackberry/email, Blackberry/encrypted and Blackberry/messenger will be categorized under the application 'Blackberry'
  - *Clearing application stats resets the tx and rx counts to zero and does not affect the current active flows.*
4. Client-Bridge
- Packet capture on the infra-AP with traffic using CCMP are unencrypted packets due to hardware based CCMP encrypt/decrypt operation.
  - The INF WLAN VLAN must match the VLAN used in the Client Bridge GE1, WLAN and SVI.
5. Wired 802.1x with Mac-Authentication enabled: Microsoft Windows clients must have "Fallback to unauthorized network access" enabled for mac-authentication to occur in the event of an 802.1x failure
6. EAP Termination
- MS-CHAPv2 is mandatory for EAP termination functionality

7. VX 9000
  - o Flash partition has been increased to 1Gb with .iso install. Simple .img upgrade will continue to work with the old 64MB flash partition.
  - o User may observe “Low memory on the running VM” message when installing VX for the first time with large disk size allocations (1TB or more).
8. AP 7502
  - o AP 7502 does not support WEP-128 and Keyguard on the 5GHz radio
9. Centralized EX-3500 switch management
  - o User must add VLAN to the VLAN database before assigning VLAN to a port
  - o While configuring processor/memory threshold commands from a centralized NX/VX controller, the falling threshold must be set prior to rising threshold.
  - o Switch port VLAN configurations may not get configured properly after the controller reload operation
10. Commit warning pop-up message will appear when VPN step-by-step wizard is selected to ensure the previous config changes are saved.
11. WiNG Express
  - o Express Manager, NX 5500E, comes preloaded (default) with 128 Express AP adoption licenses.
  - o The preloaded adoption licenses on the existing Express Manager platforms, VX 9000E and NX 7510E, has been changed from 64 to 128 starting with WiNG 5.8.
12. To operate Cisco phones with AP 7532, the interface radio settings should include dynamic-chain-selection strict
13. Captive Portal: OAUTH may not work properly with Lumina phone running older Windows version (< 8.1). Please upgrade Lumina phones to latest OS.
14. The WiNG GUI may become unresponsive in Firefox browser when 10,000+ adopted APs are displayed on the navigation tree. This is due to Shockwave plugin.

#### **New in v5.7.2**

1. WiNG 5.7.2 includes performance improvements for AP 7532/7522 when connected to 3af power source.
2. Added support for host alias for critical-resource ip-address that user can define on AP device or Profile context.
3. WiNG 5.7.2 adds NAND fixes and new bit error correction algorithm for AP 650/6532 to reduce potential flash corruption issues.
4. WiNG 5.7.2 validated VMM support on AP 7562.

#### **New in v5.7.1**

1. AP 622, 6522, 6562 - Default value for radio lna control on 2.4GHz has been changed to improve receive sensitivity and range in low/medium AP density environments.
2. DHCP Vendor Class Identifier has been changed use “Wing” instead of Motorola (5.7)/Zebra (5.5.6) to be consistent with rest of re-branding changes, e.g. WingAP.AP7532, WingAP8132, WingRFS.RFS4000 and etc.
3. Captive Portal internal web-page templates are enhanced for mobile friendly rendering. Existing WiNG5.x deployments using internally hosted web-pages for captive portal will automatically get this functionality on upgrading to WiNG5.7.1. Please note that there will be slight changes to pages – page style, background color, font color etc.
4. AP 7562 sensor functionality will be supported in later ADSP release.

#### **New in v5.7**

1. FIPS: Encrypted parts of configuration are lost when downgrading from WiNG 5.7.  
Workaround:
  - disable password encryption before the downgrade #no password-encryption secret 2 <password>
  - perform the downgrade
  - enable password encryption #password-encryption secret 2 <password>

2. 'no ip dhcp trust' functionality does not work on the AP 7502 FE ports.  
FE port on AP 7502 will not drop the packet because switch on AP 7502 is not configured to drop.  
FE port will pass discover packets from dhcp server irrespective of "no ip dhcp trust" to ge1. User can configure GE1 to drop.
3. The AP 6521 will include support for configuration and management of the on-board AAA server in the HTTP User Interface. This UI is found on the standard WiNG OS for the AP 6521, and the AP 6521 Express. Please note that the Virtual Controller function will be disabled when the on-board AAA server is enabled on a standalone AP 6521. To use the Virtual Controller function, you must disable the on-board AAA server.
4. Web Filtering :
  - URLs in custom category will get priority over standard/predefined category irrespective of precedence configured
  - Web Filtering is not supported on the NX65xx/NX45xx platforms
5. Wired captive portal – to support clients with MAC authentication, 802.1x configuration is also required on the controller
6. OpenDNS:
  - The dhcp server/pool policy configuration is required to include the OpenDNS IP (208.67.220.220, 208.67.222.222 ) as the dns-server
  - The ip access-list is required to include the following firewall rules to prevent clients from using any unauthorized DNS server  
*permit udp any host 208.67.222.222 eq dns rule-precedence 1 rule-description "allow dns queries only to OpenDNS"*  
*deny udp any any eq dns rule-precedence 10 rule-description "block all other dns queries"*
7. WiNG Express Manager
  - a. Express Manager (NX 7510E) can be accessed using default IP 192.168.0.1 and 'admin' is the supported user role.
  - b. Smart-RF is enabled by default with channel override capabilities on individual APs. Any Smart-RF channel list change will take effect after the device reboot.
  - c. RADIUS services will not be supported on AP 6511 and AP 6521.
  - d. DHCP service should be started at the site-level and APs have to adopt to the Express Manager before starting the DHCP service.
  - e. VLAN 1 and 2200 are reserved VLANs – they are not available for user configuration
  - f. GUI will be supported on the following browsers/version
    - i. IE10 and above
    - ii. Chrome
    - iii. Firefox
  - g. Country code should be configured at the site-level for the AP radios to function.
  - h. Auto-provisioning policy must be created before adopting APs to a site. Express Manager needs to be reloaded for any changes to the auto-provisioning policy to take effect.
  - i. Event history page may experience slow to refresh when the event table size is large
  - j. Default profile configuration (inherited from the system) can be modified at the site-level, however needs manual reconfiguration to revert to defaults
  - k. Disable DFS checkbox under Advanced Smart-RF tab removes DFS channels from the available channel list
  - l. Floor maps should be loaded independently on the standby in a cluster scenario
  - m. Firmware upgrade for the Express Manager should be administered through the System basic configuration screen. Upgrading through the devices screen is not supported.
  - n. Access to the NX 7510E USB port is not available from the Express Manager UI
  - o. There is no periodic auto-refresh for the UI charts, tables and map. Needs manual page refresh using refresh button.



- p. Site icon can be removed from the Dashboard map only after the corresponding site profile has been deleted from the system.
- q. AP upgrade status is shown on the Active Express Manager while the upgrade is initiated from the Standby in a cluster setup
- r. Site connectivity to the Express Manager needs to be active for the mac-registration feature to function.
- s. For infinite lease option on the dhcp pool configuration, the user needs to set "0" for the day, hours and minutes.

8. ETSI 1.7.1 Adaptivity Limitation on AP 622, AP 6522, AP 6562

This note applies to the following APs that end with "-EU". These APs are sold to countries that comply with the EU directives - AP 622, AP 6522, and AP 6562. This does not apply to APs that end in "-US" or "-WR"

- Radio 1 will support operation as a 2.4Ghz data radio compliant with ETSI 1.7.1 adaptivity directive
- Radio 2 cannot be enabled for operation as a 2.4Ghz data radio. Radio 2 will support operation as a 5Ghz data radio only
- If using Radio 2 in 2.4Ghz, please enable Radio 1 for data access in 2.4Ghz
- When Radio 2 is configured as a dual-band security sensor with an ADSP appliance;
- Radio 2 will not support Air Termination, AP Test, and Network Assurance at 2.4Ghz band
- Radio 2 will support receive packet and forensic security analysis at 2.4Ghz band
- Radio 2 will support Air Termination, AP Test, Network Assurance and all packet receive functions on the 5Ghz band

9. The following defaults and CLI commands / help-strings have been changed as part of the de-branding :

	WiNG 5.7.x	Older versions
Default username / password	admin / admin123	admin / motorola
Default DNS name	"WiNG-wlc"	"Motorola-wlc"
Default WLAN name	"WLAN-1"	"Motorola"
CLI command	"wing-extensions"	"motorola-extensions"
	"wing-ie"	"symbol-ie"
CLI help string	WiNG	Motorola or Symbol
802.1x default username / password	admin / admin123	admin / motorola

10. AP 6522/6532/6562/71xx - VRRP and OSPF feature support have been removed

**New in v5.6.x**

1. IPV6:

- IPv6 ACLs do not support the object oriented firewall feature in this release.
- IPv6 implementation does not support IPsec VPNs in this release.
- IPv6 – MLD snooping is not supported on the ethernet switch ports on the NX 4524 and NX 6524 platforms. It is supported only on UP1, UP2 ports.
- IPv6 – When there are multiple DHCP servers (one for IPv4 and another for IPv6) that respond to option 191, ensure that both provide valid IP addresses/ hostnames. Otherwise, with both servers responding the later response will override the previous response. If the later response does not contain valid information, AP will not be able to adopt to the controller.

2. VX 9000:

- MAC address of the device should not be changed once installed/configured.
- Only 1 GE1 interface is supported on the VX platform.
- VX 9000 instances running in Amazon EC2 must use "Elastic IP" to retain the public IP when the instance is stopped and restarted.
- VX 9000 - VMWare and other hypervisors need to be configured in promiscuous mode for features like VRRP to work correctly.

- When creating a cluster between multiple VX 9000's, all instances should use identical resources (e.g. replication from one instance with higher memory to a smaller one can lead the smaller instance to run out of memory).
  - VX 9000 – Ipv6 is not supported when using Microsoft HyperV as the virtualization platform. Dataplane support does not work correctly with Microsoft HyperV. It works fine with other supported hypervisors.
3. Captive Portal Time Based Voucher is only supported with Active: Standby configurations. Active: Active based clusters are not supported. The database gets replicated from the Active Controller to the Standby Controller periodically (default is 5 min).
  4. eBGP Scaling by platform is as follows:
    - RFS 4000/RFS 6000 – 6000 routes
    - NX 9510 – 9000 routes
    - NX 4500/NX 6500 – 12 routes
  5. T5 adoption – https must be enabled on the WiNG controller for T5 adoption to work
  6. Wired Captive Portal
    - If wired captive portal is being used along with wireless captive portal on the same controller, then same captive portal policy needs to be used for both wired and wireless captive portal enforcement.
    - If Wired captive portal is being implemented for a particular bridged vlan on the controller's physical interface that receives APs traffic, then applying wireless captive portal for the same bridge vlan is not valid, since the wireless client will then be subjected to captive portal enforcement twice.
  7. The following default values have been changed/ corrected:
    - *route-limit num-routes 12288 retry-count 5 retry-timeout 60 reset-time 1* | *route -limit num-routes 12288 retry-count 5 retry-timeout 60 reset-time 3* ..... reset time was changed from 1 to 3.
    - *vrrp-state-check* command previously present in "router ospf" context, has been moved to device/profile context
    - *min-misconfiguration-recovery-time 120* .... Was increased from 60 to 120.

#### **New in v5.5.6**

1. Currently, for all events, forward-to-switch is on by default. Due to this setting a controller adopting many APs gets too many events sometimes. So for certain events, forward-to-switch setting will be off by default. This will apply whether event-system-policy is used or not. The events being changed are: "dot11 client-associated", "dot11 client-disassociated", and "dot11 client-info".
2. Flow control on AP 6511 has been disabled to prevent transmission and receive of pause packets.
3. AP discovery tool will work on windows 7 laptop only with static IP.

#### **New in v5.5.5**

1. When upgrading to WiNG 5.5.5 – AP statistics will not be available on the controller until APs have also been upgraded to WiNG 5.5.5.
2. CPLD images on AP 7131/7161/7181 have been updated. AP 7131N CPLD image is without change.
3. "No service" page for captive portal enhancements:  
WiNG 5.5 has introduced support for "no service" page support. However - the failure page was ONLY displayed if the Access Point (or Wireless Client) can reach a DNS server. WiNG 5.5.5 addresses the issue with DNS reachability and provides option to configure "service monitor dns crm <crm-name> vlan <failover-vlan>". This service command will monitor DNS server reachability. When DNS server is not reachable, the clients are moved to failover-vlan. In the

failover-vlan every time DNS request comes from captive portal clients, they are redirected to No-service page since DNS server is not reachable.

In case of extended VLAN, CRM for service monitor should be configured on the controller with sync-adoptees option. Any CRM state changes would be forwarded to the adopted devices which would redirect the wireless clients on the WLAN to no-service page in case the monitored CRM is down.

4. AP 622/6522/6562 enhancement for radio 1.  
New configuration option added to improve Rx sensitivity of Radio 1 (2.4GHz) on AP622/AP6522/AP6562 platform. Useful for deployments with low AP density, high ceilings (warehouses), VOIP services etc.  
Under radio configuration (profile/device → interface radio 1): "*service radio-lna ms*"  
Default is "*service radio-lna ang*".
5. MCD devices with Jedi radios can have connectivity issues when 5.5 and 11 mpbs rates configured on infrastructure. Impacted devices are: MC1790, MC5590, MC7590, MC7594, MC9590, MC9596, MC3190, MC75, MC9190, MC55, VC6090, VC6096, MT2090, MK3900, MK4900, MK590.  
If SSID/band is used exclusively for 802.11g or 802.11gn devices (i.e. no 802.11b devices), configure the data-rates on the SSID/radio to be "g-only" or "gn" or custom with 5.5 and 11 Mbps excluded from the basic rate set.  
If SSID/band is used by 802.11b-only devices as well, configure the data-rates on the SSID/radio to be custom with 1 Mbps and/or 2 Mbps as basic and exclude 5.5 Mbps and 11 Mbps from the supported rates.

#### **New in v5.5.4**

1. New event was added to track down IP address of associated client. All events are enabled by default in the system.  
*Rfs4000(config-event-policy)#event dot11 client-info*
2. One can now configure SNMP community strings for SNMP traps. Previously it was using default community string – public.  
*Rfs4000(config-management-policy-default)#snmp-server host <ip> <ver> <port>*  
*changed to*  
*Rfs4000(config-management-policy-default)##snmp-server host <ip> <ver> <port>*  
*community ?*  
*WORD Enter Trap Community Name*

Host and Version is mandatory parameters while port (default 162) and community (default public) is optional parameters. Default community string is public.

#### **New in v5.5.3**

- The command - "*device-upgrade load-image <image-type> URL*" changed to "*device-upgrade load-image <image-type> <URL> <on device or domain name>*". When on device or domain name is given then the image will be loaded on remote device or RF domain manager respectively. If URL is missing then location of the image will be images loaded on the self device.
- The command - "*show device-upgrade versions on rf-domain-manager*" changed to "*show device-upgrade versions on <device or domain name>*".
- New web UI:
  - a. When using new web UI to configure Express SKU Aps – use of CLI at the same time is not recommended as it can lead to configuration corruption.
  - b. New web UI configuration can't be done though Nexus 7 chrome browser as all the fields are misplaced in UI.
- Currently device upgrade on multiple rf-domains does not work from NOC controller when the RFDs are all controller managed. Each domain needs to be upgrade separately.
- Smart-rf calibration has been removed in this release.



- NX 9xxx controller will not reboot correctly if USB flash drive is mounted. Please remove the USB when rebooting the controller.
- CDP and LLDP protocols are enabled by default on WiNG devices. If the wired infrastructure has a combination of managed and unmanaged switches and some are not CDP protocol aware, then CDP protocol needs to be disabled on AP profiles to avoid the L2 switch flooding the packets to all ports.  
WiNG 5.5.x release introduced an enhancement to learn the APs wired side connected port through CDP or LLDP packet processing, so the CDP packet flooding needs to be avoided to eliminate the excessive packet flooding from the APS to controller.
- WiNG 5.5.4 does NOT include support for ADSP unified mode for NX 7500 series.

### **New in v5.5.2**

1. Change in behavior for “*show wireless xxxxx*” cli commands and techsupport for centralized controller deployments:

For centralized controller deployments (multiple RF-Domains across distributed locations), all “*show wireless xxxxx*” commands will resolve only to the local rf-domain. This will prevent a “*show wireless xxxxx*” cli command without any rf-domain specified or a techsupport dump operation initiated on the centralized controller from collecting statistics information from all the distributed locations (rf-domains). New mechanisms have been added to collect rf-domain specific statistics individually or globally.

2. New Display Mode in the CLI to view RF-Domain specific or global (across all rf-domains) wireless statistics:

From the CLI (in EXEC mode/privileged EXEC mode):

“*on rf-domain <rf-domain\_name>*” sets the display mode for wireless statistics show commands to resolve to a particular rf-domain, all “*show wireless xxxxx*” commands executed in this mode will automatically return the output corresponding to that rf-domain without the user specifying the “*on <rf-domain\_name>*” extension to every command.

“*on rf-domain all*” sets the display mode for wireless statistics show commands to run in global mode – i.e. for each “*show wireless xxxxx*” command that you run, the controller will display statistics across all rf-domains.

3. Ability to generate wireless stats summary report on a per rf-domain basis or globally (across all rf-domains):

From the CLI (in privileged EXEC mode) –

“*service copy stats-report rf-domain <rf-domain-name> <URL>*”

“*service copy stats-report global <URL>*”

Note: The above option could be utilized for generating inventory/reporting at a system level.

### **4. Deprecating the usage of TKIP Encryption:**

From January 1<sup>st</sup>, 2014, the WPA TKIP is no longer allowed for Wi-Fi Alliance product certification. For AP/STA products wishing to support a legacy device that is capable of supporting only TKIP encryption, they are required to implement mixed mode with WPA/WPA2.

Following changes are enforced from WiNG 5.5.3 release onwards to comply with the above Wi-Fi Alliance requirement:

- Configuring encryption type as TKIP for a wlan will no longer be supported; wlangs requiring to support TKIP clients should use *tkip-ccmp* as the encryption type.
  - Upgrading from a prior WiNG 5.x to release to WiNG 5.5.3 will automatically modify the configurations for wlangs using ‘*tkip*’ as encryption type to ‘*tkip-ccmp*’ and will add “*service wpa-wpa2 exclude-ccmp*” command to avoid any post upgrade incompatibility issues.
  - For new configurations, to handle certain legacy/non-Wi-Fi compliant client situations where the client driver is incompatible or does not operate properly in a mixed mode TKIP-CCMP configuration, add the following command “*service wpa-wpa2 exclude-ccmp*” to the wlan configuration. This configuration allows the wlan to operate in TKIP only modes until the non-compliant wireless clients are phased out of the network.
5. Change in terminology for adoption/upgrade related action commands/events/traps:

With WiNG 5.5 One View deployment scenarios supporting controllers to be adopted and managed by a centralized controller cluster, existing “ap-xxxx” action commands have been replaced with “device-xxxx” action commands. For example: ap-upgrade xxxx will now be referred to as device-upgrade xxxx.

All adoption related events and traps are modified to reflect the “device” terminology instead of “ap”.

6. Ability to optionally include ‘dhcp client-identifier’ as part of DHCP Discover/Request packets: If your DHCP server uses dhcp client identifier for static bindings (dhcp lease reservations) and responds only to DHCP Discover/Requests with dhcp client identifier present, then the client identifier can be included by configuring the following command “dhcp client include client-identifier” under the SVI (interface vlan X) which is configured as DHCP client.
7. Auto-provisioning policy: ‘reevaluate-everytime’ command is modified to ‘evaluate-always’ and moved to ‘auto-provisioning-policy’ from device/profile context. Upgrade from 5.5.1 to 5.5.3 or later versions should work in accordance with location and syntax changes. However, downgrade from 5.5.3 to former versions would cause the command to disappear from all contexts.

#### **New in v5.5.1**

1. NIST SP 800-131A regulation made 1028 bit certificates obsolete as of January 1, 2014. All self-signed on-board certificates which are 1028 bits will be regenerated upon upgrade. Customers need to upgrade all third party certificates to be compliant to new regulations.
2. “show global domain managers” will show incorrect values for number of APs if domain has APs on version below WiNG 5.5.

#### **New in v5.5**

1. WLAN controller does not retain saved auto upgrade configuration when downgrading from 5.5 to pre-5.5 release. This is because “ap-upgrade” commands were renamed to “device-upgrade” in 5.5. When upgrading to 5.5, the conversion happens automatically, however, when downgrading from 5.5 the previous firmware release does not understand “device-upgrade”. The workaround is to manually fix the configuration.
2. Mesh Connex Migration – With the introduction of Auto Channel Select, Mesh Connex Configuration will be migrated when the WLAN controller reboots. The following parameters get migrated:
  - Channel list from smart-rf is copied on to the rf-domain.
  - Priority meshpoint name and root recovery parameters are copied to the meshpoint-device configuration under device context or profile of the APs.
3. WiNG 5.5 extended L2tpv3 support for AP 6521, AP 621 and AP 6511. In addition on configuring l2tpv3 settings on those APs – following is required to be set in AP profile for l2tpV3 to work – “service l2tpv3 enable”.
4. WiNG 5.5 introduced addition of precedence to ip nat rules.  
*ip nat inside source list mylist ?  
precedence Set precedence of access list*  
For example: ip nat inside source list mylist precedence 1 interface vlan2 overload
5. In WiNG 5.5 legacy mesh related show commands have been replaced with ‘mint’ to remove confusion with meshpoint functionality. Use “show wireless mint links” to see the legacy mesh links.
6. **Captive Portal Deployments using External (or) Advanced pages:**  
Captive portal query string delimiter has been changed to ‘&’ instead of ‘?’ from WiNG 5.5 onwards. When upgrading to a 5.5.x based firmware, the JavaScript embedded in the external or advanced webpage(s) needs to be updated to parse the new style of query strings.  
Following line needs to be modified under function **getQueryVariable(variable),**  
**var vars = query.split("?"); === change it to == var vars = query.split(/[?&]/);**  
Please ensure that this function gets updated in all the captive portal pages that uses it.

### **New in version 5.4.x**

1. When upgrading from prior versions – new profiles for newly supported platforms will not be present in the startup-config. User can either create a default profile or do “erase startup-config”.
2. ADSP SA cannot be run through a mesh with AP7131N tri radio; non root AP has 3rd radio as sensor
3. Interoperability with Samsung S2 devices:  
A Samsung Galaxy S2 device sometimes fails to connect using EAP-MAC authentication and WEP64 encryption. It's recommended to reduce the number of attempts (authentication eap wireless-client attempts) from default 3 to 2.
4. With 802.11r enabled WLAN – some clients might have problems associating. Please create a different WLAN for non 802.11r enabled clients.
5. MCX max range feature – the maximum range is 25 km except for 5Ghz 40Mhz channels where range is 24km.
6. It's recommended disabling IP DoS attacks in firewall policy when configuring IGMP snooping.
7. 10 GbE support on the NX 9510 is limited to SFP+ SR interfaces that are included in the controller. LR or XR SFP+ are not supported.
8. There is a single profile for AP71XX. However, for AP 7161 and AP 7181 placement is set to "outdoor" at the device level. So even though the profile in the controller doesn't have the "outdoor" setting, when configuration is pushed to the AP, the outdoor placement is automatically enforced.
9. On AP 6511, AP 6521, ES 6510 or AP 621, when adopted by a controller, the GUI is disabled, to make the memory available for other core functions such as additional mint routes. It is assumed that when an AP is adopted to a controller the controllers' GUI will be used for its configuration. To re-enable the GUI on these APs - use the “memory profile” parameter. Note that when an adopted AP (6521, 6511) or ES 6510 is separated from a controller to operate in standalone mode, the GUI will remain disabled due to this feature, unless the above command is used.  
If APs are already separated from the controller:
  - Connect to AP CLI.
  - Set memory profile to 'standalone' under device override or profile context.

If APs are adopted to controller then memory profile configuration change can be applied from controller CLI:

- Connect to Controller CLI.
- Set memory profile to 'standalone' under AP profile context.

Changing the memory profile reboots the AP which then comes up with GUI.

e.g. CONTROLLER(config-profile-default-ap6511)#memory-profile (adopted | standalone).

### **From previous releases (prior to 5.4.0.0):**

1. When using Juniper ex2200-24p-4g or related models when connecting Zebra Access Points – either disable IGMP snooping on the Juniper switches to ensure AP adoption or configure firewall policy filter that will allow the flow of traffic to specified destination-mac-address – 01:A0:F8:00:00/48.
2. If using an 802.3af 10/100 power injector to power up the 802.11n APs, when plugged into a Gig E wired switch, please set link speed to 100 full, or user a GigE Power Injector.
3. APs (& ES) have a shadow or secondary IP for gaining access to the AP if the IP address of the AP is not known but the MAC address is known. To derive the shadow IP address of an AP, use the last two hex bytes of the AP's MAC address to determine the last two octets of the IP address.  
AP MAC address - 00:C0:23:00:F0:0A  
AP IP address equivalent – 169.254.240.10
4. To derive the AP's IP address using its factory assigned MAC address



- Open the Windows calculator by selecting Start>All Programs>Accessories>Calculator. This menu path may vary slightly depending on your version of Windows.
  - With the Calculator displayed, select View>Scientific. Select the Hex radio button.
  - Enter a hex byte of the AP's MAC address. For example, F0.
  - Select the Dec radio button. The calculator converts the F0 to 240. Repeat this process for the last AP MAC address octet.
5. If the system flash is full from packet traces, crash files or ap-images, then there may not be enough space left on the device to create hotspot pages. If this happens, users must clear enough space from flash to allow hotspot pages to be created.
  6. Multicipher support: Some of clients keep on sending deauthentication request when associated to WEP security WLAN in multicipher configuration. Please use different BSSIDs with the same WLAN, with different ciphers.
  7. Commit is not allowed with radio configuration having two WLANs mapped with different data rates to the same BSS, as this is not a supported configuration.
  8. Auto-tunnel for VPN
    - A single group id/PSK is supported on RFS controllers. All APs use same group id/PSK.
    - When APs are behind NAT (e.g. two remote sites), it is required that the AP IP address are different.
    - Auto IPsec tunnel termination has been verified on Cisco Gateways with PSK/RSA authentication.
  9. VRRP
    - VRRP version 3.0 (RFC 5798) and 2.0 (RFC 3768) are supported. Default is version 2 to support interoperability. Please note that only version 3 supports sub-second failover.
    - Services like DHCP, RADIUS, NAT, and VPN running on the virtual IP are supported
    - For DHCP relay, you can point to the DHCP server as virtual IP
    - For VPN, on the initiator side, remote peer can be configured as virtual IP
  10. If using TFTP to upgrade an AP 6521, AP 6511, ES 6510 or AP 621, on the TFTP server please configure the following settings: Per packet timeout – 15 seconds and Maximum retries – 20.
  11. When using iPods as clients, you may see WPA2 group key rotation handshake failures while MUs are idle (2.4GHz band). Change the handshake timeout to 2 sec to correct this problem. From the wlan config, the cli command is: wpa-wpa2 handshake timeout X (where X is the timeout in ms, within a range of 10-5000)
  12. Auto assign sensor is not available for AP 6511, AP 6521, ES 6510 or AP 621 – since this feature requires a reboot on low memory devices, which cannot be done with Smart RF enabled.
  13. To safeguard against unknown attacks, it is recommended that management access be restricted to authorized hosts/subnets. This can be done using the restrict-mgmt-access host/subnet cli command under management-policy.
  14. When AP adopts to the Controller, the clock is not getting sync with controller clock immediately. It happens over period of time depending on time delta.

## 7. DFS Tables, Sensor and Radio Share

1. Following is the DFS support in WiNG 5.8.3 for the supported radio platforms:

Product	Master DFS FCC	Master DFS IC	Master DFS ETSI	Master DFS Japan	Client DFS FCC	Client DFS IC	Client DFS ETSI	Client DFS Japan
AP 650 AP 6532	Enabled	Enabled	Enabled	Enabled	Enabled	Enabled	Enabled	Enabled
AP 7131	Enabled	Enabled	Enabled	Enabled	Enabled	Enabled	Enabled	Enabled



Product	Master DFS FCC	Master DFS IC	Master DFS ETSI	Master DFS Japan	Client DFS FCC	Client DFS IC	Client DFS ETSI	Client DFS Japan
AP 7161	Enabled	Enabled	Enabled	Enabled	Enabled	Enabled	Enabled	Enabled
AP 7181	Disabled	Disabled	Enabled	Enabled	Disabled	Disabled	Enabled	Enabled
AP 6511	Enabled	Enabled	Enabled	Enabled	Enabled	Enabled	Enabled	Enabled
AP 621 AP 6521	Enabled	Enabled	Enabled	Enabled	Enabled	Enabled	Enabled	Enabled
AP 622 AP 6522 AP 6562	Enabled	Enabled	Enabled	Enabled	Enabled	Enabled	Enabled	Enabled
AP 8132	Enabled	Enabled	Enabled	Enabled	Enabled	Enabled	Enabled	Enabled
AP 8122	Enabled	Enabled	Enabled	Disabled	Enabled	Enabled	Enabled	Disabled
AP 8163	Enabled	Enabled	Enabled	Disabled	Enabled	Enabled	Enabled	Disabled
MOD-8132-6001S-WW	NA	NA	NA	NA	Enabled	Enabled	Enabled	Enabled
AP 8222/8232	Enabled	Enabled	Enabled	Enabled	Disabled	Disabled	Disabled	Disabled
AP 7502	Enabled	Enabled	Enabled	Enabled	Disabled	Disabled	Disabled	Disabled
AP 7532 AP 7522	Enabled	Enabled	Enabled	Enabled	Enabled	Enabled	Enabled	Enabled
AP 7562	Enabled	Enabled	Enabled	Enabled	Enabled	Enabled	Enabled	Enabled
AP 8533	Disabled	Disabled	Enabled	Disabled	Disabled	Disabled	Enabled	Disabled
AP 8432	Disabled	Disabled	Enabled	Disabled	Disabled	Disabled	Enabled	Disabled

2. Air Defense sensor capabilities are supported on the 802.11n/802.11ac APs in this release, and are available for enabling the WIPS functionality as well as the Network Assurance Capabilities. There are some caveats on managing the AP directly via ADSP, for certain AP platforms:

Network Assurance Toolset when Radio is dedicated as a sensor	Spectrum Analysis	Advanced Spectrum Analysis	Live RF	Live View	AP Testing	Connectivity Testing
AP 621/6511/6521 <sup>1</sup>	No	Yes	Yes	Yes	Yes	Yes
AP 650/6532	Yes	No	Yes	Yes	Yes	Yes
AP 622/6522/6562	No	Yes	Yes	Yes	Yes	Yes
AP 7131/7161/7181	Yes	No	Yes	Yes	Yes	Yes
AP 7532/7522/7562	No	Yes	Yes	Yes	Yes	Yes
AP 8132/8122	No	Yes	Yes	Yes	Yes	Yes
AP 8232/ 8222	No	No	No	No	No	No
AP 7502	No	No	No	No	No	No
AP 8533 <sup>2</sup>	No	No	No	No	No	No
AP 8432 <sup>2</sup>	No	No	No	No	No	No

Notes:

<sup>1</sup>GUI is disabled and number of SSH sessions is limited to 1

<sup>2</sup>Support is limited to WIPS only Network assurance and LBS is not supported for AP 8533 and AP 8432 in the dedicated sensor mode for WiNG 5.8.3. For WIPS - support is limited to dedicated sensor (Radio 3) for AP 8533. For WIPS - support is limited to dedicated sensor (Radio 1) for AP 8432.



3. Radio Share functionality (allows for enabling the Network Assurance toolkit in ADSP, without dedicating a radio as a sensor) is available on the 802.11n/802.11ac APs with some caveats – please see details below:

Network Assurance Toolset with Radio Share	Spectrum Analysis <sup>2</sup>	Advanced Spectrum Analysis <sup>3</sup>	Live RF	Live View	AP Testing	Connectivity Testing
AP 6511/ 621/6521 <sup>1</sup>	No	Yes	Yes	Yes	Yes	Yes
AP 650/6532	No	No	Yes	Yes	Yes	Yes
AP 622/6522/6562	No	Yes	Yes	Yes	Yes	Yes
AP 7131/7161/7181	No	No	Yes	Yes	Yes	Yes
AP 7532/7522/7562	No	No	Yes	Yes	Yes	Yes
AP 8132/8122/8163	No	Yes	Yes	Yes	Yes	Yes
AP 8232/8222	No	No	No	No	No	No
AP 7502	No	No	No	No	No	No
AP 8533 <sup>4</sup>	No	No	No	No	No	No
AP 8432 <sup>4</sup>	No	No	No	No	No	No

Notes:

<sup>1</sup>GUI is disabled when Radio Share is enabled.

<sup>2</sup>Spectrum Analysis is not supported with Radio share enabled.

<sup>3</sup>Advanced Spectrum Analysis in RadioShare mode may impact WLAN performance.

Radio-share is not supported for AP 8533 and AP 8432 in WiNG 5.8.3 (none of WIPS, network assurance and LBS functions in that mode are supported).

## 8. Vulnerability updates

In case a patch has been applied to address vulnerability even though vulnerabilities was addressed – some security scans only check the version number of the component as opposed to testing the actual vulnerability – and therefore might still report issue being present.

### WiNG 5.8.3

openssl package has been updated to 1.0.1p to incorporate latest security vulnerability fixes.

CVE-2015-7547: glibc getaddrinfo stack-based buffer overflow

TLS/SSL Server Support for DES and IDEA Cipher Suites (ssl-des-ciphers) was removed

TLS 1.0 and TLS 1.1 disabled by default.

The SSH server support for the diffie-hellman-group1-sha1 key exchange algorithm, which is known to have a potential security weakness has been removed.

### WiNG 5.8.2

Linux kernel patched to address security vulnerability CVE-2015-5707

### WiNG 5.8.1

openssl package has been updated to 0.9.8zg to incorporate latest security vulnerabilities fixes.

CVE-2015-5600 – openssl package has been patched to address this vulnerability.

openLDAP package has been updated to incorporate latest security vulnerabilities fixes.

### WiNG 5.8

cURL and libcurl packages have been patched to address security vulnerability CVE-2015-3143, CVE-2015-3145 and CVE-2015-3148.

RC4 algorithm has been disabled in SSL/TLS package used to address security vulnerability CVE-2015-2808.

NTP package has been upgraded to version 4.2.8p2 to address security vulnerabilities CVE-2015-1798 and CVE-2015-1799

Linux kernel patched to address security vulnerability CVE-2014-8160.



Xen package has been patched to address security vulnerabilities CVE-2014-8866, CVE-2015-2044, CVE-2015-2150 and CVE-2015-2151.

OpenSSL package has been upgraded to version 0.9.8.zf to address security vulnerabilities CVE-2015-0289 and CVE-2015-0293.

**WiNG 5.7**

OpenSSL package has been upgraded from version 0.9.8za to 0.9.8zc to address Purecloud security scan vulnerabilities.

OpenSSH package has been ungraded to 6.6p1 and addresses security vulnerability CVE-2014-2532.

**WiNG 5.5.6:**

NTP v4.2.8p1 that addresses the following security vulnerabilities outlined in CVE-2014-9297, CVE-2014-9298, CVE-2014-9295, CVE-2014-9295, CVE-2014-9295, CVE-2014-9296 .

CVE-2015-0235 - GHOST Linux Vulnerability.

CVE-2014-4877 - wget updated to v1.16.

**WiNG 5.5.5**

Updated GNU bash program for NX series of controllers that fixes the Shellshock family of security vulnerabilities outlined in CVE-2014-6271, CVE-2014-7169, CVE-2014-7186, CVE-2014-7187, CVE-2014-6277 and CVE-2014-6278.

Includes ability to disable/enable sslv3 for https module under management policy context. This is to address CVE-2014-3566 aka Poodle attack. New command is " https sslv3". Default setting is "no https sslv3".

**WiNG 5.5.2**

Security Scan reports: NTP "monlist" Feature Denial of Service Vulnerability "Serious; see EUI"

**WiNG 5.5.1**

Cross-Site Request Forgery (CSRF) based on CWE-352 family vulnerability

SecScan Qualys: Deprecated Public Key Length (QualysVersion Scanner 7.3.31-1, Vulnerability Signatures 2.2.580-2)

OpenSSH vulnerabilities - SSH Insecure HMAC algorithms enabled and SSH RC4 Cipher enabled

**WiNG 5.4.x**

CVE-2010-4478 - OpenSSH J-PAKE Session Key Retrieval Vulnerability

CVE-2012-0814 - OpenSSH Commands Information Disclosure Vulnerability

CVE-2012-3547 - Radius Security Vulnerability: freeradius and EAP-TLS length checks buggy

CVE-2013-4559 - lighttpd: setuid/setgid/setgroups return values not checked

CVE-2011-4362 - lighttpd: out-of-bounds read due to signedness error

**9. Issues Fixed**

Following issues have been fixed in WiNG 5.8.3 release:

SPR#	Description
SPR 28209	VX 9000 does not lookup users with multiple LDAP group memberships
SPR 28352	AP 8163: false radar detection on 3rd radio
SPR 28812	When multiple lines are entered in Captive portal Web page textbox (via GUI) - it's displayed as a single line of text.
SPR 28837	Application Visibility Control (AVC) is not blocking China lightweight QQ version with pre-defined QQ filters
SPR 28868	Band steering - probe entries are not aging out resulting in association denial for single band clients
SPR 28883	MCX: non root is getting unadopted and data loss on mapping same meshpoint on 5ghz and 2.4ghz
SPR 28897	AP 8163: Software heater functionality shuts down USB radio when board temperature is less than 15C



SPR#	Description
SPR 28955	A new dhcp pool that gets created is pushed to all the APs adopted to the VC. Should be on the VC only.
SPR 28995	CFGD.error when booted to 5.8.2 with 'mint level 1 area-id \$ALIAS'.
SPR 29000	SWiFT UI: Unable to configure email id as the username in email settings of guest management.
SPR 29000	SWiFT UI: guest self registration feature - in the guest management config page: unable to add a username containing special characters like @ under "Email Settings".
SPR 29001	Webpage location external shows default page details, reproducible only with chrome.
SPR 29006	SSM process crashes and restarts when the name resolution for nsight server fails.
SPR 29008	Need a provision to change the native vlan on Express controllers.
SPR 29028	Non TPC capable radios do not turn on when set to SMART operating under the Malaysia country code.
SPR 29049	All incoming traffic on VX 9000 is on the native vlan when "Trunking" feature in enabled on Hyper-V.
SPR 29056	Missing GUI configuration for Policy Based Routing on NX platforms
SPR 29073	GUI has option to add ex35xx into the auto provisioning policy - needs to be removed.
SPR 29083	GUI issue with autoprovisioning when editing rules.
SPR 29094	Time based access WLAN is off by 1 hour on some sites with the same Time zone on NX/AP
SPR 29101	Application error seen while editing the policy name in the peer configuration using edit icon
SPR 29154	Radius dynamic authorization failure while issuing COA request from NAS
SPR 29189	Controller CLI SSH Session Crashes To Diag mode During Mail Event Notification Sent To Recipients when Event System Policy Enabled
SPR 29210	AP 6532 crashes due to IP access-list rules created with alias expand to very high number of backend rules.
SPR 29228	MCX-ACS Scanning Loop using 4.9 GHz channels
SPR 29237	When using WiNG 5.8.2 wizard, the WLANs that are created in the wizard are not mapped to the radios of all the default-AP profiles.
SPR 29275	WLAN shutdown with reason primary port link loss.
SPR 29296	When controller-managed RFDs are enabled the stats for some of the RFDs are not reported to Nsight
SPR 29309	AP crashes if Spectralink IP phones connect in TKIP mode
SPR 29361	Cannot assign static IP address on VLAN interface via UI from virtual controller
SPR 29362	Cannot modify host name from virtual controller AP UI for adopted APs
SPR 29363	SSH Weak Key Exchange Algorithm
SPR 29364	Insecure Transport: Weak SSL Protocol
SPR 29382	Default gateway IP not persistent when configured via UI on virtual controller
SPR 29387	Use the 'wlan-list' API request with tree selection (like /System) instead of 'wlan-list-all' API for Reports PCI CDE Wlans
SPR 29388	Able to view details of only 1 radio when carrying out an SNMP walk for radio stats.
SPR 29395	DPI enabled is causing roaming issues and TPC flows being dropped.
SPR 29397	Clients are always POSTURE Redirected after roaming to a new AP in a Cisco CWA scenario
SPR 29398	The BCMC RX counter for AP7532 is always zero. The TX counter increments on transmitting broadcast traffic.
SPR 29436	AP7532/22/62 radio is getting turned off instead of RADAR_WAIT when DFS is detected on all channels
SPR 29475	MCX Roots Losing Broadcast Key Thus The Broadcast Traffic Coming Out From the MCX Radio Is Not Encrypted Therefore Dropped By Non-Roots / VMM
SPR 29478	Wired client redirection does not work due to failure to add wired client IP in the L3 entity table
WING-28466	Cfgd memory leak
WING-28970	Security Analysis: Authentication Bypass through Privilege escalation





SPR#	Description
WING-29108	Sensor: EAP TLS AP Test fails to get IP from DHCP and ARP Responses
WING-29250	Sensor: AP 7532 rebooting when termination started by sensor in radio-share mode running 5.7.2.x and later
WING-29367	NSight: filter for authentication under event-log tab currently shows devices login information, move this to system and include dot1x . eap and radius event logs under authentication filter
WING-29639	NSight : Client Timeline does not work when the search is done using Client hostname/MAC (Global search is missing MAC key)
WING-29403	AP 8163 USB radio is not entering scan ahead mode when sensor server configured
WING-29465	NSight : Report returns all rf-domain information when the report is scheduled for System and allowed-location is used
WING-29495	Add a service command to change the simultaneous connections per IP in the range of 3 to 64
WING-29524	NSight : While generating reports on scaled setup pdf file fails to generate
WING-29535	NSight : Update reports to be consistent with UI, using bar charts
WING-29546	GUI : import running-config throws application error. "running-config is a file"
WING-29550	Worst site by SNR dashboard lists SNR values which is divided by the total number of APs in the site, it should be by total APs that are reporting the SNR
WING-29600	Upgrade from 5.8.1-12R to alter releases results in AP getting rim core.
WING-29608	Accounting packet carries MAC address instead of username after carrying out an FT roam.
WING-29614	SSM fails to send updates for adding online or offline clients when NSight update interval is 5 minutes
WING-29653	NSight : On device details page, Cedar's third radio (dedicated sensor) displays the same no. of client as that of 5GHz radio which is incorrect
WING-29665	Wired captive portal authentication fails on RFS 4000 when proxied through centralized controller is configured
WING-29668	Controller v5.8.2 doesn't adopt EX3500 switch or T5.
WING-29738	AP6522 - not able to copy tech support, gzip uses more memory, times out in ftp server.
WING-29760	UI: Service - "preview page" displays error after adding a custom field in Registration page field
WING-29768	NSight : Smart-rf Top X widgets do not display any data for last 1hr, 8hr, 1 day and 1 week
WING-29779	MCX: Packet drops are seen on non root meshpoint and VMM APs are losing connectivity
WING-29785	NX9510 crashed while testing captive portal operation on a "local controller site"
WING-29819	Navigation tab that gets built on top of NSight UI, should have underline for only those items, clicking which retraces the action.
WING-29839	NSight : If allowed location attribute is not pushed from RADIUS/TACACS, then all rf-domains should be visible in NSight UI
WING-29844	Global search for MUs doesn't function correctly
WING-29851	show critical resources shows status of deleted or unconfigured CRM policy as well. showing on CLI and GUI as well
WING- 29871	NSight: MU search does not work when the search query specifies desired result type(s)
WING-29945	Display Filters for Device and Client List – Ability to apply a display filter to the Client List table and Device List table in the Monitor Screen.
WING-29957	Configuration - Services - Captive Portal- Preview Page doesn't display check-box menu on Age-range field after configuring on Registration page
WING-29963	NX7500 kernel panic when IPv4 GRE tunnel is configured
WING-29968	ADSP locationing feature is broken on AP 7532



SPR#	Description
WING-29970	file-sync should be enabled to push trust-point even when 'trustpoint https <trust-point-name> is configured on AP/site-controller-profile.
WING-29972	Trustpoint on site-controllers gets deleted for unknown reason after the functionality is working for a day or two.
WING-29975	CP - Progress bar and Upload status table auto disappear although Upload progress is not complete
WING-29991	GRE: show gre info detail shows invalid TX and RX bytes on NX7500 and AP7131
WING-29997	AP Test: AP 650,AP 622 and AP6511 crashes while running AP Test and WVA test in 2.4Ghz
WING-30039	cfgd error, NameError: global name 'dlog_stats' is not defined
WING-30053	cfgd error observed after removing 2 haddisks out of 4 disk, in RAID 10, from NX9600, Also RAID status not showing up as degraded
WING-30058	FT-over-DS fails when roaming between AP 7532.
WING-30080	Service pktcap – Transmit packets captured on radio show last two octets to be 00-00 and not the right bss
WING-30081	Remote debug packet capture on wireless shows packets outgoing on non-existent wlan-32
WING-30083	UI: Debug captive portal clients not working
WING-30086	Captive Portal: After successful login the screen says "Disconnected"
WING-30091	AP 7532 panic and dpd2 core seen on WiNG 5.8.2 when dpi is enabled..
WING-30131	CVE-2015-7547: glibc getaddrinfo stack-based buffer overflow
WING-30342	TLS/SSL Server Supports DES and IDEA Cipher Suites (ssl-des-ciphers)
WING-30365	CFGD memory leak observed on AP when ACL with 500 entries applied multiple times
WING-30439	AP 7532/22/62 broadcast group bit in the TIM field is always set even if no broadcasts are buffered
WING-30517	CFGD error in mart.py during send_event - UnicodeDecodeError: 'utf8' codec can't decode
WING-30518	Captive Portal: Guest registration data export in csv format fails
WING-30547	pktcap core files generated when executing the remote debug pktcap commands
WING-30552	Poor WLAN Client performance when connected to mesh AP7532
WING-30589	AP 7532/7522/7562 memory corruption fixes seen during roaming with and without dpi enabled.

## 10. Known Issues

Following issues are known issue in WiNG 5.8.x:

CQ/ SPR	Headline	Comments
CQ 202258	CP Bandwidth voucher: User is not getting configured data limit for bandwidth based voucher	This is seen for the upstream traffic which is the opposite of the general traffic in a hotspot, and TCP based applications will anyway back off once they are throttled
CQ 200221	Even after disabling routing "show ip route" has all static route entry and traffic between two networks is not dropped	
CQ 204643	WiNG Express Manager – terminate rogue device function may not work in certain conditions	
CQ 207979	Zebra NSight: Modifying a scheduled report schedule may not work properly.	Workaround is to delete the existing schedule and recreate



CQ/ SPR	Headline	Comments
CQ 208273	EX 3500 Management: Configuring class-map and policy-map description does not allow special characters	
CQ 207946	EAP termination functionality may not work with certain versions of Cisco-ISE	
CQ 207562	AP 8132 sends Aggregated FT response with both category code 126 and 6 in a certain configuration condition	
CQ 209653	Zebra NSight: Table data for sensor APs in the MAPVIEW / Floormap may show inapplicable channel value	
WING-30422	SWiFT UI: in application policy enforcement time, not able to create a time entry, if the previous entry is for entire day.	Configure the time manually other than "00:00". Just specifying the day in the rules the system will configure start and end time to 00:00 by default (from 5.8.3).
WING-30423	SWiFT: in security schedule policy tab, even when there is no change, apply button when used shows saving config and some earlier config is lost for schedule policy created earlier.	Config is lost when 'apply' is triggered without making any config changes. Please avoid clicking apply.
WING-29260	AP 8533 - Port is down permanently when changing from auto duplex to Half duplex/Full duplex (Speed 100Mbps)	Avoid setting Half duplex on AP 8533
WING-30078	SWiFT: User can't add both WLAN and MCX on the same radio	
WING-29788	AP7532/7522/7562 series APs radio can't go below 9dbm	
WING-29042	AP Test: AP Test on ap6511 radioshare mode fails with the message "BSS is on channel on which sensor not allowed to transmit"	Only seen when used changes radio band. Workaround: reboot AP after band change and before running the test.
WING-30565	AP 8432 reboots when re-configuring sensor server	
SPR 29448	AVC stats on NSight showing less than AVC stats on WiNG in "show dpi app stats all".	
WSP-8376	Sensor: AP 6522/AP 7131 Uplink test fails when running AP test	
WING-28786	AP 8533 - LLDP neighbor on GE2 is not discovered and displayed.	