

### Service Release Notes for WiNG 5.9.1.2-006R

**Please Note:** Service releases are made available to fix specific customer reported issues in a timely manner. Service releases are not as extensively tested as main releases (such as 5.9.1.0-029R). The next maintenance or manufacturing release will incorporate all qualifying and preceding service releases.

This document is an addendum to the release notes for the main release 5.9.1.0-029R.

#### Contents

- Resolved Issues
- Platforms supported
- Upgrade/Downgrade Process

#### Resolved Issues

This service release 5.9.1.2-006R contains important fixes for customer reported issues and several enhancements.

#### Additional Enhancements:

**AP 7662:** AP-7662-680B40-US and AP-7662-680B40-WR SKUs are now fully supported.

**Egypt regulatory** – WiNG 5.9.1.2 introduces following new SKUs to comply with Egypt regulatory requirements: AP7662-680B40-EG. Egypt SKUs will be available pending regulatory approval.

AP 7602/AP 7622 – adds support for new NAND component. Downgrade below 5.9.1.2 for Aps with new NAND will be prevented.

Following is a list of SPRs/CRs fixed in this release:

SPR/CQ	Description
SPR 3384	NX 5500 is missing ExtremeLocation and sensor policy in configuration parameters.
SPR 3385	NSight charts not displayed correctly after changing band / wlan filters on the monitor page at site level.
SPR 3387	AP 6532 is carrying VHT element in association response which should not be there
WING-35984	"rhal_dlbcn_job:1413 :1]above current_nf:-70 last_nf:-73 thr:-75 bcn_miss_total:0 bcn_miss_consec:0." Messages are seen on the console
WING-36015	Patch Client Bridge Supplicant to prevent KRACK vulnerability

WING-36058	HT elements should not be in the beacon if encryption is not CCMP
WING-36061	EGuest reports: Report generation is failing with custom-period
WING-36089	EGuest: Generated password for voucher is not added to the database
WING-36131	Can't select a country code for WR SKUs in GUI or Setup Wizard

## 2. Platforms Supported

This release applies to all platforms released with WiNG 5.9.1.0-029R.

Reminder:

Dependent AP platforms: AP 621, 622, 650 are EOL and engineering support has ended.

Independent AP platforms: AP 6511, AP 6511E, AP 7131, AP 7181, AP 8222, ES 6510 are EOL and engineering support has ended.

Controller platforms: RFS 4011, RFS 7000, NX 9000, NX 45XX and NX 65XX platforms are EOL and engineering support has ended.

## 3. Firmware Upgrade/Downgrade Procedure

The method described in this section uses the Command Line Interface (CLI) procedures. To log into the CLI, either SSH, Telnet or serial access can be used.

**For detailed upgrade procedure – please refer to WiNG 5.9.1 release notes.**

### Upgrade from WiNG v5.x.x.x to WiNG v5.9.1.x

1. Copy the controller image to your tftp/ftp server.
2. Use the **—upgrade ftp://<username>:<password>@<ip address of server>/<name of file>**, or **—upgrade tftp://<ip address of server>/<name of file>** command from CLI or **Switch->Firmware->Update Firmware** option from the GUI. You may need to specify the username and password for your ftp server.
3. Restart the controller. From CLI the command is **—reload**.

