



IQ Engine v10.8.5c Release Notes

New Features, Fixes, and Known Issues

9039242-10 Rev AA
April 2026



Copyright © 2026 Extreme Networks, Inc. All rights reserved.

Legal Notice

Extreme Networks, Inc. reserves the right to make changes in specifications and other information contained in this document and its website without prior notice. The reader should in all cases consult representatives of Extreme Networks to determine whether any such changes have been made.

The hardware, firmware, software or any specifications described or referred to in this document are subject to change without notice.

Trademarks

Extreme Networks and the Extreme Networks logo are trademarks or registered trademarks of Extreme Networks, Inc. in the United States and/or other countries.

All other names (including any product names) mentioned in this document are the property of their respective owners and may be trademarks or registered trademarks of their respective companies/owners.

For additional information on Extreme Networks trademarks, see: <https://www.extremenetworks.com/about-extreme-networks/company/legal/trademarks>

Open Source Declarations


Some software files have been licensed under certain open source or third-party licenses.

End-user license agreements and open source declarations can be found at: <https://www.extremenetworks.com/support/policies/open-source-declaration/>



Table of Contents

| | |
|---|-----------|
| Abstract..... | iv |
| Help and Support..... | v |
| Subscribe to Product Announcements..... | v |
| General Release Information for Release 10.8.5c..... | 7 |
| Release Date..... | 7 |
| New Hardware Support..... | 7 |
| Hardware Platforms Support..... | 7 |
| Management Platforms Supported..... | 8 |
| New Features in Release 10.8.5c..... | 9 |
| Addressed Issues in Release 10.8.5c..... | 10 |
| Known Issues in Release 10.8.5c..... | 11 |
| Earlier 10.8 Releases..... | 12 |
| Release 10.8.1 New Features and Addressed Issues..... | 12 |
| Release Date..... | 12 |
| New Hardware Supported..... | 12 |
| New Features in Release 10.8.1..... | 12 |
| Addressed Issues in Release 10.8.1..... | 13 |
| Release 10.8.2 New Features and Addressed Issues..... | 13 |
| New Hardware Support..... | 13 |
| Release 10.8.2a New Features and Addressed Issues..... | 15 |
| New Hardware Support..... | 15 |
| New Features in Release 10.8.2a..... | 16 |
| Addressed Issues in Release 10.8.2a..... | 16 |
| Release 10.8.3 New Features and Addressed Issues..... | 16 |
| New Hardware Support..... | 16 |
| New Features in 10.8.3..... | 16 |
| Addressed Issues in 10.8.3..... | 16 |
| Release 10.8.4 New Features and Addressed Issues..... | 17 |
| New Hardware Support..... | 17 |
| New Features in 10.8.4..... | 17 |
| Addressed Issues in 10.8.4..... | 18 |
| Release 10.8.5 New Features and Addressed Issues..... | 19 |
| New Hardware Support..... | 19 |
| New Features in 10.8.5..... | 19 |
| Addressed Issues in 10.8.5..... | 20 |
| Release 10.8.5b New Features and Addressed Issues..... | 20 |
| New Hardware Support..... | 20 |
| New Features in 10.8.5b..... | 21 |
| Addressed Issues in 10.8.5b..... | 21 |



Abstract

This release note for Extreme Networks IQ Engine version 10.8.5c describes defect resolutions, known limitations, and platform support details for enterprise wireless access point deployments managed using ExtremeCloud IQ 25.7.0 and later. The release introduces no new features or hardware support and instead concentrates on corrective maintenance to improve reliability, security, and operational consistency across supported access point models, including the AP3000, AP4000, AP5000, and AP4060 families. Addressed issues in this release include fixes for authentication and access control behavior (802.1X, EAP-TLS, WPA2/WPA3, legacy PEAP-MSCHAPv2), client roaming and reassociation stability, QoS rate-limiting enforcement, VLAN reassignment accuracy, and multicast and ECWP roaming scenarios. A documented known issue identifies boot failures caused by unsupported micro-USB console cables with a defined workaround. The content targets experienced network administrators and wireless engineers responsible for upgrading, validating, and troubleshooting production IQ Engine deployments.



Help and Support

If you require assistance, contact Extreme Networks using one of the following methods:

Extreme Portal

Search the GTAC (Global Technical Assistance Center) knowledge base; manage support cases and service contracts; download software; and obtain product licensing, training, and certifications.

The Hub

A forum for Extreme Networks customers to connect with one another, answer questions, and share ideas and feedback. This community is monitored by Extreme Networks employees, but is not intended to replace specific guidance from GTAC.

Call GTAC

For immediate support: (800) 998 2408 (toll-free in U.S. and Canada) or 1 (408) 579 2800. For the support phone number in your country, visit www.extremenetworks.com/support/contact.

Before contacting Extreme Networks for technical support, have the following information ready:

- Your Extreme Networks service contract number, or serial numbers for all involved Extreme Networks products
- A description of the failure
- A description of any actions already taken to resolve the problem
- A description of your network environment (such as layout, cable type, other relevant environmental information)
- Network load at the time of trouble (if known)
- The device history (for example, if you have returned the device before, or if this is a recurring problem)
- Any related RMA (Return Material Authorization) numbers


Subscribe to Product Announcements

You can subscribe to email notifications for product and software release announcements, Field Notices, and Vulnerability Notices.

1. Go to [The Hub](#).
2. In the list of categories, expand the **Product Announcements** list.
3. Select a product for which you would like to receive notifications.

4. Select **Subscribe**.
5. To select additional products, return to the **Product Announcements** list and repeat steps 3 and 4.

You can modify your product selections or unsubscribe at any time.



General Release Information for Release 10.8.5c

Release Date

April 2026

New Hardware Support

There is no new hardware supported for Release 10.8.5c.

Hardware Platforms Support

- AP302W
- AP305C
- AP305CX
- AP305C-1
- AP410C
- AP410C-1
- AP460C
- AP460S6C
- AP460S12C
- AP510C
- AP510CX
- AP630
- AP650
- AP650X
- AP3000
- AP3000X
- AP4000
- AP4000-1
- AP4020
- AP4020FX
- AP4020X
- AP4060X
- AP5010

- AP5020
- AP5050D
- AP5050U

Management Platforms Supported

ExtremeCloud IQ 25.7.0 and later



Note


ExtremeCloud IQ Engine Release 10.8.5c is the alternative to 10.8.6 for deployments that do not require support for the Multi-Link Operation (MLO) feature.

Related Links

[New Features in Release 10.8.5c](#) on page 9


[Addressed Issues in Release 10.8.5c](#) on page 10

[Known Issues in Release 10.8.5c](#) on page 11



New Features in Release 10.8.5c


There are no new features for Release 10.8.5c.



Addressed Issues in Release 10.8.5c


Table 1: Release Notes

| Issue ID | Description |
|--------------------------------------|---|
| CFD-15343 (03178845) | Fixed an issue where user profile/VLAN assignment could remain incorrect after a username change (user versus machine authentication) by redoing reassignment instead of using stale roaming-cache data. |
| CFD-16019 (03213922) | Fixed ECWP fallback roaming where the AP could send a disassociation during client reassociation by removing vendor driver logic that initiated disassociation during TX validation (multicast L3 roaming scenarios). |
| CFD-16175 (03230588) | Fixed AP5020 upstream QoS rate limiting not being enforced by ensuring the FE correctly detects QoS-flagged packets and applies the configured per-client limit. |
| CFD-16508 (03220996, 03243636) | Fixed wired 802.1X supplicant authentication failures (EAP-TLS) after an OpenSSL upgrade by loading/parsing the private key in the application and attaching it directly to the SSL object. |
| HOS-23531 | Fixed a defect with 802.11w/MFP mode configuration. |
| HOS-23898 | Fixed a backwards compatibility issue for legacy authentication (such as PEAP-MSCHAPv2) for both wired and wireless (related: CFD-14824) by adding the MD4 cryptographic module back into IQ Engine. |



Known Issues in Release 10.8.5c

| Issue ID | Description |
|-----------|--|
| HOS-18313 | <p>AP5010, AP5050D, and AP5050U devices will not boot when some non-Extreme micro-USB cables are connected.</p> <p>Note: Use the Extreme Networks certified ACC-WIFI-MICRO-USB console cable for all Extreme Networks access points. Other MICRO-USB console cables are not tested and certified by Extreme Networks.</p> <p>Workaround: Use an Extreme Networks-certified console cable, or plug in the cable after the AP boots.</p> |



Earlier 10.8 Releases

- [Release 10.8.1 New Features and Addressed Issues](#) on page 12
- [Release 10.8.2 New Features and Addressed Issues](#) on page 13
- [Release 10.8.2a New Features and Addressed Issues](#) on page 15
- [Release 10.8.3 New Features and Addressed Issues](#) on page 16
- [Release 10.8.4 New Features and Addressed Issues](#) on page 17
- [Release 10.8.5 New Features and Addressed Issues](#) on page 19
- [Release 10.8.5b New Features and Addressed Issues](#) on page 20

The following sections provide information about changes for earlier IQ Engine 10.8 releases.

Release 10.8.1 New Features and Addressed Issues

Release Date

March 2025

New Hardware Supported

Release 10.8.1 adds support for the AP4020.

New Features in Release 10.8.1

| Feature ID | New feature | Description |
|------------|---|--|
| HOS-20155 | AP4020: Imago Tag ESL Support | The AP4020 supports the VusionGroup ImagoTag ESL dongle. |
| HOS-20158 | AP4020—Wi-Fi mesh support | IQ Engine 10.8.1 supports wireless backhaul mesh for the AP4020. |
| HOS-20690 | AP5020: Wi-Fi 7 11BE—Support for UL MU-MIMO | IQ Engine 10.8.1 supports UL MU-MIMO for the AP5020. |
| HOS-20722 | AP4020: Support for UL MU-MIMO | IQ Engine 10.8.1 supports UL MU-MIMO for the AP4020. |
| HOS-20734 | AP4020: Support for DL OFDMA | IQ Engine 10.8.1 supports downlink OFDMA for the AP4020. |

| Feature ID | New feature | Description |
|------------|--|--|
| HOS-20754 | AP4020: Support for enhanced packet capture | The AP4020 supports Enhanced Packet Capture. |
| HOS-21715 | AP5020: HotSpot 2.0 Configuration in IQ Engine support | IQ Engine 10.8.1 supports Hotspot 2.0 for the AP5020. |
| HOS-21793 | AP5020: FA (Autosense) IQ Engine Default LLDP Handling | IQ Engine 10.8.1 LLDP is enabled by default for the AP5020. |
| HOS-22152 | AP4020: Support 802.3az Green Ethernet | IQ Engine 10.8.1 supports Energy-Efficient Ethernet (EEE) or IEEE 802.3az for the AP4020. This feature allows physical-layer transmitters to consume less power during idle states or low data activity. |
| HOS-22381 | AP4020—"RegreSSHion" Vulnerability in OpenSSH | CVE-2024-6387, also known as the "regreSSHion" vulnerability, is fixed. |

Addressed Issues in Release 10.8.1

| Issue ID | Description |
|-----------|---|
| CFD-13308 | We increased the AUTH timeout value to give users sufficient time to enter the credentials for AP5000 and AP5020. |
| CFD-13309 | We resolved an issue where the AP5020 sent probe responses with a basic rate of 24Mbps instead of the configured 36Mbps. |
| CFD-13374 | We resolved an issue where AP5020 models with shut-down SSIDs were still broadcasting with Open Authentication, even after rebooting. |

Release 10.8.2 New Features and Addressed Issues

New Hardware Support

There is no new hardware supported for Release 10.8.2.

Table 2: New features in 10.8.2

| Feature ID | New feature | Description |
|------------|---|---|
| HOS-18924 | AP5020: Client mode support 2.4, 5G , 6G | IQ Engine supports Client Mode on 2.4 GHz, 5 GHz, & 6 GHz radios on the AP5020. |
| HOS-18929 | AP5020: Support for Spectrum Analyzer 2.4G/5G | The 2.4 GHz & 5 GHz radios on the AP5020 support Spectrum Intelligence. |

Table 2: New features in 10.8.2 (continued)

| Feature ID | New feature | Description |
|------------|--|---|
| HOS-20276 | Enhancement to Reduced Neighbor Report (RNR) - AP3K, AP5010/5050 | The AP3000, AP3000X, AP5010, AP5050U, and AP5050D support Enhanced Reduced Neighbor Report (eRNR). This feature adds advanced RNR capability and provides useful information to Wi-Fi 6E/7 clients by probing in the 2.4 and 5 GHz bands for Wi-Fi 6 SSID capabilities for the radio housed in the AP. The probe also looks for neighbor APs to which the client could eventually roam. The Co-Located bit in the RNR IE indicates that the 6 GHz radio is housed in the same AP. A value of 0 indicates a different BSSID for a neighboring 6 GHz radio. |
| HOS-20642 | AP5020: Support for WPA3 Beacon Protection | The AP5020 supports Wi-Fi 7 Beacon Protection to protect Wi-Fi beacon frames from disruption or interference. |
| HOS-20751 | AP4020: Support for AKM 24 for WPA3-Personal (SAE) | The AP4020 supports WPA-3 Personal (SAE) AKM 24. |
| HOS-20752 | AP4020: Support for WPA3 Beacon Protection | The AP4020 supports Wi-Fi 7 Beacon Protection to protect Wi-Fi beacon frames from disruption or interference. |
| HOS-21357 | AP4020: Support for Spectrum Analyzer 2.4G/5G | The 2.4 GHz & 5 GHz radios on the AP4020 support Spectrum Intelligence. |
| HOS-21359 | AP4020: Client Mode supports 2.4, 5G, 6G | IQ Engine supports Client Mode on 2.4 GHz, 5 GHz, & 6 GHz radios on the AP4020. |
| HOS-21537 | AP4020: Support for Essentials Sensing 4th radio | IQ Engine supports the 4th radio on the AP4020 reporting to Essentials. |
| HOS-21713 | AP4020: Support for dynamic packet capture | The AP4020 supports Dynamic Packet Capture. |
| HOS-21979 | Port Description (TLV) to LLDP Neighbor (AX & 4000) | We added the "Port Description" to the #show LLDP Neighbor output in IQ Engine (AP305C, AP410C, AP460C, AP305CX, AP460S6, S12, and 4000) |
| HOS-22052 | HotSpot 2.0 Configuration In IQ Engine for the AP4000 | The AP4000 supports HotSpot 2.0. |
| HOS-22053 | HotSpot 2.0 Configuration In IQ Engine for the AP4020 | The AP4020 supports HotSpot 2.0. |

Table 2: New features in 10.8.2 (continued)

| Feature ID | New feature | Description |
|------------|--|---|
| HOS-22078 | Enable the FIPS feature for AP4020 | The AP4020 supports Secure-Mode for GovRAMP-compliant RDCs. |
| HOS-22239 | Report BLE Scan Results via HTTPS with Token Renewal for WiFi 6E | WiFi 6E APs support a token-based secure method of sending BLE Data to an HTTPS server. |

Table 3: Addressed issues in 10.8.2

| Issue ID | Description |
|-------------------------|--|
| CFD-12903 (03038362) | We resolved an issue where the error " <code>^-- unknown keyword or invalid input</code> " occurred when using CLI Access from ExtremeCloud IQ. |
| CFD-12949 (03038743) | We resolved an issue where a vulnerability was detected for HTTP/HTTPS on APs running IQ Engine 10.7r3. |
| CFD-13238 (03056232) | We resolved a latency issue with the AP5010 running IQ Engine Release 10.7.3 or 10.7.5. |
| CFD-13524 (03074406) | We resolved an issue where local PPSK user groups caused the configuration audit for APs running IQ Engine Release 10.7.5 to report missing users. |
| CFD-13628 (03082265) | We resolved an issue where some APs in the same management VLAN flooded logs with " <code>pmksa_cache_auth_add</code> ". The issue occurred with the 11r feature enabled in ExtremeCloud IQ, when an 11r-supported client connected or disconnected. This issue is fixed in Release 10.8.2 by enabling the log only when debug auth is on. |
| HOS-22363 | We resolved an issue where packet captures for an AP4020 running IQ Engine 10.8.1 using the Enhanced Packet Capture tool in ExtremeCloud IQ did not include beacon frames. |
| HOS-22445 | We resolved an issue with the AP4020 and ADSP-sensor mode and BSS/air-termination, where the sensor successfully sent DeAuth packets, and errors occurred after a few hours. |
| HOS-22670 | We resolved an issue with the error: Check certificates and key files failed. For IQ Engine Release 10.8.2, we strongly recommend updating your certificates to use cryptographic keys of at least 2048 bits with a widely accepted strong algorithm. |

Release 10.8.2a New Features and Addressed Issues

New Hardware Support

There is no new hardware supported for Release 10.8.2a.

New Features in Release 10.8.2a

There are no new features in this release.

Addressed Issues in Release 10.8.2a

This patch release resolves an issue for the AP4020 and AP5020 access points, where the ACSP (RRM protocol) could select the same 6 GHz channel as a neighboring access point.

Release 10.8.3 New Features and Addressed Issues

New Hardware Support

There is no new hardware supported for Release 10.8.3.

New Features in 10.8.3

| Feature ID | New feature | Description |
|------------|--|--|
| HOS-21750 | Wi-Fi 7 Platforms - Enhancement to Reduced Neighbor Report (RNR) | Enhanced Reduced Neighbor Report (RNR) provides improved roaming for 6 GHz clients. |
| HOS-22323 | Fabric-Attach (Autosense) IQ Engine new Default LLDP Handling (AP302W, AP305C, AP410C, AP460C, AP510C) | IQ Engine 10.8.3 enables LLDP for the AP302W, AP305C, AP410C, AP460C, and AP510C by default. |
| HOS-22984 | Fabric-Attach (Autosense) IQ Engine new Default LLDP Handling (AP4000) | IQ Engine 10.8.3 enables LLDP for the AP4000 by default. |

Addressed Issues in 10.8.3

| Issue ID | Description |
|----------------------|---|
| CFD-13644 (03082327) | We resolved an issue where ExtremeCloud IQ and CLI displayed different values for the AP5020 WiFi2 channel width. |
| CFD-13950 (03056147) | We resolved an issue where ExtremeCloud IQ did not reflect a change in VLAN/Subnet in "show int usb0". |
| HOS-22705 | We resolved an issue where the AP4020 crashed when using Spectrum Intelligence on WiFi0 (2.4 GHz). |
| HOS-22838 | We increased the allocated memory for 3-radio access points (AP4000, AP4000U, AP4020, AP5010, AP5020, AP5050D, AP5050U) from 20 Mb to 64 Mb. This increase resolves issues reported in CFD-13612. |

| Issue ID | Description |
|-----------|---|
| HOS-22874 | We implemented a fix to add 6G neighbors (different SSID) with ERNR enabled to all 2.4G and 5G BSS with ERNR enabled. |
| HOS-22959 | We resolved an issue where an L7 crash occurred on the AP4020 with the AVC (ZOOM) application. |
| HOS-22967 | We resolved an issue where IDM authentication (Enterprise and PPSK) failed on FIPS-enabled APs. |
| HOS-22982 | We resolved an issue where parsing certificates and key files failed on the AP5020. |
| HOS-23131 | We resolved an issue where the IDM Certificate failed to apply on AP3000, AP5010, and AP5050 devices. We strongly advise that you upgrade your certificates to use cryptographic keys of at least 2048 bits with a widely accepted strong algorithm. |

Release 10.8.4 New Features and Addressed Issues

New Hardware Support

Release 10.8.4 introduces support for the following new hardware:

- AP4020FX
- AP4020X
- AP4060

New Features in 10.8.4

| Feature ID | New feature | Description |
|------------|--|--|
| HOS-20013 | AP5020 to AP5020 WiFi mesh support for WDO | The AP5020 supports mesh/wireless bridge on 2.4 Ghz, 5 GHz, and 6 GHz. |
| HOS-21281 | Change Primary Default IQE Public DNS (Including Factory Images) | OpenDNS became unavailable in certain countries and territories. Therefore, we changed the primary public DNS for IQ Engine from OpenDNS to Cloudflare (1.0.0.1). The secondary public DNS entry for IQ Engine is still OpenDNS (208.67.220.220). This change applies to the following models: AP3000, AP3000X, AP4020, AP4020X, AP4020FX, AP5010, AP5020, AP5050D, and AP5050U. |
| HOS-21553 | IQ Engine Support for the AP4020FX Platform | IQ Engine supports the AP4020FX platform. |
| HOS-21554 | IQ Engine Support for the AP4060X Platform | IQ Engine supports the AP4060X platform. |
| HOS-21556 | IQ Engine Support for the AP4060 Platform | IQ Engine supports the AP4060 platform. |

| Feature ID | New feature | Description |
|------------|---|---|
| HOS-21587 | AP4020FX: Support for Indoor AFC | The AP4020FX supports Indoor AFC. |
| HOS-21810 | Solum dongle support for WiFi 7 APs | The AP4020, AP4020X, AP4020FX, and AP5020 support the Solum dongle. |
| HOS-21811 | Hanshow dongle support for WiFi 7 APs | The AP4020, AP4020X, AP4020FX, and AP5020 support the Hanshow dongle. |
| HOS-22600 | Update Curl in IQ Engine— 11ax and AP4000 | IQ Engine for the 802.11AX APs and the AP4000 has been updated to address two CVEs: <ul style="list-style-type: none"> • CVE-2018-1000005 • CVE-2018-1000007 |
| HOS-22626 | Update the OpenSSH Version to the Latest (AX & 4K) | We strongly recommend that you upgrade OpenSSH to the latest available version. For more information, see CVE-2024-6387. |
| HOS-22811 | AP4060/X: Add Outdoor Mode to Access Point (IQ Engine Only) | The AP4060 and AP4060X support outdoor AFC for 6 GHz standard power (IQ Engine only). |
| HOS-22858 | IQ Engine: Standards-Based GRE Failover | IQ Engine supports a secondary Standards-based GRE IP Address. This feature introduces the new Failover IP Address field. |
| HOS-23199 | Fabric Attach Redundancy Support | Fabric Attach for IQ Engine supports redundancy (red0) on AP3000, AP3000X, AP4000, AP4000U, AP4020, AP5010, AP5020, and AP5050D. Therefore, when a failover from Eth0 to Eth1 occurs, the failover maintains the VLAN to I-SID mapping. |
| HOS-23248 | WBA OpenRoaming Support In IQ Engine— AP4020X support | The AP4020X supports the WBA OpenRoaming feature. |
| HOS-23332 | AP4060/AP4060X for Outdoor AFC Support | The AP4060 & AP4060X support outdoor AFC (6 GHz Standard Power, for IQ Engine only). |

Addressed Issues in 10.8.4

| Issue ID | Description |
|-------------------------|---|
| CFD-13173 (03053176) | We resolved an issue where a scheduled scan did not run, even when a trigger condition existed. |
| CFD-13506 (03064391) | We resolved an issue where communication occurred between devices connected to an AP5020, with the Inter-station Traffic setting disabled. |
| CFD-13749 (03087413) | We resolved an issue where incorrectly displayed network health as 0/100 Poor . |

| Issue ID | Description |
|-------------------------|--|
| CFD-13977 (03094885) | We resolved an issue where AP302W devices configured for a maximum power drop of 3dB, were dropping by 11dB. |
| CFD-14176 (03101888) | We resolved an issue where ExtremeCloud IQ ignored the RADIUS VLAN attribute when using PPSK with MAC authentication and user profile classification. |
| CFD-14224 (03097693) | We resolved an issue where neighboring APs chose the same 5GHz DFS channel when the SDR profile was enabled. |
| CFD-14289 (03123431) | We resolved an issue where AP410C devices experienced random high CPU usage spikes. |
| CFD-14436 (02916216) | We resolved an issue where an AP5010 repeatedly experienced an Unable to handle kernel paging request at virtual address 000103f4aa00040b error. |
| CFD-14956 (03154832) | We resolved an issue where wifi0 radio went down for AP5020 devices upgraded to 10.8.3 and was restored after downgrading to 10.8.2a. |
| HOS-23136 | We resolved an issue where beacon protection was not enabled for all 6GHz SSIDs. For example, if an SSID is on both the 5GHz and 6GHz bands and beacon protection is disabled on 5GHz, beacon protection is still mandatory for the 6GHz band. |

Release 10.8.5 New Features and Addressed Issues

New Hardware Support

There is no new hardware supported for Release 10.8.5.

New Features in 10.8.5

| Feature ID | New Feature | Description |
|------------|---|--|
| HOS-23332 | AP4060/4060X Outdoor AFC Support | Added Automated Frequency Coordination support for AP4060 and AP4060X access points operating in outdoor mode. |
| HOS-23092 | AP4060/X Essentials Sensing 4th Radio Support | Introduced shared sensing support for 2.4 GHz and 5 GHz bands on the fourth radio to enable WIPS Essentials applications and ADSP on-premises functionality on AP4060/X platforms. |
| HOS-23079 | AP4020FX Essentials Sensing 4th Radio Support | Introduced shared sensing support for 2.4 GHz and 5 GHz bands on the fourth radio to enable WIPS Essentials applications and ADSP on-premises functionality on AP4020FX platforms. |

| Feature ID | New Feature | Description |
|------------|--|---|
| HOS-23062 | AP4020X Essentials Sensing 4th Radio Support | Introduced shared sensing support for 2.4 GHz and 5 GHz bands on the fourth radio to enable WIPS Essentials applications and ADSP on-premises functionality on AP4020X platforms. |
| HOS-22905 | OpenSSH Version Update | Updated OpenSSH to version 10.0p2 for AX and 4K series access points (platforms 302W, 305C, 410C, 460C, 510C, 4000) to address CVE-2024-6387 security vulnerability. |
| HOS-22811 | AP4060/X Outdoor Mode Support | Added outdoor operational mode configuration capability for AP4060 and AP4060X access points, including support for outdoor omni-angle mount and outdoor fixed-angle mount deployment options. |
| HOS-22770 | LLDP System Capabilities Enhancement | Enhanced LLDP neighbor information by adding system capabilities and enabled capabilities data to the LLDP/CDP Info EVENT, enabling improved network topology visibility and switch identification. |
| HOS-21556 | AP4060 IQEngine Platform Support | Introduced IQEngine support for the AP4060 access point platform, including indoor and outdoor mode configurations. |
| HOS-21554 | AP4060X IQEngine Platform Support | Introduced IQEngine support for the AP4060X access point platform with external antenna capability. |

Addressed Issues in 10.8.5

| Issue ID | Description |
|-----------|--|
| HOS-23697 | Fixed an issue where AP5020 access points were missing power configurations for radios A, AN-HT20, and AC-VT80 in the Isle of Man (IM) country code. The compliance table has been updated to include the correct power settings for this region. |
| HOS-21883 | Addressed the issue where AP5020, AP5000, AP4000, AP5050, and AP4060 access points exhibited low antenna power output when increasing transmit power settings. This affected multiple channel bandwidths (20MHz, 40MHz, and 80MHz) on the 5GHz band, where certain antennas showed significantly reduced power levels at higher configured power settings. |

Release 10.8.5b New Features and Addressed Issues

New Hardware Support

There is no new hardware supported for Release 10.8.5b.

New Features in 10.8.5b

| Feature ID | New Feature | Description |
|------------|---|--|
| HOS-19952 | Support for Packet Capture on Thread interface —AP5010 | The Packet Capture tool supports the Thread Interface on the AP5010. |
| HOS-23474 | Thread: Refactor commissioner start and stop | When the Thread Commissioner Start or Stop function is used, the commissioning operation applies at the building level rather than targeting individual device IDs. This change improves device onboarding in scenarios where the Thread network has become segmented, resulting in multiple isolated Thread network partitions. |
| HOS-23898 | IQ Engine to Add MD4 for Legacy Supplicant Authentication | We added the MD4 cryptographic module back into IQ Engine to support backwards compatibility for legacy authentication, such as PEAP-MSCHAPv2, for both wired and wireless. This update resolves CFD-14824. |

Addressed Issues in 10.8.5b

| Issue ID | Description |
|--|---|
| CFD-15141 (03169486) | Fixed an issue where the 6th- and 9th-generation Apple iPad (MR7F2LL/A) failed to connect to a WPA3 SSID with 802.11r enabled on AP5010 running IQ Engine 10.8.3. The AP incorrectly processed iPad association requests, treating the WPA IE version as WPA2 and rejecting the RSN information element when 802.11r mobility domain information was present. |
| CFD-15234 (03176342) | Fixed an issue where the client snapshot report on AP5020 displayed SSID names as unrecognizable or corrupted symbols. The SSID name field in the DCD stats snapshot incorrectly populated with garbage values instead of the actual SSID string upon client association. |
| CFD-15356 (03177352) | Addressed the issue where AP5020 units running IQ Engine 10.8.2a reported a gradual increase in memory utilization from approximately 48% after reboot to up to 70% over the course of a week, along with FWTRAP-related reboots. The memory usage increase and FW trap crashes are resolved in IQ Engine 10.8.3a and later. |
| CFD-15385 (03172946, 03218917, 03225560) | Fixed an issue where Wi-Fi sub-interfaces were missing from the authentication host access point daemon (HAPD) interface list after an SSID un-bind and re-bind sequence or following a power outage. This caused security SSIDs to broadcast as Open SSIDs, or prevented Open SSIDs from assigning IP addresses to clients. |

| Issue ID | Description |
|--------------------------------------|--|
| CFD-15554 (03192730) | Fixed an issue where AP5020 and AP4020 units running IQ Engine 10.8.4 or 10.8.5 crashed with a kernel panic triggered by a NULL pointer dereference in the Broadcom Wi-Fi driver key management receive path (wlc_keymgmt_recvdata). The crash also occurred in the ADSP sensor receive path (ah_adsp_sensor_rx) under IQ Engine 10.8.5. |
| CFD-15607 (03193484, 03237962) | Fixed an issue where AP4020 units running IQ Engine 10.8.3a or 10.8.4 rebooted randomly because an attempt to read from an unreadable memory address in the wlc_keymgmt_recvdata path of the Broadcom WLAN driver cause a kernel panic. |
| CFD-15648 (03175771) | Fixed an issue where Zebra MC3300x and WT6000 handheld scanners periodically disconnected from AP510CX. The ARP requests from the scanners were held in the AP beyond the tolerance threshold of the client before being forwarded, causing the client to interpret the lack of response as a connectivity failure and disconnect. |
| CFD-15695 (03201360) | Fixed an issue where AP5010 units running IQ Engine 10.8.3a rebooted frequently with a kernel panic triggered by a NULL pointer dereference in the wipsk (WIPS) module during ADSP air termination processing. The crash occurred in the Fpm_ThreadFunc path when the ADSP sensor transmitted deauthentication frames to rogue clients. |
| CFD-15764 (03190727) | Fixed an issue where the lighttpd web server process on AP5020 units running IQ Engine 10.8.2a and 10.8.5 failed to restart automatically after a crash, causing the Guest Essentials captive portal to stop functioning. TCP traffic interception was also disrupted due to TCP RST packets. A factory reset was required to restore portal functionality. |
| CFD-15804 (03209689) | Fixed an issue where AP410C-1 units running IQ Engine 10.8.4 and 10.8.5 crashed with a kernel panic in the ah_cwp_vector function within the forwarding engine (fe) module. The crash occurred during ingress packet processing and affected multiple APs across deployments. |
| CFD-15819 (03208411) | Fixed an issue where AP5020 units did not apply the configured 2.4 GHz minimum basic rate (MBR) after any type of reboot, including factory reset. The AP broadcasted legacy 802.11b rates (1, 2, 5.5, 11 Mbps) despite the running configuration reflecting the correct MBR settings. A Delta update or CLI push was required to enforce the correct rates in the current boot cycle. |
| CFD-15880 (000131745) | Fixed an issue where the SNMP process on AP5020 units running IQ Engine 10.8.2a failed and generated core dumps within hours of a complete configuration push. Rebooting the AP temporarily restored SNMP functionality, but the process continued to fail intermittently. |
| CFD-15948 (03202131) | Addressed the issue where Windows clients failed to connect to a WPA3 SSID on AP410C running IQ Engine 10.8.5, while macOS clients connected successfully. The issue persisted even with 802.11r disabled and with updated Windows Wi-Fi drivers. Enabling WPA2 as a workaround restored client connectivity. |

| Issue ID | Description |
|-----------------------------------|--|
| CFD-15960 (03220254) | Fixed an issue where AP5020 units running IQ Engine 10.8.4 and 10.8.5 rebooted due to firmware (FW) trap events, primarily TRAP type 0x7, and non-maskable interrupt (NMI)-triggered hardware watchdog resets. The issue affected approximately 6 out of 100 APs in the deployment. |
| CFD-16013 (03223115, 03231632) | Fixed an issue where Windows 11 clients failed to authenticate to an 802.1x SSID when the AP acting as the RADIUS server ran IQ Engine 10.8.5. The client connected successfully on IQ Engine 10.8.3 and 10.8.4. Other client operating systems such as Android and iOS were unaffected. |
| CFD-16064 (03223727) | Fixed an issue where Wi-Fi clients intermittently failed to obtain a DHCP IP address when connecting to a Guest Essentials SSID on AP5020 running IQ Engine 10.8.5. The forwarding engine dropped DHCP Discover packets with a "dhcp: blocked, drop pak" error. The issue did not occur on IQ Engine 10.8.2a. |
| CFD-16085 (03225809) | Addressed the issue where the active client count displayed in XIQ under Manage > Devices did not match the actual client count reported by the AP CLI. The discrepancy occurred randomly across APs in environments with mixed XIQ-SE and standard AP data sources. |
| CFD-16150 (03227182) | Fixed an issue where the weak SNR probe request suppression feature did not function on AP5020 running IQ Engine 10.7r5 and later, including 10.8.3 and 10.8.5. Clients with an SNR below the configured suppression threshold were still permitted to associate. The feature worked correctly on IQ Engine 10.7.3. The root cause is related to a conflict with the dynamic capture function. |
| CFD-16261 (03234068) | Fixed an issue where AP5020 units continued to broadcast beacon and probe response frames for SSIDs that were in a shutdown state during the ACSP channel selection process. Clients associated with the shut-down SSID received an IP address of 0.0.0.0 and could not complete the connection process. |
| HOS-22918 | Fixed an issue where iPhone 16 failed to roam with WPA3 FT- SAE+beacon protection (5ghz/6ghz) configured on AP5020 and AP4020 APs. |
| HOS-24087 | Fixed an issue where AP3000 and AP5000 series clients failed to connect to the AD server. |