

Customer Release Notes

VSP Operating System Software

Software Release 9.2.3.0

February 2026

INTRODUCTION:

This document provides specific information for version 9.2.3.0 of agent software for the VSP Operating System Software.

The purpose of this version is to address customer and internally found software issues.

Newly Purchased Switches Require Software Upgrade. You should promptly upgrade the VOSS software to the latest version available by visiting the Extreme Portal.

Extreme Networks recommends that you thoroughly review this document prior to installing or upgrading this product.

For the latest firmware versions, visit the download site at:
www.extremenetworks.com/support/

NEW IN THIS RELEASE:

None.

IMPORTANT NOTES BEFORE UPGRADING TO THIS RELEASE:

Please see "VOSS Release Notes for version 9.2.0.0" available at
<https://www.extremenetworks.com/support/release-notes>

UPGRADE CONSIDERATIONS WHEN UPGRADING TO 9.2.3.0 FROM PREVIOUS RELEASES:

Please see "VOSS Release Notes for version 9.2.0.0" available at
<https://www.extremenetworks.com/support/release-notes>

PLATFORMS SUPPORTED:

Please see "VOSS Release Notes for version 9.2.0.0" available at
<https://www.extremenetworks.com/support/release-notes> for details regarding supported platforms.

FILE NAMES FOR THIS RELEASE:

Virtual Services Platform 4900 Series

File Name	Module or File Type	File Size (bytes)
FabricIPSecGW_VM_5.2.0.0.ova	Fabric Ipsec Gateway Virtual Machine	4034211840
restconf_yang.tgz	YANG Model	506020
TPVM_Ubuntu20.04_04_14Apr2022.qcow2	Third Party Virtual Machine	4641982464
VOSS4900.9.2.3.0_edoc.tar	Logs Reference	39854080
VOSS4900.9.2.3.0.md5	MD5 Checksums	611
VOSS4900.9.2.3.0_mib_sup.txt	MIB - supported object names	1570551
VOSS4900.9.2.3.0_mib.txt	MIB - objects in the OID compile order	8657615
VOSS4900.9.2.3.0_mib.zip	Archive of all MIB files	1284341
VOSS4900.9.2.3.0_oss-notice.html	Open-source software - Master copyright file	2889456
VOSS4900.9.2.3.0.sha512	SHA512 Checksums	1722
VOSS4900.9.2.3.0.tgz	Release 9.2.3.0 archived software distribution	325360553
VOSSv9.1.0_HELP_EDM_gzip.zip	EDM Help file	5569440

Virtual Services Platform 7400 Series

File Name	Module or File Type	File Size (bytes)
FabricIPSecGW_VM_5.2.0.0.ova	Fabric Ipsec Gateway Virtual Machine	4034211840
restconf_yang.tgz	YANG model	506020
TPVM_Ubuntu20.04_04_14Apr2022.qcow2	Third Party Virtual Machine (TPVM)	4641982464
VOSS7400.9.2.3.0_edoc.tar	Logs Reference	39854080
VOSS7400.9.2.3.0.md5	MD5 Checksums	611
VOSS7400.9.2.3.0_mib_sup.txt	MIB - supported object names	1571930
VOSS7400.9.2.3.0_mib.txt	MIB - objects in the OID compile order	8657615
VOSS7400.9.2.3.0_mib.zip	Archive of all MIB files	1284341
VOSS7400.9.2.3.0_oss-notice.html	Open-source software - Master copyright file	2889456
VOSS7400.9.2.3.0.sha512	SHA512 Checksums	1722
VOSS7400.9.2.3.0.tgz	Release 9.2.3.0 archived software distribution	324985400
VOSSv9.1.0_HELP_EDM_gzip.zip	EDM Help file	5569440

Note about image download:

Ensure images are downloaded using the binary file transfer. Perform MD5 checksum check on downloaded files to ensure file integrity.

Check that the file type suffix is “.tgz” and the image names after download to device match those shown in the above table. Some download utilities have been observed to append “.tar” to the file name or change the filename extension from “.tgz” to “.tar”. If file type suffix is “.tar” or file name does not exactly

match the names shown in above table, rename the downloaded file to the name shown in the table above so that the activation procedures will operate properly.

Load activation procedures:

```
software add VOSS4900.9.2.3.0.tgz
software activate 9.2.3.0.GA
```

or

```
software add VOSS7400.9.2.3.0.tgz
software activate 9.2.3.0.GA
```

CHANGES IN THIS RELEASE:

New Features in This Release
None

Old Features Removed From This Release
None

Problems Resolved in This Release	
CFD-13575	FabricIPSecGW_VM_5.2.0.0.ova was not working after upgrade.
CFD-14443	Fan query via SNMP results in “Fan not present”.
CFD-14694	An unexpected reboot may be triggered after processing a RADIUS request related to an accounting interim-update packet.
CFD-15426	Incorrect ARP processing with Anycast Gateway One-IP, triggering dropped replies (no CLIP) and unresponsive hosts (with CLIP).
CFD-15427	Unable to locally ping the Anycast Gateway IP address even though it is reachable from other external devices.
CFD-15468	An unexpected reboot may be triggered when a BOOTP or DHCP packet is processed.
CFD-13965, VOSS-34163	ISIS hello-auth key configuration may be lost after a power outage event.
CFD-15593	In a DVR environment, a data structure being accessed concurrently from multiple threads without proper synchronization may cause an unexpected reboot.
CFD-15657	If Radius I-SID is identical to Fail-Open I-SID, it is not kept on the port after the Radius server becomes reachable again.
CFD-15670	Static SWUNI configuration triggers warnings when Radius authorizes MACs but supplies no VLAN/I-SID mappings.
CFD-15687	After a reboot or if LACP aggregates after TUNI MLT is already configured, LLDP packets received on LAG ports are not copied to CPU on TUNI.
CFD-15773, VOSS-34392	Manual restart of ZTP creates multiple ztpOperCheck threads.
CFD-15892	Newly configured ACE is doing its action even though ACL is operationally disabled.
CFD-15896	If a UNI port is channelized after the I-SID is configured and redistributed in Multi-Area mode, NNI traffic fails to egress traffic on UNI subports.

Problems Resolved in This Release	
CFD-15950	VLAN is wrongly configured as tagged rather than untagged when using legacy RADIUS VLAN/I-SID mappings with auto-isid configured.
CFD-15951	On a specific scenario, NNI channelized ports may drop traffic due to an incorrectly programmed ASIC table.
VOSS-34563	ISIS Hello packets should not be padded for Fabric Extend logical interface with configured MTU.
CFD-16058, CFD-16062, CFD-16079	Restarting dhclient process during reboot creates a core file.
CFD-16080	An unexpected reboot may occur due to an improper data structures handling.
CFD-16093	Restconf authentication may fail with user defined RWA access level account.
CFD-16195	LLDP neighbor does not get discovered with MACSEC enabled on port.
CFD-16408	IPv6 VRRP adv-int command is not correctly reflected in configuration.

Fixes from Previous Releases
VOSS 9.2.3.0 incorporates all fixes and content from previous releases including VOSS 8.10.9.0, VOSS 9.0.5.1, VOSS 9.1.3.0 and VOSS 9.2.2.0.

OUTSTANDING ISSUES:

Please see “VOSS Release Notes for version 9.2.0.0” available at <https://www.extremenetworks.com/support/release-notes> for details regarding Known Issues.

CFD-11778	A loop may occur for few seconds before LACP SMLT comes up A fix for this issue is available starting with 9.3.0.0 release
CFD-13260	L3 connectivity lost to all devices over the Fabric Extend link when ISIS remote is enabled, but there is no ISIS remote interface Workaround: disable ISIS remote A fix for this issue is available starting with 9.3.0.0 release
CFD-13322	IPv6 FHS DHCP-Snooping does not work in Fabric mode A fix for this issue is available starting with 9.3.0.0 release
CFD-13639	In an MA environment, prefixes might be installed wrongly on OSPF ASBR routing table A fix for this issue is targeted for 9.4.0.0 release
CFD-14948	A data forwarding issue was identified in environments utilizing vIST where MAC addresses move rapidly between access points (APs). This behavior resulted in a mismatch between hardware and software forwarding tables, leading to packet drops A fix for this issue is available starting with 9.3.1.0 release
CFD-15107	FA Interface authentication may fail after a reboot Workaround: reconfigure FA key A fix for this issue is available starting with 9.3.1.0 release
CFD-15125	In a specific scenario involving inter-VRF static routes, a static route entry may fail to be programmed into the hardware forwarding tables A fix for this issue is available starting with 9.3.1.0 release
CFD-15355	Wireless clients on FA dynamic VLANs fail to get DHCP IP address when no platform VLAN exists for the same A fix for this issue is targeted for 9.5.0.0 release
CFD-15424	In a vIST environment, if the NNIs are configured through auto-sense, a loop occurs for few seconds before LACP SMLT comes up Workaround: statically configure the vIST NNIs A fix for this issue is targeted for 9.4.0.0 release

KNOWN LIMITATIONS:

Please see “VOSS Release Notes for version 9.2.0.0” available at <https://www.extremenetworks.com/support/release-notes> for details regarding Known Limitations.

Regular cleanup of unneeded files on USB drives is recommended to minimize possibility of USB corruption when a system is reset, shut down, or power is lost.

DOCUMENTATION CORRECTIONS:

For other known issues, please refer to the product release notes and technical documentation available at: <https://www.extremenetworks.com/support/documentation>.

GLOBAL SUPPORT

By Phone: +1 800-998-2408 (toll-free in U.S. and Canada)

For the toll-free support number in your country:
www.extremenetworks.com/support/

By Email: support@extremenetworks.com

By Web: www.extremenetworks.com/support/

By Mail: Extreme Networks, Inc.
6480 Via Del Oro
San Jose, CA 95119

For information regarding the latest software available, recent release note revisions, or if you require additional assistance, please visit the Extreme Networks Support website.

Copyright © 2026 Extreme Networks, Inc. - All Rights Reserved.

Legal Notice

Extreme Networks, Inc. reserves the right to make changes in specifications and other information contained in this document and its website without prior notice. The reader should in all cases consult representatives of Extreme Networks to determine whether any such changes have been made.

The hardware, firmware, software or any specifications described or referred to in this document are subject to change without notice.

Trademarks

Extreme Networks and the Extreme Networks logo are trademarks or registered trademarks of Extreme Networks, Inc. in the United States and/or other countries. All other names (including any product names) mentioned in this document are the property of their respective owners and may be trademarks or registered trademarks of their respective companies/owners.

For additional information on Extreme Networks trademarks, please see:

www.extremenetworks.com/company/legal/trademarks