

BayRS Version 12.04 and Site Manager Software Version 6.04 Release Notes

BayRS Version 12.04
Site Manager Software Version 6.04

Part No. 301894-D Rev. 00
March 1999



Bay Networks

Where Information Flows.™



Copyright © 1999 Bay Networks, Inc.

All rights reserved. Printed in the USA. March 1999.

The information in this document is subject to change without notice. The statements, configurations, technical data, and recommendations in this document are believed to be accurate and reliable, but are presented without express or implied warranty. Users must take full responsibility for their applications of any products specified in this document. The information in this document is proprietary to Bay Networks, Inc.

The software described in this document is furnished under a license agreement and may only be used in accordance with the terms of that license. A summary of the Software License is included in this document.

Trademarks

AN, BLN, GAME, and Bay Networks are registered trademarks and ARN, BayRS, and the Bay Networks logo are trademarks of Bay Networks, Inc.

All other trademarks and registered trademarks are the property of their respective owners.

Restricted Rights Legend

Use, duplication, or disclosure by the United States Government is subject to restrictions as set forth in subparagraph (c)(1)(ii) of the Rights in Technical Data and Computer Software clause at DFARS 252.227-7013.

Notwithstanding any other license agreement that may pertain to, or accompany the delivery of, this computer software, the rights of the United States Government regarding its use, reproduction, and disclosure are as set forth in the Commercial Computer Software-Restricted Rights clause at FAR 52.227-19.

Statement of Conditions

In the interest of improving internal design, operational function, and/or reliability, Bay Networks, Inc. reserves the right to make changes to the products described in this document without notice.

Bay Networks, Inc. does not assume any liability that may occur due to the use or application of the product(s) or circuit layout(s) described herein.

Portions of the code in this software product may be Copyright © 1988, Regents of the University of California. All rights reserved. Redistribution and use in source and binary forms of such portions are permitted, provided that the above copyright notice and this paragraph are duplicated in all such forms and that any documentation, advertising materials, and other materials related to such distribution and use acknowledge that such portions of the software were developed by the University of California, Berkeley. The name of the University may not be used to endorse or promote products derived from such portions of the software without specific prior written permission.

SUCH PORTIONS OF THE SOFTWARE ARE PROVIDED "AS IS" AND WITHOUT ANY EXPRESS OR IMPLIED WARRANTIES, INCLUDING, WITHOUT LIMITATION, THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE.

In addition, the program and information contained herein are licensed only pursuant to a license agreement that contains restrictions on use and disclosure (that may incorporate by reference certain limitations and notices imposed by third parties).

Bay Networks, Inc. Software License Agreement

NOTICE: Please carefully read this license agreement before copying or using the accompanying software or installing the hardware unit with pre-enabled software (each of which is referred to as "Software" in this Agreement). BY COPYING OR USING THE SOFTWARE, YOU ACCEPT ALL OF THE TERMS AND CONDITIONS OF THIS LICENSE AGREEMENT. THE TERMS EXPRESSED IN THIS AGREEMENT ARE THE ONLY TERMS

UNDER WHICH BAY NETWORKS WILL PERMIT YOU TO USE THE SOFTWARE. If you do not accept these terms and conditions, return the product, unused and in the original shipping container, within 30 days of purchase to obtain a credit for the full purchase price.

1. License Grant. Bay Networks, Inc. (“Bay Networks”) grants the end user of the Software (“Licensee”) a personal, nonexclusive, nontransferable license: a) to use the Software either on a single computer or, if applicable, on a single authorized device identified by host ID, for which it was originally acquired; b) to copy the Software solely for backup purposes in support of authorized use of the Software; and c) to use and copy the associated user manual solely in support of authorized use of the Software by Licensee. This license applies to the Software only and does not extend to Bay Networks Agent software or other Bay Networks software products. Bay Networks Agent software or other Bay Networks software products are licensed for use under the terms of the applicable Bay Networks, Inc. Software License Agreement that accompanies such software and upon payment by the end user of the applicable license fees for such software.

2. Restrictions on use; reservation of rights. The Software and user manuals are protected under copyright laws. Bay Networks and/or its licensors retain all title and ownership in both the Software and user manuals, including any revisions made by Bay Networks or its licensors. The copyright notice must be reproduced and included with any copy of any portion of the Software or user manuals. Licensee may not modify, translate, decompile, disassemble, use for any competitive analysis, reverse engineer, distribute, or create derivative works from the Software or user manuals or any copy, in whole or in part. Except as expressly provided in this Agreement, Licensee may not copy or transfer the Software or user manuals, in whole or in part. The Software and user manuals embody Bay Networks’ and its licensors’ confidential and proprietary intellectual property. Licensee shall not sublicense, assign, or otherwise disclose to any third party the Software, or any information about the operation, design, performance, or implementation of the Software and user manuals that is confidential to Bay Networks and its licensors; however, Licensee may grant permission to its consultants, subcontractors, and agents to use the Software at Licensee’s facility, provided they have agreed to use the Software only in accordance with the terms of this license.

3. Limited warranty. Bay Networks warrants each item of Software, as delivered by Bay Networks and properly installed and operated on Bay Networks hardware or other equipment it is originally licensed for, to function substantially as described in its accompanying user manual during its warranty period, which begins on the date Software is first shipped to Licensee. If any item of Software fails to so function during its warranty period, as the sole remedy Bay Networks will at its discretion provide a suitable fix, patch, or workaround for the problem that may be included in a future Software release. Bay Networks further warrants to Licensee that the media on which the Software is provided will be free from defects in materials and workmanship under normal use for a period of 90 days from the date Software is first shipped to Licensee. Bay Networks will replace defective media at no charge if it is returned to Bay Networks during the warranty period along with proof of the date of shipment. This warranty does not apply if the media has been damaged as a result of accident, misuse, or abuse. The Licensee assumes all responsibility for selection of the Software to achieve Licensee’s intended results and for the installation, use, and results obtained from the Software. Bay Networks does not warrant a) that the functions contained in the software will meet the Licensee’s requirements, b) that the Software will operate in the hardware or software combinations that the Licensee may select, c) that the operation of the Software will be uninterrupted or error free, or d) that all defects in the operation of the Software will be corrected. Bay Networks is not obligated to remedy any Software defect that cannot be reproduced with the latest Software release. These warranties do not apply to the Software if it has been (i) altered, except by Bay Networks or in accordance with its instructions; (ii) used in conjunction with another vendor’s product, resulting in the defect; or (iii) damaged by improper environment, abuse, misuse, accident, or negligence. THE FOREGOING WARRANTIES AND LIMITATIONS ARE EXCLUSIVE REMEDIES AND ARE IN LIEU OF ALL OTHER WARRANTIES EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. Licensee is responsible for the security of its own data and information and for maintaining adequate procedures apart from the Software to reconstruct lost or altered files, data, or programs.

4. Limitation of liability. IN NO EVENT WILL BAY NETWORKS OR ITS LICENSORS BE LIABLE FOR ANY COST OF SUBSTITUTE PROCUREMENT; SPECIAL, INDIRECT, INCIDENTAL, OR CONSEQUENTIAL DAMAGES; OR ANY DAMAGES RESULTING FROM INACCURATE OR LOST DATA OR LOSS OF USE OR PROFITS ARISING OUT OF OR IN CONNECTION WITH THE PERFORMANCE OF THE SOFTWARE, EVEN IF BAY NETWORKS HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES. IN NO EVENT

SHALL THE LIABILITY OF BAY NETWORKS RELATING TO THE SOFTWARE OR THIS AGREEMENT EXCEED THE PRICE PAID TO BAY NETWORKS FOR THE SOFTWARE LICENSE.

5. Government Licensees. This provision applies to all Software and documentation acquired directly or indirectly by or on behalf of the United States Government. The Software and documentation are commercial products, licensed on the open market at market prices, and were developed entirely at private expense and without the use of any U.S. Government funds. The license to the U.S. Government is granted only with restricted rights, and use, duplication, or disclosure by the U.S. Government is subject to the restrictions set forth in subparagraph (c)(1) of the Commercial Computer Software—Restricted Rights clause of FAR 52.227-19 and the limitations set out in this license for civilian agencies, and subparagraph (c)(1)(ii) of the Rights in Technical Data and Computer Software clause of DFARS 252.227-7013, for agencies of the Department of Defense or their successors, whichever is applicable.

6. Use of Software in the European Community. This provision applies to all Software acquired for use within the European Community. If Licensee uses the Software within a country in the European Community, the Software Directive enacted by the Council of European Communities Directive dated 14 May, 1991, will apply to the examination of the Software to facilitate interoperability. Licensee agrees to notify Bay Networks of any such intended examination of the Software and may procure support and assistance from Bay Networks.

7. Term and termination. This license is effective until terminated; however, all of the restrictions with respect to Bay Networks' copyright in the Software and user manuals will cease being effective at the date of expiration of the Bay Networks copyright; those restrictions relating to use and disclosure of Bay Networks' confidential information shall continue in effect. Licensee may terminate this license at any time. The license will automatically terminate if Licensee fails to comply with any of the terms and conditions of the license. Upon termination for any reason, Licensee will immediately destroy or return to Bay Networks the Software, user manuals, and all copies. Bay Networks is not liable to Licensee for damages in any form solely by reason of the termination of this license.

8. Export and Re-export. Licensee agrees not to export, directly or indirectly, the Software or related technical data or information without first obtaining any required export licenses or other governmental approvals. Without limiting the foregoing, Licensee, on behalf of itself and its subsidiaries and affiliates, agrees that it will not, without first obtaining all export licenses and approvals required by the U.S. Government: (i) export, re-export, transfer, or divert any such Software or technical data, or any direct product thereof, to any country to which such exports or re-exports are restricted or embargoed under United States export control laws and regulations, or to any national or resident of such restricted or embargoed countries; or (ii) provide the Software or related technical data or information to any military end user or for any military end use, including the design, development, or production of any chemical, nuclear, or biological weapons.

9. General. If any provision of this Agreement is held to be invalid or unenforceable by a court of competent jurisdiction, the remainder of the provisions of this Agreement shall remain in full force and effect. This Agreement will be governed by the laws of the state of California.

Should you have any questions concerning this Agreement, contact Bay Networks, Inc., 4401 Great America Parkway, P.O. Box 58185, Santa Clara, California 95054-8185.

LICENSEE ACKNOWLEDGES THAT LICENSEE HAS READ THIS AGREEMENT, UNDERSTANDS IT, AND AGREES TO BE BOUND BY ITS TERMS AND CONDITIONS. LICENSEE FURTHER AGREES THAT THIS AGREEMENT IS THE ENTIRE AND EXCLUSIVE AGREEMENT BETWEEN BAY NETWORKS AND LICENSEE, WHICH SUPERSEDES ALL PRIOR ORAL AND WRITTEN AGREEMENTS AND COMMUNICATIONS BETWEEN THE PARTIES PERTAINING TO THE SUBJECT MATTER OF THIS AGREEMENT. NO DIFFERENT OR ADDITIONAL TERMS WILL BE ENFORCEABLE AGAINST BAY NETWORKS UNLESS BAY NETWORKS GIVES ITS EXPRESS WRITTEN CONSENT, INCLUDING AN EXPRESS WAIVER OF THE TERMS OF THIS AGREEMENT.

Contents

Preface

Bay Networks Technical Publicationsvii

How to Get Help viii

BayRS Version 12.04 and Site Manager Software Version 6.04 Release Notes

Maintenance Release Methodology 1

Year 2000 Compliance 2

Image Builder Operational Note 2

BayRS Version 12.04 Fixed Anomalies 2

Site Manager Software Version 6.04 Fixed Anomalies 11

Bay Networks Technical Publications

You can now print Bay Networks technical manuals and release notes free, directly from the Internet. Go to support.baynetworks.com/library/tpubs/. Find the Bay Networks product for which you need documentation. Then locate the specific category and model or version for your hardware or software product. Using Adobe Acrobat Reader, you can open the manuals and release notes, search for the sections you need, and print them on most standard printers. You can download Acrobat Reader free from the Adobe Systems Web site, www.adobe.com.

You can purchase Bay Networks documentation sets, CDs, and selected technical publications through the Bay Networks Collateral Catalog. The catalog is located on the World Wide Web at support.baynetworks.com/catalog.html and is divided into sections arranged alphabetically:

- The “CD ROMs” section lists available CDs.
- The “Guides/Books” section lists books on technical topics.
- The “Technical Manuals” section lists available printed documentation sets.

Make a note of the part numbers and prices of the items that you want to order. Use the “Marketing Collateral Catalog description” link to place an order and to print the order form.

How to Get Help

For product assistance, support contracts, information about educational services, and the telephone numbers of our global support offices, go to the following URL:

<http://www.baynetworks.com/corporate/contacts/>

In the United States and Canada, you can dial 800-2LANWAN for assistance.

BayRS Version 12.04 and Site Manager Software Version 6.04 Release Notes

This document lists the anomalies (also referred to as bugs, change requests, or CRs) that have been fixed in Bay Networks® BayRS™ Version 12.04 and Site Manager Software Version 6.04.

Use the BayRS Version 12.00 and Site Manager Software Version 6.00 documentation with BayRS Version 12.04 and Site Manager Software Version 6.04.

Maintenance Release Methodology

BayRS Version 12.04 and Site Manager Software Version 6.04 are Maintenance Releases.

Maintenance Releases are designated by a change in the second number to the right of the decimal point. They provide a collection of software bug fixes for the current Major Release. No new software or hardware features or functionality for either software or hardware is introduced beyond that already contained in the current Major Release.

A Maintenance Release will occur approximately each 3 to 4 months after a Major Release occurs. A Maintenance Release replaces the current Major Release (or the prior Maintenance Release) and will become the current shipping version of BayRS. Each Maintenance Release will be a consolidation of the prior bug fixes made through Revision Releases, and will roll up all such software bug fixes provided by the recent Revision Releases.

Year 2000 Compliance

BayRS Version 12.04 and Site Manager Software Version 6.04 are Year 2000 Compliance Certified by Bay Networks. They have successfully passed Bay Networks Test Procedure which tests conformance to the Bay Networks Year 2000 compliance definition, both of which can be found at the Bay Networks Year 2000 Web Site at <http://www.baynetworks.com/year2000/>.

Image Builder Operational Note

If you are using Image Builder in Site Manager Software Version 6.10 to modify a BayRS Version 12.04 router image, you will receive an error. Please contact Bay Networks Customer Support to obtain the patch for this problem.

BayRS Version 12.04 Fixed Anomalies

Bay Networks has fixed the following anomalies in BayRS Version 12.04.

=====		
SITE MANAGER COMPATIBILITY		
=====		
Router Version	is managed by	Site Manager version
v12.04 -----		> 6.04
v12.03 -----		> 6.03
v12.02 -----		> 6.02
v12.01 revision 1 -----		> 6.01 and 6.01 rev 1
v12.01 revision 2 -----		> 6.01 and 6.01 rev 1
v12.01 revision 3 -----		> 6.01 and 6.01 rev 3
=====		

CR 25189: OSPF

A fault occurs in OSPF when you attempt to configure OSPF Global changes for an Ethernet port on an AS boundary router.

CR 25921: LOADER

If there is a panic on a slot from which the router booted, the Technician Interface suffers a delay of approximately 20 seconds for any loadable action.

CR 27734: ASN

An ASN router generates a log message indicating a redundant power supply failure even when the redundant power supply is not present. To disable this message, enable `wfHwEntry.wfRASNRPSUPresent`.

CR 29963: DLSw

A bus error occurs in DLSw when the IP interface is bounced repeatedly.

CR 30692: APPN

Added log message to identify which slot is APPN soloist to avoid confusion.

CR 32886: DLSw

When you disconnect a PU1 controller and reconnect it to the SDLC Primary line on a router, DLSw gets stuck cycling between the disconnect and established states.

CR 33169: SWSERV

Creating a hot standby demand circuit dynamically never maps to the primary circuit for initialization. This condition causes the upper-layer interface to remain up even when the primary client is in the up state.

CR 35093: L2TP

Memory leaks can occur on a DP gate when any of the circuits are bounced. Although DP normally saves the information when a circuit gate dies, if the **if_counter** was not being saved and **g_malloc** runs when the circuit gate comes back up, memory leaks result.

CR 73560: BGP

The router faults in an ATM PVC environment while continuously disabling and enabling ATM and IP interfaces.

CR 75844: SRB

If you use an SRB filter based on the NetBIOS name, faults can occur.

CR 78275: Filters

The router faults after reordering the filters when you create a new bridge traffic filter on an ATM SVC. This only occurs if there is a matching packet for one of the new filters.

CR 78835: X.25

A TCP session cannot be established after you disable and then re-enable TCP.

CR 80322: SWSERV

A bus error occurs when you disable a sync port and then re-enable it after the backup circuit has been activated. This affects configurations for direct FR mode PVCs with ISDN backup support.

CR 80490: BGP

BGP still uses old information after a dynamic change.

CR 85348: IPEX

Router sends frames out of sequence at both the LAPB and X.25 layers before disconnecting with a related bus error.

CR 85908: Packet Capture

When packet capture is enabled on an ATM circuit over an ATM LAN emulation, the router faults. If you enable packet capture on an ATM circuit but do not start it, the router does not fault.

CR 86982: DLSw

An SNA (System Network Architecture) suffers delays in reconnecting after a line interruption. This occurs when the client attempts to reestablish a connection before the host is responsive. The router's broadcast reduction feature shuts down further attempts to contact the host for a specified period of time.

CR 87362: PPP

IP circuits in a PPP connection fail to recover after they are bounced.

CR 88102: IPX

The router may run out of resources and fault when running IPX with many host entries.

CR 88298: VINES

When a router running VINES receives an RDR for a local client, it does not add the client to the neighbor table.

CR 88634: WEP

The WEP protocol is not supported on VME platforms. As a result, attempts to set passwords using the **ksession** command are unsuccessful, and are not followed by an informational message clarifying this condition.

CR 88700: X.25

When IPEX initiates a TCP connection, it wildcards the source IP address and then selects an appropriate IP address. The MIB parameter, `wfIpexMappingCfgLocalIpAddr`, allows for configuration of a source IP address to prevent IPEX from going down whenever the IP address goes down.

CR 88830: OSPF

OSPF experiences delays running Dijkstra to converge the network after the interface goes down.

CR 89307: QLLC

QLLC can't re-establish a TCP connection between PC3270 and an IBM host when the token ring slot is reset on the host router.

CR 89356: IP

A failure may occur on the router when an IP circuit transitions between primary and backup.

CR 89369: MOSPF

Multicast traffic does not propagate from one area to another area in MOSPF.

CR 89603: OSPF

When an ECMP route is lost, it is deleted from the author slot but remains on other slots where the path was learned from another protocol with lower preference.

CR 89614: X.25

A bus error occurs when using compression and an X.25 PDN service.

CR 89696: NTP

When the Network Time Protocol Peer Preference option is set to "no," the local time changes with the remote peer server, so the timing of scheduled reboots is thrown off.

CR 89704: NTP

The Peer Filter option used during the configuration of the Network Time Protocol doesn't function properly. When an NTP access filter is set for a particular peer server, the local time does not update even if the filter type is set to Prefer. The router must be rebooted for the filter to take effect.

CR 90210: DLSw

If you change the XID values while a link station is in session, the current DLS session is not reset dynamically.

CR 90220: IP

When you configure a router for Bridge IP host mode and add a static route and save the configuration, the route gets removed from the routing table after a reboot.

CR 90310: ISDN

ARN and AN router ISDN BRI S/T adapter modules fail due to an improperly programmed ISAC internal register.

CR 90538: X.25

IPEX sends out the Reset Indication with 0x1d (network is out of order) cause code after receiving a TCP abort or close message. Some vendors require that this be configurable.

CR 90619: MULTILINE

The **show sync statistics circuit** provides partial information on a multiline circuit configuration.

CR 91053: GAME

The **show sync base** script does not display all known sync states.

CR 91071: DLSw

If you disable DLS, with the DLS peers configured and TCP connections up, the TCP connections to the peers are closed, but `wfDlsPeerEntry.wfDlsPeerStates` reflects a connected state.

CR 91169: IP

The IP forwarding table becomes corrupt with a range of addresses marked as unreachable after a change in the topology occurs with variable-length subnets and overlapping routes.

CR 91334: SDLC

Implemented SDLC flagstreaming on the coprocessors on the Quad and Octal sync link modules. This was originally done on the Dual sync link module in CR 35096.

CR 91606: IP

Changing a circuit from primary on one slot to dial backup on another slot can cause inconsistencies in the IP routing table.

CR 91759: IP

When inbound IP traffic filters are applied to router interfaces with actions of FORWARD_TO_NEXT_HOP_INTERFACE and FORWARD_TO_FIRST_UP_NEXT_HOP_INTERFACE, tag violation faults can occur.

CR 91805: DLSw

When configured to activate peer first, the router does not retry the connection after it has been brought down due to inactivity.

CR 91930: X.25

Add Transpac cause code and fast select support for conformance testing.

CR 91984: SWSERV

When the auto_termination option is set to On on an on-demand circuit, and the circuit is taken down, a bus error occurs.

CR 92090: OSPF

A router configured with OSPF should ignore a contiguous mask that it receives. However, a bus error occurs instead.

CR 92242: IP

IP transmits an ARP for a next-hop host out an incorrect interface. If there is a device running proxy ARP, it responds to this ARP, which causes the router to send packets to this next hop out the wrong interface.

CR 92592: DLSw

A bus error occurs if you set the MIB attributes for wfDlsLocalDeviceCanureachTimer and wfDlsLocalDeviceCanureachRetries to zero to prevent the SDLC interface from initiating CanUReach messages.

CR 92616: DLSw

Following a failed SDLC to LLC2 connection between a 3174 cluster controller and the 5745 Enterprise Server, the ESM and router are unable to restore the connection. Each subsequent CANUREACH fails and you must stop and restart DLSw to restore normal operation.

CR 92923: ARP

Proxy ARP is not updating the ARP cache correctly after a new MAC address is configured on an adjacent router on the same network.

CR 93067: MCT1E1

An ASN takes a bus error in the MCT1 driver when it receives traffic.

CR 93242: DECnet

The broadcast route timer cannot be set beyond 8191 seconds, even though the timer has a valid range of 1 to 65535 seconds.

CR 93345: ARP

A memory leak occurs in ARP when the data link circuits are bounced repeatedly.

CR 94119: OSI

In a looped environment, OSI can receive its own link state packet from a neighbor with the same sequence number in its database. Because OSI fails to acknowledge the LSP, the remote side resends the LSP until it ages out prematurely.

CR 94120: OSI

Bouncing the OSI interface causes multiple copies of routing updates to be sent.

CR 94132: MOSPF

When MOSPF experiences large spikes in CPU utilization when running on all slots, dropped packets result. This happens every 30 minutes on an ABR when OSPF refreshes type 3 LSAs or receives a refreshed type 3 LSA from another router.

CR 94243: MOSPF

The wfMospfForwardEntry MIB does not increment age properly.

CR 94365: IP

Deleting an IP FORWARD-TO-NEXT-HOP traffic filter will result in a bus error.

CR 94714: BGP

When an entry is deleted from the RIB (routing information block) table in BGP, not all memory associated with the entry is released. This eventually leads to an out-of-memory fault.

CR 94903: VINES

If the router receives a VIP (VINES IP) packet destined for a client at the network layer, sourced from a station on the same LAN, and if the client's routing server is not in the routing table, but the client is in the router's neighbor table, this causes a fault and VINES resets on the router.

CR 95024: ATM

The **readexe** command fails on the VNR image.

CR 95323: LLC

LLC faults on an out-of-buffer condition and this causes the LLC circuit to terminate improperly. As a result, DLS never learns that the interface is down and does not recover.

CR 95450: IP

A bus error occurs when you set the wfIpBaseDirectedBcastEnable MIB to disable in ISP mode.

CR 95494: ISDN

If the primary link goes down and dial backup takes over before the primary link slot has cleaned up, the routing table is in a state where the directly connected network (now using the backup link) does not appear in the IP routing table.

CR 96869: ATM

A router running LAN emulation will stop responding to LE_ARP requests after you change the state of the source route spanning tree. This problem occurs when you change the topology or source route STP global state, or when you bounce a source route STP interface.

CR 96266: X.25/IPEX

If an X.25 connection is not established, the IpexSession MIB is not successfully removed.

Site Manager Software Version 6.04 Fixed Anomalies

Bay Networks has fixed the following anomalies in Site Manager Software Version 6.04.

=====

Site Manager Software Version 6.04 is a post-6.00 revision. This version is backward compatible and supports the following router software versions:

12.04

12.03

12.02

12.01

12.00

11.02

11.01

11.00

10.01

=====

CR 22893: Site Manager

PC Site Manager incorrectly allows you to set the month value to zero in the Router Date and Time window and then sets the month to 1.

CR 30036: SWSERV

Site Manager 5.01 does not allow selection of the 56K adaption rate option for AN and ARN ISDN outgoing phone numbers.

CR 30072: ISDN

Site Manager reports an internal error, "line not found," when you configure an ISDN leased line as a primary line for a backup circuit on an ARN.

CR 33127: Frame

You cannot apply a bridge filter to a specific frame relay service record other than the default service record. When you attempt to do so at the Circuit Menu, you are prompted for entry of physical circuits, rather than service records.

CR 35360: Switched Services

When you edit a configuration dynamically, after adding Hot Standby as a secondary circuit, the primary circuit IP connection goes down.

CR 35686: IP

Attempting to report on more than one protocol (defined in xxxRouteSource and xxxExtRouteSource) in Report Generator can cause an invalid entry error. This occurs because the MIB and CDL for xxxRouteSource and xxxExtRouteSource are incorrectly defined with enumerations hard coded in the MIB.

CR 72188: BGP

Site Manager does not allow you to configure IBGP peers if the peer is not on the same network as the local IP interface.

CR 78305: SNMP

When you try to add an SNMP trap exception using Site Manager 6.00 and above, and BayRS 11.02, you get an error message.

CR 79192: MCT1E1

Site Manager does not properly add the 31st logical line to an MCE1 time slot.

CR 86105: ISDN

Site Manager 6.00 or higher closes the Configuration window when you select the ISDN BRI U Interface card on an AN router.

CR 91582: Site Manager

A generic error occurs when you connect to a 5380 with Site Manager 7.01 and Win NT.

CR 92645: X.25

Site Manager deletes the IPEX button from the X.25 configuration after you delete a service record. This prevents you from configuring the IPEX mapping table.

CR 92884: BGP

Site Manager versions 6.01 and later require the following two configurable fields: Multi-Exit Discriminator and Multi-Exit Discriminator Value.

CR 92943: ATM

When you delete an ATM circuit using Site Manager, the circuit seems to disappear but actually remains on the router. If you attempt to then add the circuit using the default name, the error "duplicate circuit name" appears.

CR 93347: IP

Site Manager does not show an hourglass or wait state message while retrieving information over the network and fails to prevent the inadvertent entry of another command while processing the retrieve. This can result in an unintended change to the router settings.

CR 93368: Site Manager

Site Manager incorrectly allows you to configure full duplex for both ports on a dual 100BASET module. For performance reasons, this is not recommended.

CR 94176: Site Manager

Site Manager will not open a configuration file in local or remote modes. This problem occurs because some MIB entries that are missing from Site Manager are included with the new *config* file.

CR 94923: SNMP

An SNMP set error can occur when edit priority/outbound filters in Site Manager 5.01/5 with IP installed. This results because the OID is not being located correctly.

CR 95222: Site Manager

The Bay Networks logo still appears on the Site Manager PC installation screen.

CR 95291: Site Manager

Site Manager 7.10 for AIX Report Generator incorrectly reports that IPEX entries are misconfigured. When this occurs, Site Manager displays the following memory error: No Memory for Octet String.

CR 95307: Site Manager

A request has been submitted for the Windows Router Files Manager to be made identical to the UNIX version when you click on the volume selector. UNIX displays a list of volumes with flash cards that you can highlight to select. Windows currently displays two buttons (ascending/descending) below the volume selector.

CR 95325: PPP

WFCFG goes into an infinite loop when you create filters for the first time on a PC. The PC is looking for an array of characters on the long word boundary, which do not appear there when the pre-processor directive pragma pack is in use on a character array.

CR 96370: Site Manager

The router's PING screen allows the entry of alphanumeric characters in numeric fields.

CR 96541: X.25

Remote X.121 address sets to 1 when you click on Apply on the X.25 service configuration window, regardless of the address you assigned.