



Nortel Multi Protocol Router

Software Patch V15.6.2.1

1. Patch Summary

Patch Date: October 20, 2006

Purpose: Software Maintenance Patch to address customer-found software issues.

2. Important Notes Before Upgrading to This Patch

None

3. Platforms Supported

Nortel Multi Protocol Router (formerly known as BayRS) software Patch V15.6.2.0 supports the following hardware platforms:

ASN
ARN
2430
5430
BLN
BCN

4. Notes for Upgrade

For details on how to upgrade your Nortel Multi Protocol Router (formerly known as the BayRS), see the *BayRS Router and BCC Fixed Anomalies (Patch Notes)* (part no. 316151-15.6 Rev 00). Patch notes are available at <http://www.nortel.com/support>; select the **BayRS Router** product family, select **Backbone Concentrator Node**, select **Documentation**, and then click **Go**.

5. Version of Previous Release

Software Version 15.6.2.0

6. Compatibility

None

7. Changes in This Patch

New Features in This Patch

None

Old Features Removed From This Patch

None

Problems Resolved in This Patch

Nortel Networks Multi Protocol Router sustaining Patch Version 15.6.2.1 resolves the following issues:

Q01296829 –

The Nortel MultiProtocol Router was required to support the new daylight savings time for North America in 2007.

Q01313961 –

A PPP LQR debug log message was inadvertently left in the code for the Nortel MultiProtocol Router. This message could fill the event log with unnecessary information.

Q01353951 –

The Nortel Multiprotocol Router experienced a fault when the inactivity time for a DLSw backup peer expired. The fault occurred only when the DLSw Primary was configured for RFC 1795.

8. Outstanding Issues

None

9. Known Limitations

None

10. Documentation Corrections

None

For other known issues, refer to the product Patch notes and technical documentation available from the Nortel Technical Support web site at: <http://www.nortel.com/support>.

Copyright © 2006 Nortel Networks - All Rights Reserved. Nortel, Nortel Networks, the Nortel logo, the Globemark, and Nortel Multiprotocol Router are trademarks of Nortel Networks Limited.

The information in this document is subject to change without notice. The statements, configurations, technical data, and recommendations in this document are believed to be accurate and reliable, but are presented without express or implied warranty. Users must take full responsibility for their applications of any products specified in this document. The information in this document is proprietary to Nortel.

To access more technical documentation, search our knowledge base, or open a service request online, visit Nortel Technical Support on the web at: <http://www.nortel.com/support>