

BayStack 470/460/BPS

Software Release 3.1.5

1. Release Summary

Release Date:28-Mar-2005Purpose:Software patch release to address customer found software issues.

2. Important Notes Before Upgrading to This Release

None.

3. Platforms Supported

BayStack 460/470 BPS 2000

4. Notes for Upgrade

Please see "Release Notes for the BayStack 470 10/100/1000 Switch" (Part No. 215148-D, available at <u>http://www.nortel.com/support</u>, select BayStack family, then Ethernet Switch 470) for details on how to upgrade your Policy Switch.

When upgrading to this code, it is essential to first load the agent code and then the diagnostic image. When downgrading to an older revision of the agent code, it is essential to downgrade the diagnostic code first and then load the agent code.

File Names For This Release

File Name	Module or File Type	File Size (bytes)
boss3601_diag.bin	Diagnostic image	457,576
boss3156.img	Agent code image	1,930,205
boss3157s.img	Agent code image (SSH)	1,877,917

5. Version of Previous Release

Software Version 3.1.4

6. Compatibility

This software release is managed with Java Device Manager (JDM) release 5.8.4.

7. Changes in This Release

New Features in This Release None.

Old Features Removed From This Release None.

Problems Resolved in This Release

Single Fiber Fault Detection (SFFD) was not consistently functional on BayStack 470-24 HW Rev. 4 and BayStack 470-48 HW Rev. 8 (**Q01058132-01**).

EAP Re-authentication timer did not always work properly with PEAP (Q01050855-01).

8. Outstanding Issues

None.

9. Known Limitations

None.

10. Documentation Corrections

For other known issues, please refer to the product release notes and technical documentation available from the Nortel Technical Support web site at: <u>http://www.nortel.com/support</u>.

Copyright © 2005 Nortel Networks Limited - All Rights Reserved. Nortel, Nortel Networks, the Nortel logo, Globemark, and <product family> are trademarks of Nortel Networks Limited.

The information in this document is subject to change without notice. The statements, configurations, technical data, and recommendations in this document are believed to be accurate and reliable, but are presented without express or implied warranty. Users must take full responsibility for their applications of any products specified in this document. The information in this document is proprietary to Nortel.

To access more technical documentation, search our knowledge base, or open a service request online, please visit Nortel Technical Support on the web at: <u>http://www.nortel.com/support</u>