



# **Release Notes for Avaya Ethernet Routing Switch 5000 Series**

Release 6.6  
NN47200-400  
Issue 09.02  
December 2013

## Notice

While reasonable efforts have been made to ensure that the information in this document is complete and accurate at the time of printing, Avaya assumes no liability for any errors. Avaya reserves the right to make changes and corrections to the information in this document without the obligation to notify any person or organization of such changes.

## Documentation disclaimer

"Documentation" means information published by Avaya in varying mediums which may include product information, operating instructions and performance specifications that Avaya may generally make available to users of its products and Hosted Services. Documentation does not include marketing materials. Avaya shall not be responsible for any modifications, additions, or deletions to the original published version of documentation unless such modifications, additions, or deletions were performed by Avaya. End User agrees to indemnify and hold harmless Avaya, Avaya's agents, servants and employees against all claims, lawsuits, demands and judgments arising out of, or in connection with, subsequent modifications, additions or deletions to this documentation, to the extent made by End User.

## Link disclaimer

Avaya is not responsible for the contents or reliability of any linked websites referenced within this site or documentation provided by Avaya. Avaya is not responsible for the accuracy of any information, statement or content provided on these sites and does not necessarily endorse the products, services, or information described or offered within them. Avaya does not guarantee that these links will work all the time and has no control over the availability of the linked pages.

## Warranty

Avaya provides a limited warranty on Avaya hardware and software. Refer to your sales agreement to establish the terms of the limited warranty. In addition, Avaya's standard warranty language, as well as information regarding support for this product while under warranty is available to Avaya customers and other parties through the Avaya Support website: <http://support.avaya.com> or such successor site as designated by Avaya. Please note that if you acquired the product(s) from an authorized Avaya Channel Partner outside of the United States and Canada, the warranty is provided to you by said Avaya Channel Partner and not by Avaya.

## Licenses

THE SOFTWARE LICENSE TERMS AVAILABLE ON THE AVAYA WEBSITE, [HTTP://SUPPORT.AVAYA.COM/LICENSEINFO](http://support.avaya.com/licenseinfo) OR SUCH SUCCESSOR SITE AS DESIGNATED BY AVAYA, ARE APPLICABLE TO ANYONE WHO DOWNLOADS, USES AND/OR INSTALLS AVAYA SOFTWARE, PURCHASED FROM AVAYA INC., ANY AVAYA AFFILIATE, OR AN AVAYA CHANNEL PARTNER (AS APPLICABLE) UNDER A COMMERCIAL AGREEMENT WITH AVAYA OR AN AVAYA CHANNEL PARTNER; AVAYA RESERVES THE RIGHT TO TAKE LEGAL ACTION AGAINST YOU AND ANYONE ELSE USING OR SELLING THE SOFTWARE WITHOUT A LICENSE. BY INSTALLING, DOWNLOADING OR USING THE SOFTWARE, OR AUTHORIZING OTHERS TO DO SO, YOU, ON BEHALF OF YOURSELF AND THE ENTITY FOR WHOM YOU ARE INSTALLING, DOWNLOADING OR USING THE SOFTWARE (HEREINAFTER REFERRED TO INTERCHANGEABLY AS "YOU" AND "END USER"), AGREE TO THESE TERMS AND CONDITIONS AND CREATE A BINDING CONTRACT BETWEEN YOU AND AVAYA INC. OR THE APPLICABLE AVAYA AFFILIATE ("AVAYA").

Avaya grants you a license within the scope of the license types described below, with the exception of Heritage Nortel Software, for which the scope of the license is detailed below. Where the order documentation does not expressly identify a license type, the applicable license will be a Designated System License. The applicable number of licenses and units of capacity for which the license is granted will be one (1), unless a different number of licenses or units of capacity is specified in the documentation or other materials available to you. "Designated Processor" means a single stand-alone computing device. "Server" means a Designated Processor that hosts a software application to be accessed by multiple users.

## Licence types

Designated System(s) License (DS). End User may install and use each copy or an Instance of the Software only on a number of Designated Processors up to the number indicated in the order. Avaya may require the Designated Processor(s) to be identified in the order by type, serial number, feature key, Instance, location or other specific designation, or to be provided by End User to Avaya through electronic means established by Avaya specifically for this purpose.

## Heritage Nortel Software

"Heritage Nortel Software" means the software that was acquired by Avaya as part of its purchase of the Nortel Enterprise Solutions Business in December 2009. The Heritage Nortel Software currently available for license from Avaya is the software contained within the list of Heritage Nortel Products located at <http://support.avaya.com/LicenseInfo/> under the link "Heritage Nortel Products", or such successor site as designated by Avaya. For Heritage Nortel Software, Avaya grants Customer a license to use Heritage Nortel Software provided hereunder solely to the extent of the authorized activation or authorized usage level, solely for the purpose specified in the Documentation, and solely as embedded in, for execution on, or (in the event the applicable Documentation permits installation on non-Avaya equipment) for communication with Avaya equipment. Charges for Heritage Nortel Software may be based on extent of activation or use authorized as specified in an order or invoice.

## Copyright

Except where expressly stated otherwise, no use should be made of materials on this site, the Documentation, Software, Hosted Service, or hardware provided by Avaya. All content on this site, the documentation, Hosted Service, and the Product provided by Avaya including the selection, arrangement and design of the content is owned either by Avaya or its licensors and is protected by copyright and other intellectual property laws including the sui generis rights relating to the protection of databases. You may not modify, copy, reproduce, republish, upload, post, transmit or distribute in any way any content, in whole or in part, including any code and software unless expressly authorized by Avaya. Unauthorized reproduction, transmission, dissemination, storage, and or use without the express written consent of Avaya can be a criminal, as well as a civil offense under the applicable law.

## Third Party Components

"Third Party Components" mean certain software programs or portions thereof included in the Software or Hosted Service may contain software (including open source software) distributed under third party agreements ("Third Party Components"), which contain terms regarding the rights to use certain portions of the Software ("Third Party Terms"). As required, information regarding distributed Linux OS source code (for those Products that have distributed Linux OS source code) and identifying the copyright holders of the Third Party Components and the Third Party Terms that apply is available in the Documentation or on Avaya's website at: <http://support.avaya.com/Copyright> or such successor site as designated by Avaya. You agree to the Third Party Terms for any such Third Party Components

## Preventing Toll Fraud

"Toll Fraud" is the unauthorized use of your telecommunications system by an unauthorized party (for example, a person who is not a

corporate employee, agent, subcontractor, or is not working on your company's behalf). Be aware that there can be a risk of Toll Fraud associated with your system and that, if Toll Fraud occurs, it can result in substantial additional charges for your telecommunications services.

### **Avaya Toll Fraud intervention**

If you suspect that you are being victimized by Toll Fraud and you need technical assistance or support, call Technical Service Center Toll Fraud Intervention Hotline at +1-800-643-2353 for the United States and Canada. For additional support telephone numbers, see the Avaya Support website: <http://support.avaya.com> or such successor site as designated by Avaya. Suspected security vulnerabilities with Avaya products should be reported to Avaya by sending mail to: [securityalerts@avaya.com](mailto:securityalerts@avaya.com).

### **Trademarks**

The trademarks, logos and service marks ("Marks") displayed in this site, the Documentation, Hosted Service(s), and Product(s) provided by Avaya are the registered or unregistered Marks of Avaya, its affiliates, or other third parties. Users are not permitted to use such Marks without prior written consent from Avaya or such third party which may own the Mark. Nothing contained in this site, the Documentation, Hosted Service(s) and Product(s) should be construed as granting, by implication, estoppel, or otherwise, any license or right in and to the Marks without the express written permission of Avaya or the applicable third party.

Avaya is a registered trademark of Avaya Inc.

All non-Avaya trademarks are the property of their respective owners. Linux® is the registered trademark of Linus Torvalds in the U.S. and other countries.

### **Downloading Documentation**

For the most current versions of Documentation, see the Avaya Support website: <http://support.avaya.com>, or such successor site as designated by Avaya.

### **Contact Avaya Support**

See the Avaya Support website: <http://support.avaya.com> for Product or Hosted Service notices and articles, or to report a problem with your Avaya Product or Hosted Service. For a list of support telephone numbers and contact addresses, go to the Avaya Support website: <http://support.avaya.com> (or such successor site as designated by Avaya), scroll to the bottom of the page, and select Contact Avaya Support.



# Contents

<b>Chapter 1: Introduction</b> .....	<b>7</b>
Purpose.....	7
Related resources.....	7
Support.....	8
Supported Switch Models.....	8
<b>Chapter 2: New in this release</b> .....	<b>11</b>
Features.....	11
802.1X-2004 support.....	11
802.1X: Default all EAP settings.....	11
802.1X: Fail Open VLAN Continuity mode.....	11
802.1X: Maximum number of EAP and NEAP clients per port.....	12
802.1X: NEAP not member of VLAN.....	12
802.1X: NEAP Phone (Avaya Support).....	12
802.1X: NEAP support for freeform password.....	12
ACLI show flash history command.....	13
ARP scaling.....	13
Change RADIUS Password.....	13
CLI list command.....	14
Default IP.....	14
EDM improved download support.....	14
EDM inactivity timeout.....	14
Link-state tracking.....	15
Out-of-band management.....	15
Remote Switch Port Analyzer (RSPAN).....	15
RO User access to Telnet and SSH.....	15
Run Scripts.....	16
Secure File Transfer Protocol (SFTP) enhancements.....	16
Show TCP Ports.....	16
Show UTC timestamp.....	16
SLA Monitor.....	17
SSH Client.....	17
VRF ping support.....	17
VRF stacking and traceroute support.....	17
Other changes.....	18
CLI interface change from FastEthernet to Ethernet.....	18
Removal of DAUR support.....	18
Removal of hybrid stack support.....	18
Removal of NSNA support.....	18
Removal of QoS filter limiting.....	18
<b>Chapter 3: Important notices and new features</b> .....	<b>19</b>
Feature document location.....	19
Release file names.....	19
Software upgrade.....	20
Upgrading diagnostic software.....	20

Upgrading agent software.....	21
How to get EDM online help files for embedded EDM.....	22
Downloading help files.....	23
How to configure the path to the embedded EDM help files.....	23
Configuring the path to the help files using ACLI.....	23
Configuring the path to the help files using EDM.....	24
Supported software and hardware capabilities.....	24
Additional information for the software feature license file.....	26
Supported standards, MIBs, and RFCs.....	27
Standards.....	27
RFCs.....	28
<b>Chapter 4: Resolved issues.....</b>	<b>31</b>
<b>Chapter 5: Known issues and limitations.....</b>	<b>37</b>
Known issues.....	37
Trap restoration and reconfiguration after upgrade to Release 6.3.....	50
Restoring trap notification functionality using ACLI.....	50
Reconfiguring traps using EDM.....	51
Reconfiguring traps using ACLI with v1 host example, password security enabled.....	51
Reconfiguring traps using ACLI with v1 host example, password security disabled.....	52
Setting the Notification Type per receiver using ACLI.....	52
Displaying Notification Types associated with the notify filter using ACLI.....	53
Enabling or disabling the Notification Type per device using ACLI.....	53
Preventing a loop during upgrade of a large network.....	53
Ethernet Routing Switch 5000 Series limitations and considerations.....	54
VLACP issue.....	56
Filter resource consumption.....	57
Flow Control.....	59

# Chapter 1: Introduction

---

## Purpose

This document describes new features and important information about the latest release. Release notes include a list of known issues (including workarounds where appropriate) and a list of resolved issues. This document also describes known limitations and expected behaviors that may first appear to be issues.

This document describes new features, hardware, upgrade alerts, known and resolved issues, and limitations for the Avaya Ethernet Routing Switch 5000 Series, Release 6.6 and higher.

These release notes provide the latest information about the current software release, as well as operational issues not included in the documentation.

The information in this document supersedes applicable information in other documents in the suite.

---

## Related resources

---

## Documentation

See the *Documentation Reference for Avaya Ethernet Routing Switch 5000 Series*, NN47200–103 for a list of the documentation for this product.

---

## Training

Ongoing product training is available. For more information or to register, you can access the Web site at <http://avaya-learning.com>.

---

## Avaya Mentor videos

Avaya Mentor videos provide technical content on how to install, configure, and troubleshoot Avaya products.

### About this task

Videos are available on the Avaya Support website, listed under the video document type, and on the Avaya-run channel on YouTube.

- To find videos on the Avaya Support website, go to <http://support.avaya.com>, select the product name, and check the *videos* checkbox to see a list of available videos.
- To find the Avaya Mentor videos on YouTube, go to <http://www.youtube.com/AvayaMentor> and perform one of the following actions:
  - Enter a key word or key words in the Search Channel to search for a specific product or topic.
  - Scroll down Playlists, and click the name of a topic to see the available list of videos posted on the site.

 **Note:**

Videos are not available for all products.

---

## Support

Visit the Avaya Support website at <http://support.avaya.com> for the most up-to-date documentation, product notices, and knowledge articles. You can also search for release notes, downloads, and resolutions to issues. Use the online service request system to create a service request. Chat with live agents to get answers to questions, or request an agent to connect you to a support team if an issue requires additional expertise.

---

## Supported Switch Models

The Avaya Ethernet Routing Switch 5600 Series, supported by software release 6.6, includes the following switch models:

- Avaya Ethernet Routing Switch 5698TFD
- Avaya Ethernet Routing Switch 5698TFD-PWR
- Avaya Ethernet Routing Switch 5650TD



- Avaya Ethernet Routing Switch 5650TD-PWR
- Avaya Ethernet Routing Switch 5632FD

Configurations can vary from a stand-alone switch to a stack of up to 8 switches. A stack can consist of any combination of switches. One of the benefits of operating Avaya Ethernet Routing Switch 5600 Series switches in a stack is management efficiency; a stack is managed with a single IP address and software is available as a single image across all models.

 **Note:**

Release 6.6 supports pure stacks of 56xx switches only. Hybrid or mixed stacking of 55xx with 56xx switches and pure stacks of 55xx switches are not supported.



# Chapter 2: New in this release

The following sections detail what's new in *Release Notes for Avaya Ethernet Routing Switch 5000 Series*, NN47200-400 for Release 6.6.

---

## Features

See the following sections for information about feature changes.

---

### 802.1X-2004 support

With the 802.1x-2004 standard the switch can authenticate both EAPOL version 1 and EAPOL version 2 supplicants.

For more information on EAPOL, see:

- *Configuring Security on Avaya Ethernet Routing Switch 5000 Series*, NN47200-501

---

### 802.1X: Default all EAP settings

This feature allows you to default all EAP settings globally and on a port level.

For more information, see:

- *Configuring Security on Avaya Ethernet Routing Switch 5000 Series*, NN47200-501

---

### 802.1X: Fail Open VLAN Continuity mode

The Fail Open VLAN Continuity mode feature introduces a new mode of operation for EAP/NEAP clients when the RADIUS server(s) become unreachable.

For more information, see:

- *Configuring Security on Avaya Ethernet Routing Switch 5000 Series*, NN47200-501

---

## 802.1X: Maximum number of EAP and NEAP clients per port

You can define the maximum number of EAP and Non-EAP clients allowed per port, from one client up to 64, where 64 would be a maximum of 32 EAP clients and 32 NEAP clients. The default for the maximum number of clients is one. There is no priority of EAP or NEAP clients for authentication.

To configure the maximum clients parameter, see:

- *Configuring Security on Avaya Ethernet Routing Switch 5000 Series*, NN47200-501

---

## 802.1X: NEAP not member of VLAN

The NEAP not member of VLAN feature ensures that ports configured with RADIUS Non-EAP authentication are assigned to at least one VLAN to make authentication possible for Non-EAP clients.

For more information, see:

- *Configuring Security on Avaya Ethernet Routing Switch 5000 Series*, NN47200-501

---

## 802.1X: NEAP Phone (Avaya Support)

NEAP IP Phone support is enhanced to recognize Avaya Red handsets through two additional DHCP signatures: Nortel-SIP-Phone-A and ccp.avaya.com.

---

## 802.1X: NEAP support for freeform password

The ability to support complex passwords for NEAP switch authentication is extended with the use of a global freeform password. A CLI configurable key consisting of a string of up to 32 ASCII characters is added to the NEAP password format used to authenticate NEAP clients.

For more information, see:

- *Configuring Security on Avaya Ethernet Routing Switch 5000 Series*, NN47200-501

---

## ACLI show flash history command

The `show flash history` command provides the current status of the Flash device. You can use the `show flash history` command to view the flash writes and erase history on a standalone unit or stack. The Flash History does not record programming done from the diagnostics or bootloader. Flash History information is stored in the Serial (PC) Electrically Erasable Programmable Read Only Memory (SEEPROM). The data does not get corrupted during an upgrade or downgrade. Flash History is automatically enabled and does not require any configuration.

For more information on the `show flash history` command, see:

- *Getting Started with Avaya Ethernet Routing Switch 5000 Series*, NN47200-303

---

## ARP scaling

In Release 6.6, the total number of ARP table entries is increased to 4,096.

For more information on ARP, see:

- *Configuring IP Routing and Multicast on Avaya Ethernet Routing Switch 5000 Series*, NN47200-503

---

## Change RADIUS Password

If you have RADIUS servers in your network, you can allow users to change account passwords when they expire.

 **Note:**

Change RADIUS password is available only in secure software builds.

You can enable or disable the Change RADIUS password feature. By default, this feature is disabled. When Change RADIUS password feature is enabled, the server reports the password expiry and system prompts you to create a new password.

For more information about the Change RADIUS password feature, see:

- *Configuring Security on Avaya Ethernet Routing Switch 5000 Series*, NN47200-501

---

## CLI list command

This feature provides an enhancement to the CLI `help` command, by adding a complete list of the CLI tree available on the unit, regardless of the current unit configuration. You can also use the “verbose” option to list the syntax of every CLI command.

For more information, see:

- *Fundamentals of Avaya Ethernet Routing Switch 5000 Series*, NN47202-104

---

## Default IP

The Ethernet Routing Switch 5600 Series sets an IP address of 192.168.1.1/24 by default if the switch does not obtain its IP from another source.

 **Note:**

As this feature overrides the UI button functionality to set the default IP address, the UI button functionality has been removed.

For more information, see:

- *Getting Started with Avaya Ethernet Routing Switch 5000 Series*, NN47200–303

---

## EDM improved download support

When downloading software to the switch, EDM provides a status bar on the progress and an indication when the download is complete.

For more information, see:

- *Getting Started with Avaya Ethernet Routing Switch 5000 Series*, NN47200–303

---

## EDM inactivity timeout

You can configure the period of time that an EDM session remains idle before the session expires. The current default expiry for an idle EDM session is 15 minutes.

For more information, see:

- *Getting Started with Avaya Ethernet Routing Switch 5000 Series*, NN47200–303

---

## Link-state tracking

The link-state tracking feature binds the link state of multiple interfaces, so that if a specified interface or its Virtual Link Aggregation Control Protocol (VLACP) state goes down, all the other interfaces in that group are placed in a temporary down state.

For more information, see:

- *Configuring VLANs, Spanning Tree, and Multi-Link Trunking on Avaya Ethernet Routing Switch 5000 Series*, NN47200–502

---

## Out-of-band management

Out-of-band management allows switch or stack management through the dedicated out-of-band management port. This port can accept an IPv4 or IPv6 address different from the switch or stack IP address. With out-of-band management, you do not require an in-band management VLAN to carry switch or stack management traffic, including Telnet, Secure Shell (SSH) protocol, Simple Network Management Protocol (SNMP), HTTP, or HTTPS. You can also use out-of-band management to download a software image or access the Enterprise Device Manager (EDM) interface for a switch or stack.

For more information, see:

- *Getting Started with Avaya Ethernet Routing Switch 5000 Series*, NN47200–303

---

## Remote Switch Port Analyzer (RSPAN)

Remote Switch Port Analyzer (RSPAN), also known as Remote Port Mirroring, enhances port mirroring by enabling mirrored traffic to be sent to one or more switches or stacks on the network.

For more information, see:

- *Configuring System Monitoring on Avaya Ethernet Routing Switch 5000 Series*, NN47200-505

---

## RO User access to Telnet and SSH

Users logged in with read-only permission can now have access to Telnet and SSH commands. Previous software releases required the user to be logged in with read-write access.

For more information on using Telnet and SSH, see:

- *Configuring Security on Avaya Ethernet Routing Switch 5000 Series*, NN47200-501

---

## Run Scripts

You can use the run scripts to automatically configure the parameters for an Avaya Stackable Ethernet switch according to Avaya's best practices for converged solutions. The scripts can be executed in a default or verbose mode.

In the default mode, the switch is configured using predetermined parameter values. In the verbose mode, you can modify the default values and settings when the script is executed.

In this release, run scripts are available for IP Office, Link Layer Discovery Protocol (LLDP), and Auto Detect Auto Configuration (ADAC).

For more information, see:

- *Getting Started with Avaya Ethernet Routing Switch 5000 Series*, NN47200-303

---

## Secure File Transfer Protocol (SFTP) enhancements

For secure (SSH) software images, the SFTP client functionality is enhanced to include download support of agent and diagnostic files, ASCII configuration file download and upload, download of license files, and DHCP external save transfer to and from an SFTP server.

For more information, see:

- *Configuring Security on Avaya Ethernet Routing Switch 5000 Series*, NN47200-501

---

## Show TCP Ports

You can view information about active IPv4 sockets similar to the output from the Unix netstat command.

For more information, see:

- *Configuring System Monitoring on Avaya Ethernet Routing Switch 5000 Series*, NN47200-505

---

## Show UTC timestamp

The show UTC timestamp feature enables you to display the UTC timestamp after issuing any show command in ACLI. By default, the timestamp state is disabled.



For more information, see:

- *Getting Started with Avaya Ethernet Routing Switch 5000 Series*, NN47200–303

---

## SLA Monitor

The Service Level Agreement (SLA) Monitor is an embedded monitoring device designed to identify and isolate performance issues in a network.

For more information, see:

- *Configuring System Monitoring on Avaya Ethernet Routing Switch 5000 Series*, NN47200-505

---

## SSH Client

SSH Client is a secure shell protocol for connecting to an SSH server accepting remote connections, and is a secure alternative to telnet. The SSH Client uses SSH version 2 and is present only on secure (SSH) images.

For more information, see:

- *Configuring Security on Avaya Ethernet Routing Switch 5000 Series*, NN47200-501

---

## VRF ping support

The ping command allows you to specify the VRF.

For more information, see:

- *Getting Started with Avaya Ethernet Routing Switch 5000 Series*, NN47200–303

---

## VRF stacking and traceroute support

In Release 6.6, VRF is now available for stacked 5600 configurations. In addition, you can specify the VRF in the traceroute command.

For more information on VRF, see:

- *Configuring IP Routing and Multicast on Avaya Ethernet Routing Switch 5000 Series, NN47200-503*

---

## Other changes

See the following sections for information about changes that are updates to previously existing information.

---

## CLI interface change from FastEthernet to Ethernet

The CLI interface command `interface FastEthernet` is changed to `interface Ethernet`. The `FastEthernet` interface command remains available, but hidden so as to provide backward compatibility.

---

## Removal of DAUR support

DAUR support has been removed for Avaya ERS 5600 Series in Release 6.6.

---

## Removal of hybrid stack support

Release 6.6 supports pure stacks of 5600 switches only. Hybrid stacks of 5500 and 5600 switches are not supported.

---

## Removal of NSNA support

NSNA support has been removed for Avaya ERS 5600 Series starting in Release 6.6.

---

## Removal of QoS filter limiting

Since Release 6.6 is not supported on ERS 5510 units that require QoS filter limiting, Release 6.6 removes ACLI commands and EDM support for QoS filter limiting.

# Chapter 3: Important notices and new features

This section describes important software and hardware related notices in the Avaya Ethernet Routing Switch 5000 Series Release 6.6.

---

## Feature document location

The following table contains a list of key software features and their location in the documentation suite.

**Table 1: Where to find information about key software features**

Feature	Document
QoS Traffic Profiling Support	<i>Configuring Quality of Service on Avaya Ethernet Routing Switch 5000 Series</i> , NN47200-504
SMLT configuration	<i>Configuring VLANs, Spanning Tree, and Multi-Link Trunking on Avaya Ethernet Routing Switch 5000 Series</i> , NN47200-502

---

## Release file names

The following table describes the Avaya Ethernet Routing Switch 5000 Series software components for this release.

**Table 2: Release 6.6 software components**

File Type	Description	File Name	File Size (bytes)
Standard runtime image software version 6.6	Standard non SSH image for the Ethernet Routing Switch 5000 Series	5xxx_660006.img	10,720,996
Secure runtime image software version 6.6	Standard SSH image for the Ethernet	5xxx_660007s.img	10,982,884

File Type	Description	File Name	File Size (bytes)
	Routing Switch 5000 Series		
Diagnostic software version 6.0.0.18	ERS 5000 diagnostic software	5xxx_60018_diags.bin	2,471,456
Enterprise Device Manager Help Files	EDM Help files zip	ERS5000v660_HELP_EDM.zip	2,558,376
MIB Definition File	MIB Definition File	Ethernet_Routing_Switch_5xxx_MIBs_6.0.zip	1,861,472
COM Plug in	ERS 5000 plugin for COM	ers5000v6.6.0.0.zip	3,836,255

---

## Software upgrade

The procedures in this section are used to upgrade the diagnostic and agent software. Use these procedures to upgrade to Software Release 6.6 and higher.

**!** **Important:**

There is no upgrade path from any agent software release earlier than 6.3 to Software Release 6.6. Devices running older agent software must first be upgraded to a version of Software Release 6.3 before upgrading to Software Release 6.6. Note that the diagnostic software running on the device should not be earlier than 6.0.0.16.

**!** **Important:**

If upgrading from a 5.x diagnostic image to a 6.x diagnostic, you should not use the no-reset option. You must execute the 6.x diagnostic prior to loading any 6.x agent images.

---

## Upgrading diagnostic software

Use the following procedure for upgrading the diagnostic software image.

1. Access the ACLI through a Telnet or Console connection.
2. Enter Privileged EXEC mode using the `enable` command.
3. Use the command `download address <ip_address> diag <image_name> [no-reset] [usb]` to transfer the diagnostic image to the device.

The following table describes the parameters for the `download diag` command.

Parameter	Description
address <ip_address>	The IPv4 or IPv6 address of the TFTP server on which the diagnostic image is hosted.
diag <image_name>	The name of the diagnostic image file on the TFTP server.
no-reset	This parameter specifies that the device will not reset after the upgrade is complete.
usb	This parameter specifies that the software download will occur from a USB device instead of the network.

The upgrade process occurs automatically without user intervention. This process deletes the contents of the flash memory and replaces it with the desired software image. Do not interrupt the download process.

When the process is complete, the device automatically resets unless the **no-reset** parameter was used. The software image initiates a self-test and returns a message when the process is complete.

During the download process the switch is not operational.

---

## Upgrading agent software

Use this procedure to upgrade agent software.

1. Access the CLI through a Telnet or Console connection.
2. Enter Privileged EXEC mode using the **enable** command.
3. Use the command **download address <ip\_address> {primary | secondary} {image <image\_name> | image-if-newer <image\_name> | poe\_module\_image <image\_name>} [no-reset] [usb]** to transfer the agent image to the device.

The following table describes the parameters for this command.

Parameter	Description
address <ip_address>	The IPv4 or IPv6 address of the TFTP server on which the agent image is hosted.
primary   secondary	Designates whether the image is stored in the primary or secondary image location. The default is primary.
image <image_name>   image-if-newer <image_name>   poe_module_image <image_name>	The name of the agent image file on the TFTP server. Each option is mutually exclusive. Use the option described with the following situation:

Parameter	Description
	<ul style="list-style-type: none"><li>• To load the agent image under normal circumstances, use the image option.</li><li>• To load the agent image only if it is newer than the current image, use the image-if-newer option.</li><li>• To load the agent image if it is a PoE module image, use the poe_module_image option.</li></ul>
no-reset	Specifies that the device will not reset after the upgrade is complete.
usb	Specifies that the software download will occur from a USB device instead of the network.

The upgrade process occurs automatically without user intervention. This process deletes the contents of the flash memory and replaces it with the desired software image. Do not interrupt the download process.

When the process is complete, the device automatically resets unless the `no-reset` parameter was used. The software image initiates a self-test and returns a message when the process is complete.

During the download process the switch is not operational.

---

## How to get EDM online help files for embedded EDM

Because help files are not included with the embedded EDM software files on the switch, a network administrator must copy the software-release-specific help files onto a TFTP server. Once the help files are downloaded to the TFTP server, the network administrator must configure the switch with the path to the help files on the TFTP server. You can use ACLI or EDM to configure a path from your switch to the help files. After the path to the help files is configured, whenever an EDM user clicks the help button on the toolbar, the switch downloads and displays help information in the Web browser.

If you are using Configuration and Orchestration Manager (COM) to manage your switch, help resides with COM and you do not need to use these procedures.

For more information about EDM, see *Fundamentals of Avaya Ethernet Routing Switch 5000 Series*, NN47202-104.

---

## Downloading help files

### Before you begin

- An available TFTP server

### About this task

Use this procedure to download EDM online help files.

### Procedure

1. To obtain EDM help files for the embedded element manager, do one of the following:
    - Go to the Avaya Web site at <http://www.avaya.com/support> and locate the help files for the appropriate product.
    - Select the help files from the software CD ROM.
  2. Download the help files to a TFTP server.
- 

---

## How to configure the path to the embedded EDM help files

If you are using embedded EDM, use the procedures in this section to configure the path to the help files. You can configure the help file path with ACLI or EDM.

---

## Configuring the path to the help files using ACLI

### About this task

Use the following procedure to configure the path to the help files using ACLI.

### Procedure

In ACLI, go to the Global Configuration mode and use the following command:  
`edm-help-file-path <path name> tftp address <tftp address>`

The following table describes the parameters for the `edm-help-file-path` command.

Parameter	Description
path name	Specifies the path name you created for EDM help files. The path name is stored in NVRAM.

Parameter	Description
TFTP address	Specifies EDM TFTP server IP address. Use this address only for EDM help files. If you do not specify a TFTP server address, the system uses the address specified most recently. WARNING: Because the TFTP server address is stored in NVRAM, each time the system returns to the default configuration, you must reconfigure the path to EDM online help.

---

### Example

Following is an example of an ACLI EDM help file path:

```
edm help-file-path ERS5000_66_Help tftp address 100.100.100.15
```

In the preceding example ERS5000\_66\_Help is a folder that contains help files and the folder is located on a TFTP server at the 100.100.100.15 address.

---

## Configuring the path to the help files using EDM

Use the following procedure to configure the path to the help files.

### Procedure steps

1. From the navigation tree, click **Edit**.
2. From the Edit tree, click **File System**.
3. Select the **Help File Path** tab.
4. In the Path dialog box, enter the path to the help file storage location.

Example

```
tftp://xxx.xxx.xxx.xxx/file_name
```

---

## Supported software and hardware capabilities

The following table lists the known limits for the Avaya Ethernet Routing Switch 5000 Series, Release 6.6 and higher, and Enterprise Device Manager.



**Table 3: Supported software and hardware capabilities**

Feature	Maximum number supported
VLANs	1024 (1k)
Protocol-based VLANs	Depending on the protocol specified, the number of protocol VLANs supported at one time varies between 3–7. See <i>Configuring VLANs, Spanning Tree, and Multi-Link Trunking on Avaya Ethernet Routing Switch 5000 Series, NN47200–502</i> for more information.
IGMP maximum number of unique groups	Layer 2 and Layer 3 992
EAPoL 802.1x supplicants	32 per port 768 per stack
Maximum number of routes (dynamic, static and local)	4000 routes for ERS 5600 units and stacks
ARP records	4096
Static ARP	256
IP interfaces	256
Static routes	512
Spanning Tree Groups	8
IPv6 DHCP relay forward paths	256
IPv6 static routes	512
IPv6 interfaces	256
IPv6 tunnels	4
Aggregation groups (link aggregation)	32
Ports per aggregation group	8
MAC addresses in fdb	16 K
OSPF areas	4 (3 areas plus area 0)
OSPF adjacencies	64
VRRP interfaces	64
ECMP	4 paths
DHCP Snooping Binding table entries	1024
DHCP relay forward paths	512
IP Management routes	4

Feature	Maximum number supported
PIM-SM multicast entries	Up to 992 for ERS 56xx series The ERS 56xx platforms support a maximum of 992 IPMC forwarding entries. These limitations are imposed on standalone ERS 56xx devices and stacks. Note: These limits do not indicate that 992 entries will actually be available since the installation of IPMC entries in hardware is also determined by free entries being available.
Allow-flood IGMP multicast addresses	The maximum number of allow-flood multicast entries is determined by the number of VLANs on the device. Each entry in the allow-flood table applies to each current VLAN; for example, if 1 entry exists in the allow-flood table and 5 VLANs are configured, then there are 5 entries programmed in hardware. Currently, the hardware limit is 4096. Note: You should not exceed this limit. The limit for the maximum number of allow-flood addresses is 128 (1 VLAN).
Link State Tracking: Instances	2
Port Mirroring: Instances	4
Port Mirroring: RSPAN VLANs	4
Port Mirroring: RSPAN destinations	4 per switch or stack
VRF: Instances	4

---

## Additional information for the software feature license file

When you create a license file to enable licensed features on an Avaya Ethernet Routing Switch 5000 Series switch with the Avaya Electronic Licensing Portal, you must specify a file name. Follow the instructions on the License Certificate within the License Kit, or for more information, see *Fundamentals of Avaya Ethernet Routing Switch 5000 Series*, NN47202-104.

You must use the following rules when you generate and name the file:

- A maximum of 63 alphanumeric characters
- Lower case only
- No spaces or special characters allowed

- Underscore (\_) is allowed
- The dot (.) and three-character file extension are required

File name example, abcdefghijk\_1234567890.lic.

The format of the file that you upload to the license generation tool, and that contains the list of MAC addresses, must be as follows:

- ASCII file format
- One MAC address per line
- No other characters, spaces, or special characters allowed
- MAC must be in hexadecimal, capitalized format, with each pair of characters separated by colon; for example, XX:XX:XX:XX:XX:XX
- The file must contain the correct MAC addresses. Any incorrect MAC addresses will result in the licensed features not working on designated units.
- The number of MAC addresses must not exceed the number of MAC addresses allowed for the License Authorization Code entered for a particular file. For example:
  - AL1016001 = 2 MAC addresses (1 stack/standalone unit)
  - AL1016002 = 20 MAC addresses (10 stacks/standalone units)
  - AL1016003 = 100 MAC addresses (50 stacks/standalone units)
  - AL1016004 = 200 MAC addresses (100 stacks/standalone units)

---

## Supported standards, MIBs, and RFCs

This section lists the standards, MIBs, and RFCs supported by the Avaya Ethernet Routing Switch 5000 Series.

---

### Standards

The following IEEE Standards contain information that applies to the Avaya Ethernet Routing Switch 5000 Series:

- IEEE 802.1D (Standard for Spanning Tree Protocol)
- IEEE 802.1p (Prioritizing)
- IEEE 802.1Q (VLAN Tagging)
- IEEE 802.1X (EAPOL)
- IEEE 802.1ab (Link Layer Discovery Protocol)

- IEEE 802.3 (Ethernet)
- IEEE 802.3u (Fast Ethernet)
- IEEE 802.3x (Flow Control)
- IEEE 802.3z (Gigabit Ethernet)
- IEEE 802.3ab (Gigabit Ethernet over Copper)
- IEEE 802.3ad (Link Aggregation)

---

## RFCs

For more information about networking concepts, protocols, and topologies, consult the following RFCs:

- RFC 768 (UDP)
- RFC 791 (IP)
- RFC 792 (ICMP)
- RFC 793 (TCP)
- RFC 826 (ARP)
- RFC 854 (Telnet)
- RFC 894 (IP over Ethernet)
- RFC 951 (BootP)
- RFC 1112 (IGMPv1)
- RFC 1157 (SNMP)
- RFC 1213 (MIB-II)
- RFC 1271 (RMON)
- RFC 1350 (TFTP)
- RFC 1493 (Bridge MIB)
- RFC 1757 (RMON)
- RFC 1945 (HTTP v1.0)
- RFC 2131 (DHCP)
- RFC 2236 (IGMPv2)
- RFC 2362 (PIM-SM)
- RFC 2474 (QoS)
- RFC 2597 (QoS)
- RFC 2598 (QoS)

- RFC 2665 (Ethernet MIB)
- RFC 2674 (Q-BRIDGE-MIB)
- RFC 2737 (Entity MIBv2)
- RFC 2819 (RMON MIB)
- RFC 2863 (Interfaces Group MIB)
- RFC 2865 (RADIUS)
- RFC 3140 (QoS)
- RFC 3246 (QoS)
- RFC 3376 (IGMPv3)
- RFC 3410 (SNMPv3)
- RFC 3411 (SNMP Frameworks)
- RFC 3412 (SNMP Message Processing)
- RFC 3413 (SNMPv3 Applications)
- RFC 3414 (SNMPv3 USM)
- RFC 3415 (SNMPv3 VACM)
- RFC 3576 (Dynamic Authorization Extensions to Remote Authentication Dial In User Service)

The following table lists IPv6 specific RFCs.

Standard	Description	Compliance
RFC 1886	DNS Extensions to support IPv6	Supported
RFC 1981	Path MTU Discovery for IPv6	Supported
RFC 2460	Internet Protocol v6 (IPv6) Specification	Supported
RFC 2461	Neighbor Discovery for IPv6	Supported
RFC 2462	IPv6 Stateless Address Auto-configuration	Auto-configuration of link local addresses only
RFC 2464	Transmission of IPv6 Packets over Ethernet Networks	Supported
RFC 3162	RADIUS and IPv6	Supported
RFC 3315	DHCPv6	Support for IPv6 DHCP Relay
RFC 4007	Scoped Address Architecture	Supported

Important notices and new features

<b>Standard</b>	<b>Description</b>	<b>Compliance</b>
RFC 4022	Management Information Base for TCP	Mostly supported
RFC 4113	Management Information Base for UDP	Mostly supported
RFC 4193	Unique Local IPv6 Unicast Addresses	Not supported
RFC 4213	Transition Mechanisms for IPv6 Hosts and Routers	Supports dual stack and configured tunnels
RFC 4291	IPv6 Addressing Architecture	Support earlier version of RFC (3513)
RFC 4293	Management Information Base for IP	Mostly supported
RFC 4301	Security Architecture for the Internet Protocol	Not supported
RFC 4443	Internet Control Message Protocol (ICMPv6)	Support earlier version of RFC (2463)

# Chapter 4: Resolved issues

The following table lists the issues resolved in the current software release.

Change Request Number	Description
<b>Resolved issues in Release 6.6</b>	
wi00486525	VRRP may intermittently bounce when multiple protocols are configured on upstream routers with traffic and large routing updates.
wi00486579	Inconsistent display of pluggable modules in BigWave Stacks.
wi00486751, wi00490844, wi00497003	When the maximum of 10 DHCP clients are bound by IP Source Guard on MLT/LACP ports, if those ports go down, several IPSG binding table full messages will be logged. This is an incorrect behavior.
wi00487998	<b>Demo License:</b> If you use a Demo License and you remove the Demo License, you must reboot the stack.
wi00488227	EDM, Multiple Port Selection: EDM can delete up to a maximum of 120 ports when you use multiple port selection. If you select more than 120 ports, some of the ports may not be disabled.
wi00488679	EDM: You cannot view and configure 802.1ab Dot1 settings for Local Protocol Vlan and Local Vlan Name using EDM. <b>Workaround:</b> Use ACLI to view and configure 802.1ab Dot1 settings for Local Protocol VLAN and Local VLAN name
wi00494658	A non-PoE phone may display as Unknown and need to be rebooted after a stack is rebooted.
wi00554963	RADIUS, RADIUS reachability: If you use the "radius reachability use-radius", the switch sends reachability requests with the username 'avaya' and a blank password. Because the Avaya ignition server does not allow accounts to be created with a blank password, the ignition server will log intrusion events when the dummy requests are regularly sent from the switch. <b>WORKAROUND:</b> Use ICMP reachability for ignition server reachability.
wi00555156	SLPP: In a stack of 5 or more units that runs a complex configuration, for example, SMLT, LACP, SLPP, or OSPF, SLPP can fail to detect and prevent loops due to inadequate system resources. SLPP PDUs are not treated as high priority packets and are not processed on time. This does not happen on SLPP ports on the base unit.
wi00555215	EDM, MSTP: If your environment contains a large number of stacks and a large number of ports and you click between the CIST Port, MSTI Bridges, and MSTI Port tabs, the system may display the Unresponsive script dialog because you have initiated a large data retrieval.

Resolved issues

Change Request Number	Description
wi00834482	When LACP and SLT's are configured IST's, some SLT ports may blocked traffic. If this happens, bouncing the SLT ports on the IST peers where the block occurs should resolve the issue and traffic can be seen forwarding again. This issue will address in the maintenance build.
wi00929935	Change in ADAC tagged frames configuration: You must delete LLDP MED network policies on phone and uplink/call server ports before configuring ADAC. There are default LLDP MED network policies on all ports that take precedence over ADAC policies.
wi00936876	OSPF, SMLT: An intermittent error may be seen when OSPF over SMLT is configured in a looped environment (SLPP enabled).
wi00982958, wi01001510	MSTP, MLT: When you attempt to enable STP learning on a MLT for an inactive MSTI, you may encounter an error message stating that the corresponding STP is not active, rather than stating that the MSTI is not active.
wi00982961	TACACS+, access mode log message: After connecting to the switch via Telnet/console with TACACS+ enabled, the access mode log message indicates <code>no security</code> .
wi00989413	EDM, Stack Health: Display of switch stack health in EDM after units in stack are renumbered may not be accurate. <b>Workaround:</b> use ACLI command.
wi00992210	MAC Security address table: Static entry in the MAC security table should be created before planning to remove unit from stack.
wi00992287	MAC Security, MAC address table: If you have a MAC security list that has only ports from a unit which is no longer part of the stack, the MAC addresses that are statically associated with the MAC security list are not removed from the MAC address table, even though the MAC security list has been erased. <b>Workaround:</b> Manually remove the static entries.
wi00994307	EDM, IGMP: The 'in port' for IGMP groups is not displayed correctly in EDM. <b>Workaround:</b> Display in ACLI.
wi00995161	RADIUS Management Accounting: When accounting is enabled/disabled from a Telnet/SSH session, NAS-Port-Type contained in the accounting packet is set incorrectly to Async, instead of Ethernet.
wi01001707, wi01001716	<p>IGMP/SMLT: On stackable switches where Spanning Tree is enabled on VLANs/ports, the following behavior can be expected due to the Spanning Tree convergence time.</p> <ol style="list-style-type: none"> <li>1. There will be a 30 second delay of multicast traffic before traffic can be forwarded to MC clients connected on the base unit of the stack when a non-base unit is rebooted.</li> <li>2. When the non-base unit rejoins the stack, there will be a delay of approximately 90 seconds before the multicast traffic can be forwarded to the multicast clients connected to the non-base unit. MC clients connected to the base unit experience the same behavior as in #1.</li> </ol>



Change Request Number	Description
wi01004253	EDM, stack information: The display of stack information in EDM after booting the base unit may not be correct. CLI should be used.
wi01007809	RADIUS accounting: When you log off a telnet/ssh session, the RADIUS accounting STOP session message sent indicates an incorrect Acct-Terminate-Cause of <code>Lost-Carrier</code> instead of <code>User-Request</code> .
wi01008960	EAP: If no more than 4 minutes and 30 seconds have passed after an EAP user is authenticated , a flush of the mac address table on the switch/stack will have no effect on the user`s authentication . However , if this timer expires , the client will try to re-authenticate and if it is still there it will get re-authenticated.
wi01009057	Security log messages: When you log out from an SSH session, you may see security log messages of <code>lost connection</code> instead of <code>user logout</code> .
wi01009215	AUR Auto-Save: The Auto Unit Replacement Auto-Save parameter value is not saved when autosave is set to disabled.
wi00993819	ADAC — CLI-EDM inconsistency for UFB and UFA: If ADAC is configured as untagged frames basic or advanced, in EDM tagging appears to be enabled for phone ports, although tagging is disabled for phone ports from the view in CLI. In ADAC untagged frames basic and advanced, LLDP policies on phone ports are untagged
wi01019181	The management traffic might be affected in a case where a static IPv4 route used for switch management from a remote network is more specific than a local route. To reestablish the management connection, the configuration of an IPv4 management route for the same network is required
wi01021166	MLT, MAC Security: When using MLT trunk ports with MAC-Security auto-learning and a set threshold (for example 20 out of 25 maximum possible value), bouncing the MLT trunk from enabled state to disabled state several times may cause the MAC SA entries learned to exceed the threshold.
wi01022088	EDM, MSTI: The error message <code>inconsistentValue</code> is displayed when trying to create an MSTI which already exists.
wi01028882	SMLT/LAG: Currently in an SMLT over LACP scenario, the CLI environment allows entering commands for binding multiple LAGs to the same SMLT ID. However, only one (the first one configured) binding becomes actually operational. Avaya recommends that you keep the LAG to SMLT ID bindings as one-to-one in order to avoid creating ambiguous device configurations.
wi01028979	PIM: The command <code>show ip pim interface enabled</code> may not return any of the enabled pim interfaces after a reset of the device.
wi01034689	EAP/NEAP, RADIUS: Using EAP/NEAP users with RADIUS assigned VLAN and fail open VLAN, authenticated users use RADIUS assigned VLAN. If the RADIUS server is unreachable, clients are moved in fail open VLAN. After defaulting to the RADIUS server, users are removed from fail open VLAN, while remaining authenticated. They will use RADIUS assigned VLAN.

Resolved issues

Change Request Number	Description
	Reauthentication is not performed in this situation (EAP and NEAP clients are not flushed).
wi01035281	SMLT: Avaya recommends that you refrain from consuming all of the trunks 1-32 since configured aggregated trunks will utilize these starting at 32 and progressing through lower numbers (31, 30, 29, ...). Trunks may be configured using values of 33-512 and not create any conflict with trunks formed by aggregation.
wi01035284	LACP and mrouter ports are mutual exclusive. Avaya recommends using mrouter ports with MLT.
wi01035500	Brouter, IGMP Snooping: ip igmp snoop is not supported on brouter port. However, no error is returned when configuring it.
wi01035841	SLPP: If the '0' option is selected from the output of the <code>slpp timeout</code> command, the slpp timeout will be set to '4'.
wi01039420	Voice VLAN: If you encounter an Invalid Voice-VLAN ID error message while attempting to enable ADAC on a standalone switch which used to be part of a stack (even if the voice VLAN is set) check that the VLAN is a voice VLAN with command <code>show vlan voice-vlan</code> . If the VLAN does not appear in the list of voice VLANs, issue the command <code>vlan voice-vlan vlan_id</code> to enable ADAC.
wi01083893	IP Office Script - When configuring IP Office from edm-offbox or snmp, console lock and intermittent critical messages appear in syslog.
<b>Resolved issues in Release 6.3.1</b>	
wi01031886	The console locks up in diagnostics when downloading an agent and pressing <b>Enter</b> twice. Diagnostics software version 6.0.0.16 fixes this problem.
<b>Resolved issues in Release 6.3</b>	
wi00491923	The system does not remove all expired MAC Source Addresses in the MAC Address Table after the aging time has expired.
wi00484828, wi00492144, wi00497730	Device Type for devices connected to the data port on a VoIP phone are being displayed as UNKNOWN instead of PASSIVE in the command output of show nsna client.
wi00492820	ADAC port configuration types not defined in manual.
wi00485407	Unnecessary system messages of STP_CLR_PCONFIG: PCFG_BRIDGING stpgld 0, portNo x are generated when disabling spanning tree on Ethernet ports.
wi00493682, wi00495091, wi00497859	Informational event type information is being sent to remote syslog server even when Event Type To Log is restricted to Critical and Serious event types.

Change Request Number	Description
wi00493706	No confirmation message is provided when an ASCII configuration, initiated via the UI (User Interface) push button, is successfully uploaded to the USB port.
wi00486074	Time Domain Reflector test ran from JDM is returning Pair Shorted as an error message for Pin Short cable problems rather than the correct error message of Pin Short.
wi00493776	MAC security Lifetime setting cannot be modified from the JDM.
wi00486100	MAC authorized clients are not reauthorized after a former base unit rejoins the stack.
wi00486318	LLDP configuration within an ASCII configuration file may fail to load during an ASCII configuration upload.
wi00486328	The cost metric, within the show ip routes output, for external routes increases to 127174722 when a fictitious OSPF virtual link is created than deleted.
wi00486432, wi00486962, wi00496973	The system does not remove user based policies nor age out the MAC addresses of Non EAPOL clients that physically migrate to a different EAPOL enabled port. This behavior will result in Non EAPOL authentication failure for migrating clients when attempting to authenticate and applying policies on their new ports. Error state will generate the following system messages: Duplicate users (different port, same user name) and bsnEapUbpFailure prohibited.
wi00486497	Unknown multicast and known multicast variables within a system classifier are not functioning correctly. Issue is exclusively on the 5600.
wi00486386	Multicast traffic is not forwarded to the destination network configured within a non-local static route (NLSR). A NLSR is similar a regular static route except that the next hop of a NLSR static route is not directly connected
wi00486635	The source IP address for traffic destined for a RADIUS server should be the IP address of the Management VLAN IP interface.
wi00494290	PIM is intermittently being disabled on random VLAN interfaces after a reboot.
wi00494367	Incorrect error message of "Invalid file name" is being generated when attempting a software download from an unreachable server.
wi00486652, wi00488134, wi00489324, wi00496995	Uploading an ASCII configuration containing IP route commands results in configuration upload failure and the following system messages: % Cannot modify settings % Duplicate Route Entry. Use Modify Operation
wi00494385	IPv4 and IPv6 IP Addresses stored within NVRAM are not overwritten by the IPv4 and IPv6 Addresses existing in the ASCII configuration file being uploaded to the unit/stack.
wi00486691	Some ARP, OSPF, or VRRP packets are unexpectedly mirrored when using XrxYtx mirroring mode and the monitored port is in the Management VLAN or in SMLT VLANs.

Resolved issues

Change Request Number	Description
wi00486687	MAC addresses are lost when a base unit fails.
wi00486701	LLDP-Med fails to configure VoIP phones with defaulted configuration. VoIP fails to initiate displaying error messages of "Starting DHCP..." or "DHCP server unreachable..".
wi00486698	ADAC syslog messages sent by non base units is displaying ADAC: System operationally during a system reboot. During a system reboot ADAC is down. The base unit sends the correct syslog message of ADAC: System operationally dis abled
wi00486715	On a pure 56xx stack, port mirroring mode XrxYtx multiplies unicast traffic on port Y in certain scenarios.
wi00486712	Disabling and re-enabling VLACP followed by a reboot will result in VLACP failing to function after the system restores from a reboot.
wi00486688	The EAP-TLS or PEAP-MsChapV2 clients could be unexpectedly transitioned to the EAP Held state on a multihost enabled port.
wi00486710	Voice traffic is blocked on a non-base unit when ARP inspection is enabled on a VoIP VLAN.
wi00494406	Walking the ipNetToPhysicalPhysAddress MIB results in a system reboot with various data access exception tasks of tLDT, tSNMP or bcmRX.
wi00494771	The LLDP Med-Network-Policies Voice Tagging command is rejected and deemed invalid by the operating system when attempting to execute the command.
wi00494479	PIM outgoing interfaces may not be installed in the r × r identity matrix (IR) if session directory tool (SDR) is flapped.
wi00494624	Continuous IPv6 ping stops working after 2147 ICMPv6 messages.
wi00486941	Telnet session hangs on ERS 5510-48T during an ASCII configuration download.
wi00487092	ACG fails to function if a ports tagging mode is Untagpvidonly and the port is also member of 2 Spanning Tree Groups.
wi00494933	After booting to default setttings the syslog will display the message <b>ASCII failed at line 1</b> . This can be ignored. This only happens after a boot to default settings and not during a normal operation or reset of the switch. This does not affect subsequent ASCII downloads. The successful application of configurations can be confirmed using the <b>show logging</b> command. The bogus message will be the first in chronological order.
wi00992380	The correct argument order when uploading the sshc key to an usb device and specifying a certain unit is : <b>sshc upload-host-key usb unit 1 key-name word dsa</b> .

# Chapter 5: Known issues and limitations

Use the information in this section to learn more about known issues and limitations. Where appropriate, use the workarounds provided.

---

## Known issues

See the following table for a list of known anomalies for the Avaya Ethernet Routing Switch 5000 Series.

**Table 4: Known issues**

Change Request number	Description
<b>Known Issues from Release 6.6</b>	
wi01067057	Downgrading software release - if you downgrade from 6.6.0 to /6.0.z/ 6.1.k/6.2.x/6.3.w you will lose the configuration, i.e. the configuration is erased.
wi01081912	TDR - pairs of wires are incorrectly displayed as swapped after a TDR test on straight through or crossover cables.
wi01083597	IP Netstat - Local and foreign addresses may be incorrectly displayed by the show ip netstat command when using TFTP transfer.
wi01087989	EDM, multiport - mcast/bcast may not be set correctly in EDM when applying configuration on all ports.
wi01092387	SSH Client, banner - an incorrect banner may be displayed after connecting to the switch via SSH Client.
wi01092410	UI Button - with the Default IP feature, the UI button no longer has the ability to set the default IP address. You can continue to configure IP parameters using the console menu and ACLI command <code>ip address</code> or in EDM from the Administration > Quick Start menu.
wi01092748	DSA Key Generation - Generation of DSA key takes much longer from Telnet and SSH than from CLI. DSA key generation from CLI takes approximately two seconds, whereas Telnet ranges from 20–30 seconds, and SSH approximately 60 seconds.
wi01094184	BGP - total imported routes count is doubled after restarting BGP and is not cleared after disabling redistribution.

Known issues and limitations

Change Request number	Description
wi01095251	SNMP, CLI - if you continuously poll the MIBs related to PoE on PWR units, the CLI response time increases on those units. Response time recovers when the polling of the MIB set is complete.
wi01095692	DHCP Snooping - When the DHCP client sends DHCP release to a DHCP server, only one syslog message is generated for a DhcpSnooping trap, instead of two. No syslog message is generated when the switch sends bsDhcpSnoopingTrap.
wi01096361	IPMGR - IP Manager configuration is not available when managing the device through COM (EDM-Offbox). The Configuration\Administration \Remote Access is grayed out even if discovering the device using a high security SNMPv3 user. This configuration will only be possible through a direct EDM connection.
wi01099044	OOB Management, CLI password type - CLI password type TACACS + doesn't apply with only out-of-band management IP configuration. If using RADIUS instead of TACACS+, CLI password type changes to RADIUS as expected.
wi01101091	QoS - For CIR equal to 64000 or 128,000 kbps, the traffic isn't limited after the expected period of time, calculated based on the configured committed rate and burst size, when sending traffic with a higher rate than the CIR. The actual burst duration is up to double the expected burst duration.
wi01102781	DHCP- DHCP packets may be displayed as filtered when DHCP Snooping is enabled, but the IP address can be obtained from the server.
wi01103115, wi01103120	IST core reboot - the recovery time in the case of an IST core reboot will be approximately 15 seconds.
wi01111136	OOB Management - Ping in a directly connected network does not work from the switch when a less specific route for the same network is configured through out-of-band management.
wi01111419	TBU reboot - the console may be flooded with debug messages when the Temporary Base Unit is rebooted.
wi01112588	VRRP, DHCP - DHCP packets are doubled in an SMLT with VRRP scenario.
wi01112641	OOB Mgmt, EDM/COM - you cannot administratively enable or disable the out-of-band port from EDM/COM. A command for this functionality is available in CLI.
wi01115099	FOV Continuity - additional Fail Open VLAN Continuity mode syslog messages may appear due to checks performed on individual client request. These messages do not reflect the final state of the ports involved.

Change Request number	Description
wi01116959	LLDP, EDM - LLDP MED network policies are not created from EDM if the port is not a member of the VLAN.
wi01117600	Voice VLANs, ADAC - if a port is configured with both ADAC and EAPOL voice VLANs, when the ADAC op-mode is modified, the port is removed from all EAP voice VLANs and remains only in the ADAC voice VLAN.
wi01120589	Pluggable Ports, EDM off-box - Pluggable Ports information cannot be obtained using the Pluggable Ports button from the EDM off-box. The button works only for EDM on-box.
wi01121469	LLDP port TLVs - MgmtAddr lldp tx-tlv is not present in EDM TLVsTxEnable tab ( Edit->Diagnostics->802.1AB->LLDP->Port tab). In ACLI it is displayed next to PortDesc, SysName, SysDesc, SysCap, under the <code>show lldp tx-tlv</code> command.
wi01122505	EDM offbox, LLDP Avaya Local File Server - an error message is received when attempting to access the configured LLDP Avaya Local File Server.
wi01122965	COM/EDM Offbox - Unavailable options from non-default VRF navigation tree are not greyed out. Only IP-> IP, IP-> DHCP Relay, and Help should be available.
wi01124972	QoS - Configuration of the 128th byte of a QoS system element is not possible. If using up to the 127th byte, configuration is properly applied.
wi01124975	QoS - QoS system elements matching more than two chunks having different pattern data in the same position cannot be applied on the same if-group.
wi01127017	PIM - Incorrect PIM join-prune-interval and query-interval values are displayed and saved in config. The 'default' command does not restore the parameters. You can manually re-enter the parameters.
wi01131174	EDM, Change RADIUS password - access to EDM is granted even though an incorrect password format is used when changing the RADIUS password in EDM.
wi01131178	EDM, Change RADIUS password, Firefox - after successfully changing the RADIUS password from a Mozilla Firefox browser through EDM, the log on button is missing from the top of the page.
wi01131546	DHCP Snooping, EDM - EDM displays 'noSuchObject' for SftpServerAddress in DHCP Snooping Global folder on non-SSH agent image.
wi01131924	EDM, Change RADIUS password - when changing the RADIUS password from EDM after the account is marked for a password change, the switch allows you to use the same set of credentials.

Change Request number	Description
wi01131927	EDM, Change RADIUS password, Firefox - when changing the RADIUS password from EDM after the account is marked for a password change, hitting the Enter button has no effect using Mozilla Firefox.
wi01131934	EDM, Change RADIUS password - when changing the RADIUS password from EDM after the account is marked for a password change and refreshing the page, the login is permitted without entering any credentials.
wi01132500	EDM, IPv6 icmp - you cannot enable/disable IPv6 icmp block-multicast-replies from EDM. This functionality exists in CLI.
wi01134096	SSH - SSH connection may fail to establish while a binary configuration is being saved.
wi01135843	Stack Monitor - Stack Monitor traps are not correctly sent at every trap-interval when one unit from a stack is removed.
wi01136733	EDM, STP BPDU-Filtering - EDM displays an incorrect error message if you enter an out-of-range value for STP BPDU-Filtering Timeout field.
wi01136918	EDM, Change RADIUS password, Firefox - when using EDM from Firefox version 3.6.2, after the account is marked for a password change, the previously entered username and password disappear.
wi01138196	show ip rip ACLI command - the switch returns 'Internal Error' for the ACLI command <code>show ip rip interface ethernet</code> on units with specific configurations. As a workaround, use the ACLI command <code>show ip rip interface vlan</code> .
wi01140365	Lossless mode - if running in lossless mode, ensure that flow control is set to asymmetric or symmetric on the switch and the connected neighbors.
wi01141450	SNMP, IPv6 – SNMP walk is interrupted if default IPv6 route is enabled and appears in the IPv6 route table. Workaround: disable the IPv6 default route, remove it, or use a more specific route. For example, <code>ipv6 default-gateway 4148:4:4:340::1, no ipv6 route ::/0 next-hop 4148:4:4:340::1 vlan 3927 enable</code> .
wi01138674, wi01140590	DHCP Snooping external save - defaulting the DHCP Snooping external save settings results in wrong ACG output. Workaround: instead of defaulting the DHCP Snooping external save configuration prior to applying a new DHCP Snooping external save configuration, you can directly overwrite your settings.
wi01142391	Copper SFP - removing and reinserting a copper SFP may cause the switch to lose 10/00 port speed setting. Connectivity may be lost until the port speed is reset manually.



Change Request number	Description
<b>Known Issues from Release 6.3.1</b>	
wi01074793	IP Office Script - run ip office script fails if switch or stack management IPv6 address is configured.
wi01088633	If the default vid = 0, then the default LLDP med-network-policies aren't sent from DUT. As a protective measure, if the LLDP-MED network policy has VID = 0, then the switch does not advertise the network policy TLV (even if the policy is enabled); for all other values of VID, the switch sends out the advertisement.
wi01067057	The configurations on the switch are lost after downgrade because binary configuration files can only be loaded in same build it was saved. <b>Workaround:</b> To fix this Binary configuration issue, the software erases both the memory blocks of NVRAM before reloading the downgrade image and blocks are set to default configurations. If the configuration is required on downgrade, then save the configuration to ASCII and restore it once the downgrade to the required software is completed.
WI01088875	In the EDM Help, the IP Route to Gateway Modem-Router (Internet/WAN) default value is 192.168.43.2 This value should be: Default IP Route set to 192.168.44.2 (Gateway Modem-Router interface).
<b>Known Issues from Release 6.3</b>	
wi00906543	EDM, 10G Ports: 10G ports are not seen in EDM under Power Management > PoE > PoE Ports.
wi00927200	NEAP, MHSa Configuration: When a disconnect message is sent for an authenticated EAP user in MHSa mode, you may experience a 15 second delay before the port reverts to the initial VLAN (or Guest VLAN).
wi00932580	NEAP, EAP clients and bsnEapRAVError trap: The bsnEapRAVError trap is generated only for EAP clients and not for NEAP clients.
wi00933750	RIP out policy: RIP out policy using network prefix to drop specific networks will not forward other route networks learned from OSPF, static, and direct routes. <b>Workaround:</b> Make a sequence 2 in the same route policy to forward any protocol.
wi00960304	EDM, ip-fwd-nh policy: When you create an ip-fwd-nh instance from the base unit using EDM, the policy may fail to attach to a port based VLAN.
wi00983765	SSH Banner has only ACLI support (no EDM support).
wi00987283	USB devices: USB devices with NTFS or exFAT file format are not supported. FAT32 is the only supported file format.

Change Request number	Description
wi00995161	RADIUS Management Accounting: When accounting is enabled/ disabled from a Telnet/SSH session, NAS-Port-Type contained in the accounting packet is set incorrectly to Async, instead of Ethernet.
wi00996182	TBU, MLT: In a stack configuration, MLT trunk members for units that are temporarily not part of the stack (for example in a reboot process) are still attached logically in the configuration of active units. This event will not show aggregated ports as they will be dynamically hidden in CLI and ACG while the missing unit is not available.
wi01000569	SNMPv3 user: When you create a new SNMPv3 user with password security disabled, using a password string within the required length but with an atom that repeats twice (for example, the password string '12341234'), the user will not be created.
wi01007577	DHCP Snooping filename: The maximum length of the DHCP Snooping external filename varies between ACLI and EDM.
wi01009777	IPFIX — EDM-Offbox: You may be unsuccessful in applying settings for a large number of ports from EDM-Offbox on a SNMPv3 discovered device. Reducing the number of selected ports will yield the expected result.
wi01038367	SSL Certificate/RSA key generation: When the switch generates an SSL certificate at the same time the RSA host key is generated, the CPU may be busy for a short time, as the two activities can be resource intensive.
wi00935460	LACP : When booting a system with one or several LAGs configured, the trunk IDs of the LAGs might not be the same after the system comes up again. The only way to predict this is on an SMLT-LACP environment where the LAG ID is bound to an LACP key
wi00983785	Security, Dynamic ARP: When Dynamic ARP Inspection is configured and ARP packets with invalid IP/MAC bindings are received on untrusted ports, traps may be generated for the first port on the corresponding unit on which the invalid ARP packet is received.
wi01010916	QoS: Disabled but not deleted QoS policy data can impact resource utilization. Avaya recommends that you delete QoS policy data that is not required for long term configuration, as opposed to simply disabling the QoS policies. If you experience unexpected resource allocation issues and disabled QoS policies are present, the initial step towards alleviating the resource issue is to delete the currently disabled QoS policies
wi01020873	IGMPv3: IGMPv3 traffic is doubled when port mirroring is configured to mirror the mrouter port on the L2 device (with IGMPv3 snooping enabled) on which the IGMP receiver is connected. You may experience this issue with port mirroring modes: Xrx, XrxOrXtx, manytoOneRx, manytoOneRxTx.

Change Request number	Description
wi01028901	L2, SMLT: On stacks that are involved in IST configuration with the IST links being VLACP enabled with a short time-out value, VLACP brings down the IST during the stack formation process due to lack of VLACPPDUs received. After the rebooted stack is formed again, the IST recovers as soon as VLACPPDUS are received. Workaround: Set a timeout-scale timer value larger than 6.
wi01030591	EDM, QoS statistics : When using QoS statistics for Traffic Profile from EDM, EvalOrder will not be correctly shown on ports from non-base units if the same Traffic Profile set uses multiple eval orders (non block configuration). QoS statistics work as expected on ports from the base unit.
wi01030811	Filter Limiting: Settings made while filter limiting is disabled (more protocol filter entries) are not seen when filter limiting is enabled (fewer protocol filter entries), but the entries are retained. When filter limiting is subsequently disabled and the switch/stack is rebooted, these retained entries will be activated unless changes made while filter limiting was enabled have created conflicts with the retained entries. You do not typically need to switch between settings. If you do, and at the same time you are changing the protocol VLANs, you need to exercise caution or the results when filter limiting is disabled may not be as expected. Changes made while filter limiting is enabled will override those that are retained in the expanded protocol filter list.
wi00946819	Port name is limited to 64 characters in both ACLI and EDM.
wi01004362	Security 802.1X EAP: In a scenario where an IP Phone and a PC behind the phone are connected into an EAPOL multihost enabled port and only the IP Phone is successfully authenticated, starting a ping over IPv6 into the system's management VLAN's IPv6 address will succeed even if the PC is not successfully authenticated. However, all other IPv4 and IPv6 traffic not destined for the switch will be dropped.
wi00945013	SNMP: SNMP inform traps are not generated correctly by the switch (both header and PDU variable bindings) and will fail to be interpreted by the receiving SNMP trap daemon host.
wi00962526	AAUR: When carrying out the AAUR process in a pure Waverunner stack, the message <code>NVR CFG - Could not acquire FLASH sem</code> will be registered throughout all units of the stack. There is no impact on the AAUR process which will be successful.
wi00925548	DecOtherEther2, Filter Limiting: When Filter Limiting is disabled and configured to use additional filter slots (beyond 7), the saved ASCII configuration will include the additional VLANs which are defined using the extended filter slots. If a switch/stack is reset to defaults, it will come up with Filter Limiting enabled and will now be limited to 7 filter slots. VLANs which are defined for the additional slots will fail to be configured on the switch. The use of a DecOtherEther2 protocol VLAN will fail since it requires 10 protocol slots. If a configuration is using the slots

Change Request number	Description
	provided by disabling filter limiting, you must disable filter limiting via ACLI and reboot the switch/stack before applying the ASCII configuration so that it is operating in the Filter Limiting disabled mode.
wi00930131	SLPP Guard: The ACLI command <b>no slpp-guard</b> disables slpp-guard on a specific port ( <b>no slpp-guard port X enable</b> ) or disables the auto re-enable timeout <b>no slpp-guard port X timeout</b> . If neither parameter is specified ( <b>enable</b> or <b>timeout</b> ), both settings will be disabled, i.e. slpp-guard is disabled and the timeout set to 0 on the specified port(s).
wi00987107	EDM, Rate Limiting: When configuring rate-limit settings for switch ports using EDM, setting pps or percent for either the broadcast or multicast traffic type will trigger the both parameter to apply for the port selection.
wi01016205	When initiating an eapol init on a port with authenticated EAPOL users that have associated DHCP-clients leases that populate the dhcp-snooping binding table, users will be de-authenticated but former entries may still populate the dhcp-snooping binding table. You can issue a manual clear mac-address table command.
wi00945962	VRRP: If you encounter the message <code>% Not enough HW resources available when enabling VRRP, try again after a 30 second interval.</code> This may result from high CPU utilization.
wi01030857	MAC Security, EDM: The MAC-Security "MacViolation" tab from EDM will not list any intruder mac-addresses as expected.
wi00973591	Even though the image has been downloaded successfully and the continuous ping was not interrupted the following messages are displayed intermittently : <code>Request time out!</code> The connection with the device may be lost or the device may be down.
wi00974433	RADIUS key for secondary servers (GRS/ERS/NRS) is deleted when defaulting primary server. Is recommended to use "no radius server host" instead of "default radius server host". This way, if a secondary server is configured, the key will remain in use for that secondary server.
wi00973591, wi00975529	RADIUS dynamic server clients statistics may not be seen when using EDM Offbox.
wi00978991	EDM, BGP: When creating a community list or As path list from EDM, with member id greater than 10, the list will not be displayed correctly from EDM.
wi00984496	EDM System up-time: Stack info uptime seen from EDM does not display uptime for non base units.

Change Request number	Description
wi00993182	EDM, LACP: In EDM, sorting the trunks in the Vlan->MLT/LACP section is possible only for the MLT tab.
wi01005364	DHCP, reboot: After reboot, DHCP requests from client pass the switch port before MAC authentication(radius-request) starts. The device receives an IP address of the Guest VLAN , even if the client is eventually authenticated and moved to initial / radius vlan .This scenario is reproducible only when clients are simulated by traffic generators; the issue is not reproducible in a real case scenario ( client = PC / IP Phone )
wi01013703	EDM, IST: IST may not be enabled when EDM is used. Workaround: Enable IST from ACLI.
wi01018390	COM: The following message is displayed, even though the connection is not lost. Request time out! The connection with the device may be lost or the device may be down.
wi01021894	LLDP: In version 6.3, the LLDP default settings for lldp tx-tlv and lldp tx-tlv med have been changed to enabled. In prior releases, the default setting for LLDP was disabled. These settings only apply when the switch is defaulted or the default LLDP setting is applied. When upgrading from a previous version, the configured LLDP settings will be retained.
wi01022549	When the device reaches a situation in which it sends out an ICMP Destination Unreachable message through a specific port, the icmpOutDestUnreachs.0 counter should be increment each time such a message is sent. Currently this counter is not incrementing properly so it is best to rely on capturing such packets if required for a traffic statistic.
wi01024984	The error message % TFTP server address has not been set is intermittently displayed for the command configure network.
wi01027416	SNMP: The error message commit failed is returned when a user tries to disable the STG of the management VLAN using SNMP .
wi01027752	Multicast traffic might be lost after maximum of multicast routing entries(992(*,G)and(S,G)) are learned on WR stacks.
wi00931239	EDM, Rate-limit: When configuring rate-limit from EDM on a multiple port selection, desired values may sometimes not be applied as expected. The same options can be set from ACLI.
wi00980212	OSPF, MAC security: Avaya recommends you do not use MAC security on OSPF enabled links on 5520 and 5530 units.
<b>Known Issues from Release 6.2</b>	

Change Request number	Description
wi00484542	<p>In an NSNA setup, you may experience temporary loss of NSNA functionality when UDP forwarding has approached maximum capacity. Workaround: Configure a filter on the port that connects to the SNAS (or depending on your configuration, on the port connected to the switch that, in turn, connects to the SNAS) to isolate NSNA SSCP traffic received by the CPU.</p> <p>Use the following CLI commands to configure a filter:</p> <pre> qos ip-element &lt;element_id&gt; src-ip &lt;ip_address/mask&gt; qos classifier &lt;value&gt; set-id &lt;value&gt; element-type ip element-id &lt;value&gt; qos action &lt;value&gt; update-lp &lt;value&gt; qos policy &lt;value&gt; port &lt;port_list&gt; clfr-type class clfr-id &lt;value&gt; in-profile-action &lt;action_id&gt; prec &lt;value&gt; </pre>
wi00486677	<p>It may take more time than usual for traffic to re-converge (approximately 10 seconds) if a stack from the core is rebooted in a highly scaled SMLT configuration (100 VLANs).</p>
wi00494404	<p>Port mirroring mode XrxYtx on a 56XX device does not mirror broadcast, multicast and unknown unicast traffic if the X and Y mirrored ports are in different MLTs.</p>
Q01979384-01	<p>HTTP connections are not displayed by the <b>show ipv6 tcp connection</b> command.</p>
wi00486821	<p>The <b>show ip ospf neighbor detail</b> command that provides detailed information for OSPF LSDB should not be run when the terminal length is set to 0.</p>
Q02004055	<p>There is currently no command to disable the <b>metric</b> and <b>route-type</b> options for the <b>route-map &lt;route_name&gt; match</b> command and no command to disable the <b>ip preference</b>, <b>metric</b>, and <b>metric-type</b> options for the <b>route-map &lt;route_name&gt; set</b> command.</p>
wi00494595	<p>Specifying a range of ports for non-base units using the <b>poe poe-shutdown port X</b> command may cause IP Phones connected to those ports to remain powered on in some stack configurations.</p>
wi00486898	<p>Wait twice the configured MAC aging time after swapping two PCs behind 2 phones in an NSNA solution before plugging the PCs back in behind the phones.</p>
wi00494935	<p>If the UBP set is configured and the QoS agent is disabled when an EAP / Non EAP user authenticates, several log messages displaying <b>QoS support is currently disabled</b> will be produced.</p>

Change Request number	Description
wi00487438	OSPF: Even though two LSA packets are sent (one with unicast destination address and one with multicast destination IP) only one LS ACK transmitted packet appears in the interface statistics table.
Q02056133-02	EDM: to enable or disable EDM access use ACLI commands <b>web-server enable</b> or <b>web-server disable</b> .
wi00495084	STP is re-enabled when moving SMLT ports from 1 STG to another.
wi00484360, wi00487405, wi00497106, wi00554983	Stacking: When you copy a binary configuration to an TFTP server, you may receive an <i>Intra-stack communication failure</i> message. This does NOT indicate a stack failure; it indicates that the command failed. <b>Workaround</b> : : If you receive the <i>intra-stack communication failure</i> message, execute the <b>copy binary</b> command until it succeeds.
wi00495158	In the SMLT network, loop may be temporarily introduced on LACP-over-SMLT port. In order to prevent loop from happening it is required to configure all LACP-over-SMLT port in "Lacp Advance mode". Under this mode, LACP port stays in Blocking mode until it receives the first LACP PDU from its partner port. In 6.2 release, it is the user's responsibility to put all LAC-over-SMLT ports in "Lacp Advance Mode.
wi00488453	Do not see the ability to set Forced Stack Mode via the EDM interface.
wi00495698	SFPs: To ensure a proper match of the remote side, before you install an SFP set shared ports to auto-negotiate. Refer to ACLI: default speed and default duplex
wi00495332	IPv6 Tunnel over IPv4 operational status is determined by combination of IPv6, IPv4 forwarding, and VLAN status. The IPv6 tunnel operational status is ACTIVE if IPv6, IPv4 forwarding is enabled and the VLAN status to which source IPv4 tunnel end point is UP (i.e. at least one port on VLAN is connected). Operational status ACTIVE does not indicate the liveliness or reachability of IPV4 remote tunnel end point.
Q02089575	Supported capabilities in Ethernet Routing Switch 5000 Series switches, the maximum supported PIM-SM entries should state up to 492 for 55xx Switches and up to 992 for 56xx Switches - not 500 and 1000.
wi00484056, wi00487793, wi00497158	TDR: Run TDR tests only for ports with Link Status UP.
wi00484096, wi00488154, wi00497196	<code>show running-config defaults</code> When you execute the <code>show running-config defaults</code> or <code>show running-config default specific</code> commands the system may take up to 4 minutes to return results, depending on the complexity of the system: for

Change Request number	Description
	example, an 8-high stack fully configured. This is considered normal behavior.
wi00496125	The old RSTP Traps command is hidden (this means is not displayed when question mark is given and the command is not autocompleted when hitting TAB). Use the new commands found under 'snmp-server notification-control'. You can obtain a list of the current notification traps available using 'show snmp-server notification-control'.
wi00487670	IPv6 DHCP Relay does not support Remote ID parameter (RFC 4649) in this release.
wi00488121	EDM, RATE LIMITING: Multiple port configuration for Rate Limiting may not work properly; the change allow rate of broadcast or multicast may produce an incorrect result. WORKAROUND: Use ACLI to configure Rate Limiting.
wi00495711	In Lossless mode, when oversubscription exceeds 10 ports to 1 port, ingress ports must be spread across groups of 24 ports.
wi00496306	Energy Saver: When energy saver is activated or deactivated, the link on a port briefly transitions. This causes some devices to re-acquire connectivity. For copper uplink ports or critical devices, it is recommended to disable energy saver at the port level.
wi00496308	EAP authentication will be restarted on copper ports when Energy Saver transitions to active or inactive state. This occurs because Energy Saver is clearing the MAC address on the EAP client port when transitioning to the active or inactive state. EAP fiber port status does not change when Energy Saver is activated or deactivated.
wi00496309	NEAP authentication is restarted on copper ports when Energy Saver transitions to active or inactive state. This occurs because Energy Saver transition clears the MAC address on the NEAP client port. NEAP fiber ports EAP status does not change when Energy Saver is activated or deactivated
wi00487721	PORT MIRRORING: Port mirroring will mirror pruned multicast streams to the monitor port. However, the streams are not actually sent to the device because they are pruned.
wi00555143	Upgrade: All trap notifications are enabled after you upgrade to R6.2.0 software, regardless whether you disabled them prior to the upgrade. For procedures to restore trap functionality, see <a href="#">Trap restoration and reconfiguration after upgrade to Release 6.3</a> on page 50.
wi00496317	ROUTING, DEFAULT GATEWAY: If you enable and disable routing globally on the management VLAN the default gateway may not work. In R6.2 you can configure the switch with default gateway (using the command <code>ip default-gateway &lt;next-hop&gt;</code> or default route (using the command <code>ip route 0.0.0.0.0.0.0.0 &lt;next-hop&gt;</code> ).



Change Request number	Description
	<p>When IP Routing is disabled (Layer 2 mode) on the switch, the default gateway serves as the default route, that is the default gateway shown by the <b>show ip</b> command.</p> <p>When IP Routing is enabled (Layer 3 mode) on the switch, the default route specified is used, that is the 0.0.0.0 route shown by the <b>show ip route</b> command.</p> <p>You can enter up to 4 static routes, management static routes, to be used for management traffic only. These routes are used in software routing only and do not affect pure data plane traffic.</p> <p>SOLUTION: You must enable routing on the management VLAN to activate management static routes which you can use for separation of management and data traffic.</p>
wi00488714	LLDP MED NETWORK POLICIES: You cannot assign custom DSCP values to Avaya 1120E IP Deskphones using LLDP MED network policies.
wi00491740, wi00496258, wi00498185	It is recommended that you use SNMPv3 to achieve security, instead of using SNMPv1 and/or SNMPv2c with community strings.
wi00554875, wi00555204, wi00555283	802.1ab MED: Both LLDP MED and ADAC policies are supported on the same port. If both types of policies are created on the same port and you delete the LLDP policy you created, then the ADAC policy is also deleted.
wi00554955	IPv6 Static Routes: In an IPV6 setup where static and backup static routes exist, if you disable the IPV6 routing on a neighbor next-hop router, the active route will remain active until ARP for the next-hop expires or until a neighbor solicit message is forced (ping, clear neighbor, clear neighbor mac address) or until you execute shutdown/noshutdown on the respective interface.
Q02149708	Energy Saver: You must not select fiber ports when you use the Multiple Port Configuration menu to enable Energy Saver on a range of ports.
Q02150634	AUR/DAUR: The reboot process can take approximately 3 minutes to complete, after which the normal CLI commands will display the AUR status.
wi00555132	AUR, LICENSING: After you perform automatic unit replacement (AUR) of a base unit, if the MAC address of the new unit introduced into the stack was not part of the original license, then, when you reboot the stack and execute the ACLI command <b>show license all</b> , the output displays that 0 licenses are present. WORKAROUND: Licenses

Change Request number	Description
	will be operational, or can be enabled, and you can verify the license state using the following ACLI commands: <ul style="list-style-type: none"> <li>• <b>show license all verbose</b> to check whether any bit is set in the License Vector in Use data</li> <li>• <b>show sys-info</b>: the Operational license field shows the current license state</li> <li>• <b>show system verbose</b>: Operational license field shows the current license state</li> </ul>
wi00933491	802.1AB MED network policies: Avaya IP phones may not apply LLDP MED network policy configurations received from the switch on older phone firmware versions.
wi01008592	LLDPDU and TLV error handling: in the scenario where you have a large number of VLANs configured and dot1 port-protocol-vlan-id and vlan-name TLVs are enabled, TLVs may not be transmitted. With the maximum size of an LLDPDU packet at 1518 bytes, some TLVs such as dot3, MED, and vendor specific Avaya TLVs may not be sent.
wi00934940	LLDP Integration: on the Avaya IP phones, the Current Conservation parameter is not set according to the PoE conservation level request TLVs.

---

## Trap restoration and reconfiguration after upgrade to Release 6.3

Use the procedures in this section to restore and reconfigure trap functionality after you upgrade to Release 6.3 software. You can reconfigure trap notification, using either EDM or ACLI.

---

### Restoring trap notification functionality using ACLI

#### About this task

Use the following procedure to restore trap notification functionality using ACLI:

#### Procedure

Use the following ACLI command to remove traps created using R6.1 and before: `no snmp-server host X.Y.Z.T 'community name'`

---

## Reconfiguring traps using EDM

### About this task

Use the following procedure to reconfigure traps using EDM:

### Procedure

1. From the navigation tree, click **Edit**.
  2. From the Edit tree, click **Snmp Server**.
  3. In the work area, select the **Community** tab.
  4. Create a community string - you must specify the Notify View name.
  5. In the work area, select the **Host** tab to create an SNMP host - use the community you created in the previous step.
  6. On the **Host** tab, use the **Notification** button to activate or deactivate individual traps.
  7. In the work area, select the **Notification Control** tab to activate or deactivate individual traps per device.
- 

---

## Reconfiguring traps using ACLI with v1 host example, password security enabled

### About this task

Use the following procedure to reconfigure traps using ACLI - v1 host example with password security enabled:

### Procedure

1. To create a community, from the Global Configuration prompt, enter the following command:  

```
snmp-server community notify-view nncli
```

Enter community string: CommunityName  
Enter community string: CommunityName
  2. To create an SNMP host using the community you created in the previous step, from the Global Configuration prompt enter the following command: `snmp-server host 10.100.68.3 port 162 v1 CommunityName filter TestFilter.`
-

---

## Reconfiguring traps using ACLI with v1 host example, password security disabled

### About this task

Use the following procedure to reconfigure traps using ACLI - v1 host example with password security disabled:

### Procedure

1. To create an SNMP community, from the Global Configuration prompt, enter the following command: `snmp-server community CommunityName notify-view nncli.`
  2. To create an SNMP host using the community you created in the previous step, from the Global Configuration prompt enter the following command: `snmp-server host 10.100.68.3 port 162 v1 CommunityName filter TestFilter.`
- 

---

## Setting the Notification Type per receiver using ACLI

### About this task

Use the following procedure to set the Notification Type per receiver using ACLI.

### Procedure

1. From the Global Configuration prompt, enter the following command: `snmp-server notify-filter TestFilter +org.`
  2. From the Global Configuration prompt, enter the following command: `snmp-server notify-filter TestFilter -linkDown.`
  3. From the Global Configuration prompt, enter the following command: `snmp-server notify-filter TestFilter -linkUp.`
-

---

## Displaying Notification Types associated with the notify filter using ACLI

### About this task

Use the following procedure to display the Notification Types associated with the notify filter using ACLI.

### Procedure

From the Global Configuration prompt, enter the following command: `show snmp-server notification notify filter`

---

---

## Enabling or disabling the Notification Type per device using ACLI

### About this task

Use the following procedure to enable or disable the Notification Type per device using ACLI.

### Procedure

1. From the Global configuration prompt, enter the following command: `no snmp-server notification-control linkDown`.
  2. From the global Configuration prompt, enter the following command: `no snmp-server notification-control linkUp`.
- 

---

## Preventing a loop during upgrade of a large network

### About this task

Use the following procedure to prevent a temporary loop during upgrade of a large network.

### Procedure

1. Shut down LAC/SMLT ports on system A.
2. Download the new software image to system A.
3. Enable LAC/SMLT ports on system A.
4. Shut down LAC/SMLT ports on system B.

5. Download the new software image to system B.
6. Enable LAC/SMLT ports on system B.

## Ethernet Routing Switch 5000 Series limitations and considerations

The following table lists known Ethernet Routing Switch 5000 Series limitations and considerations:

**Table 5: Ethernet Routing Switch 5000 Series considerations**

Item	Description
1	Some terminal programs can cause the Console Interface to crash if you enter a RADIUS secret containing the character "k". The issue has been reproduced using Tera Term Pro (version 2.3), as well as Minicom (version 2.1) on a Linux system.
2	Avaya recommends that you avoid using MAC security on a trunk (MLT).
3	Failed attempts to log in (using TACACS+ authentication and accounting) are not stored in the accounting file.
4	When switches are in MSTP mode and connected using a trunk (MLT), and at least one MSTI is configured, the switch can return an incorrect STPG root if you change the mode to STPG and reset the switches.
5	When you use the EDM/Web to configure and add VLAN ports to an STG other than the default STG, STG membership of the port may change. In that case, the new STG participation of that port will be disabled. WORKAROUND: Enable participation of the ports in the new STG after you enable the STG.
6	While downloading the image file, you may receive the following error message: "Error reading image file." WORKAROUND: Typically, this issue can be resolved by simply restarting the image download. If this does not resolve the issue, Avaya recommends that you try an alternate method to download the image to the switch (that is, the Web Interface).
7	The IPFIX sampling data rate cannot be changed because of a related hardware limitation.
8	Release 5.1 introduced a Demo License to enable OSPF, ECMP, VRRP, SMLT, and IPFIX for a period of 30 days. The trial license expires at the end of the 30-day period and the features, except SMLT, are disabled. The system sends traps advising of license expiration but SMLT remains enabled until the stack or unit is reset.

Item	Description
	<p>Avaya recommends that, when you receive the first trap, the administrator begins to manually disable SMLT and ensure removal of any cabling loop. Because Spanning Tree Protocol needs to be disabled and, because SMLT is implemented through cabling, SMLT is not disabled with the other features because a network loop would form. After demo license expiry, when the stack or unit is reset, SMLT is disabled and a loop will form if there has been no intervention to remove or disable the ports participating in the IST.</p> <p>Demo license expiry traps:            Five days prior to demo license expiry: bsnTrialLicenseExpiration: Trial license 1 will expire in 5 day(s).            One day prior to demo license expiry: bsnTrialLicenseExpiration: Trial license 1 will expire in 1 day(s).            At termination of demo license: bsnTrialLicenseExpiration: Trial license 1 has expired.</p>
9	Avaya recommends that you do not enable IP Source Guard on trunk ports.
10	Avaya recommends that you do not enable Critical-IP functionality with VRRP in an SMLT environment.
11	<p>Lossless Mode: Lossless activates in oversubscription scenarios even if rate-limiting is applied to certain ingress streams and slowing them is not necessary. Lossless gives fair access to bandwidth, meaning that if you have 3 ingress streams of 100% line rate competing on 1 egress port, lossless will slow down the sender transmit rates to a 33-33-33 percentage, and it does this by sending pause frames. If you have 2 streams coming in at 100% and a third at 20%, lossless will not interfere with this stream, the egress percentages will be 40-40-20. If the third stream transmit rate exceeds 33%, lossless will begin to apply to it as well. In this situation, if applying a meter to this stream, limiting it at under 33%, lossless doesn't activate and doesn't interfere. However, if the third stream is either broadcast or multicast traffic and a rate-limiting setting is applied instead of a meter, lossless will activate - it will send pause frames to the sender. The egress rate of the stream is not affected, it will be the one imposed by the rate-limiting setting, but the transmit rate will vary because of the pause frames.</p>
12	Lossless Mode: In Lossless buffering mode, if you use ingress traffic with queue 1 + ingress traffic with queue 2, and the egress port is on a different asic from ingress ports, QoS queue shaper may limit the bandwidth for queue 1 under the min-rate and egress traffic may be under the expected rates.
13	ARP Table Size for ERS 5600: The maximum number of entries in the ARP table is 4096.
14	MAC Filtering List: Release 6.3 of ERS 5000 increases the maximum number of entries in the MAC Filtering List to 128. More upper limit testing is required.
15	Inexistent VLAN Mapping for MSTI: EDM/SNMP support for VLAN Mapping for MSTI is not available in Release 6.3.
16	In Release 6.3, the LLDP default settings for lldp tx-tlv and lldp tx-tlv med have been changed to enabled. In prior releases, the default setting for LLDP was disabled. These settings only apply when the switch is defaulted or the default

Item	Description
	LLDP setting is applied. When upgrading from a previous version, the configured LLDP settings will be retained.
17	<p>You cannot enable MAC Security on LACP enabled ports. The following message displays:</p> <pre data-bbox="423 394 1352 485">%Cannot modify settings %MAC Security status cannot be modified. Disable LACP first.</pre>
18	<p>Rate Limiting: When you have the following scenario:</p> <ol data-bbox="423 590 1352 779" style="list-style-type: none"> <li>1. rate-limiting is performed at 10% (or by setting any percent value threshold)</li> <li>2. the speed ratio between the inbound port and the client port is 10:1 (for example 10Gbps inbound link and 1Gbps client port link)</li> <li>3. inbound broadcast or multicast traffic throughput on the inbound link is more than 10% link-rate speed</li> </ol> <p>then the client port will receive <math>0.1 * [\text{inbound traffic rate}]</math> and not the expected 1Gbps broadcast or multicast traffic.</p> <p>Example:</p> <ul data-bbox="423 909 1352 1014" style="list-style-type: none"> <li>• inbound port link rate = 10Gbps , client outbound link rate = 1Gbps , rate limiting set to both at 10%</li> <li>• inbound traffic rate = 3Gbps broadcast traffic</li> </ul> <p>The actual client traffic received rate = 333Mbps and not the expected 1Gbps</p>
19	In a stack configuration, SSHC configuration options are only available from the base unit
20	<p>When you manually create an LLPD MED network policy, LLDP checks that the specified VLAN ID corresponds to a voice VLAN created inside the VLAN application. If the VLAN is not a voice VLAN or the VLAN does not exist, the switch displays a warning message. The switch creates the policy even if the VLAN is not voice enabled or does not exist. The switch may display one of the following messages:</p> <pre data-bbox="423 1360 1352 1493">% Policy will be set on port x with vlan-id of a non-existent vlan y % Policy will be set on port x member of the non-voice vlan y</pre>

---

## VLACP issue

In some situations, when you use VLACP the ERS 5000 series switches remove a link from service due to variations in the arrival time of VLACP messages (VLACP PDUs) from the far end. The issue can exist between the ERS 5600 models and ERS 8300 and ERS 8600 models when the system runs short timers with a default timeout interval of 3 time-outs or less. The



ERS 5600 switches maintain a rolling history of the last 3 received VLACP PDUs (by default) and calculate the time variance across and between these VLACP messages.

SOLUTION: Increase the VLACP timeout-scale value to 3 or more.

---

## Filter resource consumption

Applications consume filter resources, which are a combination of masks and filters, also known as rules.

A filter specifies the bit pattern to match.

A mask specifies the bit position to match and the evaluation precedence of the filters.

To enable some applications, for example BaySecure, Port Mirroring, and IGMP, a set number of masks and filters are required.

The following table summarizes the applications that require mask and filter resources.

**Table 6: Application mask and filter resource requirements**

Application	Category	Masks required	Filters required
Ethernet Routing Switch 5600 Series			
Broadcast ARP and ARP Inspection	Non QoS	1	1
DHCP Relay or DHCP Snooping	Non QoS	1	2
QoS (default untrusted policy)	QoS	2	2
QoS (DAPP with status tracking)	QoS	1	1
QoS (Auto QoS)	QoS	1	4
Port Mirroring (MAC-based)	Non QoS	1	2
EAP Authentication (EAPoL packet filter)	Non QoS	1	2
IPFIX	Non QoS	1	1
ADAC	Non QoS	1	1
RIP	Non QoS	1	1
UDP Broadcast	Non QoS	1	1

Application	Category	Masks required	Filters required
BGP (ERS 5600 only)	Non QoS	1	2
VRRP	Non QoS	1	2
OSPF	Non QoS	1	2
Content Based Forwarding (ERS 5600 only)	Non QoS	1	1
IP Source Guard	Non QoS	1	11
PIM	Non QoS	1	1

On the ERS 5600 Series switches the resources are shared across groups of ports. For each group of ports there 16 masks and 256 filters available for each mask. By default, the system consumes 2 masks and 2 filters for ARP filtering and DHCP relay on all ports, leaving 14 masks available for each group and 254 filters available for each mask and group for QoS and other non QoS applications to configure dynamically.

You can use the `show qos diag` command to assess the current filter resource usage for each port on ERS 5000 Series switches.

The `show qos diag` command displays the number of QoS masks and filters and non QoS masks and filters consumed on each port. You can determine whether an application that requires filter resources can be enabled on a port by verifying that the number of available masks and filters meets the mask and filter requirements of the application.

On the ERS 5600 Series switches, you can count the unused masks to determine the number of available masks for a port by using the output of the `show qos diag` command. The ERS 5600 Series switches share resources across a group of ports. The filters used by QoS or non QoS applications on a port for a specific mask determine the available filters for that mask for all ports from that group.

On the ERS 5600 Series switches, you can determine the number of filters available for a mask from a group of ports by adding the total number of QoS and non QoS filters in use and subtracting that number from 256. If the number of filters in use for a mask equals 256, you cannot use that mask on other ports from the same group.

**Example - IP Source Guard on an ERS 5600 Series switch port**

On ERS 5600 Series switches you need 1 mask and 11 filters to enable IP Source Guard on a port. When you view the `show qos diag` command output you see that port 5 is currently using a total of 4 masks. IP Source Guard uses the next available mask and, from the command output, you can see that there are 256 filters available for mask 14. So you can enable IP Source Guard.

## Flow Control

The default value for flow control is asymmetric/asymm-pause-frame (forced settings / autonegotiation advertisement). When upgrading from an older software version (that had symmetric as default), the symmetric/pause-frame settings are changed to asymmetric/asymm-pause-frame.

### Example

Disabling flow control when autonegotiation is enabled:

```
ERS>enable
ERS#configure terminal
ERS(config)#interface ethernet 7-8
ERS(config-if)#auto-negotiation-advertisements port 7 1000-full
ERS(config-if)#show auto-negotiation-advertisements port 7-8
Port Autonegotiation Advertised Capabilities
-----
7                               1000Full
8    10Full 10Half 100Full 100Half 1000Full           AsymmPause
ERS(config-if)#show interfaces 7-8
          Status      Auto
Port Trunk Admin Oper  Link Negotiation  Speed Duplex Control
-----
7                               1000Full           AsymmPause
8    10Full 10Half 100Full 100Half 1000Full           AsymmPause
ERS(config-if)#show interfaces 7-8
          Status      Auto
Port Trunk Admin Oper  Link Negotiation  Speed Duplex Control
-----
7                               1000Full           AsymmPause
8    10Full 10Half 100Full 100Half 1000Full           AsymmPause
```

Enabling asymmetric flow control when autonegotiation is enabled:

```
ERS>enable
ERS#configure terminal
ERS(config)#interface ethernet 7-8
ERS(config-if)#auto-negotiation-advertisements port 7 1000-full asymm-pause-frame
ERS(config-if)#show auto-negotiation-advertisements port 7-8
Port Autonegotiation Advertised Capabilities
-----
7                               1000Full           AsymmPause
8    10Full 10Half 100Full 100Half 1000Full           AsymmPause
ERS(config-if)#show interfaces 7-8
          Status      Auto
Port Trunk Admin Oper  Link Negotiation  Speed Duplex Control
-----
7                               1000Full           AsymmPause
8    10Full 10Half 100Full 100Half 1000Full           AsymmPause
```

Disabling flow control when autonegotiation is disabled:

```
ERS>enable
ERS#configure terminal
ERS(config)#interface ethernet 7-8
ERS(config-if)#duplex port 7-8 full
ERS(config-if)#flowcontrol port 7-8 disable
ERS(config-if)#show interfaces 7-8
          Status      Auto
Port Trunk Admin Oper  Link Negotiation  Speed Duplex Control
-----
7                               1000Full           AsymmPause
8    10Full 10Half 100Full 100Half 1000Full           AsymmPause
```

Enabling asymmetric flow control when autonegotiation is disabled:

```
ERS>enable
ERS#configure terminal
ERS(config)#interface ethernet 7-8
ERS(config-if)#flowcontrol port 7-8 asymmetric
ERS(config-if)#show interfaces 7-8
```

Port	Trunk	Admin	Oper	Link	Auto	Speed	Duplex	Flow
		Status			Negotiation			Control
7		Enable	Up	Up	Disabled	1000Mbps	Full	Asymm
8		Enable	Up	Up	Disabled	1000Mbps	Full	Asymm