Part No. 207101-C June 2000

4401 Great America Parkway Santa Clara, CA 95054

Release Notes for the BayStack 350/410/450 Management Software



Copyright © 2000 Nortel Networks

All rights reserved. June 2000.

The information in this document is subject to change without notice. The statements, configurations, technical data, and recommendations in this document are believed to be accurate and reliable, but are presented without express or implied warranty. Users must take full responsibility for their applications of any products specified in this document. The information in this document is proprietary to Nortel Networks NA Inc.

The software described in this document is furnished under a license agreement and may be used only in accordance with the terms of that license. The software license agreement is included in this document.

Trademarks

NORTEL NETWORKS is a trademark of Nortel Networks.

BayStack is a trademark of Nortel Networks.

Microsoft, MS, MS-DOS, Windows, and Windows NT are registered trademarks of Microsoft Corporation.

All other trademarks and registered trademarks are the property of their respective owners.

Introduction

This release note describes information that was not included in the *Reference for the BayStack 350/410/450 Management Software Operations* (Part number 201245-A).

Known Issues of Device Manager

The following are known issues that you may encounter when using the Device Manager version 4.0.0.

Multilink Trunks Specifics

When creating multilink trunks using Device Manager, click Apply in the VLAN > MLT dialog box to create the trunk and click Apply again to enable the trunk.

Base Unit Specifics

If the stack's base unit ID is any number other than 1, Device Manager incorrectly reports the base unit information as 1. If you have not assigned unit 1 as ID to any switch, Device Manager does not recognize the base unit information.

Resetting the Switch Stack

If you click Reset in Edit > chassis > Base Unit Info dialog box, Device Manager resets the base unit of the stack only. It does not reset the entire switch stack.