

Customer Release Notes

ExtremeCloud Appliance

Firmware Version V04.76.08.0006

December 18, 2020

INTRODUCTION:

The ExtremeCloud Appliance, the newest addition to the Smart OmniEdge portfolio, is a next generation orchestration application offering all the mobility services required for modern unified access deployments. The ExtremeCloud Appliance extends all the ease-of-use and simplified workflows of the ExtremeCloud public cloud application to on-prem/private cloud deployments. The ExtremeCloud Appliance includes comprehensive critical network services for wireless and wired connectivity, wireless device secure onboarding, distributed and centralized data paths, role-based access control through the Application Layer (Layer 7), integrated location services, and IoT device onboarding through a single platform. Built on field proven architectures with the latest technology, the embedded operating system supports containerization of applications enabling future expansion of value-added applications for the unified access edge.

The E3120 is a large application appliance meeting the needs of high-density and mission critical deployments with support for up to 10,000 APs/Defenders, 2000 switches, and 100,000 mobility sessions in high-availability mode. An optional redundant power supply is available for ordering separately.

The E2120 is an application appliance meeting the needs of medium sized high-density and mission critical deployments with support for up to 4,000 APs/Defenders, 800 switches and 32,000 mobility sessions in high-availability mode. An optional redundant power supply is available for ordering separately.

The E1120 is an entry to mid-level platform expandable to 250 APs/Defenders, 100 switches, and 4,000 mobility sessions in high-availability mode.

The VE6120 is an elastic virtual appliance that supports up to 1,000 APs/Defenders, up to 400 switches and 16,000 mobility sessions in high-availability mode depending on the hosting hardware.

The VE6120 and VE6120H offer elastic capacities to cover the full range of offering as VMWare/MS Hyper-V, ranging from VE6120/VE6120H-Small to VE6120/VE6120H-Large.

The VE6125 XL is a virtual appliance that supports up to 4,000 APs/Defenders, up to 400 switches and 32,000 mobility sessions in high-availability mode, depending on the hosting hardware.

The ExtremeCloud Appliance offers the ability to expand capacity to meet any growing business needs. The hardware and virtual packages are available for purchase using a traditional CAPEX model, while the adoption licenses are available as an annual subscription service in 5, 25, 100, 500 and 2000 managed device increments.

This Release includes all previous 4.36.xx.xxxx and 4.56.xx.xxxx enhancements and changes

Enhancements in 04.76.08.0006	I.D
Corrected issue with deploying L7 rules from the Extreme Management Center (XMC) Policy Manager.	ECA-2172
Removed the restriction where SNMP v3 user couldn't be saved when the password included the "&" character.	ECA-2259
Rectified "Client Distribution by Protocols" widget that incorrectly displayed wireless clients with protocol of "N/A".	ECA-2261
Improved shared memory handling and prevented creation of internal component's core files.	ECA-2265
Removed the condition where a mismatch of encryption key and a password caused issues with restoring config backup.	ECA-2266
Improved validation of External Captive Portal URL and prevented saving of incorrect configuration entry.	ECA-2301

Extreme Networks recommends that you thoroughly review this document prior to installing or upgrading this product.

For the latest firmware versions, visit the download site at:
www.extremenetworks.com/support/

FIRMWARE SPECIFICATION:

Status	Version No.	Type	Release Date
Current Version	V.04.76.08.0006	Maintenance Release	December 18, 2020
Previous Version	V.04.76.07.0003	Maintenance Release	October 27, 2020
Previous Version	V.04.76.06.0006	Maintenance Release	September 03, 2020
Previous Version	V.04.76.05.0009	Maintenance Release	July 07, 2020
Previous Version	V.04.76.04.0005	Maintenance Release	May 19, 2020
Previous Version	V.04.76.03.0015	Feature Release	April 20, 2020
Previous Version	V.04.76.02.0035	Feature Release	March 30, 2020
Previous Version	V.04.76.01.0081	Feature Release	February 11, 2020

SUPPORTED APPLIANCES, ACCESS POINTS AND SWITCHES:

Product Name	Image
ExtremeCloud Appliance VE6120 VMware Min Supported ESXi version 5.1 or later, (tested 6.7)	ECA-04.76.08.0006-1.dle
ExtremeCloud Appliance VE6120H (Windows server 2016 or later)	ECA-04.76.08.0006-1.spe
ExtremeCloud Appliance VE6125	ECA-04.76.08.0006-1.rse

Product Name	Image
Min Supported ESXi version 5.5 or later, (tested 6.7)	
ExtremeCloud Appliance E1120	ECA-04.76.08.0006-1.sme
ExtremeCloud Appliance E2120	ECA-04.76.08.0006-1.jse
ExtremeCloud Appliance E3120	ECA-04.76.08.0006-1.ose
Note: With v4.76.01, all adopted APs are adopted into Campus mode for Centralized Deployments.	
AP-7522-67030-1-WR AP-7522-67030-EU AP-7522-67030-US AP-7522-67030-WR AP-7522-67040-1-WR AP-7522-67040-EU AP-7522-67040-US AP-7522-67040-WR AP-7522E-67030-EU AP-7522E-67030-US AP-7522E-67030-WR AP-7522E-67040-EU AP-7522E-67040-US AP-7522E-67040-WR	AP7522-LEAN-7.3.1.4-003R.img
AP-7532-67030-1-WR AP-7532-67030-EU AP-7532-67030-IL AP-7532-67030-US AP-7532-67030-WR AP-7532-67040-1-WR AP-7532-67040-EU AP-7532-67040-US AP-7532-67040-WR	AP7532-LEAN-7.3.1.4-003R.img
AP-7562-670042-1-WR AP-7562-670042-EU AP-7562-670042-IL AP-7562-670042-US AP-7562-670042-WR AP-7562-67040-1-WR AP-7562-67040-EU AP-7562-67040-US AP-7562-67040-WR AP-7562-6704M-1-WR AP-7562-6704M-EU AP-7562-6704M-US AP-7562-6704M-WR	AP7562-LEAN-7.3.1.4-003R.img
AP-7612-680B30-US	AP7612-LEAN-7.3.1.4-003R.img

Product Name	Image
AP-7612-680B30-WR	
AP-7632-680B30-IL AP-7632-680B30-TN AP-7632-680B30-US AP-7632-680B30-WR AP-7632-680B40-TN AP-7632-680B40-US AP-7632-680B40-WR	AP7632-LEAN-7.3.1.4-003R.img
AP-7662-680B30-IL AP-7662-680B30-TN AP-7662-680B30-US AP-7662-680B30-WR AP-7662-680B40-TN AP-7662-680B40-US AP-7662-680B40-WR	AP7662-LEAN-7.3.1.4-003R.img
AP-8432-680B30-EU AP-8432-680B30-US AP-8432-680B30-WR	AP8432-LEAN-7.3.1.4-003R.img
AP-8533-68SB30-EU AP-8533-68SB30-US AP-8533-68SB30-WR AP-8533-68SB40-EU AP-8533-68SB40-US AP-8533-68SB40-WR	AP8533-LEAN-7.3.1.4-003R.img
SA201	AP391x-10.51.17.0006.img
AP310e-CAN AP310e-FCC AP310e-IL AP310e-WR AP310i-CAN AP310i-FCC AP310i-IL AP310i-WR	AP3xx-LEAN-7.3.1.4-003R.img
AP3912i-FCC AP3912i-ROW	AP391x-10.51.17.0006.img
AP3915e-FCC AP3915e-ROW AP3915i-FCC AP3915i-ROW	AP391x-10.51.17.0006.img
AP3916ic-FCC AP3916ic-ROW	AP391x-10.51.17.0006.img

Product Name	Image
AP3916-camera	AP3916IC-V1-0-14-1.dlf
AP3917e-FCC AP3917e-ROW AP3917i-FCC AP3917i-ROW AP3917k-FCC AP3917k-ROW	AP391x-10.51.17.0006.img
AP3935e-FCC AP3935e-ROW AP3935i-FCC AP3935i-IL AP3935i-ROW	AP3935-10.51.17.0006.img
AP3965e-FCC AP3965e-ROW AP3965i-FCC AP3965i-ROW	AP3935-10.51.17.0006.img
AP410e-CAN AP410e-FCC AP410e-IL AP410e-WR AP410i-CAN AP410i-FCC AP410i-IL AP410i-WR	AP4xx-LEAN-7.3.1.4-003R.img
AP460e-CAN AP460e-FCC AP460e-IL AP460e-WR AP460i-CAN AP460i-FCC AP460i-IL AP460i-WR	AP4xx-LEAN-7.3.1.4-003R.img
AP505i-FCC AP505i-WR	AP5xx-LEAN-7.3.1.4-003R.img
AP510e-FCC AP510e-WR AP510i-FCC AP510i-WR	AP5xx-LEAN-7.3.1.4-003R.img
AP560h-FCC AP560h-WR AP560i-FCC	AP5xx-LEAN-7.3.1.4-003R.img

Product Name	Image
AP560i-WR	
Switches	
210-12p-10GE2 210-24p-10GE2 210-48p-10GE2 210-12p-10GE2 POE 210-24p-10GE2 POE 210-48p-10GE2 POE	210-series_V1.02.05.0013.stk fp-connector-3.3.0.4.pyz (cloud connector)
220-12p-10GE2 220-24p-10GE2 220-48p-10GE2 220-12p-10GE2 POE 220-24p-10GE2 POE 220-48p-10GE2 POE	220-series_V1.02.05.0013.stk fp-connector-3.3.0.4.pyz (cloud connector)
X440G2-12t-10G4 X440G2-24t-10G4 X440G2-48t-10G4 X440G2-12t-10G4 POE X440G2-24t-10G4 POE X440G2-48t-10G4 POE	summitX-30.2.1.8-patch2-5.xos summitX-30.2.1.8-cloud_connector-3.4.1.8.xmod (cloud connector)
X620-16x	summitX-30.2.1.8-patch2-5.xos summitX-30.2.1.8-cloud_connector-3.4.1.8.xmod (cloud connector)

NETWORK MANAGEMENT SOFTWARE SUPPORT

Network Management Suite (NMS)	Version
ExtremeManagement™ Center	8.4 or higher
ExtremeControl™	8.4 or higher
ExtremeAnalytics™	8.4 or higher

Air Defense and Location	Version
ExtremeAirDefense™	10.3
ExtremeLocation™	3.1
ExtremeGuest	Version
ExtremeGuest™	6.0.1.0-001R

Note:

Platform and AP Configuration functions are not supported by ExtremeManagement™.

ExtremeCloud Appliance does not yet expose support for ExtremeLocation™ Calibration procedure. ExtremeLocation will work correctly for Zone and Occupancy level analytics but does not fully support

Position Tracking with this release. Enhanced support for Position Tracking will be added to a future release of ExtremeCloud Appliance.

INSTALLATION INFORMATION:

Appliance Installations	
E1120	ExtremeCloud Appliance E1120 Installation Guide
E2120	ExtremeCloud Appliance E2120 Installation Guide
E3120	ExtremeCloud Appliance E3120 Installation Guide
VE6120/VE6125	ExtremeCloud Appliance VE6120/VE6125 Installation Guide
VE6120H	ExtremeCloud Appliance VE6120H Installation Guide

PREVIOUS RELEASES EXTREMECLOUD APPLIANCE

Enhancements in 04.76.07.0003	I.D
Corrected ambiguous help message for CLI “dedicated scanner” command.	ECA-2182
Removed restriction that prevented users to create and use VLAN ID 1 ExtremeCloud Appliance.	ECA-2198
Increased appliance stability by improving memory handling within the RADIUS client component.	ECA-2199
Added explicit trust to DHCP server exchanges for Decentralized site WLAN profiles.	ECA-2231

Enhancements in 04.76.06.0006	I.D
Preserved value of self-generated NAS IP on upgrades.	ECA-1867
Corrected issue with inclusion of AP-hostname in AP beacon for AP3900 series.	ECA-1993
Corrected periodically displayed stale “last seen” time on Client Monitor screen.	ECA-2031
Improved appliance stability by preventing restarts of internal core component.	ECA-2041
Removed the condition that prevented addition of AP7662 to a device group.	ECA-2098
Rectified the problem that caused Samsung Galaxy A5, A8 and A10 connected to AP8432 to be shown as “Unknown” device.	ECA-2103
Enhanced robustness of appliance for handling internally generated policy references used in External captive portal. Incorrect references could lead to system instability.	ECA-2140
Corrected synchronization issue with low level QOS definitions for installations in a High-Availability configuration.	ECA-2154

Enhancements in 04.76.05.0009	
Corrected an issue where the AP name was not sent to Extreme Management Center or onboard reports for some events.	ECA-1210
Improved responsiveness for adding 1000s of MAC addresses to Policy Groups.	ECA-1231

Removed a delay of 15-20 seconds that was used when displaying error pages for Captive portal-based authentication.	ECA-1719
Addressed an issue with importing 2000 APs using Migration tool on VE6125.	ECA-1731
Removed the condition that shut down both radios on AP310 after certain config changed.	ECA-1739
Rectified false positive reporting of missing NTP server.	ECA-1817
Corrected a condition that caused unexpected AP rebooting following upgrade of a High-Availability pair.	ECA-1866
Addressed missing updates of Policy rule-hit counters for SA201.	ECA-1872
Fine-tuned discovery procedure to correct an issue where AP3915i wouldn't reconnect to the appliance.	ECA-1893
Improved calculation of traffic throughput and ensured that graph display is correct.	ECA-1914

Enhancements in 04.76.04.0005	
Addressed issue where platform not applying Roles based on client's identity.	nse0004425 / ECA-908
Addressed limitation whereby the Auto-Channel Selection (ACS) for AP3900 series only triggers if the access point is directly managed (adopted) by the appliance instance from which the ACS request is issued.	ECA-1605
Addressed issue where actions to "Retrieve Traces" using the graphical user interface failed for the EXOS switches.	ECA-461
Addressed issue where entering IPv6 address with notation 0:0:0:0:0:0:0:0 converts rule to IPv4 on Save action.	ECA-1681

Enhancements in 04.76.03.0015	
<p>Documented limits for importing Ekahau .SVG files. Documentation addresses issue where importing Ekahau map files results in ExtremeCloud Appliance hanging for a few minutes then logging you out.</p> <p>Please observe the following limits for importing of Ekahau model files:</p> <ul style="list-style-type: none"> -46 MB uncompressed .SVG files on physical appliances. -18 MB uncompressed .SVG files on virtual appliances. <p>Files larger than these limits will not import on the corresponding appliance as noted.</p>	ECA-1421
Addressed issue where Blacklist/Whitelist not working when network is on AP4xx.	ECA-1486
Addressed issue where client can't connect to a network with WPA3-Compatibility with PMF Required.	ECA-1496
Addressed issue where during creating a new network with auth type set to WPA3-Compatibility mode and setting the Protected Management Frames as Required.	ECA-1488
Addressed incompatibility between Defender for IOT Application (3.31) and ExtremeCloud Appliance 4.76.02.	ECA-1538

Enhancements in 04.76.02.0035

<p>Re-introduced support for Distributed site deployments through upgrade. Upgrade process grandfathers Distributed sites through upgrade from 4.56 release or configuration import.</p> <p>Settings and assignments for Legacy WiNG (AP75xx, AP76xx, AP8533/8432) or AP5xx models are preserved on upgrade. Grandfathering supports:</p> <ul style="list-style-type: none"> - Creation of new sites (per 4.56 adopted device set) - Adoption of WiNG Legacy or AP5xx devices to existing or new sites - Leveraging auto-adoption rules to Distributed Sites. <p>Caveats:</p> <p>AP4xx access points are supported in a Centralized site only. AP4xx will not adopt or extend a Distributed site.</p> <p>A fresh installation of 4.76.02:</p> <ul style="list-style-type: none"> - Does not support Distributed sites or adoption of Legacy AP models - AP5xx and AP4xx models adopt only to a Centralized site. 	<p>ECA-1150</p>
<p>Advanced Override option to manually adjust the WLAN assignment configuration per AP radio.</p> <p>Enables customer to adjust radio assignments for specific APs without adjusting the associated configuration Profile. Once overridden, the AP WLAN list is per specific assignment. Override is intended for diagnostics and temporary validation of network settings.</p>	<p>ECA-450</p>
<p>Site Assigned Adoption - You can override the global load balancing mode for AP adoption, in a High-Availability setup, for a specific Site. Site advanced configuration allows you to specify the appliance, in a High-Availability Pair, to which adopted access points will be homed (Primary Appliance or Backup Appliance). Unless overridden, the default global High-Availability mode (Active-Active or Passive-Active) setting prevails.</p>	<p>ECA-1152</p>
<p>Consistently use AP Name in Station Events (End-System) reports.</p>	<p>ECA-1154</p>
<p>Enhancements to Access Point and Client Views:</p> <ul style="list-style-type: none"> - Significantly expanded the list of available information for column display. - Introduced Query Builder utility that enables users to build complex, relational, multi-criteria filters. After executing a query, the distribution rendered is limited to elements returned by the query. - Introduced a new Visualize Column utility represents the values of a particular column as a pie chart. The pie chart displays a distribution of values based on a selected column. 	<p>ECA-1153</p>
<p>Support I-SID = 0 to support Fabric Attach Standalone Proxy mode on Extreme Networks Ethernet Routing Switches. Standalone Proxy mode indicates that the network does not include a Fabric Attach Server switch (and therefore does not include a Shortest Path Bridging Fabric Core).</p>	<p>ECA-964</p>
<p>Provide visual indication of ongoing upgrade operation for managed devices. Status displays blue icon during device upgrade process.</p>	<p>ECA-918</p>
<p>ExtremeWireless Migration Application is an add-on container application that facilitates migration from ExtremeWireless to ExtremeCloud Appliance. The tool provides a simple interface that allows users to provide a configuration archive for an ExtremeWireless (10.51+) controller. It will extract and import the following:</p> <ul style="list-style-type: none"> - AP Settings (including AP Name, Description, and radio settings) for AP39xx series access points. AP models not supported by ExtremeCloud Appliance will be ignored. - Policy/Role definitions - VLAN (Topology) settings. <p>Contact GTAC for help accessing the Migration Application.</p>	<p>ECA-585</p>

Redesigned appliance Copy Upgrade dialog, providing more intuitive representation of upload methods and enhanced warning of maximum capacity limits for upgrade image storage.	ECA-84
Update to the channel energy chart.	ECA-1344

Changes in 04.76.02.0035	I.D
Addressed issue where WiNG Proxy: Proxied site/AP not displayed after manually deleted from ExtremeCloud Appliance.	ECA-1199
Addressed issue where RADIUS - Server Status configuration is not applied properly.	ECA-1028
Addressed issue where upgrading the X440-G2 from the user interface is not supported in ExtremeCloud Appliance v4.76.01 revision. An upgrade to the latest image can be performed through the CLI.	ECA-1222
During upgrade of a High-Availability Pair configuration to 4.76.01, it is recommended to start the upgrade with the Secondary appliance.	ECA-1223
Addressed issue where channel occupancy widgets have been abstracted to Radio 1 and Radio 2 to better accommodated representation of dual-5.0GHz devices, such as the AP510/AP560. Older band specific widgets (2.4 GHz and 5.0 GHz) should not be used going forward. Those widgets will be removed in future product updates.	ECA-331
Improved logic on access points for Packet Capture function to address situations that impacted stability.	ECA-515
Addressed issue where after availability upgrade from 4.56 to 4.76, neither appliance was aware of the AP SW version on the AP page. Displays AP versions only after upgrading the APs to v7.3.0.	ECA-1217
Addressed issue preventing configuration of WPAv3-Personal. WPAv3-Personal privacy setting on a Network (SSID) will save correctly.	ECA-1220

Enhancements in 04.76.01.0081	
A new LED pattern mode "Normal - Solid" is available. The LED selection on the AP was adjusted to support this new mode, which is now the default mode for APs operating in Centralized Sites.	ECA-712
Support Adoption and Configuration of X465 Switch. VIM Modules are supported. Management through ExtremeCloud Appliance UI, does not support Extended Edge, Stacking or MLAG configurations.	ECA-647
Support for AAA Policy definitions: AAA Policy profiles provide a much more detailed configuration of parameters for authentication integration with third-party servers. AAA Policy profiles directly bypass the integrated <i>OnBoard</i> engine.	ECA-300
Expand definition for Called-Station-ID encoding for authentication integration with external RADIUS server. New formats include the ability to utilize general identifiers such as Site, City or Region as identifiers during user-authentication, facilitating simpler policy constructs for large installations requiring larger/coarse references.	ECA-300
The AP inventory report was added as a file into the Tech Support Archive.	ECA-639
Persist customer entered criteria. When user moves from AP or Client List view, to Details view, and back to List view, the criteria and filtering remain intact.	ECA-630
Enable "Minimize Impact Upgrade" as the default method for AP upgrades.	ECA-629
The auto-refresh period is now configurable from the user interface. Auto-refresh period is available for intervals of 30 seconds, 1 minute, 3 minutes, and 5 minutes. By default, auto-refresh is OFF.	ECA-628

All reports for managed devices and attached clients now provide a consistent experience for the Refresh action. The Refresh function is now included on all list pages, beside the Search field option.	ECA-627
Added support for Agile Multiband for the AP500 and AP400 series access points. Agile Multiband. Multiband Operation (MBO) is configured per network. MBO enables better use of WiFi network resources and improves the roaming experience. It allows the APs and stations to exchange information and facilitates efficient use of multiple frequency bands or channels that are available in the APs and the stations.	ECA-563
Provided the capability for Tech Support to include configuration and log files related to the Onboard server component.	ECA-562
Supported Adoption and configuration of AP400 series models: <ul style="list-style-type: none"> AP410i-FCC, AP410e-FCC, AP410i-WR, AP410e-WR, AP410i-CAN, AP410e-CAN, AP410i-IL, AP410e-IL AP460i-FCC, AP460e-FCC, AP460i-WR, AP460e-WR, AP460i-CAN, AP460e-CAN, AP460i-IL, AP460e-IL 	ECA-559
Provided the ability to adjust the Poll-Timeout via the RestAPI. The Poll-Timeout value can be set per Profile and on a per-AP override basis.	ECA-498
Enhanced granularity of access definitions for administrator accounts. Admin accounts now have granular control over what type of configuration elements can be edited or viewed.	ECA-451
The Adoption screen allows the user to manually assign a device (AP or Switch) to a specified site. The user is presented with the option to directly create the representative device group if one is not yet defined, or if the device needs a different assignment to better meet the use case.	ECA-296
Increased the size of a floor plan's geographic representation to 200,000m ²	ECA-678

Changes in 04.76.01.0081	I.D
Fabric attach VLANs was not supported as control VLAN for mesh networks. This issue was addressed.	ECA-578
Stability improvements for serving 802.1x and 802.11r services are included AP500 series image WiNG 7.2.1.1-06R. (Default AP image with this package). See Release Notes of 7.2.1.1-06R.	ECA-558
Reboot of the peer ExtremeCloud Appliance is required when availability is configured for the first time to ensure synchronization of configuration of ONBOARD attributes, such as Device Groups. This issue will be addressed in a subsequent release.	ECA-551
Corrected resource management issue with authentication library that could prevent administrative access to system's graphical user interface.	ECA-545
Removed limitation to 'AP Test' feature whereby it was only available for channels 1 and 36, for deployments of AP500 series as Extreme AirDefense sensor channels.	ECA-529
Corrected issue where generating tech support on All, Log, or Wireless AP, the output of the AP inventory would not include all the APs that are configured and the AP BSSIDs.	ECA-482
After switching from Whitelist mode to Blacklist mode, it's possible for the traffic from the blacklisted client not to be filtered and to be able to connect to different wireless networks and obtain Internet access. This issue has been addressed.	ECA-373

Changes in 04.56.07.0006	I.D
Updated UI behavior for AP MAC address field to allow selection of value, instead of just simply jump to AP record.	ECA-1174
Improved synchronization logic for statistics engine components to avoid possible representation of time series graphs with a 'saw' pattern.	ECA-1167
Updated floorplan logic to address issue with imported Ekahau models that contained references to 0 length lines, which could affect ability to save modifications such as boundary adjustments.	ECA-1166
Provided representation of connection uptime for APs in Distributed Sites.	ECA-1164
Improved session management logic to better account for re-associations of clients during the Hold-down time (30 secs) following the client's explicit DISCONNECT request from the network.	ECA-1133
Corrected logic bug with time range filtering in <i>Station Events</i> reporting.	ECA-1082
Adjusted configuration logic for Client Ports, such as AP7612, to ensure that traffic to client ports is always untagged, regardless of whether VLAN traffic is tagged on the AP's uplink port.	ECA-1016
Corrected issue preventing the definition of Customer Layer 7 rules for user access control.	ECA-975

Changes in 04.56.06.0013	I.D
Corrected issue for consistent display of BSSID for network assignments on APs.	ECA-1060
Improved error handling for End-System session re-sync operations to address and prevent possible cyclic race-conditions when addressing session state discrepancies.	ECA-1081
Corrected issue with handling of configuration for large channel widths that could result in the radio not starting correctly.	ECA-1065
Corrected issue with display of widgets for Top Sites by Channel Utilization/SNR charts displaying "Undefined".	ECA-1057
Improved resilience of UI server to better address possible delays on initial startup.	ECA-995
Corrected behavior to restart AP when management connectivity lost, and session persistence option is disabled.	ECA-972
Updated description of client Whitelisting behavior, especially calling out impact of empty lists.	ECA-971
Updated UI representation of Events to support custom column sizing.	ECA-927
Addressed logic flaw that could result in resetting of WLAN assignments to <i>Profiles</i> after modifications to network setting.	ECA-912
Improved consistency display of assigned RF Policy for Access Points for UI refresh.	ECA-879
Fixed a race condition, where RADIUS CoA-Request would not get ACK'ed by Controller while client is roaming to new AP.	ECA-807

Changes in 04.56.05.0005	I.D
Corrected an issue with the evaluation of policies pushed from PolicyManager for Distributed Sites.	ECA-856

Corrected column labeling for Access Point display to reflect radio ID instead of operational frequency band.	ECA-855
Hardened logic for IP Address reporting for RADIUS accounting to address possible "race condition" (when two events happen at the same time) when clients switch networks.	ECA-840
Corrected configuration option for AP500 series to enable AutoLogin Captive Portal detection by default.	ECA-764
Adjusted reporting of "Last Seen" timestamp for Clients to correspond with time of last status update vs presence in the session's table.	ECA-750
Improved handling and protection against possible corruption of client hostnames with non-printable characters, which could cause stats processing to stall.	ECA-699

Changes in 04.56.04.0009	I.D
Corrected issue affecting the reporting of statistics in Proxy mode for WiNG controllers with serial numbers different than 14 or 16 characters long.	ECA-760
Improved display of Max Transmit power setting to be scoped to regulatory allowed range of <i>Requested Channel</i> .	ECA-682
Enhanced configuration view of access points to display value of requested channel.	ECA-680
Improved efficiency of <i>Client</i> list views in the UI when rendering a larger number of clients.	ECA-751
Addressed issue with representation of Site status, for sites that only manage switches.	ECA-655
Corrected issue that was preventing column resizing for <i>Client</i> views.	ECA-686
Improved logic handling on Access Point management to protect against possible issues due to fragmented exchanges.	ECA-709
Corrected issue with offset index for interface ID in CTAlias SNMP table.	ECA-734
Addressed issue with client registration for ExtremeCloud Appliance extension of ExtremeWireless Inter-Access Controller mobility domain.	ECA-711
Adjusted default behavior for RADIUS Accounting Start to trigger after client obtains an IP address.	ECA-743

Changes in 04.56.03.0004	I.D
Addressed issue with Synchronization of Session Information across both HA peers, which could affect the ability of a client to roam across APs without re-authenticating when 802.11r configured.	ECA-656
Corrected UI display issue where IP mask and Default Gateway IP addressed for AP7632 may be reported as 0.0.0.0.	ECA-654

Known Restrictions and Limitations:

Known Restriction or Limitation	I.D
Reconfiguration of Link aggregation (LAG) may be needed after upgrade to 4.76.06.	ECA-1979
The names of Captive portal WLANs should be shorter than 29 characters. Longer names could cause upgrade failure and loss of configuration.	ECA-2175
To make NAS-IP identifier more deterministic, 4.76 changes the default behavior from using an internal topology bound interface (typically 127.x.x.x range) to referencing the IP address of the Admin port. If authentication policy in external servers is conditional on NAS IP address, you can transition to use a corresponding AAA policy	ECA-1867

Known Restriction or Limitation	I.D
and configuring the NAS IP to be reported as the same value as previously used with 4.56 (or earlier)	
AP310 models are not currently supported by ExtremeLocation(TM). Do not enable ExtremeLocation settings in the Profile configurations for AP310 device groups. Doing so may have a negative impact on AP performance.	ECA-1620
When AP510e works as dual band concurrent data forwarder - operation mode 1 – to avoid confusion it is recommended to disable group 2 antennas, port 5-8.	ECA-1074
The switch primary/backup availability is not supported on the EXOS switches running the 3.4.1.8 cloud connector. This affects the deployments where two XCAs are configured in availability pair. If the primary XCA is going down, then the EXOS switches will not send statistics to the backup XCA and will be marked in red "Critical" state. When the primary XCA is coming up again, then the switches will resume sending statistics information to the primary XCA and the state of the switch will be marked with a green "Running" state	ECA-455
Monitor Networks under Distributed Network, Meshpoint is missing Channel information. This problem will be addressed in a future release.	ECA-566
Editing or Deleting Control VLAN under the Mesh Network is not possible. This problem will be corrected into a future release.	ECA-573
Allow UTF-8 characters in JSON payload for all Rest API so non-ASCII / Unicode characters are accepted in Rest API requests to comply with current Rest API standards.	ECA-321
For ExtremeCloud Appliance installations configured for authentication of administrators over RADIUS server, the GUI responsiveness may be slow, possibly over 30 seconds, if target server(s) are unavailable/unreachable at login time. If outage is extensive, system will eventually timeout to validate against local credentials, if so provisioned.	ECA-1396
Policy rules applied to AP7632 users do not produce expected results. This issue will be resolved in a future release.	ECA-238
<p>For High-Availability installations, on systems configured with RADIUS Accounting or Smart RF enabled, clients (end-systems) may experience a momentary disconnect during the upgrade process (Maintenance Window).</p> <p>Users reconnect immediately back to the available infrastructure, so impact is negligible. For smoother Session Availability with Fast-Failover during a Failover event, it is recommended to not run these options at this time.</p> <p>This issue is being investigated and will be addressed in future releases.</p>	ECA-1264
GUI Mesh Report is missing the information about Root AP with Ethernet connection. This problem will be addressed in a future release.	ECA-565
Widgets do not show tooltips for Lower and Upper values. This issue will be addressed in a future release.	ECA-567
In Smart RF mode, the AP 510 power may drop to 0dBm and returns to 4dBm.	ECA-469
Upgrade failure will occur when using special characters (escape back slash) in topology.	ECA-466

Known Restriction or Limitation	I.D
Policy rules applied to AP7632 users do not produce expected results. This issue will be resolved in a future release.	ECA-238
<p>For High-Availability installations, on systems configured with RADIUS Accounting or Smart RF enabled, clients (end-systems) may experience a momentary disconnect during the upgrade process (Maintenance Window).</p> <p>Users reconnect immediately back to the available infrastructure, so impact is negligible. For smoother Session Availability with Fast-Failover during a Failover event, it is recommended to not run these options at this time.</p> <p>This issue is being investigated and will be addressed in future releases.</p>	ECA-1264
Allow UTF-8 characters in JSON payload for all Rest API so non-ASCII / Unicode characters are accepted in Rest API requests to comply with current Rest API standards.	ECA-321
For ExtremeCloud Appliance installations configured for authentication of administrators over RADIUS server, the GUI responsiveness may be slow, possibly over 30 seconds, if target server(s) are unavailable/un-reachable at login time. If outage is extensive, system will eventually timeout to validate against local credentials, if so provisioned.	ECA-1396
GUI Mesh Report is missing the information about Root AP with Ethernet connection. This problem will be addressed in a future release.	ECA-565
Monitor Networks under Distributed Network, Meshpoint is missing Channel information. This problem will be addressed in a future release.	ECA-566
Editing or Deleting Control VLAN under the Mesh Network is not possible. This problem will be corrected into a future release.	ECA-573
When AP510e works as dual band concurrent data forwarder - operation mode 1 – to avoid confusion it is recommended to disable group 2 antennas, port 5-8.	ECA-1074
Firmware for ExtremeWireless AP3900 series Access Points does not currently support Smart RF and therefore no Smart RF data is displayed.	ECA-1484
The switch primary/backup availability is not supported on the EXOS switches running the 3.4.1.8 cloud connector. This affects the deployments where two appliances are configured in an availability pair. If the primary appliance is going down, then the EXOS switches will not send statistics to the backup appliance and will be marked in red "Critical" state. When the primary appliance is coming up again, then the switches will resume sending statistics information to the primary appliance and the state of the switch will be marked with a green "Running" state.	ECA-455
Widgets do not show tooltips for Lower and Upper values. This issue will be addressed in a future release.	ECA-567
In SmartRF mode, the AP510 power may drop to 0dBm and returns to 4dBm.	ECA-469
Special Characters such as “ @ ; / \ ” I must not be used in configuration fields of ExtremeCloud Appliance, when configuring entities such as (AP, Topology, Site, Network, etc.). Some of those characters are treated as control or escape characters. Using special characters in text fields can result in problems when exporting the system configuration and lead to failures on configuration import, such as during a system upgrade.	Info ECA-466

Known Restriction or Limitation	I.D
<p>Recommendation settings for setup of redundant RADIUS server authentication:</p> <ol style="list-style-type: none"> 1) Response Window to 5s [Default: 20s] 2) Revival Interval to 10s [Default: 60s] 	<p>Info ECA-875</p>
<p>For High-Availability configurations, during upgrade phases or configuration restore operations, wait until the availability link is established and synchronized before attempting to make any new configuration changes. The Availability status will only re-establish to Synched status when both appliances are running the exact same firmware revision.</p> <p>During upgrade periods, the Availability link will only re-establish when both the appliance status of availability link and synchronization status can be found:</p> <ul style="list-style-type: none"> • "Network Health" widget on Dashboard • Administration -> System -> Availability 	<p>Info ECA-776</p>
<p>Deployment of appliances behind NAT is not officially supported. While configurations are available that enable this operation, this configuration is not validated by engineering. Therefore for installations requiring remote connectivity options, direct public address exposure is the recommended and officially supported configuration.</p>	<p>Info</p>
<p>Several old Intel clients (i.e. Intel dual band Wireless AC – 7260) if they are using old drivers are NOT seeing BSSID / SSID advertising 11x capability. This is a client issue (forward compatibility). Other older clients may have this issue.</p> <p>See: https://www.intel.com/content/www/us/en/support/articles/000054799/network-and-io/wireless-networking.html</p> <p>See KB https://gtacknowledge.extremenetworks.com/articles/Solution/AP510-Unable-to-see-the-SSID-on-my-laptop</p> <p>NB -- The client driver update must be done from Intel\drivers' site because the Windows update reports that the client is running the latest driver.</p> <p>If the client driver cannot be controlled (in a BYOD environment), then the AP radios must be configured on a/n/ac (disable ax) until all clients will upgrade to the latest driver.</p>	<p>Info</p>
<p>Appliances in a High-Availability pair must be at the same exact software revision (and time synched) for configuration synchronization to propagate to the peer. During the upgrade process of a High-Availability pair, any configuration changes made while only one appliance has been upgraded (and therefore resulting in a version mismatch) will not be propagated until the peer is correspondingly upgraded to the same revision. We recommend that you NOT perform any configuration changes to one of the members of a High-Availability pair while the peer has a different software revision.</p>	<p>nse0005086</p>
<p>Please allow at least 20 seconds between stopping and re-starting a packet capture on a Site.</p>	<p>nse0004124</p>
<p>ExtremeGuest support will be finalized in the next maintenance release and by the release of eGuest server 6.0.</p>	

Known Restriction or Limitation	I.D
Enabling the appliance as a DHCP server for an attached segment is not currently recommended. Experiencing issues with persistence of Default Gateway and IP range settings. This issue will be corrected in an upcoming release.	nse0003529
Wired packet captures for APs in Campus Sites may take up to 1 minute to show results. This issue will be addressed in a subsequent release.	nse0004545
Client Badge in a Floor plan may not show correctly. This issue will be addressed in a subsequent release.	nse0004565
For Off Channel Scan to work on Distributed APs, 'Smart Monitoring' should be disabled in a Smart-RF profile.	nse0004568
When configuring system for NTP time assignment, ensure that NTP server is properly configured. Incorrect time settings (like timestamps far in the future) may adversely affect system operation, such as certificate expiration that may trigger failures in device registration or system instability.	nse0003696
Multicast rules for Topologies (VLANs) are only enforced on Centralized Site deployments (ExtremeWireless APs). The multicast rules are not enforced by Distributed Sites (ExtremeWirless WiNG APs). Topology assignment in Distributed Sites does not filter multicast. Therefore, traffic is bridged between wireless and wired). AP76xx, AP8432, and AP8533 bridge all multicast traffic from wired to wireless network.	Info
For service authentication in Distributed Sites (ExtremeWireless WiNG), the Default Unauth Role is applied if the configured RADIUS server can't be reached for authentication. The MBA Timeout Role configured for an MBA network is not applied to an End Client (Mobile Unit [MU]) session.	Info
<p>Certain wireless clients (such as Qualcomm Killer Wireless 1535 and Intel 7265D/8260/8265) have been known to not complete the 4-way handshake in order to fulfill the association process in networks that have both PMF/MFP (802.11w) and Fast-Transition (802.11r [FT]) enabled.</p> <p>The currently recommended workaround is to not enable PMF/MFP configuration on a service that is also using 802.11r. Such clients have been demonstrated to work correctly on services with just 802.11r (FT) enabled.</p>	nse0003416
<p>Interaction with ExtremeManagement Center – Management of ExtremeCloud Appliance by ExtremeManagement Center will be enhanced over time with the roadmap. ExtremeManagement Center v8.4 is the minimum release base for integration. Version 8.4 provides recognition of an ExtremeCloud Appliance and representation of Wireless Clients and managed Access Points included in the Wireless tab.</p> <p>Additional integration will be delivered in upcoming releases. ExtremeManagement Center 8.4 is the current recommended minimum release.</p>	Info
<p>MAC address for Clients on ExtremeWireless WiNG™ APs are displayed in the Username column. WiNG APs send the username as a MAC Address, causing NAC to reevaluate the rule engines.</p> <p>This situation will be addressed in a future release.</p>	nse0003279
<p>Wireless capture on Wing APs may return the wrong packet captures containing wired packets and wireless packets only for uplink.</p> <p>This situation will be addressed in a future release.</p>	nse0002243

Known Restriction or Limitation	I.D
Several features of WiNG 7 OS are still under-development plan towards full feature parity. Several functions may be available in the user interface, due to common provisioning, but are not yet fully supported.	Info
Device Level Country override is not supported for WiNG Proxy Mode. Only one country-code assignment per site is supported. All APs at the site must match the same country.	Info
Combining MAC Based Authentication and LAG for switch ports is not currently supported. Engineering is investigating. The issue will be addressed in an upcoming release.	nse0004445
The GUI set action "Retrieve Traces" might fail for the EXOS switches. Repeat setting the "Retrieve Traces" action until the switch uploads the logs and traces the tar file to the ExtremeCloud Appliance.	nse0004866
Currently fabric attach VLANs are not supported as control VLAN for mesh networks.	nse0005152
With on air busy channel conditions, it is possible for the ACS not to produce the expected results. In this instance, perform manual channel selection.	nse0005045
Stability improvements for serving 802.1x and 802.11r services are included AP500 Series image WiNG 7.2.1.1-06R. (Default AP image with this package). See Release Notes of 7.2.1.1-06R.	nse0005125
Upgrade failure will occur when using special characters (escape back slash) in topology.	nse0004876
An AP crash will occur when starting packet capture from ExtremeCloud Appliance. This problem will be resolved by the 7.3.0 Wing AP release.	nse0005010
Simultaneous Backup tunnel High-Availability is only enabled for Access Points deployed in Centralized sites. The Network Health widget on the main dashboard, will only count APs in distributed site against their actual connectivity state (Attached to either Primary or Backup controller). The connectivity counters will therefore only reflect (count) the active tunnel.	nse0004956
GUI Mesh Report is missing the information about Root AP with Ethernet connection. This problem will be addressed in a future release.	nse0005134
In the 3120 Platform, sometimes time series legend for non-empty charts are shown as 'NoData'.	nse0005137
An issue was observed for AP7632 where the Tunnel-Private-Group-ID value is not used or ignored, and client receives the Default Role.	nse0005030
Policy rules applied to AP7632 users do not produce expected results. This issue will be resolved in a future release.	nse0004045
Editing or deleting Control VLAN under the Mesh Network is not possible. This problem will be corrected into a future release.	nse0005144
After switching from Whitelist mode to Blacklist mode traffic there is the possibility for the traffic from the blacklisted client not to be filtered and be able to connect to different wireless networks and obtain Internet access. This problem will be resolved in the next release.	nse0004572
Reboot of the peer ExtremeCloud Appliance is required when Availability is configured for the first time to ensure synchronization of the configuration of	nse0005113

Known Restriction or Limitation	I.D
ONBOARD attributes, such as Device Groups. This issue will be addressed in a subsequent release.	
Corrected resource management issue with authentication library that could prevent administrative access to system's graphical user interface.	nse0005101
Docker requires exclusive use of subnet 172.17.0.0/16 for containers. Customers should not use an IP address in that range for any VLAN or network interface.	nse0005065
ExtremeCloud Appliance user accounts created in the pre-registration page do not propagate to the AAA policy.	nse0005028
Monitor Networks under Distributed Network, Mesh point is missing channel information. This problem will be addressed in a future release.	nse0005135

SUPPORTED WEB BROWSERS

For ExtremeCloud Appliance management GUI, the following Web browsers were tested for interoperability:

- Firefox 38.0
- Google Chrome 43.0

Note: Microsoft IE browser is not supported for UI management.

The Wireless Clients (Captive Portal, AAA):

Browsers	Version	OS
Firefox	68.0	Windows 10
Safari	Preinstalled with iOS 12.2	iOS 12.2
Safari	Preinstalled with iOS 9.3.5	iOS 9.3.5
Microsoft Edge	42.17134	Windows 10
Microsoft IE	11	Windows 7 Windows 8.1 Windows 10
Chrome	75.0.37770.142	Windows 7 Windows 10

PORT LIST

The following list of ports may need to remain open so that the Appliances and APs will function properly on a network that includes protection equipment like a firewall.

ExtremeWireless TCP/UDP Port Assignment Reference

Comp. Source	Comp. Dest	Protocol (TCP/UDP)	Src Port	Dest Port	Service	Remark	Open Firewall Req'd
Ports for AP/Appliance Communication							
Appliance	Access Point	UDP	Any	13910	WASSP	Management and Data Tunnel between AP and Appliance	Yes
Access Point	Appliance	UDP	Any	13910	WASSP	Management and Data Tunnel between AP and Appliance	Yes
Appliance	Access Point	UDP	4500	Any	Secured WASSP	Management Tunnel between AP and Appliance	Optional
Access Point	Appliance	UDP	Any	4500	Secured WASSP	Management Tunnel between AP and Appliance	Optional
Access Point	Appliance	UDP	Any	13907	WASSP	AP Registration to Appliance	Yes
Access Point	Appliance	UDP	Any	67	DHCP Server	If Appliance is DHCP Server for AP	Optional
Access Point	Appliance	UDP	Any	68	DHCP Server	If Appliance is DHCP Server for AP	Optional
Access Point	Appliance	UDP	Any	427	SLP	AP Registration to Appliance	Optional
Appliance	Access Point	TCP/UDP	Any	69	TFTP	AP image transfer	Yes
Access Point	Appliance	TCP/UDP	Any	69	TFTP	AP image transfer	Yes
Appliance	Access Point	TCP/UDP	Any	22	SCP	AP traces	Yes
Any	Access Point	TCP	Any	2002, 2003	RCAPD	AP Real Capture (if enabled)	Optional
Any	Access Point	TCP/UDP	Any	22	SSH	Remote AP login (if enabled)	Optional

Comp. Source	Comp. Dest	Protocol (TCP/UDP)	Src Port	Dest Port	Service	Remark	Open Firewall Req'd
Any	Access Point	TCP/UDP	Any	445	Microsoft CIFS	LDAP support	Optional
Any	Access Point	TCP/UDP	Any	137, 138, 139	NetBIOS	LDAP support	Optional
Ports for Appliance Management							
Any	Appliance	TCP/UDP	Any	22	SSH	Appliance CLI access	Yes
Any	Appliance	TCP/UDP	Any	5825	HTTPS	Appliance GUI access	Yes
Any	Appliance	TCP/UDP	Any	161	SNMP	Appliance SNMP access	Yes
Any	Appliance	TCP/UDP	Any	162	SNMP Trap	Appliance SNMP access	Yes
Any	Appliance	TCP	Any	80	HTTP	Appliance SNMP access ICP Self Registration	Yes
Any	Appliance	TCP	Any	443	HTTPS	ICP Self Registration	Yes
Any	Appliance	UDP	500	500	IKE	IKE phase 1	Yes
Any	Appliance	TCP/UDP	Any	69	TFTP	TFTP support	Yes
Any	Appliance	UDP	Any	4500	IPSec	IPSec NAT traversal	Yes
Any	Appliance	UDP	Any	13907	Discovery	Used by Discovery	Yes
Any	Appliance	UDP	Any	13910	WASSP	Used by L3 WASSP	Yes
Ports for Inter Controller Mobility¹ and Availability							
Appliance	Appliance	UDP	Any	13911	WASSP	Mobility and Availability Tunnel	Yes
Appliance	Appliance	TCP	Any	427	SLP	SLP Directory	Yes
Appliance	Appliance	TCP	Any	20506	Langley	Remote Langley Secure	Yes
Appliance	Appliance	TCP	Any	60606	Mobility	VN MGR	Yes
Appliance	Appliance	TCP	Any	123	NTP	Availability time sync	Yes

¹For extension of ExtremeWireless deployment via Inter Controller Mobility.

Comp. Source	Comp. Dest	Protocol (TCP/UDP)	Src Port	Dest Port	Service	Remark	Open Firewall Req'd
Appliance	DHCP Server	UDP	Any	67	SLP	Asking DHCP Server for SLP DA	Yes
DHCP Server	Appliance	UDP	Any	68	SLP	RespoECA from DHCP Server for SLP DA request	Yes
Core Back-End Communication							
Appliance	DNS Server	UDP	Any	53	DNS	If using DNS	Optional
Appliance	Syslog Server	UDP	Any	514	Syslog	If Appliance logs to external syslog server	Optional
Appliance	RADIUS Server	UDP	Any	1812	RADIUS Authentication and Authorization	If using RADIUS AAA	Optional
Appliance	RADIUS Server	UDP	Any	1813	RADIUS Accounting	If enabled RADIUS accounting	Optional
Appliance	RADIUS server	UDP	Any	1814	RADIUS Authentication and Authorization	If using RADIUS AAA	Optional
Appliance	RADIUS server	UDP	Any	1815	RADIUS Accounting	If enabled RADIUS Accounting	Optional
Dynamic Auth. Server (NAC)	Appliance	UDP	Any	3799	DAS	Request from DAS client to disconnect a specific client	Optional
Appliance	AeroScout Server	UDP	1144	12092	Location Based Service Proxy	Aeroscout Location-Based Service	Optional
AeroScout Server	Appliance	UDP	12092	1144	Location Based Service Proxy	Aeroscout Location-Based Service	Optional

IETF STANDARDS MIB SUPPORT:

RFC No.	Title	Groups Supported
Draft version of 802.11	IEEE802dot11-MIB	
1213	RFC1213-MIB	Most of the objects supported
1573	IF-MIB	ifTable and interface scalar supported
1907	SNMPv2-MIB	System scalars supported
1493	BRIDGE-MIB	EWC supports relevant subset of the MIB
2674	P-BRIDGE-MIB	EWC supports relevant subset of the MIB
2674	Q-BRIDGE-MIB	EWC supports relevant subset of the MIB

EXTREME NETWORKS PRIVATE ENTERPRISE MIB SUPPORT

Extreme Networks Private Enterprise MIBs are available in ASN.1 format from the Extreme Networks website at: <https://extremeportal.force.com/>.

Standard MIBs

Title	Description
IEEE802dot11-MIB	Standard MIB for wireless devices
RFC1213-MIB.my	Standard MIB for system information
IF-MIB	Interface MIB
SNMPv2-MIB	Standard MIB for system information
BRIDGE-MIB	VLAN configuration information that pertains to EWC
P-BRIDGE-MIB	VLAN configuration information that pertains to EWC
Q-BRIDGE-MIB	VLAN configuration information that pertains to EWC

Siemens Proprietary MIB

Title	Description
HIPATH-WIRELESS-HWC-MIB.my	Configuration and statistics related to EWC and associated objects
HIPATH-WIRELESS-PRODUCTS-MIB.my	Defines product classes
HIPATH-WIRELESS-DOT11-EXTNS-MIB.my	Extension to IEEE802dot11-MIB that complements standard MIB
HIPATH-WIRELESS-SMI.my	Root for Chantry/Siemens MIB

802.11AC AND 802.11N CLIENTS

Please refer to the latest release notes for ExtremeWireless™ 10.41.09 or later and/or ExtremeWireless WiNG 5.9.02 or later for the list of compatibility test devices.

RADIUS SERVERS AND SUPPLICANTS**RADIUS Servers Used During Testing**

Vendor	Model OS	Version
FreeRADIUS	1.1.6	FreeRADIUS
FreeRADIUS IAS	1.0.1	FreeRADIUS
	5.2.3790.3959	Microsoft Server 2003 IAS
SBR50	6.1.6	SBR Enterprise edition
NPS	6.0.6002.18005	Microsoft Server 2008 NPS

802.1x Supplicants Supported

Vendor	Model OS	Version
Juniper Networks® / Funk	Odyssey client	Version 5.10.14353.0
		Version 5.00.12709.0
		Version 4.60.49335.0
Microsoft®	Wireless Zero Configuration	Version Windows XP-4K-891859-Beta1
	Wireless Network Connection Configuration	Version Microsoft Window Server 2003, Enterprise Edition R2 SP2
	Wi-Fi Protected Access 2 (WPA2)/Wireless Provisioning Services Information Element (WPS IE) update for Windows XP with Service Pack 2	Version WindowsXP-KB893357-v2-x86-ENU.exe
Intel®	Intel PRO Set/Wireless	Version 13.0.0.x (with Windows® Intel® driver version 13.0.0.x)
Microsoft® Wireless Zero	Windows 7, 8, 8.1 Pro, 10 Pro Windows Phone 8.1, Windows Mobile 10	Provided with Windows®

Appliance LAN Switch Verification

Vendor	Model OS	Version	Role
Extreme	X-460-G2	12.5.4.5	ExtremeCloud Appliance connection
Extreme	X440G2-48p-10G4	21.1.1.4	ExtremeCloud Appliance connection
Extreme	Summit 300-48	7.6e1.4	ExtremeCloud Appliance connection
Extreme	VSP-4850GTS-PWR	(6.0.1.1_B003) (PRIVATE) HW Base: ERS 4850	ExtremeCloud Appliance connection
Extreme	K6	08.63.02.0004	ExtremeCloud Appliance connection
Extreme	K6	08.42.03.0006	ExtremeCloud Appliance connection
Extreme	X440G2-48p-10GE4	21.1.5.2	ExtremeCloud Appliance connection
Extreme	X440-G2-12p	21.1.1.4	ExtremeCloud Appliance connection
Extreme	X460-48p	12.5.4.5	ExtremeCloud Appliance connection
Cisco	Catalyst 3550	12.1(19)EA1c	ExtremeCloud Appliance connection

CERTIFICATION AUTHORITY

Server Vendor	Model OS	Version
Microsoft CA	Windows Server 2003 Enterprise Edition	5.2.3790.1830
Microsoft CA	Windows Server 2008 Enterprise Edition	6.0
OpenSSL	Linux	0.9.8e

RADIUS ATTRIBUTES SUPPORT

RADIUS Authentication and Authorization Attributes

Attribute	RFC Source
Called-Station-Id	RFC 2865, RFC 3580
Calling-Station-Id	RFC 2865, RFC 3580
Class	RFC 2865
EAP-Message	RFC 3579
Event-Timestamp	RFC 2869
Filter-Id	RFC 2865, RFC 3580
Framed-IPv6-Pool	RFC 3162
Framed-MTU	RFC 2865, RFC 3580
Framed-Pool	RFC 2869

Attribute	RFC Source
Idle-Timeout	RFC 2865, RFC 3580
Message-Authenticator	RFC 3579
NAS-Identifier	RFC 2865, RFC 3580
NAS-IP-Address	RFC 2865, RFC 3580
NAS-IPv6-Address	RFC 3162
NAS-Port	RFC 2865, RFC 3580
NAS-Port-Id	RFC 2865, RFC 3580
NAS-Port-Type	RFC 2865, RFC 3580
Password-Retry	RFC 2869
Service-Type	RFC 2865, RFC 3580
Session-Timeout	RFC 2865
State	RFC 2865
Termination-Action	RFC 2865, RFC 3580
Tunnel Attributes	RFC 2867, RFC 2868, RFC 3580
User-Name	RFC 2865, RFC 3580
Vendor-Specific	RFC 2865

RADIUS Accounting Attributes

Attribute	RFC Source
Acct-Authentic	RFC 2866
Acct-Delay-Time	RFC 2866
Acct-Input-Octets	RFC 2866
Acct-Input-Packets	RFC 2866
Acct-Interim-Interval	RFC 2869
Acct-Output-Octets	RFC 2866
Acct-Output-Packets	RFC 2866
Acct-Session-Id	RFC 2866
Acct-Session-Time	RFC 2866
Acct-Status-Type	RFC 2866
Acct-Terminate-Cause	RFC 2866

GLOBAL SUPPORT:

By Phone: +1 800-998-2408 (toll-free in U.S. and Canada)

For the toll-free support number in your country:

<https://extremeportal.force.com/>

By Email: support@extremenetworks.com

By Web: <https://extremeportal.force.com/>

By Mail: Extreme Networks, Inc.
6480 Via Del Oro
San Jose, CA 95119 USA

For information regarding the latest software release, recent release note revisions and documentation, or if you require additional assistance, please visit the Extreme Networks Support website.

Extreme Networks and the Extreme Networks logo are trademarks or registered trademarks of Extreme Networks, Inc. in the United States and/or other countries. All other names (including any product names) mentioned in this document are the property of their respective owners and may be trademarks or registered trademarks of their respective companies/owners. Extreme Networks IPS includes software whose copyright is licensed from MySQL AB.

For additional information on Extreme Networks trademarks, please see: www.extremenetworks.com/company/legal/trademarks/