

IQ Engine Release Notes

Version 10.6.3



Copyright © 2023 Extreme Networks, Inc. All rights reserved.

Legal Notice

Extreme Networks, Inc. reserves the right to make changes in specifications and other information contained in this document and its website without prior notice. The reader should in all cases consult representatives of Extreme Networks to determine whether any such changes have been made.

The hardware, firmware, software or any specifications described or referred to in this document are subject to change without notice.

Trademarks

Extreme Networks and the Extreme Networks logo are trademarks or registered trademarks of Extreme Networks, Inc. in the United States and/or other countries.

All other names (including any product names) mentioned in this document are the property of their respective owners and may be trademarks or registered trademarks of their respective companies/owners.

For additional information on Extreme Networks trademarks, see: www.extremenetworks.com/company/legal/trademarks

Open Source Declarations

Some software files have been licensed under certain open source or third-party licenses. End-user license agreements and open source declarations can be found at: https://www.extremenetworks.com/support/policies/open-source-declaration/



Table of Contents

| General Release Information | 4 |
|--------------------------------|---|
| Current Release: 10.6r3a | 4 |
| Release 10.6.3 | 4 |
| New hardware supported | 4 |
| Hardware platforms supported | |
| Management platforms supported | |
| New Features | 6 |
| Addressed Issues | 7 |
| Known Issues | 8 |



General Release Information

Current Release: 10.6r3a

September 2023

There is no new hardware supported with this release. For information about feature updates, see New Features.

Release 10.6.3

August 2023

New hardware supported

There is no new hardware supported with this release.

Hardware platforms supported

- AP650
- AP650X
- AP305C/CX
- AP305C-1
- AP302W
- AP510C/CX
- AP410C
- AP410C-1
- AP460C
- · 460S6C
- 460S12C
- AP3000
- AP3000X
- · AP4000
- AP4000-1
- AP5010
- AP5050D
- AP5050U

Management platforms supported

ExtremeCloud IQ 23.5.0 and later

Virtual Appliance 21.1.23.4



New Features

Table 1: Release 10.6.3a

| Feature ID | New Feature | Description |
|------------------------|-------------|--|
| XIQ-22858 HOS-19697 | | Added AP305C(X) and AP410C-WR support for Montenegro and Bosnia. |

Table 2: Release 10.6.3

| Feature ID | New Feature | Description |
|------------|-------------|--|
| HOS-19186 | AP5010 | Regulatory changes for the Dominican Republic. Removed channels 120–128 and reduced power for channels 36–48 to match Canadian levels. |



Addressed Issues

| Issue ID | Description |
|-----------|--|
| CFD-9248 | Resolved an issue with AP5010 not sending the model in sysDescr OID via SNMP. |
| HOS-19099 | Resolved an issue with AP3000/AP5050 in Client Mode, where the local client on Eth1 cannot open the Web GUI. |
| HOS-19114 | Fixed frequency error for AP5050, when running below -40°C. |
| HOS-19469 | TCP Port 5918, which is externally accessible, is now closed by default. |



Known Issues

| Issue ID | Description |
|---|---|
| CFD-7445 | 802.11ax client, such as iPhone 12/13, experiences difficulties when receiving 11ac frames if the MCS rate >5 on a Wavel chip platform, such as AP230, AP122, and AP130. Workaround: Use 11AC with lower MCS rates (from 0-3), or use 11N. |
| HOS-17683 | Some WPA3 clients cannot associate to the AP4000 properly when band steering is enabled. Workaround: Disable band steering. |
| HOS-18313 AP5010, AP5050D, and AP5050U devices will not boot some non-Extreme micro-USB cables are connected. Note: For all Extreme Networks access points, use the Extrement Networks certified ACC-WIFI-MICRO-USB console cables have not been certification. Other MICRO-USB console cables have not been certification. Workaround: Use an Extreme Networks certified consoler. | |
| | cable, or plug in the cable after the AP boots. |