



# IQ Engine 10.0r9 Release Notes

**Release date:** June 19, 2020

**Hardware platforms supported:** AP150W

**Management platforms supported:** ExtremeCloud IQ 20.5.1.1 and later

---

## New Features and Enhancements

This release introduces the following new features and enhancements:

**Kr00k Vulnerability Mitigation:** This release fixes a known issue with Broadcom Wi-Fi clients. You can find additional information about the Kr00k vulnerability at the following URL:

<https://nvd.nist.gov/vuln/detail/CVE-2019-15126>

**Router Mode Support for AP150W:** Using that AP150W running IQ Engine 10.0r9 enables administrators to configure the AP150W to function as a router with many of the same routing capabilities as the XP200P. Running 10.0r9, the AP 150W also retains integrated Wi-Fi capabilities.

---

## Known and Addressed Issues

The following tables list known and addressed issues in IQ Engine 10.0.

### Known Issues in IQ Engine 10.0r9

There are no known issues in this release.

### Addressed Issues in IQ Engine 10.0r9

CVE-2019-15126 HOS-15944	Broadcom access points and wireless clients were vulnerable to traffic decryption during a very short time window during the dissociation process.
-----------------------------	--

### Addressed Issues in IQ Engine 10.0r8

CFD-4471	When an admin configured an SSID to drop all non-management traffic destined for the ap, users were unable to authenticate to the network using PPSK self-registration.
CFD-4470	Wildcard characters did not function properly in walled garden captive web portals when NAT was enable on a user profile.
CFD-4453	Disconnecting a client from a WPA3 SSID caused all other clients to disconnect.
CFD-4422	In the output of different commands, IQ Engine reported different values for the same transmit power parameter.
CFD-4398	BLE iBeacons were inconsistently reported in the AP650 iBeacon monitor list output.
CFD-4309	AP650 access points rebooted soon after Cisco phones connected.

---

CFD-4300	When some APs were configured for scheduled reboot, Wi-Fi interfaces were shut down, preventing clients from reconnecting after the reboot.
CFD-4245	AP630 and AP650 access points were dropping a high number of packets.
CFD-4242	Some internal running processes of AP630 access points became unresponsive.
CFD-4190	AP1130 access point were rebooting spontaneously.
CFD-4126	When NTLMv1 was disabled in Active Directory, some access points were unable to act as RADIUS servers using PEAP with MS-CHAP-v2 authentication.
CFD-4086	Network users were sometime assigned to incorrect VLANs and RADIUS attributes were used for classification.
CFD-4085	IQ Engine was reporting high interference to ExtremeCloud IQ.