

### IQ Engine 10.5r4

Release Notes

February 2023



Copyright © 2023 Extreme Networks, Inc. All rights reserved.

#### **Legal Notice**

Extreme Networks, Inc. reserves the right to make changes in specifications and other information contained in this document and its website without prior notice. The reader should in all cases consult representatives of Extreme Networks to determine whether any such changes have been made.

The hardware, firmware, software or any specifications described or referred to in this document are subject to change without notice.

#### **Trademarks**

Extreme Networks and the Extreme Networks logo are trademarks or registered trademarks of Extreme Networks, Inc. in the United States and/or other countries.

All other names (including any product names) mentioned in this document are the property of their respective owners and may be trademarks or registered trademarks of their respective companies/owners.

For additional information on Extreme Networks trademarks, see: www.extremenetworks.com/company/legal/trademarks

#### **Open Source Declarations**

Some software files have been licensed under certain open source or third-party licenses. End-user license agreements and open source declarations can be found at: https://www.extremenetworks.com/support/policies/open-source-declaration/



# **Table of Contents**

eneral Release Information		
Release Date	∠	
Hardware platforms supported	∠	
Management platforms supported		
New Features		
Known Issues	6	
Addressed Issues	7	



### **General Release Information**

### **Release Date**

February 2023

### Hardware platforms supported

- AP130
- AP250
- AP650
- AP122
- AP1130
- AP150W
- AP30
- AP305C/CX
- AP305C-1
- AP302W
- AP510C/CX
- AP410C
- AP410C-1
- AP460C,
- 460s6C
- 460S12C
- AP4000
- AP4000-1
- AP5010
- AP5050D
- AP5050U

### Management platforms supported

ExtremeCloud IQ 22.7.0 and later



## **New Features**

AP5010 now supports **AirDefense** and **Location Essentials**.



## **Known Issues**

Issue ID	Description
HOS-18620/HOS-1492	Client (iPhone13/Pixel 6/Samsung s21/ax210/ax411) not able connect to WPA3 enterprise with Fast Transition (FT)-enabled SSID.  Workaround: Remove the Fast Transition feature from the SSID.
HOS-17683	Some WPA3 clients cannot associate to the AP4000 properly when band steering is enabled.  Workaround: Disable band steering.
HOS-18432	AP4000: Client (Pixel 6) cannot roam with WPA3 Fast Transition (FT)
CFD-7445 (02496570, 02626393, 02651353)	802.11ax client, such as iPhone 12/13, experiences difficulties when receiving 11ac frames if the MCS rate >5 on a Wave1 chip platform, such as AP230, AP122, and AP130.  Workaround: Use 11AC with lower MCS rates (from 0-3), or use 11N.
CFD-8791 (02632593)	APs do not come back online after a Meraki router reboot.



## **Addressed Issues**

Issue ID	Description
HOS-18402	It is no longer possible to cause a denial of service to the self-registration captive portal by sending hundreds of repeated registration requests for private pre-shared keys (PPSKs) within a short period of time (e.g., one minute), which would cause the web server to temporarily cease being available.