



Nortel VPN Client

Software Patch V10.01_103

1. Release Summary

Release Date: August 25, 2009

Purpose: Software Patch to address customer found software issues.

2. Important Notes Before Upgrading to This Release

None.

3. Platforms Supported

The Nortel VPN Client V10.01_103 is intended for use on the following Microsoft software platform:

Microsoft Windows Vista

4. Notes for How To Install/Upgrade

Please see the "Nortel VPN Client - Installation and Upgrades" for Version 10.01 (Part No. NN46110-412 01.01).

5. Version of Previous Release

Nortel VPN Client V10.01_102

6. Compatibility

N/A

7. Changes in This Release

New Features in This Release

N/A

Old Features Removed From This Release

N/A

Problems Resolved in This Release

Nortel VPN Client sustaining Patch Version 10.01.103 fixes the following issues:

Q02035248 –

Installation in System context was not successful for NVC. We added the support in this release.

Q02016901 –

In rare occasions, blue screen of death may occur on machines that have Microsoft Virtual PC 2007 installed. The issue happens on VPN tunnel brought up via wireless connection only. We fixed the bug in this release.

Q02046562-01 –

Authentication fails when user uses Response Only Software Token Mode. The failure happens when the pin has been cleared for a specific token assigned to a user. When the pin is cleared, the NVC enters into "new pin" mode where the user first logs in without a pin and is then asked to input one. After the user inputs a pin, they are asked to reenter the pin. After the pin is reentered, the client responds with a pop up message of "Access Denied". The problem has been fixed in this release.

8. Outstanding Issues

None

9. Known Limitations

None.

10. Documentation Corrections

For known issues, please refer to the product release notes and technical documentation available from the Nortel Technical Support web site at: <http://www.nortel.com/support>.

Copyright © 2009 Nortel Networks - All Rights Reserved. Nortel, Nortel Networks, the Nortel logo, the Globemark, and Contivity are trademarks of Nortel Networks.

The information in this document is subject to change without notice. The statements, configurations, technical data, and recommendations in this document are believed to be accurate and reliable, but are presented without express or implied warranty. Users must take full responsibility for their applications of any products specified in this document. The information in this document is proprietary to Nortel.

To access more technical documentation, search our knowledge base, or open a service request online, please visit Nortel Technical Support on the web at: <http://www.nortel.com/support>



Nortel VPN Client

Software Patch V10.01_102

1. Release Summary

Release Date: May 08, 2009

Purpose: Software Patch to address customer found software issues.

2. Important Notes Before Upgrading to This Release

None.

3. Platforms Supported

The Nortel VPN Client V10.01_102 is intended for use on the following Microsoft software platform:

Microsoft Windows Vista

4. Notes for How To Install/Upgrade

Please see the "Nortel VPN Client - Installation and Upgrades" for Version 10.01 (Part No. NN46110-412 01.01).

5. Version of Previous Release

Nortel VPN Client V10.01_052

6. Compatibility

N/A

7. Changes in This Release

New Features in This Release

N/A

Old Features Removed From This Release

N/A

Problems Resolved in This Release

Nortel VPN Client sustaining Patch Version 10.01.102 fixes the following issues:

Q01961497 –

When the "Client Screen Saver Password Required" is enabled on NVR, a tunnel can't be established from a 64bit client machine.

Q01982378 –

When NVC is not able to do CRL checking during an attempt to bring up an SSL VPN tunnel, a misleading error message will be displayed on the screen.

Q02005006 –

SSL VPN session is not cleaning up properly.

Q01990731 –

If the CA Certificate is not installed in machine cert store, SSL VPN tunnel can't be established.

Q01983037 –

NVC does not work with RSA SecureID in "New Pin Mode".

8. Outstanding Issues

None

9. Known Limitations

None.

10. Documentation Corrections

For known issues, please refer to the product release notes and technical documentation available from the Nortel Technical Support web site at: <http://www.nortel.com/support>.

Copyright © 2009 Nortel Networks - All Rights Reserved. Nortel, Nortel Networks, the Nortel logo, the Globemark, and Contivity are trademarks of Nortel Networks.

The information in this document is subject to change without notice. The statements, configurations, technical data, and recommendations in this document are believed to be accurate and reliable, but are presented without express or implied warranty. Users must take full responsibility for their applications of any products specified in this document. The information in this document is proprietary to Nortel.

To access more technical documentation, search our knowledge base, or open a service request online, please visit Nortel Technical Support on the web at: <http://www.nortel.com/support>