

WiNG 7.4.0.0-025R Release Notes

CC	DNTENTS
Ov	erview2
1.	Platforms Supported2
2.	New Features in WiNG 7.4.0.03
	New platforms
	New features4
3.	General Information for Firmware Upgrade / Downgrade4
	3.1 Device Upgrade/Downgrade matrix4
	3.2 Software compatibility matrix with Extreme Products6
:	3.3 General Important Notes on Upgrade / Downgrade6
:	3.4 Device Upgrade/Downgrade Procedure6
:	3.5 AutoInstall7
4.	Firmware Upgrade / Downgrade – Controllers7
	4.1 Platform Important notes7
	4.2 Device Upgrade Options
	4.3 Auto Upgrade9
5. I	Firmware Upgrade/Downgrade – Independent APs9
!	5.1 Standalone AP Upgrade / Downgrade9
!	5.2 Virtual Controller upgrade9
!	5.3 Upgrading APs through WiNG controller or ExtremeCloud Appliance
6.	Important Notes10
7.	DFS Tables, Sensor and Radio Share17
8.	Vulnerability updates19
9.	Issues Fixed
10.	Known Issues
Glo	bal Support:



OVERVIEW

WiNG 7.4.0.0 continues to build on unique WiNG7 software architecture that combines the scale, features and functions of ExtremeWireless and ExtremeWireless WiNG, offering flexible deployment option covering both campus and distributed modes. WING 7.4.0.0 is a minor release that extends feature support for new 11ax AP portfolio for ExtremeWireless OmniEdge product line as well as provides stability fixes for new APs.

Extreme Campus Controller (XCC) 5.06.01 release will include this WiNG release.

1. PLATFORMS SUPPORTED

Note:

APXXXX-LEAN-7.4.0.0-025R.img - built <u>without</u> <u>GUI component</u>. AP lean images are also bundled within controller full image.

NXXXXX-LEAN-7.4.0.0-025R.img - built without AP images.

WiNG 7.4.0.0 supports the following platforms with the corresponding firmware images:

Controller Platform	Firmware Image
NX 9500/ NX 9510	NX9500-7.4.0.0-025R.img, NX9500-LEAN-7.4.0.0-025R.img
NX 9600 / NX 9610	NX9600-7.4.0.0-025R.img, NX9600-LEAN-7.4.0.0-025R.img
NX 75XX	NX7500-7.4.0.0-025R.img, NX7500-LEAN-7.4.0.0-025R.img
NX 5500	NX5500-7.4.0.0-025R.img, NX5500-LEAN-7.4.0.0-025R.img

Virtual Platform	Firmware Image
VX 9000 ¹ -production iso/img image	VX9000-INSTALL-7.4.0.0-025R.iso, VX9000-7.4.0.0-025R.img, VX9000-LEAN- 7.4.0.0-025R.img
VX 9000 – demo iso image	VX9000-DEMO-INSTALL-7.4.0.0-025R.iso ²

¹VX 9000 image has default 64 AP license.

²The VX demo image is a 60-day trial image of the VX 9000 software VM that can be used for demos and in the lab environments. This image does not need any additional licenses; it comes with 16 AAP licenses built-in. There is no migration from the demo image to the production image.

AP Platforms	Firmware Image
AP310/360	AP3xx-7.4.0.0-025R.img AP3xx-LEAN-7.4.0.0-025R.img (included in all Controller images)

06/11/2020 P/N: 9036747-00 Rev AA



AP Platforms	Firmware Image
AP410/460	AP4xx-7.4.0.0-025R.img
	AP4xx-LEAN-7.4.0.0-025R.img (included in all Controller images)
AP505/510/560	AP5xx-7.4.0.0-025R.img
	AP5xx-LEAN-7.4.0.0-025R.img (included in all Controller images)
AP 7522	AP7522-7.4.0.0-025R.img
	AP7522-LEAN-7.4.0.0-025R.img (included in all NX controller images)
AP 7532	AP7532-7.4.0.0-025R.img
	AP7532-LEAN-7.4.0.0-025R.img (included in all NX controller images)
AP 7562	AP7562-7.4.0.0-025R.img
	AP7562-LEAN-7.4.0.0-025R.img (included in all NX controller images)
AP 8533	AP8533-7.4.0.0-025R.img
	AP8533-LEAN-7.4.0.0-025R.img (included in all NX controller images)
AP 8432	AP8432-7.4.0.0-025R.img
	AP8432-LEAN-7.4.0.0-025R.img (included in all NX controller images)
AP 7612	AP7612-7.4.0.0-025R.img
	AP7612-LEAN-7.4.0.0-025R.img (included in all NX controller images)
AP 7632	AP7632-7.4.0.0-025R.img
	AP7632-LEAN-7.4.0.0-025R.img (included in all NX controller images)
AP 7662	AP7662-7.4.0.0-025R.img
	AP7662-LEAN-7.4.0.0-025R.img (included in all NX controller images)

2. NEW FEATURES IN WING 7.4.0.0

New platforms

AP 310/360 Introduction

AP310i/e (Indoor) and AP360i/e (Outdoor) APs are a new Enterprise WiFI 6 (802.11ax) APs with dual band 2x2 SoC radios.

The following SKU models are supported:

- -FCC for FCC domain
- -WR for rest of the world outside the North America, excluding Canada and Israel.
- -CAN for Canada only
- -IL for Israel only



New features

WiNG distributed features supported in this release are explained below. WiNG campus features are described in Extreme Campus Controller (XCC) 5.06.01 release note. Please refer to it for more information.

MeshConnex support on AP4xx

MCX is now supported on AP410i/e and AP460i/e APs.

(Please see known issues in section 10)

ImagoTag secure connectivity

The new version of ImagoTag ESL solution is now upgraded with secure connectivity between AP and ESL server on-prem or on-cloud. This requires upgrading the existing on-prem ESL servers and adding new parameters in the iot-device-imagotags policy. This feature is available for AP410, AP310 and AP8432.

XIQ

WiNG devices can now be managed from XIQ. Any WiNG controller that is onboarded to XIQ supports this feature. Users can use SSH proxy option on XIQ to open SSH connection with WiNG controller for accessing CLI. Similarly, users can use WEB proxy option on XIQ to launch the GUI of WiNG controller from XIQ. Users can use their existing credentials to access WiNG CLI or GUI. This feature is also supported on WiNG access points configured in Virtual Controller mode.

11ax sensor enhancement

Support for terminating WPA3 client using role-based firewall is added to 11ax sensors.

Regulatory update:

DFS channels support for US and Canada is added for AP3xx and AP4xx. Please refer to section 7 below for more information.

3. GENERAL INFORMATION FOR FIRMWARE UPGRADE / DOWNGRADE

3.1 Device Upgrade/Downgrade matrix

This section documents allowed upgrade/ downgrade combinations. Please ensure that the WiNG controller and AP are on the same WiNG version after the upgrade is complete in the controller deployment.



Adaptive with the RFS controller	Upgrade from	Downgrade to	Notes
AP 7532/AP 7522	v5.5.3.1 onwards, excluding v5.6.x	v5.5.3.1 onwards, excluding v5.6.x	AP image is contained within the NX controller image
AP 7612/7632/7662	v5.9.1	v5.9.1	AP image is contained within the NX controller image.
AP 8533/ AP 8432	v5.8.4 onwards	v5.8.4 onwards	AP image is contained within the NX controller image.
AP 505/510i	v7.1 onwards	v7.1	AP 5xx image is contained within the controller image
AP 510e	v7.1.1 onwards	V7.1.1	AP 5xx image is contained within the controller image
AP 560i-FCC	v7.1.1 onwards	v7.1.1	AP 5xx image is contained within the controller image
AP 560h-FCC	v7.1.2 onwards	V7.1.2	AP 5xx image is contained within the controller image
AP 410/460i	v7.3.0.0 onwards	v7.3.0.0	AP 4xx image is contained within the controller image
AP 410/460e	v7.3.0.0 onwards	v7.3.0.0	AP 4xx image is contained within the controller image
AP 310i/e	v7.3.1.0 onwards	v7.3.1.0	AP 3xx image is contained within the controller image
AP 360i/e	v7.4.0.0 onwards	v7.4.0.0	AP 3xx image is contained within the controller image
NX 5500	v5.8 onwards	v5.8 onwards	NX 5500 is supported starting with v5.8
NX 75XX	v5.5.2 onwards	v5.5.2 onwards	Note: WiNG 5.6 doesn't support NX 7500.
NX 9500	v5.2.1 onwards	v5.2.1 onwards	
NX 9510	v5.4.1 onwards	v5.4.1 onwards	
NX 96XX	v5.5.6 onwards	v5.5.6 onwards	NX 96XX is not supported with v5.6.x and v5.7.x
VX 9000	v5.6 onwards	v5.6 onwards	



WiNG	Extreme CloudAppliance	ADSP	ExtremeGuest	ExtremeNSight	ExtremeLocation
WiNG 7.1	4.36.01	n/a	ExtremeGuest 5.9.3.1	n/a	n/a
WiNG 7.1.1	4.36.02	10.1.0-13a	ExtremeGuest 5.9.3.1	n/a	n/a
WiNG 7.1.2	4.36.03	10.1.0-13a	ExtremeGuest 5.9.3.1	n/a	2.1
WiNG 7.2.0	4.56.01	10.2.x	ExtremeGuest 5.9.3.1	n/a	2.1
WiNG 7.2.1	4.56.02	10.2.x	ExtremeGuest 5.9.3.1/6.0	n/a	3.1
WiNG 7.3.0	4.76.01	10.3	n/a	n/a	n/a
WiNG 7.3.1	4.76.03	10.4	n/a	n/a	n/a
WiNG 7.4.0	5.06.01	TBD	n/a	n/a	n/a

3.2 Software compatibility matrix with Extreme Products

3.3 General Important Notes on Upgrade / Downgrade

IMPORTANT:

- WiNG controller must be running a WiNG 7 controller code to be able to recognize, adopt and upgrade 11ax APs.
- Always create config back-up before the upgrade.
- Firmware upgrades can take several minutes; aborting an update by removing power may damage the AP or controller. Please allow time for devices to complete the upgrade. Where APs are powered through PoE connections to WLAN controllers, the controller needs to stay up during the upgrade process.
- Both the WiNG controller and WiNG AP should be upgraded to the same versions a firmware mismatch can cause network disruptions and should be avoided. When upgrading, the controllers should be upgraded first and then the APs. When downgrading, the APs should be downgraded first, and then the controller.

3.4 Device Upgrade/Downgrade Procedure



- 1. Copy firmware image for device that needs to be upgraded to you ftp/tftp server. Refer to section 2 for correct firmware image for your device.
- Use the -upgrade ftp://<username>:<password>@<ip address of server>/<name of file>, or -upgrade tftp://<ip address of server>/<name of file> command from CLI or Switch Firmware->Update Firmware option from the GUI. You may need to specify the username and password for your ftp server.
- 3. Restart the device. From CLI the command is —reload.

3.5 AutoInstall

AutoInstall in WiNG 5 works via the DHCP server. This requires the definition of Vendor Class and three sub-options that can be either sent separately or under option 43:

Option 186 - defines the tftp/ftp server and ftp username, password information (IP address and protocol need to enter as a string: —ftp://admin:admin123@192.168.1.10||)

Option 187 - defines the firmware path and file name

Option 188 - defines the config path and file name

Autoinstall of firmware and autoinstall of configuration can be enabled or disabled. Ensure to enable "ip dhcp client request options all" on the VLAN interface which is being used to perform the above autoinstall.

DHCP vendor class for platforms is noted below:

Appliances:

- WingNX.NX5500
- WingNX.NX9000

AP:

- WingAP.AP310
- WingAP.AP410
- WingAP.AP505
- WingAP.AP7522
- WingAP.AP7612
- WingAP.AP8432
- WingAP.AP8533

• WingAP.AP360

WingNX.NX7500

- WingAP.AP460
- WingAP.AP510
- WingAP.AP7532
 - WingAP.AP7632

- WingNX.VX
- WingAP.AP560
- WingAP.AP7562
- WingAP.AP7662

4. FIRMWARE UPGRADE / DOWNGRADE – CONTROLLERS

4.1 Platform Important notes

- 1. VX 9000:
 - a. Secondary storage: VX 9000 has disk size limitation on the default disk of 2TB. However, when a secondary virtual disk is used, VX 9000 can support disks size larger than 2TB
 - Enabling secondary storage does not copy data files to the new location
 - It is recommended immediately after provisioning the guest instance, before enabling NSight or Captive-Portal



- If the secondary storage needs to be enabled after NSight/Captive-portal, it is
 recommended to back up the database, and restore the database after secondary
 storage is enabled.
- If the VX 9000 instance is not a primary (replica-set member), the database server will perform full data sync after it is restarted with the new secondary storage disk.
- 2. When upgrading from prior versions new profiles for newly supported platforms will not be present in the startup-config. The user can either create a default profile or do "erase startup-config".

4.2 Device Upgrade Options

WiNG 7.x supports device firmware upgrade from the controller. For firmware upgrade through the controller, firmware image needs to be loaded onto a controller and the same can be used for the upgrade of all the corresponding devices.

Available firmware on the controller can be checked using the below command:

nx9600#show device-upgrade versions

If device firmware is not part of controller image, a new image can be uploaded using the following command:

nx9600#device-upgrade load-image

Once device firmware is loaded on the controller, below are the different options that are available for device firmware upgrade:

• Manual Upgrade

Firmware upgrade can be initiated on a single or a list of Aps using the below command.

nx9600#device-upgrade ap505 ? no-reboot No reboot (manually reboot after the upgrade) reboot-time Schedule a reboot time upgrade-time Schedule an upgrade time

nx9600#device-upgrade ap510 all ?

forceForce upgrade on all devicesno-rebootNo reboot (manually reboot after the upgrade)reboot-timeSchedule a reboot timestaggered-rebootReboot one at a time without network being hitupgrade-timeSchedule an upgrade time

Scheduling Firmware upgrade

Firmware upgrade can be scheduled on a controller, that is upgrade time and reboot time can be configured. Firmware upgrade on the Aps follows the configured upgrade time.

nx9600# device-upgrade all ? no-reboot No reboot (manually reboot after the upgrade) reboot-time Schedule a reboot time staggered-reboot Reboot one at a time without network being hit

upgrade-time Schedule an upgrade time

Upgrade through RF Domain manager

Manual Firmware upgrade can be initiated through a domain manager

nx9600#device-upgrade rf-domain ? DOMAIN-NAME RF-Domain name



all	Upgrade all RF Domains
containing	Specify domains that contain a sub-string in the domain name
filter	Specify additional selection filter

4.3 Auto Upgrade

Auto firmware upgrade can be enabled on the controller using the below command. When enabled, any AP with a firmware version different than the controller will be upgraded to the controller's version on adoption.

nx9600 (config-device-XXX)# device-upgrade auto The number of concurrent firmware upgrades can be configured using the below command based on the bandwidth available between the controller and the Aps.

nx9600(config-device-XXX)# device-upgrade count ? <1-20> Number of concurrent AP upgrades

Note: Auto upgrade on the APs always happens through the controller.

5. FIRMWARE UPGRADE/DOWNGRADE – INDEPENDENT APS

5.1 Standalone AP Upgrade / Downgrade

- 1. Copy firmware image for device that needs to be upgraded to you ftp/tftp server. Refer to section 2 for correct firmware image for your device.
- Use the —upgrade ftp://<username>:<password>@<ip address of server>/<name of file>, or —upgrade tftp://<ip address of server>/<name of file> command from CLI or Switch->Firmware->Update Firmware option from the GUI. You may need to specify the username and password for your ftp server.
- 3. Restart the device. From CLI the command is —reload.

5.2 Virtual Controller upgrade

- 1. If there are no adopters/controllers in the network and several APs are required to be upgraded, use WiNG Virtual Controller (VC) mode to perform bulk AP upgrades.
- 2. Use WiNG configuration wizard to configure Virtual Controller (VC) on the AP.
- 3. When done with the WiNG configuration wizard, upgrade the VC to the latest image by using following command:

ap510-1349AC#upgrade tftp://<hostname|IP>path/file

- 4. After upgrade is done, reboot the AP to load the latest code. **ap510-1349AC#reload**
- Load the AP image file on to the VC by using following command: ap510-1349AC#device-upgrade load-image ap510 tftp://<hostname|IP>/path/file
- 6. Add rest of the APs to the network, the Virtual Controller (VC) will listen to the MLCP request from new APs, adopt and upgrade all the APs automatically.

5.3 Upgrading APs through WiNG controller or ExtremeCloud Appliance



- 1. APs with default unknown operation mode will find appropriate controllers based on the network provided discovery mechanism i.e. DHCP or DNS.
 - Standard DHCP option 191
 - Standard DHCP option 192
 - Vendor Class Identifier DHCP option 191
 - DNS response for 'wing-wlc*'
- 2. If the AP is being adopted by the ExtremeCloud Appliance, upon adoption ExtremeCloud Appliance will automatically upgrade the AP image.
- 3. If the AP is adopted by a WiNG 7 controller, the controller will perform an upgrade based on how it's configured for upgrades i.e. auto upgrade upon adoption or on demand upgrade refer to section 4.2 in this document.

6. IMPORTANT NOTES

<u>New in v7.4.0</u>

- Following features are now supported in WiNG 7.4.0:
 - Distributed mode:
 - Secure ImagoTag connectivity for all 11ax APs and AP8432.
 - IMPORTANT 7.4.0.0 doesn't support unencrypted mode of connectivity with ESL server. Also, with any existing ImagoTag policy in AP, AP will not be able to connect to ESL server on-prem or on-cloud supporting encrypted communication. On-prem ESL server should be upgraded and appropriate configuration changes to ImagoTag policy made for a successful communication.

CONFIGURATION

```
iot-device-type-imagotag-policy VCLOUD
enable
output-power Level-A
window-size 14
payload-size 32
ssl
no ssl-cn-verify
no ssl-strict-verify
no fcc-mode
trustpoint <trustpoint-name>
channel managed
server hostname <server> port 7354
```

- ssl Mandatory for encrypted communication
- **ssl-cn-verify** Enable to validate the Common Name in server certificate with configured server IP or hostname.
- ssl-strict-verify Enable strict validation of server certificates.
- trustpoint Trustpoint pointing to CA certificate (Global or local).



- **port** Default port is 7353 which is for cleartext communication. For secure communication port is 7354 which needs to be specified.
- MCX support on AP4xx

Campus mode:

- Enhanced Client Bridge support on all 11ax APs
- \circ XCC redirection
- Configurable Redirect Port for HTTP-Proxy Environments
- URL-Redirect (Cisco-AVP) and URL-Redirect ACL support
- Policy rules are extended from 64 to 256 for each MU
- VxLAN support
- Telemetry support to report AP's CPU, memory and disk usage
- Multiple new MU capabilities reporting

New in v7.3.1

• Following features are now supported in WiNG 7.3.1:

Distributed mode:

- Virtual controller support on wifi6 APs. Please refer to WiNG 7.3.1.1 release note for details.
- Imagotag ESL support on AP4xx and AP3xx.

<u>New in v7.3.0</u>

- Following features are now supported in WiNG 7.3.0: <u>Distributed and Campus mode:</u>
 - ADSP support:
 - Spectrum Analysis.
 - AP Test
 - SU/MU-11ac Beamforming is supported on AP505/510/560/410/460
 - STBC/SU MU_MIMO is supported in HE field on AP505/510/560/410/460
 - OFDMA needs to be disabled for AP500 and AP400.
 - Solid LED enable/disable command

CLI command will look as below.

[no] led change-blinking-to-solid-on

Default value: "Disabled"

<u>New in v7.2.1</u>

- Following features are now supported in WiNG 7.2.1:
 - Imagotag support for AP5xx.
 - Euclid, 3rd party RTLS support.



- Apple client support:
 - Apple client will not stay associated to WLAN with Fast BSS and FT-over DS reason code:17. Please disable PMF and Multiband operation to work around this issue.
 - Any Apple mobile client with iOS Version less than 12.1.1, won't connect to a WPA2/WPA3 transition mode WLAN.
 Official support for WPA3 is set for iOS version 13.
- Agile Multiband Operation
 - PMF-optional, 802.11v, 802.11u, 802.11k turned on by default now.
 - Default Value: "Enabled"
- Smart Sensor important notes:
 - o BLE sensor and smart-sensor feature currently can't be enabled simultaneously
 - \circ $\,$ 3rd radio on AP 8533 must be disabled in the config.
 - When smart-sensor feature is enabled in the config trigger command needs to be issued on the domain to start sensor assignment.
 - When using smart-sensor feature please use AP 8533 profile not anyap profile.
 - BLE sensor and smart-sensor currently can't be enabled together.
 - Smart-sensor feature currently can't be triggered in controller-managed rf-domains.
- New 11ax config:

0

- OFDMA enable/disable command:
 - CLI Command will look as below under Radio context: [no] 11axOFDMA(dl | ul | both)

Default value: "Disabled"

- BSS Coloring:
 - [no] 11axBSS-color (1-63)
 - Default Value: "Disabled"
 - Note: This functionality is currently not fully supported.
 - TWT enable/disable command:
 - [no] 11axTWT
 - Default value: "Disabled"

Note: This functionality is currently not fully supported.

- Guard Interval:
 We already have a CLI command to set GI on legacy AP with options GI-Any or GI-Long
 3 new options added in WING-7.2.0 release as "base | double | guadruple"
- 11ax added functionality:
 - Custom rates are now supported.
 - 160Mhz channels are now supported on 5Ghz.
 - Existing ldpc has been turned on by default now.
 - Sniffer re-direct support for 11ax
 - OFDMA, MU-MIMO not supported yet.

<u>New in v7.2.0</u>

• Following features are now supported in WiNG 7.2.0:



Distributed and Campus mode:

- ExtremeLocation support:
 - Following features are supported:
 - Zone tracking (requires 6 sec feed interval)
 - Position tracking (requires 1 sec feed interval)
- ADSP support on AP 5xx:
 - 802.11ax LiveView.
 - Radio share support
- AP 5xx: SmartRF Support for Dual 5GHz split radio mode.

Distributed mode:

- AeroScout RTLS is now supported on AP 5xx.
- ExtremeAnalytics (Purview):
 - Support for TCP RTT.
 - Support for custom applications rules.
- WPA3 support:
 - When the WPA3 is configured, no inferior encryption shall exist on the same AP as WPA3. This is enforced by WiFi Alliance as the mandatory requirement for WPA3.
 - New CLI command to configure WPA3 authentication type:

ap505-1344D4(config-wlan-temp)#authentication-type ?

sae WPAv3-Personal (SAE Authentication)

sae-psk WPAv3-Compatibility (SAE or WPAv2 PSK authentication)

 AP 5xx Sniffer-redirect is now (Note: 802.11ax protocol support will be added in later release).

Campus mode:

- a. RTLS AiristaFlow (EKAHAU), AeroScout, Centrak, Euclid.
- b. OCS support when SMART-RF is not enabled for ADSP sensor and ExremeLocation sensor support.
- c. DFS Fallback Channels on 5Ghz Radio in Campus mode Adding the Client Load Balance on AP505/AP510/AP560. This feature allows the APs in the same load balance group to communicate with each other to balance the number of clients associated with each APs inside the same group. Requires XCA 4.56.01 release.
- d. Client Load Balance on AP505/510 In Campus mode Adding the support of a predefined channel on the 5GHz band on AP505/AP510/AP560 which allows the AP to switch to this predefined channel in case there is a Rader signal detected by DFS algorithm on the operational channel. Note: feature already exists in Distributed mode. Requires XCA 4.56.01 release.
- e. AP "Name" in the Beacon in Campus mode Ability to add AP hostname to the beacon. Requires XCA 4.56.01 release.



 WiNG 7.2 added ability to enable/disable 11ax functionality on the AP 5505/AP510/AP560: ap510-137D1E(config-device-94-9B-2C-13-7D-1E-if-radio2)#? Radio Mode commands: 11axSupport Configure support for 802.11ax mode

ap510-137D1E(config-device-94-9B-2C-13-7D-1E-if-radio2)#no 11axSupport ap510-137D1E(config-device-94-9B-2C-13-7D-1E-if-radio2)#11axSupport

The default value is "11axSupport" which enables the 11ax mode on the radio.

- AP 5xx 11ax radio functionality limitations:
 - 11ax enabled WLAN must be on the 1st BSS
 - 40Mhz channels are not supported on 2.4 Ghz radio.
 - Customer rates are not supported please use default rates only.
 - Channel width of 160Mhz is not supported.
- AP 5xx now supports 512 clients per radio.
- When adopting any AP running firmware prior to WING 7.2, wireless clients fail to associate to APs running prior version with reason code "max-clients on wlan associated". WLANs mapped to those APs will need to use the workaround of setting "wireless-client count-per-radio 256".
- There is a configuration error issue when adopting APs that don't support RRM-TPC report with firmware prior to 7.4.0.0.0 and 5.9.6. Workaround: Disable RRM-TPC in WLAN when it is adopting AP5xx with firmware prior to 7.4.0.0.0 or other APs running 5.9.5 or earlier that don't support RRM-TPC.

<u>New in v7.1.2</u>

- Following features are now supported in WiNG 7.1.2: <u>Distributed and Campus mode:</u>
 - ExtremeLocation support (limited):
 - Following features are supported:
 - Presence
 - Following is not yet fully supported in this release:
 - Zone tracking (requires 6 sec feed interval)
 - Position tracking (requires 1 sec feed interval)
 - IoT support:
 - iBeacon
 - Eddystone
 - iBeacon Scan
 - Eddystone-url Scan

Distributed mode:



- a. LACP support for AP 5xx.
- b. USP port support on AP 5xx.
- c. Strict 11ac association for AP5xx.

Campus mode:

- d. Smart-RF (requires ExtremeCloudAppliance 4.36.03 release). Note: select-shutdown feature is not supported in this release.
- e.

 AP560h antenna options – there are two options for AP560h internal antenna: ap560(config-device)#antenna-id internal ? internal-560h-30 Internal 560h eight feed 30 degree sector antenna (Default option) internal-560h-70 Internal 560h eight feed 70 degree sector antenna

- 3. ExtremeAnalytics (Purview) important notes:
 - a. Application policy for ExtremeAnalytics DPI engine can be configured from WING controllers for ExtremeAnalytics DPI engine supporting APs. WING controllers however don't support ExtremeAnalytics DPI engine in current release. Support for same will be enabled on WING controllers in a future release.
 - b. Application and application category names are different in legacy application policy and Purview application policy rules.
 - c. RTP and TCP-RTT metadata configuration and extraction is not supported in current release for Purview DPI engine supporting APs.
 - d. Application groups for ExtremeAnalytics DPI engine applications will not work with NSight release 5.9.3.
 - e. Custom application configuration no longer supports multiple url-lists for hostnames, common names and server names and port-proto rules. If custom application configuration exists with multiple such rules, make sure to split it up into multiple custom application configuration each containing only one rule for url-list, common name, server name and port-proto rule as applicable.
 - f. WiNG 7.1.2 doesn't have UI support for configuring Purview (ExtremeAnalytics) policy configuration only available in CLI.

New in v7.1.1

- 1. WiNG 7.1 controllers can adopt WiNG 5.9.4 and WiNG 5.9.4.1 APs in this release. WiNG 5.9.4 APs should be in separate rf-domain from WiNG 7.1 APs.
- 2. Following features are now supported in WiNG 7.1.1:

Distributed mode:

- a. REST API
- b. ADSP sensor <u>dedicated mode only</u> (refer to matrix below for features supported).
- c. Smart-rf Select-shutdown
- d. Dynamic VC (note: heterogenous AP deployment is not supported yet).
- e. IPsec and L2TPv3 tunneling
- f. Layer 3 assisted mobility
- g. NAT



- h. Bonjour support
- i. WiNG extensions (including scan assist)
- j. USB port

Campus mode:

- a. ADSP sensor
- b. Energy Efficient ethernet
- 3. AP 510e configuring "antenna-id" command in device/profile of the AP is needed to radio to operate.

"antenna-id group-1 antenna_name"– use for 2.4/5GHz dual band antenna types. "antenna-id group-2 antenna_name" - use for 5GHz single band antenna types.

 For AP 510e when using high gain directional antennas in 4x4 mode – lower channels are not supported, and radio will not be enabled. Please reference antenna guide for correct channel, power and antenna settings.

<u>New in v7.1</u>

- 1. WiNG 7.1 will only support AP 505/510 in this release. 11AC ExtremeWireless WiNG APs will be added in later release.
- 2. Following features are not supported on AP505/510 in this release: Distributed mode:
 - NSight
 - ADSP sensor
 - Location sensor (all modes)
 - MCX and MCX related features
 - REST API
 - Layer 3 assisted mobility
 - Smart-RF:
 - Select-shutdown
 - Dual 5Ghz radio support
 - Client Bridge
 - IoT/BLE
 - AVC and Application Policy
 - Dynamic VC and Heterogenous AP deployment has not been tested
 - NAT
 - Bonjour support
 - WiNG extensions (including scan assist)
 - IPsec and L2TPv3 tunneling
 - LACP
 - Receive Sensitivity

6480 Via Del Oro



San Jose, CA 95119

+1 888-257-3000

- PPPoE
- 802.11k
- RTLS (Aeroscout, Centrak, and Ekahau)
- USB port is not supported yet
- Sniffer redirect

Campus mode:

- 802.11r (Fast Transition)
- Smart-RF
- Client Load Balance/Band Steering
- Airtime Fairness
- Admission Control
- IoT/BLE/Thread
- ADSP sensor
- ExtremeLocation sensor
- Positioning
- RTLS (Aeroscout, Centrak, and Ekahau
- Probe Suppression on Low RSS
- USB port not supported
- 3. Smart-rf for dual 5Ghz radio on AP510 is not supported currently please assign channel and power statically.
- 4. WiNG 7.1 controllers can adopt WiNG 5.9.3 APs only in this release. WiNG 5.9.3 APs should be in separate rf-domain from WiNG 7.1 APs.
- 5. Default BLE beacon tx power must be changed to value permitted for 7632/62 platform to permit adoption i.e. beacon tx power 10.
- 6. AP 505/510 default password in all modes is admin123 for all operational modes.
- 7. Setting of custom rates is not supported in this release please use default rates.

Deriving secondary IP

APs have a shadow or secondary IP for gaining access to the AP if the IP address of the AP is not known but the MAC address is known. To derive the shadow IP address of an AP, use the last two hex bytes of the AP's MAC address to determine the last two octets of the IP address.

- AP MAC address 00:C0:23:00:F0:0A
- AP IP address equivalent 169.254.240.10

To derive the AP's IP address using its factory assigned MAC address

- Open the Windows calculator by selecting Start>All Programs>Accessories>Calculator. This menu path may vary slightly depending on your version of Windows.
- With the Calculator displayed, select View>Scientific. Select the Hex radio button.
- Enter a hex byte of the AP's MAC address. For example, F0.
- Select the Dec radio button. The calculator converts the F0 to 240. Repeat this process for the last AP MAC address octet.

7. DFS TABLES, SENSOR AND RADIO SHARE



Product	Master DFS FCC	Master DFS IC	Master DFS ETSI	Master DFS Japan	Client DFS FCC	Client DFS IC	Client DFS ETSI	Client DFS Japan
AP 310i	Enabled	Enabled	Enabled	Disabled	Disabled	Disabled	Disabled	Disabled
AP 310e	Enabled	Enabled	Enabled	Disabled	Disabled	Disabled	Disabled	Disabled
AP 360i	Enabled	Enabled	Enabled	Disabled	Disabled	Disabled	Disabled	Disabled
AP 360e	Enabled	Enabled	Enabled	Disabled	Disabled	Disabled	Disabled	Disabled
AP 410i	Enabled	Enabled	Enabled	Disabled	Disabled	Disabled	Disabled	Disabled
AP 410e	Enabled	Enabled	Enabled	Disabled	Disabled	Disabled	Disabled	Disabled
AP 460i	Enabled	Enabled	Enabled	Disabled	Disabled	n/a	n/a	n/a
AP 460e	Enabled	Enabled	Enabled	Disabled	Disabled	n/a	n/a	n/a
AP 505i	Enabled	Enabled	Enabled	Enabled	Disabled	n/a	n/a	n/a
AP 505e	Enabled	Enabled	Enabled	Enabled	Disabled	n/a	n/a	n/a
AP 510i	Enabled	Enabled	Enabled	Enabled	Disabled	n/a	n/a	n/a
AP 510e	Enabled	Enabled	Enabled	Enabled	Disabled	n/a	n/a	n/a
AP 560i	Enabled	Enabled	Enabled	Enabled	Disabled	n/a	n/a	n/a
AP 560e	Enabled	Enabled	Enabled	Enabled	Disabled	n/a	n/a	n/a

1. Following is the DFS support in WiNG 7.4.0.0 for the supported radio platforms:

2. Air Defense sensor capabilities interop matrix supported on the 802.11ax APs

As a dedicated sensor	WIPS & Advanced Forensics	Spectrum Analysis	Advanced Spectrum Analysis	Live View	AP Test	Connection Troubleshooti ng	WVA	Alarms	Termination
AP 310/360	No	No	No	No	No	No	No	No	No
AP 410/460	Yes	No	Yes	Yes	Yes	No	Yes	Yes	Yes
AP 505/510/ 560	Yes	No	Yes	Yes	Yes	No	Yes	Yes	Yes



3. Radio Share functionality

As radiosha re sensor	WIPS & Advanced Forensics	Spectrum Analysis	Advanced Spectrum Analysis	Live View	AP Test	Connection Troubleshoot ing	WVA	Alarms	Termination
AP 310/360	No	No	No	No	No	No	No	No	No
AP 410/460	Np	No	No	No	No	No	No	Yes	Yes
AP 505/510 /560	Yes	No	No	Yes	Yes	No	No	Yes	Yes

8. VULNERABILITY UPDATES

In case a patch has been applied to address vulnerability even though vulnerability was addressed – some security scans only check the version number of the component as opposed to testing the actual vulnerability – and therefore might still report issue being present.

WiNG 7.4.0

No updates in this release

WiNG 7.3.1

No updates in this release

WiNG 7.3.0

CVE-2019-16275: hostapd before 2.10 Allow an incorrect indication of disconnection in certain situations because source address validation is mishandled.

CVE-2019-13012 GNOME GLib (aka glib2.0).

WiNG 7.2.1

CVE-2018-2048: Wget vulnerability in version 1.16

CVE-2019-13377: Timing-based side-channel attack against WPA3's Dragonfly handshake when using Brainpool curves

WiNG 7.2.0

Linux Kernel 4.1.51 Patch Update for Vulnerability: TCP SACK panic, CVE-2019-11477.

WPA supplicant updated to v2.8 to mitigate following WPA3 vulnerabilities: CVE-2019-9494, CVE-2019-9495, CVE-2019-9496, CVE-2019-9497, CVE-2019-9498, CVE-2019-9499.



WiNG 7.1.2

Both Campus and Distributed mode are using same openSSL version 1.0.2q

WiNG 7.1/7.1.1

No updates in this release

9. ISSUES FIXED

Following issues have been fixed in WiNG 7.4.0 release:



CR/ESR	Description
WING-42828	Packet capture shows channel and RSSI 0
WING-42919	AP310 not reporting RSSI
WING-42920	AP310 not reporting interferences on 2.4GHz
WING-42840	VX9000 does not boot up on Hyper-V
WING-42755	Timezone Europe/Moscow is not reflecting the correct time and adds one hour
WING-42897	AP crashes during macbook 802.1x auth with secure tunnel
WING-39525	AP4xx panics
WING-39445	AP5xx FT roam with expired PMK Id
WING-39396	AP5xx FT not working
WING-42961	AP460 antenna usage changed after upgrade
WING-42271	Samsung Galaxy A5, A8 and A10 connected to AP8432 show as unknown
WING-42861	Reported AP serial number in not matching with label
WING-42978	Added CDP Support to WiNG APs
WING-42967	Captive portal error displayed with a delay of 15-20 seconds
WING-43095	AP5xx/AP4xx/AP3xx Unknown personality- LLDP tlv-s aligned with WiNG
WING-42827	Wireshark shows malformed packet captured on radio
WING-42652	AP7632 reboots with "force reset for recovery" on 5.9.3.1 booting 7.3.0
WING-43154	AP510 crash
WING-42986	NX5500 Cold boot when User associates to Captive portal Wlan
WING-42871	Fabric attach not accepted when native vlan is configured with isid mapping
WING-43095	AP5xx/AP4xx/AP3xx Align LLDP in unknown mode with WiNG

10. KNOWN ISSUES

CR/SPR	Headline	Comments
WING-43109	AP460 MCX: Non-root AP uses fixed 20Mhz channel width for mesh connection.	Use 20MHz channel width on both root and non-root AP for mesh connection.



CR/SPR	Headline	Comments
WING-43156	AP460 MCX: Non-Root AP selects another parent even though it has good link with current parent.	Configure non-root AP with fixed parent AP.
WING-43207	AP460 MCX: Non-root and root APs will need separate mesh profiles explicitly specifying AP roles.	Explicitly configure "root" in root AP's meshpoint configuration.

GLOBAL SUPPORT:

By Phone: +1 800-998-2408 (toll-free in U.S. and Canada)

For the toll-free support number in your country: <u>www.extremenetworks.com/support/</u>

- By Email: support@extremenetworks.com
- By Web: <u>www.extremenetworks.com/support/</u>
- By Mail: Extreme Networks, Inc. 6480 Via Del Oro San Jose, CA 95119

For information regarding the latest software available, recent release note revisions, or if you require additional assistance, please visit the Extreme Networks Support website.

© Extreme Networks. 2019. All rights reserved.