

## Service Release Notes

### WiNG 5.9.8.1-004R

#### IMPORTANT

Service releases are made available to fix specific customer reported issues in a timely manner. Service releases are not as extensively tested as main releases such as **5.9.8.0-002R**. The next maintenance or manufacturing release will incorporate all qualifying and preceding service releases.

This document is an addendum to the release notes for the main release 5.9.8.0-002R.

#### Contents

Features.....	1
Fixed Issues.....	1
Platforms Support.....	2
Notes.....	2

#### Features

Following changes are available.

CR	Description
WING-42812	Interface radio or bluetooth changes are not reflected at the NSight
WING-37563	Symbol name still in the MIB
WING-42317	Legacy Wing Smart RF log for power change – XCA

#### Fixed Issues

Following customer issues are fixed.

ESR/SPR	Description
WING-42733	WING-MIB.mib description indicate Total system ram in megabytes. but return value is kilobytes
WING-42755	Timezone Europe/Moscow is not reflecting the correct time and adds one hour
WING-42492	WiNG v5.9.7.0 UI (403 forbidden) with HTTPS using standard image
WING-42374	AP7662 is crash kernel NULL pointer. PC is at 0x0a%W LR is at process_tx_info+0x178/0x9e0 [qca_ol]
WING-41989	AP7632 kernel panic PC is at kfree
WING-42190	Unable to handle kernel NULL pointer dereference at virtual address 00000004 PC is at skb_recycler_alloc+0xec/0x280 LR is at __netdev_alloc_skb+0x14/0x64
WING-42691	AP7632 Wing 5.9.7 Fkernel BUG
WING-42835	AP7662 crash at PC is at ol_tx_completion_handler+0x910/0x958 [qca_ol] LR is at ol_tx_completion_handler+0x910/0x958 [qca_ol]

WING-42271	Samsung Galaxy A5,A8 and A10 connected to AP8432 show as unknown
WING-41988	AP7632 reboots due to the watchdog
WING-42652	AP7632 reboots with "force reset for recovery" on 5.9.3.1 booting 7.3.0
WING-42402	AP7662 reboot with message %KERN-3-ERR: [ 671.585466] force reset for recovery.
WING-37834	AP7632 After multiple reloads unable to get DHCP leases, and interface related commands are not working
WING-42256	Packet drops for MINT L2 tunnels for a controller-managed deployment
WING-42179	issues with client traffic passing through MiNT tunnel, when VRRP on GW used

## Platforms Support

Supported in this release,

AP8163, AP7502, AP7522, AP7532, AP7562, AP7602, AP7612, AP7622, AP7632, AP7662, AP8432, AP8533, RFS4000, NX5500, NX7500, NX9500, NX9600, VX9000

## Notes

1. WING-42256, WING-42179 -- During downgrade one observation is seen if the CLI is "**l2-tunnel-forward-additional-packet-types wmp vrrp**" then after downgrading to any older build results in "**no l2-tunnel-forward-additional-packet-types**". The user needs to manually needs to again reconfigure wmp.