

Customer Release Notes

ExtremeCloud Appliance

Firmware Version V04.56.04.0009
November 22, 2019

INTRODUCTION:

The ExtremeCloud Appliance, the newest addition to the Smart OmniEdge portfolio, is a next generation orchestration application offering all the mobility services required for modern unified access deployments. The ExtremeCloud Appliance extends all the ease-of-use and simplified workflows of the ExtremeCloud public cloud application to on-prem/private cloud deployments. The ExtremeCloud Appliance includes comprehensive critical network services for wireless and wired connectivity, wireless device secure onboarding, distributed and centralized data paths, role-based access control through the Application Layer (Layer 7), integrated location services, and IoT device onboarding through a single platform. Built on field proven architectures with the latest technology, the embedded operating system supports containerization of applications enabling future expansion of value-added applications for the unified access edge.

The E3120 is a large application appliance meeting the needs of high-density and mission critical deployments with support for up to 10,000 APs/Defenders, 2000 switches, and 100,000 mobility sessions in high-availability mode. An optional redundant power supply is available for ordering separately.

The E2120 is an application appliance meeting the needs of medium sized high-density and mission critical deployments with support for up to 4,000 APs/Defenders, 800 switches and 32,000 mobility sessions in high-availability mode. An optional redundant power supply is available for ordering separately.

The E1120 is an entry to mid-level platform expandable to 250 APs/Defenders, 100 switches, and 4,000 mobility sessions in high-availability mode.

The VE6120 is an elastic virtual appliance that supports up to 1,000 APs/Defenders, up to 400 switches and 16,000 mobility sessions depending on the hosting hardware.

The VE6125 XL is a virtual appliance that supports up to 4,000 APs/Defenders, up to 400 switches and 32,000 mobility sessions depending on the hosting hardware.

The ExtremeCloud Appliance offers the ability to expand capacity to meet any growing business needs. The hardware and virtual packages are available for purchase using a traditional CAPEX model, while the adoption licenses are available as an annual subscription service in 5, 25, 100, 500 and 2000 managed device increments.

This Release includes all previous 4.36.xx.xxxx and 4.56.xx.xxxx enhancements and changes



| Changes in 04.56.04.0009 | I.D |
|---|---------|
| Corrected issue affecting the reporting of statistics in Proxy mode for WiNG controllers with serial numbers different than 14 or 16 characters long. | ECA-760 |
| Improved display of Max Transmit power setting to be scoped to regulatory allowed range of <i>Requested Channel</i> . | ECA-682 |
| Enhanced configuration view of access points to display value of requested channel. | ECA-680 |
| Improved efficiency of <i>Client</i> list views in the UI when rendering a larger number of clients. | ECA-751 |
| Addressed issue with representation of Site status, for sites that only manage switches. | ECA-655 |
| Corrected issue that was preventing column resizing for <i>Client</i> views. | ECA-686 |
| Improved logic handling on Access Point management to protect against possible issues due to fragmented exchanges. | ECA-709 |
| Corrected issue with offset index for interface ID in CTAlias SNMP table. | ECA-734 |
| Addressed issue with client registration for XCA extension of ExtremeWireless Inter-Access Controller mobility domain. | ECA-711 |
| Adjusted default behavior for RADIUS Accounting Start to trigger after client obtains an IP address. | ECA-743 |

| Enhancements in 04.56.04.0009 | |
|---|---------|
| Updated criteria for RADIUS Accounting-start-on-IP to ignore (IPv6) link-local addressing. Accounting will start once client obtains a routable IP address. | ECA-733 |
| Enable POE Status by Default for managed AP7612 client port. | ECA-715 |

Extreme Networks recommends that you thoroughly review this document prior to installing or upgrading this product.

For the latest firmware versions, visit the download site at:
www.extremenetworks.com/support/

FIRMWARE SPECIFICATION:

| Status | Version No. | Type | Release Date |
|------------------|-----------------|---------------------|--------------------|
| Current Version | V.04.56.04.0009 | Maintenance Release | November 22, 2019 |
| Previous Version | V.04.56.03.0004 | Maintenance Release | October 18, 2019 |
| Previous Version | V.04.56.02.0030 | Maintenance Release | September 30, 2019 |
| Previous Version | V.04.56.01.0055 | Service Release | September 25, 2019 |
| Do not use | V.04.56.01.0046 | Feature Release | July 31, 2019 |

SUPPORTED APPLIANCES, ACCESS POINTS AND SWITCHES:

| Product Name | Image |
|---|-------------------------|
| ExtremeCloud Appliance VE6120 VMware (Supported ESXi is 5.1; tested 5.5; 6.0; 6.5) | ECA-04.56.04.0009-1.dle |

| Product Name | Image |
|---|-------------------------------------|
| ExtremeCloud Appliance VE6125 | ECA-04.56.04.0009-1.rse |
| ExtremeCloud Appliance E1120 | ECA-04.56.04.0009-1.sme |
| ExtremeCloud Appliance E2120 | ECA-04.56.04.0009-1.jse |
| ExtremeCloud Appliance E3120 | ECA-04.56.04.0009-1.ose |
| <p>Note: The minimum release dependency for WiNG APs is ExtremeWireless WiNG v5.9.2.2. WiNG APs must be manually upgraded to v5.9.2.2 or above before being adopted by ExtremeCloud Appliance. After upgrade, reset the WiNG AP to the factory settings. For more information, see GTAC article: ExtremeCloud Appliance - WiNG AP will not connect to ExtremeCloud Appliance.</p> | |
| <p>AP-7522-67030-1-WR AP-7522-67030-EU AP-7522-67030-US AP-7522-67030-WR AP-7522-67040-1-WR AP-7522-67040-EU AP-7522-67040-US AP-7522-67040-WR AP-7522E-67030-EU AP-7522E-67030-US AP-7522E-67030-WR AP-7522E-67040-EU AP-7522E-67040-US AP-7522E-67040-WR</p> | <p>AP7522-LEAN-7.2.1.3.008R.img</p> |
| <p>AP-7532-67030-1-WR AP-7532-67030-EU AP-7532-67030-IL AP-7532-67030-US AP-7532-67030-WR AP-7532-67040-1-WR AP-7532-67040-EU AP-7532-67040-US AP-7532-67040-WR</p> | <p>AP7532-LEAN-7.2.1.3.008R.img</p> |
| <p>AP-7562-670042-1-WR AP-7562-670042-EU AP-7562-670042-IL AP-7562-670042-US AP-7562-670042-WR AP-7562-67040-1-WR AP-7562-67040-EU AP-7562-67040-US AP-7562-67040-WR AP-7562-6704M-1-WR</p> | <p>AP7562-LEAN-7.2.1.3.008R.img</p> |

| Product Name | Image |
|---|------------------------------|
| AP-7562-6704M-EU AP-7562-6704M-US AP-7562-6704M-WR | |
| AP-7612-680B30-US AP-7612-680B30-WR | AP7612-LEAN-7.2.1.3.008R.img |
| AP-7632-680B30-IL AP-7632-680B30-TN AP-7632-680B30-US AP-7632-680B30-WR AP-7632-680B40-TN AP-7632-680B40-US AP-7632-680B40-WR | AP7632-LEAN-7.2.1.3.008R.img |
| AP-7662-680B30-IL AP-7662-680B30-TN AP-7662-680B30-US AP-7662-680B30-WR AP-7662-680B40-TN AP-7662-680B40-US AP-7662-680B40-WR | AP7662-LEAN-7.2.1.3.008R.img |
| AP-8432-680B30-EU AP-8432-680B30-US AP-8432-680B30-WR | AP8432-LEAN-7.2.1.3.008R.img |
| AP-8533-68SB30-EU AP-8533-68SB30-US AP-8533-68SB30-WR AP-8533-68SB40-EU AP-8533-68SB40-US AP-8533-68SB40-WR | AP8533-LEAN-7.2.1.3.008R.img |
| <p>NOTE: All AP75xx family access points use binary image AP7532-LEAN-5.9.x.x-xxxR.img. AP7632 and AP7662 access points use binary image AP7632-LEAN-5.9.x.x-xxxR.img. During an image upload, the GUI requires that the name of the binary image matches the name of the AP type. Therefore, a manual rename of the binary image is necessary.</p> | |
| SA201 | AP391x-10.51.08.0004.img |
| AP3912i-FCC AP3912i-ROW | AP391x-10.51.08.0004.img |
| AP3915e-FCC AP3915e-ROW AP3915i-FCC AP3915i-ROW | AP391x-10.51.08.0004.img |
| AP3916ic-FCC AP3916ic-ROW | AP391x-10.51.08.0004.img |

| Product Name | Image |
|--|--|
| AP3916-camera | AP3916IC-V1-0-14-1.dif |
| AP3917e-FCC AP3917e-ROW AP3917i-FCC AP3917i-ROW AP3917k-FCC AP3917k-ROW | AP391x-10.51.08.0004.img |
| AP3935e-FCC AP3935e-ROW AP3935i-FCC AP3935i-IL AP3935i-ROW | AP3935-10.51.08.0004.img |
| AP3965e-FCC AP3965e-ROW AP3965i-FCC AP3965i-ROW | AP3935-10.51.08.0004.img |
| AP505i-FCC AP505i-WR | AP5xx-LEAN-7.2.1.3.008R.img |
| AP510e-FCC AP510e-WR AP510i-FCC AP510i-WR | AP5xx-LEAN-7.2.1.3.008R.img |
| AP560h-FCC AP560h-WR AP560i-FCC AP560i-WR | AP5xx-LEAN-7.2.1.3.008R.img |
| Switches | |
| 210-12p-10GE2 210-24p-10GE2 210-48p-10GE2 210-12p-10GE2 POE 210-24p-10GE2 POE 210-48p-10GE2 POE | 210-series_V1.02.05.0013.stk fp-connector-3.3.0.4.pyz (cloud connector) |
| 220-12p-10GE2 220-24p-10GE2 220-48p-10GE2 220-12p-10GE2 POE 220-24p-10GE2 POE 220-48p-10GE2 POE | 220-series_V1.02.05.0013.stk fp-connector-3.3.0.4.pyz (cloud connector) |
| X440G2-12t-10G4 X440G2-24t-10G4 X440G2-48t-10G4 X440G2-12t-10G4 POE | summitX-30.2.1.8-patch2-4.xos summitX-30.2.1.8-cloud_connector-3.4.1.8.xmod (cloud connector) |

| Product Name | Image |
|--|--|
| X440G2-24t-10G4 POE X440G2-48t-10G4 POE | |
| X620-16x | summitX-30.2.1.8-patch2-4.xos summitX-30.2.1.8-cloud_connector-3.4.1.8.xmod (cloud connector) |

NETWORK MANAGEMENT SOFTWARE SUPPORT

| Network Management Suite (NMS) | Version |
|--------------------------------|---------------|
| ExtremeManagement™ Center | 8.3 or higher |
| ExtremeControl™ | 8.3 or higher |
| ExtremeAnalytics™ | 8.3 or higher |

| Air Defense and Location | Version |
|--------------------------|---------|
| ExtremeAirDefense™ | 10.2 |
| ExtremeLocation™ | 3.1 |

Note:

Platform and AP Configuration functions are not supported by ExtremeManagement™.

ExtremeCloud Appliance does not yet expose support for ExtremeLocation™ Calibration procedure. ExtremeLocation will work correctly for Zone and Occupancy level analytics but does not fully support Position Tracking with this release. Enhanced support for Position Tracking will be added to a future release of ExtremeCloud Appliance.

INSTALLATION INFORMATION:

| Appliance Installations | |
|-------------------------|---|
| E1120 | ExtremeCloud Appliance E1120 Installation Guide |
| E2120 | ExtremeCloud Appliance E2120 Installation Guide |
| E3120 | ExtremeCloud Appliance E3120 Installation Guide |
| VE6120/VE6125 | ExtremeCloud Appliance VE6120/VE6125 Installation Guide |

PREVIOUS RELEASES EXTREMECLOUD APPLIANCE

| Changes in 04.56.03.0004 | I.D |
|--|------------|
| Addressed issue with Synchronization of Session Information across both HA peers, which could affect the ability of a client to roam across APs without re-authenticating when 802.11r configured. | ECA-656 |
| Corrected UI display issue where IP mask and Default Gateway IP addressed for AP7632 may be reported as 0.0.0.0. | ECA-654 |

| Enhancements in 04.56.02.0030 | |
|---|--|
| Support Mesh configuration (MeshConnex) and visualization of Mesh topology for ExtremeWireless WiNG 802.11AC based AP models. (Consult the Supported Models list in the Release Notes document.) | |
| Support Mesh configuration (MeshConnex) and visualization of Mesh topology for ExtremeWireless AP3900 series devices. (Consult Supported Model list in the Release Notes document.) | |
| <p>Introduces support for WPA3 SAE modes for AP500 Series (505/510/560) and ExtremeWireless WiNG AP7522/32/62 and AP8432/8533. Requires AP firmware revision 7.2.2.1-6R or later.</p> <p>Note: WPAv3 is not yet supported by AP7612/32/62 or AP3900 series devices. WPA3 support on those models will be introduced in a future release.</p> <p>This release includes support for WPAV3 Simultaneous Authentication of Equals (SAE) protocol, for modes WPA3-SAE (aka WPA3-Personal) and WPA3-Compatibility (SAE or WPA2 PSK). WPA3 is configurable as the Privacy option on the Network (SSID) configuration.</p> <p>If configured as WPA3-Personal, the SSID will only be available on devices that support WPA3. It will not be present on non-supporting devices.</p> <p>WPA3-Compatibility, on the other hand, will configure the service as WPA-SAE on APs that support WPA3, and equivalent WPA3-PSK on devices that do not yet support WPA3. WPA3-Compatibility mode is the recommended setting for services requiring WPA3 privacy levels.</p> | |
| Enabled Adoption support for AP560x-WR (AP560i-WR and AP560i-WR) variants. Initial country support includes Canada, European Union, and Singapore. | |
| Enable configuration of access point to operate as a Thread (IOT) Gateway for Centralized sites. | |
| <p>Enable advertising of AP Hostname in the AP's beacon to facilitate easier identification of an access point over the RF. AP Hostname is derived from user defined AP Name, but stripped of non-compliant characters. AP Hostname is capped at 32 characters.</p> <p>AP Hostname in beacon is disabled by default. It can be enabled on a per Network/SSID basis for ExtremeWireless WiNG access points, or on a per AP basis based on the Identification pattern for ExtremeWireless (AP3900 series) access points.</p> | |

| | |
|---|--|
| Exposed management of 802.11ax specific features, such as enable/disable OFDMA, Configuration of BSS Coloring values, Target Wake Time (TWT). These functions can be enabled per profile or overridden on a per access point basis. | |
| Enhanced Access Points Device List to allow customization to display Operational Power Level as selectable column (This column is not shown by default.) | |
| Enable support for Client Band Steering for AP500 Series in Centralized sites. | |

| Changes in 04.56.02.0030 | I.D |
|--|------------|
| Addressed issue: Occasional display of power levels at 31dBm and configuration locking when Session Persistence is enabled. Fix addressed by including AP500 Series image WiNG 7.2.0.2-17R. (Default AP image with this package). See Release Notes of 7.2.0.2-17R. | nse0005002 |
| Addressed issue: XCA Switch Console connection never connects to GUI. | nse0005145 |
| Addressed issue: Guest Portal Registered User Info Missing. | nse0004920 |
| Addressed issue: Prior releases of ExtremeCloud Appliance firmware may not have correctly exported the setting for "Preferred Channel" for statically configuration of access points. After upgrade, access points may resort to dynamically selecting best channel. For statically assigned configurations, best practice is to note the desired channel for access points prior to upgrade. Administrator may be required to re-set the Preferred Channel settings. This issue has now been addressed as of 4.56.01.55 and 4.56.02.30. It is corrected for upgrades from these builds forward. | nse0005148 |
| Addressed issue: Addressed calculation error for Total Bytes, which could result in reset of the accumulated value. | nse0004958 |
| Addressed issue: Problem with returning values list of APs by Channel via SNMP. Improves data integrity and reporting by Extreme Management Center. | nse0004936 |
| Addressed issue: Adjusted default to disable Interim RADIUS Accounting by default. Administration selection over interim period will be considered for a future release. | nse0005044 |
| Addressed issue: Wing Proxy paired E3120s - synchronization status changes every 30 seconds. | nse0004440 |
| Addressed issue: Adjusted validation logic for saving Sites to remove occurrences of false validation errors. | nse0004999 |
| Addressed issue: When non-root APs have wired connection to the same network as root APs, a network loop may be created, causing a packet storm. To avoid this condition, either: - Don't connect non-root APs to the same wired network as root APs. or - Use automatic loop detection - Configure all APs as root and enable critical resource monitoring. | nse0005108 |
| Addressed issue: Smart RF - failed to parse error. | nse0004594 |
| Addressed issue: Addressed stability issues when configuring Mesh networks for AP3900 series. | nse0005063 |

| | |
|---|------------|
| Addressed issue: Corrected issue with Captive Portal end-user session expiration on the backup appliance in Active-Passive High availability mode. Improving resource clean up on peer for users that are not actually active on the appliance but may be known due to incorrect redirection configuration (such as DNS reference to inactive system). | nse0005037 |
| Addressed issue where XCA 4.56.01 core dump and RF Manager is down. | nse0004937 |
| Addressed issue: GUI could not start a new capture after a packet capture ended. | nse0004210 |
| Addressed issue: Centralized Mode Mesh GUI report - Missing Parent and Child Link. | nse0005130 |
| Addressed issue: Client location will only be displayed on a floor plan using "show associated clients" and "show unassociated clients" if the system time of the computer where the browser is running matches the system time of the XCA. | nse0004857 |
| Addressed issue: Corrected issue with defining SNMPv3 password length in GUI. | nse0004926 |
| Addressed issue: If the user chooses to reset a switch in CLI mode, using either the GUI RESET Pending action or from the CLI prompt with the "unconfigure switch all" CLI command, the admin account will have the password disabled. As a workaround, the user needs to change the switch to GUI mode first before going back to CLI mode. The user will be able to login in CLI mode using the configured GUI mode admin account password. | nse0004838 |
| Addressed issue: Improved robustness of statistics collection components to address possible instabilities resulting from incorrect source RF data, such as bad channel width. | nse0004905 |

Enhancements in 04.56.01.0055

| | |
|--|------------|
| Feature Enhancement: Support configuring and learning of Static IP definition for Managed APs. | nse0004848 |
| Functionality adjustment: Changed RADIUS accounting behavior to no longer issue 'Accounting Stop' on the source appliance when users roam to the peer appliance in an Active-Active High-Availability configuration. The appliance to which the user roams issues an 'Accounting Start', informing the server that the appliance is now the source for metrics for the corresponding end-system session. | nse0005039 |
| Feature Adjustment: Adjust default behavior of <i>RADIUS Accounting</i> to defer sending until Client IP is known. | nse0005012 |

Changes in 04.56.01.0055

| | I.D |
|--|------------|
| Address setting misconfiguration that can inadvertently constrain connectivity between APs and appliances, leading to possible repeated retries and delay in providing configuration updates. Improved configuration re-trial logic on AP to ensure recovery in case of configuration record push failures. Please upgrade to 7.2.0.2-17R (Default AP image with this package). | nse0004594 |
| Improved robustness of statistics collection components to address possible instabilities resulting from incorrect source RF data, such as bad channel width. | nse0004905 |
| Addressed issue with returning values list of APs by Channel via SNMP. Improves data integrity and reporting by Extreme Management Center. | nse0004936 |
| Improved robustness handling of RF Management components to deal with large volumes of connection establishment between access points and the appliance. | nse0004937 |

| Changes in 04.56.01.0055 | I.D |
|---|--|
| Improved assertion of session attribute uniqueness for session management of access points. | nse0004952 |
| Addressed calculation error for "Total Bytes", which could result in reset of the accumulated value. | nse0004958 |
| Included AP500 Series image WiNG 7.2.0.2-17R. (Default AP image with this package). See Release Notes of 7.2.0.2-17R. | nse0005002 nse0005005 nse0004976 nse0004979 nse0005006 |
| Corrected issue with Captive Portal end-user session expiration on the backup appliance in Active-Passive High availability mode. Improving resource clean up on peer for users that are not actually active on the appliance but may be known due to incorrect redirection configuration (such as DNS reference to inactive system). | nse0005037 |
| Adjusted default to disable Interim RADIUS Accounting by default. Administration selection over interim period will be considered for a future release. | nse0005044 |
| Updated Default AP505, AP510, AP560 image to WiNG 7.2.0.2-017R. | nse0005058 |
| Corrected issue with timer settings for 802.11r that could result in inadvertent re-associations. | nse0005066 |
| Corrected Export/Import logic for <i>Last Requested Channel</i> configuration for WiNG access points. | nse0004624 |

| Enhancements in 04.56.01.0046 |
|--|
| Provide method to deliver Extreme Manufacturing Certificates for VE6120 appliances |
| Block MU-to-MU Client |
| CLI: Switch Diagnostics |
| VE6125 - Extra Large (XL) |
| Reporting: Client Properties - Show associate Site |
| Reporting: AP Reports - Client Load |
| Reporting: AP Reports - Operational Role |
| Reporting: AP Reports - Availability mode |
| Reporting: AP Reports - RF Profile |
| Reporting: AP Reports - RFDM manager |
| Reporting: AP Reports - Ethernet Mac Address |
| Auxiliary CLI configuration for ExtremeXOS switches |
| UI Workflow: Better Regional Zoom for Site Location |
| Support AP560i/h-FCC variants |
| WiNG 7.2: Pick up 7.2 as default image for AP500 APs |
| Custom Channel List override per AP |
| Admin: API Keys |

| Changes in 04.56.01.0046 | I.D |
|--|------------|
| Addressed issue where IPv6 Router Advertisement was not sent as unicast to the wireless client | nse0004062 |
| Addressed issue where Wing Proxy: No radios info for proxied APs after reloaded and XCA reboot/upgrade | nse0004145 |
| Addressed issue where Wing Proxy: No radios info for proxied APs after reloaded and XCA reboot/upgrade | nse0004145 |
| Addressed issue where AP5xx Admission Control Voice and Video does not work for VoIP hand sets | nse0004152 |
| Addressed issue where Client/AP Actions available for Proxied installations | nse0004284 |
| Addressed issue where GUI Alignment Issue - Hover-over edit in the Roles screen is misaligned | nse0004290 |
| Addressed issue where XCA - allows AP510e + high gain ANT config when compliancePower =< 0dBm | nse0004429 |
| Addressed issue where Ap510 distributed cannot associate client with ADSP Inline mode | nse0004447 |
| Addressed issue for Workflow where the delete /edit icon displaced | nse0004449 |
| Addressed issue where Captive Portal timing out after client registration - clients never get authenticated | nse0004457 |
| Addressed issue where Authenticate MAC Locally option keeps getting checked (enabled) automatically under the Network | nse0004470 |
| Addressed issue where Defender GUI front end "gives up" after about 5 seconds where the XCA GUI front end waits longer | nse0004509 |
| Addressed issue where AP510 in smart RF did not start scan on second radio | nse0004584 |
| Addressed issue where Smoke Test: Changing config can make BSSIDs go to 0 on WiNG 7 Identifi AP | nse0004588 |
| Addressed issue where upgrading VE6120 configuration from small to medium causes filters to be lost | nse0004604 |
| Addressed issue where AP505 hidden SSID not working in campus or distributed mode | nse0004628 |
| Addressed issue where Unable to configure required maximum power level in ECA GUI | nse0004660 |
| Addressed issue where XCA Unexpected reboot - mu_s_mgr | nse0004661 |
| Addressed issue where Unable to configure required maximum power level in ECA GUI for AP39xx | nse0004699 |
| Addressed issue where XCA error message when using special chars in SNMP passwords | nse0004718 |
| Addressed issue where deserialize error when trying to save new RF Management Policy | nse0004819 |
| Addressed issue where Unable to import maps from Ekahau 10.x into XCA | nse0004835 |
| Addressed issue where Multicast filters on Fabric Attach VLAN are not preserved on upgrade | nse0004679 |

Known Restrictions and Limitations:

| Known Restriction or Limitation | I.D |
|---|---|
| <p>For High-Availability configurations, during upgrades phases or configuration restore operations, wait until availability link is established and synchronized before attempting to make any new configuration changes. The Availability status will only re-establish to Synched status when both appliances are running the exact same firmware revision.</p> <p>During upgrade periods, the Availability link will only re-establish when both the appliance Status of availability link and synchronization status can be found:</p> <ul style="list-style-type: none"> • "Network health" widget on dashboard • Administration -> System -> Availability | <p>Info ECA-776</p>  |
| <p>Special Characters such as "@" ; / \ " must not be used in configuration fields of ExtremeCloud Appliance, when configuring entities such as (AP, Topology, Site, Network, etc). Some of those characters are treated as control or escape characters. Using special characters in text fields can result in problems when exporting the system configuration and lead to failures on configuration import, such during a system upgrade.</p> | <p>Info ECA-466</p>  |
| <p>Several old Intel clients (i.e. Intel dual band Wireless AC – 7260) if they are using old drivers are NOT seeing BSSID / SSID advertising 11x capability. This is a client issue (forward compatibility). Other older clients may have this issue.</p> <p>See KB https://gtacknowledge.extremenetworks.com/articles/Solution/AP510-Unable-to-see-the-SSID-on-my-laptop</p> <p>NB -- The client driver update <u>must</u> be done from Intel\drivers site because the Windows update reports that the client is running the latest driver.</p> <p>If the client driver cannot be controlled (in a BYOD environment), then the AP radios must be configured on a/n/ac (disable ax) until all clients will upgrade to the latest driver.</p> | <p>Info</p>  |
| <p>Appliances in a High-Availability pair must be at the same exact software revision (and time synched) for configuration synchronization to propagate to the peer. During the upgrade process of a High-Availability pair, any configuration changes made while only one appliance has been upgraded (and therefore resulting in a version mismatch) will not be propagated until the peer is correspondingly upgraded to the same revision. We recommend that you NOT perform any configuration changes to one of the members of a High-Availability pair while the peer has a different software revision.</p> | <p>nse0005086</p> |
| <p>Please allow at least 20 seconds between stopping and re-starting a packet capture on a Site.</p> | <p>nse0004124</p> |
| <p>ExtremeGuest support will be finalized in the next maintenance release and by the release of eGuest server 6.0.</p> | |
| <p>Enabling the appliance as a DHCP server for an attached segment is not currently recommended. Experiencing issues with persistence of Default Gateway and IP range settings. This issue will be corrected in an upcoming release.</p> | <p>nse0003529</p> |
| <p>Wired packet captures for APs in Campus Sites may take up to 1 minute to show results. This issue will be addressed in a subsequent release.</p> | <p>nse0004545</p> |

| Known Restriction or Limitation | I.D |
|---|------------|
| Client Badge in a Floor plan may not show correctly. This issue will be addressed in a subsequent release. | nse0004565 |
| For Off Channel Scan to work on Distributed APs, 'Smart Monitoring' should be disabled in a Smart-RF profile. | nse0004568 |
| When configuring system for NTP time assignment, ensure that NTP server is properly configured. Incorrect time settings (like timestamps far in the future) may adversely affect system operation, such as certificate expiration that may trigger failures in device registration or system instability. | nse0003696 |
| Multicast rules for Topologies (VLANs) are only enforced on Centralized Site deployments (ExtremeWireless APs). The multicast rules are not enforced by Distributed Sites (ExtremeWireless WiNG APs). Topology assignment in Distributed Sites does not filter multicast. Therefore, traffic is bridged between wireless and wired). AP76xx, AP8432, and AP8533 bridge all multicast traffic from wired to wireless network. | Info |
| For service authentication in Distributed Sites (ExtremeWireless WiNG), the Default Unauth Role is applied if the configured RADIUS server can't be reached for authentication. The MBA Timeout Role configured for an MBA network is not applied to an End Client (Mobile Unit [MU]) session. | Info |
| <p>Certain wireless clients (such as Qualcomm Killer Wireless 1535 and Intel 7265D/8260/8265) have been known to not complete the 4-way handshake in order to fulfill the association process in networks that have both PMF/MFP (802.11w) and Fast-Transition (802.11r [FT]) enabled.</p> <p>The currently recommended workaround is to not enable PMF/MFP configuration on a service that is also using 802.11r. Such clients have been demonstrated to work correctly on services with just 802.11r (FT) enabled.</p> | nse0003416 |
| <p>Interaction with ExtremeManagement Center – Management of ExtremeCloud Appliance by ExtremeManagement Center will be enhanced over time with the roadmap. ExtremeManagement Center v8.3 is the minimum release base for integration. Version 8.3 provides recognition of an ExtremeCloud Appliance and representation of Wireless Clients and managed Access Points included in the Wireless tab.</p> <p>Additional integration will be delivered in upcoming releases. ExtremeManagement Center 8.3 is the current recommended minimum release.</p> | Info |
| <p>MAC address for Clients on ExtremeWireless WiNG™ APs are displayed in the Username column. WiNG APs send the username as a MAC Address, causing NAC to reevaluate the rule engines.</p> <p>This situation will be addressed in a future release.</p> | nse0003279 |
| <p>Wireless capture on Wing APs may return the wrong packet captures containing wired packets and wireless packets only for uplink.</p> <p>This situation will be addressed in a future release.</p> | nse0002243 |
| Several features of WiNG 7 OS are still under-development plan towards full feature parity. Several functions may be available in the user interface, due to common provisioning, but are not yet fully supported. | Info |
| Device Level Country override is not supported for WiNG Proxy Mode. Only one country-code assignment per site is supported. All APs at the site must match the same country. | Info |

| Known Restriction or Limitation | I.D |
|---|------------|
| Combining MAC Based Authentication and LAG for switch ports is not currently supported. Engineering is investigating. The issue will be addressed in an upcoming release. | nse0004445 |
| The switch primary/backup availability is not supported on the EXOS switches running the 3.4.1.8 Cloud Connector. This affects the deployments where ExtremeCloud Appliance is configured in an availability pair. If the primary appliance is going down, then the EXOS switches will not send statistics to the backup appliance, and the switch will be marked in red "Critical" state. When the primary appliance is coming up again, the switches will resume, sending statistical information to the primary appliance, and the state of the switch will be marked with a green "Running" state. | nse0004854 |
| The GUI set action "Retrieve Traces" might fail for the EXOS switches. The user might need to repeat setting the "Retrieve Traces" action until the switch uploads the logs and traces tar file to the ExtremeCloud Appliance. | nse0004866 |
| In SmartRF mode, the AP 510 power may drop to 0dBm and returns to 4dBm. Disabling Coverage Hole Recovery will work around this problem. | nse0004881 |
| Currently fabric attach VLANs are not supported as control VLAN for mesh networks. | nse0005152 |
| In condition of on air busy channel conditions it is possible for the ACS not to produce the expected results. In this instances a manual channel selection should be performed. | nse0005045 |
| Platform is not applying Roles based on client's identity. This issue will be solved in a future release. | nse0004425 |
| Stability improvements for serving 802.1x and 802.11r services are included AP500 Series image WiNG 7.2.1.1-06R. (Default AP image with this package). See Release Notes of 7.2.1.1-06R. | nse0005125 |
| Upgrade failure will occur when using special characters (escape back slash) in topology. | nse0004876 |
| An AP crash will occur when starting packet capture from XCA. This problem will be resolved by the 7.3.0 Wing AP release. | nse0005010 |
| When AP5xx (Campus Mode) is used as AirDefense sensor, ADSP 'AP Test' feature works only for wireless networks in channel 1 and 36. It does not work on other channels. | nse0005056 |
| <p>Simultaneous Backup tunnel High-Availability is only enabled for Access Points deployed in Centralized sites. For devices adopted to Distributed sites the device maintains only one connection at a time, to the Primary appliance, and switches to Backup appliance only in case of a High-Availability fail-over event.</p> <p>The Network Health widget on the main dashboard, will only count APs in distributed site against their actual connectivity state (Attached to either Primary or Backup controller). The connectivity counters will therefore only reflect (count) the active tunnel.</p> | nse0004956 |
| GUI Mesh Report is missing the information about Root AP with Ethernet connection. This problem will be addressed in a future release. | nse0005134 |
| In 3120 Platform, some time time series legend for non empty charts are shown as 'NoData' | nse0005137 |
| An issue was observed for AP 7632 where the Tunnel-Private-Group-ID value is not used/ignored and client receives the Default Role. | nse0005030 |

| Known Restriction or Limitation | I.D |
|---|------------|
| Policy rules applied to AP7632 users do not produce expected results. This issue will be resolved in a future release. | nse0004045 |
| Editing or deleting Control VLAN under the Mesh Network is not possible. This problem will be corrected into a future release. | nse0005144 |
| After switching from Whitelist mode to Blacklist mode traffic there is the possibility for the traffic from the blacklisted client not to be filtered and be able to connect to different wireless networks and obtain Internet access. This problem will be resolved in the next release. | nse0004572 |
| Reboot of the peer XCA is required when availability is configured for the first time to ensure synchronization of the configuration of ONBOARD attributes, such as Device Groups. This issue will be addressed in a subsequent release. | nse0005113 |
| When generating tech support on All or Log or Wireless AP, the output of the AP inventory does not include all of the APs that are configured and the AP BSSIDs. This issue will be corrected in a future release. | nse0004902 |
| Corrected resource management issue with authentication library that could prevent administrative access to system's graphical user interface. | nse0005101 |
| Docker requires exclusive use of subnet 172.17.0.0/16 for containers. Customer should not use any IP address in that range for any VLAN or network interface. | nse0005065 |
| Widgets do not show tooltips for Lower and Upper values. This issue will be addressed in a future release. | nse0005136 |
| XCA user accounts created in pre-registration page do not propagate to the AAA policy. | nse0005028 |
| Monitor Networks under Distributed Network, Meshpoint is missing Channel information. This problem will be addressed in a future release. | nse0005135 |

SUPPORTED WEB BROWSERS

For ExtremeCloud Appliance management GUI, the following Web browsers were tested for interoperability:

- Firefox 38.0
- Google Chrome 43.0

Note: Microsoft IE browser is not supported for UI management.

The Wireless Clients (Captive Portal, AAA):

| Browsers | Version | OS |
|----------------|----------------------------|-------------------------|
| Firefox | 68.0 | Windows 10 |
| Chrome | 75.0.37770.142 | Windows 7 Windows 10 |
| Microsoft Edge | 42.17134 | Windows 10 |
| Safari | Preinstalled with iOS 12.2 | iOS 12.2 |

| Browsers | Version | OS |
|--------------|-----------------------------|--|
| Safari | Preinstalled with iOS 9.3.5 | iOS 9.3.5 |
| Microsoft IE | 11 | Windows 7 Windows 8.1 Windows 10 |

PORT LIST

The following list of ports may need to remain open so that the Appliances and APs will function properly on a network that includes protection equipment like a firewall.

ExtremeWireless TCP/UDP Port Assignment Reference

| Comp. Source | Comp. Dest | Protocol (TCP/UDP) | Src Port | Dest Port | Service | Remark | Open Firewall Req'd |
|---|--------------|--------------------|----------|-----------|---------------|---|---------------------|
| Ports for AP/Appliance Communication | | | | | | | |
| Appliance | Access Point | UDP | Any | 13910 | WASSP | Management and Data Tunnel between AP and Appliance | Yes |
| Access Point | Appliance | UDP | Any | 13910 | WASSP | Management and Data Tunnel between AP and Appliance | Yes |
| Appliance | Access Point | UDP | 4500 | Any | Secured WASSP | Management Tunnel between AP and Appliance | Optional |
| Access Point | Appliance | UDP | Any | 4500 | Secured WASSP | Management Tunnel between AP and Appliance | Optional |
| Access Point | Appliance | UDP | Any | 13907 | WASSP | AP Registration to Appliance | Yes |
| Access Point | Appliance | UDP | Any | 67 | DHCP Server | If Appliance is DHCP Server for AP | Optional |
| Access Point | Appliance | UDP | Any | 68 | DHCP Server | If Appliance is DHCP Server for AP | Optional |
| Access Point | Appliance | UDP | Any | 427 | SLP | AP Registration to Appliance | Optional |
| Appliance | Access Point | TCP/UDP | Any | 69 | TFTP | AP image transfer | Yes |
| Access Point | Appliance | TCP/UDP | Any | 69 | TFTP | AP image transfer | Yes |

| Comp. Source | Comp. Dest | Protocol (TCP/UDP) | Src Port | Dest Port | Service | Remark | Open Firewall Req'd |
|---|--------------|--------------------|----------|---------------|----------------|---|---------------------|
| Appliance | Access Point | TCP/UDP | Any | 22 | SCP | AP traces | Yes |
| Any | Access Point | TCP | Any | 2002, 2003 | RCAPD | AP Real Capture (if enabled) | Optional |
| Any | Access Point | TCP/UDP | Any | 22 | SSH | Remote AP login (if enabled) | Optional |
| Any | Access Point | TCP/UDP | Any | 445 | Microsoft CIFS | LDAP support | Optional |
| Any | Access Point | TCP/UDP | Any | 137, 138, 139 | NetBIOS | LDAP support | Optional |
| Ports for Appliance Management | | | | | | | |
| Any | Appliance | TCP/UDP | Any | 22 | SSH | Appliance CLI access | Yes |
| Any | Appliance | TCP/UDP | Any | 5825 | HTTPS | Appliance GUI access | Yes |
| Any | Appliance | TCP/UDP | Any | 161 | SNMP | Appliance SNMP access | Yes |
| Any | Appliance | TCP/UDP | Any | 162 | SNMP Trap | Appliance SNMP access | Yes |
| Any | Appliance | TCP | Any | 80 | HTTP | Appliance SNMP access ICP Self Registration | Yes |
| Any | Appliance | TCP | Any | 443 | HTTPS | ICP Self Registration | Yes |
| Any | Appliance | UDP | 500 | 500 | IKE | IKE phase 1 | Yes |
| Any | Appliance | TCP/UDP | Any | 69 | TFTP | TFTP support | Yes |
| Any | Appliance | UDP | Any | 4500 | IPSec | IPSec NAT traversal | Yes |
| Any | Appliance | UDP | Any | 13907 | Discovery | Used by Discovery | Yes |
| Any | Appliance | UDP | Any | 13910 | WASSP | Used by L3 WASSP | Yes |
| Ports for Inter Controller Mobility¹ and Availability | | | | | | | |
| Appliance | Appliance | UDP | Any | 13911 | WASSP | Mobility and Availability Tunnel | Yes |
| Appliance | Appliance | TCP | Any | 427 | SLP | SLP Directory | Yes |

¹For extension of ExtremeWireless deployment via Inter Controller Mobility.

| Comp. Source | Comp. Dest | Protocol (TCP/UDP) | Src Port | Dest Port | Service | Remark | Open Firewall Req'd |
|------------------------------------|------------------|--------------------|----------|-----------|---|---|---------------------|
| Appliance | Appliance | TCP | Any | 20506 | Langley | Remote Langley Secure | Yes |
| Appliance | Appliance | TCP | Any | 60606 | Mobility | VN MGR | Yes |
| Appliance | Appliance | TCP | Any | 123 | NTP | Availability time sync | Yes |
| Appliance | DHCP Server | UDP | Any | 67 | SLP | Asking DHCP Server for SLP DA | Yes |
| DHCP Server | Appliance | UDP | Any | 68 | SLP | RespoECA from DHCP Server for SLP DA request | Yes |
| Core Back-End Communication | | | | | | | |
| Appliance | DNS Server | UDP | Any | 53 | DNS | If using DNS | Optional |
| Appliance | Syslog Server | UDP | Any | 514 | Syslog | If Appliance logs to external syslog server | Optional |
| Appliance | RADIUS Server | UDP | Any | 1812 | RADIUS Authentication and Authorization | If using RADIUS AAA | Optional |
| Appliance | RADIUS Server | UDP | Any | 1813 | RADIUS Accounting | If enabled RADIUS accounting | Optional |
| Appliance | RADIUS server | UDP | Any | 1814 | RADIUS Authentication and Authorization | If using RADIUS AAA | Optional |
| Appliance | RADIUS server | UDP | Any | 1815 | RADIUS Accounting | If enabled RADIUS Accounting | Optional |
| Dynamic Auth. Server (NAC) | Appliance | UDP | Any | 3799 | DAS | Request from DAS client to disconnect a specific client | Optional |
| Appliance | AeroScout Server | UDP | 1144 | 12092 | Location Based Service Proxy | Aeroscout Location-Based Service | Optional |
| AeroScout Server | Appliance | UDP | 12092 | 1144 | Location Based | Aeroscout Location-Based Service | Optional |

| Comp. Source | Comp. Dest | Protocol (TCP/UDP) | Src Port | Dest Port | Service | Remark | Open Firewall Req'd |
|--------------|------------|--------------------|----------|-----------|---------------|--------|---------------------|
| | | | | | Service Proxy | | |

IETF STANDARDS MIB SUPPORT:

| RFC No. | Title | Groups Supported |
|-------------------------|------------------|---|
| Draft version of 802.11 | IEEE802dot11-MIB | |
| 1213 | RFC1213-MIB | Most of the objects supported |
| 1573 | IF-MIB | ifTable and interface scalar supported |
| 1907 | SNMPv2-MIB | System scalars supported |
| 1493 | BRIDGE-MIB | EWC supports relevant subset of the MIB |
| 2674 | P-BRIDGE-MIB | EWC supports relevant subset of the MIB |
| 2674 | Q-BRIDGE-MIB | EWC supports relevant subset of the MIB |

EXTREME NETWORKS PRIVATE ENTERPRISE MIB SUPPORT

Extreme Networks Private Enterprise MIBs are available in ASN.1 format from the Extreme Networks website at: <https://extremeportal.force.com/>

Standard MIBs

| Title | Description |
|------------------|---|
| IEEE802dot11-MIB | Standard MIB for wireless devices |
| RFC1213-MIB.my | Standard MIB for system information |
| IF-MIB | Interface MIB |
| SNMPv2-MIB | Standard MIB for system information |
| BRIDGE-MIB | VLAN configuration information that pertains to EWC |
| P-BRIDGE-MIB | VLAN configuration information that pertains to EWC |
| Q-BRIDGE-MIB | VLAN configuration information that pertains to EWC |

Siemens Proprietary MIB

| Title | Description |
|----------------------------|--|
| HIPATH-WIRELESS-HWC-MIB.my | Configuration and statistics related to EWC and associated objects |

| | |
|------------------------------------|---|
| HIPATH-WIRELESS-PRODUCTS-MIB.my | Defines product classes |
| HIPATH-WIRELESS-DOT11-EXTNS-MIB.my | Extension to IEEE802dot11-MIB that complements standard MIB |
| HIPATH-WIRELESS-SMI.my | Root for Chantry/Siemens MIB |

802.11AC AND 802.11N CLIENTS

Please refer to the latest release notes for ExtremeWireless™ 10.41.09 or later and/or ExtremeWireless WiNG 5.9.02 or later for the list of compatibility test devices.

RADIUS SERVERS AND SUPPLICANTS

RADIUS Servers Used During Testing

| Vendor | Model OS | Version |
|----------------|----------------|---------------------------|
| FreeRADIUS | 1.1.6 | FreeRADIUS |
| FreeRADIUS IAS | 1.0.1 | FreeRADIUS |
| | 5.2.3790.3959 | Microsoft Server 2003 IAS |
| SBR50 | 6.1.6 | SBR Enterprise edition |
| NPS | 6.0.6002.18005 | Microsoft Server 2008 NPS |

802.1x Supplicants Supported

| Vendor | Model OS | Version |
|--------------------------|---|---|
| Juniper Networks® / Funk | Odyssey client | Version 5.10.14353.0 |
| | | Version 5.00.12709.0 |
| | | Version 4.60.49335.0 |
| Microsoft® | Wireless Zero Configuration | Version Windows XP-4K-891859-Beta1 |
| | Wireless Network Connection Configuration | Version Microsoft Window Server 2003, Enterprise Edition R2 SP2 |
| | Wi-Fi Protected Access 2 (WPA2)/Wireless Provisioning Services Information Element (WPS IE) update for Windows XP with Service Pack 2 | Version WindowsXP-KB893357-v2-x86-ENU.exe |
| Intel® | Intel PRO Set/Wireless | Version 13.0.0.x (with Windows® Intel® driver version 13.0.0.x) |

| Vendor | Model OS | Version |
|--------------------------|---|------------------------|
| Microsoft® Wireless Zero | Windows 7, 8, 8.1 Pro, 10 Pro Windows Phone 8.1, Windows Mobile 10 | Provided with Windows® |

Appliance LAN Switch Verification

| Vendor | Model OS | Version | Role |
|---------|------------------|---|------------------|
| Extreme | X-460-G2 | 12.5.4.5 | ECA connection |
| Extreme | X440G2-48p-10G4 | 21.1.1.4 | ECA connectivity |
| Extreme | Summit 300-48 | 7.6e1.4 | ECA connection |
| Extreme | VSP-4850GTS-PWR | (6.0.1.1_B003) (PRIVATE) HW Base: ERS 4850 | ECA connection |
| Extreme | K6 | 08.63.02.0004 | ECA connection |
| Extreme | K6 | 08.42.03.0006 | ECA connection |
| Extreme | X440G2-48p-10GE4 | 21.1.5.2 | ECA connection |
| Extreme | X440-G2-12p | 21.1.1.4 | ECA connection |
| Extreme | X460-48p | 12.5.4.5 | ECA connection |
| Cisco | Catalyst 3550 | 12.1(19)EA1c | ECA connection |

CERTIFICATION AUTHORITY

| Server Vendor | Model OS | Version |
|---------------|--|---------------|
| Microsoft CA | Windows Server 2003 Enterprise Edition | 5.2.3790.1830 |
| Microsoft CA | Windows Server 2008 Enterprise Edition | 6.0 |
| OpenSSL | Linux | 0.9.8e |

RADIUS ATTRIBUTES SUPPORT

RADIUS Authentication and Authorization Attributes

| Attribute | RFC Source |
|--------------------|--------------------|
| Called-Station-Id | RFC 2865, RFC 3580 |
| Calling-Station-Id | RFC 2865, RFC 3580 |
| Class | RFC 2865 |
| EAP-Message | RFC 3579 |
| Event-Timestamp | RFC 2869 |
| Filter-Id | RFC 2865, RFC 3580 |

| Attribute | RFC Source |
|-----------------------|------------------------------|
| Framed-IPv6-Pool | RFC 3162 |
| Framed-MTU | RFC 2865, RFC 3580 |
| Framed-Pool | RFC 2869 |
| Idle-Timeout | RFC 2865, RFC 3580 |
| Message-Authenticator | RFC 3579 |
| NAS-Identifier | RFC 2865, RFC 3580 |
| NAS-IP-Address | RFC 2865, RFC 3580 |
| NAS-IPv6-Address | RFC 3162 |
| NAS-Port | RFC 2865, RFC 3580 |
| NAS-Port-Id | RFC 2865, RFC 3580 |
| NAS-Port-Type | RFC 2865, RFC 3580 |
| Password-Retry | RFC 2869 |
| Service-Type | RFC 2865, RFC 3580 |
| Session-Timeout | RFC 2865 |
| State | RFC 2865 |
| Termination-Action | RFC 2865, RFC 3580 |
| Tunnel Attributes | RFC 2867, RFC 2868, RFC 3580 |
| User-Name | RFC 2865, RFC 3580 |
| Vendor-Specific | RFC 2865 |

RADIUS Accounting Attributes

| Attribute | RFC Source |
|-----------------------|------------|
| Acct-Authentic | RFC 2866 |
| Acct-Delay-Time | RFC 2866 |
| Acct-Input-Octets | RFC 2866 |
| Acct-Input-Packets | RFC 2866 |
| Acct-Interim-Interval | RFC 2869 |
| Acct-Output-Octets | RFC 2866 |
| Acct-Output-Packets | RFC 2866 |
| Acct-Session-Id | RFC 2866 |
| Acct-Session-Time | RFC 2866 |

| | |
|----------------------|----------|
| Acct-Status-Type | RFC 2866 |
| Acct-Terminate-Cause | RFC 2866 |

GLOBAL SUPPORT:

By Phone: +1 800-998-2408 (toll-free in U.S. and Canada)

For the toll-free support number in your country:
<https://extremeportal.force.com/>

By Email: support@extremenetworks.com

By Web: <https://extremeportal.force.com/>

By Mail: Extreme Networks, Inc.
6480 Via Del Oro
San Jose, CA 95119 USA

For information regarding the latest software release, recent release note revisions, or if you require additional assistance, please visit the Extreme Networks Support website.

Extreme Networks and the Extreme Networks logo are trademarks or registered trademarks of Extreme Networks, Inc. in the United States and/or other countries. All other names (including any product names) mentioned in this document are the property of their respective owners and may be trademarks or registered trademarks of their respective companies/owners. Extreme Networks IPS includes software whose copyright is licensed from MySQL AB.

For additional information on Extreme Networks trademarks, please see: www.extremenetworks.com/company/legal/trademarks/