



February 2026

NetIron OS 6.3.00m for ExtremeRouting MLX Series Devices

Release Notes 1.0

Copyright © 2026 Extreme Networks, Inc. All Rights Reserved.

Legal Notice

Extreme Networks, Inc. reserves the right to make changes in specifications and other information contained in this document and its website without prior notice. The reader should in all cases consult representatives of Extreme Networks to determine whether any such changes have been made.

The hardware, firmware, software or any specifications described or referred to in this document are subject to change without notice.

Trademarks

Extreme Networks and the Extreme Networks logo are trademarks or registered trademarks of Extreme Networks, Inc. in the United States and/or other countries.

All other names (including any product names) mentioned in this document are the property of their respective owners and may be trademarks or registered trademarks of their respective companies/owners.

For additional information on Extreme Networks trademarks, please see:

www.extremenetworks.com/company/legal/trademarks

Open Source Declarations

Some software files have been licensed under certain open source or third-party licenses. End-user license agreements and open source declarations can be found at:

www.extremenetworks.com/support/policies/software-licensing

Contents

Preface	7
Contacting Extreme Technical Support.....	7
Extreme resources	7
Document feedback.....	8
Overview	9
Behavior changes	10
Behavior changes in release NetIron 6.3.00m	10
Behavior changes in release NetIron 6.3.00k	10
Behavior changes in release NetIron 6.3.00j	10
Behavior changes in release NetIron 6.3.00h	10
Behavior changes in release NetIron 6.3.00g	10
Behavior changes in release NetIron 6.3.00f	10
Behavior changes in release NetIron 6.3.00e	10
Behavior changes in release NetIron 6.3.00d	10
Behavior changes in release NetIron 6.3.00c	10
Behavior changes in release NetIron 6.3.00a1	10
Software Features.....	12
New software features introduced in R6.3.00m	12
New software features introduced in R6.3.00k.....	12
New software features introduced in R6.3.00j.....	12
New software features introduced in R6.3.00h.....	12
New software features introduced in R6.3.00g.....	12
New software features introduced in R6.3.00f	12
New software features introduced in R6.3.00e.....	12
New software features introduced in R6.3.00d.....	13
New software features introduced in R6.3.00c.....	13
New software features introduced in R6.3.00.....	13
CLI commands.....	15
New CLI commands in NetIron R6.3.00m	15
New CLI commands in NetIron R6.3.00k	15
New CLI commands in NetIron R6.3.00j	15
New CLI commands in NetIron R6.3.00h	15

New CLI commands in NetIron R6.3.00g	15
New CLI commands in NetIron R6.3.00f	15
New CLI commands in NetIron R6.3.00e	15
New CLI commands in NetIron R6.3.00d	15
New CLI commands in NetIron R6.3.00c	15
New CLI commands in NetIron R6.3.00	15
Modified CLI commands in NetIron R6.3.00d	16
Modified commands	16
Deprecated commands in NetIron R6.3.00d	16
Deprecated commands	16
Reinstated commands in NetIron R6.3.00e	16
The following LP debug commands are reinstated which were removed in NetIron R6.3.00d	16
MIBs and messages	18
MIBs	18
Messages	19
RFCs and standards	19
Hardware support	20
Supported Devices	20
Supported devices for Network Packet Broker R6.3.00a	20
Supported Modules	21
Supported Power Supplies	27
Supported Optics	28
Software upgrade and downgrade	29
Image file names	29
Upgrading MLX Series and NetIron XMR devices	29
Upgrading CER 2000 Series devices	32
Upgrading Network Packet Broker devices	33
Migration path	37
Upgrade and downgrade considerations	37
Limitations and restrictions	48
Important notes	48
Defects	50
TSBs—Critical issues to consider prior to installing this release	50
Open Defects in NI6.3.00m	51

Open Defects in NI6.3.00k	51
Open Defects in NI6.3.00j	51
Open Defects in NI 6.3.00h	51
Open Defects in NI6.3.00g	51
Open Defects in NI6.3.00f	51
Closed with code changes NI6.3.00m	53
Closed with code changes NI6.3.00k	53
Closed with code changes NI6.3.00j	54
Closed with code changes NI6.3.00h	56
Closed with code changes NI6.3.00g	56
Closed with code changes NI6.3.00f	59
Closed with code changes NI6.3.00d	72
Closed with code changes NI6.3.00c	84
Closed with code changes NI6.3.00a1	100

Document History

Version	Summary of changes	Publication date
1.0	Initial release	February 2026

Preface

Contacting Extreme Technical Support

As an Extreme customer, you can contact Extreme Technical Support using one of the following methods: 24x7 online or by telephone. OEM customers should contact their OEM/solution provider. If you require assistance, contact Extreme Networks using one of the following methods:

- GTAC (Global Technical Assistance Center) for immediate support
- Phone: 1-800-998-2408 (toll-free in U.S. and Canada) or +1 408-579-2826. For the support phone number in your country, visit: www.extremenetworks.com/support/contact.
- Email: support@extremenetworks.com. To expedite your message, enter the product name or model number in the subject line.
- GTAC Knowledge - Get on-demand and tested resolutions from the GTAC Knowledgebase, or create a help case if you need more guidance.
- The Hub - A forum for Extreme customers to connect with one another, get questions answered, share ideas and feedback, and get problems solved. This community is monitored by Extreme Networks employees, but is not intended to replace specific guidance from GTAC.
- Support Portal - Manage cases, downloads, service contracts, product licensing, and training and certifications.

Before contacting Extreme Networks for technical support, have the following information ready:

- Your Extreme Networks service contract number and/or serial numbers for all involved Extreme Networks products
- A description of the failure
- A description of any action(s) already taken to resolve the problem
- A description of your network environment (such as layout, cable type, other relevant environmental information)
- Network load at the time of trouble (if known)
- The device history (for example, if you have returned the device before, or if this is a recurring problem)
- Any related RMA (Return Material Authorization) numbers

Extreme resources

Visit the Extreme website to locate related documentation for your product and additional Extreme resources.

White papers, data sheets, and the most recent versions of Extreme software and hardware manuals are available at www.extremenetworks.com. Product documentation for all supported releases is available to registered users at <https://www.extremenetworks.com/support/documentation/>.

Document feedback

Quality is our first concern at Extreme, and we have made every effort to ensure the accuracy and completeness of this document. However, if you find an error or an omission, or you think that a topic needs further development, we want to hear from you.

You can provide feedback in two ways:

- Use our short online feedback form at <https://www.extremenetworks.com/documentation-feedback/>
- Email us at documentation@extremenetworks.com

Provide the publication title, part number, and as much detail as possible, including the topic heading and page number if applicable, as well as your suggestions for improvement.

Overview

NetIron OS Release 6.3.00 enhances the capabilities of ExtremeRouting MLX Series, and ExtremeRouting CER 2000 Series in the following areas:

- * BGP services,

- * Network Packet Broker functionality

In addition, this release also has further enhancements to manageability and troubleshooting functions to enable efficient network operations.

With these features, the MLX Series Router continues as the leading platform for converged data center and service provider network services.

Behavior changes

[Behavior changes in release NetIron 6.3.00m](#)

There are no behavior changes in release NetIron 6.3.00m.

[Behavior changes in release NetIron 6.3.00k](#)

There are no behavior changes in release NetIron 6.3.00k.

[Behavior changes in release NetIron 6.3.00j](#)

There are no behavior changes in release NetIron 6.3.00j.

[Behavior changes in release NetIron 6.3.00h](#)

There are no behavior changes in release NetIron 6.3.00h.

[Behavior changes in release NetIron 6.3.00g](#)

There are no behavior changes in release NetIron 6.3.00g.

[Behavior changes in release NetIron 6.3.00f](#)

There are no behavior changes in release NetIron 6.3.00f.

[Behavior changes in release NetIron 6.3.00e](#)

There are no behavior changes in release NetIron 6.3.00e.

[Behavior changes in release NetIron 6.3.00d](#)

There are no behavior changes in release NetIron 6.3.00d.

[Behavior changes in release NetIron 6.3.00c](#)

There are no behavior changes in release NetIron 6.3.00c.

[Behavior changes in release NetIron 6.3.00a1](#)

There are no behavior changes in release NetIron 6.3.00a1.

Software Features

NOTE: The NetIron 6.3.00 release (the image files and the documentation) is no longer available from the Extreme Portal. New software features introduced in release 6.3.00 are included in release 6.3.00a.

[New software features introduced in R6.3.00m](#)

No new software features are introduced in NetIron 6.3.00m release.

[New software features introduced in R6.3.00k](#)

No new software features are introduced in NetIron 6.3.00k release.

[New software features introduced in R6.3.00j](#)

No new software features are introduced in NetIron 6.3.00j release.

[New software features introduced in R6.3.00h](#)

No new software features are introduced in NetIron 6.3.00h release.

[New software features introduced in R6.3.00g](#)

No new software features are introduced in NetIron 6.3.00g release.

[New software features introduced in R6.3.00f](#)

No new software features are introduced in NetIron 6.3.00f release.

[New software features introduced in R6.3.00e](#)

No new software features are introduced in NetIron 6.3.00e release.

New software features introduced in R6.3.00d

The following software features are introduced in NetIron 6.3.00d release.

- Support was added for nested DHCPv6 headers.

New software features introduced in R6.3.00c

The following software features are introduced in NetIron 6.3.00c release.

Management features and enhancements

- **New CAM profiles:** This feature adds two new CAM profiles which is an extension from the existing profiles to increase the size of IP-VPN partition (Multiservice-7) and IPv4 (IPv4-extended).

Monitoring

- **CAM error monitoring and recovery:** This feature is an addition of NP memory registers CAM1 ERR STATUS1 REGISTER and CAM3 ERR STATUS1 REGISTER into CAM error monitoring and takes necessary recovery action.

New software features introduced in R6.3.00

The following software features are introduced in NetIron 6.3.00 release.

Management features and enhancements

- **SSH server management:** This feature configures the SSH server to allow incoming SSH connection requests from ports that belong to any VRF and from the out-of-band management port when the management VRF is configured.
- **Increase maximum telnet session number from 5 to 10:** The maximum telnet session is increased from 5 to 10.

Security

- **Regular expression support in RADIUS command authorization:** The Extreme-specific RADIUS attribute `foundry-command-string` now supports specifying a range of data for a CLI command.

IP Routing

- **BGP Large Communities:** RFC8092 BGP Large Communities attribute is supported. All routes with this attribute belong to the communities specified in the attribute.
- **Increase number of loopback interfaces in NetIron to 1024:** The number of supported loopback interfaces is increased to 1024.

Monitoring

- Beginning with Extreme NetIron Release 6.3.00a, the Network Processor (NP) error monitoring and recovery feature is supported on Extreme NetIron 8x10G, 2x100G, 20x10G, 2x100G-CFP2 and 4x10G-IPSEC line card modules for ExtremeRouting XMR/MLX Series.

Network Packet Broker

- The maximum TVF LAG FID group size (system-max tvf-lag-lb-fid-group) is increased to 32.

CLI commands

New CLI commands in NetIron R6.3.00m

- None

New CLI commands in NetIron R6.3.00k

- None

New CLI commands in NetIron R6.3.00j

- None

New CLI commands in NetIron R6.3.00h

- None

New CLI commands in NetIron R6.3.00g

- None

New CLI commands in NetIron R6.3.00f

- kill tftp 1
NOTE: The 'kill tftp <session-id>' command resets the tftp.current_operation value back to 0 from non-zero value so that new TFTP/SCP sessions can be created.
The valid value for <session-id> is 1.
- show ip ssh tftp

This command display output as below.

```
mlx#sh ip ssh tftp
```

```
Jun 9 18:32:18.223 TFTP: cli_show_tftp_read: tftp.current_operation = 0
```

New CLI commands in NetIron R6.3.00e

- None

New CLI commands in NetIron R6.3.00d

- None

New CLI commands in NetIron R6.3.00c

- None

New CLI commands in NetIron R6.3.00

- ip large-community-list extended
- ip large-community-list standard
- ip ssh include-all-vrf
- match large-community-list
- set large-community
- set large-community-list
- system-max loopback-interface
- show default values
- show ip bgp routes large-community
- show ip bgp routes large-community-access-list
- show ip bgp routes large-community-regex

- show ip bgp routes detail large-community
- show ip bgp routes detail large-community-access-list
- show ip bgp routes detail large-community-regex

Modified CLI commands in NetIron R6.3.00d

- show ip bgp vrf vrf-all tags
- show ipv6 bgp vrf vrf-all tags

Modified commands

- ip ssh strict-management-vrf
- neighbor send-community
- show ip ssh config
- show who
- system-max tvf-lag-lb-fid-group

Deprecated commands in NetIron R6.3.00d

- None

Deprecated commands

There are no deprecated commands in this release.

Reinstated commands in NetIron R6.3.00e

The following LP debug commands are reinstated which were removed in NetIron R6.3.00d.

- access-list
- alarm-monitoring
- all
- arp-guard
- bfd
- cfm
- cluster
- destination
- dot1x-mka
- erp
- filters
- gtp-de-encapsulation
- gvrp
- HQOS
- lkev2

- Ip
- Ipsec
- Iptunnel
- Ipv6
- LACP
- link-keepalive
- link-oam
- LLDP
- Loopdetect
- Mac
- Match-payload-len
- Mmrp
- Mport
- Mrp
- Mvrp
- Openflow
- packet-encap-proc
- packet-timestamp
- pos
- profile
- source-port-label
- statistics
- trace-l2
- tvf-domain
- Vlan
- Vlan-translation
- Vll
- Vpls
- Vsrp
- Y1731

MIBs and messages

MIBs

New MIB Objects in 6.3.00m

No MIB objects were introduced in release NetIron 6.3.00m

New MIB Objects in 6.3.00k

No MIB objects were introduced in release NetIron 6.3.00k

New MIB Objects in 6.3.00j

No MIB objects were introduced in release NetIron 6.3.00j

New MIB Objects in 6.3.00h

No MIB objects were introduced in release NetIron 6.3.00h

New MIB Objects in 6.3.00g

No MIB objects were introduced in release NetIron 6.3.00g

New MIB Objects in 6.3.00f

No MIB objects were introduced in release NetIron 6.3.00f

New MIB Objects in 6.3.00e

No MIB objects were introduced in release NetIron 6.3.00e

New MIB Objects in 6.3.00d

No MIB objects were introduced in release NetIron 6.3.00d

Modified MIBs in 6.3.00c

The following MIBs have been modified for this release: Not Applicable

Deprecated MIBs in 6.3.00c

The following MIBs have been deprecated beginning with this release: Not Applicable

New MIB Objects in 6.3.00c

No MIB objects were introduced in release NetIron 6.3.00c

Modified MIBs

The following MIBs have been modified for this release: Not Applicable

Deprecated MIBs

The following MIBs have been deprecated beginning with this release: Not Applicable

Messages

New Messages

The following messages are new in this release: Not Applicable

Modified Messages

The following messages have been modified for this release: Not Applicable

Deprecated Messages

The following messages have been deprecated beginning with this release:

- Not Applicable

RFCs and standards

The following new RFC is supported in this release.

- RFC8092 -- BGP Large Communities Attribute

Hardware support

Supported Devices

The following devices are supported in this release:

NOTE: Beginning with NetIron OS 6.3.00a and later, the ExtremeSwitching CES 2000 Series devices are not supported. Refer to the [End of Sale and End of Support](#) page for additional information.

ExtremeRouting XMR Series	ExtremeRouting MLX Series	ExtremeRouting CER 2000 Series
XMR 4000	MLX-4	CER-RT 2024C-4X
XMR 8000	MLX-8	CER-RT 2024F-4X
XMR 16000	MLX-16	CER 2024C
XMR 32000	MLX-32	CER-RT 2024C
	MLXe-4	CER 2024F
	MLXe-8	CER-RT 2024F
	MLXe-16	CER 2048C
	MLXe-32	CER-RT 2048C
		CER 2048CX
		CER-RT 2048CX
		CER 2048F
		CER-RT 2048F
		CER 2048FX
		CER-RT 2048FX

Supported devices for Network Packet Broker R6.3.00a

XMR Series	MLX Series
XMR 4000	MLX-4
XMR 8000	MLX-8
XMR 16000	MLX-16
XMR 32000	MLX-32
	MLXe-4
	MLXe-8
	MLXe-16
	MLXe-32

Supported Modules

The following interface modules are supported in this release:

Module	Description	Compatible devices		Generation
		MLXe with MLX or MR2-M mgmt. module	MLXe with XMR or MR2-X mgmt. module	
BR-MLX-10GX4-IPSEC-M	MLX 4-port 10 GbE/1 GbE combo and 4-port 1 GbE (-M) IPsec module with 512,000 IPv4 routes or 240,000 IPv6 routes in hardware	Yes	Yes	3
BR-MLX-10GX20-X2	MLX 20-port 10 GbE/1 GbE (X2) SFP+ and SFP combo module with extended route table support for up to 2.4 million IPv4 or 1.8 million IPv6 routes in hardware. Integrated hardware-enabled MACsec.	Yes	Yes	3
BR-MLX-10GX20-M	MLX 20-port 10 GbE/1 GbE (M) combo module. Supports SFP+ and SFP with up to 512,000 IPv4 routes or 240,000 IPv6 routes in FIB. Integrated hardware-enabled MACsec.	Yes	Yes	3
BR-MLX-1GCX24-X-ML	MLX 24-port (X) 10/100/1,000 copper (RJ-45) module with IPv4/IPv6/MPLS hardware support. Supports 512,000 IPv4 routes in FIB. License upgradable to "X" scalability (1 million IPv4 routes in hardware).	Yes	No	1.1

Module	Description	Compatible devices		Generation
		MLXe with MLX or MR2-M mgmt. module	MLXe with XMR or MR2-X mgmt. module	
BR-MLX-100GX2-CFP2-M	MLX 2-port 100 GbE (M) CFP2 module. Supports 512,000 IPv4 routes in FIB.	Yes	Yes	3
BR-MLX-100GX2-CFP2-X2	MLX 2-port 100 GbE (X2) CFP2 module with extended route table support for up to 2.4 million IPv4 or 1.8 million IPv6 routes in hardware.	Yes	Yes	3
BR-MLX-10GX8-X	MLX Series 8-port 10 GbE (X) module with IPv4/IPv6/MPLS hardware support—requires SFP optics. Supports up to 1 million IPv4 routes in FIB. Requires high-speed switch fabric modules.	Yes	Yes	2
BR-MLX-1GCX24-X	MLX 24-port (X) 10/100/1,000 copper (RJ-45) module with IPv4/IPv6/MPLS hardware support. Supports 1 million IPv4 routes in hardware.	Yes	Yes	1.1

Module	Description	Compatible devices		Generation
		MLXe with MLX or MR2-M mgmt. module	MLXe with XMR or MR2-X mgmt. module	
BR-MLX-40GX4-M	MLX Series 4-port 40 GbE (M) module with IPv4/IPv6/MPLS hardware support and support for QSFP+ optics, including both LR and SR versions. Supports up to 512,000 IPv4 routes or 128,000 IPv6 routes. Requires high-speed switch fabric modules.	Yes	Yes	3
BR-MLX-10GX4-X	MLX Series 4-port 10 GbE (X) module with IPv4/IPv6/MPLS hardware support—requires XFP optics. Supports 1 million IPv4 routes in hardware.	Yes	Yes	1.1
BR-MLX-10GX4-X-ML	MLX/MLXe 4-port 10 GbE (ML) module with IPv4/IPv6/MPLS hardware support—requires XFP optics. Supports 512,000 IPv4 routes in FIB. License upgradable to “X” scalability (1 million IPv4 routes in hardware).	Yes	No	1.1
NI-MLX-10GX8-M	MLX Series 8-port 10 GbE (M) module with IPv4/IPv6/MPLS hardware support and up to 512,000 IPv4 routes—requires SFP+ optics and high-speed switch fabric modules.	Yes	No	2

Module	Description	Compatible devices		Generation
		MLXe with MLX or MR2-M mgmt. module	MLXe with XMR or MR2-X mgmt. module	
BR-MLX-1GFX24-X	MLX Series 24-port FE/GbE (SFP) module, with IPv4/IPv6/MPLS hardware support. Supports 1 million IPv4 routes in hardware.	Yes	Yes	1.1
BR-MLX-1GFX24-X-ML	MLX Series 24-port FE/GbE (SFP) module, with IPv4/IPv6/MPLS hardware support. Supports 512,000 IPv4 routes in FIB. License upgradable to “X” scalability (1 million IPv4 routes in hardware).	Yes	No	1.1
BR-MLX-10GX24-DM	MLXe 24-port 10 GbE module with IPv4/IPv6/MPLS hardware support—requires SFP optics. Supports 256,000 IPv4 routes in FIB.	Yes	No	3a
NI-MLX-10GX8-D	MLX Series 8-port 10-GbE (D) module with IPv4/IPv6 hardware support - requires SFPP optics. Supports 256K IPv4 routes in FIB. Does not support MPLS. Requires high speed switch fabric modules.	Yes	No	2

Module	Description	Compatible devices		Generation
		MLXe with MLX or MR2-M mgmt. module	MLXe with XMR or MR2-X mgmt. module	
BR-MLX-10GX10-X2	MLX 10-port 10-Gbe/1Gbe (X2) SFP+ and SFP combo module with extended route table support up to 2M IPv4 and 800K IPv6 routes in hardware. MACsec enabled. Upgradeable to 20X10G-X2 using additional software license.	Yes	Yes	3
BR-MLX-1GX20-U10G-M	MLXe twenty (20)-port 1-GBE/1-GBE (M) module with IPv4/IPv6/MPLS hardware support. Requires SFP optics. Supports 512K IPv4 routes in FIB. Requires high speed switch fabric modules. Upgradeable to 10G, with BR-MLX-1GX20-U10G-MUPG license.	Yes	Yes	3

Module	Description	Compatible devices		Generation
		MLXe with MLX or MR2-M mgmt. module	MLXe with XMR or MR2-X mgmt. module	
BR-MLX-1GX20-U10G-X2	MLXe twenty (20)-port 1-GBE (X2) module with IPv4/IPv6/MPLS hardware support. Requires SFP optics. Supports simultaneous 2M IPv4 and 0.8M IPv6, or 1.5M IPv4 and 1M IPv6 routes in FIB. Requires hSFM. Upgradeable to 10G with extra license.	Yes	Yes	3

- Depending on your router model, you can install up to 32 single-slot interface modules, or 16 double-slot interface modules.
- Interface modules are hot-swappable. Interface modules can be removed and replaced without powering down the system.
- Gen 3 - X2 modules with an MR2-M module will only support 512M routes.

Supported Power Supplies

The following table lists the power supplies that are available for the devices supported in this release:

Part number	Description	Compatible devices
BR-MLXE-ACPWR-1800	1800W power supply.	16-, 8- and 4-slot MLXe and 16 and 8-Slot XMR/MLX AC
BR-MLXE-DCPWR-1800	1800W power supply.	16-, 8- and 4-slot MLXe and 16 and 8-Slot XMR/MLX DC
NI-X-ACPWR	1200W power supply.	16-, 8- and 4-slot MLXe and 16 and 8-Slot XMR/MLX AC
NI-X-DCPWR	1200W power supply.	16-, 8- and 4-slot MLXe and 16 and 8-Slot XMR/MLX DC
NI-X-ACPWR-A	1200W power supply.	4-Slot XMR/MLX AC
NI-X-DCPWR-A	1200W power supply.	4-Slot XMR/MLX DC
BR-MLXE-32-ACPWR-3000	AC 3000W power supply.	32-slot MLXe/XMR/MLX
BR-MLXE-32-DCPWR-3000	DC 3000W power supply.	32-slot MLXe/XMR/MLX
NIBI-32-ACPWR-A	AC 2400W power supply.	32-Slot MLXe/XMR/MLX
NIBI-32-DCPWR	2400W power supply.	32-Slot MLXe/XMR/MLX DC

Supported Optics

Extreme-branded Top Level SKU	Description
10301	ASSY, SR SFP+ SHIPPING
10302	ASSY, LR SFP+ SHIPPING
10310	ZR SFP+ module
10051H	1000BASE-SX SFP, Hi
10052H	1000BASE-LX SFP, Hi
10056H	1000BASE-BX-D BiDi SFP, Hi
10057H	1000BASE-BX-U BiDi SFP, Hi
10070H	10/100/1000BASE-T SFP, Hi
100G-ADPT-CFP2-QSFP	100G CFP2 to QSFP28 adapter
100G-CWDM4-QSFP2KM	100G CWDM4 QSFP28 2km
100G-LR4-QSFP10KM	100G LR4 QSFP28 10km
100G-SR4-QSFP100M	100G SR4 QSFP28 100m
10G-ER-SFP40KM-ET	10G ER SFP+ 40km Ext.Temp
10G-LR-SFP10KM-ET	10G LR SFP+ 10km Ext.Temp
10G-SR-SFP300M-ET	10G SR SFP+ 300m Ext.Temp
10G-USR-SFP100M	10G USR SFP+ 100m Hight Rx Sens 8pack
40G-AOC-QSFP100M	40G AOC QSFP+ 100m
40G-AOC-QSFP10M	40G AOC QSFP+ 10m
40G-AOC-QSFP20M	40G AOC QSFP+ 20m
40G-AOC-QSFP5M	40G AOC QSFP+ 5m
40G-BDSR-QSFP150M	40G BiDi SR QSFP+ 150m
40G-DACA-QSFP1M	40G Active DAC QSFP+ 1m
40G-DACA-QSFP5M	40G Active DAC QSFP+ 5m
40G-DACP-QSFP1M	40G Passive DAC QSFP+ 1m
40G-DACP-QSFP3M	40G Passive DAC QSFP+ 3m
40G-DACP-QSFP5M	40G Passive DAC QSFP+ 5m
40G-DACP-QSFPZ5M	40G Passive DAC QSFP+ 0.5m
40G-ESR4-QSFP400M-NT	40G ESR4 QSFP+ 400m 10G-SR interop.
40G-LM4-QSFP160M	40G LM4 QSFP+ 160m 160m MMF. 1km SMF
40G-LR4-QSFP10KM	40G LR4 QSFP+ 10km
40G-SR4-QSFP150M	40G SR4 QSFP+ 150m
MGBIC-LC01-G	1GB SX MM, SFP, TAA

Software upgrade and downgrade

Image file names

Download the following images from www.extremenetworks.com.

NOTE: Beginning with NetIron OS 6.3.00a and later, the ExtremeSwitching CES 2000 Series devices are not supported. Refer to the [End of Sale and End of Support](#) page for additional information.

NOTE: Hitless upgrade is not supported from version 6.3.00a onwards.

Upgrading MLX Series and NetIron XMR devices

NOTE: When upgrading MLX Series and XMR Series devices, follow the manifest upgrade to ensure all required files are upgraded. Boot upgrade is not part of the manifest upgrade. If the boot image is R05.6.00 or older, upgrade the boot image.

Required images for R6.3.00m MLX Series/XMR software upgrade

```
# Copyright 1996-2018 Extreme Networks
#           All rights reserved.
# Manifest File for XMR/MLX Release 06.3.00

-NETIRON_IRONWARE_VER XMR-MLXV6.3.00m
#=====

-DIRECTORY /Boot/InterfaceModule
xmlprm05900.bin

-DIRECTORY /Boot/ManagementModule
xmprm05900.bin

# Application Images

-DIRECTORY /Combined/FPGA
lpfpga06300m.bin

-DIRECTORY /Combined/Application
xm06300m.bin

-DIRECTORY /Monitor/InterfaceModule
xmlb06200.bin

-DIRECTORY /Monitor/ManagementModule
xmb06200.bin

-DIRECTORY /Application/ManagementModule
xmr06300m.bin
```

-DIRECTORY /Application/InterfaceModule
xmlp06300m.bin

-DIRECTORY /FPGA/InterfaceModule

pbif4x40_06300m.bin 2.11
pbif8x10_06300m.bin 2.24
pbifmrj_06300m.bin 4.04
pbifsp2_06300m.bin 4.02
statsmrj_06300m.bin 0.09
xgmacsp2_06300m.bin 0.17
xpp2x100_06300m.bin 1.06
xpp4x40_06300m.bin 6.20
xpp4x10g3_06300m.bin 0.00
xpp8x10_06300m.bin 1.10
xppmrj_06300m.bin 1.03
xppsp2_06300m.bin 1.01
xppxsp2_06300m.bin 1.01
pbif-ber-g3_06300m.bin 2.11
xpp20x10g3_06300m.bin 0.01
xpp2x100g3_06300m.bin 0.01

-DIRECTORY /FPGA/ManagementModule

mbridge32_06300m.xsvf 36
mbridge_06300m.xsvf 37
sbridge_06300m.mcs 6
hsbridge_06300m.mcs 17

-END_OF_IMAGES

-DIRECTORY /Signatures

xmlprm05900.sig
xmprm05900.sig
xmlb06200.sig
xmb06200.sig
xmr06300m.sig
xmlp06300m.sig
lpfpga06300m.sig
hsbridge_06300m.sig
mbridge_06300m.sig
mbridge32_06300m.sig
sbridge_06300m.sig
pbif4x40_06300m.sig
pbif8x10_06300m.sig
pbifmrj_06300m.sig
pbifsp2_06300m.sig
pbif-ber-g3_06300m.sig
statsmrj_06300m.sig
xgmacsp2_06300m.sig
xpp2x100_06300m.sig
xpp20x10g3_06300m.sig
xpp2x100g3_06300m.sig
xpp4x40_06300m.sig
xpp4x10g3_06300m.sig

xpp8x10_06300m.sig
xppmrj_06300m.sig
xppsp2_06300m.sig
xppxsp2_06300m.sig
xmlprm05900.sha256
xmprm05900.sha256
xmlb06200.sha256
xmb06200.sha256
xmr06300m.sha256
xmlp06300m.sha256
lpfpga06300m.sha256
hsbridge_06300m.sha256
mbridge_06300m.sha256
mbridge32_06300m.sha256
sbridge_06300m.sha256
pbif4x40_06300m.sha256
pbif8x10_06300m.sha256
pbifmrj_06300m.sha256
pbifsp2_06300m.sha256
pbif-ber-g3_06300m.sha256
statsmrj_06300m.sha256
xgmacsp2_06300m.sha256
xpp2x100_06300m.sha256
xpp20x10g3_06300m.sha256
xpp2x100g3_06300m.sha256
xpp4x40_06300m.sha256
xpp4x10g3_06300m.sha256
xpp8x10_06300m.sha256
xppmrj_06300m.sha256
xppsp2_06300m.sha256
xppxsp2_06300m.sha256

MIBS:

-DIRECTORY /MIBS
xmr06300m.mib
xmr06300m_std.mib

-DIRECTORY /Yang
ExampleXML.txt
common-defs.yang
interface-config.yang
interface-statedata.yang
mpls-config.yang
mpls-statedata.yang
netiron-config.yang
netiron-statedata.yang
version-statedata.yang
vlan-config.yang
vlan-statedata.yang

-DIRECTORY /Tools
sbsupgrd.zip

```
-DIRECTORY
MLX06300m_Manifest.txt
MLX06300m_Manifest.sig
MLX06300m_Manifest.sha256
```

```
-DIRECTORY /Manuals
```

FPGA file names and supported modules

File Name	Supported Modules
pbif4x40_06300a1.bin	4x40G modules
pbif8x10_06300a1.bin	8x10G modules
pbifmrj_06300a1.bin	24x1G and 48x1G modules
pbifsp2_06300a1.bin	2x10G, 4x10G, 4x10G-x and 20x1G modules
statsmrj_06300a1.bin	24x1G and 48x1G modules
xgmacsp2_06300a1.bin	2x10G, 4x10G-x and 4x10G modules
xpp2x100_06300a1.bin	2x100G modules (double-wide CFP-based module)
xpp4x40_06300a1.bin	4x40G modules
xpp4x10g3_06300a1.bin	4x10G modules
xpp8x10_06300a1.bin	8x10G modules
xppmrj_06300a1.bin	24x1G and 48x1G modules
xppsp2_06300a1.bin	2x10G, 4x10G, and 20x1G modules
xppxsp2_06300a1.bin	4x10G-x
pbif-ber-g3_06300a1.bin	20x10G and 2x100G modules (-M and -X2)
xpp20x10g3_06300a1.bin	20x10G modules
xpp2x100g3_06300a1.bin	2x100G modules (half-slot CFP2-based module)
mbridge32_06300a1.xsvf	MBRIDGE32
mbridge_06300a1.xsvf	MBRIDGE
sbridge_06300a1.mcs	Switch fabric modules
hsbridge_06300a1.mcs	High speed switch fabric modules

Upgrading CER 2000 Series devices

When upgrading CER 2000 Series devices, follow the manifest upgrade to ensure all required files are upgraded. Boot upgrade is not part of the manifest upgrade. If the boot image is R05.5.00 or older, upgrade the boot image.

Required images for R6.3.00m CER 2000 software upgrade

```
# Copyright 1996-2018 Extreme Networks
# All rights reserved.
```

```

# Manifest File for XMR/MLX Release 06.3.00

-NETIRON_IRONWARE_VER CES-CERV6.3.00m
#=====

-DIRECTORY /Boot
ceb06000.bin

-DIRECTORY /Application
ce06300m.bin

-DIRECTORY /FPGA
pbifmetro_06300m.bin

-END_OF_IMAGES

-DIRECTORY /Signatures
ceb06000.sig
ce06300m.sig
pbifmetro_06300m.sig
ceb06000.sha256
ce06300m.sha256
pbifmetro_06300m.sha256

-DIRECTORY /MIBS
ce06300m.mib
ce06300m_std.mib

-DIRECTORY /Yang
ExampleXML.txt
common-defs.yang
interface-config.yang
interface-statedata.yang
mpls-config.yang
mpls-statedata.yang
netiron-config.yang
netiron-statedata.yang
version-statedata.yang
vlan-config.yang
vlan-statedata.yang

-DIRECTORY
CES-CER06300m_Manifest.txt
CES-CER06300m_Manifest.sig
CES-CER06300m_Manifest.sha256

-DIRECTORY /Manuals

```

Upgrading Network Packet Broker devices

NOTE: When upgrading MLX Series and XMR Series devices, follow the manifest upgrade to ensure all required files are upgraded. Boot upgrade is not part of the manifest upgrade. If the boot image is

NetIron OS 6.3.00m for ExtremeRouting MLX Series Devices Release Notes

R05.6.00 or older, upgrade the boot image.

Required images for Network Packet Broker R6.3.00m software upgrade

```
# Copyright 1996-2018 Extreme Networks
#           All rights reserved.
# Manifest File for XMR/MLX Release 06.3.00

-NETIRON_IRONWARE_VER XMR-MLXV6.3.00m
#=====

-DIRECTORY /Boot/InterfaceModule
xmlprm05900.bin

-DIRECTORY /Boot/ManagementModule
xmprm05900.bin

# Application Images

-DIRECTORY /Combined/FPGA
lpfpga_npb_06300m.bin

-DIRECTORY /Combined/Application
xm06300m.bin

-DIRECTORY /Monitor/InterfaceModule
xmlb06200.bin

-DIRECTORY /Monitor/ManagementModule
xmb06200.bin

-DIRECTORY /Application/ManagementModule
xmr06300m.bin

-DIRECTORY /Application/InterfaceModule
xmlp06300m.bin

-DIRECTORY /FPGA/InterfaceModule
pbif4x40_06300m.bin 2.11
pbif8x10_06300m.bin 2.24
pbifmrj_06300m.bin 4.04
pbifsp2_06300m.bin 4.02
statsmrj_06300m.bin 0.09
xgmacsp2_06300m.bin 0.17
xpp2x100_06300m.bin 1.06
xpp4x40_06300m.bin 6.20
xpp4x10g3_06300m.bin 0.00
xpp8x10_06300m.bin 1.10
xppmrj_06300m.bin 1.03
xppsp2_06300m.bin 1.01
xppxsp2_06300m.bin 1.01
pbif-ber-g3_06300m.bin 2.11
```

```
xpp20x10g3_npb_06300m.bin 0.10
xpp2x100g3_npb_06300m.bin 0.10

-DIRECTORY /FPGA/ManagementModule
mbridge32_06300m.xsvf 36
mbridge_06300m.xsvf 37
sbridge_06300m.mcs 6
hsbridge_06300m.mcs 17
```

```
-END_OF_IMAGES
```

```
-DIRECTORY /Signatures
xmlprm05900.sig
xmprm05900.sig
xmlb06200.sig
xmb06200.sig
xmr06300m.sig
xmlp06300m.sig
lpfpga_npb_06300m.sig
hsbridge_06300m.sig
mbridge_06300m.sig
mbridge32_06300m.sig
sbridge_06300m.sig
pbif4x40_06300m.sig
pbif8x10_06300m.sig
pbifmrj_06300m.sig
pbifsp2_06300m.sig
pbif-ber-g3_06300m.sig
statsmrj_06300m.sig
xgmacsp2_06300m.sig
xpp2x100_06300m.sig
xpp20x10g3_npb_06300m.sig
xpp2x100g3_npb_06300m.sig
xpp4x40_06300m.sig
xpp4x10g3_06300m.sig
xpp8x10_06300m.sig
xppmrj_06300m.sig
xppsp2_06300m.sig
xppxsp2_06300m.sig
xmlprm05900.sha256
xmprm05900.sha256
xmlb06200.sha256
xmb06200.sha256
xmr06300m.sha256
xmlp06300m.sha256
lpfpga_npb_06300m.sha256
hsbridge_06300m.sha256
mbridge_06300m.sha256
mbridge32_06300m.sha256
sbridge_06300m.sha256
pbif4x40_06300m.sha256
pbif8x10_06300m.sha256
pbifmrj_06300m.sha256
```

```

pbifsp2_06300m.sha256
pbif-ber-g3_06300m.sha256
statsmrj_06300m.sha256
xgmacsp2_06300m.sha256
xpp2x100_06300m.sha256
xpp20x10g3_npb_06300m.sha256
xpp2x100g3_npb_06300m.sha256
xpp4x40_06300m.sha256
xpp4x10g3_06300m.sha256
xpp8x10_06300m.sha256
xppmrj_06300m.sha256
xppsp2_06300m.sha256
xppxsp2_06300m.sha256

# MIBS:

-DIRECTORY /MIBS
xmr06300m.mib
xmr06300m_std.mib

-DIRECTORY /Yang
ExampleXML.txt
common-defs.yang
interface-config.yang
interface-statedata.yang
mpls-config.yang
mpls-statedata.yang
netiron-config.yang
netiron-statedata.yang
version-statedata.yang
vlan-config.yang
vlan-statedata.yang

-DIRECTORY /Tools
sbsupgrd.zip

-DIRECTORY
MLX_npb_06300m_Manifest.txt
MLX_npb_06300m_Manifest.sig
MLX_npb_06300m_Manifest.sha256

-DIRECTORY /Manuals

```

FPGA file names for NPB and supported modules

File Name	Supported Modules
xpp20x10g3_npb_06300a1.bin	20x10G modules FPGA for NPB
xpp2x100g3_npb_06300a1.bin	2x100G modules (half-slot CFP2-based module) FPGA to NPB

Migration path

To establish an appropriate migration path from your current release of Extreme NetIron, consult your Extreme TAC representative (see the Preface of this document).

Upgrade and downgrade considerations

To upgrade to NetIron 6.3.00a1 and later releases, a multiple step upgrade process is required. The multiple step upgrade process is not required for CER or CES.

Scenario 1

Customers running releases 05.9.00a, 05.6.00ga, 05.6.00h, 05.8.00e, 05.7.00e or subsequent releases can directly upgrade to NetIron 6.3.00a1 and later releases.

NOTE: If you are not running one of the releases listed above, you CANNOT directly upgrade to 6.3.00a1 or later releases.

Scenario 2

To upgrade from 05.6.00c or any later release (other than the images mentioned in Scenario 1), a two-step approach is required.

1. Upgrade to 05.9.00a or any of the following releases: 05.6.00ga, 05.6.00h, 05.8.00e, 05.7.00e or subsequent patch releases and reload the device.
2. Upgrade to NetIron 6.3.00a1 (and later releases). Reload the device.

Scenario 3

To upgrade to NetIron 6.3.00a1 and later releases from releases prior to R05.6.00c, a multiple step approach is required.

1. Upgrade to 5.9.00a or any of the following releases: 05.6.00ga, 05.6.00h, 05.8.00e or 05.7.00e and reload the device.
2. Upgrade again to the same image which was used in step 1 and reload the device again. This ensures that the device will have the SHA256 signatures on the device if they are needed, for example for LP Auto-upgrade.
3. Upgrade to NetIron 6.3.00a1 or later releases and reload the device.

Scenario 4

Use Scenario 4 if you want to use the following features specific to the NPB FPGA.

- VxLAN header stripping
 - GTP de-encapsulation
 - Packet Timestamping
 - Source port labeling
 - NVGRE stripping
 - NetIron 6.3.00a1 UDA Enhancements
1. Upgrade to NetIron 6.3.00a1 and later releases using any of above scenarios based on the image from which the upgrade is being performed.
 2. Reload the device again and verify that the system is up with NetIron 6.3.00a1 or later releases.
 3. Configure the **fpga-mode-npb** command and save the configuration.
 4. Upgrade to the NetIron 6.3.00a1 or later NPB image using MLX_npb_06300a1_Manifest.txt and reload the device.
 5. Make sure BR-MLX-10Gx20 and BR-MLX-100Gx2-CFP2 have NPB XPP images.
 6. Verify the system. Check the output of the **show version** command and the **show flash** command to make sure the image versions are correct. Check the output of the **show module** command to make sure the line cards are not in Interactive state due to FPGA mismatch. Interactive state is an error state due to FPGA mismatch.

Show output examples

The following examples provide excerpts of the command output.

Output examples for the show version command

MLX show version command output:

```
dutA# show version
System Mode: MLX
Chassis: MLXe 8-slot (Serial #: BGB2516H00Z, Part #: 40-1000362-03)
NI-X-HSF Switch Fabric Module 2 (Serial #: BEU0414H041, Part #: 60-1001588-14)
FE 1: Type fe600, Version 1
FE 3: Type fe600, Version 1
Switch Fabric Module 2 Up Time is 2 days 1 hours 35 minutes 54 seconds
=====
SL M2: BR-MLX-MR2-M Management Module Active (Serial #: BVR2533K01J, Part #: 60-1002375-06):
Boot   : Version 5.9.0T165 Copyright (c) 2017-2019 Extreme Networks, Inc.
Compiled on Mar 19 2015 at 03:16:46 labeled as xmpr05900
(521771 bytes) from boot flash
Monitor : Version 6.2.0T165 Copyright (c) 2017-2019 Extreme Networks, Inc.
Compiled on Feb 11 2021 at 08:07:34 labeled as xmb06200
(547993 bytes) from code flash
IronWare : Version 6.3.0mT163 Copyright (c) 2017-2019 Extreme Networks, Inc.
Compiled on Jan 7 2026 at 02:37:52 labeled as xmr06300m
```

(10715712 bytes) from Primary
Board ID : 00 MBRIDGE Revision : 37
1666 MHz Power PC processor 7448 (version 8004/0202) 166 MHz bus
512 KB Boot Flash (MX29LV040C), 128 MB Code Flash (MT28F256J3)
4096 MB DRAM INSTALLED
4096 MB DRAM ADDRESSABLE
Active Management uptime is 2 days 1 hours 35 minutes 54 seconds

=====
SL M1: BR-MLX-MR2-M Management Module Standby (Serial #: BVP0431H004, Part #: 60-1002374-06):
Boot : Version 5.9.0T165 Copyright (c) 2017-2019 Extreme Networks, Inc.
Compiled on Mar 19 2015 at 03:16:46 labeled as xmprpm05900
(521771 bytes) from boot flash
Monitor : Version 6.2.0T165 Copyright (c) 2017-2019 Extreme Networks, Inc.
Compiled on Feb 11 2021 at 08:07:34 labeled as xmb06200
(547993 bytes) from code flash
IronWare : Version 6.3.0mT163 Copyright (c) 2017-2019 Extreme Networks, Inc.
Compiled on Jan 7 2026 at 02:37:52 labeled as xmr06300m
(10715712 bytes) from Primary

Board ID : 00 MBRIDGE Revision : 37
1666 MHz Power PC processor 7448 (version 8004/0202) 166 MHz bus
512 KB Boot Flash (MX29LV040C), 128 MB Code Flash (MT28F256J3)
4096 MB DRAM INSTALLED
4096 MB DRAM ADDRESSABLE
Standby Management uptime is 2 days 1 hours 35 minutes 10 seconds

=====
SL 1: BR-MLX-1GCx24-X 24-port 10/100/1000Base-T Copper Module (Serial #: BNA0440G018, Part #: 60-1001878-08)
License: MLX-1Gx24-X-Upgrade (LID: dpcFJFiFGN)
Boot : Version 5.6.0T175 Copyright (c) 2017-2019 Extreme Networks, Inc.
Compiled on Sep 20 2013 at 16:43:00 labeled as xmlprpm05600
(423373 bytes) from boot flash
Monitor : Version 6.2.0T175 Copyright (c) 2017-2019 Extreme Networks, Inc.
Compiled on Feb 11 2021 at 08:11:50 labeled as xmlb06200
(574086 bytes) from code flash
IronWare : Version 6.3.0mT177 Copyright (c) 2017-2019 Extreme Networks, Inc.
Compiled on Jan 7 2026 at 02:58:46 labeled as xmlp06300m
(9589606 bytes) from Primary

FPGA versions:
Valid PBIF Version = 4.04, Build Time = 11/10/2014 22:10:00

Valid XPP Version = 1.03, Build Time = 6/30/2016 10:37:00

Valid STATS Version = 0.09, Build Time = 11/21/2010 14:52:00

BCM56512GMAC 0
BCM56512GMAC 1
666 MHz MPC MPC8541E (version 8020/0020) 333 MHz bus
512 KB Boot Flash (MX29LV040C), 16 MB Code Flash (MT28F128J3)
1024 MB DRAM, 8 KB SRAM

LP Slot 1 uptime is 2 days 1 hours 35 minutes 11 seconds

=====

SL 2: BR-MLX-10Gx4-M-IPSEC 4-port 1/10GbE and 4-port 1GbE Module (Serial #: CWH0423K020, Part #: 60-1002974-06)

Boot : Version 5.9.0T175 Copyright (c) 2017-2019 Extreme Networks, Inc.

Compiled on Mar 19 2015 at 03:17:00 labeled as xmlprm05900

(449576 bytes) from boot flash

Monitor : Version 6.2.0T175 Copyright (c) 2017-2019 Extreme Networks, Inc.

Compiled on Feb 11 2021 at 08:11:50 labeled as xmlb06200

(574086 bytes) from code flash

IronWare : Version 6.3.0mT177 Copyright (c) 2017-2019 Extreme Networks, Inc.

Compiled on Jan 7 2026 at 02:58:46 labeled as xmlp06300m

(9589606 bytes) from Primary

FPGA versions:

Valid PBIF Version = 2.11, Build Time = 8/19/2016 14:54:00

Valid XPP Version = 0.00, Build Time = 4/13/2017 16:22:00

XGMAC-2 0

XGMAC-2 1

XGMAC-2 2

XGMAC-2 3

1199 MHz MPC P2010E (version 8021/1051) 599 MHz bus

512 KB Boot Flash (MX29LV040C), 66846720 Bytes (~64 MB) Code Flash (MT28F256J3)

3072 MB DRAM, 8 KB SRAM

LP Slot 2 uptime is 2 days 1 hours 35 minutes 8 seconds

=====

SL 3: NI-MLX-10Gx8-M 8-port 10GbE (M) Module (Serial #: BEQ0402G0AN, Part #: 60-1001587-12)
(LID: dgsFJFHIFcp)

Boot : Version 5.9.0T175 Copyright (c) 2017-2019 Extreme Networks, Inc.

Compiled on Mar 19 2015 at 03:17:00 labeled as xmlprm05900

(449576 bytes) from boot flash

Monitor : Version 6.2.0T175 Copyright (c) 2017-2019 Extreme Networks, Inc.

Compiled on Feb 11 2021 at 08:11:50 labeled as xmlb06200

(574086 bytes) from code flash

IronWare : Version 6.3.0mT177 Copyright (c) 2017-2019 Extreme Networks, Inc.

Compiled on Jan 7 2026 at 02:58:46 labeled as xmlp06300m

(9589606 bytes) from Primary

FPGA versions:

Valid PBIF Version = 2.24, Build Time = 4/7/2016 14:16:00

Valid XPP Version = 1.10, Build Time = 2/7/2017 10:41:00

MACXPP40G 0

MACXPP40G 1

1333 MHz MPC MPC8548 (version 8021/0022) 533 MHz bus

512 KB Boot Flash (MX29LV040C), 64 MB Code Flash (MT28F256J3)

1024 MB DRAM, 8 KB SRAM

LP Slot 3 uptime is 2 days 1 hours 35 minutes 11 seconds

=====
SL 4: BR-MLX-10Gx4-X 4-port 10GbE Module (Serial #: BMY0406H045, Part #: 60-1001875-10)
License: MLX-10Gx4-X-Upgrade (LID: doaFJFLjFJK)
Boot : Version 5.9.0T175 Copyright (c) 2017-2019 Extreme Networks, Inc.
Compiled on Mar 19 2015 at 03:17:00 labeled as xmlprm05900
(449576 bytes) from boot flash
Monitor : Version 6.2.0T175 Copyright (c) 2017-2019 Extreme Networks, Inc.
Compiled on Feb 11 2021 at 08:11:50 labeled as xmlb06200
(574086 bytes) from code flash
IronWare : Version 6.3.0mT177 Copyright (c) 2017-2019 Extreme Networks, Inc.
Compiled on Jan 7 2026 at 02:58:46 labeled as xmlp06300m
(9589606 bytes) from Primary
FPGA versions:
Valid PBIF Version = 4.02, Build Time = 8/26/2013 14:30:00

Valid XPP Version = 1.01, Build Time = 9/6/2013 14:16:00

Valid XGMAC Version = 0.17, Build Time = 1/7/2015 10:29:00

XGMAC-2 0

XGMAC-2 1

666 MHz MPC MPC8541E (version 8020/0020) 333 MHz bus
512 KB Boot Flash (MX29LV040C), 16 MB Code Flash (MT28F128J3)
1024 MB DRAM, 8 KB SRAM
LP Slot 4 uptime is 1 days 10 hours 32 minutes 45 seconds

=====
SL 6: BR-MLX-1Gfx24-X 24-port 1GbE SFP Module (Serial #: BND0428H013, Part #: 60-1001892-11)
License: MLX-1Gx24-X-Upgrade (LID: dpfFJHNjFGI)
Boot : Version 5.9.0T175 Copyright (c) 2017-2019 Extreme Networks, Inc.
Compiled on Mar 19 2015 at 03:17:00 labeled as xmlprm05900
(449576 bytes) from boot flash
Monitor : Version 6.2.0T175 Copyright (c) 2017-2019 Extreme Networks, Inc.
Compiled on Feb 11 2021 at 08:11:50 labeled as xmlb06200
(574086 bytes) from code flash
IronWare : Version 6.3.0mT177 Copyright (c) 2017-2019 Extreme Networks, Inc.
Compiled on Jan 7 2026 at 02:58:46 labeled as xmlp06300m
(9589606 bytes) from Primary
FPGA versions:
Valid PBIF Version = 4.04, Build Time = 11/10/2014 22:10:00

Valid XPP Version = 1.03, Build Time = 6/30/2016 10:37:00

Valid STATS Version = 0.09, Build Time = 11/21/2010 14:52:00

BCM56512GMAC 0

BCM56512GMAC 1

666 MHz MPC MPC8541E (version 8020/0020) 333 MHz bus
512 KB Boot Flash (MX29LV040C), 16 MB Code Flash (MT28F128J3)
1024 MB DRAM, 8 KB SRAM

LP Slot 6 uptime is 2 days 1 hours 35 minutes 12 seconds

=====
SL 8: BR-MLX-10Gx4-X 4-port 10GbE Module (Serial #: BMY0413H00Z, Part #: 60-1001875-10)
License: MLX-10Gx4-X-Upgrade (LID: doaFJGJjFFb)

Boot : Version 5.9.0T175 Copyright (c) 2017-2019 Extreme Networks, Inc.

Compiled on Mar 19 2015 at 03:17:00 labeled as xmlprm05900

(449576 bytes) from boot flash

Monitor : Version 6.2.0T175 Copyright (c) 2017-2019 Extreme Networks, Inc.

Compiled on Feb 11 2021 at 08:11:50 labeled as xmlb06200

(574086 bytes) from code flash

IronWare : Version 6.3.0mT177 Copyright (c) 2017-2019 Extreme Networks, Inc.

Compiled on Jan 7 2026 at 02:58:46 labeled as xmlp06300m

(9589606 bytes) from Primary

FPGA versions:

Valid PBIF Version = 4.02, Build Time = 8/26/2013 14:30:00

Valid XPP Version = 1.01, Build Time = 9/6/2013 14:16:00

Valid XGMAC Version = 0.17, Build Time = 1/7/2015 10:29:00

XGMAC-2 0

XGMAC-2 1

666 MHz MPC MPC8541E (version 8020/0020) 333 MHz bus

512 KB Boot Flash (MX29LV040C), 16 MB Code Flash (MT28F128J3)

1024 MB DRAM, 8 KB SRAM

LP Slot 8 uptime is 2 days 1 hours 35 minutes 12 seconds

=====
All show version done

dutA#

CER show version command output

180832_CER2048CX#show version

System: NetIron CER (Serial #: 1V0530G0A3, Part #: 40-1000620-02)

License: RT_SCALE, ADV_SVCS_PREM (LID: GxFKiFiFcI)

Boot : Version 6.0.0T185 Copyright (c) 2017-2019 Extreme Networks, Inc.

Compiled on Jun 7 2016 at 16:10:10 labeled as ceb06000

(465568 bytes) from boot flash

Monitor : Version 6.0.0T185 Copyright (c) 2017-2019 Extreme Networks, Inc.

Compiled on Jun 7 2016 at 16:10:10 labeled as ceb06000

(465568 bytes) from code flash

IronWare : Version 6.3.0mT183 Copyright (c) 2017-2019 Extreme Networks, Inc.

Compiled on Jan 7 2026 at 03:41:46 labeled as ce06300m

(18589803 bytes) from Primary

CPLD Version: 0x00000010

Micro-Controller Version: 0x0000000d

Extended route scalability

PBIF Version: 0x0162

800 MHz Power PC processor 8544 (version 8021/0022) 400 MHz bus

512 KB Boot Flash (MX29LV040C), 64 MB Code Flash (MT28F256J3)

NetIron OS 6.3.00m for ExtremeRouting MLX Series Devices Release Notes

2048 MB DRAM
System uptime is 19 days 17 hours 50 minutes 18 seconds
180832_CER2048CX#

Output example for the show flash command

MLX show flash command output

dutA# show flash

```
~~~~~  
Active Management Module (Right Slot)  
Code Flash - Type MT28F256J3, Size 128 MB  
o IronWare Image (Primary)  
  Version 6.3.0mT163, Size 10715712 bytes, Check Sum a7b7  
  Compiled on Jan 7 2026 at 02:37:52 labeled as xmr06300m  
o LP Kernel Image (Monitor for LP Image Type 0)  
  Version 6.2.0T175, Size 574086 bytes, Check Sum 57d3  
  Compiled on Feb 11 2021 at 08:11:50 labeled as xmlb06200  
o LP IronWare Image (Primary for LP Image Type 0)  
  Version 6.3.0mT177, Size 9589606 bytes, Check Sum f59f  
  Compiled on Jan 7 2026 at 02:58:46 labeled as xmlp06300m  
o Monitor Image  
  Version 6.2.0T165, Size 547993 bytes, Check Sum 1422  
  Compiled on Feb 11 2021 at 08:07:34 labeled as xmb06200  
o Startup Configuration  
  Size 789 bytes, Check Sum d462  
  Modified on 00:35:10 Pacific Tue Jan 27 2026
```

```
~~~~~  
Boot Flash - Type MX29LV040C, Size 512 KB  
o Boot Image  
  Version 5.9.0T165, Size 521771 bytes, Check Sum 4fb8  
  Compiled on Mar 19 2015 at 03:16:46 labeled as xmpr05900  
~~~~~
```

```
~~~~~  
Standby Management Module (Left Slot)  
Code Flash: Type MT28F256J3, Size 128 MB  
o IronWare Image (Primary)  
  Version 6.3.0mT163, Size 10715712 bytes, Check Sum a7b7  
  Compiled on Jan 7 2026 at 02:37:52 labeled as xmr06300m  
o LP Kernel Image (Monitor for LP Image Type 0)  
  Version 6.2.0T175, Size 574086 bytes, Check Sum 57d3  
  Compiled on Feb 11 2021 at 08:11:50 labeled as xmlb06200  
o LP IronWare Image (Primary for LP Image Type 0)  
  Version 6.3.0mT177, Size 9589606 bytes, Check Sum f59f  
  Compiled on Jan 7 2026 at 02:58:46 labeled as xmlp06300m  
o Monitor Image  
  Version 6.2.0T165, Size 547993 bytes, Check Sum 1422  
  Compiled on Feb 11 2021 at 08:07:34 labeled as xmb06200  
o Startup Configuration  
  Size 789 bytes, Check Sum d462  
  Modified on 00:35:11 Pacific Tue Jan 27 2026
```

Boot Flash: Type MX29LV040C, Size 512 KB
o Boot Image
Version 5.9.0T165, Size 521771 bytes, Check Sum 4fb8
Compiled on Mar 19 2015 at 03:16:46 labeled as xmprpm05900

~~~~~  
Line Card Slot 1

Code Flash: Type MT28F128J3, Size 16 MB  
o IronWare Image (Primary)  
Version 6.3.0mT177, Size 9589606 bytes, Check Sum f59f  
Compiled on Jan 7 2026 at 02:58:46 labeled as xmllp06300m  
o Monitor Image  
Version 6.2.0T175, Size 574086 bytes, Check Sum 57d3  
Compiled on Feb 11 2021 at 08:11:50 labeled as xmlb06200

Boot Flash: Type MX29LV040C, Size 512 KB  
o Boot Image  
Version 5.6.0T175, Size 423373 bytes, Check Sum 4c2c  
Compiled on Sep 20 2013 at 16:43:00 labeled as xmllprpm05600

FPGA Version (Stored In Flash):  
PBIF Version = 4.04, Build Time = 11/10/2014 22:10:00

XPP Version = 1.03, Build Time = 6/30/2016 10:37:00

STATS Version = 0.09, Build Time = 11/21/2010 14:52:00

~~~~~  
Line Card Slot 2

Code Flash: Type MT28F256J3, Size 66846720 Bytes (~64 MB)
o IronWare Image (Primary)
Version 6.3.0mT177, Size 9589606 bytes, Check Sum f59f
Compiled on Jan 7 2026 at 02:58:46 labeled as xmllp06300m
o Monitor Image
Version 6.2.0T175, Size 574086 bytes, Check Sum 57d3
Compiled on Feb 11 2021 at 08:11:50 labeled as xmlb06200

Boot Flash: Type MX29LV040C, Size 512 KB
o Boot Image
Version 5.9.0T175, Size 449576 bytes, Check Sum 3bc9
Compiled on Mar 19 2015 at 03:17:00 labeled as xmllprpm05900

FPGA Version (Stored In Flash):
PBIF Version = 2.11, Build Time = 8/19/2016 14:54:00

XPP Version = 0.00, Build Time = 4/13/2017 16:22:00

~~~~~  
Line Card Slot 3

Code Flash: Type MT28F256J3, Size 64 MB  
o IronWare Image (Primary)  
Version 6.3.0mT177, Size 9589606 bytes, Check Sum f59f  
Compiled on Jan 7 2026 at 02:58:46 labeled as xmllp06300m

o Monitor Image  
Version 6.2.0T175, Size 574086 bytes, Check Sum 57d3  
Compiled on Feb 11 2021 at 08:11:50 labeled as xmlb06200  
Boot Flash: Type MX29LV040C, Size 512 KB  
o Boot Image  
Version 5.9.0T175, Size 449576 bytes, Check Sum 3bc9  
Compiled on Mar 19 2015 at 03:17:00 labeled as xmlprm05900  
FPGA Version (Stored In Flash):  
PBIF Version = 2.24, Build Time = 4/7/2016 14:16:00  
  
XPP Version = 1.10, Build Time = 2/7/2017 10:41:00

~~~~~

Line Card Slot 4
Code Flash: Type MT28F128J3, Size 16 MB
o IronWare Image (Primary)
Version 6.3.0mT177, Size 9589606 bytes, Check Sum f59f
Compiled on Jan 7 2026 at 02:58:46 labeled as xmlp06300m
o Monitor Image
Version 6.2.0T175, Size 574086 bytes, Check Sum 57d3
Compiled on Feb 11 2021 at 08:11:50 labeled as xmlb06200
Boot Flash: Type MX29LV040C, Size 512 KB
o Boot Image
Version 5.9.0T175, Size 449576 bytes, Check Sum 3bc9
Compiled on Mar 19 2015 at 03:17:00 labeled as xmlprm05900
FPGA Version (Stored In Flash):
PBIF Version = 4.02, Build Time = 8/26/2013 14:30:00

XPP Version = 1.01, Build Time = 9/6/2013 14:16:00

XGMAC Version = 0.17, Build Time = 1/7/2015 10:29:00

~~~~~

Line Card Slot 6  
Code Flash: Type MT28F128J3, Size 16 MB  
o IronWare Image (Primary)  
Version 6.3.0mT177, Size 9589606 bytes, Check Sum f59f  
Compiled on Jan 7 2026 at 02:58:46 labeled as xmlp06300m  
o Monitor Image  
Version 6.2.0T175, Size 574086 bytes, Check Sum 57d3  
Compiled on Feb 11 2021 at 08:11:50 labeled as xmlb06200  
Boot Flash: Type MX29LV040C, Size 512 KB  
o Boot Image  
Version 5.9.0T175, Size 449576 bytes, Check Sum 3bc9  
Compiled on Mar 19 2015 at 03:17:00 labeled as xmlprm05900  
FPGA Version (Stored In Flash):  
PBIF Version = 4.04, Build Time = 11/10/2014 22:10:00  
  
XPP Version = 1.03, Build Time = 6/30/2016 10:37:00

STATS Version = 0.09, Build Time = 11/21/2010 14:52:00

~~~~~

Line Card Slot 8

Code Flash: Type MT28F128J3, Size 16 MB

o IronWare Image (Primary)

Version 6.3.0mT177, Size 9589606 bytes, Check Sum f59f

Compiled on Jan 7 2026 at 02:58:46 labeled as xmlp06300m

o Monitor Image

Version 6.2.0T175, Size 574086 bytes, Check Sum 57d3

Compiled on Feb 11 2021 at 08:11:50 labeled as xmlb06200

Boot Flash: Type MX29LV040C, Size 512 KB

o Boot Image

Version 5.9.0T175, Size 449576 bytes, Check Sum 3bc9

Compiled on Mar 19 2015 at 03:17:00 labeled as xmlprm05900

FPGA Version (Stored In Flash):

PBIF Version = 4.02, Build Time = 8/26/2013 14:30:00

XPP Version = 1.01, Build Time = 9/6/2013 14:16:00

XGMAC Version = 0.17, Build Time = 1/7/2015 10:29:00

~~~~~

All show flash done

dutA#

*CER show flash command output*

180832\_CER2048CX#show flash

~~~~~

Code Flash - Type MT28F256J3, Size 64 MB

o IronWare Image (Primary)

Version 6.3.0mT183, Size 18589803 bytes, Check Sum 172a

Compiled on Jan 7 2026 at 03:41:46 labeled as ce06300m

o Monitor Image

Version 6.0.0T185, Size 465568 bytes, Check Sum d5b7

Compiled on Jun 7 2016 at 16:10:10 labeled as ceb06000

o Startup Configuration

Size 2784 bytes, Check Sum 4dd6

Modified on 11:47:19 GMT+00 Fri Jan 09 2026

Boot Flash - Type MX29LV040C, Size 512 KB

o Boot Image

Version 6.0.0T185, Size 465568 bytes, Check Sum d5b7

Compiled on Jun 7 2016 at 16:10:10 labeled as ceb06000

~~~~~

180832\_CER2048CX#

### **OpenFlow upgrade and downgrade**

When downgrading the system from NetIron 6.3.00a1 (and later releases) to NetIron 05.8.00, if there are any VRF interfaces which are enabled with OpenFlow, some unexpected IFL entries will be seen after moving to R05.8.00. These unexpected IFL entries may affect the L3VPN/6VPE traffic.

Extreme recommends removing OpenFlow from the VRF interfaces before downgrading the router to R05.8.00. For upgrade and migration considerations, refer to the latest version of the Extreme NetIron Software Upgrade Guide.

### **Hitless upgrade support**

Hitless upgrade is not supported from version 6.3.00a onwards

# Limitations and restrictions

## Important notes

Hitless upgrade is not supported from version 6.3.00a onwards.

Saving system information to flash

- This feature is not supported on Gen1 LPs.

Support for Management IP as snmp trap-source

- IPV6 support is not present currently for trap source addresses.

ACL/PBR co-existence with Openflow on same port

- PBR/ACL is not supported on L23 openflow hybrid port.
- L2 PBR/ACL is not supported on L3 openflow hybrid port.
- L3 PBR/ACL is not supported on L2 openflow hybrid port.
- L2 ACL Deny logging is not supported openflow hybrid port.

RADIUS Over Transport Layer Security (TLS)

- Dot1x accounting is not supported over RADSEC/TLS.

IPv6 ACL based rate limit for CES/CER

- ACL based rate limit is supported only on physical interface.

SCP based simplified upgrade

- This is not supported on CES/CER devices.
- This feature is supported on MR2 management modules.
- Feature is supported from 5.7 and above version.
- The signature verification is performed when the firmware version is 6.1.
- Verification supported only when pre-upgrade version on device is NetIron 6.1 and above.

OpenFlow group table

- The only action allowed in action bucket is output port.
- Each action bucket can have only one output port.
- Maximum of 8 buckets are allowed in an OpenFlow group with logical ports.
- Group types All, Indirect and Fast-Failover are not supported for logical port groups. Only SELECT group type will be supported.
- Bucket statistics is not supported.
- Group cannot have physical port and logical port in the buckets. Either physical ports or logical ports should be present.
- Modification of a group with all physical ports to all logical ports in the buckets and vice versa are not supported.
- Generic OpenFlow rule with action logical port group is not supported.

NetIron OS 6.3.00m for ExtremeRouting MLX Series Devices Release Notes

- This feature is not supported in CES/R.
- Logical port group along with actions other than L2VPN/L3VPN label in flow action are not supported.

#### VLAN modification in MPLS egress

- Pop VLAN action is limited to OpenFlow hybrid ports as output in action.
- In a dual tagged packet, only modification of outer VLAN is supported and addition/deletion of outer VLAN the inner VLAN modification/addition/deletion are not supported.

#### SCP checksum, firmware integrity

- The signature verification is not performed for copying LP application, monitor to specific slot using TFTP , Slot1/Slot2 and LP boot using from Slot1/Slot2

IPv6 ACL Scaling 4k Enhancement is supported only on XMR /MLX Series.

#### LDP interface transport address

- LDP interface transport address should not be enabled when there are multiple parallel adjacencies (interfaces) present between the LDP routers. If user wishes to enable this feature then they should remove the additional adjacencies. If a user enables this feature with multiple adjacencies to a peer then it is possible that the interface transport address may not be used and/or the session would be torn down due to role conflict.
- Pre-requisites: Enabling LDP interface transport address feature on the interface (adjacency) will cause any existing session to flap and come back up with interface IP address as transport address (only in cases where there is a single adjacency between the peers). This can be service impacting and something the user should be well aware of before executing the command.

# Defects

## TSBs—Critical issues to consider prior to installing this release

Technical Support Bulletins (TSBs) provide detailed information about high priority defects or issues present in a release. The following sections specify all current TSBs that have been identified as being a risk to or resolved with this specific release. Please review carefully and refer to the complete TSB for relevant issues prior to migrating to this version of code. TSBs can be found at <https://extremeportal.force.com/> (note that TSBs are generated for all Extreme platforms and products, so not all TSBs apply to this release).

### TSB issues resolved in NI 6.3.00h

| TSB  | Summary |
|------|---------|
| None |         |

### TSB issues outstanding in NI 6.3.00h

| TSB  | Summary |
|------|---------|
| None |         |

## Open Defects in NI6.3.00m

There are no open defects in NetIron OS 6.3.00m as of January 2026

## Open Defects in NI6.3.00k

There are no open defects in NetIron OS 6.3.00k as of January 2025

## Open Defects in NI6.3.00j

There are no open defects in NetIron OS 6.3.00j as of March 2024

## Open Defects in NI 6.3.00h

There are no open defects in NetIron OS 6.3.00h as of July 2023.

## Open Defects in NI6.3.00g

There are no open defects in NetIron OS 6.3.00g as of March 2023.

## Open Defects in NI6.3.00f

This section lists software defects with Critical, High, and Medium Technical Severity unresolved as of July 2022 in NetIron OS 6.3.00f.

|                          |                                                                                                                                                      |                             |                                         |
|--------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-----------------------------------------|
| <b>Parent Defect ID:</b> | NI-17372                                                                                                                                             | <b>Issue ID:</b>            | NI-17420                                |
| <b>Severity:</b>         | S2 - Major                                                                                                                                           |                             |                                         |
| <b>Product:</b>          | NetIron OS                                                                                                                                           | <b>Reported in Release:</b> | NI 06.0.00gd                            |
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                                                                                                                  | <b>Technology:</b>          | OSPF - IPv4 Open<br>Shortest Path First |
| <b>Symptom:</b>          | Router LSA links may stuck in STUB type with OSPF neighbors in FULL or LOADING state                                                                 |                             |                                         |
| <b>Condition:</b>        | 1.The OSPF ABR upgraded to 6.0gd<br>2.ABR has at least 3 neighbors including 1 or 2 in non-backbone areas and originates more than 2000 Summary LSAs |                             |                                         |
| <b>Recovery:</b>         | Clear ip ospf neighbor <neighbor ip address>                                                                                                         |                             |                                         |

|                          |                                                                                                                                 |                             |                 |
|--------------------------|---------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-----------------|
| <b>Parent Defect ID:</b> | NI-14748                                                                                                                        | <b>Issue ID:</b>            | NI-22477        |
| <b>Severity:</b>         | S2 - Major                                                                                                                      |                             |                 |
| <b>Product:</b>          | NetIron OS                                                                                                                      | <b>Reported in Release:</b> | NI 06.0.00a     |
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                                                                                             | <b>Technology:</b>          | IPv6 Addressing |
| <b>Symptom:</b>          | IPv6 neighborship may not be established                                                                                        |                             |                 |
| <b>Condition:</b>        | When IPv6 neighbor solicitation request is received from the peer with source address same as configured interface IPV6 address |                             |                 |

|                          |               |                             |             |
|--------------------------|---------------|-----------------------------|-------------|
| <b>Parent Defect ID:</b> | NI-9750       | <b>Issue ID:</b>            | NI-22479    |
| <b>Severity:</b>         | S3 - Moderate |                             |             |
| <b>Product:</b>          | NetIron OS    | <b>Reported in Release:</b> | NI 06.0.00f |

|                          |                                                                                                                                                                                            |                    |                                         |
|--------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------|-----------------------------------------|
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                                                                                                                                                        | <b>Technology:</b> | BGP4+ - IPv6 Border<br>Gateway Protocol |
| <b>Symptom:</b>          | BGP multipaths are not happened properly for BGP IPv6 routes that are learned in VRF                                                                                                       |                    |                                         |
| <b>Condition:</b>        | 1. iBGP neighborship established with 2 neighbors in VRF2. BGP multipaths are enabled3. The same route is advertised from both the neighbors with the same local_pref, MED, ORIGIN, weight |                    |                                         |
| <b>Workaround:</b>       | Configure "always-compare-med" in 'router bgp'                                                                                                                                             |                    |                                         |

|                          |                                                                                                                                                                     |                             |                                        |
|--------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|----------------------------------------|
| <b>Parent Defect ID:</b> | NI-9732                                                                                                                                                             | <b>Issue ID:</b>            | NI-22483                               |
| <b>Severity:</b>         | S3 - Moderate                                                                                                                                                       |                             |                                        |
| <b>Product:</b>          | NetIron OS                                                                                                                                                          | <b>Reported in Release:</b> | NI 06.0.00f                            |
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                                                                                                                                 | <b>Technology:</b>          | BGP4 - IPv4 Border<br>Gateway Protocol |
| <b>Symptom:</b>          | Following error messages may be observed on MLX in Line card console:-<br>kbp_duplicate_entry_IPVPN[0] idx : 0x00200bee tbl_id : 32 vpn_id = 4099, pfx : x.y.0.0/32 |                             |                                        |
| <b>Condition:</b>        | On the reception of route update message for /32 prefix which matches local IP's network part                                                                       |                             |                                        |

|                          |                                                                                                                                                                                        |                             |             |
|--------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-------------|
| <b>Parent Defect ID:</b> | NI-9731                                                                                                                                                                                | <b>Issue ID:</b>            | NI-22484    |
| <b>Severity:</b>         | S2 - Major                                                                                                                                                                             |                             |             |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                             | <b>Reported in Release:</b> | NI 06.0.00f |
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                                                                                                                                                    | <b>Technology:</b>          | Multi-VRF   |
| <b>Symptom:</b>          | Line card module may go high with the following error message on Line card console:-<br>kbp_duplicate_entry_IPDAVC[0] idx : 0x002b198f tbl_id : 48 vc_label = 500010, pfx : x.y.0.0/16 |                             |             |
| <b>Condition:</b>        | 1. SA learning enabled for routed packets2. Connected VRF route is leaked into another VRF for which label redistribution is blocked by BGP route map                                  |                             |             |

|                          |                                                         |                             |                                                  |
|--------------------------|---------------------------------------------------------|-----------------------------|--------------------------------------------------|
| <b>Parent Defect ID:</b> | NI-9114                                                 | <b>Issue ID:</b>            | NI-22535                                         |
| <b>Severity:</b>         | S3 – Moderate                                           |                             |                                                  |
| <b>Product:</b>          | NetIron OS                                              | <b>Reported in Release:</b> | NI 05.8.00f                                      |
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                     | <b>Technology:</b>          | DHCP - Dynamic Host<br>Configuration<br>Protocol |
| <b>Symptom:</b>          | High CPU may be observed on CER                         |                             |                                                  |
| <b>Condition:</b>        | Processed high rate of fragmented DHCP protocol packets |                             |                                                  |

## Closed with code changes NI6.3.00m

This section lists software defects with Critical, High, and Medium Technical Severity closed with a code change as of January 2026 in NetIron OS 6.3.00m.

|                          |                                                                                                                                                                                                                                                                                                              |                             |             |
|--------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-------------|
| <b>Parent Defect ID:</b> | NI-22683                                                                                                                                                                                                                                                                                                     | <b>Issue ID:</b>            | NI-22683    |
| <b>Severity:</b>         | S3 - Moderate                                                                                                                                                                                                                                                                                                |                             |             |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                                                                                                                   | <b>Reported in Release:</b> | NI 06.0.00k |
| <b>Technology Group:</b> | MCT                                                                                                                                                                                                                                                                                                          | <b>Technology:</b>          | OSPFv2      |
| <b>Symptom:</b>          | OSPF neighborship stays in the FULL/LOAD or LOAD/LOAD or LOAD/FULL states without moving to FULL/FULL state.                                                                                                                                                                                                 |                             |             |
| <b>Condition:</b>        | <ol style="list-style-type: none"> <li>[1]. OSPF adjacency should be configured on the neighbors</li> <li>[2]. any form of redistribute commands are configured to advertise type-5 LSAs</li> <li>[3]. There should be retransmissionq build up should happen possibly due to slow neighbors etc.</li> </ol> |                             |             |

## Closed with code changes NI6.3.00k

This section lists software defects with Critical, High, and Medium Technical Severity closed with a code change as of January 2025 in NetIron OS 6.3.00k.

|                          |                                                                                                                                                                                        |                             |                                          |
|--------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|------------------------------------------|
| <b>Parent Defect ID:</b> | NI-22652                                                                                                                                                                               | <b>Issue ID:</b>            | NI-22652                                 |
| <b>Severity:</b>         | S3 - Moderate                                                                                                                                                                          |                             |                                          |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                             | <b>Reported in Release:</b> | NI 06.0.00d                              |
| <b>Technology Group:</b> | MPLS                                                                                                                                                                                   | <b>Technology:</b>          | MPLS VPLS - Virtual Private LAN Services |
| <b>Symptom:</b>          | MLX fails to drop unicast frame with destination mac learnt on rx port                                                                                                                 |                             |                                          |
| <b>Condition:</b>        | <ol style="list-style-type: none"> <li>1. MPLS-VPLS domain is configured.</li> <li>2. Packets are received with destination mac which is leaned on the receiving interface.</li> </ol> |                             |                                          |

|                          |                                                                                                                                                                                                                                                                                                                                                                                                                                                       |                             |                                     |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-------------------------------------|
| <b>Parent Defect ID:</b> | NI-22655                                                                                                                                                                                                                                                                                                                                                                                                                                              | <b>Issue ID:</b>            | NI-22655                            |
| <b>Severity:</b>         | S3 - Moderate                                                                                                                                                                                                                                                                                                                                                                                                                                         |                             |                                     |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                                                                                                                                                                                                                                                            | <b>Reported in Release:</b> | NI 06.3.00f                         |
| <b>Technology Group:</b> | Layer 3 Routing/Network Layer                                                                                                                                                                                                                                                                                                                                                                                                                         | <b>Technology:</b>          | BGP4 - IPv4 Border Gateway Protocol |
| <b>Symptom:</b>          | MLX device crashes.                                                                                                                                                                                                                                                                                                                                                                                                                                   |                             |                                     |
| <b>Condition:</b>        | <ol style="list-style-type: none"> <li>1. MP-BGP is configured on the device.</li> <li>2. An IP prefix is learned as iBGP from a VPNv4 neighbor and simultaneously as eBGP from another source.</li> <li>3. configure "neighbor xx.xx.xx.xx shutdown" and "no neighbor xx.xx.xx.xx shutdown" under vpnv4 address-family under router bgp config mode.</li> <li>4. Either VRF is removed or the IP prefix learnt through ibgp is withdrawn.</li> </ol> |                             |                                     |

|                          |                                                                                                                                                                                                    |                             |                          |
|--------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|--------------------------|
| <b>Parent Defect ID:</b> | NI-22656                                                                                                                                                                                           | <b>Issue ID:</b>            | NI-22656                 |
| <b>Severity:</b>         | S3 - Moderate                                                                                                                                                                                      |                             |                          |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                         | <b>Reported in Release:</b> | NI 06.3.00f              |
| <b>Technology Group:</b> | MPLS                                                                                                                                                                                               | <b>Technology:</b>          | MPLS Traffic Engineering |
| <b>Symptom:</b>          | MPLS RSVP LSP fails, when reconfiguring the IP address and MPLS-interface .                                                                                                                        |                             |                          |
| <b>Condition:</b>        | <p>Applying the below command sequence quickly on the mpls-interface.</p> <pre>no mpls-int ve xx int ve xx no ip address xx.xx.xx.xx/xx ip address xx.xx.xx.xx/xx router mpls mpls-int ve xx</pre> |                             |                          |
| <b>Workaround:</b>       | A delay in executing the re-adding of the sequence works.                                                                                                                                          |                             |                          |

|                          |                                         |                             |                                     |
|--------------------------|-----------------------------------------|-----------------------------|-------------------------------------|
| <b>Parent Defect ID:</b> | NI-22661                                | <b>Issue ID:</b>            | NI-22661                            |
| <b>Severity:</b>         | S2 - Major                              |                             |                                     |
| <b>Product:</b>          | NetIron OS                              | <b>Reported in Release:</b> | NI 06.3.00f                         |
| <b>Technology Group:</b> | Layer 3 Routing/Network Layer           | <b>Technology:</b>          | BGP4 - IPv4 Border Gateway Protocol |
| <b>Symptom:</b>          | MLX devices crashes.                    |                             |                                     |
| <b>Condition:</b>        | Execute "show ip bgp vrf vrf-all tags". |                             |                                     |

## Closed with code changes NI6.3.00j

This section lists software defects with Critical, High, and Medium Technical Severity closed with a code change as of March 2024 in NetIron OS 6.3.00j.

|                          |                                                                       |                             |                                   |
|--------------------------|-----------------------------------------------------------------------|-----------------------------|-----------------------------------|
| <b>Parent Defect ID:</b> | NI-22641                                                              | <b>Issue ID:</b>            | NI-22641                          |
| <b>Severity:</b>         | S3 – Moderate                                                         |                             |                                   |
| <b>Product:</b>          | NetIron OS                                                            | <b>Reported in Release:</b> | NI 06.3.00f                       |
| <b>Technology Group:</b> | Layer 3 Routing/Network Layer - ARP - Address Resolution Protocol     | <b>Technology:</b>          | ARP - Address Resolution Protocol |
| <b>Symptom:</b>          | Mac-IP mapping is not added to the ARP table on GARP packet received. |                             |                                   |
| <b>Condition:</b>        | Sending GARP request or reply packet to any L3 interface of MLX.      |                             |                                   |

|                          |             |                             |             |
|--------------------------|-------------|-----------------------------|-------------|
| <b>Parent Defect ID:</b> | NI-22617    | <b>Issue ID:</b>            | NI-22617    |
| <b>Severity:</b>         | S3 – Medium |                             |             |
| <b>Product:</b>          | NetIron OS  | <b>Reported in Release:</b> | NI 06.3.00a |

|                          |                                                                                                                                                                                                                                |                    |                                          |
|--------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------|------------------------------------------|
| <b>Technology Group:</b> | MPLS                                                                                                                                                                                                                           | <b>Technology:</b> | MPLS VPLS - Virtual Private LAN Services |
| <b>Symptom:</b>          | LDP session drops on MLX acting as PE.                                                                                                                                                                                         |                    |                                          |
| <b>Condition:</b>        | <ol style="list-style-type: none"> <li>1. MLX and CISCO are PEs in the MPLS domain.</li> <li>2. VPLS peering exists between these PEs.</li> <li>3. The link on CISCO connected towards its CE(VPLS endpoint) flaps.</li> </ol> |                    |                                          |

|                          |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |                             |                                      |
|--------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|--------------------------------------|
| <b>Parent Defect ID:</b> | NI-22625                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | <b>Issue ID:</b>            | NI-22625                             |
| <b>Severity:</b>         | S2 – Major                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |                             |                                      |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | <b>Reported in Release:</b> | NI 06.3.00f                          |
| <b>Technology Group:</b> | Layer 3 Routing/Network Layer                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | <b>Technology:</b>          | BGP4+ - IPv6 Border Gateway Protocol |
| <b>Symptom:</b>          | Some of the ipv6 routes are lost on EBGp peer.                                                                                                                                                                                                                                                                                                                                                                                                                                                    |                             |                                      |
| <b>Condition:</b>        | <ol style="list-style-type: none"> <li>1. There is a EBGp sessions between two of middle bgp peers to two of the downstream external ebgp peers which are also cross-connected.</li> <li>2. There is another EBGp session between middle bgp peers to the upstream bgp peer.</li> <li>3. From downstream EBGp peers send routes and same are learnt on the upsteam bgp peer.</li> <li>4. Withdraw sent routes from the first downstream bgp peer from where routes are initially sent.</li> </ol> |                             |                                      |

|                          |                                                                     |                             |             |
|--------------------------|---------------------------------------------------------------------|-----------------------------|-------------|
| <b>Parent Defect ID:</b> | NI-22608                                                            | <b>Issue ID:</b>            | NI-22608    |
| <b>Severity:</b>         | S3 – Medium                                                         |                             |             |
| <b>Product:</b>          | NetIron OS                                                          | <b>Reported in Release:</b> | NI 06.3.00e |
| <b>Technology Group:</b> | Other                                                               | <b>Technology:</b>          | Other       |
| <b>Symptom:</b>          | Unable to display Extreme branded 10Base ZR optic properly.         |                             |             |
| <b>Condition:</b>        | just connect the extreme branded ZR optic to two MLXs back to back. |                             |             |

## Closed with code changes NI6.3.00h

This section lists software defects with Critical, High, and Medium Technical Severity closed with a code change as of July 2023 in Netlron OS 6.3.00h.

|                          |                                                                                                                                                                                                         |                             |                                         |
|--------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-----------------------------------------|
| <b>Parent Defect ID:</b> | NI-22603                                                                                                                                                                                                | <b>Issue ID:</b>            | NI-22603                                |
| <b>Severity:</b>         | S2 - Major                                                                                                                                                                                              |                             |                                         |
| <b>Product:</b>          | Netlron OS                                                                                                                                                                                              | <b>Reported in Release:</b> | NI 06.3.00g                             |
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                                                                                                                                                                     | <b>Technology:</b>          | OSPF - IPv4 Open<br>Shortest Path First |
| <b>Symptom:</b>          | <ol style="list-style-type: none"> <li>OSPF database overflow</li> <li>Missing connected routes from the ASBR</li> </ol>                                                                                |                             |                                         |
| <b>Condition:</b>        | <ol style="list-style-type: none"> <li>OSPF is running on MLX and neighborship is established with it's peers.</li> <li>ASBR device in the network and sent type-5 LSAs of connected routes.</li> </ol> |                             |                                         |

## Closed with code changes NI6.3.00g

This section lists software defects with Critical, High, and Medium Technical Severity closed with a code change as of March 2023 in Netlron OS 6.3.00g.

|                          |                                                                                                                                                                                                                                                                                                 |                             |                                                             |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-------------------------------------------------------------|
| <b>Parent Defect ID:</b> | NI-22381                                                                                                                                                                                                                                                                                        | <b>Issue ID:</b>            | NI-22381                                                    |
| <b>Severity:</b>         | S3 - Moderate                                                                                                                                                                                                                                                                                   |                             |                                                             |
| <b>Product:</b>          | Netlron OS                                                                                                                                                                                                                                                                                      | <b>Reported in Release:</b> | NI 06.2.00ea                                                |
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                                                                                                                                                                                                                                                             | <b>Technology:</b>          | VRRPv3 - Virtual<br>Router Redundancy<br>Protocol Version 3 |
| <b>Symptom:</b>          | ipv6 ping does not work for the VIP address.                                                                                                                                                                                                                                                    |                             |                                                             |
| <b>Condition:</b>        | <ol style="list-style-type: none"> <li>ipv6 VRRP should be configured between atleast two router's ports on the same broadcast domain.</li> <li>configure "no activate" on the Master VRRP interface.</li> <li>configure "activate" on the same router on which step 2 is performed.</li> </ol> |                             |                                                             |
| <b>Workaround:</b>       | By re-configuring VIP address, ping will start working.                                                                                                                                                                                                                                         |                             |                                                             |

|                          |                                                                                                                                                                                                                                                                        |                             |              |
|--------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|--------------|
| <b>Parent Defect ID:</b> | NI-22546                                                                                                                                                                                                                                                               | <b>Issue ID:</b>            | NI-22546     |
| <b>Severity:</b>         | S3 - Moderate                                                                                                                                                                                                                                                          |                             |              |
| <b>Product:</b>          | Netlron OS                                                                                                                                                                                                                                                             | <b>Reported in Release:</b> | NI 06.2.00cc |
| <b>Technology Group:</b> | Monitoring                                                                                                                                                                                                                                                             | <b>Technology:</b>          | Syslog       |
| <b>Symptom:</b>          | In MLX systems where line cards have been replaced after NP memory parity errors, executing certain commands like "show sysmon logs" can trigger the recording of rapid false parity error messages in syslog.                                                         |                             |              |
| <b>Condition:</b>        | <ol style="list-style-type: none"> <li>MLX having LP cards running into NP memory parity errors.</li> <li>These problematic LP cards are hot-swapped with good working cards without reloading the entire chassis.</li> <li>Execute the "show sysmon logs".</li> </ol> |                             |              |

|                          |                                                                                                                                                                                                                                                                                     |                             |                                         |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-----------------------------------------|
| <b>Parent Defect ID:</b> | NI-22563                                                                                                                                                                                                                                                                            | <b>Issue ID:</b>            | NI-22563                                |
| <b>Severity:</b>         | S3 - Moderate                                                                                                                                                                                                                                                                       |                             |                                         |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                                                                                          | <b>Reported in Release:</b> | NI 06.3.00                              |
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                                                                                                                                                                                                                                                 | <b>Technology:</b>          | OSPF - IPv4 Open<br>Shortest Path First |
| <b>Symptom:</b>          | OSPF Not Redistributing Connected Subnets                                                                                                                                                                                                                                           |                             |                                         |
| <b>Condition:</b>        | <ol style="list-style-type: none"> <li>1. OSPF is configured and learned a route with a certain prefix and installed into the routing table.</li> <li>2. configure the same more specific address on MLX interfaces.</li> <li>3. "Redistribute connected" is configured.</li> </ol> |                             |                                         |

|                          |                                                                                                                                                                                                                                                                                                                                                                                                                                 |                             |                                             |
|--------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|---------------------------------------------|
| <b>Parent Defect ID:</b> | NI-22564                                                                                                                                                                                                                                                                                                                                                                                                                        | <b>Issue ID:</b>            | NI-22564                                    |
| <b>Severity:</b>         | S2 - Major                                                                                                                                                                                                                                                                                                                                                                                                                      |                             |                                             |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                                                                                                                                                                                                                                      | <b>Reported in Release:</b> | NI 06.3.00f                                 |
| <b>Technology Group:</b> | IP Multicast                                                                                                                                                                                                                                                                                                                                                                                                                    | <b>Technology:</b>          | PIM - Protocol-<br>Independent<br>Multicast |
| <b>Symptom:</b>          | When multicast TTL=1 packets are received, High LP CPU is observed.                                                                                                                                                                                                                                                                                                                                                             |                             |                                             |
| <b>Condition:</b>        | <ol style="list-style-type: none"> <li>1. In a certain multicast topology MLX is connected to multicast source with another intermediate router(say SLX/CER/CES) by VE interfaces.</li> <li>2. And this MLX has a group joined through IGMP report from some end stations where another source also sends the traffic to the same group.</li> <li>3. From the first source send the multicast traffic with TTL = 2 .</li> </ol> |                             |                                             |

|                          |                                                                                                          |                             |                                                  |
|--------------------------|----------------------------------------------------------------------------------------------------------|-----------------------------|--------------------------------------------------|
| <b>Parent Defect ID:</b> | NI-22569                                                                                                 | <b>Issue ID:</b>            | NI-22569                                         |
| <b>Severity:</b>         | S2 - Major                                                                                               |                             |                                                  |
| <b>Product:</b>          | NetIron OS                                                                                               | <b>Reported in Release:</b> | NI 06.3.00f                                      |
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                                                                      | <b>Technology:</b>          | DHCP - Dynamic Host<br>Configuration<br>Protocol |
| <b>Symptom:</b>          | The crash happened with EXCEPTION 1100, DTLB Load Task: dhcp6                                            |                             |                                                  |
| <b>Condition:</b>        | On reception of some weird dhcpv6 attacker packets with destination ipv6 address as a multicast address. |                             |                                                  |

|                          |                                                                                                                                                                                                                                  |                             |                                 |
|--------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|---------------------------------|
| <b>Parent Defect ID:</b> | NI-22573                                                                                                                                                                                                                         | <b>Issue ID:</b>            | NI-22573                        |
| <b>Severity:</b>         | S2 - Major                                                                                                                                                                                                                       |                             |                                 |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                                       | <b>Reported in Release:</b> | NI 06.2.00e                     |
| <b>Technology Group:</b> | Management                                                                                                                                                                                                                       | <b>Technology:</b>          | CLI - Command Line<br>Interface |
| <b>Symptom:</b>          | <p>Chassis had reloaded itself on task ssh-1 with the below call stack on performing "show running-config".</p> <p>Possible Stack Trace (function call return address list)</p> <p>20025398: write_runConfig_to_terminal(pc)</p> |                             |                                 |

|                   |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |
|-------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|                   | 2002537c: write_runConfig_to_terminal(lr)<br>202f2330: call_action_func<br>202f2e28: parse_node<br>202f28a4: parse_node_recurse<br>202f30fc: parse_node<br>202f136c: parser<br>203671fc: parse_input<br>20abdbe0: ssh_event_handler<br>20ad0fbc: ProcessChannelData<br>20ace5e8: ShProcessMessage<br>20ad7978: ProcessClientInputData<br>20ad7110: ShFiniteStateMachine<br>209d9680: HandleProtocolAction<br>209d9460: HandleConnectionTask<br>20abc7b0: ssh_connection_task<br>20abcefc: ssh_socket_control<br>20abfb98: ssh_receive_data_ready<br>20abfbdc: ssh_tcp_receive_data_ready_callback<br>20bbfd9c: itc_process_msgs_internal<br>20bc0248: itc_process_msgs<br>20ab7e6c: ssh_in_task<br>00005e18: sys_end_task |
| <b>Condition:</b> | Executing the "show running-config" on SSH terminal for a random number of times.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |

|                          |                                                                                                                                                     |                             |                             |
|--------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-----------------------------|
| <b>Parent Defect ID:</b> | NI-22581                                                                                                                                            | <b>Issue ID:</b>            | NI-22581                    |
| <b>Severity:</b>         | S3 - Moderate                                                                                                                                       |                             |                             |
| <b>Product:</b>          | NetIron OS                                                                                                                                          | <b>Reported in Release:</b> | NI 06.3.00d                 |
| <b>Technology Group:</b> | Management                                                                                                                                          | <b>Technology:</b>          | NTP - Network Time Protocol |
| <b>Symptom:</b>          | LP Cards rebooted with the 'CARD_DOWN_REASON_FID_DISTRIBUTION_FAILED' error in syslog.                                                              |                             |                             |
| <b>Condition:</b>        | 1. NTP should be configured in MLX and the time should be synced between MLX and NTP server.<br>2. configure "clock summer-time" in MP config mode. |                             |                             |

|                          |                                                                                                                                                                                                                                 |                             |                                           |
|--------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-------------------------------------------|
| <b>Parent Defect ID:</b> | NI-22523                                                                                                                                                                                                                        | <b>Issue ID:</b>            | NI-22590                                  |
| <b>Severity:</b>         | S2 - Major                                                                                                                                                                                                                      |                             |                                           |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                                      | <b>Reported in Release:</b> | NI 06.2.00b                               |
| <b>Technology Group:</b> | IP Multicast                                                                                                                                                                                                                    | <b>Technology:</b>          | IGMP - Internet Group Management Protocol |
| <b>Symptom:</b>          | Random Multicast passive S,G groups disappear from 3x10 dynamic LAG                                                                                                                                                             |                             |                                           |
| <b>Condition:</b>        | 1. In a certain multicast topology MLX is connected to multicast source with another intermediate router(say SLX/CER/CES) by a LAG with at least two ports.<br>2. And this MLX has a group joined through IGMP report from some |                             |                                           |

|  |                                                                                                                                                 |
|--|-------------------------------------------------------------------------------------------------------------------------------------------------|
|  | end stations.<br>3. Disable/enable is performed a random number of times on the primary port of the LAG between MLX and its neighboring router. |
|--|-------------------------------------------------------------------------------------------------------------------------------------------------|

|                          |                                                                                                                                                                                                                                                                                                                                                                                            |                             |                 |
|--------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-----------------|
| <b>Parent Defect ID:</b> | NI-22570                                                                                                                                                                                                                                                                                                                                                                                   | <b>Issue ID:</b>            | NI-22592        |
| <b>Severity:</b>         | S2 - Major                                                                                                                                                                                                                                                                                                                                                                                 |                             |                 |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                                                                                                                                                                                                 | <b>Reported in Release:</b> | NI 06.0.00g     |
| <b>Technology Group:</b> | Data Center Fabric                                                                                                                                                                                                                                                                                                                                                                         | <b>Technology:</b>          | Logical Chassis |
| <b>Symptom:</b>          | system crashed with exception 0000 softCheck due to task:fid_mgr with the below stack trace.<br>Possible Stack Trace (function call return address list)<br>20cb9414: fid_mgr_queue_active(pc)<br>20cb9414: fid_mgr_queue_active(lr)<br>20cbbc78: fid_mgr_timeout<br>20ba3af4: itc_process_msgs_internal<br>20ba3fa0: itc_process_msgs<br>20cb7070: fid_mgr_task<br>00005e18: sys_end_task |                             |                 |
| <b>Condition:</b>        | After the crash, when the system is coming up and the system is heavily loaded with FIDs processing is happening.                                                                                                                                                                                                                                                                          |                             |                 |

|                          |                                                                                                                                                                                                                                                                                                                                                                                                                                              |                             |                                      |
|--------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|--------------------------------------|
| <b>Parent Defect ID:</b> | NI-22520                                                                                                                                                                                                                                                                                                                                                                                                                                     | <b>Issue ID:</b>            | NI-22593                             |
| <b>Severity:</b>         | S2 - Major                                                                                                                                                                                                                                                                                                                                                                                                                                   |                             |                                      |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                                                                                                                                                                                                                                                   | <b>Reported in Release:</b> | NI 06.3.00ca                         |
| <b>Technology Group:</b> | Layer 3 Routing/Network Layer                                                                                                                                                                                                                                                                                                                                                                                                                | <b>Technology:</b>          | OSPF - IPv4 Open Shortest Path First |
| <b>Symptom:</b>          | Active MP reset unexpectedly in ospf task and failed over to standby with the below stack trace.<br>Possible Stack Trace (function call return address list)<br>2111f3b0: ospf_process_age_lsdb_entry(pc)<br>2111f710: ospf_process_age_lsdb_entry(lr)<br>2111e858: ospf_router_timer<br>210e63c4: ospf_timer_callback<br>20bc16d8: itc_process_msgs_internal<br>20bc1b84: itc_process_msgs<br>210e6738: ospf_task<br>00005e18: sys_end_task |                             |                                      |
| <b>Condition:</b>        | <ol style="list-style-type: none"> <li>1. In a certain area ( say area 0) 6 MLX routers are present in the topology.</li> <li>2. duplicate IP addresses are configured on 3 of the MLX routers with varying masks.</li> <li>3. "Redistribute connected" is configured.</li> </ol>                                                                                                                                                            |                             |                                      |

## Closed with code changes NI6.3.00f

This section lists software defects with Critical, High, and Medium Technical Severity closed with a code

change as of July 2022 in NetIron OS 6.3.00f.

|                          |                                                                                                                                              |                             |                          |
|--------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|--------------------------|
| <b>Parent Defect ID:</b> | NI-9583                                                                                                                                      | <b>Issue ID:</b>            | NI-10863                 |
| <b>Severity:</b>         | S2 - Major                                                                                                                                   |                             |                          |
| <b>Product:</b>          | NetIron OS                                                                                                                                   | <b>Reported in Release:</b> | NI 06.0.00d              |
| <b>Technology Group:</b> | MPLS                                                                                                                                         | <b>Technology:</b>          | MPLS Traffic Engineering |
| <b>Symptom:</b>          | FRR Facility backup LSP is not up                                                                                                            |                             |                          |
| <b>Condition:</b>        | When "ip ospf passive" is configured on interface, there is no notification sent to MPLS daemon to cause TE flush or RSVP IGP sync reaction. |                             |                          |

|                          |                                                                                                                                                 |                             |                              |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|------------------------------|
| <b>Parent Defect ID:</b> | NI-9531                                                                                                                                         | <b>Issue ID:</b>            | NI-10955                     |
| <b>Severity:</b>         | S2 - Major                                                                                                                                      |                             |                              |
| <b>Product:</b>          | NetIron OS                                                                                                                                      | <b>Reported in Release:</b> | NI 06.2.00                   |
| <b>Technology Group:</b> | Management                                                                                                                                      | <b>Technology:</b>          | CLI - Command Line Interface |
| <b>Symptom:</b>          | LAG creation through EVM shows successful even though it is failed in device with the following error message :-<br>LAG test deployment failed! |                             |                              |
| <b>Condition:</b>        | LAG creation through EVM with participating LAG member ports do not have similar properties                                                     |                             |                              |

|                          |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |                             |                                     |
|--------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-------------------------------------|
| <b>Parent Defect ID:</b> | NI-8808                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               | <b>Issue ID:</b>            | NI-13602                            |
| <b>Severity:</b>         | S2 - Major                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |                             |                                     |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | <b>Reported in Release:</b> | NI 05.8.00ec                        |
| <b>Technology Group:</b> | Layer 3 Routing/Network Layer                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         | <b>Technology:</b>          | BGP4 - IPv4 Border Gateway Protocol |
| <b>Symptom:</b>          | Standby Management Module may unexpectedly reload with the following stack trace:-<br>Possible Stack Trace (function call return address list)<br>20ec94d4: bgp_check_for_fwd_address(pc)<br>20ec93ec: bgp_check_for_fwd_address(lr)<br>20efbd18: bgp_RIB_in_delete_route<br>20f7952c: bgp_check_for_aggrgation<br>20effd40: bgp_remove_route_advertisement<br>20efbdf4: bgp_RIB_in_delete_route<br>20efda08: bgp_vrf_RIB_in_delete_all_self_nlris<br>20eb4e88: bgp_clear_all_vrf_neighbors<br>20f57744: bgp_clear_neighbor_itc_request_callback<br>20b14584: itc_process_msgs_internal<br>20b14a24: itc_process_msgs<br>20f73ed8: bgp_task<br>00005e18: sys_end_task |                             |                                     |
| <b>Condition:</b>        | Execution of "clear ip bgp neighbor all" command                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |                             |                                     |

|                          |         |                  |          |
|--------------------------|---------|------------------|----------|
| <b>Parent Defect ID:</b> | NI-9959 | <b>Issue ID:</b> | NI-14642 |
|--------------------------|---------|------------------|----------|

|                          |                                                                                            |                             |                                   |
|--------------------------|--------------------------------------------------------------------------------------------|-----------------------------|-----------------------------------|
| <b>Severity:</b>         | S2 - Major                                                                                 |                             |                                   |
| <b>Product:</b>          | NetIron OS                                                                                 | <b>Reported in Release:</b> | NI 06.2.00b                       |
| <b>Technology Group:</b> | MPLS                                                                                       | <b>Technology:</b>          | LDP - Label Distribution Protocol |
| <b>Symptom:</b>          | Ping may fail from non-default VRF to default VRF over MPLS                                |                             |                                   |
| <b>Condition:</b>        | Route towards the destination is learnt on MPLS entry interface which is under default-VRF |                             |                                   |

|                          |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |                             |                                     |
|--------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-------------------------------------|
| <b>Parent Defect ID:</b> | NI-21976                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | <b>Issue ID:</b>            | NI-21976                            |
| <b>Severity:</b>         | S1 - Critical                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |                             |                                     |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | <b>Reported in Release:</b> | NI 06.0.00hc                        |
| <b>Technology Group:</b> | Layer 3 Routing/Network Layer                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | <b>Technology:</b>          | BGP4 - IPv4 Border Gateway Protocol |
| <b>Symptom:</b>          | <p>"Unexpected reload of MP due to BGP dampening crash with the following stack trace:<br/>Possible Stack Trace (function call return address list)<br/>20ebbd78: debug_assert(pc)<br/>20fa6bf4: bgp_RIB_out_delete_NLRI(lr)<br/>20fa6bf4: bgp_RIB_out_delete_NLRI<br/>20fb4f68: bgp_remove_route_advertisement<br/>20fbd2e8:<br/>bgp_check_and_update_bgp_route_in_ip_table_as_necessary<br/>20ff91f8: bgp_route_dampening_timer_event<br/>20fdbdec: bgp_timer<br/>20fd7340: bgp_timeout_func<br/>20ba6ea4: itc_process_msgs_internal<br/>20ba7350: itc_process_msgs<br/>2102c6fc: bgp_task<br/>00005e18: sys_end_task<br/>"</p> |                             |                                     |
| <b>Condition:</b>        | <p>"1. BGP is configured on MLX with dampening configured<br/>2. Few routes are being advertised and withdrawn continuously from the peer BGP router."</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |                             |                                     |

|                          |                                                                     |                             |                              |
|--------------------------|---------------------------------------------------------------------|-----------------------------|------------------------------|
| <b>Parent Defect ID:</b> | NI-21999                                                            | <b>Issue ID:</b>            | NI-21999                     |
| <b>Severity:</b>         | S2 - Major                                                          |                             |                              |
| <b>Product:</b>          | NetIron OS                                                          | <b>Reported in Release:</b> | NI 05.8.00f                  |
| <b>Technology Group:</b> | Layer 2 Switching                                                   | <b>Technology:</b>          | LAG - Link Aggregation Group |
| <b>Symptom:</b>          | LAG Ports are in LACP Blocked state                                 |                             |                              |
| <b>Condition:</b>        | Dynamic LAG configured on MLX device with 2 or more ports involved. |                             |                              |

|                          |               |                             |            |
|--------------------------|---------------|-----------------------------|------------|
| <b>Parent Defect ID:</b> | NI-22057      | <b>Issue ID:</b>            | NI-22057   |
| <b>Severity:</b>         | S3 - Moderate |                             |            |
| <b>Product:</b>          | NetIron OS    | <b>Reported in Release:</b> | NI 06.3.00 |

|                          |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |                    |                             |
|--------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------|-----------------------------|
| <b>Technology Group:</b> | Security                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | <b>Technology:</b> | ACLs - Access Control Lists |
| <b>Symptom:</b>          | <p>"Active MM module may be reloaded unexpectedly with the below stack trace.<br/>Possible Stack Trace (function call return address list)<br/>206a7554: cli_check_if_acl(pc)<br/>206a86c4: cli_update_name_acl(lr)<br/>206a86c4: cli_update_name_acl<br/>2069e72c: wr_config_acl_ext<br/>206a8970: retrieve_acl_config<br/>201259ac: retrieve_running_config<br/>20ac6204: ssh_parse_scp_cmd_out<br/>20abec28: ssh_event_handler<br/>20ad217c: ProcessChannelData<br/>20acf7a8: ShProcessMessage<br/>20ad8b38: ProcessClientInputData<br/>20ad82d0: ShFiniteStateMachine<br/>209da7dc: HandleProtocolAction<br/>209da5bc: HandleConnectionTask<br/>20abd948: ssh_connection_task<br/>20abe094: ssh_socket_control<br/>20ac0d58: ssh_receive_data_ready<br/>20ac0d9c: ssh_tcp_receive_data_ready_callback<br/>20bc0788: itc_process_msgs_internal<br/>20bc0c34: itc_process_msgs<br/>20ab8ffc: ssh_in_task<br/>00005e18: sys_end_task"</p> |                    |                             |
| <b>Condition:</b>        | <p>"1. Having Large number of ipv4 access-list with so many rules under each policy.<br/>2. when try to save the configuration with write-memory."</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |                    |                             |

|                          |                                                                                                                                                                          |                             |                     |
|--------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|---------------------|
| <b>Parent Defect ID:</b> | NI-22061                                                                                                                                                                 | <b>Issue ID:</b>            | NI-22061            |
| <b>Severity:</b>         | S3 - Moderate                                                                                                                                                            |                             |                     |
| <b>Product:</b>          | NetIron OS                                                                                                                                                               | <b>Reported in Release:</b> | NI 06.3.00bc        |
| <b>Technology Group:</b> | Monitoring                                                                                                                                                               | <b>Technology:</b>          | Hardware Monitoring |
| <b>Symptom:</b>          | Ports remain down after the remote device reloaded                                                                                                                       |                             |                     |
| <b>Condition:</b>        | <p>"1. Connect two MLX devices back-to-back through the passive TAP<br/>2. On one MLX flap the interface connected to the other MLX or upgrade or downgrade the MLX"</p> |                             |                     |

|                          |                                                                     |                             |                                     |
|--------------------------|---------------------------------------------------------------------|-----------------------------|-------------------------------------|
| <b>Parent Defect ID:</b> | NI-22069                                                            | <b>Issue ID:</b>            | NI-22069                            |
| <b>Severity:</b>         | S1 - Critical                                                       |                             |                                     |
| <b>Product:</b>          | NetIron OS                                                          | <b>Reported in Release:</b> | NI 06.0.00hc                        |
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                                 | <b>Technology:</b>          | BGP4 - IPv4 Border Gateway Protocol |
| <b>Symptom:</b>          | Intermittently generating BGP updates with Malformed Attribute List |                             |                                     |

|                   |                                                                                                                                                                           |
|-------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Condition:</b> | "1. Connect two MLX devices running 6.0he image<br>2. configure BGP and bring up the neighborship<br>3. Send BGP updates in a jumbo packet which is more than 1500 bytes" |
|-------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

|                          |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |                             |                             |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-----------------------------|
| <b>Parent Defect ID:</b> | NI-22087                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | <b>Issue ID:</b>            | NI-22087                    |
| <b>Severity:</b>         | S3 - Moderate                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |                             |                             |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | <b>Reported in Release:</b> | NI 06.3.00bc                |
| <b>Technology Group:</b> | Security                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | <b>Technology:</b>          | ACLs - Access Control Lists |
| <b>Symptom:</b>          | <p>"Active MM module may be reloaded unexpectedly with the below stack trace.<br/>Possible Stack Trace (function call return address list)<br/>202f852c: l4_port_to_name(pc)<br/>21256d14: wr_config_ip6_acl_filter(lr)<br/>21256d14: wr_config_ip6_acl_filter<br/>212579ec: wr_config_ip6_acl<br/>201259a4: retrieve_running_config<br/>20ac6204: ssh_parse_scp_cmd_out<br/>20abec28: ssh_event_handler<br/>20ad217c: ProcessChannelData<br/>20acf7a8: ShProcessMessage<br/>20ad8b38: ProcessClientInputData<br/>20ad82d0: ShFiniteStateMachine<br/>209da7dc: HandleProtocolAction<br/>209da5bc: HandleConnectionTask<br/>20abd948: ssh_connection_task<br/>20abe094: ssh_socket_control<br/>20ac0d58: ssh_receive_data_ready<br/>20ac0d9c: ssh_tcp_receive_data_ready_callback<br/>20bc0788: itc_process_msgs_internal<br/>20bc0c34: itc_process_msgs<br/>20ab8ffc: ssh_in_task<br/>00005e18: sys_end_task"</p> |                             |                             |
| <b>Condition:</b>        | <p>"1. Having Large number of ipv6 access-list with so many rules under each policy.<br/>2. when try to save the configuration with write-memory."</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |                             |                             |

|                          |                                                                                                                                                                                                                                                                                         |                             |             |
|--------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-------------|
| <b>Parent Defect ID:</b> | NI-22349                                                                                                                                                                                                                                                                                | <b>Issue ID:</b>            | NI-22349    |
| <b>Severity:</b>         | S2 - Major                                                                                                                                                                                                                                                                              |                             |             |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                                                                                              | <b>Reported in Release:</b> | NI 06.2.00f |
| <b>Technology Group:</b> | SDN                                                                                                                                                                                                                                                                                     | <b>Technology:</b>          | OpenFlow    |
| <b>Symptom:</b>          | <p>"MLXe-4 crashed while runing 'show tech' following SW upgrade from 06000j &gt; 06200f with below stack trace<br/>Possible Stack Trace (function call return address list)<br/>22684a50: strstr(pc)<br/>223ef4d4: openflow_show_groups_range(lr)<br/>20038888: show_tech_support"</p> |                             |             |

|                   |                                                                                                                                                               |
|-------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------|
|                   | 20364f38: timer_callback_wrapper<br>20bc1714: itc_process_msgs_internal<br>20bc1bc0: itc_process_msgs<br>20ab9428: ssh_in_task<br>00005e18: sys_end_task<br>" |
| <b>Condition:</b> | "1. Openflow has been configured in MLX device which has 6.0j image.<br>2. Upgrade to 6.3e or lower image"                                                    |

|                          |                                                                                                                                                                                                                                                                                                                                                              |                             |                              |
|--------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|------------------------------|
| <b>Parent Defect ID:</b> | NI-22376                                                                                                                                                                                                                                                                                                                                                     | <b>Issue ID:</b>            | NI-22376                     |
| <b>Severity:</b>         | S3 - Moderate                                                                                                                                                                                                                                                                                                                                                |                             |                              |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                                                                                                                                                                   | <b>Reported in Release:</b> | NI 06.3.00d                  |
| <b>Technology Group:</b> | Layer 2 Switching                                                                                                                                                                                                                                                                                                                                            | <b>Technology:</b>          | MCT - Multi-Chassis Trunking |
| <b>Symptom:</b>          | VPLS forwarding issues when MCT peer has CCEP ports                                                                                                                                                                                                                                                                                                          |                             |                              |
| <b>Condition:</b>        | "1. Connect two MCT peers back-to-back (i.e dual MCT configuration) with ICL link between them is configured using psedo-wire<br>2. disable the LAG connected towards Active PE, so that the CCEP traffic goes only towards standby PE<br>3. Issue ping or send traffic from the CCEP device to the remote CCEP port on the other side of dual MCT topology" |                             |                              |

|                          |                                                                                                                                                                                             |                             |                |
|--------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|----------------|
| <b>Parent Defect ID:</b> | NI-22378                                                                                                                                                                                    | <b>Issue ID:</b>            | NI-22378       |
| <b>Severity:</b>         | S3 - Moderate                                                                                                                                                                               |                             |                |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                  | <b>Reported in Release:</b> | NI 06.0.00g    |
| <b>Technology Group:</b> | MPLS                                                                                                                                                                                        | <b>Technology:</b>          | IPv6 over MPLS |
| <b>Symptom:</b>          | When pinging an IPv6 Ve/VPLS interface, intermittent packet loss is observed                                                                                                                |                             |                |
| <b>Condition:</b>        | "1. VEOVPLS interface is configured on the PE router on which IPv6 address is configured<br>2. Issue ping from CE device, which is connected to the VPLS end-point of the above PE device " |                             |                |

|                          |                                                       |                             |                                            |
|--------------------------|-------------------------------------------------------|-----------------------------|--------------------------------------------|
| <b>Parent Defect ID:</b> | NI-22393                                              | <b>Issue ID:</b>            | NI-22393                                   |
| <b>Severity:</b>         | S3 - Moderate                                         |                             |                                            |
| <b>Product:</b>          | NetIron OS                                            | <b>Reported in Release:</b> | NI 06.3.00d                                |
| <b>Technology Group:</b> | Layer 3 Routing/Network Layer                         | <b>Technology:</b>          | DHCP - Dynamic Host Configuration Protocol |
| <b>Symptom:</b>          | DHCPv6 release-reply message not reaching the client. |                             |                                            |
| <b>Condition:</b>        | Linux is used as the dhcpv6 server application.       |                             |                                            |

|                          |               |                             |                    |
|--------------------------|---------------|-----------------------------|--------------------|
| <b>Parent Defect ID:</b> | NI-22424      | <b>Issue ID:</b>            | NI-22424           |
| <b>Severity:</b>         | S3 - Moderate |                             |                    |
| <b>Product:</b>          | NetIron OS    | <b>Reported in Release:</b> | NI 06.3.00bc       |
| <b>Technology Group:</b> | Security      | <b>Technology:</b>          | SSH - Secure Shell |

|                   |                                                                                                                                                          |
|-------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Symptom:</b>   | Keep getting "Another TFTP/SCP session is in progress" error message in syslog.                                                                          |
| <b>Condition:</b> | "1. Open two ssh/telnet sessions<br>2. Upload or download on one of the SSH/Telnet session<br>3. Try upload or download on the other SSH/Telnet session" |

|                          |                                                                                                                                                                                         |                             |                                           |
|--------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-------------------------------------------|
| <b>Parent Defect ID:</b> | NI-22458                                                                                                                                                                                | <b>Issue ID:</b>            | NI-22458                                  |
| <b>Severity:</b>         | S3 - Moderate                                                                                                                                                                           |                             |                                           |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                              | <b>Reported in Release:</b> | NI 06.3.00ca                              |
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                                                                                                                                                     | <b>Technology:</b>          | GRE - Generic<br>Routing<br>Encapsulation |
| <b>Symptom:</b>          | Incorrect Error being displayed while configuring VRF in an IP GRE tunnel, hence unable to configure VRF forwarding under the tunnel                                                    |                             |                                           |
| <b>Condition:</b>        | "1. Configure multiple ip addresses on the physical interface which is the source interface of the GRE tunnel to be configured<br>2. Try to add such a GRE tunnel into non-default VRF" |                             |                                           |

|                          |                                                                                                                                                                                                                                                                               |                             |                                         |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-----------------------------------------|
| <b>Parent Defect ID:</b> | NI-22462                                                                                                                                                                                                                                                                      | <b>Issue ID:</b>            | NI-22462                                |
| <b>Severity:</b>         | S3 - Moderate                                                                                                                                                                                                                                                                 |                             |                                         |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                                                                                    | <b>Reported in Release:</b> | NI 06.3.00d                             |
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                                                                                                                                                                                                                                           | <b>Technology:</b>          | OSPF - IPv4 Open<br>Shortest Path First |
| <b>Symptom:</b>          | Type5 LSA gets max aged 3,600 and the network becomes unstable.                                                                                                                                                                                                               |                             |                                         |
| <b>Condition:</b>        | 1. There are two ABRs connecting area 0 and NSSA area.<br>2. The address configured on NSSA internal router and the static address configured on NSSA ABRs are in the same subnet.<br>3. Redistribute connected on NSSA internal routers and redistribute static on NSSA ABR. |                             |                                         |

|                          |                                                                                                                                    |                             |                                        |
|--------------------------|------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|----------------------------------------|
| <b>Parent Defect ID:</b> | NI-22463                                                                                                                           | <b>Issue ID:</b>            | NI-22463                               |
| <b>Severity:</b>         | S3 - Moderate                                                                                                                      |                             |                                        |
| <b>Product:</b>          | NetIron OS                                                                                                                         | <b>Reported in Release:</b> | NI 06.3.00d                            |
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                                                                                                | <b>Technology:</b>          | BGP4 - IPv4 Border<br>Gateway Protocol |
| <b>Symptom:</b>          | Paging for "show ip bgp vrf vrf-all tags" is not working if the number of routes in any of the multiple vrfs is more than 22 lines |                             |                                        |
| <b>Condition:</b>        | "1. BGP is enabled on multiple (two or more) vrfs<br>2. Atleast one of the VRFs have more than 22 routes to display"               |                             |                                        |

|                          |               |                             |             |
|--------------------------|---------------|-----------------------------|-------------|
| <b>Parent Defect ID:</b> | NI-22465      | <b>Issue ID:</b>            | NI-22465    |
| <b>Severity:</b>         | S3 - Moderate |                             |             |
| <b>Product:</b>          | NetIron OS    | <b>Reported in Release:</b> | NI 06.3.00d |

|                          |                                                                                                                                                                                                                                                                                                              |                    |                                           |
|--------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------|-------------------------------------------|
| <b>Technology Group:</b> | IP Multicast                                                                                                                                                                                                                                                                                                 | <b>Technology:</b> | IGMP - Internet Group Management Protocol |
| <b>Symptom:</b>          | MLX LAG in one-arm routing scenario loops back multicast RTCP control traffic                                                                                                                                                                                                                                |                    |                                           |
| <b>Condition:</b>        | <p>"1. A Router is configured with L3 multicast with PIM as the control protocol</p> <p>2. This router is one-arm routing scenario where the ingress (VLAN) and egress (VLAN) traffic have the same physical interface</p> <p>3. Try to IGMP join in the ingress VLAN which is the source VLAN as well."</p> |                    |                                           |

|                          |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |                             |                                          |
|--------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|------------------------------------------|
| <b>Parent Defect ID:</b> | NI-14761                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | <b>Issue ID:</b>            | NI-22472                                 |
| <b>Severity:</b>         | S1 - Critical                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |                             |                                          |
| <b>Product:</b>          | Netron OS                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | <b>Reported in Release:</b> | NI 06.0.00f                              |
| <b>Technology Group:</b> | MPLS                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | <b>Technology:</b>          | MPLS VPLS - Virtual Private LAN Services |
| <b>Symptom:</b>          | <p>24X10G Line card module may reload unexpectedly with the below stack trace:-</p> <p>20b6a954: darter_ppcr_dword_read(pc)</p> <p>20b75ac4: darter_ppcr_retrieve_mvid(lr)</p> <p>20b76468: darter_ppcr_retrieve_mvid_index</p> <p>20a8b92c: ppcr_retrieve_mvid</p> <p>20a66eb4: ppcr_dm_mmpls_entry</p> <p>20963428: yyparse</p> <p>20920378: sys_parse</p> <p>20c7692c: cli_lp_parser_cmds</p> <p>20c62aa0: call_action_func</p> <p>20c632ec: parse_node</p> <p>20c62da0: parse_node_recurse</p> <p>20c63430: parse_node</p> <p>20c622a4: parser</p> <p>20c69f58: parse_input</p> <p>2091ff58: sys_console_input_process</p> <p>207f6b9c: lp_console_task</p> <p>00040158: sys_end_task</p> |                             |                                          |
| <b>Condition:</b>        | Rarely observed during the execution of this debug command 'dm entry me/1 mmpls <index>'                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |                             |                                          |

|                          |                                                                                                                 |                             |                                     |
|--------------------------|-----------------------------------------------------------------------------------------------------------------|-----------------------------|-------------------------------------|
| <b>Parent Defect ID:</b> | NI-9740                                                                                                         | <b>Issue ID:</b>            | NI-22473                            |
| <b>Severity:</b>         | S2 - Major                                                                                                      |                             |                                     |
| <b>Product:</b>          | Netron OS                                                                                                       | <b>Reported in Release:</b> | NI 06.0.00f                         |
| <b>Technology Group:</b> | Layer 3 Routing/Network Layer                                                                                   | <b>Technology:</b>          | BGP4 - IPv4 Border Gateway Protocol |
| <b>Symptom:</b>          | <p>Management module may reload unexpectedly with the below stack trace:-</p> <p>20eb7b5c: debug_assert(pc)</p> |                             |                                     |

|                   |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |
|-------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|                   | 20fa325c: bgp_RIB_out_delete_NLRI(lr)<br>20fa325c: bgp_RIB_out_delete_NLRI<br>20fb4150: bgp_add_or_remove_ribout_if_necessary<br>20fb8e00:<br>bgp_check_and_update_bgp_route_in_ip_table_as_necessary<br>20faabdc: bgp_RIB_in_add_route<br>21050d44: bgp_process_NLRI_fields<br>2104a6fc: bgp_process_update_message_from_peer<br>20f8f23c: bgp_process_update_message_received_event<br>20f87a88: bgp_execute_bgp_finite_state_machine<br>21047f34: bgp_process_received_message<br>20fc0538: bgp_tcp_receive_call<br>20fd2884: bgp_io_process<br>21027630: bgp_io_task<br>00005e18: sys_end_task |
| <b>Condition:</b> | 1. Router configured with 'advertise-best-external' for BGP<br>2. Churn in the BGP network due to change in the best-external path repeatedly                                                                                                                                                                                                                                                                                                                                                                                                                                                      |

|                          |                                                                                      |                             |                             |
|--------------------------|--------------------------------------------------------------------------------------|-----------------------------|-----------------------------|
| <b>Parent Defect ID:</b> | NI-17438                                                                             | <b>Issue ID:</b>            | NI-22474                    |
| <b>Severity:</b>         | S3 - Moderate                                                                        |                             |                             |
| <b>Product:</b>          | NetIron OS                                                                           | <b>Reported in Release:</b> | NI 06.2.00b                 |
| <b>Technology Group:</b> | Management                                                                           | <b>Technology:</b>          | NTP - Network Time Protocol |
| <b>Symptom:</b>          | NTP packets may not be authenticated after upgrade from 6.2b releases                |                             |                             |
| <b>Condition:</b>        | 1)Configured IPv6 on the NTP server<br>2)Configured management VRF with IPv6 address |                             |                             |

|                          |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |                             |                                 |
|--------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|---------------------------------|
| <b>Parent Defect ID:</b> | NI-9593                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | <b>Issue ID:</b>            | NI-22475                        |
| <b>Severity:</b>         | S2 - Major                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |                             |                                 |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                | <b>Reported in Release:</b> | NI 06.0.00d                     |
| <b>Technology Group:</b> | Traffic Management                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | <b>Technology:</b>          | Traffic Queueing and Scheduling |
| <b>Symptom:</b>          | Line card may reload unexpectedly with the below stack trace:-<br>Possible Stack Trace (function call return address list)<br>rw2_collect_stats_via_dma_4x40(pc)<br>rw2_collect_stats_via_dma_4x40(lr)<br>rw2_collect_stats_via_dma<br>rw2_collect_stats_via_direct_read_4x40<br>rw2_collect_stats_via_direct_read<br>rw2_read_petra_stats_direct_read_at_index<br>Fap20v_hw_read_per_q_counters<br>fap20v_read_n_return_per_q_counters<br>lp_get_tm_one_voq_data_stat<br>scp_show_tm_voq_stat<br>scp_info_mplp_show_process_ipc<br>mplp_show_process_ipc |                             |                                 |

|                   |                                                                                                                                            |
|-------------------|--------------------------------------------------------------------------------------------------------------------------------------------|
|                   | ipc_multi_module_handler<br>ipc_process_messages<br>ipc_receive_packet<br>ge_process_ipc_data_msg<br>lp_ipc_task<br>sys_end_task           |
| <b>Condition:</b> | 1. Reception of CPU traffic like unknown unicast or protocol<br>2. On repeated execution of the command "show tm-voq-stat" for CPU traffic |

|                          |                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |                             |                  |
|--------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|------------------|
| <b>Parent Defect ID:</b> | NI-17559                                                                                                                                                                                                                                                                                                                                                                                                                                                                 | <b>Issue ID:</b>            | NI-22476         |
| <b>Severity:</b>         | S2 - Major                                                                                                                                                                                                                                                                                                                                                                                                                                                               |                             |                  |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                                                                                                                                                                                                                                                                               | <b>Reported in Release:</b> | NI 06.0.00d      |
| <b>Technology Group:</b> | Security                                                                                                                                                                                                                                                                                                                                                                                                                                                                 | <b>Technology:</b>          | TACACS & TACACS+ |
| <b>Symptom:</b>          | Active MM module may be reloaded unexpectedly with the below stack trace.<br>Possible Stack Trace (function call return address list)<br>207bf470: tacplus_create_md5_hash(pc)<br>207bf448: tacplus_create_md5_hash(lr)<br>207bf54c: tacplus_md5_xor<br>207bb67c: tacplus_send_account_pkt<br>2079ef3c: aaa_tcp_outgoing_connection_ready_callback<br>20ba0540: itc_process_msgs_internal<br>20ba09ec: itc_process_msgs<br>207d62d0: snms_task<br>00005e18: sys_end_task |                             |                  |
| <b>Condition:</b>        | 1. Configured TACACS+ accounting for CLI commands by specifying the privilege level as 0 as below<br>aaa accounting commands 0 default start-stop tacacs+<br>2. with TACACS+ server key of 30 characters<br>3. Continuous execution of command "show ip interface" from SSH                                                                                                                                                                                              |                             |                  |

|                          |                                                                   |                             |             |
|--------------------------|-------------------------------------------------------------------|-----------------------------|-------------|
| <b>Parent Defect ID:</b> | NI-9956                                                           | <b>Issue ID:</b>            | NI-22478    |
| <b>Severity:</b>         | S4 - Minor                                                        |                             |             |
| <b>Product:</b>          | NetIron OS                                                        | <b>Reported in Release:</b> | NI 06.2.00b |
| <b>Technology Group:</b> | Monitoring                                                        | <b>Technology:</b>          | Syslog      |
| <b>Symptom:</b>          | telnet client may not be observed in 'show logging' as configured |                             |             |
| <b>Condition:</b>        | 'telnet client <ip-address>' is configured from a telnet session. |                             |             |

|                          |                                                    |                             |                                                |
|--------------------------|----------------------------------------------------|-----------------------------|------------------------------------------------|
| <b>Parent Defect ID:</b> | NI-9745                                            | <b>Issue ID:</b>            | NI-22480                                       |
| <b>Severity:</b>         | S3 - Moderate                                      |                             |                                                |
| <b>Product:</b>          | NetIron OS                                         | <b>Reported in Release:</b> | NI 06.0.00f                                    |
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                | <b>Technology:</b>          | ICMP - Internet<br>Control Message<br>Protocol |
| <b>Symptom:</b>          | IPv6 traffic may not be forwarded to destined port |                             |                                                |
| <b>Condition:</b>        | Specific to Ipv6 Hop-by-hop and fragmented packets |                             |                                                |

|                          |                                                               |                             |                                      |
|--------------------------|---------------------------------------------------------------|-----------------------------|--------------------------------------|
| <b>Parent Defect ID:</b> | NI-9743                                                       | <b>Issue ID:</b>            | NI-22481                             |
| <b>Severity:</b>         | S2 - Major                                                    |                             |                                      |
| <b>Product:</b>          | NetIron OS                                                    | <b>Reported in Release:</b> | NI 06.0.00f                          |
| <b>Technology Group:</b> | IP Multicast                                                  | <b>Technology:</b>          | PIM - Protocol-Independent Multicast |
| <b>Symptom:</b>          | Multicast traffic forwarding may fail on MLX with High LP CPU |                             |                                      |
| <b>Condition:</b>        | When source traffic moves to a different port on same VE      |                             |                                      |

|                          |                                                                    |                             |                                        |
|--------------------------|--------------------------------------------------------------------|-----------------------------|----------------------------------------|
| <b>Parent Defect ID:</b> | NI-9738                                                            | <b>Issue ID:</b>            | NI-22482                               |
| <b>Severity:</b>         | S2 - Major                                                         |                             |                                        |
| <b>Product:</b>          | NetIron OS                                                         | <b>Reported in Release:</b> | NI 06.0.00f                            |
| <b>Technology Group:</b> | Layer 3 Routing/Network Layer                                      | <b>Technology:</b>          | OSPFv3 - IPv6 Open Shortest Path First |
| <b>Symptom:</b>          | IPv6 traffic may not be forwarded over VEOVPLS interface           |                             |                                        |
| <b>Condition:</b>        | MPLS LSP primary path goes down on disabling the VEOVPLS interface |                             |                                        |

|                          |                                                                         |                             |                           |
|--------------------------|-------------------------------------------------------------------------|-----------------------------|---------------------------|
| <b>Parent Defect ID:</b> | NI-9651                                                                 | <b>Issue ID:</b>            | NI-22485                  |
| <b>Severity:</b>         | S3 - Moderate                                                           |                             |                           |
| <b>Product:</b>          | NetIron OS                                                              | <b>Reported in Release:</b> | NI 06.2.00                |
| <b>Technology Group:</b> | Traffic Management                                                      | <b>Technology:</b>          | Rate Limiting and Shaping |
| <b>Symptom:</b>          | Burst traffic may be forwarded more than the configured rate on CES/CER |                             |                           |
| <b>Condition:</b>        | Bursty traffic with Rate-limit is configured on the interface           |                             |                           |

|                          |                                                                                                                                            |                             |                       |
|--------------------------|--------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-----------------------|
| <b>Parent Defect ID:</b> | NI-9962                                                                                                                                    | <b>Issue ID:</b>            | NI-22486              |
| <b>Severity:</b>         | S3 - Moderate                                                                                                                              |                             |                       |
| <b>Product:</b>          | NetIron OS                                                                                                                                 | <b>Reported in Release:</b> | NI 06.2.00b           |
| <b>Technology Group:</b> | Layer 3 Routing/Network Layer                                                                                                              | <b>Technology:</b>          | Static Routing (IPv4) |
| <b>Symptom:</b>          | Line card module CPU usage may go high                                                                                                     |                             |                       |
| <b>Condition:</b>        | 1. Static route configured for a host<br>2. Along with the reception of traffic for the configured host<br>ex:<br>ip route a.b.c.d/32 ve x |                             |                       |

|                          |               |                             |                                           |
|--------------------------|---------------|-----------------------------|-------------------------------------------|
| <b>Parent Defect ID:</b> | NI-9961       | <b>Issue ID:</b>            | NI-22487                                  |
| <b>Severity:</b>         | S3 - Moderate |                             |                                           |
| <b>Product:</b>          | NetIron OS    | <b>Reported in Release:</b> | NI 06.2.00b                               |
| <b>Technology Group:</b> | Management    | <b>Technology:</b>          | SNMP - Simple Network Management Protocol |

|                   |                                                                                     |
|-------------------|-------------------------------------------------------------------------------------|
| <b>Symptom:</b>   | Show statistics CLI may display incorrect out utilization for 100G Line card module |
| <b>Condition:</b> | Observed with traffic rate more than 55Gbps                                         |

|                          |                                                                                                                                               |                             |                              |
|--------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|------------------------------|
| <b>Parent Defect ID:</b> | NI-3836                                                                                                                                       | <b>Issue ID:</b>            | NI-22488                     |
| <b>Severity:</b>         | S3 - Moderate                                                                                                                                 |                             |                              |
| <b>Product:</b>          | Netron OS                                                                                                                                     | <b>Reported in Release:</b> | NI 05.8.00                   |
| <b>Technology Group:</b> | Layer 2 Switching                                                                                                                             | <b>Technology:</b>          | LAG - Link Aggregation Group |
| <b>Symptom:</b>          | LACP counter statistics may display boundary values like 42949672 or 429496729 unless the relevant LACP packets are actually received or sent |                             |                              |
| <b>Condition:</b>        | On execution of 'show lacp' cli command                                                                                                       |                             |                              |

|                          |                                                                                                                                                                                                                                              |                             |                                      |
|--------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|--------------------------------------|
| <b>Parent Defect ID:</b> | NI-9763                                                                                                                                                                                                                                      | <b>Issue ID:</b>            | NI-22489                             |
| <b>Severity:</b>         | S3 - Moderate                                                                                                                                                                                                                                |                             |                                      |
| <b>Product:</b>          | Netron OS                                                                                                                                                                                                                                    | <b>Reported in Release:</b> | NI 06.0.00f                          |
| <b>Technology Group:</b> | Layer 3 Routing/Network Layer                                                                                                                                                                                                                | <b>Technology:</b>          | BGP4+ - IPv6 Border Gateway Protocol |
| <b>Symptom:</b>          | show commands in BGP may not filter expected entries on certain conditions                                                                                                                                                                   |                             |                                      |
| <b>Condition:</b>        | <ol style="list-style-type: none"> <li>1. Regular expression used to filter the BGP entries</li> <li>2. BGP prefixes with repeated numbers/values in the expression</li> </ol> ex: show ip bgp sum   i x.x.y to filter prefixes like z.x.x.y |                             |                                      |

|                          |                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |                             |                             |
|--------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-----------------------------|
| <b>Parent Defect ID:</b> | NI-9649                                                                                                                                                                                                                                                                                                                                                                                                                                                                | <b>Issue ID:</b>            | NI-22490                    |
| <b>Severity:</b>         | S2 - Major                                                                                                                                                                                                                                                                                                                                                                                                                                                             |                             |                             |
| <b>Product:</b>          | Netron OS                                                                                                                                                                                                                                                                                                                                                                                                                                                              | <b>Reported in Release:</b> | NI 06.2.00                  |
| <b>Technology Group:</b> | Security                                                                                                                                                                                                                                                                                                                                                                                                                                                               | <b>Technology:</b>          | ACLs - Access Control Lists |
| <b>Symptom:</b>          | Loss of connectivity and ARP is not resolved                                                                                                                                                                                                                                                                                                                                                                                                                           |                             |                             |
| <b>Condition:</b>        | <ol style="list-style-type: none"> <li>1. MLX is upgraded to 6.0a and above versions with 4x10G module</li> <li>2. L4 deny all ACL applied on the physical interface as given below:-<br/>           ip access-list extended ABC<br/>           permit ip x.0.0.0 0.0.0.y any<br/>           deny ip any any<br/>           interface ethernet a/b<br/>           enable<br/>           ip address x.0.0.z/y<br/>           ip access-group ABC in         </li> </ol> |                             |                             |

|                          |               |                             |             |
|--------------------------|---------------|-----------------------------|-------------|
| <b>Parent Defect ID:</b> | NI-17677      | <b>Issue ID:</b>            | NI-22491    |
| <b>Severity:</b>         | S3 - Moderate |                             |             |
| <b>Product:</b>          | Netron OS     | <b>Reported in Release:</b> | NI 06.2.00c |

|                          |                                                                                                                                                                                                                                                        |                    |                             |
|--------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------|-----------------------------|
| <b>Technology Group:</b> | Security                                                                                                                                                                                                                                               | <b>Technology:</b> | ACLs - Access Control Lists |
| <b>Symptom:</b>          | MLX console may respond slow and SSH through VE interfaces/inband are slow                                                                                                                                                                             |                    |                             |
| <b>Condition:</b>        | <ol style="list-style-type: none"> <li>1. Applying ACL with more rules to many virtual interfaces</li> <li>2. Start continuous traffic from source matching applied ACL rules</li> <li>3. Enable 'acl-accounting' and 'sflow' on interfaces</li> </ol> |                    |                             |

|                          |                                                                                                                                                                                                                                                                                                                                                                                                                                         |                             |                                                                  |
|--------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|------------------------------------------------------------------|
| <b>Parent Defect ID:</b> | NI-17590                                                                                                                                                                                                                                                                                                                                                                                                                                | <b>Issue ID:</b>            | NI-22498                                                         |
| <b>Severity:</b>         | S2 - Major                                                                                                                                                                                                                                                                                                                                                                                                                              |                             |                                                                  |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                                                                                                                                                                                                                                              | <b>Reported in Release:</b> | NI 06.0.00f                                                      |
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                                                                                                                                                                                                                                                                                                                                                                                                     | <b>Technology:</b>          | IS-IS - IPv6<br>Intermediate System<br>to Intermediate<br>System |
| <b>Symptom:</b>          | ISIS level 1 routes are not redistributed to Level 2 database                                                                                                                                                                                                                                                                                                                                                                           |                             |                                                                  |
| <b>Condition:</b>        | <ol style="list-style-type: none"> <li>1. Interface is configured with circuit type Level 1<br/>ex:<br/>int eth x/y<br/>isis circuit-type level-1</li> <li>2. Device is configured as level-1-2 router to redistribute the inter area routes from Level-1 into Level-2 database.<br/>ex:<br/>address-family ipv4 unicast<br/>default-metric y<br/>maximum-paths x<br/>metric-style wide<br/>redistribute connected level-1-2</li> </ol> |                             |                                                                  |

|                          |                                                                                                                                                                                                                                                                                                                                                 |                             |                  |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|------------------|
| <b>Parent Defect ID:</b> | NI-22507                                                                                                                                                                                                                                                                                                                                        | <b>Issue ID:</b>            | NI-22507         |
| <b>Severity:</b>         | S2 - Major                                                                                                                                                                                                                                                                                                                                      |                             |                  |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                                                                                                                                                      | <b>Reported in Release:</b> | NI 06.2.00e      |
| <b>Technology Group:</b> | Security                                                                                                                                                                                                                                                                                                                                        | <b>Technology:</b>          | TACACS & TACACS+ |
| <b>Symptom:</b>          | Management Module failover                                                                                                                                                                                                                                                                                                                      |                             |                  |
| <b>Condition:</b>        | <ol style="list-style-type: none"> <li>1. Configured TACACS+ accounting for CLI commands by specifying the privilege level as 0 as below<br/>aaa accounting commands 0 default start-stop tacacs+</li> <li>2. with TACACS+ server key of 30 characters</li> <li>3. Continuous execution of the command "show ip interface" from SSH"</li> </ol> |                             |                  |

|                          |               |                             |                        |
|--------------------------|---------------|-----------------------------|------------------------|
| <b>Parent Defect ID:</b> | NI-22539      | <b>Issue ID:</b>            | NI-22539               |
| <b>Severity:</b>         | S3 - Moderate |                             |                        |
| <b>Product:</b>          | NetIron OS    | <b>Reported in Release:</b> | NI 06.3.00e            |
| <b>Technology Group:</b> | Security      | <b>Technology:</b>          | Security Vulnerability |

|                   |                                                                                         |
|-------------------|-----------------------------------------------------------------------------------------|
| <b>Symptom:</b>   | CVE-2022-0778 - Porting OpenSSL DSA signature algorithm has been shown to be vulnerable |
| <b>Condition:</b> | 1. Configure DSA key algorithm<br>2. Try doing SSH to MLX                               |

|                          |                                                                                                                                                                                                                                                                               |                             |                                         |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-----------------------------------------|
| <b>Parent Defect ID:</b> | NI-22540                                                                                                                                                                                                                                                                      | <b>Issue ID:</b>            | NI-22540                                |
| <b>Severity:</b>         | S3 - Moderate                                                                                                                                                                                                                                                                 |                             |                                         |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                                                                                    | <b>Reported in Release:</b> | NI 06.3.00d                             |
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                                                                                                                                                                                                                                           | <b>Technology:</b>          | OSPF - IPv4 Open<br>Shortest Path First |
| <b>Symptom:</b>          | Originating external lsa after e-route processing for a network with longest mask /29 instead of /24                                                                                                                                                                          |                             |                                         |
| <b>Condition:</b>        | 1. There are two ABRs connecting area 0 and NSSA area.<br>2. The address configured on NSSA internal router and the static address configured on NSSA ABRs are in the same subnet.<br>3. Redistribute connected on NSSA internal routers and redistribute static on NSSA ABR. |                             |                                         |

|                          |                                                                                                                                                                                                                                                                               |                             |                                         |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-----------------------------------------|
| <b>Parent Defect ID:</b> | NI-22541                                                                                                                                                                                                                                                                      | <b>Issue ID:</b>            | NI-22541                                |
| <b>Severity:</b>         | S3 - Moderate                                                                                                                                                                                                                                                                 |                             |                                         |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                                                                                    | <b>Reported in Release:</b> | NI 06.3.00d                             |
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                                                                                                                                                                                                                                           | <b>Technology:</b>          | OSPF - IPv4 Open<br>Shortest Path First |
| <b>Symptom:</b>          | Lower router-id also translates type7 to type5 and it should be done by only higher router id end                                                                                                                                                                             |                             |                                         |
| <b>Condition:</b>        | 1. There are two ABRs connecting area 0 and NSSA area.<br>2. The address configured on NSSA internal router and the static address configured on NSSA ABRs are in the same subnet.<br>3. Redistribute connected on NSSA internal routers and redistribute static on NSSA ABR. |                             |                                         |

## Closed with code changes NI6.3.00d

This section lists software defects with Critical, High, and Medium Technical Severity closed with a code change as of June 2021 in NetIron OS 6.3.00d.

|                          |                                                                                                                                                                                                                               |                             |                             |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-----------------------------|
| <b>Parent Defect ID:</b> | NI-8524                                                                                                                                                                                                                       | <b>Issue ID:</b>            | NI-10818                    |
| <b>Severity:</b>         | S2 - High                                                                                                                                                                                                                     |                             |                             |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                                    | <b>Reported in Release:</b> | NI 06.0.00a                 |
| <b>Technology Group:</b> | MPLS                                                                                                                                                                                                                          | <b>Technology:</b>          | MPLS Traffic<br>Engineering |
| <b>Symptom:</b>          | Device may reload unexpectedly with the following stack trace:-<br>Possible Stack Trace (function call return address list)<br>2159f290: rrr_pkt_edit_rcv(pc)<br>2159f260: rrr_pkt_edit_rcv(lr)<br>21d1adf8: rsvp_pkt_process |                             |                             |

|                   |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |
|-------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|                   | 21d19b48: rrr_rcv_rsvp_message<br>21d8da74: rrr_rcv_sck_data_msg2<br>21d8d7a8: rrr_rcv_sck_data_msg<br>21d8a970: rrip_sock_to_rsvp_proc<br>21dae0ac: rri_receive_proc<br>214a1a7c: nbb_dispatch_process<br>214a0eb8: nbb_schedule_one<br>214a1370: nbb_scheduler<br>214af9d4: nbb_spin_start<br>214a49d8: nbs_spin_start<br>216aef54: mpls_rsvp_recive_data_itc_callback<br>20b8fe8c: itc_process_msgs_internal<br>20b90338: itc_process_msgs<br>2170a434: mpls_task<br>00005e18: sys_end_task |
| <b>Condition:</b> | On reception of Malformed MPLS RSVP Hello packet                                                                                                                                                                                                                                                                                                                                                                                                                                               |

|                          |                                                                                                                                         |                             |                           |
|--------------------------|-----------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|---------------------------|
| <b>Parent Defect ID:</b> | NI-21470                                                                                                                                | <b>Issue ID:</b>            | NI-21518                  |
| <b>Severity:</b>         | S3 - Medium                                                                                                                             |                             |                           |
| <b>Product:</b>          | Netron OS                                                                                                                               | <b>Reported in Release:</b> | NI 06.0.00ha              |
| <b>Technology Group:</b> | Traffic Management                                                                                                                      | <b>Technology:</b>          | Rate Limiting and Shaping |
| <b>Symptom:</b>          | Class-id 0 Re-mapping value may get corrupted in rate-limit table                                                                       |                             |                           |
| <b>Condition:</b>        | It is observed rarely after making changes/rebinding when both global and interface rate-limits are configured concurrently on a system |                             |                           |

|                          |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |                             |                                     |
|--------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-------------------------------------|
| <b>Parent Defect ID:</b> | NI-17605                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | <b>Issue ID:</b>            | NI-21530                            |
| <b>Severity:</b>         | S3 - Medium                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |                             |                                     |
| <b>Product:</b>          | Netron OS                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  | <b>Reported in Release:</b> | NI 06.0.00f                         |
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | <b>Technology:</b>          | BGP4 - IPv4 Border Gateway Protocol |
| <b>Symptom:</b>          | Management Module may unexpectedly reload with the following stack trace:<br>Exception Type 0000 (Soft Check), bgp Timeout (30s)<br>0000f030: msr<br>00000000: dar<br>00000000: dsisr<br>225f9ac8: memset(pc)<br>20fe76ac: bgp_best_route_selection_with_sorting(lr)<br>20fe7fc4: bgp_best_route_selection_and_change<br>20fb8724: bgp_check_and_update_bgp_route_in_ip_ta<br>20ff7320: bgp_clear_dampened_paths<br>21009088: bgp_clear_dampening_itc_request_callbac<br>20ba3ac0: itc_process_msgs_internal<br>20ba3f6c: itc_process_msgs |                             |                                     |

|                   |                                                                                                                     |
|-------------------|---------------------------------------------------------------------------------------------------------------------|
|                   | 210275d8: bgp_task<br>00005e18: sys_end_task                                                                        |
| <b>Condition:</b> | It is observed rarely while clearing dampening routes using clear command like below:<br><br>clear ip bgp dampening |

|                          |                                                                                                                  |                             |                 |
|--------------------------|------------------------------------------------------------------------------------------------------------------|-----------------------------|-----------------|
| <b>Parent Defect ID:</b> | NI-21141                                                                                                         | <b>Issue ID:</b>            | NI-21537        |
| <b>Severity:</b>         | S2 - High                                                                                                        |                             |                 |
| <b>Product:</b>          | NetIron OS                                                                                                       | <b>Reported in Release:</b> | NI 06.0.00h     |
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                                                                              | <b>Technology:</b>          | IPv6 Addressing |
| <b>Symptom:</b>          | Connectivity loss may be observed in IPv6 network                                                                |                             |                 |
| <b>Condition:</b>        | It is observed rarely on a MCT/ VEOVPLS configured device with MCT spoke connection in between the cluster peers |                             |                 |

|                          |                                                                                                                                                                                                                                                                                                      |                             |                          |
|--------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|--------------------------|
| <b>Parent Defect ID:</b> | NI-21431                                                                                                                                                                                                                                                                                             | <b>Issue ID:</b>            | NI-21558                 |
| <b>Severity:</b>         | S2 - High                                                                                                                                                                                                                                                                                            |                             |                          |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                                                                                                           | <b>Reported in Release:</b> | NI 05.8.00h              |
| <b>Technology Group:</b> | Traffic Management                                                                                                                                                                                                                                                                                   | <b>Technology:</b>          | QoS - Quality of Service |
| <b>Symptom:</b>          | Packet priority may not be retained for control traffic                                                                                                                                                                                                                                              |                             |                          |
| <b>Condition:</b>        | It is seen rarely on a MLX device, when the priority (TOS/DSCP) of the control traffic is modified at user level.<br><br>Note: A New CLI (disable-ppgxt-prioritization) has been introduced to override the default behavior thereby retaining the actual priority value of control packets/traffic. |                             |                          |

|                          |                                                                                                                                          |                             |                  |
|--------------------------|------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|------------------|
| <b>Parent Defect ID:</b> | NI-21149                                                                                                                                 | <b>Issue ID:</b>            | NI-21573         |
| <b>Severity:</b>         | S3 - Medium                                                                                                                              |                             |                  |
| <b>Product:</b>          | NetIron OS                                                                                                                               | <b>Reported in Release:</b> | NI 06.0.00c      |
| <b>Technology Group:</b> | Security                                                                                                                                 | <b>Technology:</b>          | TACACS & TACACS+ |
| <b>Symptom:</b>          | Sometimes SSH session may fail to login on specific vty                                                                                  |                             |                  |
| <b>Condition:</b>        | 1.AAA authentication, authorization and accounting configured<br>2.Frequent creation and termination of SSH sessions with CLI's executed |                             |                  |

|                          |                                                                                               |                             |                                          |
|--------------------------|-----------------------------------------------------------------------------------------------|-----------------------------|------------------------------------------|
| <b>Parent Defect ID:</b> | NI-21442                                                                                      | <b>Issue ID:</b>            | NI-21585                                 |
| <b>Severity:</b>         | S3 - Medium                                                                                   |                             |                                          |
| <b>Product:</b>          | NetIron OS                                                                                    | <b>Reported in Release:</b> | NI 06.2.00                               |
| <b>Technology Group:</b> | MPLS                                                                                          | <b>Technology:</b>          | MPLS VPLS - Virtual Private LAN Services |
| <b>Symptom:</b>          | VPLS index in 'show mpls vpls local' does not match with index in 'show logging' log message. |                             |                                          |
| <b>Condition:</b>        | Multiple VPLS instances with multiple VPLS peers are configured.                              |                             |                                          |

|                          |                                                                                               |                             |                                        |
|--------------------------|-----------------------------------------------------------------------------------------------|-----------------------------|----------------------------------------|
| <b>Parent Defect ID:</b> | NI-21588                                                                                      | <b>Issue ID:</b>            | NI-21589                               |
| <b>Severity:</b>         | S3 - Medium                                                                                   |                             |                                        |
| <b>Product:</b>          | Netlron OS                                                                                    | <b>Reported in Release:</b> | NI 06.0.00ha                           |
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                                                           | <b>Technology:</b>          | BGP4 - IPv4 Border<br>Gateway Protocol |
| <b>Symptom:</b>          | BGP route updates may get stuck in ToSend queue                                               |                             |                                        |
| <b>Condition:</b>        | 1.Routes with a large amount of attributes set<br>2.Update message length more than 1400bytes |                             |                                        |

|                          |                                         |                             |                                             |
|--------------------------|-----------------------------------------|-----------------------------|---------------------------------------------|
| <b>Parent Defect ID:</b> | NI-21631                                | <b>Issue ID:</b>            | NI-21632                                    |
| <b>Severity:</b>         | S2 - High                               |                             |                                             |
| <b>Product:</b>          | Netlron OS                              | <b>Reported in Release:</b> | NI 06.0.00jc                                |
| <b>Technology Group:</b> | Monitoring                              | <b>Technology:</b>          | OAM - Operations,<br>Admin &<br>Maintenance |
| <b>Symptom:</b>          | 100G Links may observe sub second flaps |                             |                                             |
| <b>Condition:</b>        | Presence of Rev 2 CFP2 ER4 optic        |                             |                                             |

|                          |                                                                                                                                                                                                                                                                                 |                             |                                    |
|--------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|------------------------------------|
| <b>Parent Defect ID:</b> | NI-21641                                                                                                                                                                                                                                                                        | <b>Issue ID:</b>            | NI-21643                           |
| <b>Severity:</b>         | S3 - Medium                                                                                                                                                                                                                                                                     |                             |                                    |
| <b>Product:</b>          | Netlron OS                                                                                                                                                                                                                                                                      | <b>Reported in Release:</b> | NI 06.2.00e                        |
| <b>Technology Group:</b> | Traffic Management                                                                                                                                                                                                                                                              | <b>Technology:</b>          | Traffic Queueing and<br>Scheduling |
| <b>Symptom:</b>          | Packet drops seen before the TM-NIF errors reach the configured limit are not logged.                                                                                                                                                                                           |                             |                                    |
| <b>Condition:</b>        | Generally, there is a TM-NIF link monitoring every 1 min and if the errors reach configured limit there is a default action like shutdown the ports etc, but if before reaching the limit if there are drops, now addressed by a new action of snmp traps through this feature. |                             |                                    |

|                          |                                                                                                                                                      |                             |                                        |
|--------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|----------------------------------------|
| <b>Parent Defect ID:</b> | NI-21674                                                                                                                                             | <b>Issue ID:</b>            | NI-21675                               |
| <b>Severity:</b>         | S3 - Medium                                                                                                                                          |                             |                                        |
| <b>Product:</b>          | Netlron OS                                                                                                                                           | <b>Reported in Release:</b> | NI 06.0.00ha                           |
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                                                                                                                  | <b>Technology:</b>          | BGP4 - IPv4 Border<br>Gateway Protocol |
| <b>Symptom:</b>          | Rate Limit causing BGP session timing out                                                                                                            |                             |                                        |
| <b>Condition:</b>        | When 'ip rate-limit ttl-exceeded-to-cpu' and 'ipv6 rate-limit hoplimit-expired-to-cpu' are configured globally, it causes their BGP sessions to flap |                             |                                        |

|                          |             |                             |              |
|--------------------------|-------------|-----------------------------|--------------|
| <b>Parent Defect ID:</b> | NI-21712    | <b>Issue ID:</b>            | NI-21712     |
| <b>Severity:</b>         | S3 - Medium |                             |              |
| <b>Product:</b>          | Netlron OS  | <b>Reported in Release:</b> | NI 06.0.00ha |

|                          |                                                      |                    |                                       |
|--------------------------|------------------------------------------------------|--------------------|---------------------------------------|
| <b>Technology Group:</b> | Monitoring                                           | <b>Technology:</b> | OAM - Operations, Admin & Maintenance |
| <b>Symptom:</b>          | Port may not come up on 2x100G CFP2 Line card module |                    |                                       |
| <b>Condition:</b>        | In the presence of Finisar 100GE QSFP28-LR4 optic    |                    |                                       |

|                          |                                                                                                                                                                                                                 |                             |                                     |
|--------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-------------------------------------|
| <b>Parent Defect ID:</b> | NI-21756                                                                                                                                                                                                        | <b>Issue ID:</b>            | NI-21756                            |
| <b>Severity:</b>         | S3 - Medium                                                                                                                                                                                                     |                             |                                     |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                      | <b>Reported in Release:</b> | NI 06.3.00a                         |
| <b>Technology Group:</b> | Layer 3 Routing/Network Layer                                                                                                                                                                                   | <b>Technology:</b>          | BGP4 - IPv4 Border Gateway Protocol |
| <b>Symptom:</b>          | default-originate command applied on the neighbor doesn't originate the default route to the neighbor                                                                                                           |                             |                                     |
| <b>Condition:</b>        | <ol style="list-style-type: none"> <li>1. BGP is configured on the router</li> <li>2. neighbor is configured with default-originate command with route-map</li> <li>3. The NULL route-map is applied</li> </ol> |                             |                                     |

|                          |                                                                                                                                     |                             |                                       |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|---------------------------------------|
| <b>Parent Defect ID:</b> | NI-9765                                                                                                                             | <b>Issue ID:</b>            | NI-21813                              |
| <b>Severity:</b>         | S3 - Medium                                                                                                                         |                             |                                       |
| <b>Product:</b>          | NetIron OS                                                                                                                          | <b>Reported in Release:</b> | NI 06.0.00f                           |
| <b>Technology Group:</b> | Monitoring                                                                                                                          | <b>Technology:</b>          | OAM - Operations, Admin & Maintenance |
| <b>Symptom:</b>          | Link may stay down for 2x100G CFP2 Line card                                                                                        |                             |                                       |
| <b>Condition:</b>        | In the presence of third party LR4 range of optics<br><br>Note: Enabling 'fec' in CLI will now be allowed for LR4 to fix this issue |                             |                                       |

|                          |                                                                                                                                                                                                                                                                                                                 |                             |                              |
|--------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|------------------------------|
| <b>Parent Defect ID:</b> | NI-21803                                                                                                                                                                                                                                                                                                        | <b>Issue ID:</b>            | NI-21817                     |
| <b>Severity:</b>         | S3 - Medium                                                                                                                                                                                                                                                                                                     |                             |                              |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                                                                                                                      | <b>Reported in Release:</b> | NI 06.2.00d                  |
| <b>Technology Group:</b> | Management                                                                                                                                                                                                                                                                                                      | <b>Technology:</b>          | CLI - Command Line Interface |
| <b>Symptom:</b>          | CER/CES may reload unexpectedly with the following stack trace:-<br>Possible Stack Trace (function call return address list)<br>000c454c: tsec_mib_dump(pc)<br>000c4544: tsec_mib_dump(lr)<br>000c4e5c: tsec_show_cmd<br>0007b730: parser<br>0007c654: cmdloop<br>000468ec: root_task<br>00040158: sys_end_task |                             |                              |
| <b>Condition:</b>        | On execution of 'tsec 1 show' cli command from OS mode                                                                                                                                                                                                                                                          |                             |                              |

|                          |          |                  |          |
|--------------------------|----------|------------------|----------|
| <b>Parent Defect ID:</b> | NI-21825 | <b>Issue ID:</b> | NI-21825 |
|--------------------------|----------|------------------|----------|

|                          |                                                                                                                                                                                                                          |                             |                                       |
|--------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|---------------------------------------|
| <b>Severity:</b>         | S3 - Medium                                                                                                                                                                                                              |                             |                                       |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                               | <b>Reported in Release:</b> | NI 06.2.00e                           |
| <b>Technology Group:</b> | Monitoring                                                                                                                                                                                                               | <b>Technology:</b>          | OAM - Operations, Admin & Maintenance |
| <b>Symptom:</b>          | Latency/loss of frames are observed for Y.1731 (dot1ag) traffic.                                                                                                                                                         |                             |                                       |
| <b>Condition:</b>        | 1)MCT is configured with member VLAN's.<br>2)Dot1ag-transparent is configured and either LP power-cycle, LP resear or reload of the chassis is performed.<br>3)802.1ag frames are transmitted with different priorities. |                             |                                       |

|                          |                                                                                                                                        |                             |                                   |
|--------------------------|----------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-----------------------------------|
| <b>Parent Defect ID:</b> | NI-21841                                                                                                                               | <b>Issue ID:</b>            | NI-21841                          |
| <b>Severity:</b>         | S3 - Medium                                                                                                                            |                             |                                   |
| <b>Product:</b>          | NetIron OS                                                                                                                             | <b>Reported in Release:</b> | NI 06.0.00j                       |
| <b>Technology Group:</b> | Layer 3 Routing/Network Layer                                                                                                          | <b>Technology:</b>          | ARP - Address Resolution Protocol |
| <b>Symptom:</b>          | After reload, ARP-Guard is applied to non-configured ports                                                                             |                             |                                   |
| <b>Condition:</b>        | 1. system has 100G card inserted in any slot<br>2. LAG is configured and applied ARP-Guard on the primary port<br>3. reload the system |                             |                                   |

|                          |                                                                                                                                                                                                            |                             |                                           |
|--------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-------------------------------------------|
| <b>Parent Defect ID:</b> | NI-21784                                                                                                                                                                                                   | <b>Issue ID:</b>            | NI-21846                                  |
| <b>Severity:</b>         | S3 - Medium                                                                                                                                                                                                |                             |                                           |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                 | <b>Reported in Release:</b> | NI 06.2.00d                               |
| <b>Technology Group:</b> | Management                                                                                                                                                                                                 | <b>Technology:</b>          | SNMP - Simple Network Management Protocol |
| <b>Symptom:</b>          | SNMP bulk may not get proper value for optical monitoring table                                                                                                                                            |                             |                                           |
| <b>Condition:</b>        | SNMP bulk get for the same slot<br><br>Example :-<br><br>snmpget -v 2c -c public 10.26.143.246<br>.1.3.6.1.4.1.1991.1.1.3.3.6.1.1.1 .1.3.6.1.4.1.1991.1.1.3.3.6.1.2.1<br>.1.3.6.1.4.1.1991.1.1.3.3.6.1.3.1 |                             |                                           |

|                          |                                                                                                                  |                             |                             |
|--------------------------|------------------------------------------------------------------------------------------------------------------|-----------------------------|-----------------------------|
| <b>Parent Defect ID:</b> | NI-21847                                                                                                         | <b>Issue ID:</b>            | NI-21847                    |
| <b>Severity:</b>         | S3 - Medium                                                                                                      |                             |                             |
| <b>Product:</b>          | NetIron OS                                                                                                       | <b>Reported in Release:</b> | NI 06.0.00je                |
| <b>Technology Group:</b> | Management                                                                                                       | <b>Technology:</b>          | NTP - Network Time Protocol |
| <b>Symptom:</b>          | NTP symmetric passive association messages are seen in the log file without specifically configured for a server |                             |                             |
| <b>Condition:</b>        | Router listening on all IP's when NTP is disabled                                                                |                             |                             |

|                          |                                                                                                                                                       |                             |                                        |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|----------------------------------------|
| <b>Parent Defect ID:</b> | NI-21752                                                                                                                                              | <b>Issue ID:</b>            | NI-21851                               |
| <b>Severity:</b>         | S3 - Medium                                                                                                                                           |                             |                                        |
| <b>Product:</b>          | NetIron OS                                                                                                                                            | <b>Reported in Release:</b> | NI 06.0.00g                            |
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                                                                                                                   | <b>Technology:</b>          | BGP4 - IPv4 Border<br>Gateway Protocol |
| <b>Symptom:</b>          | Some prefix in RTM is not updated with change in BGP route table                                                                                      |                             |                                        |
| <b>Condition:</b>        | When BGP maximum-path has been configured, routing table still show old multipath routes even though BGP table has been updated with new route paths. |                             |                                        |

|                          |                                                                                                                                                                          |                             |                                         |
|--------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-----------------------------------------|
| <b>Parent Defect ID:</b> | NI-21809                                                                                                                                                                 | <b>Issue ID:</b>            | NI-21852                                |
| <b>Severity:</b>         | S2 - High                                                                                                                                                                |                             |                                         |
| <b>Product:</b>          | NetIron OS                                                                                                                                                               | <b>Reported in Release:</b> | NI 06.0.00f                             |
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                                                                                                                                      | <b>Technology:</b>          | OSPF - IPv4 Open<br>Shortest Path First |
| <b>Symptom:</b>          | redistribute route learned through Type-7 LSA in NSSA area is not installed in the routing table                                                                         |                             |                                         |
| <b>Condition:</b>        | <ol style="list-style-type: none"> <li>1. Two ABR exists in an NSSA area</li> <li>2. static route is configured and advertised by ASBR through redistribution</li> </ol> |                             |                                         |

|                          |                                                           |                             |                 |
|--------------------------|-----------------------------------------------------------|-----------------------------|-----------------|
| <b>Parent Defect ID:</b> | NI-21855                                                  | <b>Issue ID:</b>            | NI-21855        |
| <b>Severity:</b>         | S2 - High                                                 |                             |                 |
| <b>Product:</b>          | NetIron OS                                                | <b>Reported in Release:</b> | NI 06.2.00ec    |
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                       | <b>Technology:</b>          | IPv6 Addressing |
| <b>Symptom:</b>          | Intermittent packet loss may be observed for IPv6 network |                             |                 |
| <b>Condition:</b>        | It is observed rarely on a VEOVPLS configured device      |                             |                 |

|                          |                                                         |                             |                     |
|--------------------------|---------------------------------------------------------|-----------------------------|---------------------|
| <b>Parent Defect ID:</b> | NI-21857                                                | <b>Issue ID:</b>            | NI-21857            |
| <b>Severity:</b>         | S3 - Medium                                             |                             |                     |
| <b>Product:</b>          | NetIron OS                                              | <b>Reported in Release:</b> | NI 06.3.00a         |
| <b>Technology Group:</b> | Security                                                | <b>Technology:</b>          | IPsec - IP Security |
| <b>Symptom:</b>          | IPSEC tunnels dropped and did not recover               |                             |                     |
| <b>Condition:</b>        | When LP was reloaded which has IPSEC tunnels configured |                             |                     |

|                          |             |                             |                                                           |
|--------------------------|-------------|-----------------------------|-----------------------------------------------------------|
| <b>Parent Defect ID:</b> | NI-21875    | <b>Issue ID:</b>            | NI-21875                                                  |
| <b>Severity:</b>         | S3 - Medium |                             |                                                           |
| <b>Product:</b>          | NetIron OS  | <b>Reported in Release:</b> | NI 06.0.00f                                               |
| <b>Technology Group:</b> | Security    | <b>Technology:</b>          | AAA - Authentication,<br>Authorization, and<br>Accounting |

|                   |                                                                                                                                       |
|-------------------|---------------------------------------------------------------------------------------------------------------------------------------|
| <b>Symptom:</b>   | May observe below error messages during AAA accounting:-<br>NOTE: AAA stopped paste as an invalid command is seen in the current mode |
| <b>Condition:</b> | Configuring Ipv6 prefix list with prefix length more than 32<br><br>Example :-<br><br>ipv6 prefix-list test2 deny ::/0 le 33          |

|                          |                                                                                                                                                                                     |                             |                                       |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|---------------------------------------|
| <b>Parent Defect ID:</b> | NI-21877                                                                                                                                                                            | <b>Issue ID:</b>            | NI-21877                              |
| <b>Severity:</b>         | S3 - Medium                                                                                                                                                                         |                             |                                       |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                          | <b>Reported in Release:</b> | NI 06.0.00j                           |
| <b>Technology Group:</b> | Monitoring                                                                                                                                                                          | <b>Technology:</b>          | OAM - Operations, Admin & Maintenance |
| <b>Symptom:</b>          | Link-OAM causing interface flap when another LP is power-cycled                                                                                                                     |                             |                                       |
| <b>Condition:</b>        | 1. Link-oam command is configured globally attaching ports from any specific LP for which timeout command should be configured less than 2 secs<br>2. Unrelated LP is power-cycled. |                             |                                       |

|                          |                                                                                                                                                                                                                                                                                                 |                             |                                     |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-------------------------------------|
| <b>Parent Defect ID:</b> | NI-21880                                                                                                                                                                                                                                                                                        | <b>Issue ID:</b>            | NI-21880                            |
| <b>Severity:</b>         | S3 - Medium                                                                                                                                                                                                                                                                                     |                             |                                     |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                                                                                                      | <b>Reported in Release:</b> | NI 06.2.00                          |
| <b>Technology Group:</b> | Layer 3 Routing/Network Layer                                                                                                                                                                                                                                                                   | <b>Technology:</b>          | GRE - Generic Routing Encapsulation |
| <b>Symptom:</b>          | Elevated CPU and Traffic Volume Due to GRE Configuration                                                                                                                                                                                                                                        |                             |                                     |
| <b>Condition:</b>        | 1. Two loopbacks (loopback system) are configured on the ingress physical port and another loopback configured on another physical port with PBR configuration.<br>2. On LB1, the nexthop is set as a specific vlan with out-going DA MAC<br>3. On LB2, next-hop-ip-tunnel is set to GRE tunnel |                             |                                     |

|                          |                                                                                   |                             |             |
|--------------------------|-----------------------------------------------------------------------------------|-----------------------------|-------------|
| <b>Parent Defect ID:</b> | NI-17554                                                                          | <b>Issue ID:</b>            | NI-21883    |
| <b>Severity:</b>         | S3 - Medium                                                                       |                             |             |
| <b>Product:</b>          | NetIron OS                                                                        | <b>Reported in Release:</b> | NI 06.0.00g |
| <b>Technology Group:</b> | Monitoring                                                                        | <b>Technology:</b>          | Syslog      |
| <b>Symptom:</b>          | Latched Low, High Optical Monitoring Messages are observed in syslog periodically |                             |             |
| <b>Condition:</b>        | Even though values are normal from "show optic" command values                    |                             |             |

|                          |             |                             |             |
|--------------------------|-------------|-----------------------------|-------------|
| <b>Parent Defect ID:</b> | NI-21904    | <b>Issue ID:</b>            | NI-21904    |
| <b>Severity:</b>         | S3 - Medium |                             |             |
| <b>Product:</b>          | NetIron OS  | <b>Reported in Release:</b> | NI 06.2.00e |

|                          |                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |                    |                 |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------|-----------------|
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                                                                                                                                                                                                                                                                                                                                                                                                                               | <b>Technology:</b> | IPv6 Addressing |
| <b>Symptom:</b>          | Management Module may unexpectedly reload with the following stack trace:-<br>220e0e34: vpls_mac_find_entry_by_vpls_idx(pc)<br>2126937c: nd6_process_neighbor_advert_message(lr)<br>2126937c: nd6_process_neighbor_advert_message<br>2123a254: icmp6_packet_received<br>212634ec: ip6_pass_packet_to_upper_layer<br>21262dec: ip6_packet_received<br>20f64614: l3_receive_packet<br>20f6508c: sw_receive_packet<br>20f65508: mp_rx_main<br>00005e18: sys_end_task |                    |                 |
| <b>Condition:</b>        | It is observed rarely on a MLX/XMR device, with VEOVPLS configured                                                                                                                                                                                                                                                                                                                                                                                                |                    |                 |

|                          |                                                                                |                             |                                         |
|--------------------------|--------------------------------------------------------------------------------|-----------------------------|-----------------------------------------|
| <b>Parent Defect ID:</b> | NI-21907                                                                       | <b>Issue ID:</b>            | NI-21907                                |
| <b>Severity:</b>         | S2 - High                                                                      |                             |                                         |
| <b>Product:</b>          | NetIron OS                                                                     | <b>Reported in Release:</b> | NI 06.2.00b                             |
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                                            | <b>Technology:</b>          | OSPF - IPv4 Open<br>Shortest Path First |
| <b>Symptom:</b>          | OSPF task may utilize around 31% of Management Module CPU                      |                             |                                         |
| <b>Condition:</b>        | On reception of larger LSA packet in the presence of standby Management Module |                             |                                         |

|                          |                                                                                                                                                       |                             |                                        |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|----------------------------------------|
| <b>Parent Defect ID:</b> | NI-21937                                                                                                                                              | <b>Issue ID:</b>            | NI-21937                               |
| <b>Severity:</b>         | S3 - Medium                                                                                                                                           |                             |                                        |
| <b>Product:</b>          | NetIron OS                                                                                                                                            | <b>Reported in Release:</b> | NI 06.0.00jf                           |
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                                                                                                                   | <b>Technology:</b>          | BGP4 - IPv4 Border<br>Gateway Protocol |
| <b>Symptom:</b>          | Some prefix in RTM is not updated with change in BGP route table                                                                                      |                             |                                        |
| <b>Condition:</b>        | When BGP maximum-path has been configured, routing table still show old multipath routes even though BGP table has been updated with new route paths. |                             |                                        |

|                          |                                                                                            |                             |                                             |
|--------------------------|--------------------------------------------------------------------------------------------|-----------------------------|---------------------------------------------|
| <b>Parent Defect ID:</b> | NI-21198                                                                                   | <b>Issue ID:</b>            | NI-21987                                    |
| <b>Severity:</b>         | S2 - High                                                                                  |                             |                                             |
| <b>Product:</b>          | NetIron OS                                                                                 | <b>Reported in Release:</b> | NI 06.0.00                                  |
| <b>Technology Group:</b> | IP Multicast                                                                               | <b>Technology:</b>          | PIM - Protocol-<br>Independent<br>Multicast |
| <b>Symptom:</b>          | Multicast video stream is not received on viewing stations in a SPT switchover environment |                             |                                             |

|                   |                                                                                                                                                                                                                                                                                                                                               |
|-------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Condition:</b> | <ol style="list-style-type: none"> <li>1. CER/MLX device is immediately connected to the source directly</li> <li>2. SLX device is connected as FHR running IGMP on one side and PIM on the other side towards the CER/MLX devices.</li> <li>3. All source/CER/SLX are in the same VLAN and the receivers are on a different VLANs</li> </ol> |
|-------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

|                          |                                                                                                                                              |                             |                                           |
|--------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-------------------------------------------|
| <b>Parent Defect ID:</b> | NI-21996                                                                                                                                     | <b>Issue ID:</b>            | NI-21996                                  |
| <b>Severity:</b>         | S2 - High                                                                                                                                    |                             |                                           |
| <b>Product:</b>          | NetIron OS                                                                                                                                   | <b>Reported in Release:</b> | NI 06.0.00h                               |
| <b>Technology Group:</b> | Management                                                                                                                                   | <b>Technology:</b>          | SNMP - Simple Network Management Protocol |
| <b>Symptom:</b>          | Optic value shows up in cli output but shows not supported in SNMP client                                                                    |                             |                                           |
| <b>Condition:</b>        | 100G or 40G LP card is inserted in any of the slot and SNMP walk or get/get-next operation performed for the object optical lane monitoring. |                             |                                           |

|                          |                                                                                                     |                             |            |
|--------------------------|-----------------------------------------------------------------------------------------------------|-----------------------------|------------|
| <b>Parent Defect ID:</b> | NI-22003                                                                                            | <b>Issue ID:</b>            | NI-22003   |
| <b>Severity:</b>         | S3 - Medium                                                                                         |                             |            |
| <b>Product:</b>          | NetIron OS                                                                                          | <b>Reported in Release:</b> | NI 06.3.00 |
| <b>Technology Group:</b> | Layer 3 Routing/Network Layer                                                                       | <b>Technology:</b>          | Multi-VRF  |
| <b>Symptom:</b>          | In-label information was not seen when sh ip bgp vpnv4 tag command was issued.                      |                             |            |
| <b>Condition:</b>        | In-label for all VRFs were not seen when the label going to upstream BGP peer for incoming traffic. |                             |            |

|                          |                                                                  |                             |                                           |
|--------------------------|------------------------------------------------------------------|-----------------------------|-------------------------------------------|
| <b>Parent Defect ID:</b> | NI-9412                                                          | <b>Issue ID:</b>            | NI-22016                                  |
| <b>Severity:</b>         | S2 - High                                                        |                             |                                           |
| <b>Product:</b>          | NetIron OS                                                       | <b>Reported in Release:</b> | NI 05.8.00fb                              |
| <b>Technology Group:</b> | Management                                                       | <b>Technology:</b>          | SNMP - Simple Network Management Protocol |
| <b>Symptom:</b>          | The maximum response time for SNMP polling may go around 300msec |                             |                                           |
| <b>Condition:</b>        | SNMP walk for snIfOpticalMonitoringInfoTable                     |                             |                                           |

|                          |             |                             |                                          |
|--------------------------|-------------|-----------------------------|------------------------------------------|
| <b>Parent Defect ID:</b> | NI-17641    | <b>Issue ID:</b>            | NI-22019                                 |
| <b>Severity:</b>         | S3 - Medium |                             |                                          |
| <b>Product:</b>          | NetIron OS  | <b>Reported in Release:</b> | NI 06.2.00ca                             |
| <b>Technology Group:</b> | MPLS        | <b>Technology:</b>          | MPLS VPLS - Virtual Private LAN Services |

|                   |                                                                                                                                                                                                          |
|-------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Symptom:</b>   | With VPLS "rate-limit input unknown-unicast", "show rate-limit counters" can show 0 drops                                                                                                                |
| <b>Condition:</b> | 1. VPLS is configured with the command "rate-limit input unknown-unicast" under the vpls instance<br>2. various traffic patterns is passed over this instance and this traffic is stopped for 30 seconds |

|                          |                                                                                                                                           |                             |                                                     |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-----------------------------------------------------|
| <b>Parent Defect ID:</b> | NI-21172                                                                                                                                  | <b>Issue ID:</b>            | NI-22031                                            |
| <b>Severity:</b>         | S3 - Medium                                                                                                                               |                             |                                                     |
| <b>Product:</b>          | NetIron OS                                                                                                                                | <b>Reported in Release:</b> | NI 06.0.00h                                         |
| <b>Technology Group:</b> | Monitoring                                                                                                                                | <b>Technology:</b>          | RAS - Reliability, Availability, and Serviceability |
| <b>Symptom:</b>          | Port may go down on 4x10G line card module                                                                                                |                             |                                                     |
| <b>Condition:</b>        | Presence of non-brocade TWINAX SFPP optic<br><br>Note: "phy disable-equalization" will be allowed for 4x10G as well in addition to 8x10G. |                             |                                                     |

|                          |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |                             |                                     |
|--------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-------------------------------------|
| <b>Parent Defect ID:</b> | NI-17614                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             | <b>Issue ID:</b>            | NI-22033                            |
| <b>Severity:</b>         | S3 - Medium                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |                             |                                     |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | <b>Reported in Release:</b> | NI 06.0.00f                         |
| <b>Technology Group:</b> | Layer 3 Routing/Network Layer                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | <b>Technology:</b>          | BGP4 - IPv4 Border Gateway Protocol |
| <b>Symptom:</b>          | Active Management Module may reload with the following stack trace:-<br>Possible Stack Trace (function call return address list)<br>20f76924: bgp_check_for_fwd_address(pc)<br>20fb9534:<br>bgp_check_and_update_bgp_route_in_ip_table_as_necessary(lr)<br>20fb9534:<br>bgp_check_and_update_bgp_route_in_ip_table_as_necessary<br>20ff447c: bgp_route_damping_timer_event<br>20fd7478: bgp_timer<br>20fd2a68: bgp_timeout_func<br>20ba3ac0: itc_process_msgs_internal<br>20ba3f6c: itc_process_msgs<br>210275d8: bgp_task<br>00005e18: sys_end_task |                             |                                     |
| <b>Condition:</b>        | Frequent route flap and route churn with BGP dampening configured on the device                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |                             |                                     |

|                          |             |                             |             |
|--------------------------|-------------|-----------------------------|-------------|
| <b>Parent Defect ID:</b> | NI-14763    | <b>Issue ID:</b>            | NI-22043    |
| <b>Severity:</b>         | S3 - Medium |                             |             |
| <b>Product:</b>          | NetIron OS  | <b>Reported in Release:</b> | NI 06.0.00f |

|                          |                                                                                                                                                                                                                                                                                                                                                                                                              |                    |                                        |
|--------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------|----------------------------------------|
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                                                                                                                                                                                                                                                                                                                                                                          | <b>Technology:</b> | BGP4 - IPv4 Border<br>Gateway Protocol |
| <b>Symptom:</b>          | Management Module may unexpectedly reload with the following stack trace:-<br>20ff5f58: bgp_print_flap_statistics_entry(pc)<br>20ff5f54: bgp_print_flap_statistics_entry(lr)<br>20ff6414: bgp_get_flap_statistics_page_itc_handler<br>2100b2c0: bgp_show_dampening_itc_request_callback<br>20ba3ac0: itc_process_msgs_internal<br>20ba3f6c: itc_process_msgs<br>210275d8: bgp_task<br>00005e18: sys_end_task |                    |                                        |
| <b>Condition:</b>        | It is observed rarely on a MLX/XMR device when,<br>1. "show ip bgp flap-statistics" is executed<br>2. Dampening events also occurs in parallel                                                                                                                                                                                                                                                               |                    |                                        |

|                          |                                                                                                                                                                         |                             |                       |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-----------------------|
| <b>Parent Defect ID:</b> | NI-17369                                                                                                                                                                | <b>Issue ID:</b>            | NI-22044              |
| <b>Severity:</b>         | S3 - Medium                                                                                                                                                             |                             |                       |
| <b>Product:</b>          | NetIron OS                                                                                                                                                              | <b>Reported in Release:</b> | NI 05.8.00d           |
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                                                                                                                                     | <b>Technology:</b>          | Static Routing (IPv4) |
| <b>Symptom:</b>          | Unstable routes with continuous route updation observed in the MLX under specific condition                                                                             |                             |                       |
| <b>Condition:</b>        | When static route configured with next-hop-vrf as non-default VRF<br>Ex:<br>vrf vrf0X<br>rd a:b<br>address-family ipv4<br>ip route x.x.x.x/y next-hop-vrf vrf0Y z.z.z.z |                             |                       |

|                          |                                                                                                   |                             |                              |
|--------------------------|---------------------------------------------------------------------------------------------------|-----------------------------|------------------------------|
| <b>Parent Defect ID:</b> | NI-17440                                                                                          | <b>Issue ID:</b>            | NI-22046                     |
| <b>Severity:</b>         | S3 - Medium                                                                                       |                             |                              |
| <b>Product:</b>          | NetIron OS                                                                                        | <b>Reported in Release:</b> | NI 06.0.00c                  |
| <b>Technology Group:</b> | Traffic Management                                                                                | <b>Technology:</b>          | Rate Limiting and<br>Shaping |
| <b>Symptom:</b>          | High LP CPU may be observed on 20x10G and 2x100G CFP2 Line card module                            |                             |                              |
| <b>Condition:</b>        | 1. Configure policy-map and apply ARP rate-limit globally<br>2. Received ARP traffic at high rate |                             |                              |

|                          |                                           |                             |                     |
|--------------------------|-------------------------------------------|-----------------------------|---------------------|
| <b>Parent Defect ID:</b> | NI-22050                                  | <b>Issue ID:</b>            | NI-22050            |
| <b>Severity:</b>         | S2 - High                                 |                             |                     |
| <b>Product:</b>          | NetIron OS                                | <b>Reported in Release:</b> | NI 06.2.00e         |
| <b>Technology Group:</b> | Security                                  | <b>Technology:</b>          | IPsec - IP Security |
| <b>Symptom:</b>          | IPSEC tunnels dropped and did not recover |                             |                     |

|                   |                                                         |
|-------------------|---------------------------------------------------------|
| <b>Condition:</b> | When LP was reloaded which has IPSEC tunnels configured |
|-------------------|---------------------------------------------------------|

|                          |                                                                                   |                             |             |
|--------------------------|-----------------------------------------------------------------------------------|-----------------------------|-------------|
| <b>Parent Defect ID:</b> | NI-22053                                                                          | <b>Issue ID:</b>            | NI-22053    |
| <b>Severity:</b>         | S3 - Medium                                                                       |                             |             |
| <b>Product:</b>          | NetIron OS                                                                        | <b>Reported in Release:</b> | NI 06.2.00f |
| <b>Technology Group:</b> | Monitoring                                                                        | <b>Technology:</b>          | Sysmon      |
| <b>Symptom:</b>          | Latched Low, High Optical Monitoring Messages are observed in syslog periodically |                             |             |
| <b>Condition:</b>        | When False threshold alarms are raised                                            |                             |             |

|                          |                                                                                                                                                                                                                                                                                                           |                             |                                                  |
|--------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|--------------------------------------------------|
| <b>Parent Defect ID:</b> | NI-22066                                                                                                                                                                                                                                                                                                  | <b>Issue ID:</b>            | NI-22066                                         |
| <b>Severity:</b>         | S3 - Medium                                                                                                                                                                                                                                                                                               |                             |                                                  |
| <b>Product:</b>          | NetIron OS                                                                                                                                                                                                                                                                                                | <b>Reported in Release:</b> | NI 06.2.00d                                      |
| <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer                                                                                                                                                                                                                                                                       | <b>Technology:</b>          | DHCP - Dynamic Host<br>Configuration<br>Protocol |
| <b>Symptom:</b>          | DHCPv6 server RELAY replies are dropped after gateway due to nested DHCP headers are not properly handled by MLX                                                                                                                                                                                          |                             |                                                  |
| <b>Condition:</b>        | <ol style="list-style-type: none"> <li>1. There are atleast 2 intermediary dhcp relay-agents between dhcp client and server.</li> <li>2. MLX is acting as relay-agent adjacent to DHCP server</li> <li>3. client has LDRA configured and carries the corresponding options in the DHCP packet.</li> </ol> |                             |                                                  |

### Closed with code changes NI6.3.00c

This section lists software defects with Critical, High, and Medium Technical Severity closed with a code change as of March 2020 in NetIron OS 6.3.00c.

|                             |                                                                                                                                                                                                 |                          |                                        |
|-----------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|----------------------------------------|
| <b>Parent Defect ID:</b>    | NI-14753                                                                                                                                                                                        | <b>Issue ID:</b>         | NI-17685                               |
| <b>Severity:</b>            | S2 - High                                                                                                                                                                                       |                          |                                        |
| <b>Product:</b>             | NetIron OS                                                                                                                                                                                      | <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer    |
| <b>Reported in Release:</b> | NI 05.8.00f                                                                                                                                                                                     | <b>Technology:</b>       | BGP4 - IPv4 Border<br>Gateway Protocol |
| <b>Symptom:</b>             | MLX may send BGP update message with empty AS-SET Path attribute to BGP peer. The update messages would be dropped by peer due to incorrect or empty AS-SET path information.                   |                          |                                        |
| <b>Condition:</b>           | <ol style="list-style-type: none"> <li>1. When BGP neighbor is configured with "remove-private-as" command on MLX device</li> <li>2. Private AS number is exist/connected in network</li> </ol> |                          |                                        |

|                          |             |                          |                                     |
|--------------------------|-------------|--------------------------|-------------------------------------|
| <b>Parent Defect ID:</b> | NI-9350     | <b>Issue ID:</b>         | NI-21189                            |
| <b>Severity:</b>         | S3 - Medium |                          |                                     |
| <b>Product:</b>          | NetIron OS  | <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer |

|                             |                                                                                                                                                                                                                            |                    |                                      |
|-----------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------|--------------------------------------|
| <b>Reported in Release:</b> | NI 05.8.00g                                                                                                                                                                                                                | <b>Technology:</b> | OSPF - IPv4 Open Shortest Path First |
| <b>Symptom:</b>             | OSPF neighbors may show all ECMP paths after upgraded MLXe fails setting a forwarding address in AS External LSA.                                                                                                          |                    |                                      |
| <b>Condition:</b>           | It is rarely observed with the following steps:-(1) OSPFv2 is enabled on the device(2) static routes are configured with gateway, which is reachable and redistributed into OSPFv2(3) Repeated image upgrade and downgrade |                    |                                      |
| <b>Workaround:</b>          | NA                                                                                                                                                                                                                         |                    |                                      |

|                             |                                                                        |                          |                               |
|-----------------------------|------------------------------------------------------------------------|--------------------------|-------------------------------|
| <b>Parent Defect ID:</b>    | NI-21238                                                               | <b>Issue ID:</b>         | NI-21306                      |
| <b>Severity:</b>            | S3 - Medium                                                            |                          |                               |
| <b>Product:</b>             | NetIron OS                                                             | <b>Technology Group:</b> | Layer 3 Routing/Network Layer |
| <b>Reported in Release:</b> | NI 06.3.00b                                                            | <b>Technology:</b>       | Static Routing (IPv4)         |
| <b>Symptom:</b>             | Traffic may be forwarded by Line card CPU causing high CPU utilization |                          |                               |
| <b>Condition:</b>           | Port is removed from GTP profile with PBR configured                   |                          |                               |
| <b>Workaround:</b>          | Re-binding the IP/IPV6 PBR on the interface                            |                          |                               |

|                             |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |                          |                                     |
|-----------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|-------------------------------------|
| <b>Parent Defect ID:</b>    | NI-21231                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       | <b>Issue ID:</b>         | NI-21347                            |
| <b>Severity:</b>            | S2 - High                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |                          |                                     |
| <b>Product:</b>             | NetIron OS                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer |
| <b>Reported in Release:</b> | NI 06.2.00a                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    | <b>Technology:</b>       | IPv6 Addressing                     |
| <b>Symptom:</b>             | Line card may reload with the following stack trace :-<br>Possible Stack Trace (function call return address list)<br>21685920: memset(pc)<br>20c09860: generic_get_mem_from_pool(lr)<br>20fcd940: ip6_get_free_cache_entry<br>20faf9fc: ip6_process_route_lookup<br>20faa738: ipv6_fwd_unicast_packet<br>20fac984: ipv6_packet_receive<br>20f350e0: rx_pkt_processing<br>20d8b720: lp_pkt_receive<br>20a1deb4: ppcr_recieve_packet<br>207f3360: lp_pbif_packet_task<br>00040158: sys_end_task |                          |                                     |
| <b>Condition:</b>           | Processing large number of ICMPv6 echo request packets for unknown destination hosts with 'ipv6 max-host-drop-cam' configured                                                                                                                                                                                                                                                                                                                                                                  |                          |                                     |
| <b>Workaround:</b>          | NA                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |                          |                                     |

|                             |                                                                                 |                          |                                         |
|-----------------------------|---------------------------------------------------------------------------------|--------------------------|-----------------------------------------|
| <b>Parent Defect ID:</b>    | NI-21312                                                                        | <b>Issue ID:</b>         | NI-21359                                |
| <b>Severity:</b>            | S3 - Medium                                                                     |                          |                                         |
| <b>Product:</b>             | NetIron OS                                                                      | <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer     |
| <b>Reported in Release:</b> | NI 05.8.00f                                                                     | <b>Technology:</b>       | OSPF - IPv4 Open<br>Shortest Path First |
| <b>Symptom:</b>             | Router ID may not displayed correctly in 'show ip ospf' config output           |                          |                                         |
| <b>Condition:</b>           | 1. OSPF is configured on the device<br>2. router-id is configured on a loopback |                          |                                         |

|                             |                                                                                                                                 |                          |                                             |
|-----------------------------|---------------------------------------------------------------------------------------------------------------------------------|--------------------------|---------------------------------------------|
| <b>Parent Defect ID:</b>    | NI-21371                                                                                                                        | <b>Issue ID:</b>         | NI-21385                                    |
| <b>Severity:</b>            | S3 - Medium                                                                                                                     |                          |                                             |
| <b>Product:</b>             | NetIron OS                                                                                                                      | <b>Technology Group:</b> | Monitoring                                  |
| <b>Reported in Release:</b> | NI 06.3.00b                                                                                                                     | <b>Technology:</b>       | OAM - Operations,<br>Admin &<br>Maintenance |
| <b>Symptom:</b>             | Port may not go down on 2x100G CFP2 Line card module                                                                            |                          |                                             |
| <b>Condition:</b>           | When "loopback system" configuration is removed from an interface having QSFP28-SR4 optic installed with no physical connection |                          |                                             |

|                             |                                                                                                                                                                                                                                            |                          |                                                |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|------------------------------------------------|
| <b>Parent Defect ID:</b>    | NI-14775                                                                                                                                                                                                                                   | <b>Issue ID:</b>         | NI-21409                                       |
| <b>Severity:</b>            | S2 - High                                                                                                                                                                                                                                  |                          |                                                |
| <b>Product:</b>             | NetIron OS                                                                                                                                                                                                                                 | <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer            |
| <b>Reported in Release:</b> | NI 06.3.00a                                                                                                                                                                                                                                | <b>Technology:</b>       | ICMP - Internet<br>Control Message<br>Protocol |
| <b>Symptom:</b>             | Host may fail to ping directly connected virtual interface and packets may get dropped in NP as Routed Packet drops                                                                                                                        |                          |                                                |
| <b>Condition:</b>           | <ol style="list-style-type: none"> <li>1. when a port is configured as untagged port in default VLAN and associated with virtual interface</li> <li>2. Rarely observed during repeated disconnection of directly connected host</li> </ol> |                          |                                                |
| <b>Workaround:</b>          | NA                                                                                                                                                                                                                                         |                          |                                                |

|                             |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |                          |                                     |
|-----------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|-------------------------------------|
| <b>Parent Defect ID:</b>    | NI-21340                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       | <b>Issue ID:</b>         | NI-21461                            |
| <b>Severity:</b>            | S2 - High                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |                          |                                     |
| <b>Product:</b>             | NetIron OS                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer |
| <b>Reported in Release:</b> | NI 06.2.00c                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    | <b>Technology:</b>       | IPv6 Addressing                     |
| <b>Symptom:</b>             | <p>Line card may reload unexpectedly with the following stack trace :-<br/>Possible Stack Trace (function call return address list)</p> <pre> 20e112dc: debug_assert(pc) 20fcdcb0: ip6_remove_cache_from_LinkList(lr) 20fce940: ip6_delete_host_cache_entry 20d1fda8: ipv6_cam_ageout_handler 20aef974: xpp80ge_age_rc2 20aefd0c: xpp80ge_age_rc 20a05d60: ppcr_rc_aging_poll 20005a74: perform_callback 2000647c: timer_timeout 00040160: sys_end_entry 0005e4a0: suspend 0005cf78: dev_sleep 00005024: xsyscall 207f18b0: main 00040158: sys_end_task </pre> |                          |                                     |
| <b>Condition:</b>           | Processing large number of ICMPv6 echo request packets for unknown destination hosts with 'ipv6 max-host-drop-cam' configured                                                                                                                                                                                                                                                                                                                                                                                                                                  |                          |                                     |

|                             |                                                                                                                                    |                          |                                           |
|-----------------------------|------------------------------------------------------------------------------------------------------------------------------------|--------------------------|-------------------------------------------|
| <b>Parent Defect ID:</b>    | NI-21465                                                                                                                           | <b>Issue ID:</b>         | NI-21481                                  |
| <b>Severity:</b>            | S3 - Medium                                                                                                                        |                          |                                           |
| <b>Product:</b>             | NetIron OS                                                                                                                         | <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer       |
| <b>Reported in Release:</b> | NI 06.3.00b                                                                                                                        | <b>Technology:</b>       | GRE - Generic<br>Routing<br>Encapsulation |
| <b>Symptom:</b>             | High LP CPU utilization may be observed                                                                                            |                          |                                           |
| <b>Condition:</b>           | Existence of tunnel interface with tunnel mode as gre ip without any tunnels established and receiving unknown GRE packets/traffic |                          |                                           |

|                             |                                                                                                                                                                                                                                                                                     |                          |                                         |
|-----------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|-----------------------------------------|
| <b>Parent Defect ID:</b>    | NI-21477                                                                                                                                                                                                                                                                            | <b>Issue ID:</b>         | NI-21485                                |
| <b>Severity:</b>            | S2 - High                                                                                                                                                                                                                                                                           |                          |                                         |
| <b>Product:</b>             | NetIron OS                                                                                                                                                                                                                                                                          | <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer     |
| <b>Reported in Release:</b> | NI 05.8.00h                                                                                                                                                                                                                                                                         | <b>Technology:</b>       | OSPF - IPv4 Open<br>Shortest Path First |
| <b>Symptom:</b>             | The routes learnt over sham-link are treated as O2 (external routes)                                                                                                                                                                                                                |                          |                                         |
| <b>Condition:</b>           | <ol style="list-style-type: none"> <li>1. In the OSPF network, there are 2 PE devices, between which sham-link is brought UP and 2 CE devices connect to each of the two PE devices.</li> <li>2. A static route is configured on one of the PE devices and redistributed</li> </ol> |                          |                                         |

|                             |                                                                 |                          |                                         |
|-----------------------------|-----------------------------------------------------------------|--------------------------|-----------------------------------------|
| <b>Parent Defect ID:</b>    | NI-9349                                                         | <b>Issue ID:</b>         | NI-21490                                |
| <b>Severity:</b>            | S3 - Medium                                                     |                          |                                         |
| <b>Product:</b>             | NetIron OS                                                      | <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer     |
| <b>Reported in Release:</b> | NI 05.8.00g                                                     | <b>Technology:</b>       | OSPF - IPv4 Open<br>Shortest Path First |
| <b>Symptom:</b>             | Inconsistent behavior may be observed between OSPFV2 and OSPFV3 |                          |                                         |
| <b>Condition:</b>           | Configuration of 'max-metric' command                           |                          |                                         |

|                             |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |                          |                              |
|-----------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|------------------------------|
| <b>Parent Defect ID:</b>    | NI-21468                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | <b>Issue ID:</b>         | NI-21492                     |
| <b>Severity:</b>            | S3 - Medium                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |                          |                              |
| <b>Product:</b>             | NetIron OS                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 | <b>Technology Group:</b> | Management                   |
| <b>Reported in Release:</b> | NI 06.0.00f                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                | <b>Technology:</b>       | CLI - Command Line Interface |
| <b>Symptom:</b>             | <p>Management Module may reload unexpectedly with the following stack trace:-</p> <p>Possible Stack Trace (function call return address list)</p> <p>203c0e40: uprintf(pc)<br/> 203c0e40: uprintf(lr)<br/> 20025b3c: copy_runConfig_startConfig<br/> 202eff7c: call_action_func<br/> 202f0a74: parse_node<br/> 202f04f0: parse_node_recurse<br/> 202f0d48: parse_node<br/> 2036485c: parse_input<br/> 2042a90c: cli_aaa_accounting_callback<br/> 2079f3bc: aaa_accounting_start<br/> 2042a160: cli_request_command_accounting<br/> 202f0964: parse_node<br/> 2036485c: parse_input<br/> 2042ab9c: cli_aaa_authorization_callback<br/> 2079f450: aaa_authorization_start<br/> 20429780: cli_request_command_authorization<br/> 202f0954: parse_node<br/> 202eefb8: parser<br/> 20364838: parse_input<br/> 20aa4e48: ssh_event_handler<br/> 20ab80a0: ProcessChannelData<br/> 20ab56bc: ShProcessMessage<br/> 20abea5c: ProcessClientInputData<br/> 20abe1f4: ShFiniteStateMachine<br/> 209c06ec: HandleProtocolAction<br/> 209c04cc: HandleConnectionTask<br/> 20aa3a18: ssh_connection_task<br/> 20aa4164: ssh_socket_control<br/> 20aa6e00: ssh_receive_data_ready<br/> 20aa6e44: ssh_tcp_receive_data_ready_callback<br/> 20ba3ac0: itc_process_msgs_internal<br/> 20ba3f6c: itc_process_msgs<br/> 20a9f0d4: ssh_in_task<br/> 00005e18: sys_end_task</p> |                          |                              |
| <b>Condition:</b>           | killing the SSH session while 'write mem' with large size running configuration is being performed                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |                          |                              |

|                             |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |                          |                                         |
|-----------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|-----------------------------------------|
| <b>Parent Defect ID:</b>    | NI-21400                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | <b>Issue ID:</b>         | NI-21494                                |
| <b>Severity:</b>            | S2 - High                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |                          |                                         |
| <b>Product:</b>             | NetIron OS                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    | <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer     |
| <b>Reported in Release:</b> | NI 06.2.00b                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | <b>Technology:</b>       | OSPF - IPv4 Open<br>Shortest Path First |
| <b>Symptom:</b>             | <p>MLX/CER router may reload unexpectedly with the following stack trace:-</p> <p>Possible Stack Trace (function call return address list)</p> <p>20fdfea0: calculate_routes_to_a_single_external_destination(pc)</p> <p>20fdfe54: calculate_routes_to_a_single_external_destination(lr)</p> <p>20fdf80c: ospf_recalc_type5_route_chunk</p> <p>20fbb610: ospf_construct_routing_table</p> <p>20fca9b0: ospf_route_calculation_process</p> <p>20fa02f4: ospf_route_calc_task</p> <p>00040158: sys_end_task</p> |                          |                                         |
| <b>Condition:</b>           | <ol style="list-style-type: none"> <li>1. OSPF is enabled on the device</li> <li>2. OSPF has learnt external LSAs with forwarding address, which is not reachable</li> </ol>                                                                                                                                                                                                                                                                                                                                  |                          |                                         |

|                             |                                                                                                                                                                                                          |                          |                  |
|-----------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|------------------|
| <b>Parent Defect ID:</b>    | NI-21440                                                                                                                                                                                                 | <b>Issue ID:</b>         | NI-21499         |
| <b>Severity:</b>            | S3 - Medium                                                                                                                                                                                              |                          |                  |
| <b>Product:</b>             | NetIron OS                                                                                                                                                                                               | <b>Technology Group:</b> | Security         |
| <b>Reported in Release:</b> | NI 06.0.00h                                                                                                                                                                                              | <b>Technology:</b>       | TACACS & TACACS+ |
| <b>Symptom:</b>             | <p>The below authentication logs will be observed for every successful TACACS login.</p> <p>Aug 14 04:19:04:I:Tacplus service for Authentication session gave response=ACCEPT from server_ip=a.b.c.d</p> |                          |                  |
| <b>Condition:</b>           | TACACS authentication is Enabled.                                                                                                                                                                        |                          |                  |

|                             |                                                                                     |                          |                                                           |
|-----------------------------|-------------------------------------------------------------------------------------|--------------------------|-----------------------------------------------------------|
| <b>Parent Defect ID:</b>    | NI-21401                                                                            | <b>Issue ID:</b>         | NI-21503                                                  |
| <b>Severity:</b>            | S3 - Medium                                                                         |                          |                                                           |
| <b>Product:</b>             | NetIron OS                                                                          | <b>Technology Group:</b> | Monitoring                                                |
| <b>Reported in Release:</b> | NI 06.0.00d                                                                         | <b>Technology:</b>       | RAS - Reliability,<br>Availability, and<br>Serviceability |
| <b>Symptom:</b>             | Timestamp of error messages in "show sysmon log" and "show logging" does not match. |                          |                                                           |
| <b>Condition:</b>           | Errors detected by sysmon monitoring                                                |                          |                                                           |

|                             |                                                                                        |                          |                                                     |
|-----------------------------|----------------------------------------------------------------------------------------|--------------------------|-----------------------------------------------------|
| <b>Parent Defect ID:</b>    | NI-21427                                                                               | <b>Issue ID:</b>         | NI-21516                                            |
| <b>Severity:</b>            | S3 - Medium                                                                            |                          |                                                     |
| <b>Product:</b>             | NetIron OS                                                                             | <b>Technology Group:</b> | Monitoring                                          |
| <b>Reported in Release:</b> | NI 06.0.00j                                                                            | <b>Technology:</b>       | RAS - Reliability, Availability, and Serviceability |
| <b>Symptom:</b>             | In show optic command output, Tx power levels will not be displayed for QSFP28 optics. |                          |                                                     |
| <b>Condition:</b>           | QSFP28 optical connector connected to the device.                                      |                          |                                                     |

|                             |                                                                                                                               |                          |          |
|-----------------------------|-------------------------------------------------------------------------------------------------------------------------------|--------------------------|----------|
| <b>Parent Defect ID:</b>    | NI-8943                                                                                                                       | <b>Issue ID:</b>         | NI-21525 |
| <b>Severity:</b>            | S3 - Medium                                                                                                                   |                          |          |
| <b>Product:</b>             | NetIron OS                                                                                                                    | <b>Technology Group:</b> | SDN      |
| <b>Reported in Release:</b> | NI 05.8.00e                                                                                                                   | <b>Technology:</b>       | OpenFlow |
| <b>Symptom:</b>             | Traffic may not be forwarded properly on an Open Flow enabled port                                                            |                          |          |
| <b>Condition:</b>           | Observed when the same Open Flow rules are pushed through Lumina controller by Rest API repeatedly with different priorities. |                          |          |

|                             |                                                                                                             |                          |                   |
|-----------------------------|-------------------------------------------------------------------------------------------------------------|--------------------------|-------------------|
| <b>Parent Defect ID:</b>    | NI-9125                                                                                                     | <b>Issue ID:</b>         | NI-21527          |
| <b>Severity:</b>            | S3 - Medium                                                                                                 |                          |                   |
| <b>Product:</b>             | NetIron OS                                                                                                  | <b>Technology Group:</b> | Layer 2 Switching |
| <b>Reported in Release:</b> | NI 05.8.00f                                                                                                 | <b>Technology:</b>       | QnQ - IEEE 802.1Q |
| <b>Symptom:</b>             | Double tagged packets with both inner and outer tag-type as 8100 may get dropped on 20X10G Line card module |                          |                   |
| <b>Condition:</b>           | Ingress port is configured as tagged with tag-type 8100                                                     |                          |                   |

|                             |                                                                                                                                                                               |                          |                               |
|-----------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|-------------------------------|
| <b>Parent Defect ID:</b>    | NI-21135                                                                                                                                                                      | <b>Issue ID:</b>         | NI-21532                      |
| <b>Severity:</b>            | S3 - Medium                                                                                                                                                                   |                          |                               |
| <b>Product:</b>             | NetIron OS                                                                                                                                                                    | <b>Technology Group:</b> | Layer 3 Routing/Network Layer |
| <b>Reported in Release:</b> | NI 06.0.00f                                                                                                                                                                   | <b>Technology:</b>       | Static Routing (IPv6)         |
| <b>Symptom:</b>             | May observe duplicate route entry messages on LP console like below:-<br>kbp_duplicate_entry_IPv6[0] idx : 0x0033a932 tbl_id : 144 pfx :00000000:00000000:00000000:00000000/0 |                          |                               |
| <b>Condition:</b>           | 1.Addition and removal of IPv6 static default NULL0 route<br>2.IPv6 is disabled on interface                                                                                  |                          |                               |

|                             |                                                                                                                                                                                                                               |                          |                           |
|-----------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|---------------------------|
| <b>Parent Defect ID:</b>    | NI-17565                                                                                                                                                                                                                      | <b>Issue ID:</b>         | NI-21533                  |
| <b>Severity:</b>            | S3 - Medium                                                                                                                                                                                                                   |                          |                           |
| <b>Product:</b>             | NetIron OS                                                                                                                                                                                                                    | <b>Technology Group:</b> | Traffic Management        |
| <b>Reported in Release:</b> | NI 06.0.00g                                                                                                                                                                                                                   | <b>Technology:</b>       | Rate Limiting and Shaping |
| <b>Symptom:</b>             | Traffic may be dropped with the packet size larger than 1100 bytes                                                                                                                                                            |                          |                           |
| <b>Condition:</b>           | <ol style="list-style-type: none"> <li>1. Port speed configured as 100M full duplex</li> <li>2. Rate-limit configured with cbs greater than 54000(256000/125000)bytes</li> <li>3. In the presence of burst traffic</li> </ol> |                          |                           |

|                             |                                                                          |                          |                                          |
|-----------------------------|--------------------------------------------------------------------------|--------------------------|------------------------------------------|
| <b>Parent Defect ID:</b>    | NI-17589                                                                 | <b>Issue ID:</b>         | NI-21535                                 |
| <b>Severity:</b>            | S3 - Medium                                                              |                          |                                          |
| <b>Product:</b>             | NetIron OS                                                               | <b>Technology Group:</b> | MPLS                                     |
| <b>Reported in Release:</b> | NI 06.2.00b                                                              | <b>Technology:</b>       | MPLS VPLS - Virtual Private LAN Services |
| <b>Symptom:</b>             | MCT Local VPLS switchover may take up to 15sec                           |                          |                                          |
| <b>Condition:</b>           | One of the MCT peer goes Down with 3.5k VPLS instances configured on MCT |                          |                                          |

|                             |                                                                  |                          |                              |
|-----------------------------|------------------------------------------------------------------|--------------------------|------------------------------|
| <b>Parent Defect ID:</b>    | NI-17613                                                         | <b>Issue ID:</b>         | NI-21536                     |
| <b>Severity:</b>            | S3 - Medium                                                      |                          |                              |
| <b>Product:</b>             | NetIron OS                                                       | <b>Technology Group:</b> | Management                   |
| <b>Reported in Release:</b> | NI 05.4.00ea                                                     | <b>Technology:</b>       | CLI - Command Line Interface |
| <b>Symptom:</b>             | LP module uptime may show incorrect value                        |                          |                              |
| <b>Condition:</b>           | Observed after LP reload with MP running for more than 1500 days |                          |                              |

|                             |                                                                                                                                      |                          |                              |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------|--------------------------|------------------------------|
| <b>Parent Defect ID:</b>    | NI-21210                                                                                                                             | <b>Issue ID:</b>         | NI-21538                     |
| <b>Severity:</b>            | S3 - Medium                                                                                                                          |                          |                              |
| <b>Product:</b>             | NetIron OS                                                                                                                           | <b>Technology Group:</b> | Management                   |
| <b>Reported in Release:</b> | NI 06.3.00b                                                                                                                          | <b>Technology:</b>       | CLI - Command Line Interface |
| <b>Symptom:</b>             | Incorrect media and optical information observed                                                                                     |                          |                              |
| <b>Condition:</b>           | <ol style="list-style-type: none"> <li>1.On 100G module with QSFP28 optic</li> <li>2.Port configured with loopback system</li> </ol> |                          |                              |

|                             |                                                                                                                                                                                                                                        |                          |                           |
|-----------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|---------------------------|
| <b>Parent Defect ID:</b>    | NI-21353                                                                                                                                                                                                                               | <b>Issue ID:</b>         | NI-21539                  |
| <b>Severity:</b>            | S2 - High                                                                                                                                                                                                                              |                          |                           |
| <b>Product:</b>             | NetIron OS                                                                                                                                                                                                                             | <b>Technology Group:</b> | Traffic Management        |
| <b>Reported in Release:</b> | NI 06.2.00c                                                                                                                                                                                                                            | <b>Technology:</b>       | Rate Limiting and Shaping |
| <b>Symptom:</b>             | Traffic may not be rate-limited as configured                                                                                                                                                                                          |                          |                           |
| <b>Condition:</b>           | When ACL based rate-limit configuration with different queue priority is modified multiple times<br>ex:<br>rate-limit output access-group xxx priority q2 policy-map xyzMbps<br>rate-limit output access-group xxx priority q0 xyz abc |                          |                           |

|                             |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |                          |                                  |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|----------------------------------|
| <b>Parent Defect ID:</b>    | NI-21164                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               | <b>Issue ID:</b>         | NI-21544                         |
| <b>Severity:</b>            | S2 - High                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |                          |                                  |
| <b>Product:</b>             | NetIron OS                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             | <b>Technology Group:</b> | Management                       |
| <b>Reported in Release:</b> | NI 05.6.00j                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | <b>Technology:</b>       | FDP - Foundry Discovery Protocol |
| <b>Symptom:</b>             | Management Module may unexpectedly reload with the following stack trace:-<br>Possible Stack Trace (function call return address list)<br>0002b1d0: free_memory_pool(pc)<br>0002b1c8: free_memory_pool(lr)<br>0002b800: free_memory<br>00027e3c: dev_free_memory<br>00005024: xsyscall<br>202ad558: os_free<br>206a5528: fdp_reallocate_cache_entry_data<br>206a56c8: fdp_reallocate_cache_entry<br>206a5778: fdp_release_one_fdp_cache_entry<br>206a6058: fdp_process_one_incoming_message<br>206a6284: fdp_process_fdp_cdp_pdu<br>20a1fa90: itc_process_msgs_internal<br>20a1fdd0: itc_process_msgs<br>206ae930: snms_task<br>00005e18: sys_end_task |                          |                                  |
| <b>Condition:</b>           | It is rarely observed when copying LP FPGA image with FDP/CDP enabled on a cluster configured MLX device                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |                          |                                  |

|                             |                                                                                                                                                                                                                                                                                                                        |                          |                                        |
|-----------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|----------------------------------------|
| <b>Parent Defect ID:</b>    | NI-21219                                                                                                                                                                                                                                                                                                               | <b>Issue ID:</b>         | NI-21546                               |
| <b>Severity:</b>            | S3 - Medium                                                                                                                                                                                                                                                                                                            |                          |                                        |
| <b>Product:</b>             | NetIron OS                                                                                                                                                                                                                                                                                                             | <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer    |
| <b>Reported in Release:</b> | NI 06.0.00g                                                                                                                                                                                                                                                                                                            | <b>Technology:</b>       | BGP4 - IPv4 Border<br>Gateway Protocol |
| <b>Symptom:</b>             | The BGP default route originated and advertised to the peer, will not have the AS_PATH prepended as per the route-map applied                                                                                                                                                                                          |                          |                                        |
| <b>Condition:</b>           | <ol style="list-style-type: none"> <li>1. BGP is enabled on the device</li> <li>2. There is a BGP peering exists with the neighbor</li> <li>3. A route-map "xxxx" is defined to prepend the AS_PATH to the default route</li> <li>3. "default-originate route-map xxxx" command configured for the neighbor</li> </ol> |                          |                                        |

|                             |                                                                                                                                                           |                          |                                             |
|-----------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|---------------------------------------------|
| <b>Parent Defect ID:</b>    | NI-21223                                                                                                                                                  | <b>Issue ID:</b>         | NI-21547                                    |
| <b>Severity:</b>            | S3 - Medium                                                                                                                                               |                          |                                             |
| <b>Product:</b>             | NetIron OS                                                                                                                                                | <b>Technology Group:</b> | Monitoring                                  |
| <b>Reported in Release:</b> | NI 06.3.00b                                                                                                                                               | <b>Technology:</b>       | OAM - Operations,<br>Admin &<br>Maintenance |
| <b>Symptom:</b>             | 10G port is initialized as 1G port speed                                                                                                                  |                          |                                             |
| <b>Condition:</b>           | <ol style="list-style-type: none"> <li>1. Any port in 20x10G module with no optic installed</li> <li>2. Loopback system configured on the port</li> </ol> |                          |                                             |
| <b>Workaround:</b>          | Configure the port speed manually                                                                                                                         |                          |                                             |

|                             |                                                                                                                                                                   |                          |                                     |
|-----------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|-------------------------------------|
| <b>Parent Defect ID:</b>    | NI-21317                                                                                                                                                          | <b>Issue ID:</b>         | NI-21548                            |
| <b>Severity:</b>            | S3 - Medium                                                                                                                                                       |                          |                                     |
| <b>Product:</b>             | NetIron OS                                                                                                                                                        | <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer |
| <b>Reported in Release:</b> | NI 06.0.00f                                                                                                                                                       | <b>Technology:</b>       | Static Routing (IPv4)               |
| <b>Symptom:</b>             | <p>May observe duplicate route entry messages on LP console like below:-</p> <pre> kbp_duplicate_entry_IP[0] idx : 0x0019ddbc tbl_id : 128 pfx : 0.0.0.0/0 </pre> |                          |                                     |
| <b>Condition:</b>           | Frequent route update and live traffic on device with IPv4 static default NULL0 route configured                                                                  |                          |                                     |

|                             |                                         |                          |                                             |
|-----------------------------|-----------------------------------------|--------------------------|---------------------------------------------|
| <b>Parent Defect ID:</b>    | NI-21313                                | <b>Issue ID:</b>         | NI-21549                                    |
| <b>Severity:</b>            | S2 - High                               |                          |                                             |
| <b>Product:</b>             | NetIron OS                              | <b>Technology Group:</b> | Monitoring                                  |
| <b>Reported in Release:</b> | NI 06.0.00d                             | <b>Technology:</b>       | OAM - Operations,<br>Admin &<br>Maintenance |
| <b>Symptom:</b>             | 100G Links may observe sub second flaps |                          |                                             |
| <b>Condition:</b>           | Presence of Rev 2 CFP2 ER4 optic        |                          |                                             |

|                             |                                                                                                                                                                          |                          |                     |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|---------------------|
| <b>Parent Defect ID:</b>    | NI-21357                                                                                                                                                                 | <b>Issue ID:</b>         | NI-21550            |
| <b>Severity:</b>            | S2 - High                                                                                                                                                                |                          |                     |
| <b>Product:</b>             | NetIron OS                                                                                                                                                               | <b>Technology Group:</b> | Security            |
| <b>Reported in Release:</b> | NI 06.0.00j                                                                                                                                                              | <b>Technology:</b>       | IPsec - IP Security |
| <b>Symptom:</b>             | High LP CPU may be observed with IPSEC data traffic                                                                                                                      |                          |                     |
| <b>Condition:</b>           | <ol style="list-style-type: none"> <li>Route to tunnel destination changes</li> <li>IPSEC data traffic received with MTU size greater than default value 1431</li> </ol> |                          |                     |

|                             |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |                          |                                             |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|---------------------------------------------|
| <b>Parent Defect ID:</b>    | NI-21370                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | <b>Issue ID:</b>         | NI-21551                                    |
| <b>Severity:</b>            | S3 - Medium                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |                          |                                             |
| <b>Product:</b>             | NetIron OS                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         | <b>Technology Group:</b> | Monitoring                                  |
| <b>Reported in Release:</b> | NI 05.8.00ec                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       | <b>Technology:</b>       | OAM - Operations,<br>Admin &<br>Maintenance |
| <b>Symptom:</b>             | <p>Management Module may unexpectedly reload with the following stack trace:</p> <p>Possible Stack Trace (function call return address list)</p> <p>0002e2cc: assert_double_free_small_memory(pc)<br/> 0002e2c4: assert_double_free_small_memory(lr)<br/> 0002e4cc: free_memory_pool<br/> 0002eafc: free_memory<br/> 0002b0e0: dev_free_global<br/> 00005024: xsyscall<br/> 20a87fc0: FreeEvent<br/> 20ae7304: scp_event_callback<br/> 20b148d0: itc_process_msgs_internal<br/> 20b14a24: itc_process_msgs<br/> 20adf8a0: scp_task<br/> 00005e18: sys_end_task</p> |                          |                                             |
| <b>Condition:</b>           | It is observed rarely on a MLX device, during removal of delay-link-event configuration.                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |                          |                                             |

|                             |                                                                                                      |                          |                                             |
|-----------------------------|------------------------------------------------------------------------------------------------------|--------------------------|---------------------------------------------|
| <b>Parent Defect ID:</b>    | NI-21436                                                                                             | <b>Issue ID:</b>         | NI-21554                                    |
| <b>Severity:</b>            | S3 - Medium                                                                                          |                          |                                             |
| <b>Product:</b>             | NetIron OS                                                                                           | <b>Technology Group:</b> | Monitoring                                  |
| <b>Reported in Release:</b> | NI 06.3.00ba                                                                                         | <b>Technology:</b>       | OAM - Operations,<br>Admin &<br>Maintenance |
| <b>Symptom:</b>             | 10G port may come as 1G                                                                              |                          |                                             |
| <b>Condition:</b>           | 1. On 20x10G module with no optic installed<br>2. Loopback system configured on a disabled interface |                          |                                             |
| <b>Workaround:</b>          | have the interface enabled before applying loopback system configuration                             |                          |                                             |

|                             |                                                                                             |                          |                                     |
|-----------------------------|---------------------------------------------------------------------------------------------|--------------------------|-------------------------------------|
| <b>Parent Defect ID:</b>    | NI-21581                                                                                    | <b>Issue ID:</b>         | NI-21582                            |
| <b>Severity:</b>            | S2 - High                                                                                   |                          |                                     |
| <b>Product:</b>             | NetIron OS                                                                                  | <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer |
| <b>Reported in Release:</b> | NI 06.2.00d                                                                                 | <b>Technology:</b>       | IPv6 Addressing                     |
| <b>Symptom:</b>             | Intermittent traffic drop may be observed sometimes                                         |                          |                                     |
| <b>Condition:</b>           | Removing and reconfiguring IPV6 address on a VE interface that receives continuous traffic. |                          |                                     |

|                             |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |                          |                                        |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|----------------------------------------|
| <b>Parent Defect ID:</b>    | NI-21352                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | <b>Issue ID:</b>         | NI-21586                               |
| <b>Severity:</b>            | S3 - Medium                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |                          |                                        |
| <b>Product:</b>             | NetIron OS                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer    |
| <b>Reported in Release:</b> | NI 06.0.00f                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  | <b>Technology:</b>       | BGP4 - IPv4 Border<br>Gateway Protocol |
| <b>Symptom:</b>             | Management Module may unexpectedly reload with the following stack trace:-<br>20f6c5a0: bgp_clear_out_policy_soft_outbound_callback(pc)<br>21044e2c: bgp_tree_partial_traverse(lr)<br>21044e2c: bgp_tree_partial_traverse<br>20f6cad0: bgp_clear_out_policy_soft_outbound<br>20f6c400: bgp_clear_one_neighbor_number_soft_outbound<br>20fd34c0: bgp_timer<br>20fd2aa0: bgp_timeout_func<br>20ba3ac0: itc_process_msgs_internal<br>20ba3f6c: itc_process_msgs<br>210275d8: bgp_task<br>00005e18: sys_end_task |                          |                                        |
| <b>Condition:</b>           | It is observed rarely while adding new BGP peers to the router and executing the BGP soft clear command like below:-<br><br>clear ip bgp neighbor x.x.x.x soft-outbound                                                                                                                                                                                                                                                                                                                                      |                          |                                        |

|                             |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |                          |                                           |
|-----------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|-------------------------------------------|
| <b>Parent Defect ID:</b>    | NI-19279                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | <b>Issue ID:</b>         | NI-21587                                  |
| <b>Severity:</b>            | S3 - Medium                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |                          |                                           |
| <b>Product:</b>             | NetIron OS                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer       |
| <b>Reported in Release:</b> | NI 05.7.00e                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         | <b>Technology:</b>       | OSPFv3 - IPv6 Open<br>Shortest Path First |
| <b>Symptom:</b>             | Management Module may unexpectedly reload with the following stack trace:-<br>21112da8: ospf6_listnode_delete_count(pc)<br>21112f40: ospf6_lsdb_remove(lr)<br>21112f40: ospf6_lsdb_remove<br>21113644: ospf6_lsdb_install<br>2111f0f4: ospf6_dbex_receive_lsa<br>2111f80c: ospf6_ls_upd<br>2112069c: ospf6_message_process<br>21104644: ospf6_router_receive_packet_callback<br>20a55c34: itc_process_msgs_internal<br>20a55f6c: itc_process_msgs<br>21103e0c: ospf6_task<br>00005e18: sys_end_task |                          |                                           |
| <b>Condition:</b>           | OSPFv3 Cost changes on a scaled network                                                                                                                                                                                                                                                                                                                                                                                                                                                             |                          |                                           |

|                             |                                                                                                                                 |                          |                                     |
|-----------------------------|---------------------------------------------------------------------------------------------------------------------------------|--------------------------|-------------------------------------|
| <b>Parent Defect ID:</b>    | NI-17371                                                                                                                        | <b>Issue ID:</b>         | NI-21600                            |
| <b>Severity:</b>            | S3 - Medium                                                                                                                     |                          |                                     |
| <b>Product:</b>             | NetIron OS                                                                                                                      | <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer |
| <b>Reported in Release:</b> | NI 06.0.00f                                                                                                                     | <b>Technology:</b>       | IPv6 Addressing                     |
| <b>Symptom:</b>             | IPv6 neighborship may not be established                                                                                        |                          |                                     |
| <b>Condition:</b>           | When IPv6 neighbor solicitation request is received from the peer with source address same as configured interface IPV6 address |                          |                                     |

|                             |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |                          |                                         |
|-----------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|-----------------------------------------|
| <b>Parent Defect ID:</b>    | NI-9624                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                | <b>Issue ID:</b>         | NI-21601                                |
| <b>Severity:</b>            | S2 - High                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |                          |                                         |
| <b>Product:</b>             | NetIron OS                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             | <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer     |
| <b>Reported in Release:</b> | NI 06.0.00e                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | <b>Technology:</b>       | OSPF - IPv4 Open<br>Shortest Path First |
| <b>Symptom:</b>             | Management Module may unexpectedly reload with the following stack trace:-<br>210ea558: ospf_free_route_entry(pc)<br>210e97c4: ospf_delete_dspt_asbr_entry_callback(lr)<br>210e97c4: ospf_delete_dspt_asbr_entry_callback<br>2033fff4: ip4_delete_entire_trie<br>210e9830: ospf_clear_dspt_asbr_routing_table<br>210e52d8: ospf_dspt_clear_whole_table<br>22077304: ospf_lsp_shortcut_destroy<br>2109ccc8: ospf_disable_operation_of_ospf_protocol<br>210fbaf8: restart_ospf<br>210fbb58: clear_ospf_all<br>210c36fc: cu_clear_ospf_all_callback<br>20ba069c: itc_process_msgs_internal<br>20ba0b48: itc_process_msgs<br>210ba678: ospf_task<br>00005e18: sys_end_task |                          |                                         |
| <b>Condition:</b>           | It is observed rarely on a MLX/XMR device,<br>1. With high scale of routes in a MCT, VRF and OSPF configured device<br>2. On restarting the OSPF process<br><br>ex: clear ip ospf vrf vrf-name all                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |                          |                                         |

|                             |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |                          |                                        |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|----------------------------------------|
| <b>Parent Defect ID:</b>    | NI-21614                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | <b>Issue ID:</b>         | NI-21615                               |
| <b>Severity:</b>            | S3 - Medium                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |                          |                                        |
| <b>Product:</b>             | NetIron OS                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer    |
| <b>Reported in Release:</b> | NI 06.0.00hb                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 | <b>Technology:</b>       | BGP4 - IPv4 Border<br>Gateway Protocol |
| <b>Symptom:</b>             | Line card module may reload unexpectedly with the following stack trace:<br>20ed7218: ip_check_if_all_children_keys_are_in_cam(pc)<br>20f30418: ip_add_entry_in_routing_table_trie(lr)<br>20f2fe68: ip_add_entry_in_routing_table_trie<br>20f32f90: ip_search_and_traverse_trie<br>20f335d4: ip4_search_and_traverse_trie<br>20e0a708: ip_route_checksum<br>20ed0900: tree_veri_func<br>20ed1838: tree_veri_func_unicast<br>20bd61b4: process_dy_veri_packet<br>20c1ce8c: ipc_multi_module_handler<br>20c1f400: ipc_process_messages<br>20c1fbdc: ipc_receive_packet<br>20036ee8: ge_process_ipc_data_msg<br>207f528c: lp_ipc_task<br>00040158: sys_end_task |                          |                                        |
| <b>Condition:</b>           | It is observed rarely on a MLX device during route sync-up in the presence of VRF routes with BGP                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |                          |                                        |

|                             |                                                                                             |                          |                                        |
|-----------------------------|---------------------------------------------------------------------------------------------|--------------------------|----------------------------------------|
| <b>Parent Defect ID:</b>    | NI-21619                                                                                    | <b>Issue ID:</b>         | NI-21620                               |
| <b>Severity:</b>            | S3 - Medium                                                                                 |                          |                                        |
| <b>Product:</b>             | NetIron OS                                                                                  | <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer    |
| <b>Reported in Release:</b> | NI 06.3.00                                                                                  | <b>Technology:</b>       | BGP4 - IPv4 Border<br>Gateway Protocol |
| <b>Symptom:</b>             | unreachable BGP route count may not be correct in show CLI output.                          |                          |                                        |
| <b>Condition:</b>           | In the presence of BGP filtered route (denying via prefix-list) with unresolvable Next Hop. |                          |                                        |

|                             |                                                                                                                                                                |                          |          |
|-----------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|----------|
| <b>Parent Defect ID:</b>    | NI-8935                                                                                                                                                        | <b>Issue ID:</b>         | NI-21671 |
| <b>Severity:</b>            | S2 - High                                                                                                                                                      |                          |          |
| <b>Product:</b>             | NetIron OS                                                                                                                                                     | <b>Technology Group:</b> | SDN      |
| <b>Reported in Release:</b> | NI 05.8.00e                                                                                                                                                    | <b>Technology:</b>       | OpenFlow |
| <b>Symptom:</b>             | Sometimes Open flow rules may not get installed                                                                                                                |                          |          |
| <b>Condition:</b>           | On receiving the update action within a second, while processing the same Open flow rule with same priority and priority should be less than the existing flow |                          |          |
| <b>Workaround:</b>          | NA                                                                                                                                                             |                          |          |

## Closed with code changes NI6.3.00a1

This section lists software defects with Critical, High, and Medium Technical Severity closed with a code change as of August 2019 in NetIron OS 6.3.00a1.

|                             |                                                                                                                             |                          |                     |
|-----------------------------|-----------------------------------------------------------------------------------------------------------------------------|--------------------------|---------------------|
| <b>Parent Defect ID:</b>    | NI-21342                                                                                                                    | <b>Issue ID:</b>         | NI-21342            |
| <b>Severity:</b>            | S2 - High                                                                                                                   |                          |                     |
| <b>Product:</b>             | NetIron OS                                                                                                                  | <b>Technology Group:</b> | Security            |
| <b>Reported in Release:</b> | NI 06.3.00a1                                                                                                                | <b>Technology:</b>       | IPsec - IP Security |
| <b>Symptom:</b>             | The certificate signing request (CSR) generated by MLXe has digest calculated using SHA1 instead of using SHA256 or SHA384. |                          |                     |
| <b>Condition:</b>           | When user issue pki enroll command to enroll for X509v3 certificate.                                                        |                          |                     |

|                             |                                                                                                                                                                 |                          |                     |
|-----------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|---------------------|
| <b>Parent Defect ID:</b>    | NI-21405                                                                                                                                                        | <b>Issue ID:</b>         | NI-21405            |
| <b>Severity:</b>            | S3 - Medium                                                                                                                                                     |                          |                     |
| <b>Product:</b>             | NetIron OS                                                                                                                                                      | <b>Technology Group:</b> | Security            |
| <b>Reported in Release:</b> | NI 06.3.00a1                                                                                                                                                    | <b>Technology:</b>       | IPsec - IP Security |
| <b>Symptom:</b>             | Sometime when MLXe is configured as a Responder only for IKEv2, IPsec tunnel will not be established when X509v3 certificates are used for peer authentication. |                          |                     |
| <b>Condition:</b>           | MLXe configured as a Responder Only for IKEv2 and X509v3 certificates are used for peer authentication.                                                         |                          |                     |
| <b>Workaround:</b>          | Stop and restart IPsec tunnel establishment from the remote peer who is initiator or make MLXe as a initiator.                                                  |                          |                     |

|                             |                                                                                                                                                                                                                                                                                                                            |                          |                     |
|-----------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|---------------------|
| <b>Parent Defect ID:</b>    | NI-21424                                                                                                                                                                                                                                                                                                                   | <b>Issue ID:</b>         | NI-21424            |
| <b>Severity:</b>            | S3 - Medium                                                                                                                                                                                                                                                                                                                |                          |                     |
| <b>Product:</b>             | NetIron OS                                                                                                                                                                                                                                                                                                                 | <b>Technology Group:</b> | Security            |
| <b>Reported in Release:</b> | NI 06.3.00a1                                                                                                                                                                                                                                                                                                               | <b>Technology:</b>       | IPsec - IP Security |
| <b>Symptom:</b>             | Sometime IPsec Tunnel can be established with a remote peer that has sent invalid X509v3 certificate in case where the remote client has in last 10 minutes sent a valid X509v3 certificate.                                                                                                                               |                          |                     |
| <b>Condition:</b>           | Establishment of IPsec tunnel by remote peer with a valid X509v3 certificate followed by teardown of the IPsec tunnel and then re-establishment of same IPsec tunnel by same remote peer with an invalid X509v3 certificate within 10 minutes of previous successful IPsec tunnel setup with the valid X509v3 certificate. |                          |                     |
| <b>Workaround:</b>          | Issue "clear ikev2 sa" before IPsec tunnel is re-established.                                                                                                                                                                                                                                                              |                          |                     |

|                             |                                                                                                                                                                                                                                            |                          |                                      |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|--------------------------------------|
| <b>Parent Defect ID:</b>    | NI-21426                                                                                                                                                                                                                                   | <b>Issue ID:</b>         | NI-21426                             |
| <b>Severity:</b>            | S2 - High                                                                                                                                                                                                                                  |                          |                                      |
| <b>Product:</b>             | NetIron OS                                                                                                                                                                                                                                 | <b>Technology Group:</b> | Layer 3<br>Routing/Network<br>Layer  |
| <b>Reported in Release:</b> | NI 06.3.00a1                                                                                                                                                                                                                               | <b>Technology:</b>       | ARP - Address<br>Resolution Protocol |
| <b>Symptom:</b>             | IPv6 Traffic is dropped when a lag which is member of a VE interface goes down due to IPv6 Neighbor Discovery Table entries are not updated to point to an alternative outgoing physical port which is up and member of same VE interface. |                          |                                      |
| <b>Condition:</b>           | Lag which is member of VE and currently selected outgoing physical port of a IPv6 neighbor discovery entries must go down and another physical port of VE which is up is selected as the new outgoing physical port for the ND6 entries.   |                          |                                      |
| <b>Workaround:</b>          | Issue " clear ipv6 neighbor ve <ve interface number>"                                                                                                                                                                                      |                          |                                      |