



# Extreme 9920 Software Release Notes

21.1.2.5

9037267-05 Rev AB  
March 2024



Copyright © 2024 Extreme Networks, Inc. All rights reserved.

## Legal Notice

Extreme Networks, Inc. reserves the right to make changes in specifications and other information contained in this document and its website without prior notice. The reader should in all cases consult representatives of Extreme Networks to determine whether any such changes have been made.

The hardware, firmware, software or any specifications described or referred to in this document are subject to change without notice.

## Trademarks

Extreme Networks and the Extreme Networks logo are trademarks or registered trademarks of Extreme Networks, Inc. in the United States and/or other countries.


All other names (including any product names) mentioned in this document are the property of their respective owners and may be trademarks or registered trademarks of their respective companies/owners.

For additional information on Extreme Networks trademarks, see: <https://www.extremenetworks.com/about-extreme-networks/company/legal/trademarks>

## Open Source Declarations

Some software files have been licensed under certain open source or third-party licenses.

End-user license agreements and open source declarations can be found at: <https://www.extremenetworks.com/support/policies/open-source-declaration/>



# Table of Contents

---

- Release Notes.....4**
  - New in this Release.....4
  - Defects Closed With Code Changes.....4
  - Defects Closed Without Code Changes.....5
  - Open Defects.....5
  - Help and Support.....7
    - Subscribe to Product Announcements.....8



# Release Notes

---

[New in this Release](#) on page 4  
[Defects Closed With Code Changes](#) on page 4  
[Defects Closed Without Code Changes](#) on page 5  
[Open Defects](#) on page 5  
[Help and Support](#) on page 7

The NPB software runs the NPB operating system and provides network packet broker functions.

## New in this Release

---

Version 21.1.2.5 of the Extreme 9920 software with the NPB application offers the following enhancements.

**Table 1: Features and Enhancements**

Enhancement	Description
Line Card Detection Optimization	Line card removal or insertion detection time has reduced from 30 secs to 3-4 secs. When a Line card is removed, it moves to the "Faulty" state and takes around 3-4 seconds to go to the "Empty" state. Insertion of a Line card also takes 3 seconds to change the state from "Present" to "Initializing" state.  <b>Note:</b> As a best practice wait until LC goes to the "Empty" state before insertion.

## Defects Closed With Code Changes

---

The following defect was closed with code changes in this release of the software.

Parent Defect ID:	NPB-5988	Issue ID:	NPB-5988
Severity:	S2 - Major		
Product:	NPB	Reported in Release:	NPB 21.1.2.4

<b>Parent Defect ID:</b>	NPB-5988	<b>Issue ID:</b>	NPB-5988
<b>Symptom:</b>	SNMP GET request does not return response and the request times out.		
<b>Condition:</b>	This issue was observed for an SNMP GET request with multiple Object Identifiers (OIDs) to 9920.		

<b>Parent Defect ID:</b>	NPB-5992	<b>Issue ID:</b>	NPB-5992
<b>Severity:</b>	S3 - Moderate		
<b>Product:</b>	NPB	<b>Reported in Release:</b>	NPB 21.1.2.4
<b>Symptom:</b>	Line card moves to the faulty state if one of the QSFP 3/11 heats up, and BMC turns the power off to that LC. The line card needs to be manually powered on using the <code>system slotoff/sloton</code> commands. The hotswap of LC also works.		
<b>Condition:</b>	This issue was observed when the QSFP temperature in one of the slots went beyond the critical temperature.		

<b>Parent Defect ID:</b>	NPB-5993	<b>Issue ID:</b>	NPB-5993
<b>Severity:</b>	S3 - Moderate		
<b>Product:</b>	NPB	<b>Reported in Release:</b>	NPB 21.1.2.4
<b>Symptom:</b>	Host name of 9920 does not appear in the XCO GUI		
<b>Condition:</b>	After reboot of 9920, configured hostname does not appear in the XCO GUI.		

## Defects Closed Without Code Changes

No defects were closed without code changes in this release of the software.

## Open Defects

The following defects are open in this release of the software.

<b>Parent Defect ID:</b>	NPB-5182	<b>Issue ID:</b>	NPB-5182
<b>Severity:</b>	S2 - Major		
<b>Product:</b>	NPB	<b>Reported in Release:</b>	NPB 21.1.1.0
<b>Symptom:</b>	Entity MIB item <code>entPhysicalVendorType</code> does not return any Vendor type OIDs, instead it returns {0 0} when SNMP walk is performed.		
<b>Condition:</b>	This issue is seen during SNMP walk of <code>entPhysicalVendorType</code> in the entity MIB.		

Parent Defect ID:	NPB-5182	Issue ID:	NPB-5182
Workaround:	No workaround		
Recovery:	No recovery available		

Parent Defect ID:	NPB-5188	Issue ID:	NPB-5188
Severity:	S3 - Moderate		
Product:	NPB	Reported in Release:	NPB 21.1.1.0
Symptom:	The <code>Link Fault Status</code> field in the <b>Show interface ethernet</b> command output may show incorrect fault status.		
Condition:	<b>no shutdown</b> on the ethernet interface.		
Workaround:	No workaround		
Recovery:	No functional impact		

Parent Defect ID:	NPB-5567	Issue ID:	NPB-5567
Severity:	S2 - Major		
Product:	NPB	Reported in Release:	NPB 21.1.2.0
Symptom:	Transport tunnel is created while configuring invalid transport protocol for system logging host.		
Condition:	Configure invalid transport protocol for the <b>system logging host</b> .		
Workaround:	Avoid invalid configuration of transport protocol for <b>system logging host</b> .		
Recovery:	Configure UDP/TCP as transport and delete the transport-tunnel created using the invalid command.		

Parent Defect ID:	NPB-5724	Issue ID:	NPB-5724
Severity:	S3 - Moderate		
Product:	NPB	Reported in Release:	NPB 21.1.2.0
Symptom:	LACP port-channel remains down after replaying the configuration with LACP rate as <code>fast</code> in the member interfaces.		
Condition:	The issue is seen when the LACP configurations are replayed with the node in default-configs. Only when <code>lacp rate fast</code> is configured on member ports.		

<b>Parent Defect ID:</b>	<b>NPB-5724</b>	<b>Issue ID:</b>	<b>NPB-5724</b>
<b>Workaround:</b>	Reboot the system with config or change <code>lACP rate normal</code> and after the port-channel comes up again change it to <code>lACP rate fast</code> on member ports.		
<b>Recovery:</b>	Disable and enable LACP in the global config mode. # no protocol lacp # protocol lacp		

<b>Parent Defect ID:</b>	<b>NPB-5953</b>	<b>Issue ID:</b>	<b>NPB-5953</b>
<b>Severity:</b>	S4 - Minor		
<b>Product:</b>	NPB	<b>Reported in Release:</b>	NPB 21.1.2.4
<b>Symptom:</b>	ACL, route-map, or listener-policy configuration fails when the sequence number is greater than 4095, but the error message displays the supported range as 1-65535.		
<b>Condition:</b>	The NPB stratum supports only 24 bits. The valid ACL, route-map, or listenerPolicy sequence number range is 1-4095.		
<b>Workaround:</b>	Ignore the CLI message for the NPB.		
<b>Recovery:</b>	Configure the sequence number between 1-4095 for the NPB.		

## Help and Support

If you require assistance, contact Extreme Networks using one of the following methods:

### Extreme Portal

Search the GTAC (Global Technical Assistance Center) knowledge base; manage support cases and service contracts; download software; and obtain product licensing, training, and certifications.

### The Hub

A forum for Extreme Networks customers to connect with one another, answer questions, and share ideas and feedback. This community is monitored by Extreme Networks employees, but is not intended to replace specific guidance from GTAC.

### Call GTAC

For immediate support: (800) 998 2408 (toll-free in U.S. and Canada) or 1 (408) 579 2800. For the support phone number in your country, visit [www.extremenetworks.com/support/contact](http://www.extremenetworks.com/support/contact).

Before contacting Extreme Networks for technical support, have the following information ready:

- Your Extreme Networks service contract number, or serial numbers for all involved Extreme Networks products
- A description of the failure

- A description of any actions already taken to resolve the problem
- A description of your network environment (such as layout, cable type, other relevant environmental information)
- Network load at the time of trouble (if known)
- The device history (for example, if you have returned the device before, or if this is a recurring problem)
- Any related RMA (Return Material Authorization) numbers

## Subscribe to Product Announcements

You can subscribe to email notifications for product and software release announcements, Field Notices, and Vulnerability Notices.

1. Go to [The Hub](#).
2. In the list of categories, expand the **Product Announcements** list.
3. Select a product for which you would like to receive notifications.
4. Select **Subscribe**.
5. To select additional products, return to the **Product Announcements** list and repeat steps 3 and 4.

You can modify your product selections or unsubscribe at any time.