

February 2021



# SLX-OS 18r.1.00g for SLX 9850 and SLX 9540

## Release Notes

Copyright © 2021 Extreme Networks, Inc. All Rights Reserved.

#### Legal Notice

Extreme Networks, Inc. reserves the right to make changes in specifications and other information contained in this document and its website without prior notice. The reader should in all cases consult representatives of Extreme Networks to determine whether any such changes have been made.

The hardware, firmware, software or any specifications described or referred to in this document are subject to change without notice.

#### Trademarks

Extreme Networks and the Extreme Networks logo are trademarks or registered trademarks of Extreme Networks, Inc. in the United States and/or other countries.

All other names (including any product names) mentioned in this document are the property of their respective owners and may be trademarks or registered trademarks of their respective companies/owners.

For additional information on Extreme Networks trademarks, please see:

[www.extremenetworks.com/company/legal/trademarks](http://www.extremenetworks.com/company/legal/trademarks)

#### Open Source Declarations

Some software files have been licensed under certain open source or third-party licenses. End-user license agreements and open source declarations can be found at:

[www.extremenetworks.com/support/policies/software-licensing](http://www.extremenetworks.com/support/policies/software-licensing)

# Contents

Release Notes.....	1
Contents.....	3
Document history.....	4
Preface .....	5
Contacting Extreme Technical Support.....	5
Extreme resources .....	5
Document feedback.....	6
Overview .....	7
New SKUs .....	8
Behavior changes .....	9
Behavior changes in release 18r.1.00g .....	9
Behavior changes in release 18r.1.00f.....	9
Behavior changes in release 18r.1.00e .....	9
Software Features .....	10
New software features in 18r.1.00g .....	10
New software features in 18r.1.00f.....	10
New software features in 18r.1.00e .....	10
CLI commands.....	12
CLI commands introduced in R18r.1.00g.....	12
CLI commands introduced in R18r.1.00f.....	12
CLI commands introduced in R18r.1.00e.....	13
RFCs, Standards, and Scalability.....	14
Hardware support .....	15
Supported devices.....	15
Supported power supplies .....	16
Supported optics.....	16
Supported Extreme optics in SLX-OS 18r.1.00d .....	18
Software upgrade and downgrade .....	19
Image file names .....	19
Upgrade and downgrade considerations.....	19
MCT Upgrade Process .....	22
Limitations and restrictions.....	26
Defects closed in 18r.1.00g.....	29
Defects closed in 18r.1.00f.....	31
Defects closed in 18r.1.00e.....	35
Defects closed in 18r.1.00d.....	40
Defects closed in 18r.1.00c.....	46

# Document history

<b>Version</b>	<b>Summary of changes</b>	<b>Publication date</b>
1.0	Initial Release Removed versions 18r.1.00d and older	January 2021
2.0	Updated description for Defect ID 55742 Defect ID 46859 was added under the section 'Defects closed in 18r.1.00e'	February 2021

# Preface

## Contacting Extreme Technical Support

As an Extreme customer, you can contact Extreme Technical Support using one of the following methods: 24x7 online or by telephone. OEM customers should contact their OEM/solution provider. If you require assistance, contact Extreme Networks using one of the following methods:

- GTAC (Global Technical Assistance Center) for immediate support
- Phone: 1-800-998-2408 (toll-free in U.S. and Canada) or +1 408-579-2826. For the support phone number in your country, visit: [www.extremenetworks.com/support/contact](http://www.extremenetworks.com/support/contact).
- Email: support@extremenetworks.com. To expedite your message, enter the product name or model number in the subject line.
- GTAC Knowledge – Get on-demand and tested resolutions from the GTAC Knowledgebase or create a help case if you need more guidance.
- The Hub – A forum for Extreme customers to connect with one another, get questions answered, share ideas and feedback, and get problems solved. This community is monitored by Extreme Networks employees but is not intended to replace specific guidance from GTAC.
- Support Portal – Manage cases, downloads, service contracts, product licensing, and training and certifications.

Before contacting Extreme Networks for technical support, have the following information ready:

- Your Extreme Networks service contract number and/or serial numbers for all involved Extreme Networks products
- A description of the failure
- A description of any action(s) already taken to resolve the problem
- A description of your network environment (such as layout, cable type, other relevant environmental information)
- Network load at the time of trouble (if known)
- The device history (for example, if you have returned the device before, or if this is a recurring problem)
- Any related RMA (Return Material Authorization) numbers

## Extreme resources

Visit the Extreme website to locate related documentation for your product and additional Extreme resources.

White papers, data sheets, and the most recent versions of Extreme software and hardware manuals are available at [www.extremenetworks.com](http://www.extremenetworks.com). Product documentation for all supported releases is available to registered users at <https://www.extremenetworks.com/support/documentation/>.

## Document feedback

Quality is our first concern at Extreme, and we have made every effort to ensure the accuracy and completeness of this document. However, if you find an error or an omission, or you think that a topic needs further development, we want to hear from you.

You can provide feedback in two ways:

- Use our short online feedback form at <https://www.extremenetworks.com/documentation-feedback/>
- Email us at [documentation@extremenetworks.com](mailto:documentation@extremenetworks.com)

Provide the publication title, part number, and as much detail as possible, including the topic heading and page number if applicable, as well as your suggestions for improvement.

# Overview

SLX-OS 18r.1.00e adds Password Encryption Policy: SHA-512 Support .

SLX-OS 18r.1.00d supports multiple customer found defect solutions.

SLX-OS 18r.1.00a supports the following solutions and features:

- L2 Exchange
  - Egress ACL rate-limiting: This is a key feature for IXP customers to flexibly rate-limit ACL filtered traffic on port/VLAN/BD
- vSLX
  - IP fabric BGP EVPN VXLAN control plane
  - L2 Exchange control plane

Note:

vSLX is community supported in the Extreme “The Hub” Community pages for Switching and Routing Data Center products.

[https://community.extremenetworks.com/extreme/categories/extreme\\_switchingrouting](https://community.extremenetworks.com/extreme/categories/extreme_switchingrouting)

Details of support process for vSLX is available in the vSLX guide and release note.

# New SKUs

No new SKUs are introduced in this release.



# Behavior changes

For information about 18r.1.00d and earlier releases, please refer to the [SLX-OS 18r.1.00d Release Notes](#).

## Behavior changes in release 18r.1.00g

- None

## Behavior changes in release 18r.1.00f

- None

## Behavior changes in release 18r.1.00e

The following system behaviors have changed in this release

- Password Encryption Policy: SHA-512 Support

# Software Features

For information about 18r.1.00d and earlier releases, please refer to the [SLX-OS 18r.1.00d Release Notes](#).

## New software features in 18r.1.00g

No new software features were added in this release.

## New software features in 18r.1.00f

No new software features were added in this release.

## New software features in 18r.1.00e

- Password Encryption Policy: SHA-512 Support

### Password encryption policy

The software supports encrypting the passwords of all existing user accounts by enabling password encryption at the device level. By default, the encryption service is enabled.

The following rules apply to password encryption:

- When you enable password encryption, all existing clear-text passwords are encrypted. Subsequently, passwords that are added in clear text are stored in encrypted format.
- There are three levels of password encryption:
  - Encryption Level 0: No encryption, clear text
  - Encryption Level 7: AES-256 encryption
  - Encryption Level 10: SHA-512 salted HASH format. This is the default encryption level.
- In the following example, the testuser account password is created in clear text after password encryption is enabled. The global encryption policy overrides command-level encryption settings, and the password is stored as encrypted.

```
device(config)# service password-encryption
device(config)# do show running-config service password-encryption
service password-encryption
device(config)# username testuser role testrole desc "Test User" encryption-level 0 password hallothere
device(config)# do show running-config username
username admin password $6$mAog0c./JxVGulzy#6wFogQmek0KOEgTav.0DVfKXzlvRodclUCAbipYft/DWnT5R6/
Y3qpq7V3JHlhRNv/wgulgXnzdtBDKPKaXbEg/encryption-level 10 role admin desc Administrator
username testuser password $6$78rhJxmF0zFKbhu4#0WvJVdRv7.ke07E5sL7m04stPw3XO9hgIxZ/
xArDpKCPk6eGTLcN0YBi3xRv856hoiDv8U9eMxxi6ZZNY4CiV/encryption-level 10 role testrole desc "Test User"
username user password $6$mAog0c./JxVGulzy#6wFogQmek0KOEgTav.0DVfKXzlvRodclUCAbipYft/DWnT5R6/
Y3qpq7V3JHlhRNv/wgulgXnzdtBDKPKaXbEg/encryption-level 10 role user desc User
```

- When you disable the password encryption service, any new passwords added in clear text are stored as clear text on the device. Existing encrypted passwords remain encrypted.
- In the following example, the testuser account password is stored in clear text after password encryption is disabled. The default accounts, user and admin, remain encrypted.

```

device(config)# no service password-encryption
device(config)# do show running-config service password-encryption
no service password-encryption
device(config)# username testuser role testrole desc "Test User" encryption-level 0 password hellothere
enable true
device(config)# do show running-config username
username admin password $6$mAog0c./JxVGulzy$6wFogQmek0KOEgTav.0DVVKzlvRodclUCAbipYft/DWnI5R6/
Y3qpg7V3JHlhRNvtwguLgXnzdtBDKPKaKbBg/encryption-level 10 role admin desc Administrator
username testuser password hellothere encryption-level 0 role testrole desc "Test User"
username user password $6$mAog0c./JxVGulzy$6wFogQmek0KOEgTav.0DVVKzlvRodclUCAbipYft/DWnI5R6/
Y3qpg7V3JHlhRNvtwguLgXnzdtBDKPKaKbBg/encryption-level 10 role user desc User

```

- If you have passwords with encryption-level 7 on the device, then you can use the exec command **password-encryption convert-enc-to-level-10** to upgrade the passwords to encryption-level 10 (SHA-512 hash format), making the passwords more secure. After you run this command, all encryption-level 7 passwords are converted to encryption-level 10. However, if you downgrade to a release lower than SLX 18r.1.00e, these accounts will not be available.
- This command is available only to admin users. Any clear-text (encryption-level 0) passwords are retained as-is in the configuration database and not converted to encryption-level 10 (SHA-512 hash format). These clear-text passwords can be converted using the **service password-encryption configuration** command.
- In the following example, testuser1 has encryption-level 7, and after running the exec command, the encryption-level is changed to 10.

```

SLX# show running-config user | inc testuser
username testuser password "cONW1RQ0nTV9Az42/9uCOqg==\n" encryption-level 7 role
testrole desc "Test User"
SLX# password-encryption convert-enc-to-level-10
%WARN:This operation will convert all existing user passwords to SHA-512 format.
However, the enc level 0 (clear-text) passwords, if any, will be retained as is in the
configurationdatabase. These configurations will be lost if the system is downgraded
to lower releases than SLX 20.1.1
Do you want to continue? [Y/N]y
All passwords are converted successfully.
SLX# show running-config user | inc testuser
username testuser password $6$gV7A5LDXqcGc8/ma
$MEVxe20jaBarALGhmSYw.p3oc9IXVj9xqNUGDnFNABGs.FAqwrM8EPDMvCJcZe/MsY9geY0ej0ligma7mWWWTz0
encryption-level 10 role testrole desc "Test User"
SLX#

```

- The exec command **password-encryption convert-enc-to-level-10** is not allowed if there is a configuration rollback in-progress.

# CLI commands

For information about 18r.1.00d and earlier releases, please refer to the [SLX-OS 18r.1.00d Release Notes](#).

## CLI commands introduced in R18r.1.00g

There are no new commands introduced in R18r.1.00g.

## CLI commands introduced in R18r.1.00f

### New commands

The following command is new in this release:

- [no] bpdu-drop-enable

This command is added at a port level to drop RPVST BPDUs. The bpdu-drop-enable command on a bridge domain should drop IEEE standard STP BPDU (with DMAC of 01-80-C2-00-00-00) as well as RPVST BPDU (which uses a non standard, proprietary DMAC). However, RPVST packets were not dropped on bridge domains. This command enables dropping of RPVST BPDUs at port level.

### Command Syntax:

```
[no] bpdu-drop-enable  
Default is no bpdu-drop-enable
```

Run this command in global context to turn on this feature on all interfaces. This command enables/disables BPDU drop on all Layer 2 (switchport) interfaces and is displayed in the running config.

```
SLX # show running config  
.  
.  
bpdu-drop-enable  
.
```

To enable L2 BPDU drop on all L2 interface use :

```
conf terminal  
bpdu-drop-enable  
end
```

Similarly to disable L2 BPDU drop on all L2 interface use:

```
conf terminal  
no bpdu-drop-enable  
end
```

To enable or disable L2 BPDU drop on a specific L2 interface, navigate into its context and apply this command. This command applies to any BPDU received on this interface.

```
conf terminal  
interface ethernet <slot/port>  
bpdu-drop-enable  
end
```

When configured on a particular L2 interface, it will be displayed in the running configuration as:

```
SLX# show running-config interface ethernet <slot/port>  
interface Ethernet <slot/port>  
bpdu-drop-enable  
switchport
```

**Command Limitations:**

1. This command is not available for port-channels.
2. Do not use this command when protocol spanning tree is configured. In such a scenario, spanning tree configuration takes precedence over this configuration.

**Modified commands**

No commands were modified in this release

**Deprecated commands**

No commands were deprecated in this release.

**CLI commands introduced in R18r.1.00e**

There are no new commands introduced in R18r.1.00e.

# RFCs, Standards, and Scalability

For RFCs, standards, and scale numbers supported in this release, refer to the [Extreme SLX-OS Scale and Standards Matrix for SLX 9850 and SLX 9540](#).

# Hardware support

## Supported devices

The following devices are supported in this release:

Supported Hardware	Description
BR-SLX9850-4-BND-AC	Extreme SLX 9850 4-slot chassis with 1 management module, 5 switch fabric modules, 2 3000W AC power supplies, 3 fan modules, and accessory kit. Power cord not included.
BR-SLX9850-4-BND-DC	Extreme SLX 9850 4-slot chassis with 1 management module, 5 switch fabric modules, 2 3000W DC power supplies, 3 fan modules, and accessory kit. Power cord not included.
BR-SLX9850-8-BND-AC	Extreme SLX 9850 8-slot chassis with 1 management module, 5 switch fabric modules, 4 3000W AC power supplies, 3 fan modules, and accessory kit. Power cord not included.
BR-SLX9850-8-BND-DC	Extreme SLX 9850 8-slot chassis with 1 management module, 5 switch fabric modules, 4 3000W DC power supplies, and 3 fan modules, and accessory kit. Power cord not included.
BR-SLX9850-10GX72S-M	Extreme SLX 9850 72-port 10 GbE/1 GbE dual-speed (M) interface module with IPv4/IPv6/MPLS hardware support. Requires SFP+ optics for 10 GbE connectivity and SFP optics for 1 GbE connectivity. Supports up to 750,000 MAC. Supports up to 1,500,000 IPv4 routes, 140,000 IPv6 routes with OptiScale™ Internet Routing.
BR-SLX9850-100GX36CQ-M	Extreme SLX 9850 36-port 100 GbE, 60-port 40 GbE, or 240-port 10 GbE flex-speed (M) interface module with IPv4/IPv6/MPLS hardware support. Requires QSFP28 optics for 100 GbE, QSFP+ optics for 40 GbE, and 40 GbE to 10 GbE breakout for 10 GbE connectivity. Supports up to 750,000 MAC. Supports up to 1,500,000 IPv4 routes, 140,000 IPv6 routes with OptiScale™ Internet Routing.
BR-SLX9850-10GX72S-D	Extreme SLX985072-port 10GbE/1GbE (D) interface module with IPv4/IPv6 hardware support. Requires SFP+ optics for 10GbE connectivity and SFP optics for 10GbE connectivity. Supports 750K MAC, 256K IPv4 routes and 64K IPv6 routes with up to 8GB packet buffers
BR-SLX9850-100GX36CQ-D	Extreme SLX 9850 36-port 100GbE, 60-port 40GbE, or 240-port 10GbE flex-speed (D) interface module with IPv4/IPv6 hardware support. Requires QSFP28, QSFP+ optics & 40GbE to 10GbE
BR-SLX9850-100GX12CQ-M	Extreme SLX 9850 12-port 100 GbE, 20-port 40GbE, or 80-port 10GbE flex-speed (M) interface module with IPv4/IPv6/MPLS hardware support. Requires QSFP28, QSFP+ optics & 40GbE to 10GbE breakout (for 10 GbE) connectivity. Supports up to 750,000 MAC. Supports up to 1,500,000 IPv4 routes, 140,000 IPv6 routes with OptiScale™ Internet Routing.
BR-SLX9850-100GX6CQ-M-UPG	6x100G POD SW license to be used with SLX9850-100Gx12CQ-M 100G blade only
XBR-SLX9850-4-S	Extreme SLX9850 Spare 4-slot chassis
XBR-SLX9850-8-S	Extreme SLX9850 Spare 8-slot chassis
BR-SLX9850-MM	Extreme SLX 9850 management module for 4-slot and 8-slot systems, includes 16GB RAM, 2 internal Solid State Drives, 4-Core Intel CPU, 2 USB 3.0 ports, 2 RJ-45 console ports, and 10GbE Services port
BR-SLX9850-4-SFM	Extreme SLX 9850 switch fabric module for 4-slot chassis
BR-SLX9850-8-SFM	Extreme SLX 9850 switch fabric module for 8-slot chassis
XBR-SLX9850-ACPWR-3000	Extreme SLX 9850 AC 3000W power supply for 4- and 8-slot chassis, 90-270V AC input
XBR-SLX9850-DCPWR-3000	Extreme SLX 9850 DC 3000W power supply for 4- and 8-slot chassis
XBR-SLX9850-4-FANM	Extreme SLX 9850 fan module for 4-slot chassis. Fan module has 2 fans
XBR-SLX9850-8-FANM	Extreme SLX 9850 fan module for 8-slot chassis. Fan module has 4 fans
XBR-SLX9850-4-CAB	Extreme SLX 9850 Cable Combo Kit for 4-slot chassis
XBR-SLX9850-8-CAB	Extreme SLX 9850 Cable Combo Kit for 8-slot chassis
XBR-SLX9850-4-SFMPNL	Extreme SLX 9850 switch fabric module blank panel for 4-slot chassis
XBR-SLX9850-8-SFMPNL	Extreme SLX 9850 switch fabric module blank panel for 8-slot chassis
XBR-SLX9850-PWRPNL	Extreme SLX 9850 power supply blank panel for 4-slot and 8-slot chassis
XBR-SLX9850-IMPNL	Extreme SLX 9850 interface module blank panel for 4-slot and 8-slot chassis
XBR-SLX9850-MMPNL	Extreme SLX 9850 management module blank panel for 4-slot and 8-slot chassis
XBR-SLX9850-4-4PRM-KIT	Extreme SLX 9850 four-post rack mounting kit for 4-slot chassis. Include 27-31" flush and recessed mounting
XBR-SLX9850-4-2PRM-KIT	Extreme SLX 9850 two-post rack mounting kit for 4-slot chassis. Include telco flush and midplane mounting
XBR-SLX9850-8-4PRM-KIT	Extreme SLX 9850 four-post rack mounting kit for 8-slot chassis. Include flush and recessed mounting
XBR-SLX9850-8-2PRM-KIT	Extreme SLX 9850 two-post rack mounting kit for 8-slot chassis. Include telco flush and midplane Mounting
BR-SLX-9540-24S-AC-F	Extreme SLX 9540-24S Switch AC with Front to Back airflow. Supports 24x10GE/1GE + 24x1GE ports

BR-SLX-9540-24S-DC-F	Extreme SLX 9540-48S Switch DC with Front to Back airflow. Supports 48x10GE/1GE + 6x100GE/40GE
BR-SLX-9540-24S-AC-R	Extreme SLX 9540-24S Switch AC with Back to Front airflow. Supports 24x10GE/1GE + 24x1GE ports
BR-SLX-9540-24S-DC-R	Extreme SLX 9540-24S Switch DC with Back to Front airflow. Supports 24x10GE/1GE + 24x1GE ports
BR-SLX-9540-48S-AC-F	Extreme SLX 9540-48S Switch AC with Front to Back airflow. Supports 48x10GE/1GE + 6x100GE/40GE
BR-SLX-9540-48S-DC-F	Extreme SLX 9540-48S Switch DC with Front to Back airflow. Supports 48x10GE/1GE + 6x100GE/40GE
BR-SLX-9540-48S-AC-R	Extreme SLX 9540-48S Switch AC with Back to Front airflow. Supports 48x10GE/1GE + 6x100GE/40GE
BR-SLX-9540-48S-DC-R	Extreme SLX 9540-48S Switch DC with Back to Front airflow. Supports 48x10GE/1GE + 6x100GE/40GE
BR-SLX-9540-24S-COD	Upgrade 24x1GE to 24x10GE/1GE
BR-SLX-9540-2C-POD	Ports on Demand for 2x100GE/40GE Uplinks
BR-SLX-9540-ADV-LIC-P	Advanced Feature License for MPLS, BGP-EVPN, CE2.0, NSX, OptiScale™ Internet Routing (for Extreme SLX 9540-24S and 9540-48S)

## Supported power supplies

- Extreme SLX 9850 AC 3000W power supply for 4- and 8-slot chassis, 90-270V AC input
- Extreme SLX 9850 DC 3000W power supply for 4- and 8-slot chassis, 48V DC input

## Supported optics

Part Number	Description
10065	10/100/1000BASE-T SFP
10301	ASSY, SR SFP+ SHIPPING
10302	ASSY, LR SFP+ SHIPPING
10303	LRM SFP+ Module
10304	1m SFP+ Cable
10305	3m SFP+ Cable
10306	5m SFP+ Cable
10310	ZR SFP+ module
10319	40g QSFP+ SR\$ 850nm
10338	10Gb SFP+ 10GBASE-T
10401	100Gb QSFP28 SR4 MMF
10405	100Gb QSFP28 PSM4
10504	25G LR SFP28 10km
10052H	1000BASE-LX SFP, Hi
10056H	1000BASE-BX-D BiDi SFP, Hi
10057H	1000BASE-BX-U BiDi SFP, Hi
10070H	10/100/1000BASE-T SFP, Hi
100G-4WDM-QSFP10KM	100G 4WDM-10 QSFP28 10km
100G-4WDM-QSFP20KM	100G 4WDM-20 QSFP28 20km
100G-4WDM-QSFP40KM	100G 4WDM-40 QSFP28 40km
100G-AOC-QSFP10M-TA	100G AOC QSFP28 10m TAA
100G-CWDM4-QSFP2KM	100G CWDM4 QSFP28 2km
100G-DACP-QSFP1M	100G Passive DAC QSFP28 1m
100G-DACP-QSFP3M	100G Passive DAC QSFP28 3m
100G-DACP-QSFP4SFP1M	100G Passive DAC QSFP28 to 4xSFP28 1m
100G-DACP-QSFP4SFP3M	100G Passive DAC QSFP28 to 4xSFP28 3m
100G-DACP-QSFP4SFP5M	100G Passive DAC QSFP28 to 4xSFP28 5m
100G-DACP-QSFP5M	100G Passive DAC QSFP28 5m
100G-ER4LT-QSFP40KM	100G ER4-lite QSFP28 40km
100G-ESR4-QSFP300M	100G ESR4 QSFP28 300m



Part Number	Description
100G-LR4-QSFP10KM	100G LR4 QSFP28 10km
100G-LR4-QSFP2KM	100G LR4 QSFP28 2km
100G-SR4-QSFP100M	100G SR4 QSFP28 100m
100G-SWDM4-QSFP100M	100G SWDM4 QSFP28 100m
10G-AOC-SFP10M	10G AOC SFP+ 10m
10G-AOC-SFP7M	10G AOC SFP+ 7m
10GB-BX10-D	10 GB, SINGLE FIBER SM, -D 10 KM
10GB-BX10-U	10 GB, SINGLE FIBER SM, -U 10 KM
10G-DACA-SFP1M	10G Active DAC SFP+ 1m
10G-DACA-SFP3M	10G Active DAC SFP+ 3m
10G-DACA-SFP5M	10G Active DAC SFP+ 5m
10G-ER-SFP40KM-ET	10G ER SFP+ 40km Ext.Temp
10G-LR-SFP10KM-ET	10G LR SFP+ 10km Ext.Temp
10G-SR-SFP300M-ET	10G SR SFP+ 300m Ext.Temp
10G-USR-SFP100M	10G USR SFP+ 100m Hight Rx Sens
25G-DACP-SFP1M	25G Passive DAC SFP28 1m
25G-DACP-SFP3M	25G Passive DAC SFP28 3m
25G-LR-SFP10KM	25G LR SFP28 10km
40G-AOC-QSFP100M	40G AOC QSFP+ 100m
40G-AOC-QSFP10M	40G AOC QSFP+ 10m
40G-AOC-QSFP20M	40G AOC QSFP+ 20m
40G-AOC-QSFP3M	40G AOC QSFP+ 3m
40G-AOC-QSFP5M	40G AOC QSFP+ 5m
40G-BDSR-QSFP150M	40G BiDi SR QSFP+ 150m
40G-DACA-QSFP1M	40G Active DAC QSFP+ 1m
40G-DACA-QSFP3M	40G Active DAC QSFP+ 3m
40G-DACA-QSFP4SFP1M	40G Active DAC QSFP+ to 4xSFP+ 1m
40G-DACA-QSFP4SFP5M	40G Active DAC QSFP+ to 4xSFP+ 5m
40G-DACA-QSFP5M	40G Active DAC QSFP+ 5m
40G-DACP-QSFP1M	40G Passive DAC QSFP+ 1m
40G-DACP-QSFP3M	40G Passive DAC QSFP+ 3m
40G-DACP-QSFP4SFP1M	40G Passive DAC QSFP+ to 4xSFP+ 1m
40G-DACP-QSFP4SFP2M	40G Passive DAC QSFP+ to 4xSFP+ 2m
40G-DACP-QSFP4SFP3M	40G Passive DAC QSFP+ to 4xSFP+ 3m
40G-DACP-QSFP4SFP5M	40G Passive DAC QSFP+ to 4xSFP+ 5m
40G-DACP-QSFP5M	40G Passive DAC QSFP+ 5m
40G-DACP-QSFPZ5M	40G Passive DAC QSFP+ 0.5m
40G-ESR4-QSFP400M-NT	40G ESR4 QSFP+ 400m 10G-SR interop.
40G-LM4-QSFP160M	40G LM4 QSFP+ 160m 160m MMF. 1km SMF
40G-LR4-QSFP10KM	40G LR4 QSFP+ 10km
40G-SR4-QSFP150M	40G SR4 QSFP+ 150m
MGBIC-LC01-G	1GB SX MM, SFP, TAA

\*Optics reference qualified and should be purchased from the respective vendors. Extreme does not sell these directly.

## Supported Extreme optics in SLX-OS 18r.1.00d

The following orderable Extreme optics are supported in release SLX-OS 18r.1.00d:

<b>Orderable Optic SKUs</b>	<b>Description</b>
100G-CWDM4-QSFP2KM	100G CWDM4 QSFP28 2km
10301	ASSY, SR SFP+ SHIPPING
10302	ASSY, LR SFP+ SHIPPING
10070H	10/100/1000BASE-T SFP, Hi
10052H	1000BASE-LX SFP, Hi
100G-LR4-QSFP10KM	100G LR4 QSFP28 10km
40G-SR4-QSFP150M	40G SR4 QSFP+ 150m

# Software upgrade and downgrade

## Image file names

Download the following images from [www.extremenetworks.com](http://www.extremenetworks.com).

Image file name	Description
SLX-OS_18r.1.00g.tar.gz	SLX-OS 18r.1.00g software
SLX-OS_18r.1.00g_all_mibs.tar.gz	SLX-OS 18r.1.00g MIBS
SLX-OS_18r.1.00g.md5	SLX-OS 18r.1.00g md5 checksum

## Upgrade/downgrade considerations using firmware download CLI through fullinstall

The fullinstall CLI option is supported through the firmware download when upgrading from release SLX- OS 17r.1.01a to SLX-OS 17r.2.01. The fullinstall CLI option is NOT supported with USB.

## Upgrade and downgrade considerations

- Upgrade from a 32-bit to 32-bit SLX-OS is performed using 'coldboot' option
- Upgrade from a 32-bit to 64-bit SLX-OS is a two-step sequential process as shown below:
  - 1) Upgrade using 'coldboot' to 17r.1.01a
  - 2) Upgrade using 'fullinstall' to 64-bit SLX OS
- Upgrade/Downgrade using 'fullinstall' takes up to 60 minutes for completion as compared to 25 minutes for 'coldboot'
- Upgrade from a 64-bit to 64-bit SLX-OS is performed using 'coldboot' option
- It is recommended to use 7zip or WinRAR to Un-compress the SLXOS tarfile
- When firmware upgrade or downgrade is performed, following matrix can be used as a reference.

<b>To</b>	<b>16r.1.00 17r.1.00 17r.1.01  (32-bit)</b>	<b>17r.1.01b  (32-bit)</b>	<b>17r.2.00a  (64-bit)</b>	<b>18r.1.00 18r.1.00a 18r.1.00b 18r.1.00c 18r.1.00d 18r.1.00e 18r.1.00f 18r.1.00g  (64-bit)</b>
<b>From</b>				
<b>16r.1.00 17r.1.00 17r.1.01  (32-bit)</b>	coldboot	coldboot	Two Step Process: 1. Upgrade to 17r.1.01b 2. Upgrade to 17r.2.00a	Two Step Process: 1. Upgrade to 17r.1.01b 2. Upgrade to 18r.1.00 18r.1.00a 18r.1.00b 18r.1.00c 18r.1.00d 18r.1.00e 18r.1.00f 18r.1.00g
<b>17r.1.01b  (32-bit)</b>	coldboot	coldboot	fullinstall	fullinstall
<b>17r.2.00a  (64-bit)</b>	Two Step Process: 1. Downgrade to 17r.1.01b 2. coldboot to 16r.1.00	fullinstall	coldboot	coldboot
<b>18r.1.00 18r.1.00a 18r.1.00b 18r.1.00c 18r.1.00d 18r.1.00e 18r.1.00f 18r.1.00g  (64-bit)</b>	Two Step Process: 1. Downgrade to 17r.1.01b 2. coldboot to 16r.1.00	fullinstall	coldboot	coldboot

## Upgrade Steps from 32-bit to 64-bit SLX-OS

1. Make sure the device is running SLXOS 17r.1.01a or later, if not, please see the 17r.1.01 documentation on how to upgrade to that release.
2. Upgrade to SLX-OS 18r.1.00 using fullinstall
3. Save Configuration  
To save the config, run

```
copy running-config startup-config
```

4. Firmware download with “fullinstall” option from source directory  
device# firmware download fullinstall ftp user releaseuser password releaseuser file release.plist directory <path> host <host\_ip>

### Notes:

Firmware download with the “fullinstall” option will retain the startup configuration file, and upon auto reboot of the device, it will replay the startup configuration file automatically.

Firmware [download] upgrade support from SLXOS 18r.1.00b [Linux Kernel 2.6] to SLXOS 19.1.0 [Linux Kernel 4.14] is available from SLXOS 18r.1.00b onwards using "fullinstall" additional keyword

Upgrade/downgrade using firmware download CLI through USB:

- Upgrade from SLX-SLX 17r.1.01a to SLX-OS 17r.2.01 is supported via firmware download CLI with “fullinstall” option.
- Upgrade from SLX 17r.1.01b to SLX-OS 17r.2.01a or later is supported via firmware download CLI with “fullinstall” option.
- USB based FWD upgrade from SLX-OS 17r.1.01a (32-bit) to SLX-OS 17r.2.01 (64-bit) or later is supported with “fullinstall” option.
- USB3.0 used for firmware download can be in VFAT or EXT4 format.

Instruction to check and upgrade FPGAs/CPLDs:

Refer to the *SLX-OS Upgrade Guide* for all variations on upgrading SLX-OS.

FPGA/CPLD versions:

<b>SLX-9850</b>	<b>Release Date</b>
MM sys FPGA	08/25/2016
LC sys FPGA	08/30/2016
SFM sys FPGA	08/04/2016
<b>SLX-9540</b>	<b>Release Date</b>
Sys FPGA	02/09/2017
CPLD 0	02/09/2017
CPLD 1	02/09/2017


## MCT Upgrade Process

This section describes the process to upgrade MCT cluster nodes with minimum traffic loss disruption.

The MCT upgrade process is divided into the following sections:

1. MCT upgrade process from SLX-OS 17r.1.01x to SLX-OS 18r.1.00d (32-bit OS to 64-bit OS)
2. MCT upgrade process from SLX-OS 18r.1.00 to SLX-OS 18r.1.00d (64-bit OS to 64-bit OS)

The steps in the MCT upgrade process use the following nomenclature for MCT nodes: Node A and Node B.



### MCT upgrade process from SLX-OS 17r.1.01x to SLX-OS 18r.1.00d:

This section describes the procedure to upgrade MCT cluster nodes from SLX-OS 17r.1.01x to SLX-OS 18r.1.00d and later releases with minimal traffic loss disruption.

This is a 32-bit OS to 64-bit OS upgrade and hence uses the firmware download command with **fullinstall** option in order to perform the upgrade.

1. Configure client isolation mode under the cluster to be loose on Node A and on Node B respectively using the `client-isolation loose` command. For example:  

```
Device(config)# cluster <Name of the cluster> <cluster-id> Device(config-cluster-1)# client-isolation loose
```
2. Isolate Node A from the network using the following steps:
  - a. Disable the MCT client-interfaces on Node A using `client-interfaces-shutdown` command under cluster configuration section.  

```
Device-A(config-cluster-1)# client-interfaces-shutdown
```
  - b. Disable the link connected to MCT peer node and uplink to the core network.  
This would result in all CCEP traffic to switch to Node B within 30 seconds depending on scale and other parameters.
3. Copy running-configuration to startup-configuration on node A.
4. Upgrade Node A to the 18r.1.00d release using the **firmware download fullinstall** command. While the upgrade on node A is in progress, the traffic would continue to pass through node B.
5. Verify that once the node comes UP, the `member-vlan` configuration under the cluster section is removed.
6. Create an evpn template and add to the existing configuration on Node A. For example:

```
Device(config)# evpn <evpn-instance-name> route-target both auto ignore-asrd auto
vlan add <NUMBER: 1-4090> (If VLAN config is present) bridge-domain add <NUMBER: 1-4090> (If L2VPN config is present)
```

7. Isolate Node B from the network using the following steps. Please note that there is complete traffic loss at this step.

- a. Disable the MCT clients from the Node B using **client-interfaces-shutdown** command under cluster configuration section.

```
Device-B(config-cluster-1)# client-interfaces-shutdown
```

- b. Disable the link connected to MCT peer node and uplink to the core.

**Note:** This step is suggested at this stage to avoid traffic duplication if L2VPN configuration is present. If L2VPN config is not present, enter the **no client-interfaces- shutdown** command on Node A before isolating Node B to minimize traffic loss. (Swap Step 7 and 9)

8. Copy running-configuration to startup-configuration on Node B.
9. Enable the interface towards the peer MCT node (ICL interface) and the uplink to the core network on Node A. (The ICL link would still be down since Node-B is isolated before this step. This is performed so that after Node B gets upgraded, the ICL link will come up once no shut is performed on the ICL link on Node-B.)

10. Bring Node A back to the network by entering the **no client-interfaces-shutdown** command under cluster configuration.

```
Device-A(config-cluster-1)# no client-interfaces-shutdown
```

This would result in all CCEP traffic to switch to Node A within 30 seconds depending on scale and other parameters.

11. Upgrade Node B to the 18r.1.00d release using the **firmware download fullinstall** command.

While the upgrade on node B is in progress, the traffic would continue to pass through node A.

12. Verify that once the Node B comes UP, the member-vlan configuration under the cluster section is removed.

13. Create an evpn template and add to the existing configuration on Node B. For example:

```
Device-B(config)# evpn <evpn-instance-name> route-target both auto ignore-asrd auto
```

```
vlan add <NUMBER: 1-4090> (If VLAN config is present) bridge-domain add <NUMBER: 1-4090> (If L2VPN config is present)
```

14. Enable the interface towards the peer MCT node (ICL) and the uplink to the core network on Node B.

15. Verify if the BGP session between the MCT peers is established and the cluster is up.

16. Bring Node B back to the network by entering the **no client-interfaces-shutdown** command under cluster configuration.

```
Device-B(config-cluster-1)# no client-interfaces-shutdown
```

17. Copy running-config to startup-config on both the nodes.

## Additional upgrade considerations for upgrading SLX9850 from 17r.1.01a or 17r.1.01b to 18r.1.00d

When upgrading a SLX9850 from 17r.1.01a or 17r.1.01b to 18r.1.00d, if TPVM is installed in the system, you must un-install it by running the “`tpvm uninstall`” command before starting firmware download. Otherwise, it will cause system initialization issue. After the system is upgraded, you can install the TPVM image from 18r.1.00 by running the “`tpvm install`” command.

## MCT upgrade process from SLX-OS 18r.1.00 to SLX-OS 18.1.00d:

This section describes the procedure to upgrade MCT cluster nodes from SLX-OS 18r.1.00 or 18r.1.00ax patch or 18r.1.00b patch to SLX-OS 18r.1.00d patch and later releases with minimal traffic loss disruption.

This is a 64-bit OS to 64-bit OS upgrade and hence uses the firmware download command with **coldboot** option to perform the upgrade.

1. Configure client isolation mode under the cluster to be loose on Node A and Node B respectively using the client-isolation loose command. For example:

```
Device(config)# cluster <Name of the cluster> <cluster-id>
Device(config-cluster-1)# client-isolation loose
```

2. Isolate Node A from the network using the following steps:

- a. Disable the MCT client-interfaces on Node A using **client-interfaces-shutdown** command under cluster configuration section.

```
Device-A(config-cluster-1)# client-interfaces-shutdown
```

- b. Interface connected to MCT peer node (ICL interface) must be left in **no shut** state.
- c. Disable uplink to the core network.

This causes all CCEP traffic to switch to Node B within 30 seconds depending on the scale and other parameters.

3. Copy running-config to startup-config on node A.
4. Upgrade Node A using **firmware download** command with **coldboot** option to the 18r.1.00c image. While the upgrade on node A is in progress, the traffic would continue to pass through node B.
5. Verify if Node A is back online after the upgrade and has completed initialization.
6. Isolate Node B from the network using the following steps.

**Note:** There is complete traffic loss at this step.

- a. Disable the MCT client-interfaces on Node B using **client-interfaces-shutdown** command under cluster configuration section.

```
Device-B(config-cluster-1)# client-interfaces-shutdown
```

- b. Interface connected to MCT peer node (ICL interface) must be left in **no shut** state.
- c. Disable uplink to the core network.

**Note:** This step is suggested at this stage in order to avoid traffic duplication if L2VPN configuration is present. If L2VPN configuration is not present, perform **no client- interfaces-shutdown** on Node A before isolating Node B in order to minimize traffic loss. (Swap Step-6 and Step-9)

7. Copy running-configuration to startup-configuration on Node B.



8. Enable the uplink to the core network on Node A. (The ICL interface would be up by now since we did not shut it prior to upgrade.)
9. Bring Node A back to the network by configuring the **no client-interfaces-shutdown** command under cluster configuration on Node A. This would result in all CCEP traffic to switch to Node A within 30 seconds depending on the scale and other parameters.  
`Device-A(config-cluster-1)# no client-interfaces-shutdown`
10. Upgrade Node B to 18r.1.00d release using the **firmware download** command with **coldboot** option. While the upgrade on node B is in progress, the traffic would continue to pass through node A.
11. Verify that once the Node B comes UP, the uplink to the CORE network on Node B is configured to come up.
12. Verify if BGP session between MCT peers is established and the cluster is up.
13. Bring Node B back to the network by bringing the client-interfaces UP using the following command under cluster configuration.  
`Device-B(config-cluster-1)# no client-interfaces-shutdown`
14. Copy running-config to startup-config on both the nodes.

## Limitations and restrictions

- Raslog and ACL buffered logging as denied packet observed for ACL permit rules when ACL applied or removed for interface.
- QoS flowcontrol tx **on** is not recommended.
- Restricted mac learning observed on remote node with PMS applied for ingress traffic.
- Conform byte size is more than packet byte size in egress RL counters.
- In lag-profile-1, the maximum number of class-maps supported on port-channel is 64 class-maps.
- When a user egress ACL rule is configured with a VLAN keyword, 100% traffic drop is observed.

### Egress ACL-based Rate Limiting:

- Support in “layer2-ratelimit” TCAM profile only.
- Support CE ports only (that is, not support for MPLS uplinks).
- Broadcast, multicast and unknown unicast packets not supported.
- Port channel is not supported.
- Rate limit counters (conform/violate) not supported.

### Additional Limitations

- Egress RL is designed to support the packet receiving at one physical port but transmitting on the different physical port. If the packets are received and transported on the same physical port, ingress rate-limit should be deployed.
- If multiple VLANs on the same ingress port belong to the same BD, and the egress ACL rate limiting is configured to rate limit one of the VLANs, all VLAN traffic is rate limited. A workaround is to add matching source or destination MAC address along with the VLAN in the ACL.
- Ingress ACL RL and egress ACL RL do not work together on the same flow of traffic.

### CLI configuration design considerations for Rate limiting:

#### SLX 9850 (4 slots)

- 156 class maps per tower if bind to interface (VOQ limitation).
- 2k class maps per system (Supported hardware entry).
- 128 class maps for port-channel in default LAG profile, 128 LAG total (LAG hardware entry).
- 256 class map for port-channel in profile-1 LAG profile, 256 LAG total (LAG hardware entry).
- 1k policy maps per system (Software scaling).
- 32K class-maps per system (Software scaling).

**Note:** For SLX 9850 (8 slots), the VOQ limitation per tower is cut in half.

## SLX 9540

- 64 class maps for port-channel in default LAG profile, 128 LAG total. (Support hardware entry).
- 128 class maps for port-channel in LAG profile-1, 128 LAG total. (Support hardware entry).
- 2k class maps per tower or system (Supported hardware entry).
- 1k policy maps per system (Software scaling).
- 32K class-maps per system (Software scaling).

### QOS resource can be running out in following cases:

1. Out of resource when user bind the policy to a port or channel, in this case SW shall fail the command with error message.
2. Out of resource when user add new class to existing policy. SW shall fail the command to add new class with error message.
3. Out of resource when user add a new port to a LAG. In this case SW can't fail the command due to design limitation. Instead, it will send raslog to inform the user (the user need to check raslog and remove the config if resource running out).

**sFlow:** sFlow packet samples that are collected are inaccurate based on probability and low rate-limit.

**L2 ACL:** Unintentional traffic leaking can occur in a short period time (within 10 ms) during the adding of an L2 and L3 ACL.

### Cos to TC mapping

- "qos map cos-traffic-class cosTC" command has known issue in this release and not taking effect for port channel.

### VPLS VC

- In certain situations, VC peer flaps can happen in the VPLS network due to excessive amount of multicast traffic. To protect the control plane protocols, the following configuration is recommended on all ingress interfaces.

- Apply BUM rate limit per interface

```
storm-control ingress broadcast limit-bps <rate in bps> storm-control ingress  
multicast limit-bps <rate in bps>
```

```
storm-control ingress unknown-unicast limit-bps <rate in bps>
```

Rate limit values should be calculated based on amount of multicast traffic expected on the interface. Unknown-unicast should be as low as possible.

- Apply MCAST rate limit per forwarding ASIC

```
qos rx-queue multicast best-effort-rate <rate in kbps>
```

Command must be configured on one interface per ASIC. Actual rate depends of amount of expected MCAST traffic per forwarding ASIC.

### BFD:

- Sessions with less than 300ms timer may flap in scale conditions
- Known issues with BFD when BFD is configured over multi-slot LAG, or multi-hop session over ECMP paths

## **L3VPN: Known issues with Peer-group, RR-group and Prefix-list ORF FRR**

### **facility backup**

- VPLS/VLL Bypass traffic will not work when router/untagged VE interfaces configured as MPLS uplink ports

**MCT L3 cases are not supported when ICL interface is configured as router/untagged VE** it is required for all MPLS uplinks to be tagged interfaces to use FRR bypass for VLL/VPLS/L3VPN applications

### **Routing over VPLS**

- pw-profile must be configured with tagged mode only under the bridge-domain instance for routing with VPLS.
- It is required for all MPLS uplinks to be tagged VE interfaces to support VEOVPLS.

### **Internet Routes Scaling**

- It is recommended that the internet routes scaling features be enabled with internet peering configurations, as qualified by Extreme
- Feature is supported with default VRF only; default VRF and non-default VRF should not be co-existing when default VRF is configured with Internet routes scaling feature

### **L3VPN jumbo limitation**

- The IPMTU value configured in CLI is applicable, if outgoing routing interface is an undelay IP interface (VE or L3 port); the IPMTU value configured in CLI is not applicable if the outgoing interface is uplink for IPoMPLS, L3VPN traffic, or ICL for MCT peers. Jumbo frames over MPLS/L3VPN tunnels can be accepted based the port L2MTU values.

### **EVPN IP Fabric**

- IPv6 Static Anycast Gateway is not supported.

### **Storm-control**

- Counters for Broadcast and Multicast storm-control are not supported in layer2-optimized-1 profile.

### **Increase scale support for class-maps under the service policy**

- The ACL/VLAN/BD Rate Limiting scale numbers are dependent on tcam profile configured. Basically, based on the tcam entries reserved for the feature, user can scale number of policers/stats for appropriate application.

Consider below example with tcam profile "layer2-optimised-1".

- Create 2K Vlan/BD based class-maps and 2K ACL based class-maps associate those with policy-map pmap1.
- Configure 1k distinct policer attributes (cir/cbs/eir/ebs) for all the policy- map/class-map combination and bind the policy-map pmap1 to any interface.
- Now overall there will be 4K policers active for that interface with 4k distinct class-maps (match criteria).
- Note: The 4K policers (class-maps) scale will not be applicable to port-channel. There are only 1,215 policers are reserved for port-channels.
- Based on the requirement user must set the tcam profile and must reboot the box for activating the same.

## Defects closed in 18r.1.00g

This section lists software defects with Critical, High, and Medium Technical Severity closed with code changes as of January 2021 in 18r.1.00g.

**Note: Parent Defect ID is the customer found Defect ID. The Issue ID is the tracking number uniquely used to check in the fix for each major release.**

<b>Parent Defect ID:</b>	SLXOS-55370	<b>Issue ID:</b>	SLXOS-55681
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Reported in Release:</b>	SLXOS 18r.1.00ch
<b>Technology Group:</b>	Security	<b>Technology:</b>	MACsec - Media Access Control security
<b>Symptom:</b>	Few MAC entries may get missed from software MAC table (L2Mgr) "show mac-address-table" after detection of mac move and not gets retrieved once after reception of traffic.		
<b>Condition:</b>	a) Port-security should be enabled on port. b) Send traffic with already learned mac (mac-move detection) and violate port-security mac count configured on port to make default action of port shut.		

<b>Parent Defect ID:</b>	SLXOS-55278	<b>Issue ID:</b>	SLXOS-55748
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Reported in Release:</b>	SLXOS 18r.1.00ch
<b>Technology Group:</b>	Security	<b>Technology:</b>	RADIUS
<b>Symptom:</b>	SLX may ignore RADIUS server response for REST API authentication		
<b>Condition:</b>	1. Configure one or more radius servers with "aaa authentication login radius local-auth-fallback" 2. Send REST query to SLX from any linux device (SLX chooses lower source UDP port numbers, hence it ignores such responses)		

<b>Parent Defect ID:</b>	SLXOS-55742	<b>Issue ID:</b>	SLXOS-55914
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Reported in Release:</b>	SLXOS 18r.1.00ch
<b>Technology Group:</b>	Layer 2 Switching	<b>Technology:</b>	Other
<b>Symptom:</b>	May notice MAC miss (address not learned) on "show mac-address-table" output once after receiving traffic with expected(missed) MAC.		
<b>Condition:</b>	a) Node should experience multiple mac-movements (between two interfaces). b) Introduce random manual shut in between mac-movement.		

<b>Parent Defect ID:</b>	SLXOS-55510	<b>Issue ID:</b>	SLXOS-56060
<b>Severity:</b>	S1 - Critical		
<b>Product:</b>	SLX-OS	<b>Reported in Release:</b>	SLXOS 18r.1.00ca
<b>Technology Group:</b>	Management	<b>Technology:</b>	Software Installation & Upgrade
<b>Symptom:</b>	Unexpected reload		
<b>Condition:</b>	There is no specific operation to hit this case as it related to CPU kernel scheduling.		

## Defects closed in 18r.1.00f

This section lists software defects with Critical, High, and Medium Technical Severity closed with code changes as of October 2020 in 18r.1.00f.

**Note: Parent Defect ID is the customer found Defect ID. The Issue ID is the tracking number uniquely used to check in the fix for each major release.**

<b>Parent Defect ID:</b>	SLXOS-42283	<b>Issue ID:</b>	SLXOS-43665
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Reported in Release:</b>	SLXOS 18r.1.00a
<b>Technology Group:</b>	MPLS	<b>Technology:</b>	MPLS VPLS - Virtual Private LAN Services
<b>Symptom:</b>	MAC learning may not be happening after Management Module switchover		
<b>Condition:</b>	In the presence of 'spanning-tree shutdown' configuration applied on Bridge Domain interfaces		
<b>Recovery:</b>	Remove and re-apply the 'spanning-tree shutdown' configuration		

<b>Parent Defect ID:</b>	SLXOS-45991	<b>Issue ID:</b>	SLXOS-45992
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Reported in Release:</b>	SLXOS 18r.1.00a
<b>Technology Group:</b>	Layer 2 Switching	<b>Technology:</b>	xSTP - Spanning Tree Protocols
<b>Symptom:</b>	User will observe that STP BPDUs are getting flooded on VPLS Bridge domain like normal multicast traffic, even though user has enabled 'bpdu drop' feature using the CLI		
<b>Condition:</b>	'bpdu drop' configured on VPLS BD is not behaving as expected , where the BPDU should be dropped instead of flooding when 'bpdu drop ' is enabled on the VPLS bridge domain.		
<b>Workaround:</b>	None		

<b>Parent Defect ID:</b>	SLXOS-49410	<b>Issue ID:</b>	SLXOS-49411
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Reported in Release:</b>	SLXOS 17r.1.01aj
<b>Technology Group:</b>	Management	<b>Technology:</b>	High Availability
<b>Symptom:</b>	Standby Management may not reach Synchronized State		
<b>Condition:</b>	In the presence of 72x10G Line cards alone, on a SLX9850 8 slot chassis		
<b>Workaround:</b>	Shouldn't be observed if 36x100G is also present		

<b>Parent Defect ID:</b>	SLXOS-50077	<b>Issue ID:</b>	SLXOS-50078
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Reported in Release:</b>	SLXOS 20.1.1
<b>Technology Group:</b>	Security	<b>Technology:</b>	User Accounts & Passwords
<b>Symptom:</b>	System level commands are accessible by non-admin users		

<b>Condition:</b>	when we have non-admin users
-------------------	------------------------------

<b>Parent Defect ID:</b>	SLXOS-50419	<b>Issue ID:</b>	SLXOS-50420
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Reported in Release:</b>	SLXOS 18x.1.00
<b>Technology Group:</b>	Management	<b>Technology:</b>	Other
<b>Symptom:</b>	Unexpected reload		
<b>Condition:</b>	It can happen when there is CPU intensive workload		

<b>Parent Defect ID:</b>	SLXOS-50340	<b>Issue ID:</b>	SLXOS-50588
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Reported in Release:</b>	SLXOS 18r.1.00d
<b>Technology Group:</b>	Layer 3 Routing/Network Layer	<b>Technology:</b>	IP Addressing
<b>Symptom:</b>	traceroute command may succeeds for disabled loopback IP address from peer		
<b>Condition:</b>	1) Configure /32 mask IP address for loopback interface. 2) Disable loopback interface using shut.		

<b>Parent Defect ID:</b>	SLXOS-50515	<b>Issue ID:</b>	SLXOS-50674
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Reported in Release:</b>	SLXOS 18r.2.00a
<b>Technology Group:</b>	Layer 3 Routing/Network Layer	<b>Technology:</b>	IP Addressing
<b>Symptom:</b>	Notices duplicate IP address message on other Vendor device with SLX connected to it.		
<b>Condition:</b>	1) Back-to-back connection b/w SLX and other Vendor device 2) Configuration of IP address with mask /31 on other Vendor device followed by SLX.		

<b>Parent Defect ID:</b>	SLXOS-51201	<b>Issue ID:</b>	SLXOS-51365
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Reported in Release:</b>	SLXOS 18r.1.00d
<b>Technology Group:</b>	IP Multicast	<b>Technology:</b>	IPv4 Multicast Routing
<b>Symptom:</b>	SLX may unexpectedly reload in hslagtd daemon		
<b>Condition:</b>	Requires processing of the high scale of timed out (S,G) entries		

<b>Parent Defect ID:</b>	SLXOS-51474	<b>Issue ID:</b>	SLXOS-51477
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Reported in Release:</b>	SLXOS 18r.1.00ch
<b>Technology Group:</b>	Layer 2 Switching	<b>Technology:</b>	VLAN - Virtual LAN
<b>Symptom:</b>	Packets may flood on the same port from where it is received		



<b>Condition:</b>	On reception of packet with ethertype of 0x88e7(PBB)
-------------------	--

<b>Parent Defect ID:</b>	SLXOS-51154	<b>Issue ID:</b>	SLXOS-51497
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Reported in Release:</b>	SLXOS 18r.1.00d
<b>Technology Group:</b>	Management	<b>Technology:</b>	SNMP - Simple Network Management Protocol
<b>Symptom:</b>	IP MTU configuration allows configuring sizes of interface MTU bounds		
<b>Condition:</b>	Configuring the IP MTU from SNMP		

<b>Parent Defect ID:</b>	SLXOS-50793	<b>Issue ID:</b>	SLXOS-52243
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Reported in Release:</b>	SLXOS 18r.1.00ch
<b>Technology Group:</b>	Monitoring	<b>Technology:</b>	OAM - Operations, Admin & Maintenance
<b>Symptom:</b>	"show media" may display encoding string that doesn't comply with the IEEE standard for certain optics.		
<b>Condition:</b>	When 100G-LR4 QSFP28 optic has encoding value 5  Ex: show media interface ethernet x/y Encoding 5 IEEE 802.3ab		

<b>Parent Defect ID:</b>	SLXOS-50376	<b>Issue ID:</b>	SLXOS-52597
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Reported in Release:</b>	SLXOS 18r.1.00ca
<b>Technology Group:</b>	Management	<b>Technology:</b>	Software Installation & Upgrade
<b>Symptom:</b>	Very rarely Management Module may fail to come up and enter into rolling reboot with Kernel Panic		
<b>Condition:</b>	Observed during module reset in the presence of CFM		

<b>Parent Defect ID:</b>	SLXOS-51831	<b>Issue ID:</b>	SLXOS-53563
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Reported in Release:</b>	SLXOS 18r.1.00ca
<b>Technology Group:</b>	MPLS	<b>Technology:</b>	MPLS VPLS - Virtual Private LAN Services
<b>Symptom:</b>	SLX fails to learn VPLS MAC from remote PE		
<b>Condition:</b>	MPLS is configured with primary & bypass-path and can be observed with the flaps only in this following sequence (a) Flap on the primary path interface (b) Flap on the bypass-path interface		

	(c) Flap on the current primary path interface
--	--

<b>Parent Defect ID:</b>	SLXOS-50677	<b>Issue ID:</b>	SLXOS-53737
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Reported in Release:</b>	SLXOS 18r.1.00e
<b>Technology Group:</b>	Layer 3 Routing/Network Layer	<b>Technology:</b>	ARP - Address Resolution Protocol
<b>Symptom:</b>	Duplicate IP address SYSLOG message may be seen on the neighboring device console with no functional impact		
<b>Condition:</b>	When /31 subnet is configured on SLX to other Vendor devices as point-to-point links		

<b>Parent Defect ID:</b>	SLXOS-52104	<b>Issue ID:</b>	SLXOS-53873
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Reported in Release:</b>	SLXOS 18r.1.00e
<b>Technology Group:</b>	MPLS	<b>Technology:</b>	MPLS VPLS - Virtual Private LAN Services
<b>Symptom:</b>	Sometimes Line card may reload unexpectedly during the execution of support save		
<b>Condition:</b>	Can be observed in the presence of 180 RSVP signaled LSP with 511 cross-connect on VPLS service		

<b>Parent Defect ID:</b>	SLXOS-51453	<b>Issue ID:</b>	SLXOS-54229
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Reported in Release:</b>	SLXOS 20.1.1
<b>Technology Group:</b>	Layer 3 Routing/Network Layer	<b>Technology:</b>	DHCP - Dynamic Host Configuration Protocol
<b>Symptom:</b>	Unexpected reload		
<b>Condition:</b>	DHCP malformed packet is received		

<b>Parent Defect ID:</b>	SLXOS-47656	<b>Issue ID:</b>	SLXOS-54270
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Reported in Release:</b>	SLXOS 20.1.1
<b>Technology Group:</b>	Layer 2 Switching	<b>Technology:</b>	VLAN - Virtual LAN
<b>Symptom:</b>	NETCONF configuration for bulk Bridge-domain LIF configuration will not succeed		
<b>Condition:</b>	By using NETCONF, user tries to configure multiple LIFs at once, in a single NETCONF request.		
<b>Workaround:</b>	None		

## Defects closed in 18r.1.00e

This section lists software defects with Critical, High, and Medium Technical Severity closed with and without a code change as of May 2020 in 18r.1.00e.

**Note: Parent Defect ID is the customer found Defect ID. The Issue ID is the tracking number uniquely used to check in the fix for each major release.**

<b>Parent Defect ID:</b>	SLXOS-38855	<b>Issue ID:</b>	SLXOS-42469
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Layer 3 Routing/Network Layer
<b>Reported in Release:</b>	SLXOS 18r.1.00aa	<b>Technology:</b>	ICMP - Internet Control Message Protocol
<b>Symptom:</b>	Not able to ping the Broadcast address.		
<b>Condition:</b>	When pinging the broadcast address from both mgmt-vrf and default-vrf interfaces.		

<b>Parent Defect ID:</b>	SLXOS-25680	<b>Issue ID:</b>	SLXOS-42650
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Monitoring
<b>Reported in Release:</b>	SLXOS 17r.1.01b	<b>Technology:</b>	OAM - Operations, Admin & Maintenance
<b>Symptom:</b>	100g link with FEC enabled does not come back after a dwdm link switch over between lanes sometimes		
<b>Condition:</b>	Requiring a fast switchover using an equipment linking a DWDM or fast hand that removes / inserts the optic rapidly without damaging the cable / optic		
<b>Workaround:</b>	Shut/no-shut		

<b>Parent Defect ID:</b>	SLXOS-43173	<b>Issue ID:</b>	SLXOS-43715
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Monitoring
<b>Reported in Release:</b>	SLXOS 18r.2.00a	<b>Technology:</b>	Hardware Monitoring
<b>Symptom:</b>	"show media optical-monitoring" command is taking close to 1 minute to refresh the smart data values.		
<b>Condition:</b>	Observed after shutdown/no shutdown of physical interfaces.		

<b>Parent Defect ID:</b>	SLXOS-43371	<b>Issue ID:</b>	SLXOS-44088
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Monitoring
<b>Reported in Release:</b>	SLXOS 18r.1.00ca	<b>Technology:</b>	Sysmon
<b>Symptom:</b>	The output of "show system monitor" is not showing correct values sometimes with respect to the power supplies.		
<b>Condition:</b>	When the number of sensors in SLX9850-8 setup is more than 90		

<b>Parent Defect ID:</b>	SLXOS-44562	<b>Issue ID:</b>	SLXOS-44563
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Management
<b>Reported in Release:</b>	SLXOS 18r.1.00c	<b>Technology:</b>	CLI - Command Line Interface
<b>Symptom:</b>	High_free memory observed as 0KB		

<b>Condition:</b>	In the output of "show process memory"		
<b>Parent Defect ID:</b>	SLXOS-42743	<b>Issue ID:</b>	SLXOS-45017
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	IP Multicast
<b>Reported in Release:</b>	SLXOS 18r.2.00	<b>Technology:</b>	PIM - Protocol-Independent Multicast
<b>Symptom:</b>	Unexpected MM reload		
<b>Condition:</b>	1. When Multicast (PIM) is enabled on multiple ports under single VLAN. 2. Any of the port receives the PIM(S,G) prune packet.		

<b>Parent Defect ID:</b>	SLXOS-45433	<b>Issue ID:</b>	SLXOS-45434
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	IP Multicast
<b>Reported in Release:</b>	SLXOS 18r.1.00c	<b>Technology:</b>	PIM - Protocol-Independent Multicast
<b>Symptom:</b>	Unexpected Management Module reload in mcagtd		
<b>Condition:</b>	1. Multicast (PIM) is enabled on multiple ports under same VLAN 2. Any of the port receives the PIM(S,G) prune packet		

<b>Parent Defect ID:</b>	SLXOS-45920	<b>Issue ID:</b>	SLXOS-45921
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Management
<b>Reported in Release:</b>	SLXOS 18r.2.00a	<b>Technology:</b>	SNMP - Simple Network Management Protocol
<b>Symptom:</b>	Snmpwalk from a linux server works to the first hop router but not beyond		
<b>Condition:</b>	MPLS L3VPN configured on in-band custom Management VRF		

<b>Parent Defect ID:</b>	SLXOS-46308	<b>Issue ID:</b>	SLXOS-46312
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Monitoring
<b>Reported in Release:</b>	SLXOS 18r.2.00ac	<b>Technology:</b>	OAM - Operations, Admin & Maintenance
<b>Symptom:</b>	1G Copper SFP interface becomes link down after reload		
<b>Condition:</b>	When speed 100 is configured on 1G copper SFP and system reload is performed.		
<b>Workaround:</b>	Speed reconfiguration on the ports will recover the issue.		

<b>Parent Defect ID:</b>	SLXOS-46646	<b>Issue ID:</b>	SLXOS-46650
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Management
<b>Reported in Release:</b>	SLXOS 18r.2.00ac	<b>Technology:</b>	SNMP - Simple Network Management Protocol
<b>Symptom:</b>	Unexpected reload.		
<b>Condition:</b>	When SLX has MPLS tunnels configured and snmpbulkwalks are continuously run for ifTable/ifXTable.		

<b>Parent Defect ID:</b>	SLXOS-46770	<b>Issue ID:</b>	SLXOS-46774
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Management
<b>Reported in Release:</b>	SLXOS 17r.2.01	<b>Technology:</b>	Other
<b>Symptom:</b>	Unexpected reload with reason as Software Fault:Kernel Panic may be observed		
<b>Condition:</b>	It can happen with a long-running process where its low 32-bit of total process utime is '0' in do_div().		

<b>Parent Defect ID:</b>	SLXOS-46855	<b>Issue ID:</b>	SLXOS-46859
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Reported in Release:</b>	SLXOS 18r.1.00ca
<b>Technology Group:</b>	Security	<b>Technology:</b>	ACLs - Access Control Lists
<b>Symptom:</b>	Unexpected reload.		
<b>Condition:</b>	When raslog logging is enabled globally and log keyword is used in ingress ACL rule		
<b>Workaround:</b>	Remove acl raslog command globally or do not use log keyword in any rule in ingress ACL policy		

<b>Parent Defect ID:</b>	SLXOS-47229	<b>Issue ID:</b>	SLXOS-47232
<b>Severity:</b>	S1 - Critical		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	MPLS
<b>Reported in Release:</b>	SLXOS 18r.1.00c	<b>Technology:</b>	LDP - Label Distribution Protocol
<b>Symptom:</b>	Few MPLS Targeted LDP peers may stay in Non-existent state.		
<b>Condition:</b>	During multiple fiber flaps on LDP LSP's.		

<b>Parent Defect ID:</b>	SLXOS-47234	<b>Issue ID:</b>	SLXOS-47364
<b>Severity:</b>	S1 - Critical		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	MPLS
<b>Reported in Release:</b>	SLXOS 18r.1.00d	<b>Technology:</b>	LDP - Label Distribution Protocol
<b>Symptom:</b>	Few MPLS Targeted LDP peers may stay in non-existent state.		
<b>Condition:</b>	1. Multiple fiber flaps observed on the Targeted-LDP LSP 2. With parallel programming enabled in the configuration		

<b>Parent Defect ID:</b>	SLXOS-47538	<b>Issue ID:</b>	SLXOS-47540
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Management
<b>Reported in Release:</b>	SLXOS 17r.1.01aj	<b>Technology:</b>	Other
<b>Symptom:</b>	REST runcmd operation fails with HTTP status code 406 or 502		
<b>Condition:</b>	Whenever upgrade and HA failover has been performed		

<b>Parent Defect ID:</b>	SLXOS-47629	<b>Issue ID:</b>	SLXOS-47631
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Monitoring
<b>Reported in Release:</b>	SLXOS 17r.1.01aj	<b>Technology:</b>	Syslog
<b>Symptom:</b>	RASLOG for optical temperature may display alarm even though the values are within boundary		

<b>Condition:</b>	During Port Up events		
<b>Parent Defect ID:</b>	SLXOS-47988	<b>Issue ID:</b>	SLXOS-47989
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Management
<b>Reported in Release:</b>	SLXOS 18r.1.00ca	<b>Technology:</b>	Other
<b>Symptom:</b>	/fabos/libexec/ethmode may be missed on standby Management Module.		
<b>Condition:</b>	During /fabos/cliexec/ifmodeshow command run from active Management Module.		

<b>Parent Defect ID:</b>	SLXOS-48011	<b>Issue ID:</b>	SLXOS-48012
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	IP Multicast
<b>Reported in Release:</b>	SLXOS 18r.1.00db	<b>Technology:</b>	PIM - Protocol-Independent Multicast
<b>Symptom:</b>	Memory leak and unexpected reload may be observed in mcagtd daemon.		
<b>Condition:</b>	On continuous execution of 'clear ip pim mcache' with multicast data traffic passing through		

<b>Parent Defect ID:</b>	SLXOS-48040	<b>Issue ID:</b>	SLXOS-48040
<b>Severity:</b>	S1 - Critical		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	MPLS
<b>Reported in Release:</b>	SLXOS 18r.1.00e	<b>Technology:</b>	LDP - Label Distribution Protocol
<b>Symptom:</b>	Few MPLS LDP peers may stay in LDP non-existent state		
<b>Condition:</b>	Occurs very rarely during multiple link flap events		

<b>Parent Defect ID:</b>	SLXOS-48075	<b>Issue ID:</b>	SLXOS-48076
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Management
<b>Reported in Release:</b>	SLXOS 18r.1.00ch	<b>Technology:</b>	Software Installation & Upgrade
<b>Symptom:</b>	Very rarely Management Module may fail to come up and enter into rolling reboot with Kernel Panic		
<b>Condition:</b>	Observed during bring up of new Chassis		

<b>Parent Defect ID:</b>	SLXOS-37572	<b>Issue ID:</b>	SLXOS-48093
<b>Severity:</b>	S1 - Critical		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	MPLS
<b>Reported in Release:</b>	SLXOS 18r.2.00	<b>Technology:</b>	IP over MPLS
<b>Symptom:</b>	After an MPLS RSVP LSP fails over to bypass, an MPLS ping initiated for the LSP causes unexpected reload of MPLS daemon		
<b>Condition:</b>	Issue will be seen only when the FRR failover happens for an RSVP LSP. Prior to failover, in protected path, MPLS ping works fine.		
<b>Workaround:</b>	No		

<b>Parent Defect ID:</b>	SLXOS-48501	<b>Issue ID:</b>	SLXOS-48502
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Security

<b>Reported in Release:</b>	SLXOS 17r.1.00a	<b>Technology:</b>	ACLs - Access Control Lists
<b>Symptom:</b>	May traffic gets permitted with hard-drop L2 ACL configured.		
<b>Condition:</b>	During configuration of log option in addition to hard-drop L2 ACL		

<b>Parent Defect ID:</b>	SLXOS-49209	<b>Issue ID:</b>	SLXOS-49210
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Monitoring
<b>Reported in Release:</b>	SLXOS 18r.1.00ch	<b>Technology:</b>	Hardware Monitoring
<b>Symptom:</b>	May observe following message in RASLOG for 1G SFP Optics like below:- "Optic inserted... is not compatible and laser is disabled"		
<b>Condition:</b>	Observed after Reload with speed configured as 1000		

<b>Parent Defect ID:</b>	SLXOS-49230	<b>Issue ID:</b>	SLXOS-49231
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	IP Multicast
<b>Reported in Release:</b>	SLXOS 18r.1.00db	<b>Technology:</b>	IGMP - Internet Group Management Protocol
<b>Symptom:</b>	Management Module may unexpectedly reload in NSM daemon		
<b>Condition:</b>	While processing high rate of IGMP join and leave messages		
<b>Workaround:</b>	None		

<b>Parent Defect ID:</b>	SLXOS-49149	<b>Issue ID:</b>	SLXOS-50007
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Security
<b>Reported in Release:</b>	SLXOS 20.1.2	<b>Technology:</b>	User Accounts & Passwords
<b>Symptom:</b>	Admin user can get the root privileges		
<b>Condition:</b>	when user try to use start-shell, python, OSCMD from admin login		

## Defects closed in 18r.1.00d

This section lists software defects with Critical, High, and Medium Technical Severity closed with and without a code change as of October 2019 in 18r.1.00d.

**Note: Parent Defect ID is the customer found Defect ID. The Issue ID is the tracking number uniquely used to check in the fix for each major release.**

<b>Parent Defect ID:</b>	SLXOS-39952	<b>Issue ID:</b>	SLXOS-39952
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Management
<b>Reported in Release:</b>	SLXOS 18r.1.00c	<b>Technology:</b>	SNMP - Simple Network Management Protocol
<b>Symptom:</b>	SNMP config fails when it tries to map the community-map to context.		
<b>Condition:</b>	When used CLI "snmp-server mib community-map <map-name> context <context-name>"		

<b>Parent Defect ID:</b>	SLXOS-22414	<b>Issue ID:</b>	SLXOS-41496
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Security
<b>Reported in Release:</b>	SLXOS 18r.2.00	<b>Technology:</b>	User Accounts & Passwords
<b>Symptom:</b>	Unexpected reload		
<b>Condition:</b>	When REST query is send with username same as role name		

<b>Parent Defect ID:</b>	SLXOS-40610	<b>Issue ID:</b>	SLXOS-41804
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Management
<b>Reported in Release:</b>	SLXOS 18r.1.00b	<b>Technology:</b>	SNMP - Simple Network Management Protocol
<b>Symptom:</b>	SNMP walk output is not showing for OID 1.3.6.1.4.1.1588.2.1.2.1.7.1.1 for active MM index on 18r.1 release, but works on 17r.2x and 18r.2x.		
<b>Condition:</b>	When SNMP query is hit for OID 1.3.6.1.4.1.1588.2.1.2.1.7.1.1 the output doesn't contain result for active MM index.		



<b>Parent Defect ID:</b>	SLXOS-39522	<b>Issue ID:</b>	SLXOS-41962
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	IP Multicast
<b>Reported in Release:</b>	SLXOS 18r.2.00	<b>Technology:</b>	PIM - Protocol-Independent Multicast
<b>Symptom:</b>	Unexpected reload		
<b>Condition:</b>	When PIM debug (ip pim packet )enable and shut/no shut on some interfaces		

<b>Parent Defect ID:</b>	SLXOS-41629	<b>Issue ID:</b>	SLXOS-41987
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Security
<b>Reported in Release:</b>	SLXOS 18r.1.00a	<b>Technology:</b>	User Accounts & Passwords
<b>Symptom:</b>	Unexpected reload		
<b>Condition:</b>	When REST query is send with username same as role name		

<b>Parent Defect ID:</b>	SLXOS-42310	<b>Issue ID:</b>	SLXOS-42472
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Layer 2 Switching
<b>Reported in Release:</b>	SLXOS 18r.2.00	<b>Technology:</b>	MCT - Multi-Chassis Trunking
<b>Symptom:</b>	Unexpected reload of device		
<b>Condition:</b>	When "cluster <>" config is done followed by 'undeploy' and peer IP change without SRC IP and then 'deploy'.		

<b>Parent Defect ID:</b>	SLXOS-39856	<b>Issue ID:</b>	SLXOS-42500
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Layer 3 Routing/Network Layer
<b>Reported in Release:</b>	SLXOS 18r.1.00a	<b>Technology:</b>	Static Routing (IPv4)
<b>Symptom:</b>	Route is not withdrawn on interface shut post HA failover		
<b>Condition:</b>	Ha failover performed and interface which is a next hop for the static route is shut		

<b>Parent Defect ID:</b>	SLXOS-42342	<b>Issue ID:</b>	SLXOS-42585
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Layer 3 Routing/Network Layer
<b>Reported in Release:</b>	SLXOS 18r.2.00a	<b>Technology:</b>	BGP4 - IPv4 Border Gateway Protocol
<b>Symptom:</b>	BGP peering may go down, when 'no router mpls' is issued, and when there are following routes under VRF: a) when learnt route is not selected b) when learnt route is re originated with network command		
<b>Condition:</b>	When learnt route is not selected or when learnt route is re-originated with 'network' command and when 'no router mpls' is issued.		
<b>Workaround:</b>	1) Shutdown BGP neighbors under VRF, remove network command. 2) Remove 'router mpls'. 3) Issue 'no shutdown' of BGP neighbors under VRF and add 'network' command.		

<b>Parent Defect ID:</b>	SLXOS-42673	<b>Issue ID:</b>	SLXOS-42676
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Layer 2 Switching
<b>Reported in Release:</b>	SLXOS 18x.1.00a	<b>Technology:</b>	MCT - Multi-Chassis Trunking
<b>Symptom:</b>	Unexpected reload		
<b>Condition:</b>	When the management cluster is down.		

<b>Parent Defect ID:</b>	SLXOS-42503	<b>Issue ID:</b>	SLXOS-42686
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Management
<b>Reported in Release:</b>	SLXOS 18r.1.00b	<b>Technology:</b>	Software Installation & Upgrade
<b>Symptom:</b>	1. Sysfpga image upgrading on SFM failed, sometimes. 2. FPGA image version checking and printing is too frequently.		
<b>Condition:</b>	SLX9850 platform		

<b>Parent Defect ID:</b>	SLXOS-42282	<b>Issue ID:</b>	SLXOS-42707
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Layer 3 Routing/Network Layer
<b>Reported in Release:</b>	SLXOS 17r.1.01_CVR	<b>Technology:</b>	ARP - Address Resolution Protocol

<b>Symptom:</b>	Intermittent ping loss between the hosts via MCT cluster node.
<b>Condition:</b>	When the MCT networks is seeing excessive MAC movement on the cluster node

<b>Parent Defect ID:</b>	SLXOS-42441	<b>Issue ID:</b>	SLXOS-42762
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Management
<b>Reported in Release:</b>	SLXOS 18r.2.00a	<b>Technology:</b>	CLI - Command Line Interface
<b>Symptom:</b>	"continue 100" under route-map does not persists after reload.		
<b>Condition:</b>	When "continue 100" is configured under route-map		

<b>Parent Defect ID:</b>	SLXOS-41226	<b>Issue ID:</b>	SLXOS-42782
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Traffic Management
<b>Reported in Release:</b>	SLXOS 18r.1.00aa	<b>Technology:</b>	QoS - Quality of Service
<b>Symptom:</b>	NetConf/REST response payload was returning with unsupported value 4. So that payload was not able to use for Netconf/REST request.		
<b>Condition:</b>	If Traffic-class to CoS mapping configured without DP value, Netconf/REST query returning with unsupported DP value 4. It fails in the Netconf/REST config with same payload.		
<b>Workaround:</b>	To make the same configuration through Netconf/REST, Make separate requests for each Dp values (0-3)		

<b>Parent Defect ID:</b>	SLXOS-42225	<b>Issue ID:</b>	SLXOS-42785
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Layer 3 Routing/Network Layer
<b>Reported in Release:</b>	SLXOS 18r.2.00	<b>Technology:</b>	BGP4 - IPv4 Border Gateway Protocol
<b>Symptom:</b>	Unexpected reload of the device		
<b>Condition:</b>	When "no cluster <>" MCT config is executed		
<b>Workaround:</b>	None		

<b>Parent Defect ID:</b>	SLXOS-42728	<b>Issue ID:</b>	SLXOS-42844
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Management
<b>Reported in Release:</b>	SLXOS 18r.1.00c	<b>Technology:</b>	CLI - Command Line Interface
<b>Symptom:</b>	"show vlan brief" and "show vlan <N>" display member interfaces in random order.		

<b>Condition:</b>	When we use the "show vlan brief" and "show vlan <N>" command in CLI.
-------------------	---

<b>Parent Defect ID:</b>	SLXOS-41137	<b>Issue ID:</b>	SLXOS-43000
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	MPLS
<b>Reported in Release:</b>	SLXOS 18r.1.00b	<b>Technology:</b>	LDP - Label Distribution Protocol
<b>Symptom:</b>	LDP session was stuck because of an incorrect state.		
<b>Condition:</b>	LDP sessions flapping and being re-established. This state made it seem that the expected connection had already been established; causing the new connection setup to fail.		

<b>Parent Defect ID:</b>	SLXOS-42874	<b>Issue ID:</b>	SLXOS-43181
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Layer 2 Switching
<b>Reported in Release:</b>	SLXOS 18r.1.00b	<b>Technology:</b>	VLAN - Virtual LAN
<b>Symptom:</b>	When traffic is flowing between two endpoint tracking enabled port , unauthenticated traffic is not dropped.		
<b>Condition:</b>	When traffic is flowing between two endpoint tracking enabled port.		

<b>Parent Defect ID:</b>	SLXOS-43195	<b>Issue ID:</b>	SLXOS-43299
<b>Severity:</b>	S1 - Critical		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Layer 2 Switching
<b>Reported in Release:</b>	SLXOS 18r.1.00c	<b>Technology:</b>	MCT - Multi-Chassis Trunking
<b>Symptom:</b>	Unexpected LC reload		
<b>Condition:</b>	When MCT MAC CCR to CCL conversion		
<b>Workaround:</b>	None		

<b>Parent Defect ID:</b>	SLXOS-42649	<b>Issue ID:</b>	SLXOS-43308
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Layer 2 Switching
<b>Reported in Release:</b>	SLXOS 17r.1.00	<b>Technology:</b>	VLAN - Virtual LAN
<b>Symptom:</b>	Vlan name is not properly displayed .It is a cosmetic issue.		
<b>Condition:</b>	When VLAN with no router interface configured .		

<b>Parent Defect ID:</b>	SLXOS-38488	<b>Issue ID:</b>	SLXOS-43448
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Layer 2 Switching
<b>Reported in Release:</b>	SLXOS 18r.1.00aa	<b>Technology:</b>	MCT - Multi-Chassis Trunking
<b>Symptom:</b>	MCT Convergence will take more time (around 26 sec)		

<b>Condition:</b>	One of the MCT pair goes down
-------------------	-------------------------------

<b>Parent Defect ID:</b>	SLXOS-42655	<b>Issue ID:</b>	SLXOS-43521
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Management
<b>Reported in Release:</b>	SLXOS 18r.2.00a	<b>Technology:</b>	CLI - Command Line Interface
<b>Symptom:</b>	The 'reload system' and 'firmware download' CLI's succeeds without confirming with 'Y/Yes' option.		
<b>Condition:</b>	When user hit ENTER without any input, the system proceeds to reboot and firmware download CLI's.		

## Defects closed in 18r.1.00c

This section lists software defects with Critical, High, and Medium Technical Severity closed with and without a code change as of **6/19/2019** in 18r.1.00c.

**Note: Parent Defect ID is the customer found Defect ID. The Issue ID is the tracking number uniquely used to check in the fix for each major release.**

<b>Parent Defect ID:</b>	SLXOS-22514	<b>Issue ID:</b>	SLXOS-30535
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Traffic Management
<b>Reported in Release:</b>	SLXOS 17r.1.01a	<b>Technology:</b>	Rate Limiting and Shaping
<b>Symptom:</b>	100G interfaces on SLX 9850 may not achieve line rate egress throughput.		
<b>Condition:</b>	On a L2VPN network 100G interfaces on SLX 9850 may not achieve line rate of egress through put.		
<b>Workaround:</b>	Augment performance with additional interfaces as required.		

<b>Parent Defect ID:</b>	SLXOS-37463	<b>Issue ID:</b>	SLXOS-37463
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Layer 3 Routing/Network Layer
<b>Reported in Release:</b>	SLXOS 18r.1.00a	<b>Technology:</b>	BGP4 - IPv4 Border Gateway Protocol
<b>Symptom:</b>	A warning is seen on console as follows. "No. of prefix received from BGP Peer 2000:31:1:8::153: exceeds warning limit 0"		
<b>Condition:</b>	When the maximum prefix config is at the IPv6 neighbor level and the ipv6 address-family activate cmd at the peer-group level and the device is reloaded with that saved config.		
<b>Workaround:</b>	Remove maximum prefix config at the neighbor and re-config.		

<b>Parent Defect ID:</b>	SLXOS-38394	<b>Issue ID:</b>	SLXOS-38394
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Security
<b>Reported in Release:</b>	SLXOS 18r.1.00b	<b>Technology:</b>	HTTP/HTTPS
<b>Symptom:</b>	Enabling or disabling HTTP(S) service on Virtual Routing and Forwarding(VRF) name other than management VRF("mgmt-vrf") may not succeed.		
<b>Condition:</b>	Enabling or disabling HTTP(S) service fails on chassis based devices		
<b>Workaround:</b>	None		

<b>Parent Defect ID:</b>	SLXOS-38406	<b>Issue ID:</b>	SLXOS-38406
--------------------------	-------------	------------------	-------------

<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Traffic Management
<b>Reported in Release:</b>	SLXOS 18r.1.00b	<b>Technology:</b>	Rate Limiting and Shaping
<b>Symptom:</b>	When egress Rate-limiter is applied on port-channel, and system is rebooted, then egress Rate-Limiter was not working.		
<b>Condition:</b>	When system was rebooted with Egress RL applied on port-channel		
<b>Workaround:</b>	After reboot, reapply egress RL.		

<b>Parent Defect ID:</b>	SLXOS-38447	<b>Issue ID:</b>	SLXOS-38447
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Layer 3 Routing/Network Layer
<b>Reported in Release:</b>	SLXOS 18r.1.00b	<b>Technology:</b>	BGP4 - IPv4 Border Gateway Protocol
<b>Symptom:</b>	L3VPN traffic may not be forwarded.		
<b>Condition:</b>	The VRFs are configured first in an order and then L3VPN config (route-target, route-distinguisher etc.) is done in a different order to those VRFs, so that the label allocation to VRFs does not happen in the order of creation of VRFs. Now if HA fail over is done, L3 VPN traffic may not be forwarded.		

<b>Parent Defect ID:</b>	SLXOS-27981	<b>Issue ID:</b>	SLXOS-38496
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Management
<b>Reported in Release:</b>	SLXOS 17r.1.01ah	<b>Technology:</b>	CLI - Command Line Interface
<b>Symptom:</b>	If user changes the startup config file to let management IP and default gateway in a different subnet from the management IP and default gateway that currently configured on SLX, and perform "copy tftp startup-config", then reload, SLX will keep the previously configured management IP and gateway after reload		
<b>Condition:</b>	User changes the startup config file to have management IP and gateway address in a different subset from the management IP and gateway that currently configured on SLX		
<b>Workaround:</b>	Before reload the system, remove the management IP and default gateway  from system using CLI		

<b>Parent Defect ID:</b>	SLXOS-20017	<b>Issue ID:</b>	SLXOS-38877
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Management
<b>Reported in Release:</b>	SLXOS 17r.1.00a	<b>Technology:</b>	SNMP - Simple Network Management Protocol
<b>Symptom:</b>	Unexpected behavior with SLX		
<b>Condition:</b>	While trying to write port alias using SNMP application.		
<b>Workaround:</b>	None		

<b>Parent Defect ID:</b>	SLXOS-38980	<b>Issue ID:</b>	SLXOS-38980
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Management
<b>Reported in Release:</b>	SLXOS 18r.1.00b	<b>Technology:</b>	SNMP - Simple Network Management Protocol
<b>Symptom:</b>	Snmp daemon terminates and restarts on HA failover.		
<b>Condition:</b>	Occurs only when there is an SNMP host configured with source-interface as management mm-ip.		
<b>Workaround:</b>	Keep source-interface configuration as default		

<b>Parent Defect ID:</b>	SLXOS-38299	<b>Issue ID:</b>	SLXOS-39007
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Other
<b>Reported in Release:</b>	SLXOS 18x.1.00a	<b>Technology:</b>	Other
<b>Symptom:</b>	Sometimes, a panic dump may be seen while rebooting the setup.		
<b>Condition:</b>	This is a rare condition which may be seen while device is rebooting or when sending high rate traffic to CPU.		
<b>Workaround:</b>	N/A		

<b>Parent Defect ID:</b>	SLXOS-39185	<b>Issue ID:</b>	SLXOS-39185
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Traffic Management
<b>Reported in Release:</b>	SLXOS 18r.1.00b	<b>Technology:</b>	Rate Limiting and Shaping
<b>Symptom:</b>	rate limiting clear command is not working		
<b>Condition:</b>	execute show command and clear command, data still shows even after clear command		

<b>Parent Defect ID:</b>	SLXOS-39214	<b>Issue ID:</b>	SLXOS-39214
--------------------------	-------------	------------------	-------------



<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	MPLS
<b>Reported in Release:</b>	SLXOS 18r.1.00b	<b>Technology:</b>	LDP - Label Distribution Protocol
<b>Symptom:</b>	LDP sessions stay down despite ping functioning between the peers.		
<b>Condition:</b>	socket supporting LDP session is terminated by HA failover or route change. Note that the problem very rarely happens.		

<b>Parent Defect ID:</b>	SLXOS-39319	<b>Issue ID:</b>	SLXOS-39319
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Other
<b>Reported in Release:</b>	SLXOS 18r.1.00c	<b>Technology:</b>	Other
<b>Symptom:</b>	On the serial console, user observes output overwritten and becoming unreadable.		
<b>Condition:</b>	On the serial console, user changes window size and observe output overwritten and becoming unreadable.		

<b>Parent Defect ID:</b>	SLXOS-39220	<b>Issue ID:</b>	SLXOS-39349
<b>Severity:</b>	S1 - Critical		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Management
<b>Reported in Release:</b>	SLXOS 18s.1.01a	<b>Technology:</b>	SNMP - Simple Network Management Protocol
<b>Symptom:</b>	LLDP-MIB::lldpLocPortId value is not correct (appears corrupted) when queried via SNMP GET operation.		
<b>Condition:</b>	Issue occurs only for SNMP GET operation (on LLDP-MIB::lldpLocPortId). SNMP GET-NEXT and snmpwalk returns correct values.		
<b>Workaround:</b>	<ol style="list-style-type: none"> <li>1. Use SNMP GET-NEXT or snmpwalk instead of SNMP GET when querying LLDP-MIB::lldpLocPortId via SNMP.</li> <li>2. Use CLI to query (LLDP-MIB::lldpLocPortId) instead of SNMP, if it's feasible.</li> </ol>		

<b>Parent Defect ID:</b>	SLXOS-38901	<b>Issue ID:</b>	SLXOS-39427
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Network Automation and Orchestration
<b>Reported in Release:</b>	SLXOS 18r.1.00aa	<b>Technology:</b>	NETCONF - Network Configuration Protocol
<b>Symptom:</b>	Seeing error while using rpc to get port channel config.		
<b>Condition:</b>	If Insight enable mmlid 1 command is enabled.		

<b>Parent Defect ID:</b>	SLXOS-39445	<b>Issue ID:</b>	SLXOS-39445
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Security
<b>Reported in Release:</b>	SLXOS 18r.1.00c	<b>Technology:</b>	TACACS & TACACS+
<b>Symptom:</b>	DCM daemon termination will be observed while executing any CLI		
<b>Condition:</b>	When AAA Command Authorization is enabled and the configured tacacs+ server are not reachable.		
<b>Workaround:</b>	Make the configured Tacacs+ server reachable.		

<b>Parent Defect ID:</b>	SLXOS-38336	<b>Issue ID:</b>	SLXOS-39626
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Management
<b>Reported in Release:</b>	SLXOS 18x.1.00a	<b>Technology:</b>	CLI - Command Line Interface
<b>Symptom:</b>	Overlay-gateway configuration doesn't show up in running-config.		
<b>Condition:</b>	Overlay-gateway configuration doesn't show up in running-config after firmware upgrade with ZTP (Zero touch provisioning),		
<b>Workaround:</b>	none		

<b>Parent Defect ID:</b>	SLXOS-38493	<b>Issue ID:</b>	SLXOS-39702
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Other
<b>Reported in Release:</b>	SLXOS 18r.1.00aa	<b>Technology:</b>	Other
<b>Symptom:</b>	file transfer may be affected if destination port is udp 646 and pkt has fragment offset.		
<b>Condition:</b>	During file transfer if destination port is udp 646 between source and destination without "mpls ldp" being enabled on the box. UDP packet with destination port 646 is trapped to cpu even without mpls being enabled on the box.		

<b>Parent Defect ID:</b>	SLXOS-34817	<b>Issue ID:</b>	SLXOS-39748
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Layer 2 Switching
<b>Reported in Release:</b>	SLXOS 18r.2.00	<b>Technology:</b>	VRP - VLAN Registration Protocol
<b>Symptom:</b>	User will observe that the REST API response for mvrp interface related operational GET command fetches the value from the global bucket for non-MVRP interfaces.		
<b>Condition:</b>	Issue was seen only when trying to fetch MVRP information using REST API infrastructure for interfaces where MVRP was not configured.		
<b>Workaround:</b>	No		

<b>Parent Defect ID:</b>	SLXOS-39783	<b>Issue ID:</b>	SLXOS-39784
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Monitoring
<b>Reported in Release:</b>	SLXOS 18r.1.00a	<b>Technology:</b>	OAM - Operations, Admin & Maintenance
<b>Symptom:</b>	nf_contrack feature in Linux kernel track all IP packets coming to CPU. It can cause nf_contrack table full issue & fragmented packet drop issue.		
<b>Condition:</b>	There is no specific condition trigger this, by default the service is up and running.		

<b>Parent Defect ID:</b>	SLXOS-29369	<b>Issue ID:</b>	SLXOS-39838
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Monitoring
<b>Reported in Release:</b>	SLXOS 18r.2.00	<b>Technology:</b>	Port Mirroring
<b>Symptom:</b>	MTU of a destination mirror port may be a non-default MTU.		
<b>Condition:</b>	1. When Global MTU is configured on the device, 2. A port is configured as a destination-mirror port		

<b>Parent Defect ID:</b>	SLXOS-25731	<b>Issue ID:</b>	SLXOS-39974
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Layer 2 Switching
<b>Reported in Release:</b>	SLXOS 17s.1.02b	<b>Technology:</b>	MCT - Multi-Chassis Trunking
<b>Symptom:</b>	MCT daemon termination followed by switch reload		
<b>Condition:</b>	MCT daemon terminates when client server sends the LACP oper key as 0.		
<b>Workaround:</b>	Remove 'esi auto lacp' config		

<b>Parent Defect ID:</b>	SLXOS-39618	<b>Issue ID:</b>	SLXOS-40059
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	MPLS
<b>Reported in Release:</b>	SLXOS 18r.1.00aa	<b>Technology:</b>	MPLS VPLS - Virtual Private LAN Services
<b>Symptom:</b>	Peers MPLS interface VE MAC learned as remote VPLS mac.		
<b>Condition:</b>	Issue seen in egress PE node, when receiving VPLS packet has inner payload DA MAC as 0100.5e00.xxxx		

<b>Parent Defect ID:</b>	SLXOS-40076	<b>Issue ID:</b>	SLXOS-40076
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	SDN
<b>Reported in Release:</b>	SLXOS 18r.1.00c	<b>Technology:</b>	OpenFlow
<b>Symptom:</b>	Openflow flows are not pushed in Openflow profile 3 (Tcam profile)		
<b>Condition:</b>	Issue will be seen in openflow-profile-3 tcam while pushing openflow flows		

<b>Parent Defect ID:</b>	SLXOS-40143	<b>Issue ID:</b>	SLXOS-40143
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Security
<b>Reported in Release:</b>	SLXOS 18r.1.00c	<b>Technology:</b>	RADIUS
<b>Symptom:</b>	On console following error message will be seen - "Dcmd[3617]: pam_radius_auth: Could not open configuration file /etc/raddb/server: No such file or directory"		
<b>Condition:</b>	When REST/RESTCONF query is given		

<b>Parent Defect ID:</b>	SLXOS-40087	<b>Issue ID:</b>	SLXOS-40367
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Management
<b>Reported in Release:</b>	SLXOS 18r.2.00	<b>Technology:</b>	High Availability
<b>Symptom:</b>	hasmd hang which was killed by SWD and switch reloaded in external login attach.		
<b>Condition:</b>	the issue may happen in brutal force login attack.		
<b>Workaround:</b>	None		

<b>Parent Defect ID:</b>	SLXOS-24384	<b>Issue ID:</b>	SLXOS-40383
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Management
<b>Reported in Release:</b>	SLXOS 17r.2.01	<b>Technology:</b>	CLI - Command Line Interface
<b>Symptom:</b>	ha chassisreboot command from ha inline help is not needed.		
<b>Condition:</b>	ha chassisreboot should have been obsoleted.		
<b>Workaround:</b>	Please use reload system command.		

<b>Parent Defect ID:</b>	SLXOS-24114	<b>Issue ID:</b>	SLXOS-40435
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Monitoring
<b>Reported in Release:</b>	SLXOS 17r.2.00	<b>Technology:</b>	OAM - Operations, Admin & Maintenance
<b>Symptom:</b>	After the devices boots up, the user will see the dcmd.sh, ccmd.sh, and netstat defunct processes.		
<b>Condition:</b>	The defunct processes will show up when the user runs the "ps aux" command.		
<b>Workaround:</b>	None. They are not harmful and so the user can just ignore them.		

<b>Parent Defect ID:</b>	SLXOS-39058	<b>Issue ID:</b>	SLXOS-40466
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Other
<b>Reported in Release:</b>	SLXOS 18r.1.00a	<b>Technology:</b>	Other
<b>Symptom:</b>	Switch reloaded with panic dump, impacting the data traffic forwarding.		
<b>Condition:</b>	High rate of software assisted layer 3 forwarding of traffic, causing connection tracking table to fill up.		
<b>Workaround:</b>	NA		

<b>Parent Defect ID:</b>	SLXOS-40476	<b>Issue ID:</b>	SLXOS-40477
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Management
<b>Reported in Release:</b>	SLXOS 18r.2.00	<b>Technology:</b>	High Availability
<b>Symptom:</b>	During DOS attacks, flood of disable pam_unix log messages are seen on console		
<b>Condition:</b>	DOS attacks on system		
<b>Workaround:</b>	Configure syslog server to redirect these messages		

<b>Parent Defect ID:</b>	SLXOS-38229	<b>Issue ID:</b>	SLXOS-40484
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Management
<b>Reported in Release:</b>	SLXOS 18r.1.00ab	<b>Technology:</b>	LLDP - Link Layer Discovery Protocol
<b>Symptom:</b>	NOS CLI "show lldp neighbors" command failed to fetch the neighbor details.		
<b>Condition:</b>	LLDP must be configured on the SLX device.		
<b>Workaround:</b>	CMSGH "show lldp neighbors" command can be used to fetch the LLDP neighbor details		

<b>Parent Defect ID:</b>	SLXOS-38762	<b>Issue ID:</b>	SLXOS-40532
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Other
<b>Reported in Release:</b>	SLXOS 18r.1.00aa	<b>Technology:</b>	Other
<b>Symptom:</b>	JSON output of REST bridge-domain config has duplicated URN part way through the output.		
<b>Condition:</b>	For vlans configured more than 100, REST bridge-domain config has duplicated URN part way through the output.		
<b>Workaround:</b>	No		

<b>Parent Defect ID:</b>	SLXOS-40884	<b>Issue ID:</b>	SLXOS-40884
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Management
<b>Reported in Release:</b>	SLXOS 18r.1.00c	<b>Technology:</b>	Software Installation & Upgrade
<b>Symptom:</b>	Firmwaredownload may fail with dpkg confd error messages on console.		
<b>Condition:</b>	While upgrade/downgrade using normal firmwaredownload /fullinstall.		

<b>Parent Defect ID:</b>	SLXOS-39462	<b>Issue ID:</b>	SLXOS-40929
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Layer 2 Switching
<b>Reported in Release:</b>	SLXOS 18r.1.00ac	<b>Technology:</b>	MCT - Multi-Chassis Trunking
<b>Symptom:</b>	MAC is not being updated with the new ifindex on the remote LC.		
<b>Condition:</b>	MAC move from one client interface to another client interface when same mac changes from CCR to CCL at the same time on remote LC.		

<b>Parent Defect ID:</b>	SLXOS-40994	<b>Issue ID:</b>	SLXOS-40994
<b>Severity:</b>	S2 - High		

<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Other
<b>Reported in Release:</b>	SLXOS 18r.1.00c	<b>Technology:</b>	Other
<b>Symptom:</b>	/var/run directory not present at bootup so /var/run/racoon2 was not created.		
<b>Condition:</b>	/var/run and /var/run/racoon2 should be present at bootup time		
<b>Workaround:</b>	add mkdir /var/run and -p option for create /var/run/racoon2 in sysinit script		

<b>Parent Defect ID:</b>	SLXOS-39963	<b>Issue ID:</b>	SLXOS-41019
<b>Severity:</b>	S3 - Medium		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Monitoring
<b>Reported in Release:</b>	SLXOS 18r.1.00b	<b>Technology:</b>	sFlow
<b>Symptom:</b>	SFLOW controller failed to capture few flows on bi-directional traffic.		
<b>Condition:</b>	SFLOW configuration enabled on interface.		

<b>Parent Defect ID:</b>	SLXOS-39538	<b>Issue ID:</b>	SLXOS-41117
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Security
<b>Reported in Release:</b>	SLXOS 18r.1.00aa	<b>Technology:</b>	AAA - Authentication, Authorization, and Accounting
<b>Symptom:</b>	Unexpected reload		
<b>Condition:</b>	When TACACS authorization fails on re-try		
<b>Workaround:</b>	Make sure we have the proper network connectivity to avoid TACACS authorization fails at first attempt.		

<b>Parent Defect ID:</b>	SLXOS-41166	<b>Issue ID:</b>	SLXOS-41168
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Management
<b>Reported in Release:</b>	SLXOS 18r.1.00b	<b>Technology:</b>	CLI - Command Line Interface
<b>Symptom:</b>	Unexpected reload of the device.		
<b>Condition:</b>	Protocol lldp has dot1-tlv/dot3-tlv config and when "show lldp neighbors detail" command is issued.		
<b>Workaround:</b>	None		

<b>Parent Defect ID:</b>	SLXOS-40759	<b>Issue ID:</b>	SLXOS-41327
<b>Severity:</b>	S1 - Critical		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	MPLS
<b>Reported in Release:</b>	SLXOS 18r.1.00aa	<b>Technology:</b>	MPLS VPLS - Virtual Private LAN Services
<b>Symptom:</b>	Not able to program MPLS tunnel		
<b>Condition:s</b>	Power-off/on line card on PE routers		

<b>Parent Defect ID:</b>	SLXOS-40826	<b>Issue ID:</b>	SLXOS-41816
<b>Severity:</b>	S2 - High		
<b>Product:</b>	SLX-OS	<b>Technology Group:</b>	Other
<b>Reported in Release:</b>	SLXOS 18r.1.00aa	<b>Technology:</b>	Other
<b>Symptom:</b>	SLX device experience unexpected sudden reload.		
<b>Condition:</b>	FWD daemon termination cause the sudden reload.		