# Nortel VPN Router
## Software Release V4_85.211

## 1. Release Summary

Release Date:   September 29, 2005
Purpose:        Software Maintenance release to address customer-found software issues.

## 2. Important Notes Before Upgrading to This Release

None

## 3. Platforms Supported

Nortel VPN Router (formerly known as Contivity Secure IP Services Gateway) Software Release V04.85.211 supports the following hardware platforms:

   600
1010
1050
1100
1600
1700
1740
2600
2700
4500
4600
5000

## 4. Notes for Upgrade

For details on how to upgrade your Nortel VPN Router (formerly known as Contivity Secure IP Services Gateway), see the *Contivity Secure IP Services Gateway Release Notes* (part no. 315000-E Rev 02). Release notes are available at http://www.nortel.com/support; select Contivity product family, then select VPN Router Portfolio, and then select Documentation and click Go.

## 5. Version of Previous Release

Software Version 4.85.208

## 6. Compatibility

None

## 7. Changes in This Release

**New Features in This Release**
None

**Old Features Removed From This Release**
None

**Problems Resolved in This Release**

Nortel Networks* Contivity* Secure IP Services Gateway sustaining release Version 4.85.211 resolves the following issues:

Q00751763 –
Closing the Java Applet after configuring VPN Router Firewall policies may cause task errors to be displayed, resulting in the policy being lost.

Q01060824 –
The Nortel VPN Router may core during the processing of an authentication packet through the Hardware Accelerator module if the authentication packet verification fails and the hardware simultaneously reports a non-fatal memory transfer (DMA) error.

Q01076568 –
When a Nortel VPN Router receives fragments with both MF and DF bits set and the Statefull Firewall or Interface Filters is enabled, an "ICMP destination unreachable: fragmentation needed" message may be returned to the caller if the reassembly of the fragments prevents the packet from being forwarded out another interface.

Q01172417 – A recent security vulnerability fix (CR Q01117695) caused an incompatibility with the Nortel VPN Client and the processing of IKE keepalive messages.

## 8. Outstanding Issues

None

## 9. Known Limitations

None

## 10. Documentation Corrections

None

For other known issues, please refer to the product release notes and technical documentation available from the Nortel Technical Support web site at: http://www.nortel.com/support.