

# Virtual Services Platform 4000 Software Release 4.0.0.1

## 1. Release Summary

Release Date: September 2014

Purpose: Service Pack with corrected content to provide product update.

## 2. Important Notes before Upgrading to This Release

None.

## 3. Platforms Supported

Virtual Services Platform VSP 4850GTS

Virtual Services Platform VSP 4850GTS-PWR+

Virtual Services Platform VSP 4450GSX-PWR+

## 4. Special Instructions for Upgrade from previous releases

None.

## 5. Notes for Upgrade

Please see “*Virtual Services Platform 4000, Release Notes*” for software release 4.0 (NN46251-401, 04.05) available at <http://www.avaya.com/support> for details on how to upgrade your Switch.

### File Names For This Release

File Name	Module or File Type	File Size (bytes)
VSP4K.4.0.0.1.tgz	Release 4.0.0.1 archived software distribution	173311262
VSP4K.4.0.0.1_modules.tgz	Release 4.0.0.1 Encryption Modules	79455

### **Note about image download:**

Ensure images are downloaded using the binary file transfer.

Check that the file type suffix is “.tgz” and the image names after download to device match those shown in the above table. Some download utilities have been observed to append “.tar” to the file name or change the filename extension from “.tgz” to “.tar”. If file type suffix is “.tar” or file name does not exactly

match the names shown in above table, rename the downloaded file to the name shown in the table above so that the activation procedures will operate properly.

**Load activation procedure:**

```
software add VSP4K.4.0.0.1.tgz
software add-modules 4.0.0.1.GA VSP4K.4.0.0.1_modules.tgz
software activate 4.0.0.1.GA
```

**6. Version of Previous Release**

Software Version 3.0, 3.0.1, 3.1, 3.1.0.2, 3.1.0.3 for VSP 4850GTS platforms and Software version 4.0 for VSP 4450GSX platform

**7. Changes in 4.0.0.1**

**New Features in This Release**

No new features in this release

**Old Features Removed From This Release**

No features removed from this release.

**Problems Resolved in This Release**

ID	Description
wi01184683	Switch incorrectly thinks it "owns" 1024 MAC Address Entries.
wi0118756	Request to Suppress SNMP Community Strings Displayed in Log File
wi01176543	VRRP Backup-Master/Unable to ping VRRP IP from device device connected to VRRP Backu
wi01188394	Malformed DHCP INFORM packet with missing END option causes memory leak

**8. Outstanding Issues**

No new issues are outstanding based on this service pack release. For prior outstanding issues, Please see the "Virtual Services Platform 4000, Release Notes release 4.0 (NN46251-401, 04.05) available at <http://www.avaya.com/support> for details regarding Known Issues.

**9. Documentation Corrections**

For other known issues, please refer to the product release notes and technical documentation available from the Avaya Technical Support web site at: <http://www.avaya.com/support> .

---

Copyright © 2014 Avaya Inc - All Rights Reserved.

The information in this document is subject to change without notice. The statements, configurations, technical data, and recommendations in this document are believed to be accurate and reliable, but are presented without express or implied warranty. Users must take full responsibility for their applications of any products specified in this document. The information in this document is proprietary to Avaya.

To access more technical documentation, search our knowledge base, or open a service request online, please visit Avaya Technical Support on the web at: <http://www.avaya.com/support>