

Customer Release Notes

Ethernet Routing Switch 3600 Series

Software Release 6.5.1

July 2021

INTRODUCTION:

This document provides specific information for version 6.5.1 of agent software for the Ethernet Routing Switch 3600 (All models).

The purpose of this version is to address customer and internally found software issues.

Extreme Networks recommends that you thoroughly review this document prior to installing or upgrading this product.

For the latest firmware versions, visit the download site at:
www.extremenetworks.com/support/

IMPORTANT NOTES BEFORE UPGRADING TO THIS RELEASE

None.

PLATFORMS SUPPORTED

Ethernet Routing Switch 3600 (All models)

NOTES FOR UPGRADE

Please see “Configuring Systems on Ethernet Routing Switch 3600 Series”, NN47213–506 available at https://documentation.extremenetworks.com/ERS_Series/ERS3600

FILE NAMES FOR THIS RELEASE

File Name	Module or File Type	File Size (bytes)
3600_6100_diags.bin	Diagnostic software	7,096,948
ers3600_651011s.img	SSH runtime image	16,446,776
ers3600v630_HELP_EDM.zip	EDM Help file zip	1,678,595
Ethernet_Routing_Switch_36xx_MIBs_6.5.0.zip	MIB definition files	1,660,031

VERSION OF PREVIOUS RELEASE

Software Version 6.5.0

COMPATIBILITY

This software release is managed with Enterprise Device Manager (EDM) which is integrated into the agent software.

CHANGES IN THIS RELEASE

New Features in This Release

None.

Old Features Removed From This Release

None.

Problems Resolved in This Release

ID	Description
ERS3600-918	10G SFP+ (AA1403043-E6) show as 1000BaseT in #show tech
ERS3600-920	10gig ports does not come up using 10306 DAC
ERS3600-921	FA Proxy agent is not updating FA Server OS version after upgrade of FA Server
ERS3600-923	ZTP+: Continuous memory leak when device is left in ZTP+ Pending Edit state
ERS3600-925	"STP_NVCFG_VLAN_STPGID parameter error, vldx = 4094" Message Continuously Scrolls On Console
ERS3600-926	A DAE may be encountered in tCliNum6 when a high number of traps are sent continuously to a trap receiver.
ERS3600-927	EDM: error when editing multiple ports from Device view - TypeError: timeStr is undefined
ERS3600-928	Logging sort-reverse does not show the current log on unit 1
CVE-2016-20009	Vulnerability found against VxWorks code For more information, please visit VN-2021-461 – "NAME:WRECK" (CVE-2016-20009)

KNOWN LIMITATIONS:

None.

DOCUMENTATION CORRECTIONS

None.

For other known issues, please refer to the product release notes and technical documentation available from the Extreme Networks support web site at: www.extremenetworks.com/support/

TROUBLESHOOTING

As good practices of help for troubleshooting various issues, Extreme Networks recommends:

- configuring the device to use the Simple Network Time Protocol to synchronize the device clock;
- setting a remote logging server to capture all level logs, including informational ones. (#logging remote level informational).
- enabling timestamps on all `show` commands using the `cli timestamp enable` command

GLOBAL SUPPORT:

By Phone: +1 800-998-2408 (toll-free in U.S. and Canada)

For the toll-free support number in your country:
www.extremenetworks.com/support/

By Email: support@extremenetworks.com

By Web: www.extremenetworks.com/support/

By Mail: Extreme Networks, Inc.
6480 Via Del Oro
San Jose, CA 95119

For information regarding the latest software available, recent release note revisions, or if you require additional assistance, please visit the Extreme Networks Support website.

Copyright © 2021 Extreme Networks, Inc. - All Rights Reserved.

Legal Notice

Extreme Networks, Inc. reserves the right to make changes in specifications and other information contained in this document and its website without prior notice. The reader should in all cases consult representatives of Extreme Networks to determine whether any such changes have been made.

The hardware, firmware, software or any specifications described or referred to in this document are subject to change without notice.

Trademarks

Extreme Networks and the Extreme Networks logo are trademarks or registered trademarks of Extreme Networks, Inc. in the United States and/or other countries. All other names (including any product names) mentioned in this document are the property of their respective owners and may be trademarks or registered trademarks of their respective companies/owners.

For additional information on Extreme Networks trademarks, please see:

www.extremenetworks.com/company/legal/trademarks