



# ExtremeSwitching™

## Read Me—Important Note on the VSP 8600 6.1 Software Mismatch Errors

Release 6.1  
9035374  
February 2018

### Software version mismatch generates warning messages when installing a new IOC module

When there is a mismatch between the software running on the switch and the software on the IOC module, the switch updates the IOC module to the version of software running on the switch. During this process you see errors that are similar to the following:

```
IO1 [12/06/17 11:50:43.513:UTC] 0x0024854b 00000000 GlobalRouter SF-APP WARNING
FabDrv_lc::mapLocalPortsToSysports dnxBcm_assignSysPortToModPort failed: unit=0 sysport=0
modId=40000 tmPort=1
IO1 [12/06/17 11:50:43.526:UTC] 0x0024854b 00000000 GlobalRouter SF-APP WARNING
FabDrv_lc::configIngressSideVOqs: UNKNOWN PORT TYPE OF 773 localPort = 1 modId = 6
IO7 [12/06/17 11:50:45.673:UTC] 0x0024854b 00000000 GlobalRouter SF-APP WARNING
FabDrv_lc::createVoqsForPort: dnxBcm_setPacketLengthAdjustForVoq failed: unit=0
voqBaseId=80000512 cos=4 PACKET_LENGTH_ADJUST=0
IO7 [12/06/17 11:50:45.688:UTC] 0x0024854b 00000000 GlobalRouter SF-APP WARNING
map_local_port_to_connectorPort: INVALID LOCAL PORT OF 10000000
```

The messages stop once the update of the IOC module software has completed. This has no impact on the switch operation.

**\* Note:**

This issue is specific to release 4.5.x and 6.1.x only.