

1. Release Summary

Release Date: 17-Sep-2004

Purpose: Software patch release to address customer reported software issues.

2. Important Notes Before Upgrading to This Release

3. Platforms Supported

BayStack 5510

4. Notes for Upgrade

Please see "Release Notes for the BayStack 5510 10/100/1000 Switch" available at <http://www.nortelnetworks.com/documentation>, select BayStack family, then BayStack 5510) for details on how to upgrade your Policy Switch.

5. Version of Previous Release

Software Version 4.0.1

6. Compatibility

This software release is managed with Java Device Manager (JDM) release 5.7.9.0.

7. Changes in This Release

New Features

None.

Old Features Removed

None.

Problems Resolved

When connecting a BayStack 5510 SX or LX GBIC to an OPTera Metro 5200 OCI card, the link would not come up (**Q00938336**).

Radius authentication was disabled in SSH versions of 4.0.0 and 4.0.1 (**Q00958850-01**).

In previous code versions, static ARP entries were deleted after the corresponding MAC addresses aged out (**Q00953766**).

A problem with static route entries (created by JDM) not saved after reboot is addressed in this release (**Q00927913**).

8. Known Issues

If ports are administratively disabled/enabled or if links are disconnected/reconnected, static ARP entries get erased (**Q00985108**). This issue will be resolved in the upcoming 4.1 release.

For other known issues, please refer to version 4.0.0 release notes from the Nortel Networks web site at: <http://www.nortelnetworks.com/documentation>.