

# **Ethernet Routing Switch 3500 Series**Software Release 5.2.2

# 1. Release Summary

Release Date: 22-December-2014

Purpose: Software patch release to address customer and internally found software issues.

## 2. Important Notes Before Upgrading to This Release

None.

# 3. Platforms Supported

Ethernet Routing Switch 3500 (All models).

# 4. Notes for Upgrade

Please see "Ethernet Routing Switch 3500 Series, Configuration – System, Software Release 5.2" (available at http://www.avaya.com/support. Click Products, select Ethernet Routing Switch 3500 Series from the A-Z list, then select Documentation > View All Documents) for details on how to upgrade your Switch.

#### **File Names for This Release**

File Name	Module or File Type	File Size (bytes)
3500_10015_diag.bin	Diagnostic image	2,095,505
3500_522002.img	Agent code image	8,528,500
3500_522003s.img	Agent code image (SSH)	8,770,868

## 5. Version of Previous Release

Software Version 5.2.1.

# 6. Compatibility

This software release is managed with Enterprise Device Manager (EDM) which is integrated into the agent software.

©2014 Avaya Inc. Rev: 01 (22-Dec-2014) Page 1 of 2



## 7. Changes in This Release

## 7.1. New Features in This Release

#### **QoS Configuration Using Traffic profile**

Please see "Ethernet Routing Switch Simplified QoS Configuration Using Traffic Profile Filter Sets Technical Configuration Guide" (Document Number: NN48500-624) for configuration guidelines.

#### 7.2 Old Features Removed From This Release

None.

#### 7.3 Problems Resolved in This Release

None.

### 8. Outstanding Issues

None.

### 9. Known Limitations

wi01202252 - No EDM support for QoS Traffic Profile

wi01202457 - QoS Traffic Profile: Not able to display statistics for a specific precedence

### 10. Documentation Corrections

None.

For other known issues, please refer to the product release notes and technical documentation available from the Avaya Technical Support web site at: http://www.avaya.com/support.

### 11. Troubleshooting

As good practices of help for troubleshooting various issues, AVAYA recommends:

- configuring the device to use the Simple Network Time Protocol to synchronize the device clock;
- setting a remote logging server to capture all level logs, including informational ones. (#logging remote level informational).

Copyright © 2014 Avaya Inc - All Rights Reserved.

The information in this document is subject to change without notice. The statements, configurations, technical data, and recommendations in this document are believed to be accurate and reliable, but are presented without express or implied warranty. Users must take full responsibility for their applications of any products specified in this document. The information in this document is proprietary to Avaya.

To access more technical documentation, search our knowledge base, or open a service request online, please visit Avaya Technical Support on the web at: <a href="http://www.avaya.com/support">http://www.avaya.com/support</a>.

©2014 Avaya Inc. Rev: 01 (22-Dec-2014) Page 2 of 2