

Ethernet Routing Switch 4500 Series Software Release 5.4.4

1. Release Summary

Release Date: 09-July-2012

Purpose: Software patch release to address customer and internally found software issues.

2. Important Notes Before Upgrading to This Release

None.

3. Platforms Supported

Ethernet Routing Switch 4500 (all models except ERS 4500-PWR+ and ERS 4800 which require minimum 5.6.0).

4. Notes for Upgrade

Please see “Ethernet Routing Switch 4500 Series, Configuration – System, Software Release 5.4” (available at <http://www.avaya.com/support> . Click Products, select Ethernet Routing Switch 4500 Series from the A-Z list, then select Documentation > View All Documents) for details on how to upgrade your Switch.

File Names for This Release

File Name	Module or File Type	File Size (bytes)
4500_5303_diag.bin	Diagnostic image	1,589,514
4500_544000.img	Agent code image	7,385,572
4500_544001s.img	Agent code image (SSH)	7,649,388

5. Version of Previous Release

Software Version 5.4.3.

6. Compatibility

This software release is managed with Enterprise Device Manager (EDM).

7. Changes in This Release

7.1. New Features in This Release

None.

7.2 Old Features Removed From This Release

None.

7.3 Problems Resolved in This Release

OSPF, Memory Leak: A Memory leak in the ipreAsm module has been fixed which could sometimes result in the switch sending out OSPF hello messages, which would then result in network reconvergence or outage. (wi01026552)

Boot default, MLT Configuration: When performing a “boot default” command, the MLT configuration will now be correctly set to default in all instances. (wi00939382)

VLAN Settings, Software Upgrade: VLAN settings are now correctly retained if upgrading or downgrading from release 5.4.4 to/from release 5.6.x. (wi00951333)

8. Outstanding Issues

None.

9. Known Limitations

None.

10. Documentation Corrections

For other known issues, please refer to the product release notes and technical documentation available from the Avaya Technical Support web site at: <http://www.avaya.com/support> .

Copyright © 2012 Avaya Inc - All Rights Reserved.

The information in this document is subject to change without notice. The statements, configurations, technical data, and recommendations in this document are believed to be accurate and reliable, but are presented without express or implied warranty. Users must take full responsibility for their applications of any products specified in this document. The information in this document is proprietary to Avaya.

To access more technical documentation, search our knowledge base, or open a service request online, please visit Avaya Technical Support on the web at: <http://www.avaya.com/support>.