

Customer Release Notes

Virtual Services Platform 8600 Series

Software Release 8.1.4.0 September 2023

INTRODUCTION:

This document provides specific information for version 8.1.4.0 of agent software for the VSP 8600.

The purpose of this version is to address customer and internally found software issues.

Extreme Networks recommends that you thoroughly review this document prior to installing or upgrading this product.

For the latest firmware versions, visit the download site at: www.extremenetworks.com/support/

IMPORTANT NOTES BEFORE UPGRADING TO THIS RELEASE:

A separate backup of the configuration file should be performed if a downgrade is carried out.

PLATFORMS SUPPORTED:

Virtual Services Platform VSP 8608

SPECIAL INSTRUCTIONS FOR UPGRADING FROM PREVIOUS RELEASES:

None.

NOTES FOR UPGRADE:

Please see "Release Notes for VSP 8600" for software release 8.1.0, available at <u>https://www.extremenetworks.com/support/release-notes</u> for details regarding Known Limitations.

| File Name | Module or File Type | File Size (bytes) |
|------------------------------|--|-------------------|
| VOSS8600.8.1.4.0.tgz | Release 8.1.4.0 archived software distribution | 184272172 |
| VOSS8600.8.1.4.0_mib.zip | Archive of all MIB files | 1156835 |
| VOSS8600.8.1.4.0_mib.txt | MIB file | 7668631 |
| VOSS8600.8.1.4.0_mib_sup.txt | MIB file | 1159472 |
| VOSS86v810_HELP_EDM_gzip.zip | EDM Help file | 5127813 |
| VOSS8600.8.1.4.0.md5 | MD5 Checksums | 426 |
| VOSS8600.8.1.4.0.sha512 | SHA512 Checksums | 1249 |

FILE NAMES FOR THIS RELEASE:

Note about image download:

Ensure images are downloaded using the binary file transfer. Perform MD5 checksum check on downloaded files to ensure file integrity.

Check that the file type suffix is ".tgz" and the image names after download to device match those shown in the above table. Some download utilities have been observed to append ".tar" to the file name or change the filename extension from ".tgz" to ".tar". If file type suffix is ".tar" or file name does not exactly match the names shown in above table, rename the downloaded file to the name shown in the table above so that the activation procedures will operate properly.

Load activation procedures:

```
software add VOSS8600.8.1.4.0.tgz
software activate VOSS8600.8.1.4.0.GA
```

COMPATIBILITY:

This software release is managed with Enterprise Device Manager (EDM), which is integrated into the agent software.

CHANGES IN THIS RELEASE:

New Features in This Release

None.

Old Features Removed From This Release None.

08/29/2023 P/N: 9037143-04 Rev. AA

| Problems Resolved in This Release | | | |
|-----------------------------------|--|--|--|
| ID | Description | | |
| VOSS-27776 | Instrumentation was added for a case where IGMP enabled VLAN interface sends the multicast traffic back to sender switch on SMLT interface and EXOS reports MAC flap between local port and uplink port. | | |
| VOSS-28380 | Packets larger than 1982 octets are being truncated down to 1982 | | |
| VOSS-28440 | After a new IO card is installed, the download operation of L3VSN routes could cause a traffic outage | | |
| VOSS-28666 | VSP8600 does not forward the first packet of the TCP segment | | |
| VOSS-28674 | Instrumentation was added for a case where an IO card loses connection to master and resets | | |
| VOSS-28764 | A VIST node stops forwarding MC stream to client while both multicast sender and group entries look fine | | |
| VOSS-29164 | Continuous ARP flapping across IST MLT ports | | |
| VOSS-29241 | Instrumentation was added for a case where slot 1 lost contact to other slots "Sending letter failed" | | |
| VOSS-29330 | If 8600 receives an Arp Request from a source whose IP address is the same as the 8600's configured VRRPv3 address, no Duplicate IP warning message appears | | |
| VOSS-29372 | VSP 8600 crashed when an invalid entry was used in IPMC code | | |

OUTSTANDING ISSUES:

Please see "Release Notes for VSP 8600" for software release 8.1.0 available at <u>https://www.extremenetworks.com/support/release-notes</u> for details regarding Known Issues.

KNOWN LIMITATIONS:

Please see "Release Notes for VSP 8600" for software release 8.1.0 available at <u>https://www.extremenetworks.com/support/release-notes</u> for details regarding Known Limitations.

| ID | Description | Workaround |
|------------|--|-------------------|
| VOSS-12399 | VSP8600 with LACP MLT ports configured as SMLT and no VIST | Fix configuration |
| | configured may cause LACP link state instability | error |
| VOSS-28681 | inVLAN ACL with pktType ipv6 does not match untagged traffic | None |

DOCUMENTATION CORRECTIONS:

For other known issues, please refer to the product release notes and technical documentation available at: <u>https://www.extremenetworks.com/support/documentation</u>.

GLOBAL SUPPORT

By Phone: +1 800-998-2408 (toll-free in U.S. and Canada)

For the toll-free support number in your country: www.extremenetworks.com/support/

- By Email: <u>support@extremenetworks.com</u>
- By Web: www.extremenetworks.com/support/
- By Mail: Extreme Networks, Inc. 6480 Via Del Oro San Jose, CA 95119

For information regarding the latest software available, recent release note revisions, or if you require additional assistance, please visit the Extreme Networks Support website.

Copyright © 2023 Extreme Networks, Inc. - All Rights Reserved.

Legal Notice

Extreme Networks, Inc. reserves the right to make changes in specifications and other information contained in this document and its website without prior notice. The reader should in all cases consult representatives of Extreme Networks to determine whether any such changes have been made.

The hardware, firmware, software or any specifications described or referred to in this document are subject to change without notice. Trademarks

Extreme Networks and the Extreme Networks logo are trademarks or registered trademarks of Extreme Networks, Inc. in the United States and/or other countries. All other names (including any product names) mentioned in this document are the property of their respective owners and may be trademarks or registered trademarks of their respective companies/owners. For additional information on Extreme Networks trademarks, please see:

www.extremenetworks.com/company/legal/trademarks