



Nortel VPN Router

Software Release V6_00.151

1. Release Summary

On September 23rd, 2005 Nortel released version 6_00.150 software for the VPN Router product family. This software was released to the Nortel support web site for customers to download. During post release performance and scaling testing for the purpose of generating the 6_00 Design Guideline document, an issue was discovered that Nortel deemed significant enough to pull the 6_00.150 software from the support site.

The issue discovered was related to the ability of the 6_00 software to run in an 802.1Q VLAN environment. If a VPN Router was configured to have greater than 8 VLANs on an interface, the VPN Router would fault as soon as traffic was passed through this interface. This issue is documented in CR Q01213204.

It should be noted that the other elements of the 6_00 release, client (6_01.14) and Contivity Tunnel Guard Agent 2.0.0.0.015, and ASA 5.0.1.1 are not effected by this issue. The versions of those applications posted on September 23rd remain valid.

Release Date: October 10, 2005

Version 6_00.151 addresses the issue mentioned above.

2. Important Notes Before Upgrading to This Release

None

3. Platforms Supported

Nortel VPN Router (formerly known as Contivity Secure IP Services Gateway) software release V06_00.151 supports the following hardware platforms

600
1010
1050
1100
1600
1700
1740
1750
2600
2700
4600
5000

4. Notes for Upgrade

For details on how to upgrade your Nortel VPN Router (formerly known as the Contivity Secure IP Services Gateway), see the *Contivity Secure IP Services Gateway Release Notes* (part no. 315000-J Rev 01). Release notes are available at <http://www.nortel.com/support>; select the Contivity product family, select VPN Router Portfolio, select Documentation, and click Go.

5. Version of Previous Release

Software Version 6.00.150

6. Compatibility

To take full advantage of this release, the following versions are recommended for the related products. This is only a recommendation; this release is compatible with all supported versions.

Contivity Client	6.01.014
Contivity Tunnel Guard Agent	2.0.0.0.015
ASA	5.0.1.1

7. Changes in This Release

Problems Resolved in This Release

Nortel Networks VPN Router sustaining release Version 6.00.151 resolves the following issues since Version 6.00.150:

Q01213204 – The VPN Router will core when running 8 or more VLANs configured on a port.

Copyright © 2005 Nortel Networks Limited - All Rights Reserved. Nortel, Nortel Networks, the Nortel logo, the Globemark, and Contivity are trademarks of Nortel Networks Limited.

The information in this document is subject to change without notice. The statements, configurations, technical data, and recommendations in this document are believed to be accurate and reliable, but are presented without express or implied warranty. Users must take full responsibility for their applications of any products specified in this document. The information in this document is proprietary to Nortel.

To access more technical documentation, search our knowledge base, or open a service request online, please visit Nortel Technical Support on the web at: <http://www.nortel.com/support>