



Nortel VPN Router

Software Patch V8_05.301

1. Patch Summary

Patch Date: September 13, 2010
Purpose: Software Maintenance Patch to address customer found software issues.

Note:

As of August 2010 Nortel VPN Router problems are no longer being reported using the Clarify tool, Clear Quest is now the tool being used. Issues are reported in Work Items (WI) not in Correction Reports (CR) as was done in Clarify. During this transition, for any issue originally reported in Clarify, the new WI number will be followed by the corresponding CR number for clarity.

2. Important Notes Before Upgrading to This Patch

None

3. Platforms Supported

Nortel VPN Router (formerly known as Contivity Secure IP Services Gateway) software Patch V08_05.301 supports the following hardware platforms

600
1010
1050
1100
1600
1700
1740
1750
2600
2700
2750
4600
5000

4. Notes for Upgrade

For details on how to upgrade your Nortel VPN Router (formerly known as the Contivity Secure IP Services Gateway), see the *Nortel VPN Router Release Notes* (NN46110-403 03.01, part no. 315000-U Rev 01. Release notes are available at <http://www.nortel.com/support>; select the Security & VPN product family, select VPN Router Portfolio, select Documentation and click Go.

5. Version of Previous Release

Software Version 8_05.300

6. Compatibility

In order to take full advantage of this Patch the following versions are recommended for the related products. This is only a recommendation; this Patch is compatible with all supported versions.

Nortel VPN Client	8.01.100
Nortel VPN Localized Client	6.02.040
Nortel VPN Client for Vista	6.07.027
Nortel Tunnel Guard Agent	4.5.0.0_014
Nortel VPN Gateway	6.0.1

NOTE: Nortel VPN Client version 5_01.103 and above is required to get the full benefit of Entrust Roaming Profiles and Entrust Link Certificates.

7. Changes in This Patch

New Features in This Patch

None

Old Features Removed From This Patch

None

Problems Resolved in This Patch

Nortel Networks VPN Router sustaining Patch Version 8.05.301 resolves the following issues:

wi00653605 (Q02153777) –

The Nortel VPN Router may not remove all references to a locally configured default route when instructed to do so if there is a reference to that route in the OSPF link state database as well.

8. Outstanding Issues

9. Known Limitations

When QOS Classifiers are configured on GUI page (QOS->Classifiers) or using CLI Commands "qos mf-class XXX":

1. A classifier or rule name containing the "?" character cannot be configured using the CLI; it must be configured from the GUI.
2. The backslash cannot be used as part of a classifier or rule name.
3. If you create a rule or classifier name, the "show running config" command will display the rule or name within double quotes.

9. Documentation Corrections

None

For known issues, please refer to the product release notes and technical documentation available from the Nortel Technical Support web site at: <http://www.nortel.com/support>.

Copyright © 2010 Nortel Networks Limited - All Rights Reserved. Nortel, Nortel Networks, the Nortel logo, the Globemark, and Contivity are trademarks of Nortel Networks Limited.

The information in this document is subject to change without notice. The statements, configurations, technical data, and recommendations in this document are believed to be accurate and reliable, but are presented without express or implied warranty. Users must take full responsibility for their applications of any products specified in this document. The information in this document is proprietary to Nortel.

To access more technical documentation, search our knowledge base, or open a service request online, please visit Nortel Technical Support on the web at: <http://www.nortel.com/support>