1. Release Summary

Release Date: 10-Dec-2004
Purpose: Software patch release to address customer found software issues.

2. Important Notes Before Upgrading to This Release

None.

3. Platforms Supported

Passport 1424T L3 switch.

4. Notes for Upgrade

Please see "Release notes for the Passport 1400 Series Switch Software Release 2.1.3, available at http://www.nortel.com/support, select Passport family, then Passport 1400) for details on how to upgrade your Policy Switch.

File Names For This Release

File Name	Module or File Type	File Size (bytes)
PP1424_214_mib.zip	MIB zip file	360,714 bytes
PP1424T_214.had	Run-time image	1,968,392 bytes

5. Version of Previous Release

Software Version 2.1.3.0

6. Compatibility

This software release is managed with Java Device Manager (JDM) release 5.7.0.0

7. Changes in This Release

New Features in This Release
None.

Old Features Removed From This Release
None.

Problems Resolved in This Release

Using Passport 1424T release 2.1.4, the password change through the web-based administration of Passport 1424T works properly now. (Q00958642)

With Passport 1424T release 2.1.4, adding static routes will no longer cause loss of L3 connectivity to Passport 1424T. (Q01050293)

8. Outstanding Issues

None.

9. Known Limitations

On a Passport 1424T, the Link/Act light flashes when LX GBIC is inserted into port 26 with no cable inserted. (Q00947128)

10. Documentation Corrections

None.

For other known issues, please refer to the product release notes and technical documentation available from the Nortel Technical Support web site at: http://www.nortel.com/support .