Ethernet Routing Switch 2500
Software Release 4.3.0.200/201

1. Release Summary

Release Date: 8-October-2010
Purpose: Software patch release to address customer found software issues.

2. Important Notes Before Upgrading to This Release

None.

3. Platforms Supported

Ethernet Routing Switch 2500 (all models).

4. Notes for Upgrade

Please see "Ethernet Routing Switch 2500 Series Overview — System Configuration" (NN47215-500, available at http://www.avaya.com/support - click Products, select Ethernet Routing Switch 2500 Series from the A-Z list, then select Documentation > View All Documents) for details on how to upgrade your Switch.

File Names For This Release

File Name	Module or File Type	File Size (bytes)
2500_10015_diag.bin	Diagnostic image	1,265,238
2500_430200.img	Agent code image	6,232,300
2500_430201.img	Agent code image (SSH)	6,335,568

5. Version of Previous Release

Software Version 4.3.0.

6. Compatibility

This software release is managed with Java Device Manager (JDM) release 6.0.9 or later.

7. Changes in This Release

New Features in This Release

None.

Old Features Removed From This Release

None.

Problems Resolved in This Release

This release resolves link instability for the 10/100/1000/SFP combo ports (2526T ports 25 & 26, and 2550T ports 49 & 50).

Problem indications: Possible link up status when no SFP inserted or links connected or, unable to bring up link on RJ-45 10/100/1000 combo port when a connection is made to the port(s).

8. Outstanding Issues

None.

9. Known Limitations

None.

10. Documentation Corrections

For other known issues, please refer to the product release notes and technical documentation available from the Avaya Technical Support web site at: http://www.avaya.com/support .