ExtremeCloud SD-WAN 23.5.0

Release Notes

7 September 2023

Contents

New Features in 23.5.0 2
Known Issues in 23.5.0 2

New Features in 23.5.0

The following table contains the new features implemented in this ExtremeCloud SD-WAN release.

Feature ID	Feature	Description
XCW-3953	Applications Anywhere - Azure	Integration of Azure managed Gateways to extend the Customer's VPN to multiple workloads in the Cloud.
XCW-4573	SaaS Applications Dictionary Auto Update	The SaaS Applications dictionary is also updated automatically once a week, in the case of Edge Cloud deployment.
XCW-4635	Enhance Topology with Cloud and External Security Gateways	External VPN gateways, Cloud VPN gateways and external security gateways are displayed at the proper locations on the maps.
XCW-1272	DHCP Server Management – Beta version	This feature includes DHCP server configuration at the global level, monitoring and troubleshooting.
XCW-431	Configuration Change Management – Phase 1 (Audit Logs)	Phase 1 focuses on configuration changes (account access, configuration, deployment, firmware, etc.).
XCW-4270	Confirmation of Firmware Upgrade	Before the firmware is upgraded, the system asks the user to confirm.
XCW-3986	Automatic upgrade at first appliance boot	When an appliance with a default factory configuration is connected for the first time, it is automatically upgraded with the latest firmware version.

Known Issues in 23.5.0

The following table contains known product issues.

Issue ID	Description
XCW-4897	All the Secure Web Gateways are not listed in the Settings -> Security panel.
XCW-4898	All the available Sites are not listed when a VPN Zone is created or edited in the Settings -> Security panel.
XCW-5310	Onboarded appliances are not visible for the Observer user profile.
XCW-5680	EdgeSentry does not generate any alarm when a Site is created with a LAN subnet which is already assigned to a Site in Harmony Connect.
XCW-5690	The Dashboard may show an incomplete or empty tunnel topology.
XCW-5691	Tunnels may disappear when the user filters data and moves on the map.
XCW-5732	Advanced Troubleshooting may not display any data.

Copyright © 2023 Extreme Networks, Inc. All rights reserved.

Legal Notice

Extreme Networks, Inc. reserves the right to make changes in specifications and other information contained in this document and its website without prior notice. The reader should in all cases consult representatives of Extreme Networks to determine whether any such changes have been made.

The hardware, firmware, software or any specifications described or referred to in this document are subject to change without notice.

Trademarks

Extreme Networks and the Extreme Networks logo are trademarks or registered trademarks of Extreme Networks, Inc. in the United States and/or other countries.

All other names (including any product names) mentioned in this document are the property of their respective owners and may be trademarks or registered trademarks of their respective companies/owners. For additional information on Extreme Networks trademarks, see: http://www.extremenetworks.com/company/legal/trademarks

Open Source Declarations

Some software files have been licensed under certain open source or third-party licenses. End- user license agreements and open source declarations can be found at:

https://www.extremenetworks.com/support/policies/open-source-declaration/