Ethernet Routing Switch 2500
Software Release 4.2.1

1. Release Summary

Release Date: 15-January-2009
Purpose: Software patch release to address customer found software issues.

2. Important Notes Before Upgrading to This Release

None.

3. Platforms Supported

Ethernet Routing Switch 2500 (all models).

4. Notes for Upgrade

Please see "Nortel Ethernet Routing Switch 2500 Series Overview — System Configuration" (NN47215-500, available at http://www.nortel.com/support - select Routers & Routing Switches, then select the appropriate Ethernet Routing Switch 2500 model) for details on how to upgrade your Switch.

File Names for This Release

File Name	Module or File Type	File Size (bytes)
2500_421000.img	Agent code image	4,798,992
2500_421001s.img	Agent code image (SSH)	4,902,124

5. Version of Previous Release

Software Version 4.2.0.

6. Compatibility

This software release is managed with Java Device Manager (JDM) release 6.0.9.

7. Changes in This Release

New Features in This Release

None.

Features Removed From This Release

A feature enhancement **(Q01645430)** that changed the VLACP interoperability behavior with Passport 8600 was removed.

Problems Resolved in This Release

8. Outstanding Issues

None.

9. Known Limitations

None.

10. Documentation Corrections

For other known issues, please refer to the product release notes and technical documentation available from the Nortel Technical Support web site at: http://www.nortel.com/support .