Ethernet Routing Switch 3500 Series
Software Release 5.0.1

1. Release Summary

Release Date: 08-August-2012
Purpose: Software patch release to introduce new features as well as to address customer and internally found software issues.

2. Important Notes Before Upgrading to This Release

None.

3. Platforms Supported

Ethernet Routing Switch 3500 (all models).

4. Notes for Upgrade

Please see "Ethernet Routing Switch 3500 Series, Configuration – System, Software Release 5.0" (available at http://www.avaya.com/support . Click Products, select Ethernet Routing Switch 3500 Series from the A-Z list, then select Documentation > View All Documents) for details on how to upgrade your Switch.

File Names for This Release

File Name	Module or File Type	File Size (bytes)
3500_1006_diag.bin	Diagnostic image	2,183,001
3500_501006.img	Agent code image	7,756,580
3500_501007s.img	Agent code image (SSH)	7,977,972
Ethernet_Routing_Switch_35xx_MIBs_5.0.1.zip	Software Release 5.0.1 MIB definition files	1,305,404

5. Version of Previous Release

Software Version 5.0.

6. Compatibility

This software release is managed with Enterprise Device Manager (EDM).

7. Changes in This Release

7.1. New Features in This Release

UntrustedBasic QoS support
Run IP Office Script
Voice VLAN Integration
802.1AB User Configurable MED Network Policy
POE+ compliance: Default in-rush current is set to Low

7.2 Old Features Removed From This Release

None.

7.3 Problems Resolved in This Release

3500 does not reliably change the PVID upon Radius reply. If port is already a member of the VLAN assigned by RADIUS at Non-EAP authentication, PVID should still be changed.

wi01026571	**EDM:Policy Unknown tab should be removed from Local Policy menu**
wi01027688	**IPOffice Script - Request IPs for the Voice and Data Vlan**
wi01026573	**EDM:Unknown TLV tab should be removed from LLDP menu**
wi01026579	**EDM:Cannot modify Policy VlanID from EDM**
wi01026660	**IPOfficeScript do not configure or ask for IPOffice Call-Server or File-Server**
wi01026582	**EDM:Policy tagged status 0 should be changed into disabled**
wi01026568	**LLDP med-network-policy settings are not saved in ACG**
wi01026574	**EDM:Cannot modify Policy Tagged from EDM**
wi01026577	**EDM:Cannot modify Policy DSCP from EDM**
wi01030185	**IPOffice Script - When run ipoffice twice an QOS error is reported by the script**
wi01026578	**EDM:Cannot modify Policy Priority from EDM**
wi01026625	**IPOfficeScript command do not have help inline explanation when using "?"**
wi01027703	**IPOffice Script - End banner is not present**

8. Outstanding Issues
None.

9. Known Limitations
None.

10. Documentation Corrections
For other known issues, please refer to the product release notes and technical documentation available from the Avaya Technical Support web site at: http://www.avaya.com/support .