BayStack 450/410
Software Release 4.5.1

1. Release Summary

Release Date: 18-August-2004
Purpose: Software patch release to address customer found software issues.

2. Important Notes Before Upgrading to This Release

None.

3. Platforms Supported

BayStack 450-24T
BayStack 450-12F
BayStack 410-24T

4. Notes for Upgrade

Please see "Release Notes for the BayStack 450 10/100/1000 Switch" (Part No. 214110-D Rev 00, available at http://www.nortelnetworks.com/documentation, select BayStack family, then BayStack 450) for details on how to upgrade your Policy Switch.

5. Version of Previous Release

Software Version 4.5.0.

6. Compatibility

This software release is managed with Java Device Manager (JDM) release 5.7.9.0.

7. Changes in This Release

New Features in This Release
None.

Old Features Removed From This Release
None.

Problems Resolved in This Release

Upgrading to previous code version (4.5.0) may cause a slow down in the management of the units/stacks. This problem could be severe at times and management tools may report units/stacks as being down. This issue is resolved in 4.5.1 release **(Q00956327).**

Rev: 1.0 (11-August-2004)

8. Known Limitations

Due to HW limitations it is not possible to perform rate limiting in 1-2% range. Therefore, the 1% option has been removed from the code; the new rate limiting value range is between 2-10% **(Q00879375)**

For other known issues, please refer to version 4.4 release notes from the Nortel Networks web site at:
http://www.nortelnetworks.com/documentation.