	Nortel VPN Client Software Release V7_01.330

1. Release Summary

Release Date: September 8, 2008
Purpose: Software Release to address customer found software issues.

2. Important Notes Before Upgrading to This Release

None.

3. Platforms Supported

Windows 2000
Windows XP

4. Notes for Upgrade

Please see the "Nortel VPN Client Release Notes" for Version 7.01 (Part No. 311773-R Rev 01), Release Notes are available at http://www.nortel.com/support (select the Security & VPN, VPN Client, select Release Notes).

5. Version of Previous Release

Software Version 7.01.280

6. Compatibility

7. Changes in This Release

New Features in This Release

None.

Old Features Removed From This Release

None.

Problems Resolved in This Release

Nortel Networks* Contivity* VPN Client sustaining Release Version 7.01.330 fixes the following issues:

Q01743142 –
The Nortel VPN Client will now support the challenge-response authentication method using the Passgo formerly Axent) libraries.

Q01771699 –
The Auto-connect feature of the Nortel VPN Client may not function in accordance with the Auto-connect rules.

Q01800795 –
Installing the Nortel VPN Client with a custom icon puts both the custom and default icon on the desktop.

Q01837118 –
The Nortel VPN Client may log "Dynamic DNS Registration complete successfully" even when the registration has failed.

Q01852861 –
The Nortel VPN Client may fail to authenticate to a remote LDAP proxy server if the German Version of the Windows OS is loaded.

Q01856458 –
When upgrading the Nortel VPN Client from the 7.01 general release to a 7.01.250 or later maintenance release the silent install option does not work properly.

Q01879517 –
The Nortel VPN Client will not install properly on the Windows 2003 Server.

Q01888507 –
When the Nortel VPN Client customized installation kit is installed, the default shortcut in start menu programs is shown, and not the custom shortcut.

Q01919237 –
The Focus (cursor) in the VPN Router Client Window defaults to the wrong field when using software token authentication.

8. Outstanding Issues

None.

9. Known Limitations

None.

10. Documentation Corrections

None.

For other known issues, please refer to the product Release notes and technical documentation available from the Nortel Technical Support web site at: http://www.nortel.com/support.