



# Locating Documentation and Software for VSP 9000

Release 4.0  
NN46250-106 (700502284 Rev 05)  
Issue 05.01  
April 2014

This document ships with multiple Virtual Services Platform 9000 components. If you ordered a 9080CP module, it may not have the latest software pre-installed. Avaya recommends that you check the Avaya Support website for the latest Virtual Services Platform 9000 software release. Avaya also recommends that you check for patches that apply to the specific software release.

Avaya recommends that you read the following documents before you install and configure Avaya Virtual Services Platform 9000:

- *Quick Start Configuration for Avaya Virtual Services Platform 9000*, NN46250-102—provides instructions to perform initial provisioning and basic configuration of the Avaya Virtual Services Platform 9000 software.
- *Release Notes for Avaya Virtual Services Platform 9000*, NN46250-401— includes a list of known issues, including workarounds if appropriate, and a list of resolved issues.
- *Documentation Reference for Avaya Virtual Services Platform 9000*, NN46250-100—contains an overview of the Avaya Virtual Services Platform 9000 documentation suite. Read this document to find the correct document that describes the task you need to perform.
- *Applying Upgrades and Patches to Avaya Virtual Services Platform 9000*, NN46250-400— contains upgrade and patching procedures that enable you to install and manage patches for the current software release, and to upgrade hardware and software from one release to another for Virtual Services Platform 9000.

For the current documentation, software, and patches, see the Avaya Support website: [www.avaya.com/support](http://www.avaya.com/support). Each patch has a readme file that explains how to install that specific patch.