



Ethernet Routing Switch 1424T

Software Release 2.1.6.1

Release Summary

Release Date: Nov 2, 2007

Purpose: Software patch release to address customer found software issues.

2. Important Notes Before Upgrading to This Release

None.

3. Platforms Supported

Ethernet Routing Switch, 1424T

4. Notes for Upgrade

Please see “Release notes for the Passport 1400 Series Switch Software Release 2.1.6, available at <http://www.nortel.com/support>, (select Passport family, then Passport 1424T) for details on how to upgrade your Policy Switch.

File Names For This Release

File Name	Module or File Type	File Size (bytes)
MIB File	PP1424T_2161_mib.zip	360714
Run-time image	PP1424T-REL-2.1.6.1.had	1972038

5. Version of Previous Release

Software Version 2.1.6.0

6. Compatibility

This software release is managed with Java Device Manager (JDM) release 5.7.0.0

7. Changes in This Release New

Features in This Release

None.

Old Features Removed From This Release

None.

Problems Resolved in This Release

Using this release, the IP services (such as Telnet) on ERS 1424T will remain functional when there is continuous ping to the switch while a telnet session is being terminated (Q01768263).

8. Outstanding Issues

None.

9. Known Limitations

For known issues, please refer to version 1.2 release notes on the Nortel Networks Web site at: <http://www.nortel.com/support>.

10. Documentation Corrections

None.

For other known issues, please refer to the product release notes and technical documentation available from the Nortel Technical Support web site at: <http://www.nortel.com/support>.

Copyright © 2007 Nortel Networks Limited - All Rights Reserved. Nortel, Nortel Networks, the Nortel logo, Globemark, and Ethernet Routing Switch 1424T are trademarks of Nortel Networks Limited. The information in this document is subject to change without notice. The statements, configurations, technical data, and recommendations in this document are believed to be accurate and reliable, but are presented without express or implied warranty. Users must take full responsibility for their applications of any products specified in this document. The information in this document is proprietary to Nortel.

To access more technical documentation, search our knowledge base, or open a service request online, please visit Nortel Technical Support on the web at: <http://www.nortel.com/support>