



1. Release Summary

Release Date: Jan 18, 2005

Purpose: Software patch release to address customer found issue.

2. Important Notes Before Upgrading to This Release

None.

3. Platforms Supported

Passport 1600 Routing Switch Series (1648T, 1612G & 1624G)

4. Notes for Upgrade

Please see Release Notes for the Passport 1600 Series Switch Software Release 1.2. (Part No 316859-G Rev 00, see <http://www.nortelnetworks.com/documentation>, select Passport family) and Release Notes document for Release 1.2 for details on how to upgrade your Passport 1600.

File Names For This Release

File Name	Module or File Type	File Size (bytes)
1600 Series switch files		
MIB	p16a1210.mib.zip	406608
Run-time image	p16a1210.img	3053636
Run-time image with SSH Encryption	p16c1210.img	3056956

5. Version of Previous Release

Software Version 1.2.0.0

6. Compatibility

This software release is managed with Java Device Manager (JDM) release 5.8.5.0

7. Changes in This Release

New Features in This Release

None.

None.

Problems Resolved in This Release

In some extremely rare cases on PP1648, for very large files that use a specific traffic pattern, a transmission error occurs, causing a file transfer failure. This extremely rare problem is now fixed in Passport 1600 series software release 1.2.1.0. (Q00989527)

Note: The V1.2.0.0 release notes incorrectly stated that this problem had been corrected. The V1.2.1.0 code includes this correction

8. Outstanding Issues

For other known issues, please refer to version 1.2 release notes on the Nortel Networks Web site at: <http://www.nortelnetworks.com/documentation>.

9. Known Limitations

For other known issues, please refer to version 1.2 release notes on the Nortel Networks Web site at: <http://www.nortelnetworks.com/documentation>.

10. Documentation Corrections

For other known issues, please refer to version 1.2 release notes on the Nortel Networks Web site at: <http://www.nortelnetworks.com/documentation>.

For other known issues, please refer to the product release notes and technical documentation available from the Nortel Technical Support web site at: <http://www.nortel.com/support> .

Copyright © 2005 Nortel Networks Limited - All Rights Reserved. Nortel, Nortel Networks, the Nortel logo, Globemark, and <product family> are trademarks of Nortel Networks Limited.

The information in this document is subject to change without notice. The statements, configurations, technical data, and recommendations in this document are believed to be accurate and reliable, but are presented without express or implied warranty. Users must take full responsibility for their applications of any products specified in this document. The information in this document is proprietary to Nortel.

To access more technical documentation, search our knowledge base, or open a service request online, please visit Nortel Technical Support on the web at: <http://www.nortel.com/support>