



Ethernet Routing Switch 1600

Software Release 1.2.4.2

Release Summary

Release Date: July 25, 2006

2. Important Notes Before Upgrading to This Release

None.

3. Platforms Supported

Ethernet Routing Switch, 1600 Series (1648T, 1612G & 1624G)

4. Notes for Upgrade

Please see Release Notes for the Ethernet Routing Switch 1600 Series switch Software Release 1.2. (Part No 316859-G Rev 00, see <http://www.nortel.com/support>, select Passport family) and Release Notes document for Release 1.2.4.1 for details on how to upgrade your Ethernet Routing Switch 1600.

File Names For This Release

File Name	Module or File Type	File Size (bytes)
1600 Series switch files		
Run-time image	P16a1242.img	3085474
Run-time image with SSH Encryption	P16c1242.img	3086878
MIBs	P16a1242.mib.zip	406608

5. Version of Previous Release

Software Version 1.2.4.0

6. Compatibility

This software release is managed with Java Device Manager (JDM) release 5.8.5.0

7. Changes in This Release New

Features in This Release

None.

Old Features Removed From This Release

None.

Problems Resolved in This Release

Using this release, there will no longer be loss of connectivity due to STP bouncing repeatedly on MLT ports. (Q01400468)

8. Outstanding Issues

None.

9. Known Limitations

For known issues, please refer to version 1.2 release notes on the Nortel Networks Web site at: <http://www.nortel.com/support>.

10. Documentation Corrections

None.

For other known issues, please refer to the product release notes and technical documentation available from the Nortel Technical Support web site at: <http://www.nortel.com/support>.

Copyright © 2005 Nortel Networks Limited - All Rights Reserved. Nortel, Nortel Networks, the Nortel logo, Globemark, and <product family> are trademarks of Nortel Networks Limited.

The information in this document is subject to change without notice. The statements, configurations, technical data, and recommendations in this document are believed to be accurate and reliable, but are presented without express or implied warranty. Users must take full responsibility for their applications of any products specified in this document. The information in this document is proprietary to Nortel.

To access more technical documentation, search our knowledge base, or open a service request online, please visit Nortel Technical Support on the web at: <http://www.nortel.com/support>