

Part No. 214113-A
September 2002

4655 Great America Parkway
Santa Clara, CA 95054

**Addendum to the Release
Notes for the BayStack 420
10/100/1000 Switch
Software Version 1.1.0**

214113-A

**NORTEL
NETWORKS**

Copyright © 2002 Nortel Networks

All rights reserved. September 2002.

The information in this document is subject to change without notice. The statements, configurations, technical data, and recommendations in this document are believed to be accurate and reliable, but are presented without express or implied warranty. Users must take full responsibility for their applications of any products specified in this document. The information in this document is proprietary to Nortel Networks Inc.

Trademarks

Nortel Networks, the Nortel Networks logo, the Globemark, Unified Networks, BayStack 420, and Optivity are trademarks of Nortel Networks.

Microsoft, Windows, and Windows NT are trademarks of Microsoft Corporation.

Adobe and Acrobat Reader are trademarks of Adobe Systems Incorporated.

Java is a trademark of Sun Microsystems, Inc.

Macintosh is a trademark of Apple Computer, Inc.

Netscape Navigator is a trademark of Netscape Communications Corporation.

Restricted rights legend

Use, duplication, or disclosure by the United States Government is subject to restrictions as set forth in subparagraph (c)(1)(ii) of the Rights in Technical Data and Computer Software clause at DFARS 252.227-7013.

Notwithstanding any other license agreement that may pertain to, or accompany the delivery of, this computer software, the rights of the United States Government regarding its use, reproduction, and disclosure are as set forth in the Commercial Computer Software-Restricted Rights clause at FAR 52.227-19.

Statement of conditions

In the interest of improving internal design, operational function, and/or reliability, Nortel Networks Inc. reserves the right to make changes to the products described in this document without notice.

Nortel Networks Inc. does not assume any liability that may occur due to the use or application of the product(s) or circuit layout(s) described herein.

Known issues

The following are know issues for the BayStack 420 10/100/1000 Switch, Software Version 1.1.0:

- When using MAC Address Security, if a unit is reset, then the MAC addresses that were allowed access will no longer be allowed access. To resolve this issue, disable and reenale the MAC Address Security. (CR Q00511575)
- If you re-enable an active port that is in blocking mode, then the spanning tree application may fail to operate on that port. Avoid enabling any ports that have already been enabled. If you should encounter this issue, disable and reenale the effected ports. (CR Q00510539)

6 Known issues
