



Ethernet Switch 325/425

Software Release 3.6.3

1. Release Summary

Release Date: 15-December-2008

Purpose: Software patch release to address customer found software issues.

2. Important Notes Before Upgrading to This Release

None.

3. Platforms Supported

Ethernet Switch 325/425

4. Notes for Upgrade

Upgrading the switch/stack to 3.6 or a higher version **must** be done through successive steps (3.0.x ->3.1.x -> 3.5.x -> 3.6.x.) in order to preserve the STP configuration settings. See CR Q01389697, Q01274880 for details. Please see "Release Notes for the Ethernet Switch 325/425" (Part No. 217155-B, available at <http://www.nortel.com/support>, select Switches & Hubs, then Ethernet Switch 425-24T) for details on how to upgrade your switch.

File Names For This Release

File Name	Module or File Type	File Size (bytes)
425_36304.img	Agent code image	2,051,472
425_36305s.img	Agent code image (SSH)	2,103,324

5. Version of Previous Release

Software Version 3.6.2.

6. Compatibility

This software release is managed with Java Device Manager (JDM) release 5.9.6.
The diagnostic version must be 3.6.0.1.

7. Changes in This Release

New Features in This Release

None.

Old Features Removed From This Release

None.

Problems Resolved in This Release

Under certain conditions, there were inconsistencies in displaying MLT status (**Q01855053**).

Sys-log message time is not synchronized with NTP server's time (**Q01939310**).

With a specific SSH client, an SSH session to the switch could not be established (**Q01837389-06**).

When using RSTP, autotopology stopped working after upgrading from 3.5.1 to 3.6.2 (**Q01938536**).

8. Outstanding Issues

None.

9. Known Limitations

None.

10. Documentation Corrections

For other known issues, please refer to the product release notes and technical documentation available from the Nortel Technical Support web site at: <http://www.nortel.com/support>.

Copyright ©2008 Nortel Networks Limited - All Rights Reserved. Nortel, Nortel Networks, the Nortel logo, and the Globemark are trademarks of Nortel Networks Limited.

The information in this document is subject to change without notice. The statements, configurations, technical data, and recommendations in this document are believed to be accurate and reliable, but are presented without express or implied warranty. Users must take full responsibility for their applications of any products specified in this document. The information in this document is proprietary to Nortel.

To access more technical documentation, search our knowledge base, or open a service request online, please visit Nortel Technical Support on the web at: <http://www.nortel.com/support>