

1. Release Summary

Release Date: 05-Nov-2004

Purpose: Software patch release to address customer reported software issues.

2. Important Notes Before Upgrading to This Release

3. Platforms Supported

BayStack 470/460/BPS

4. Notes for Upgrade

Please see "Release Notes for the BayStack 470/460/BPS 10/100/1000 Switch" available at <http://www.nortelnetworks.com/support> select BayStack family, then BayStack 470/460/BPS) for details on how to upgrade your Policy Switch.

5. Version of Previous Release

Software Version 3.1.2

6. Compatibility

This software release is managed with Java Device Manager (JDM) release 5.7.4.0.

7. Changes in This Release

New Features

None.

Old Features Removed

None.

Problems Resolved

In previous code versions it was not possible to add QoS filters for virus protection through the Web interface (**Q00900780**).

On a hybrid stack, all the MAC addresses were not always properly displayed when using the CLI (Q00915551).

802.1p priority settings were incorrectly mapped to the BPS2000 dual-GIG MDA's 8 egress hardware queues (Q00991174).

802.1P priority settings were incorrectly mapped to the stacking module's 2 egress hardware queues (Q01004739).

8. Known Limitations

None.

For other known issues, please refer to version 3.0.0 release notes from the Nortel Networks web site at: <http://www.nortelnetworks.com/support>